



The Commonwealth of Massachusetts

DEPARTMENT OF PUBLIC UTILITIES

PIPELINE ENGINEERING AND SAFETY DIVISION

INCIDENT REPORT

88 Waltham Street, Maynard, Massachusetts

January 3, 2008

PIPELINE ENGINEERING AND SAFETY DIVISION

Accident File

Explosion

Location: Maynard, Massachusetts

Date of Accident: January 3, 2008

Gas Company: NSTAR Gas Company

Estimated Property Damage: \$152,449*

Report Issued – May 12, 2010

* Estimated by NSTAR Gas Company

Table of Contents

I.	INTRODUCTION	1
A.	Scope of the Investigation.....	1
B.	Overview of Incident.....	2
II.	BACKGROUND	3
III.	THE DEPARTMENT'S INVESTIGATION.....	3
A.	Description of the Scene	3
1.	Records of the Service Line to 88 Waltham Street	4
2.	Leak Surveys of Service Line to 88 Waltham Street and the Street Main	4
IV.	FAILURE ANALYSIS OF THE PIPE SAMPLE.....	5
V.	FINDINGS AND CONCLUSIONS	6
A.	Findings	6
B.	Conclusions.....	6
VI.	NSTAR ACTIONS.....	7

Exhibits

Exhibit 1	Nstar Gas Incident Report
Exhibit 2	Photographs of Space Heaters
Exhibit 3	Service Line From 88 Waltham Street
Exhibit 4	Operating Pressure of Service Line
Exhibit 5	Maynard Fire Department Report
Exhibit 6	Depth of Main on Waltham Street
Exhibit 7	Service Line Installation
Exhibit 8	Department Notification of the Incident
Exhibit 9	Leak Survey Prior to Incident
Exhibit 10	Post-Incident Leak Survey
Exhibit 11	Photographs of Incident site and Residence

I. INTRODUCTION

A. Scope of the Investigation

The Massachusetts Department of Public Utilities (“Department”), Pipeline Engineering and Safety Division (“Division”), pursuant to G.L. c. 164, § 105A and a Federal Certification Agreement as provided for in 49 U.S.C. § 60105, has investigated a release of natural gas (“gas”) at 88 Waltham Street, Maynard, Massachusetts (“Incident”).¹ The release of gas contributed to a fire and over \$150,000 in property damage to the dwelling, as estimated by the operator of the natural gas facilities, NSTAR Gas Company (“NSTAR” or “Operator”) (Exh. 1).

As part of the Department’s annual certification process by the United States Department of Transportation (“U.S. DOT”), the Department must report to the U.S. DOT each accident or incident . . . involving a fatality, personal injury requiring hospitalization, or property damage or loss of more than an amount the Secretary establishes... and any other accident the [Department] considers significant, and a summary of the investigation by the [Department] of the cause and circumstances surrounding the accident or incident. 49 U.S.C. § 60105(c).

The purpose of this report is to inform the U.S. DOT as to the cause and circumstances surrounding the Incident.

¹ Incident means any of the following events:

1. An event that involves a release of gas from a pipeline or liquefied natural gas or gas from an LNG facility and,
 - a. A death, or personal injury necessitating in-patient hospitalization; or
 - b. Estimated property damage, including cost of gas lost, of the operator or others, or both, of \$50,000 or more.
2. An event that results in an emergency shutdown of an LNG facility.
3. An event that is significant in the judgment of the operator, even though it did not meet the criteria of paragraphs (1) or (2). 49 C.F.R. Part 191, § 191.3.

The Department has established procedures for determining the nature and extent of violations of codes and regulations pertaining to safety of pipeline facilities and the transportation of gas, including but not limited to, 220 C.M.R. §§ 101.00 through 113.00. See 220 C.M.R. § 69.00 et seq. The Division also enforces the U.S. DOT safety standards for gas pipeline systems as set forth in 49 C.F.R. Part 192 ("Part 192"). G.L. c. 164, § 105A.

B. Overview of Incident

On January 3, 2008, the owner of the residence ("owner") placed two kerosene-fired torpedo heaters in the home's crawl space to thaw frozen water pipes (Exh. 2). In the vicinity of the heaters was a ½ inch plastic gas line inserted into a ¾ inch steel gas service line (id.).² The approximate length of the service line in the crawl space was twenty six feet (Exh. 3). The operating pressure of the service line was 45 pounds per square inch gauge ("psig")³ (Exh. 4).

At approximately 6:21 p.m., the Maynard Fire Department received an alarm. They arrived at the site at 6:23 p.m. to find a working fire (Exh. 5). According to the Maynard Fire Department report, "[f]irst attempts to contain the fire seemed successful but a broken gas line

² "Service line" means a distribution line that transports gas from a common source of supply to an individual customer, to two adjacent or adjoining residential or small commercial customers, or to multiple residential or small commercial customers served through a meter header or manifold. A service line ends at the outlet of the customer meter or at the connection to a customer's piping, whichever is further downstream, or at the connection to customer piping if there is no meter.

³ The term, "psig," refers to the pressure expressed in pounds exerted on one square inch of surface area. The designation "gauge," indicates the readings are already adjusted to ignore the surrounding atmospheric pressure, which is 14.7 psi at sea level. If psig gauge were not connected to any pressure source, it would read zero even though it is actually sensing 14.7 psi at sea level.

from the street flashed twice, command ordered the building evacuated and requested the gas company to respond as soon as possible (id.).” The Maynard Fire Department report concluded that the cause of the fire was likely the use of a space heater in a confined area to thaw frozen pipes (id. at 2).

II. BACKGROUND

Waltham Street is in a residential area of Maynard. The neighborhood consists of multi-family two and three-story dwellings and some single family, one-story dwellings. The Incident occurred in a two-story, single family building at 88 Waltham Street. NSTAR stated that a two inch steel gas main,⁴ installed in 1924, underlay Waltham Street (Exh. 4). The operating pressure of the gas main at the time of the incident was 45 psig (id.). The main was installed at a depth of 30 inches (Exh. 6). A 21 foot section of bare steel service line with a plastic insert supplied gas to 88 Waltham Street (Exh. 7).

III. THE DEPARTMENT’S INVESTIGATION

A. Description of the Scene

On Wednesday, January 9, 2008, at 8:54 a.m., the Division received a call from an independent fire investigator (Exh. 8). The investigator reported that at around 6 p.m., on January 3, 2008, a “gas related” fire had occurred at 88 Waltham Street, Maynard, MA (id.). The investigator also reported that a 30 foot gas line existed in the basement/crawl space, before the meter (id.).

⁴ "Main" means a distribution line that serves as a common source of supply for more than one service line.

On Friday, January 11, 2008, at approximately 8:45 a.m., two investigators from the Department's Pipeline Engineering and Safety Division arrived at the scene. Upon arrival at the scene, the investigators met with Jonathan Pfister, NSTAR Compliance and Corrosion Manager, and Chief Stephen J. Kulik of the Maynard Fire Department.

The investigators then entered the building basement and observed that the meter in the original basement had been removed by NSTAR (Exh. 11). The investigators also observed two bullet type space heaters in a crawl space facing the gas service (id.).

Also observed in the crawl space was an approximately twenty-six foot section of steel pipe which carried the inserted ½ inch plastic pipe from the stone foundation, through the crawl space, to the meter in the original basement (id.). The investigators observed a threaded coupling and two fittings on the service line approximately three feet from the wall entry point. The investigators also observed that the threaded couplings at the fittings appeared to be loose (id.). The investigators also observed water pipes and several other pipes in the crawl space.

1. Records of the Service Line to 88 Waltham Street

The original ¾ inch bare steel service line was installed in 1924 (Exh. 7). A 21 foot section of the service line was relayed with one inch bare steel on August 24, 1949 (id.). On February 5, 1982, the entire service was inserted with ½ inch plastic (id.). The company has no records of leaks on the service pipe (id.).

2. Leak Surveys of Service Line to 88 Waltham Street and the Street Main

On March 6, 2007, a mobile leak survey was conducted on Waltham Street and the surrounding area; there were no leaks found (Exh. 9). NSTAR conducted a walking leak

survey on the service line to 88 Waltham Street on January 11, 2008, gas readings were recorded from one percent gas to three percent⁵ gas at the building foundation and ten percent gas a short distance from the foundation in the vicinity of a 90 degree bend in the service approximately ten feet outside the north side of 88 Waltham Street (Exh. 10). Also, a reading of ten percent gas was recorded in the street at the main (id.).

IV. FAILURE ANALYSIS OF THE PIPE SAMPLE

Altran Solutions (“Altran”) conducted the failure analysis of the service line segment for this investigation. Department representatives observed all aspects of the failure analysis. In May, 2009, Altran submitted its results to the Department (“Altran Report”).⁶ Altran’s analysis composed six subsections: Visual, Boroscopic, Sectioning and Examinations, Tensile Testing, Analytical Analyses, and Pressure Testing (id.). The purpose of the testing was to document the condition of the plastic service line, identify leaks, characterize deposits, leaks, and fracture surfaces.

Based on these tests results, a summary of Altran’s major conclusions are as follows:

The results of the testing and evaluation indicate the leakage failure of the pipe was due to application of localized high temperature, resulting in polymer melting and material flow. Several thermal and chemical analyses were performed on polymeric material from the leak site and, for reference, from distant portions of the pipe. No evidence of contamination or manufacturing defects was found, and no burning (charring) was seen. The mechanical, analytical and

⁵ “Percent gas” includes all concentrations (measured as a percent of volume in air) of a flammable gas or vapor that will propagate flame when exposed to a source of ignition. Many common flammable liquids have very wide explosive ranges. The explosive range of all flammable gases and vapors will vary with temperature and pressure.

⁶ Copies of Altran’s report may be purchased from Altran Solutions Corporation, 80 Fargo Street, Boston, Massachusetts 02210-2122, (617) 204-1000

pressure tests suggest the material was not defective or measurably degraded from age. The noted deformation from twisting and bursting are consistent with softening of the material to the point where the internal gas pressure exceeded the lowered strength of the pipe wall causing the burst (*id.* at 12).

V. FINDINGS AND CONCLUSIONS

A. Findings

- (1) The Maynard Fire Department received an alarm at 6:21 p.m. on January 3, 2008, reporting a building fire at 88 Waltham Street, Maynard, MA.
- (2) An approximately twenty-six foot section of plastic gas service line was encased in steel and ran through a crawl space to the basement of 88 Waltham Street, Maynard.
- (3) Water pipes also occupied the same crawl space.
- (4) Department investigators found two bullet type space heaters in the crawl space.
- (5) The space heaters were facing the gas service pipe.
- (6) Department investigators observed a loose union on the steel gas service pipe in the crawl space.
- (7) The Maynard Fire Department stated the unofficial cause was the use of a space heater in a confined area to thaw frozen pipes.

B. Conclusions

The Altran Report's conclusion that the plastic pipe failed due to the application of localized high temperature, resulting in polymer melting and material flow is reasonable, and based upon substantial and specific evidence. The likely source of the damage to the plastic service pipe was heat from two bullet type space heaters. The location of the release of gas into the atmosphere was possibly at the loose fittings of the steel pipe in the crawl space. The two space heaters are possible sources for the ignition of the released gas.

VI. NSTAR ACTIONS

On April 12, 2010, the Division issued a Warning Letter to the Operator. NSTAR Gas Company, 08-PLW-14. 220 C.M.R. § 69.03(1). The Division reviewed the circumstances of the Operator's post-Incident leak investigation, and had reason to believe that NSTAR may not have completed a leak investigation of certain leak locations the Operator identified after the Incident, consistent with its Operating and Maintenance Procedures. The Division requested that NSTAR provide records to demonstrate that it has notified all personnel that they must always implement, and follow, NSTAR Leak Investigation procedures.

EXHIBIT 1

Nstar Gas Incident Report



U.S. Department of Transportation
Pipeline and Hazardous Materials Safety
Administration

INCIDENT REPORT - GAS DISTRIBUTION SYSTEM

Report Date _____
No. _____
(DOT Use Only)

INSTRUCTIONS

Important: Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the Office Of Pipeline Safety Web Page at <http://ops.dot.gov>.

PART A - GENERAL REPORT INFORMATION

Check: Original Report Supplemental Report Final Report

1. Operator Name and Address

- a. Operator's 5-digit Identification Number 0 / 2 / 6 / 5 / 2 /
- b. If Operator does not own the pipeline, enter Owner's 5-digit Identification Number / / / / /
- c. Name of Operator NSTAR Gas Company
- d. Operator street address One NSTAR Way
- e. Operator address Westwood, Norfolk, Massachusetts 02090
City, County or Parish, State and Zip Code

2. Time and date of the incident

 1 / 8 / 2 / 1 / 0 / 1 / 0 / 3 / 0 / 8 /
hr. month day year

3. Incident Location

- a. 88 Waltham Street
Street or nearest street or road
- b. Maynard, Middlesex County
City and County or Parish
- c. Massachusetts 01754-2437
State and Zip Code
- d. Latitude: 4 / 2 / . / 4 / 3 / Longitude: - / 7 / 1 / . / 4 /
(if not available, see instructions for how to provide specific location)
- e. Class location description
 Class 1 Class 2 Class 3 Class 4
- f. Incident on Federal Land Yes No

4. Type of leak or rupture

- Leak: Pinhole Connection Failure (complete sec. F5)
 Puncture, diameter or cross section (inches) _____
- Rupture (if applicable):
 Circumferential - Separation
- Longitudinal
- Tear/Crack, length (inches) _____
- Propagation Length, total, both sides (feet) _____
- N/A
- Other: Unknown: under investigation

5. Consequences (check and complete all that apply)

- a. Fatality Total number of people: / / / /
Employees: / / / / General Public: / / / /
Non-employee Contractors: / / / /
- b. Injury requiring inpatient hospitalization
Total number of people: / / / /
Employees: / / / / General Public: / / / /
Non-employee Contractors: / / / /
- c. Property damage/loss (estimated) Total \$152,449
Gas loss \$949 Operator damage \$1500
Public/private property damage \$150,000
- d. Gas ignited Explosion No Explosion
- e. Gas did not ignite Explosion No Explosion
- f. Evacuation (general public only) / / / / / people
Evacuation Reason:
 Unknown
 Emergency worker or public official ordered, precautionary
 Threat to the public
 Company policy

6. Elapsed time until area was made safe:

 0 / 2 / hr. 3 / 9 / min.

7. Telephone Report

 8 / 5 / 9 / 4 / 5 / 9 / 0 / 1 / 1 / 1 / 0 / 8 /
NRC Report Number month day year

8. a. Estimated pressure at point and time of incident:

 45 PSIG

b. Max. allowable operating pressure (MAOP): 60 PSIG

c. MAOP established by:

- Test Pressure _____ psig
- X 49 CFR § 192. 619 (a)(3)

PART B - PREPARER AND AUTHORIZED SIGNATURE

 Jonathan Pfister, Manager, Compliance and Corrosion
(type or print) Preparer's Name and Title

 781-441-8421
Area Code and Telephone Number

 Jonathan.Pfister@nstar.com
Preparer's E-mail Address

 781-441-8436
Area Code and Facsimile Number

 Jonathan Pfister
Authorized Signature

 Jonathan Pfister
Manager, Compliance and Corrosion
(type or print) Name and Title

 2/8/08
Date

 781-441-8421
Area Code and Telephone Number

PART C - ORIGIN OF THE INCIDENT

- 1. Incident occurred on
 - Main
 - Service Line
 - Pressure Limiting and Regulating Facility
 - Meter Set
 - Other: _____
- 2. Failure occurred on
 - Body of pipe
 - Joint
 - Other: Unknown; under investigation
 - Pipe Seam
 - Component
- 3. Material involved (*pipe, fitting, or other component*)
 - Steel
 - Cast/Wrought Iron
 - Polyethylene Plastic (complete all items that apply in a-c)
 - Other Plastic (complete all items that apply in a-c)
 - Plastic failure was: a. ductile b. brittle c. joint failure
 - Other material: _____
- 4. Year the pipe or component which failed was installed: 1 / 9 / 8 / 2 /

PART D - MATERIAL SPECIFICATION (if applicable)

- 1. Nominal pipe size (NPS) 10 / 0 / . / 5 / in.
- 2. Wall thickness 10 / . / 0 / 9 / in.
- 3. Specification PE 2406 - Aldyl A SMYS / / / / / / / /
- 4. Seam type N/A
- 5. Valve type N/A
- 6. Pipe or valve manufactured by DuPont in year 1 / / / /

PART E - ENVIRONMENT

- 1. Area of incident
 - In open ditch
 - Under pavement
 - Under ground
 - Inside/under building
 - Above ground
 - Under water
 - Other: _____
- 2. Depth of cover: N/A inches

PART F - APPARENT CAUSE

Important: There are 25 numbered causes in this section. Check the box to the left of the primary cause of the incident. Check one circle in each of the supplemental items to the right of or below the cause you indicate. See the instructions for this form for guidance.

F1 - CORROSION

If either F1 (1) External Corrosion, or F1 (2) Internal Corrosion is checked, complete all subparts a - e.

1. External Corrosion

- a. Pipe Coating
 - Bare
 - Coated
 - Unknown
- b. Visual Examination
 - Localized Pitting
 - General Corrosion
 - Other: _____
- c. Cause of Corrosion
 - Galvanic
 - Improper Cathodic Protection
 - Microbiological
 - Stray Current
 - Other: _____

2. Internal Corrosion

- d. Was corroded part of pipeline considered to be under cathodic protection prior to discovering incident?
 - No
 - Yes
 - Unknown
 Year Protection Started: 1 / / / /
- e. Was pipe previously damaged in the area of corrosion?
 - No
 - Yes
 - Unknown
 How long prior to incident: 1 / / / / years 1 / / / / months

F2 - NATURAL FORCES

- 3. Earth Movement ⇒ Earthquake Subsidence Landslide Other: _____
- 4. Lightning
- 5. Heavy Rains/Floods ⇒ Washouts Flotation Mudslide Scouring Other: _____
- 6. Temperature ⇒ Thermal stress Frost heave Frozen components Other: _____
- 7. High Winds

F3 - EXCAVATION

- 8. Operator Excavation Damage (*including their contractors*) / Not Third Party
- 9. Third Party Excavation Damage (*complete a-d*)
 - a. Excavator group
 - General Public
 - Government
 - Excavator other than Operator/subcontractor
 - b. Type: Road Work Pipeline Water Electric Sewer Phone/Cable/Fiber Landowner Railroad
 - Building Construction
 - Other: _____
 - c. Did operator get prior notification of excavation activity?
 - No
 - Yes: Date received: 1 / / / / mo. 1 / / / / day 1 / / / / yr.
 Notification received from: One Call System Excavator General Contractor Landowner
 - d. Was pipeline marked?
 - No
 - Yes (*If Yes, check applicable items i - iv*)
 - i. Temporary markings: Flags Stakes Paint
 - ii. Permanent markings: Yes No
 - iii. Marks were (*check one*) Accurate Not Accurate
 - iv. Were marks made within required time? Yes No

F4 - OTHER OUTSIDE FORCE DAMAGE

- 10. Fire/Explosion as primary cause of failure ⇒ Fire/Explosion cause: Man made Natural *Describe in Part G*
- 11. Car, truck or other vehicle not relating to excavation activity damaging pipe
- 12. Rupture of Previously Damaged Pipe
- 13. Vandalism

F5 - MATERIAL OR WELDS

Material

- 14. Body of Pipe ⇒ Dent Gouge Wrinkle Bend Arc Burn Other: _____
- 15. Component ⇒ Valve Fitting Vessel Extruded Outlet Other: _____
- 16. Joint ⇒ Gasket O-Ring Threads Fusion Other: _____

Weld

- 17. Butt ⇒ Pipe Fabrication Other: _____
- 18. Fillet ⇒ Branch Hot Tap Fitting Repair Sleeve Other: _____
- 19. Pipe Seam ⇒ LF ERW DSAW Seamless Flash Weld Other: _____
- HF ERW SAW Spiral Other: _____

Complete a-f if you indicate any cause in part F5.

a. Type of failure:

- Construction Defect ⇒ Poor Workmanship Procedure not followed Poor Construction Procedures
- Material Defect

- b. Was failure due to pipe damage sustained in transportation to the construction or fabrication site? Yes No
- c. Was part which leaked pressure tested before incident occurred? Yes, complete d-f, if known No

d. Date of test: / / mo. / / day / / yr.

e. Time held at test pressure: / / hr.

f. Estimated test pressure at point of incident: _____ PSIG

F6 - EQUIPMENT OR OPERATIONS

- 20. Malfunction of Control/Relief Equipment ⇒ Valve Instrumentation Pressure Regulator Other: _____
- 21. Threads Stripped, Broken Pipe Coupling ⇒ Nipples Valve Threads Mechanical Couplings Other: _____
- 22. Leaking Seals

23. Incorrect Operation

- a. Type: Inadequate Procedures Inadequate Safety Practices Failure to Follow Procedures Other: _____
- b. Number of employees involved in incident who failed post-incident drug test: / / / Alcohol test: / / /
- c. Was person involved in incident qualified per OQ rule? Yes No d. Hours on duty for person involved: / / /

F7 - OTHER

- 24. Miscellaneous, describe: _____
- 25. Unknown
 - Investigation Complete Still Under Investigation (submit a supplemental report when investigation is complete)

PART G - NARRATIVE DESCRIPTION OF FACTORS CONTRIBUTING TO THE EVENT (Attach additional sheets as necessary)

NSTAR Gas was notified of a house fire by the Maynard Fire Department at 6:50 pm and requested to shut the gas to the building at the street. It was believed that gas may be fuelling the fire in the crawl space area of the basement. The homeowner had been using kerosene-fired torpedo heaters to thaw frozen water pipes in the crawl space, in the vicinity of the gas service piping passing through the crawl space. The fire involved timber framing and flooring adjacent to and above the heater location. The gas service piping was bare steel installed in 1911 and inserted with plastic in 1982. After the area was made safe NSTAR personnel observed bubbling from a pool of water on the dirt crawl space floor, at a threaded union in the steel casing pipe. It is unclear whether a leak in the plastic piping caused the fire or whether the fire damaged the plastic service piping, causing the leak. The service piping will be examined by an independent laboratory to determine the cause of failure

EXHIBIT 2

Photographs of Space Heaters



1. Steel service line with inserted plastic line looking from the inside meter set going through the crawl space.
2. Space heater positioned towards service line.

Heater #1 at crawl space entry



Heater #2 inside the crawl space





EXHIBIT 3

Service Line from 88 Waltham Street

NSTAR Gas Company service line recovered from 88 Waltham Street, Maynard.





Portion of gas service line recovered from crawl space of 88 Waltham Street, Maynard.

EXHIBIT 4

Operating Pressure of Service Line

IR PL 1-5 Provide records for the main on Waltham Street, including but not limited to, installation date, MAOP, leak history (over the last 2 years) and operating pressure at the time of the incident. Include in your response a description of any maintenance or replacement work on the main within the last 2 years

Response

GIS records indicate that the 2-inch steel main on Waltham Street was installed in 1924. No other records related to the main installation exist. Please see Exhibit 1-5-1. The MAOP of the main is 60 psig. Over the two years prior to the incident, two Class III leaks were found on Waltham Street, as follows:

September 11, 2006 @ Powder Mill Rd. (Leakage Control Report# 172857, Exhibit 1-5-2);

November 20, 2007 @ Hemlock Lane; recheck of previously known leak discovered (August 31, 2001. (Leak Management System Leak# 182249, Exhibit 1-5-3)

The operating pressure at the approximate time of the incident was 45 psig per the SCADA pressure log, Exhibit 1-5-4.

No maintenance or replacement work has been performed on the main on Waltham Street within the last two years

EXHIBIT 5

Maynard Fire Department Report

K1 Person / Entity Involved

Business name (if applicable) _____ Phone _____

MR **Aaron** **Jeanson**
 Prefix First Name MI Last Name Suffix

Check if same address as incident

88 **Waltham** **ST**
 Number Prefix Street or Highway Street Type Suffix

Post Office Box _____ Apt./Suite/Room _____ City **Maynard**

MA **01754**
 State Zip

K2 Owner Same as Person Involved

Business name (if applicable) _____ Phone _____

Prefix First Name MI Last Name Suffix

Check if same address as incident

Number Prefix Street or Highway Street Type Suffix

Post Office Box _____ Apt./Suite/Room _____ City _____

State Zip Insurance Co. _____ Total Insurance _____

L Remarks

Comments for this incident have been printed on an additional comments page.

M Authorization

00817	<input checked="" type="checkbox"/>	Chief	Incident C	01/04/2008
Officer in charge ID		Position or Rank	Assignment	Date
		Stephen J. Kulik		
00825	<input checked="" type="checkbox"/>	Capt.	Shift Comm	01/04/2008
Member Making Report		Position or Rank	Assignment	Date
		William H. Soar		

Maynard Fire Department

A	<u>17174</u> FDID	<u>MA</u> State	<u>01/03/2008</u> Incident Date	<u>HQ</u> Station	<u>8000016</u> Incident Number	<u>000</u> Exposure	<input type="checkbox"/> Delete <input type="checkbox"/> Change <input type="checkbox"/> No Activity	NFIRS-1 Basic
----------	----------------------	--------------------	------------------------------------	----------------------	-----------------------------------	------------------------	--	--------------------------

B Location		<input type="checkbox"/> Address on Wildland Form		Census Tract _____	
<input checked="" type="checkbox"/> Street Address	<u>88</u> Number	_____	<u>Waltham</u> Street	<u>ST</u> Type	_____
<input type="checkbox"/> Intersection	_____	_____	<u>Maynard</u> City	<u>MA</u> State	<u>01754</u> Zip Code
<input type="checkbox"/> In front of	_____	_____	_____	_____	_____
<input type="checkbox"/> Rear of	_____	_____	_____	_____	_____
<input type="checkbox"/> Adjacent to	_____	_____	_____	_____	_____
<input type="checkbox"/> Directions	Cross Street or Directions, as applicable				

C Incident Type <u>1110</u> Building Fire	E1 Dates & Times	E2 Shifts / Alarms
D Aid Given or Received	Alarm	Mon. Day Year Time <u>01/03/08</u> <u>18:21</u>
	Arrival <input checked="" type="checkbox"/> Arrival	<u>01/03/08</u> <u>18:23</u>
	Control <input checked="" type="checkbox"/> Control	<u>01/03/08</u> <u>21:30</u>
	Last Unit Clear <input checked="" type="checkbox"/> Last Unit Clear	<u>01/04/08</u> <u>00:46</u>
	_____	_____
1 <input checked="" type="checkbox"/> Received	_____	<u>1</u> <u>3</u> <u>01</u> Shift Alarms Dist.
2 <input type="checkbox"/> Automatic Rec'vd	_____	E3 Special Studies
3 <input type="checkbox"/> Given	_____	
4 <input type="checkbox"/> Automatic Given	_____	
5 <input type="checkbox"/> Other Aid Given	_____	
N <input type="checkbox"/> None	_____	
_____	_____	ID# Value
MA Only <input type="checkbox"/> Critical Incident <input type="checkbox"/> Team Mobilized <input type="checkbox"/> Circumstances _____		

F Actions Taken	G1 Resources	G2 Dollar Loss & Values
<u>11</u> Extinguish	Apparatus Personnel	LOSSES: NONE
Primary Action Taken (1)	Suppression <u>12</u> <u>0</u>	Property <u>150000</u> <input type="checkbox"/>
<u>12</u> Salvage & overhaul	EMS <u>1</u> <u>0</u>	Contents <u>75000</u> <input type="checkbox"/>
Additional Action Taken (2)	Other <u>2</u> <u>0</u>	PRE-INCIDENT VALUE
_____	<input type="checkbox"/> Check if counts include mutual aid resources	Property <u>350000</u> <input type="checkbox"/>
Additional Action Taken (3)	_____	Contents <u>100000</u> <input type="checkbox"/>

Completed Modules	H1 Casualties	H3 Hazmat Release	I Mixed Use Property
<input checked="" type="checkbox"/> Fire-2	<input checked="" type="checkbox"/> None	N <input checked="" type="checkbox"/> None	NN <input checked="" type="checkbox"/> Not Mixed
<input checked="" type="checkbox"/> Structure-3	Deaths Inj.	1 <input type="checkbox"/> Natural Gas	10 <input type="checkbox"/> Assembly Use
<input type="checkbox"/> Civ. Casualty-4	Fire Service <u>0</u> <u>0</u>	2 <input type="checkbox"/> Propane Gas	20 <input type="checkbox"/> Education Use
<input type="checkbox"/> Fire Casualty-5	Civilian <u>0</u> <u>0</u>	3 <input type="checkbox"/> Gasoline	33 <input type="checkbox"/> Medical Use
<input type="checkbox"/> EMS-6		4 <input type="checkbox"/> Kerosene	40 <input type="checkbox"/> Residential Use
<input type="checkbox"/> Hazmat-7		5 <input type="checkbox"/> Diesel Fuel/Fuel Oil	51 <input type="checkbox"/> Row of Stores
<input type="checkbox"/> Wildland-8	H2 Detector Altered Occupants	6 <input type="checkbox"/> Household Solvents	53 <input type="checkbox"/> Enclosed Mall
<input checked="" type="checkbox"/> Apparatus-9	1 <input type="checkbox"/> Yes	7 <input type="checkbox"/> Motor Oil	58 <input type="checkbox"/> Business & Resid.
<input type="checkbox"/> Personnel-10	2 <input type="checkbox"/> No	8 <input type="checkbox"/> Paint	59 <input type="checkbox"/> Office Use
<input type="checkbox"/> Arson-11	U <input checked="" type="checkbox"/> Unknown	0 <input type="checkbox"/> Other	60 <input type="checkbox"/> Industrial Use
			63 <input type="checkbox"/> Military Use
			65 <input type="checkbox"/> Farm Use
			00 <input type="checkbox"/> Other Mixed Use

1st Company to Arrive <u>E-1</u>	**Alarm 911- Tie Line	J Property Use	419 1 or 2 family dwelling
-------------------------------------	-----------------------	----------------	--------------------------------------

17174	MA	01/03/2008	HQ	8000016	000	<input type="checkbox"/> Delete	NFIRS Comments
FDID	State	Incident Date	Station	Incident Number	Exposure	<input type="checkbox"/> Change	

.We received a call on 911 reporting a Bld. Fire at 88 Waltham St. Struck Box 44 and responded with E1,E4, L1. E4 reported off with smoke showing and the occupants out of the Bld. E1 dropped a 4 inch supply line from the hydrant at Waltham and wood Ln. and proceeded to the scene . On arrival a working fire was requested. E1 advanced a 1.75 hand line into the structure to the basement where the fire originated. C10 arrived at 1823 and assumed command .E2 on arrival was told to help E1 with the fire attack. E3 on arrival stretched a second line to back up the other line. command requested a second alarm at 1831 bringing mutual aid from Acton , Stow, and Sudbury , concord covered the station. First attempts to contain the fire seemed successful but a broken gas line from the street flashed twice and command ordered the bld. evacuated and requested the gas company to respond as soon as possible. Both Nstar gas and electric responded . A Third alarm was requested at 1855 bringing a Concord and sudbury engine to the scene. The power was cut however shut down of the gas was delayed due to location of the street main. Several companies were released by command while waiting for the gas shut down. however during this aprox. 35-40 minute time frame the fire intensified and started to run the walls with the possibility of overtaking the structure. command had the dismissed companies return to the scene and interior operations resumed with the gas still leaking. Acton fire R-29 was on scene at 2049 for air supply . Operations continued and the fire was knocked down and declared under control at 2130. Salvage and overhaul continued while 2nd and 3rd alarm companies picked up. At 2208 the 1st alarm companies were dismissed with the exception of E2 which was held for detail company . The 1st alarm companies returned to quarters and were returned to service . At that time the Hudson cover company was released. Off duty members were released at 0003 and at 0046 E2 was clear from the detail and returned to Quarters and placed back in service and the off duty members released.

Equipment used 250 Ft. 4 inch supply line, 3 -1.75 inch hand lines, multiple air packs, multiple hand tools , 4 power saws, 1 30 ft. ground ladder, Generator and portable lights.

Insurance Agency Gallant and Brock 199 Great Rd. Acton Ma. 01720
Insurance Carrier Cambridge Mutual Ins. 95 Old River Rd. Andover Ma.
Policy # Hp 2525522 Effective date 8-14-07- 8-14-08
Dwelling \$214,000
Property \$107,000
Personal Liability \$ 1,000,000

The unofficial cause is the use of space heater in a confined area to thaw frozen pipes,
The official cause is still pending the outcome of the F.I.U. Investigation.

Maynard Fire Department

A	<u>17174</u> FDID	<u>MA</u> State	<u>01/03/2008</u> Incident Date	<u>HQ</u> Station	<u>8000016</u> Incident Number	<u>000</u> Exposure	<input type="checkbox"/> Delete <input type="checkbox"/> Change <input type="checkbox"/> No Activity	NFIRS-2 Fire
----------	----------------------	--------------------	------------------------------------	----------------------	-----------------------------------	------------------------	--	-------------------------

B. Property Details B1 <u>1</u> <input type="checkbox"/> Not Residential No. of residential units in building of origin B2 <u>1</u> <input type="checkbox"/> Bldgs not involved No. of buildings involved B3 <u>0</u> <input checked="" type="checkbox"/> None <input type="checkbox"/> Less than one acre Acres burned (outside fire)	C On-Site Materials or Products <input checked="" type="checkbox"/> None NNN On-site materials (1) On-site materials (2) On-site materials (3)	1 <input type="checkbox"/> Bulk storage or warehousing 2 <input type="checkbox"/> Processing or manufacturing 3 <input type="checkbox"/> Packaged goods for sale 4 <input type="checkbox"/> Repair or Service 1 <input type="checkbox"/> Bulk storage or warehousing 2 <input type="checkbox"/> Processing or manufacturing 3 <input type="checkbox"/> Packaged goods for sale 4 <input type="checkbox"/> Repair or Service 1 <input type="checkbox"/> Bulk storage or warehousing 2 <input type="checkbox"/> Processing or manufacturing 3 <input type="checkbox"/> Packaged goods for sale 4 <input type="checkbox"/> Repair or Service
--	---	--

D Ignition D1 <u>71</u> Area of origin Substructure area or space, cra D2 <u>12</u> Heat Source Radiated, conducted heat from D3 <u>17</u> Item first ignited Structural member or framing D4 <u>63</u> Type of material first ignited Sawn wood, including all finishe <input type="checkbox"/> Confined to item	E1 Cause of Ignition <input type="checkbox"/> Exposure Report 1 <input type="checkbox"/> Intentional 2 <input checked="" type="checkbox"/> Unintentional 3 <input type="checkbox"/> Failure of equipment 4 <input type="checkbox"/> Act of nature 5 <input type="checkbox"/> Cause under investigation U <input type="checkbox"/> Undetermined after invest. E2 Factors Contributing <input type="checkbox"/> None <u>12</u> Heat source too close to combustibles. Factor contributing to ignition (1) Factor contributing to ignition (2)	E3 Human Factors Contributing to Ignition 1 <input type="checkbox"/> Asleep <input checked="" type="checkbox"/> None 2 <input type="checkbox"/> Possibly impaired by alcohol or drugs 3 <input type="checkbox"/> Unattended person 4 <input type="checkbox"/> Mentally disabled 5 <input type="checkbox"/> Physically disabled 6 <input type="checkbox"/> Multiple persons 7 <input type="checkbox"/> Age was a Factor Estimated age 1 <input type="checkbox"/> Male 2 <input type="checkbox"/> Female
---	---	--

F1 Equipment Involved in Ignition <input type="checkbox"/> None <u>143</u> Heater, oil filled Equipment involved Brand _____ Model _____ Serial # _____ Year _____	F2 Equipment Power <u>11</u> Electrical line voltage (> 50 vol) Equipment Power Source F3 Equipment Portability 1 <input checked="" type="checkbox"/> Portable 2 <input type="checkbox"/> Stationary Portable equipment normally can be moved by one person, is designated to be used in multiple locations.	G Fire Suppression Factors <input checked="" type="checkbox"/> None NNN None Fire suppression factor (1) Fire suppression factor (2) Fire suppression factor (3)
---	--	--

H1 Mobile Property Involved <input checked="" type="checkbox"/> None 1 <input type="checkbox"/> Not involved in ign, burned 2 <input type="checkbox"/> Involved in ign, did not burn 3 <input type="checkbox"/> Involved in ignition and burned	H2 Mobile Property Type & Make Mobile property type _____ Mobile property make _____ Year _____ Mobile property model _____ License Plate Number _____ State _____ VIN Number _____	Local Use <input type="checkbox"/> Pre-Fire Plan Available Some of the information presented in this report may be based upon reports from other agencies: <input type="checkbox"/> Arson report attached <input type="checkbox"/> Police report attached <input type="checkbox"/> Coroner report attached <input type="checkbox"/> Other reports attached
---	---	---

Car Stolen

I1 Structure Type 1 <input checked="" type="checkbox"/> Enclosed Building 2 <input type="checkbox"/> Portable/mobile structure 3 <input type="checkbox"/> Open structure 4 <input type="checkbox"/> Air supported 5 <input type="checkbox"/> Tent 6 <input type="checkbox"/> Open platform (e.g. piers) 7 <input type="checkbox"/> Underground structure 8 <input type="checkbox"/> Connective structure 0 <input type="checkbox"/> Other type of structure	I2 Building Status 1 <input type="checkbox"/> Under construction 2 <input checked="" type="checkbox"/> Occupied & operating 3 <input type="checkbox"/> Idle, not routinely used 4 <input type="checkbox"/> Under major renovation 5 <input type="checkbox"/> Vacant and secured 6 <input type="checkbox"/> Vacant and unsecured 7 <input type="checkbox"/> Being demolished 0 <input type="checkbox"/> Other U <input type="checkbox"/> Undetermined	I3 Bldg Height _____ <u>2</u> _____ Stories at or above grade level _____ <u>1</u> _____ Stores below grade level	I4 Main Floor Size _____ <u>700</u> _____ Total square feet OR _____ <u>0</u> _____ <u>0</u> _____ Length (ft) BY Width (ft)	NFIRS-3 Structure Fire
---	--	--	--	---------------------------------------

J1 Fire Origin 1 <input checked="" type="checkbox"/> Below grade Story of Fire Origin	J3 No. of Stories Damaged by Flame Count the ROOF as part of the highest story _____ <u>1</u> _____ Number of stories w/ minor damage (1 to 24% flame damage) _____ <u>1</u> _____ Number of stories w/ significant damage (25 to 49% flame damage) _____ <u>0</u> _____ Number of stories w/ heavy damage (50 to 74% flame damage) _____ <u>0</u> _____ Number of stories w/ extreme damage (75 to 100% flame damage)	K Material Contributing Most to Flame Spread No flame spread OR same as material first ignited OR unable to determine _____ <u>10</u> _____ Structural component or finish, or item contributing most K2 63 Sawn wood, including all finished Type of material contributing most
J2 Fire Spread 2 <input type="checkbox"/> Confined to room of origin 3 <input type="checkbox"/> Confined to floor of origin 4 <input checked="" type="checkbox"/> Confined to building of origin 5 <input type="checkbox"/> Beyond building of origin		

L1 Presence of Detectors N <input type="checkbox"/> None Present 1 <input checked="" type="checkbox"/> Present U <input type="checkbox"/> Undetermined	L3 Detector Power Supply 1 <input type="checkbox"/> Battery only 2 <input type="checkbox"/> Hardwire only 3 <input type="checkbox"/> Plug in 4 <input type="checkbox"/> Hardwire with battery 5 <input type="checkbox"/> Plugin with battery 6 <input type="checkbox"/> Mechanical 7 <input type="checkbox"/> Multiple Detectors & PS 0 <input type="checkbox"/> Other _____ U <input checked="" type="checkbox"/> Undetermined	L5 Detector Effectiveness 1 <input type="checkbox"/> Alerted occupants they responded 2 <input type="checkbox"/> Occupants failed to respond 3 <input type="checkbox"/> There were no occupants 4 <input type="checkbox"/> Failed to alert occupants U <input checked="" type="checkbox"/> Undetermined
L2 Detector Type 1 <input checked="" type="checkbox"/> Smoke 2 <input type="checkbox"/> Heat 3 <input type="checkbox"/> Combination smoke - heat 4 <input type="checkbox"/> Sprinkler, water flow detection 5 <input type="checkbox"/> More than 1 type present 0 <input type="checkbox"/> Other _____ U <input type="checkbox"/> Underdetermined	L4 Detector Operation 1 <input type="checkbox"/> Fire too small to activate 2 <input checked="" type="checkbox"/> Operated 3 <input type="checkbox"/> Failed to operate U <input type="checkbox"/> Undetermined	L6 Detector Failure Reason 1 <input type="checkbox"/> Power failure, shutoff 2 <input type="checkbox"/> Improper installation or placement 3 <input type="checkbox"/> Defective 4 <input type="checkbox"/> Lack of maintenance, cleaning 5 <input type="checkbox"/> Battery missing or disconnected 6 <input type="checkbox"/> Battery discharged or dead 0 <input type="checkbox"/> Other _____ U <input type="checkbox"/> Undetermined

M1 Presence of Auto. Exting. System N <input checked="" type="checkbox"/> None Present 1 <input type="checkbox"/> Present	M3 Automatic Extinguishment System Operation 1 <input type="checkbox"/> Operated & effective 2 <input type="checkbox"/> Operated & not effective 3 <input type="checkbox"/> Fire too small to activate 4 <input type="checkbox"/> Failed to operate 0 <input type="checkbox"/> Other U <input type="checkbox"/> Undetermined	M5 Failure Reason 1 <input type="checkbox"/> System shut off 2 <input type="checkbox"/> Not enough agent 3 <input type="checkbox"/> Agent discharged but did not reach fire 4 <input type="checkbox"/> Wrong type of system 5 <input type="checkbox"/> Fire in unprotected area 6 <input type="checkbox"/> System damaged 7 <input type="checkbox"/> Lack of maintenance 8 <input type="checkbox"/> Manual intervention 0 <input type="checkbox"/> Other _____ U <input type="checkbox"/> Undetermined
M2 Type of Automatic Extinguishment 1 <input type="checkbox"/> Wet pipe sprink. 6 <input type="checkbox"/> Halogen sys 2 <input type="checkbox"/> Dry pipe sprink. 7 <input type="checkbox"/> CO2 system 3 <input type="checkbox"/> Other sprink sys 0 <input type="checkbox"/> Other system 4 <input type="checkbox"/> Dry chem. sys U <input type="checkbox"/> Undetermined 5 <input type="checkbox"/> Foam system	M4 Number of Sprinklers _____ <u>0</u> _____	

EXHIBIT 6

Depth of Main on Waltham Street



COMPANY ACTIVITY REPORT
COMPANY 200

DIG-SAFE # **20081706714** PERMIT # SHEET **1** OF **1**

ADDRESS **88 WALTHAM ST** FROM DATE **MAY 15, 19, 08** COST AREA **34310** WORK ORDER

TYPE OF WORK	JOB NUMBER	OLD SERVICE				OLD MAIN				ACCOUNTS AND SUBS
		SIZE	MATL	MIN YR PRESS	LENGTH	SIZE	MATL	MIN YR PRESS	LENGTH	
New Sew										01647587

LEAK REPORTS LEAK CLASS SOAP TESTED PRESSURE TESTED @ PSIG FOR **99 LB 17** AN OD BS BARRICADES # PLATES - NUMBER SIZE

DEPTH OF FITS: CONDITION OF PIPE: **FAIR TO POOR**


PAVING					BOD / LB.		PIPELINE				SAND, HT OR GRAVEL	LEDGE / BOULDERS			HOLES			MAN VALVES	
L	W	TH	TYPE	LOC	L	W	FOOTAGE	SIZE	MAT	PRESS	DEPTH	L	W	D	L	W	D		
6	4	4	I	ST	31	2'	55	1/2	PL	1P	2'-6"								
8	2	4	I	ST															
4	4	4	I	DRIVE															

TYPE OF PAVING TO BE PUT BACK IF DIFFERENT: DEPTH OF PAVING TO BE PUT BACK IF DIFFERENT:

REMARKS: **New Sew main to Bld.** PERSONNEL AND EQUIPMENT

EQUIPMENT & VEHICLES	NAME OR JOB TITLE	HOURS
6140	MINASIAN	
74110	DANAGHUE	
	GARDZINA	

MATERIAL	PLAS	STL	SIZE	QUAN	MATERIAL	PLAS	STL	SIZE	QUAN	MATERIAL	PLAS	STL	SIZE	QUAN
PIPE	✓		1/2	55	TEE WRO		✓	1/2	1	REDUCER				
PIPE					T.D.W. TOP					L.W. COOK				
METER FIT		✓	3/4	1	T.D.W. TEE					ELBOW				
RIBBON	✓	✓	1/2	1	EXP PLUG					CLAMP				
COUPLING	Not	✓	1/2	4	PLUG					PLUG KIT				
VALVE		✓	1/2	1	GAP					MAXI CPLNG				
WIRE				55	VALVE BOX	✓			1	FLOW LIMITER	✓		1/2	1
TAPE				55	TRNS FIT					EL. FLUMON CPLG				
POIN LOCK					AWOOD				17					



NETAR GAS/FOREMAN/SPECTOR: **GARDZINA** SUPERINTENDENT: **[Signature]** CONTRACTOR: **[Signature]** CONTRACTOR FOREMAN:

EXHIBIT 7

Service Line Installation

PIPE RUN: 2205

WALTHAM ST

MAY

INTERMEDIATE

PAR. #1 13-
1911

INSTALLED PIPE ID. 7675 RETIRED PERCENT: 100%
NEW MAIN 367' of 4.00" Uncoated Steel
Description: NORTH SIDE FROM MAIN ST TO PARKER ST

INSTALLED PIPE ID. 7676 RETIRED PERCENT: 20%
NEW MAIN 996' of 3.00" Uncoated Steel
Description: NORTH SIDE FROM PARKER ST TO HAYES ST

INSTALLED PIPE ID. 7677 RETIRED PERCENT: 2%
NEW MAIN 816' of 2.00" Uncoated Steel
Description: NORTH SIDE FROM HAYES ST TO #74

REFERENCE:

BK 7 - PG 90 / BK 8 - PG 95,119 / PLAN

#####

PAR. #2 13-
1924

INSTALLED PIPE ID. 7678
NEW MAIN 542' of 2.00" Uncoated Steel
Description: NORTH SIDE FROM #74 TO #95

REFERENCE:

SAUND. BK 10 - PG 20 / PLAN

#####

PAR. #3 13-6046 4180
1965

INSTALLED PIPE ID. 7679
NEW MAIN 782' of 2.00" Uncoated Steel
Description: NORTH SIDE FROM #95 E'RLY TO #120

REFERENCE:

BK 9 - PG 112

#####

PAR. #4 13-8500
1973

INSTALLED PIPE ID. 7680
NEW MAIN 744' of 2.00" Coated Steel
Description: SOUTH SIDE FROM #120 E'RLY TO DUMPSIDE GARDEN APTS.

1975 ±
618' OF 2" IP Running behind #'s 141 → 145
188' OF 2" IP Running behind #'s 145 & 147
(stage coach Apt's)

ORIGINAL

Distribution Record

Street & No. **88 Waltham St., Maynard** Tax District **122.04.2-86125** Service Order **Nº 2737**
 Name-Owner
 Address-Owner
 Name-Occupant **Joseph Congami** Date **8/24/49**
 Service-New Relay

COST SUMMARY			GAS MATERIAL	Size or Number	Private Property	Public Property	Cost Unit	COST Private Property	COST Public Property
Public	Private								
Material			Pipe-Ft.	1"		2			
Labor			"	3/4"		2			
Car Checks			" <i>g.d. pipes</i>	5"		2			OBsolete INFO
Auto			Caps	2 1/4"		1			THIS DATA ON
Compressor			"						
Total Direct			Elbows	1" x 3/4"		1			<i>Traced</i>
SERVICE DATA			Gate						
Main to St. Line	17	0	" Box	7'		1			(115)
St. Line to Bldg.	4	0	Stop Clock	1"		1			
<i>P.P.C.</i> Total	21	0	Plugs						
CHARGE CUSTOMER			"						
Min. Charge	<i>No charge</i>		Nipples	3/4" x 2"		3			
Excess Ft.			"						
Amount			Tees	3/4"		1			
Abandoned	<i>21.17 3/4 pipes</i>		"						
Ft. @	<i>laid back 1918</i>		Unions						
			<i>Deerover Compling</i>	3/4" x 1 1/2"		1			*MY05260*
			<i>Compling</i>	1" x 3/4"		1			
			TOTALS						

Service from **2" H.P. " Main on South Waltham St** **6-24** 19**49** By **cook**
 COMPLETED
 CA-21C-15T

IR PL 1-6 Provide records for the service line to 88 Waltham Street, including but not limited to: installation date, line size, material, pressure, number of meters, service line leak history and maintenance history of company owned property (meters, regulators, piping)

Response

Records indicate the original $\frac{3}{4}$ inch bare steel service was installed in 1911 (Exhibit 1-6-1). A 21-foot section was relayed with 1-inch bare steel on August 24, 1949 (Exhibit 1-6-2). On February 5, 1982 the entire service was inserted with $\frac{1}{2}$ inch plastic (Exhibit 1-6-3).

At the time of the incident there were two meters at 88 Waltham St. The second meter was installed in 2000 (Service Call Management system service record, Exhibit 1-6-4) and was shut off on October 23, 2006 at the request of the customer (Service Call Management system service record, Exhibit 1-6-5; Gas Mobile-Work Order History Report, Exhibit 1-6-6).

The Company has no record of service leaks at 88 Waltham St. The Company performed a seven-year meter exchange on June 13, 2003 (Exhibit 1-6-7).

EXHIBIT 8

Department Notification of the Incident

Stevens, William (DPU)

From: Stevens, William (DPU)
Sent: Wednesday, January 09, 2008 8:54 AM
To: Bourne, Christopher (DPU)
Subject: 88 Waltham Street, Maynard, MA- Jan. 3, 2008 Incident?

Chris,

I just got a call from Tim Delaney, 603-819-3191 from EFI investigators. He reported that around 6 p.m. January 3, 2008, a "gas related" fire at 88 Waltham Street, Maynard, MA - a two story and single family house. Tim reported that there is about a 30 foot gas line running inside the house, before the meter. Part of the line passes through a small crawl space (before the meter). There was an ignition, and there is house fire damage where the crawlspace was.

Tim stated that a witness saw a flash in the crawl space. The Fire Department vented the gas by cutting a hole in the floor. Tim also reported that there was a second flash. NSTAR has the meters, and Tim reported that NSTAR is doing work on the premises in the driveway.

Tim reported that NSTAR has the materials and wondered whether there would be any testing of the pipes.

William Stevens
Assistant General Counsel
Pipeline Engineering and Safety Division
Commonwealth of Massachusetts
Department of Public Utilities
One South Station
Boston, MA 02110
tel 617.305.3620
fax 617.345.9103

Privileged, confidential, protected communication for the intended recipient only

EXHIBIT 9

Leak Survey Prior to Incident

IR PL 1-9 Provide the date and results of the last leakage survey of the mains and the gas service to 88 Waltham Street, conducted prior to the incident. Provide the date and results of the last atmospheric corrosion survey of the exposed service line.

Response

Prior to the incident, a mobile leakage survey was last conducted on the main on Waltham Street in the area of the incident on March 6, 2007. There were no leaks found during the mobile survey.

Services in the Town of Maynard were scheduled for walking survey in 2005 and the Company is currently searching its archives to attempt to locate the records of those surveys.

EXHIBIT 10

Post-Incident Leak Survey

IR PL 1-10 Provide the date and results of the leakage survey conducted after the incident.

Response

A walking leakage survey was conducted on the service piping at 88 Waltham Street on January 11, 2008. Gas readings ranged from 1% gas to 3% gas at the building foundation and 10% gas a short distance from the foundation in the vicinity of the 90-degree bend in the service. In the street, a reading of 10% gas was observed at the main. The leak was referred to gas distribution as a Class I leak at 2:05 pm on January 11, 2008 (Special Request Survey form dated 1-11-08, Exhibit 1-10-1; Leakage Control Report # 182263, Exhibit 1-10-2).

A walking leakage survey was conducted over the main and services on Waltham Street between Third Street and Wood Lane on January 17, 2008. Two class III leaks were discovered during that survey (Special Request survey form dated 1-17-08, Exhibit 1-10-3):

92 Waltham Street (Leakage Control Report # 181393, Exhibit 1-10-4);


Waltham Street @ First Street (Leakage Control Report # 181392, Exhibit 1-10-5)

EXHIBIT 11


Photographs of Incident Site and Residence



Location of Meter set in basement.



Service line and shutoff located in original basement entering from crawl space.



Threaded coupling where gas may have escaped



88 Waltham Street



Space heater used in crawl space