W. Scott Randolph Director - Regulatory Affairs



Verizon Communications 1300 I Street, NW Suite 500E Washington, DC 20005 Phone: 202 515-2530 Fax: 202 336-7922 srandolph@verizon.com

June 13, 2001

Bruce A. Franca
Acting Chief, Office of Engineering and Technology
Federal Communications Commission
445 Twelfth Street, S.W.
7-C153
Washington, DC 20554

RE: Final Service Disruption Report for May 14, 2001 Event

Dear Mr. Franca,

In accordance with the outage reporting thresholds established in CC Docket 91-273, we are enclosing Verizon's Final Service Disruption Report for the outage affecting the Taunton, MA area on May 14, 2001.

If you have any questions regarding this matter, please call me at (202) 515-2530.

Sincerely,

W. Scott Randolph

Director - Regulatory Affairs

**Enclosure** 

cc:

R. Kimball

K. Nilsson

## WIRE LINE OUTAGE REPORT

Reporting Carrier	Date of Incident			
Verizon	05/14/2001			
Time of Incident	Geographic Area Affected			
10:42 AM EDT	Taunton, MA			
Services Affected	Number of Customers Affected			
Tutural ATTA Tutura (Can	Approximately 60, 200			
IntraLATA Intraoffice	Number of Blocked Calls			
IntraLATA Interoffice X	157,906			
InterLATA Interoffice X	Outage Duration			
E911 X	46,600 lines for Taunton area for 1 Hr 26 Mins			
	13,600 lines for Norton area for 3 Hrs 38 Mins			
Background of the Incident				
On Monday May 14, 2001 at 1042 hours, working fiber optic jumper cables were mistakenly cut in the Taunton (TNTNMAPL***), Massachusetts Central Office (CO) by a Verizon Equipment Installation crew. The cut jumpers caused both the working and protect sides of two fiber systems to fail. One system between Taunton and Brockton carried 24 T3s and the second system between Taunton and Norton carried 7 T3s.  An Equipment Installation job to remove obsolete fiber optic multiplexers began in March, 2001. In April, the CO Engineer added work items to the removal job to relieve congestion in the fiber trough. The Equipment Installation group never issued a revised Method of Procedure detailing this additional work. Without the revised MOP detailing the proper procedures and tools for this work activity, the technician mistakenly cut working fiber optic jumpers which connect the multiplexers in the CO.				
Technicians were dispatched to both the Taunton and Norton COs. Upon arrival in Taunton, the technicians identified the cut fiber jumpers and requested replacements. By 1208 hours, the 24 T3s to Brockton were restored and by 1420 hours, the remaining 7 T3s to Norton were restored. During this disruption, some customers in Southeastern Massachusetts attempting to call 911 would have reached a fast busy until calls were rerouted to the secondary E911 tandem at 1351.				
Direct Cause Procedural- Service Provider- Failure to follow standard procedures/documentation				
Root Cause				
Procedural- Service Provider- Insufficient supervision/control				
Name and Type of Equipment	Specific Part of the Network Involved			
Alcatel Fiber Optic Multiplexers	Interoffice Facilities			
Methods Used to Restore Service				
Fiber Optic Jumpers were run to restore service temporarily.				

Steps Taken to Prevent Recurrence of the Incident

- The Verizon Equipment Installation issued a Flash notification for personnel to review existing MOPs for compliance with the Safetime Practice
- The Verizon Equipment Installation will issue a Bulletin highlighting the requirements for detailed MOPs, procedures for removing fiber cables, appropriate notification procedures and Safetime policy
- The Verizon Equipment Installation Managers will review the above mentioned Bulletin and Installation Practices with all technicians at face-to face meetings.

Evaluation of Best Practices

PR03: MOPs and Acceptance/Verification Check-Off Sheets for Hardware and Software Growth/Change Activities

Contact Person	Telephone Number of Contact Person
William S. Randolph	202-515-2530

01-062

## VERIZON FCC NETWORK DISRUPTION INITIAL REPORT

TICKET #: ARQ-IF4

		05/14/2001	10:45:00 AM TNTNMAPL***			
2.	GEOGRAPHIC AREA AFFECTED: TECHEN,	, MA	111111111111111111111111111111111111111			
3.	MAXIMUM NUMBER OF CUSTOMERS AFF	ECTED: 50,000				
4.	TYPE OF SERVICES AFFECTED:					
	ERGENCY-SERVICE 🔀 INTERLATA PRALATA 🔲 800 SERVICES	OTHER				
5.	DURATION OF OUTAGE: 01:25:00					
6.	ESTIMATED NUMBER OF BLOCKED CAL		VENDOR:			
7A	TYPE EQUIPMENT: Fiber - Non Sone	et Equipment	AEUDON:			
7B.	APPARENT OR KNOWN CAUSE OF INCID					
8.	METHOD USED TO RESTORE SERVICE: Not available at this time					
9.	STEPS TAKEN TO PREVENT RECURRENT Not available at this time		entforth helow.			
confi	uant to Section 0,459 (b) of the Commission dentiality is requested for items: on for confidentiality:			viii be submitted		
□ A F	con for confidentiality.  Request to supplement the showing request ditiously.	ied by section 0.438 (E	) is timeny made and			
-	uast Supplement:	10.00 514		•		
DAT	E AND TIME OF REPORT: 05/14/2001	12:42:36 PM				
CON	ITACT AND TELEPHONE #: Michael Pearce	800-400-4662				
NOTE: Retention period is 6 Years						