

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME	INSPECTION DATE	
OUTLET WORKS - removed/inoperable		
AREA INSPECTED	CONDITION	OBSERVATIONS
TYPE		Unknown - no longer in place/in service
INTAKE STRUCTURE		N/O, possibly replaced by U/S wall
TRASHRACK		N/D
PRIMARY CLOSURE		N/O
SECONDARY CLOSURE		N/O
CONDUIT		N/O
OUTLET STRUCTURE/HEADWALL		N/O; rapids/boulders at probable former outlet channel
OUTLET WORKS		
EROSION ALONG TOE OF DAM		N/O
SEEPAGE/LEAKAGE		N/O
DEBRIS/BLOCKAGE		N/O
UNUSUAL MOVEMENT		N/O
DOWNSTREAM AREA		rock lined channel leading back to main channel/slow fall/race
MISCELLANEOUS		
ADDITIONAL COMMENTS:		

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

Potential Recommendation Notes

Removal?

unlikely

Breach/Spillway Adjustments?

N/A

Repurposing?

possible if gates added to spillway

Fish/eel passage?

little room for fish ladder - possible past location  
of outlet works or up side of aux Spillway?

Notes:

work completed on dam w/in last 5 years; concrete clearly new

possible gatehouse/sauna/powerhouse left side of dam

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**PHOTOS**

**PHOTOGRAPHS INSTRUCTION PAGE:**

*All photographs shall be color photographs. Photographs shall be clear and include scale references where applicable. Photographs shall include, but not be limited to the following:*

1. *Overview of dam from upstream*
2. *Overview of dam from downstream*
3. *Overview of upstream face from right abutment*
4. *Overview of upstream face from left abutment*
5. *Overview of dam crest from right abutment*
6. *Overview of dam crest from left abutment*
7. *Overview of downstream face from right abutment*
8. *Overview of downstream face from left abutment*
9. *Overview of spillway from upstream*
10. *Overview of spillway from downstream (tailrace or channel area)*
11. *Overview of right training wall*
12. *Overview of left training wall*
13. *Overview of weir*
14. *Overview of stilling basin*
15. *Overview of downstream channel*
16. *Overview of gatehouse exterior*
17. *Overview of gatehouse interior*
18. *Overview of operators*
19. *Outlet inlets and discharge points*
20. *Overview of reservoir*
21. *Areas of specific deficiencies (e.g., cracks, erosion, displacement, seeps, deterioration, etc.)*

*Each photograph shall include a caption indicating the subject of the photograph as well as highlighting any specific deficiencies pictured. All photographs shall be presented with no more than two (2) photos per page. Photo location and orientation shall be indicated on the site plan included in the section entitled "Figures". Alternatively, for clarity, a separate figure can be provided in this appendix to show figure locations.*

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**SKETCH**

Sketch of the dam site showing the dam structure, foundation, and surrounding terrain. The sketch includes a north arrow and elevation markers.



The sketch depicts a dam structure with a foundation and embankment. The foundation appears to be a rectangular area with some internal features. The embankment rises from the foundation. The surrounding terrain is shown with various lines and shading to indicate slope and vegetation. A north arrow is located in the upper left corner of the sketch area. Elevation markers are present along the right side of the sketch, indicating different levels or heights of the terrain and the dam structure.

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

**DAM SAFETY INSPECTION**

NAME OF DAM: <u>Muzzy Meadow Dam</u>		STATE ID #:
AKA NAME:		WATERCOURSE NAME:
<u>DAM LOCATION INFORMATION</u>		
CITY/TOWN:	<u>Spencer</u>	LAT. / LONG.:
STATE:	<u>MA</u>	HAZARD CLASS:
<u>GENERAL DAM INFORMATION</u>		
TYPE OF DAM:	<u>earth</u>	
PURPOSE OF DAM:	<u>recreation, aesthetics; future skating, walking trail?</u>	
YEAR BUILT:		
<u>INSPECTION SUMMARY</u>		
DATE OF INSPECTION:	<u>11/27/18</u>	NAME OF INSPECTOR: <u>RLW</u>
TIME OF INSPECTION:	<u>1:25 PM</u>	OTHER ATTENDEES: <u>HF, PD</u>
WEATHER CONDITIONS:	<u>Sunny, partly cloudy</u> <u>40°F breezy</u>	
<u>GENERAL DAM DATA</u>		
PRIMARY SPILLWAY TYPE:	<u>0</u>	AUXILIARY SPILLWAY TYPE: <u>1</u>
NUMBER OF OUTLETS:	<u>1</u>	TYPE OF OUTLETS: <u>concrete culvert</u>
HAS THE DAM BEEN BREACHED OR OVERTOPPED?	<u>Unknown</u>	
IS THERE A FISH LADDER? (LIST TYPE IF PRESENT)	<u>NO</u>	
DOES THE CREST SUPPORT A PUBLIC ROAD?	<u>NO</u>	
ROADS/DRIVEWAY IMMEDIATELY DOWNSTREAM OF DAM?	<u>Maple St/ Rte 31</u>	
ACCESS CONDITIONS TO THE SITE:	<u>Walk/drive; No recreation access</u>	
SECURITY DEVICES?	<u>gate on chain link fence around outlet</u>	

*gabway project  
D/S buried*

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT





DAM NAME		INSPECTION DATE	
EMBANKMENT (CREST)			
AREA INSPECTED	CONDITION	OBSERVATIONS	
CREST	SURFACE TYPE	earth w/ grass	
	SURFACE CRACKING	N/A	
	SINKHOLES, ANIMAL BURROWS	N/A - but possible	
	VERTICAL ALIGNMENT (DEPRESSIONS)	minor undulation	
	HORIZONTAL ALIGNMENT	good	
	RUTS AND/OR PUDDLES	N/A	
	VEGETATION (PRESENCE/CONDITION)	mowed grass; some minor erosion; trees/shrub/s fence at right about	
	ABUTMENT CONTACT	good	
	CONDITION OF JOINTS (CONCRETE)	N/A	
	ADDITIONAL COMMENTS:	no damage to bridge roadway + bridge deck	

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
DOWNSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
D/S WALLS	1. WALL TYPE	
	2. WALL ALIGNMENT	
	3. WALL CONDITION	
	4. HEIGHT: TOP OF WALL TO MUDLINE	min: / max: 
	5. SEEPAGE OR LEAKAGE	
	6. ABUTMENT CONTACT	
	7. EROSION/SINKHOLES BEHIND WALL	
	8. ANIMAL BURROWS	
	9. UNUSUAL MOVEMENT	
	10. WET AREAS AT TOE OF WALL	
	11. VEGETATION	
	12. SCOUR/EROSION AT BASE OF WALL	
ADDITIONAL COMMENTS:		

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE
UPSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
1. WALL TYPE		
2. WALL ALIGNMENT		
3. WALL CONDITION		
4. HEIGHT: TOP OF WALL TO MUDLINE	min:	max: avg:
5. ABUTMENT CONTACT		
U/S WALLS	6. EROSION/SINKHOLES BEHIND WALL	
	7. ANIMAL BURROWS	
	8. UNUSUAL MOVEMENT	
	9. VEGETATION	
	10. SCOUR/EROSION AT BASE OF WALL	
	ADDITIONAL COMMENTS:	

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT



DAM NAME	INSPECTION DATE	
DOWNSTREAM AREA		
AREA INSPECTED	CONDITION	OBSERVATIONS
D/S AREA	ABUTMENT LEAKAGE	N/b
	FOUNDATION SEEPAGE	N/D
	SLIDE, SLOUGH, SCARP	N/D
	WEIRS	N/D
	DRAINAGE SYSTEM	N/T
	INSTRUMENTATION	N/b
	VEGETATION	N/o
	ACCESSIBILITY	highly access - major road
	DOWNSTREAM HAZARD DESCRIPTION	maple st connecting streets, homes + businesses
	ADDITIONAL COMMENTS:	WATER

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
PRIMARY SPILLWAY			
AREA INSPECTED	CONDITION	OBSERVATIONS	
SPILLWAY TYPE			
WEIR TYPE			
SPILLWAY CONDITION			
TRAINING WALLS			
SPILLWAY CONTROLS AND CONDITION			
UNUSUAL MOVEMENT			
APPROACH AREA			
DISCHARGE AREA			
DEBRIS			
WATER LEVEL AT TIME OF INSPECTION			
ADDITIONAL COMMENTS:			
Signature _____ Date _____			

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
AUXILIARY SPILLWAY			
AREA INSPECTED	CONDITION	OBSERVATIONS	
SPILLWAY TYPE			
WEIR TYPE			
SPILLWAY CONDITION			
TRAINING WALLS			
SPILLWAY CONTROLS AND CONDITION			
UNUSUAL MOVEMENT			
APPROACH AREA			
DISCHARGE AREA			
DEBRIS			
WATER LEVEL AT TIME OF INSPECTION			
ADDITIONAL COMMENTS:  WWD			

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME	MND	INSPECTION DATE
OUTLET WORKS		
AREA INSPECTED	CONDITION	OBSERVATIONS
TYPE	<u>concrete</u>	
INTAKE STRUCTURE	<u>concrete</u>	
TRASHRACK	yes - poor condition; bent/deformed	
PRIMARY CLOSURE	gate - iron; unknown condition	
SECONDARY CLOSURE		
CONDUT	unknown	
OUTLET STRUCTURE/HEADWALL	unknown - stream buried	
EROSION ALONG TOE OF DAM	N/O; erosion along sides of outlet structure	
SEEPAGE/LEAKAGE	N/O	
DEBRIS/BLOCKAGE	leaves in trash rack; garbage visible under water	
UNUSUAL MOVEMENT	N/O	
DOWNSTREAM AREA		
MISCELLANEOUS		
ADDITIONAL COMMENTS:	water very dark - unable to see gate condition or debris extent + underwater; some flow in approach area & audible in structure	

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

Potential Recommendation Notes

**Removal?**

No - town planner hopes to complete gateway project @ pond - limited space but highly visible

**Breach/Spillway Adjustments?**

Possible daylighting project

**Repurposing?**

No - not enough height

**Fish/eel passage?**

N/A - No downstream outlet to connect

**Notes:**

Problem w/public throwing dog waste into pond  
- pet waste signs posted nearby

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**PHOTOS**

**PHOTOGRAPHS INSTRUCTION PAGE:**

*All photographs shall be color photographs. Photographs shall be clear and include scale references where applicable. Photographs shall include, but not be limited to the following:*

1. *Overview of dam from upstream*
2. *Overview of dam from downstream*
3. *Overview of upstream face from right abutment*
4. *Overview of upstream face from left abutment*
5. *Overview of dam crest from right abutment*
6. *Overview of dam crest from left abutment*
7. *Overview of downstream face from right abutment*
8. *Overview of downstream face from left abutment*
9. *Overview of spillway from upstream*
10. *Overview of spillway from downstream (tailrace or channel area)*
11. *Overview of right training wall*
12. *Overview of left training wall*
13. *Overview of weir*
14. *Overview of stilling basin*
15. *Overview of downstream channel*
16. *Overview of gatehouse exterior*
17. *Overview of gatehouse interior*
18. *Overview of operators*
19. *Outlet inlets and discharge points*
20. *Overview of reservoir*
21. *Areas of specific deficiencies (e.g., cracks, erosion, displacement, seeps, deterioration, etc.)*

*Each photograph shall include a caption indicating the subject of the photograph as well as highlighting any specific deficiencies pictured. All photographs shall be presented with no more than two (2) photos per page. Photo location and orientation shall be indicated on the site plan included in the section entitled "Figures". Alternatively, for clarity, a separate figure can be provided in this appendix to show figure locations.*

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

SKETCH



**Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan**  
**VISUAL DAM ASSESSMENT**

**DAM SAFETY INSPECTION**

NAME OF DAM:	<u>Cranberry Meadow</u> <i>Pond Dam</i>		STATE ID #:	
AKA NAME:				
<b>DAM LOCATION INFORMATION</b>				
CITY/TOWN:	<u>Spencer</u>	LAT. / LONG.:		
STATE:	<u>MA</u>	HAZARD CLASS:		
<b>GENERAL DAM INFORMATION</b>				
TYPE OF DAM:	<u>Earth</u>			
PURPOSE OF DAM:	<u>Recreation - lake houses, swimming, boating (motor? + non)</u>			
YEAR BUILT:				
<b>INSPECTION SUMMARY</b>				
DATE OF INSPECTION:	<u>11/29/18</u>	NAME OF INSPECTOR:	<u>RLW</u>	
TIME OF INSPECTION:	<u>8:36 AM</u>	OTHER ATTENDEES:	<u>HF, PD</u>	
WEATHER CONDITIONS:	<u>Sunny, few clouds, 36°F, windy</u>			
<b>GENERAL DAM DATA</b>				
PRIMARY SPILLWAY TYPE:	<u>concrete ramp</u>	AUXILIARY SPILLWAY TYPE:	<u>/</u>	
NUMBER OF OUTLETS:	<u>/</u>	TYPE OF OUTLETS:	<u>/</u>	
HAS THE DAM BEEN BREACHED OR OVERTOPPED?	<u>Unknown</u>			
IS THERE A FISH LADDER? (LIST TYPE IF PRESENT)	<u>No</u>			
DOES THE CREST SUPPORT A PUBLIC ROAD?	<u>No</u>			
ROADS/DRIVEWAY IMMEDIATELY DOWNSTREAM OF DAM?	<u>Yes - Cranberry Meadow Road</u>			
ACCESS CONDITIONS TO THE SITE:	<u>drive-up; <del>no</del> informal</u>			
SECURITY DEVICES?	<u><del>None</del>; Posted "Private Property"; Gate on right side</u>			

*of bridge across spillway*

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
EMBANKMENT (CREST)			
AREA INSPECTED	CONDITION	OBSERVATIONS	
CREST	SURFACE TYPE	eastern	
	SURFACE CRACKING	n/a	
	SINKHOLES, ANIMAL BURROWS	n/a	
	VERTICAL ALIGNMENT (DEPRESSIONS)	good/n/a	
	HORIZONTAL ALIGNMENT	good	
	RUTS AND/OR PUDDLES	n/a	
	VEGETATION (PRESENCE/CONDITION)	grass, mowed; small trees + brush on edges	
	ABUTMENT CONTACT	good	
	CONDITION OF JOINTS (CONCRETE)	n/a	
ADDITIONAL COMMENTS:		<p><i>Bridge over top of spillway post of no trespassing</i></p> <p>- could NOT access left abutment</p>	
<i>Spillway</i>			

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
DOWNSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
D/S WALLS	1. WALL TYPE	Masonry; unsure if mortared (appears not), per. capped w/ timbers
	2. WALL ALIGNMENT	poor -
	3. WALL CONDITION	poor - see align, etc.
	4. HEIGHT: TOP OF WALL TO MUDLINE	min: NO Access max:
	5. SEEPAGE OR LEAKAGE	Yes - visible at base; possible but covered by debris above
	6. ABUTMENT CONTACT	good - left; unknown - right
	7. EROSION/SINKHOLES BEHIND WALL	unable to observe
	8. ANIMAL BURROWS	unable to observe
	9. UNUSUAL MOVEMENT	yes - see 5
	10. WET AREAS AT TOE OF WALL	brush, grass
	11. VEGETATION	unable to observe
	12. SCOUR/EROSION AT BASE OF WALL	
ADDITIONAL COMMENTS:		Wall covered by debris
		GND

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	EMPI	INSPECTION DATE
UPSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
1. WALL TYPE		
2. WALL ALIGNMENT		
3. WALL CONDITION		
4. HEIGHT: TOP OF WALL TO MUDLINE	min:	max: avg:
5. ABUTMENT CONTACT		
6. EROSION/SINKHOLES BEHIND WALL		
U/S WALLS		
7. ANIMAL BURROWS		
8. UNUSUAL MOVEMENT		
9. VEGETATION		
10. SCOUR/EROSION AT BASE OF WALL		
ADDITIONAL COMMENTS:		
INITIALS: [initials]		
DATE: [date]		
REMARKS: [initials]		

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
DOWNSTREAM AREA		
AREA INSPECTED	CONDITION	OBSERVATIONS
	ABUTMENT LEAKAGE	unable to observe
	FOUNDATION SEEPAGE	N/A
	SLIDE, SLOUGH, SCARP	yes - steep slopes, somewhat slab by veg & debris
	WEIRS	N/A
	DRAINAGE SYSTEM	N/A
	INSTRUMENTATION	N/A
	VEGETATION	small trees, shrubs
	ACCESSIBILITY	difficult walking - steep slopes
	DOWNSTREAM HAZARD DESCRIPTION	Cranberry Meadow flood crosses tailwater
	ADDITIONAL COMMENTS:	

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	CMPD	INSPECTION DATE
PRIMARY SPILLWAY		
AREA INSPECTED	CONDITION	OBSERVATIONS
SPILLWAY TYPE	Concrete chute	
WEIR TYPE	wooden weir boards; leaking three	
SPILLWAY CONDITION	good; minor cracking in walls, outlet training walls <del>gaps</del> scored, scored 2' of	
④ TRAINING WALLS	minor cracking, minor aggregate exposure small score tally 2' behind each	
SPILLWAY CONTROLS AND CONDITION	weir board - appear old, start early rot	
UNUSUAL MOVEMENT	N/A	
APPROACH AREA	clear,	
DISCHARGE AREA	rocky tailwater, small scour pool	
DEBRIS	small sticks & leaves against weir board	
WATER LEVEL AT TIME OF INSPECTION	6" below weir board; 0.3 ft over spillway	
ADDITIONAL COMMENTS:		
④ bridge directly over weir boards - provides foot & small vehicle likely lawn mower, atv) access / lattice gate in foot	bridge	directly over weir boards - provides foot & small vehicle likely lawn mower, atv) access / lattice gate in foot
④ erosion behind training walls		

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
 VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE		
AUXILIARY SPILLWAY			
AREA INSPECTED	CONDITION	OBSERVATIONS	
	SPILLWAY TYPE		
	WEIR TYPE		
	SPILLWAY CONDITION		
	TRAINING WALLS		
	SPILLWAY CONTROLS AND CONDITION		
	UNUSUAL MOVEMENT		
SPILLWAY	APPROACH AREA		
	DISCHARGE AREA		
	DEBRIS		
	WATER LEVEL AT TIME OF INSPECTION		
	ADDITIONAL COMMENTS:		
	GROUT		

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME		INSPECTION DATE	
OUTLET WORKS			
AREA INSPECTED	CONDITION	OBSERVATIONS	
TYPE			
INTAKE STRUCTURE			
TRASHRACK			
PRIMARY CLOSURE			
SECONDARY CLOSURE			
CONDUIT			
OUTLET STRUCTURE/HEADWALL			
OUTLET WORKS			
EROSION ALONG TOE OF DAM			
SEEPAGE/LEAKAGE			
DEBRIS/BLOCKAGE			
UNUSUAL MOVEMENT			
DOWNSTREAM AREA			
MISCELLANEOUS			
ADDITIONAL COMMENTS:			

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

Potential Recommendation Notes

Removal? Lake assoc., private properties along shore

Breach/Spillway Adjustments?

Add ~~outlet~~ outlet to allow drawdown



Repurposing?

Insufficient height flexibility due to properties, embankment height to raise embankment

Drawdown pass.

Fish/eel passage?

Fish ladder or natural passage

↑ would be tight

Notes:

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**PHOTOS**

**PHOTOGRAPHS INSTRUCTION PAGE:**

*All photographs shall be color photographs. Photographs shall be clear and include scale references where applicable. Photographs shall include, but not be limited to the following:*

1. *Overview of dam from upstream*
2. *Overview of dam from downstream*
3. *Overview of upstream face from right abutment*
4. *Overview of upstream face from left abutment*
5. *Overview of dam crest from right abutment*
6. *Overview of dam crest from left abutment*
7. *Overview of downstream face from right abutment*
8. *Overview of downstream face from left abutment*
9. *Overview of spillway from upstream*
10. *Overview of spillway from downstream (tailrace or channel area)*
11. *Overview of right training wall*
12. *Overview of left training wall*
13. *Overview of weir*
14. *Overview of stilling basin*
15. *Overview of downstream channel*
16. *Overview of gatehouse exterior*
17. *Overview of gatehouse interior*
18. *Overview of operators*
19. *Outlet inlets and discharge points*
20. *Overview of reservoir*
21. *Areas of specific deficiencies (e.g., cracks, erosion, displacement, seeps, deterioration, etc.)*

*Each photograph shall include a caption indicating the subject of the photograph as well as highlighting any specific deficiencies pictured. All photographs shall be presented with no more than two (2) photos per page. Photo location and orientation shall be indicated on the site plan included in the section entitled "Figures". Alternatively, for clarity, a separate figure can be provided in this appendix to show figure locations.*

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**SKETCH**



Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM SAFETY INSPECTION

NAME OF DAM:	<u>Lake Whittmore Dam</u>	STATE ID #:	
AKA NAME:		WATERCOURSE NAME:	
<u>DAM LOCATION INFORMATION</u>			
CITY/TOWN:	<u>Spencer, MA</u>	LAT. / LONG.:	
STATE:		HAZARD CLASS:	
<u>GENERAL DAM INFORMATION</u>			
TYPE OF DAM:	<u>earth</u>		
PURPOSE OF DAM:	<u>recreation</u>		
YEAR BUILT:			
<u>INSPECTION SUMMARY</u>			
DATE OF INSPECTION:	<u>11/29/18</u>	NAME OF INSPECTOR:	<u>RLW</u>
TIME OF INSPECTION:	<u>12:00</u>	OTHER ATTENDEES:	<u>NF, PD</u>
WEATHER CONDITIONS:	<u>39°F, cloudy, breezy/windy</u>		
<u>GENERAL DAM DATA</u>			
PRIMARY SPILLWAY TYPE:	<u>concrete, ogee</u>	AUXILIARY SPILLWAY TYPE:	<u>/</u>
NUMBER OF OUTLETS:	<u>1</u>	TYPE OF OUTLETS:	<u>2</u>
HAS THE DAM BEEN BREACHED OR OVERTOPPED?	<u>unknown</u>		
IS THERE A FISH LADDER? (LIST TYPE IF PRESENT)	<u>No</u>		
DOES THE CREST SUPPORT A PUBLIC ROAD?	<u>No</u>		
ROADS/DRIVEWAY IMMEDIATELY DOWNSTREAM OF DAM?	<u>yes -</u>		
ACCESS CONDITIONS TO THE SITE:	<u>walk through private property</u>		
SECURITY DEVICES?	<u>gate + chain link fence around outlet</u>		

TYPE	DESCRIPTION	NOTES	TYPE	DESCRIPTION	NOTES
1			2		
3			4		
5			6		
7			8		
9			10		
11			12		
13			14		
15			16		
17			18		
19			20		
21			22		
23			24		
25			26		
27			28		
29			30		
31			32		
33			34		
35			36		
37			38		
39			40		
41			42		
43			44		
45			46		
47			48		
49			50		
51			52		
53			54		
55			56		
57			58		
59			60		
61			62		
63			64		
65			66		
67			68		
69			70		
71			72		
73			74		
75			76		
77			78		
79			80		
81			82		
83			84		
85			86		
87			88		
89			90		
91			92		
93			94		
95			96		
97			98		
99			100		
101			102		
103			104		
105			106		
107			108		
109			110		
111			112		
113			114		
115			116		
117			118		
119			120		
121			122		
123			124		
125			126		
127			128		
129			130		
131			132		
133			134		
135			136		
137			138		
139			140		
141			142		
143			144		
145			146		
147			148		
149			150		
151			152		
153			154		
155			156		
157			158		
159			160		
161			162		
163			164		
165			166		
167			168		
169			170		
171			172		
173			174		
175			176		
177			178		
179			180		
181			182		
183			184		
185			186		
187			188		
189			190		
191			192		
193			194		
195			196		
197			198		
199			200		
201			202		
203			204		
205			206		
207			208		
209			210		
211			212		
213			214		
215			216		
217			218		
219			220		
221			222		
223			224		
225			226		
227			228		
229			230		
231			232		
233			234		
235			236		
237			238		
239			240		
241			242		
243			244		
245			246		
247			248		
249			250		
251			252		
253			254		
255			256		
257			258		
259			260		
261			262		
263			264		
265			266		
267			268		
269			270		
271			272		
273			274		
275			276		
277			278		
279			280		
281			282		
283			284		
285			286		
287			288		
289			290		
291			292		
293			294		
295			296		
297			298		
299			300		
301			302		
303			304		
305			306		
307			308		
309			310		
311			312		
313			314		
315			316		
317			318		
319			320		
321			322		
323			324		
325			326		
327			328		
329			330		
331			332		
333			334		
335			336		
337			338		
339			340		
341			342		
343			344		
345			346		
347			348		
349			350		
351			352		
353			354		
355			356		
357			358		
359			360		
361			362		
363			364		
365			366		
367			368		
369			370		
371			372		
373			374		
375			376		
377			378		
379			380		
381			382		
383			384		
385			386		
387			388		
389			390		
391			392		
393			394		
395			396		
397			398		
399			400		
401			402		
403			404		
405			406		
407			408		
409			410		
411			412		
413			414		
415			416		
417			418		
419			420		
421			422		
423			424		
425			426		
427			428		
429			430		
431			432		
433			434		
435			436		
437			438		
439			440		
441			442		
443			444		
445			446		
447			448		
449			450		
451			452		
453			454		
455			456		
457			458		
459			460		
461			462		
463			464		
465			466		
467			468		
469			470		
471			472		
473			474		
475			476		
477			478		
479			480		
481			482		
483			484		
485			486		
487			488		
489			490		
491			492		
493			494		
495			496		
497			498		
499			500		
501			502		
503			504		
505			506		
507			508		
509			510		
511			512		
513			514		
515			516		
517			518		
519			520		
521			522		
523			524		
525			526		
527			528		
529			530		
531			532		
533			534		
535			536		
537			538		
539			540		
541			542		
543			544		
545			546		
547			548		
549			550		
551			552		
553			554		
555			556		
557			558		
559			560		
561			562		
563			564		
565			566		
567			568		
569			570		
571			572		
573			574		
575			576</td		

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
EMBANKMENT (D/S SLOPE)		
AREA INSPECTED	CONDITION	OBSERVATIONS
TYPE (EARTH, CONCRETE, MASONRY)	earth	
WET AREAS (NO FLOW)	N/I/O; see veg	
SEEPAGE (EARTH) OR LEAKAGE (CONCRETE)	N/I/O	
SLIDE, SLOUGH, SCARP	N/I/O	
EMBANKMENT-ABUTMENT CONTACT	gravel	
SINKHOLE/ANIMAL BURROWS	N/I/O	
EROSION	possible? - surface not uniform; poss evidence of pre or post piping	
UNUSUAL MOVEMENT	N/I/O	
VEGETATION (PRESENCE/CONDITION)	grass (mowed); mess under D/S pine trees	
CONDITION OF JOINTS (CONCRETE)	N/I/O	
ADDITIONAL COMMENTS:		

Charlton-Snencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE
EMBANKMENT (CREST)		
AREA INSPECTED	CONDITION	OBSERVATIONS
CREST	SURFACE TYPE	earth w/ grass
	SURFACE CRACKING	N/0
	SINKHOLES, ANIMAL BURROWS	N/0 - large surface
	VERTICAL ALIGNMENT (DEPRESSIONS)	minor indentations
	HORIZONTAL ALIGNMENT	good
	RUTS AND/OR PUDDLES	N/0
	VEGETATION (PRESENCE/CONDITION)	mixed grass
	ABUTMENT CONTACT	good; slightly lower than crest at left abutment
	CONDITION OF JOINTS (CONCRETE)	N/0
	ADDITIONAL COMMENTS:	good condition overall

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
INSTRUMENTATION			
AREA INSPECTED	CONDITION	OBSERVATIONS	
1. PIEZOMETERS			
2. OBSERVATION WELLS			
3. STAFF GAGE AND RECORDER			
4. WEIRS			
5. INCLINOMETERS			
6. SURVEY MONUMENTS			
7. DRAINS			
8. FREQUENCY OF READINGS			
9. LOCATION OF READINGS			
ADDITIONAL COMMENTS:			
Initial Observations:			
Non-observables:			
Comments:			

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
DOWNSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
D/S WALLS	1. WALL TYPE	
	2. WALL ALIGNMENT	
	3. WALL CONDITION	
	4. HEIGHT: TOP OF WALL TO MUDLINE	min: max:
	5. SEEPAGE OR LEAKAGE	
	6. ABUTMENT CONTACT	
	7. EROSION/SINKHOLES BEHIND WALL	
	8. ANIMAL BURROWS	
	9. UNUSUAL MOVEMENT	
	10. WET AREAS AT TOE OF WALL	
	11. VEGETATION	
	12. SCOUR/EROSION AT BASE OF WALL	
ADDITIONAL COMMENTS:		

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
UPSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
U/S WALLS	1. WALL TYPE	concrete
	2. WALL ALIGNMENT	good
	3. WALL CONDITION	good
	4. HEIGHT: TOP OF WALL TO MUDLINE	min: 1', max: 6 - 7' avg: 5'
	5. ABUTMENT CONTACT	good
	6. EROSION/SINKHOLES BEHIND WALL	some soil loss
	7. ANIMAL BURROWS	N/I/O
	8. UNUSUAL MOVEMENT	N/I/O
	9. VEGETATION	sparse vines climbing wall; grass on top surface
	10. SCOUR/EROSION AT BASE OF WALL	left - N/I/O
ADDITIONAL COMMENTS:		none

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
DOWNSTREAM AREA			
AREA INSPECTED	CONDITION	OBSERVATIONS	
ABUTMENT LEAKAGE	N/I/O		
FOUNDATION SEEPAGE	N/I/O		
SLIDE, SLOUGH, SCARP	N/I/O		
WEIRS		small rock weir built by pp?	
DRAINAGE SYSTEM	N/I/O	tailwater runs below toe of dam	
INSTRUMENTATION	N/I/O		
VEGETATION		grass, large + small trees	
ACCESSIBILITY		walk thru private property	
DOWNSTREAM HAZARD DESCRIPTION		2 houses (priv.), public road, more houses + businesses	
ADDITIONAL COMMENTS:		Bank Erosion undermining large pine tree @ edge of tailwater	

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE
PRIMARY SPILLWAY		
AREA INSPECTED	CONDITION	OBSERVATIONS
SPILLWAY TYPE	concrete edge	
WEIR TYPE	broad crested	
SPILLWAY CONDITION	good	
TRAINING WALLS	concrete - straight at spillway + 90° wing walls at discharge. minor spalling ↓ efflorescent cracking	
SPILLWAY CONTROLS AND CONDITION	N/A	
UNUSUAL MOVEMENT	N/A	
APPROACH AREA	clear	
DISCHARGE AREA	narrow tankster w/ weir at end of spillway; wingwalls separated by few large pieces of wood	
DEBRIS	11"; wind over lake increased flow over spillway (during gage/s)	
WATER LEVEL AT TIME OF INSPECTION		
ADDITIONAL COMMENTS:		

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
AUXILIARY SPILLWAY		
AREA INSPECTED	CONDITION	OBSERVATIONS
SPILLWAY	SPILLWAY TYPE	
	WEIR TYPE	
	SPILLWAY CONDITION	
	TRAINING WALLS	
	SPILLWAY CONTROLS AND CONDITION	
	UNUSUAL MOVEMENT	
	APPROACH AREA	
	DISCHARGE AREA	
	DEBRIS	
	WATER LEVEL AT TIME OF INSPECTION	
ADDITIONAL COMMENTS:		

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME	INSPECTION DATE	
OUTLET WORKS		
AREA INSPECTED	CONDITION	OBSERVATIONS
TYPE	concrete box - drop inlet?	drop inlet?
INTAKE STRUCTURE	trashrack	Unknown
PRIMARY CLOSURE	hydraulic gate	Unknown
SECONDARY CLOSURE	conduit	Concrete - 12" or 15" <del>or 18"</del> <sup>minor</sup> slope spalling
OUTLET STRUCTURE/HEADWALL	EROSION ALONG TOE OF DAM	mitered to slope; no headwall N/A
OUTLET WORKS	SEEPAGE/LEAKAGE	N/A
	DEBRIS/BLOCKAGE	N/A
	UNUSUAL MOVEMENT	N/A
	DOWNSTREAM AREA	small stone pool w/ armored slope joins main bank
	MISCELLANEOUS	
	ADDITIONAL COMMENTS:	

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

Potential Recommendation Notes

Removal?

No - privately owned; rec + private properties

Breach/Spillway Adjustments?

No

Repurposing?

No

Fish/eel passage?

possible native like fishway

Notes:

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**PHOTOS**

**PHOTOGRAPHS INSTRUCTION PAGE:**

*All photographs shall be color photographs. Photographs shall be clear and include scale references where applicable. Photographs shall include, but not be limited to the following:*

1. *Overview of dam from upstream*
2. *Overview of dam from downstream*
3. *Overview of upstream face from right abutment*
4. *Overview of upstream face from left abutment*
5. *Overview of dam crest from right abutment*
6. *Overview of dam crest from left abutment*
7. *Overview of downstream face from right abutment*
8. *Overview of downstream face from left abutment*
9. *Overview of spillway from upstream*
10. *Overview of spillway from downstream (tailrace or channel area)*
11. *Overview of right training wall*
12. *Overview of left training wall*
13. *Overview of weir*
14. *Overview of stilling basin*
15. *Overview of downstream channel*
16. *Overview of gatehouse exterior*
17. *Overview of gatehouse interior*
18. *Overview of operators*
19. *Outlet inlets and discharge points*
20. *Overview of reservoir*
21. *Areas of specific deficiencies (e.g., cracks, erosion, displacement, seeps, deterioration, etc.)*

*Each photograph shall include a caption indicating the subject of the photograph as well as highlighting any specific deficiencies pictured. All photographs shall be presented with no more than two (2) photos per page. Photo location and orientation shall be indicated on the site plan included in the section entitled "Figures". Alternatively, for clarity, a separate figure can be provided in this appendix to show figure locations.*

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

SKETCH

Sketch of the dam site showing the dam structure and surrounding area. The sketch includes a north arrow, a scale bar from 0 to 1000 feet, and various points labeled A through T. Point A is at the top left, B is at the top center, C is at the top right, D is at the middle left, E is at the middle center, F is at the middle right, G is at the bottom left, H is at the bottom center, I is at the bottom right, J is at the far bottom left, K is at the far bottom center, L is at the far bottom right, and T is at the top right. The dam structure is shown as a thick line with a height of 100' and a width of 100'. The surrounding terrain is indicated by hatching and contour lines.

**Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan**  
**VISUAL DAM ASSESSMENT**

**DAM SAFETY INSPECTION**

NAME OF DAM:	<u>Sugden Reservoir</u>	STATE ID #:	<u>MA00698</u>
AKA NAME:			
<u>DAM LOCATION INFORMATION</u>			
CITY/TOWN:	<u>Sugden</u>	LAT. / LONG.:	
STATE:	<u>MA</u>	HAZARD CLASS:	
<u>GENERAL DAM INFORMATION</u>			
TYPE OF DAM:	<u>earth</u>		
PURPOSE OF DAM:	<u>Recreation, poss. flood control</u>		
YEAR BUILT:			
<u>INSPECTION SUMMARY</u>			
DATE OF INSPECTION:	<u>11/27/19</u>	NAME OF INSPECTOR:	<u>RLW</u>
TIME OF INSPECTION:	<u>10:31</u>	OTHER ATTENDEES:	<u>WF, PD</u>
WEATHER CONDITIONS:	<u>Rain/snow, 36°F, windy, cloudy</u>		
<u>GENERAL DAM DATA</u>			
PRIMARY SPILLWAY TYPE:	<u>ogee, concrete</u>	AUXILIARY SPILLWAY TYPE:	<u>N/O</u>
NUMBER OF OUTLETS:	<u>1 -</u>	TYPE OF OUTLETS:	<u>unknown</u>
HAS THE DAM BEEN BREACHED OR OVERTOPPED?	<u>No</u>		
IS THERE A FISH LADDER? (LIST TYPE IF PRESENT)	<u>No</u>		
DOES THE CREST SUPPORT A PUBLIC ROAD?	<u>No</u>		
ROADS/DRIVeway IMMEDIATELY DOWNSTREAM OF DAM?	<u>Road - Paxton Road</u>		
ACCESS CONDITIONS TO THE SITE:	<u>drive to D/S area</u>		
SECURITY DEVICES?	<u>N/A</u>		

TEC @ bridge; working w/ facilities on other bridge  
 Mike + Kim  
 + culvert  
 replacement  
 work

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

EMBANKMENT (D/S SLOPE)			INSPECTION DATE
AREA INSPECTED	CONDITION	OBSERVATIONS	
TYPE (EARTH, CONCRETE, MASONRY)	<u>Earth</u>	<u>fairly</u>	
WET AREAS (NO FLOW)	<u>N/I</u>	<u>left about wet - bouncy</u>	
SEEPAGE (EARTH) OR LEAKAGE (CONCRETE)	<u>N/I</u>	<u>wet down</u>	
SLIDE, SLOUGH, SCARP	<u>N/I</u>	<u>good</u>	
EMBANKMENT-ABUTMENT CONTACT	<u>N/I</u>		
SINKHOLE/ANIMAL BURROWS	<u>N/I</u>	<u>grass, mowed</u>	
EROSION	<u>N/I</u>		
UNUSUAL MOVEMENT	<u>N/I</u>		
VEGETATION (PRESENCE/CONDITION)	<u>grass, mowed</u>		
CONDITION OF JOINTS (CONCRETE)	<u>N/A</u>		
			ADDITIONAL COMMENTS:

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		Sugden Reservoir Dam		INSPECTION DATE
				EMBANKMENT (U/S SLOPE)
AREA INSPECTED	CONDITION	OBSERVATIONS		
TYPE (EARTH, CONCRETE, MASONRY)	earth, or man-made			
SLIDE, SLOUGH, SCARP	<del>little</del> , limited below gatehouse (used for water access)			
SLOPE PROTECTION TYPE AND COND.	armour, fair - see reg			
SINKHOLE/ANIMAL BURROWS	N/A - veg			
EMBANKMENT-ABUTMENT CONTACT	good			
U/S EROSION	N/A			
UNUSUAL MOVEMENT	N/A			
VEGETATION (PRESENCE/CONDITION)	cut trees + shrubs; roots/stumps still in place btwn armour stones			
CONDITION OF JOINTS (CONCRETE)	N/A			
ARMOURING				
ADDITIONAL COMMENTS:				
<i>you know</i>				

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE
EMBANKMENT (CREST)		
AREA INSPECTED	CONDITION	OBSERVATIONS
CREST	SURFACE TYPE	grass, mowed
	SURFACE CRACKING	N/C
	SINKHOLES, ANIMAL BURROWS	<del>no</del> yes - at least one 3-4"
	VERTICAL ALIGNMENT (DEPRESSIONS)	good (N/C)
	HORIZONTAL ALIGNMENT	good
	RUTS AND/OR PUDDLES	N/C
	VEGETATION (PRESENCE/CONDITION)	grass only
	ABUTMENT CONTACT	good
	CONDITION OF JOINTS (CONCRETE)	N/C
ADDITIONAL COMMENTS:		Small area of sloughing/erosion on W/S side of crest

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
Sugden Reservoir Dam		INSTRUMENTATION	
AREA INSPECTED	CONDITION	OBSERVATIONS	
1. PIEZOMETERS			
2. OBSERVATION WELLS			
3. STAFF GAGE AND RECORDER			
4. WEIRS			
5. INCLINOMETERS			
6. SURVEY MONUMENTS			
7. DRAINS			
8. FREQUENCY OF READINGS			
9. LOCATION OF READINGS			
ADDITIONAL COMMENTS:		Good condition	

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		Sugden Reservoir Dam		INSPECTION DATE
DOWNSTREAM WALLS				
AREA INSPECTED	CONDITION	OBSERVATIONS		
D/S WALLS	1. WALL TYPE			
	2. WALL ALIGNMENT			
	3. WALL CONDITION			
	4. HEIGHT: TOP OF WALL TO MUDLINE	min:	max:	
	5. SEEPAGE OR LEAKAGE			
	6. ABUTMENT CONTACT			
	7. EROSION/SINKHOLES BEHIND WALL			
	8. ANIMAL BURROWS			
	9. UNUSUAL MOVEMENT			
	10. WET AREAS AT TOE OF WALL			
	11. VEGETATION			
	12. SCOUR/EROSION AT BASE OF WALL			
ADDITIONAL COMMENTS:				
<i>Sugden Reservoir Dam</i>				

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
<u>Sugden Reservoir</u>			
UPSTREAM WALLS			
AREA INSPECTED	CONDITION	OBSERVATIONS	
1. WALL TYPE			
2. WALL ALIGNMENT			
3. WALL CONDITION			
4. HEIGHT: TOP OF WALL TO MUDLINE		min:	max:
5. ABUTMENT CONTACT			
6. EROSION/SINKHOLES BEHIND WALL			
7. ANIMAL BURROWS			
8. UNUSUAL MOVEMENT			
9. VEGETATION			
10. SCOUR/EROSION AT BASE OF WALL			
ADDITIONAL COMMENTS: <i>no major erosion or damage found</i>			

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
		DOWNSTREAM AREA	
AREA INSPECTED	CONDITION	OBSERVATIONS	
D/S AREA	ABUTMENT LEAKAGE	N/I/O	
	FOUNDATION SEEPAGE	<del>N/I/O</del> wet area D/S of spillway	
	SLIDE, SLOUGH, SCARP	N/I/O	
	WEIRS	N/I/C	
	DRAINAGE SYSTEM	drain right of primary spillway	
	INSTRUMENTATION	small trees in tailwater channel (N/I/B)	
	VEGETATION	✓	
	ACCESSIBILITY	drive/walk	
	DOWNSTREAM HAZARD DESCRIPTION	Roxton Road Utility pole 2 bridges	
	ADDITIONAL COMMENTS:	Some trees in tailwater channel	

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
		PRIMARY SPILLWAY	
AREA INSPECTED	CONDITION	OBSERVATIONS	
	SPILLWAY TYPE	concrete ogee	
	WEIR TYPE	broad crested	
	SPILLWAY CONDITION	good, <del>min</del> <sup>no</sup> <del>soft</del> cracks + spal	
	TRAINING WALLS	concrete, good	
	SPILLWAY CONTROLS AND CONDITION	N/A	
	UNUSUAL MOVEMENT	N/D	
	APPROACH AREA	clear	
	DISCHARGE AREA	tailwater - bedrock	
	DEBRIS	small amt of large branches	
	WATER LEVEL AT TIME OF INSPECTION	~1 ft below Spillway	
ADDITIONAL COMMENTS:		<u>Stilling basin - conc wall 2 ft</u>	
		<u>conc basin down</u>	

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
<u>Sugden Reservoir Dam</u>			
AUXILIARY SPILLWAY			
AREA INSPECTED	CONDITION	OBSERVATIONS	
SPILLWAY TYPE			
WEIR TYPE			
SPILLWAY CONDITION			
TRAINING WALLS			
SPILLWAY CONTROLS AND CONDITION			
UNUSUAL MOVEMENT			
APPROACH AREA			
DISCHARGE AREA			
DEBRIS			
WATER LEVEL AT TIME OF INSPECTION			
ADDITIONAL COMMENTS:			
<i>Good No issues</i>			

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME		Sugden Reservoir Dam		INSPECTION DATE
OUTLET WORKS				
AREA INSPECTED	CONDITION	OBSERVATIONS		
TYPE	Unknown	Water in impoundment, could not observe		
INTAKE STRUCTURE				
TRASHRACK	N/O			
PRIMARY CLOSURE	gatehouse, mech N/O			
SECONDARY CLOSURE				
CONDUIT	concrete			
OUTLET STRUCTURE/HEADWALL	concrete, spalling along top, eroded around sides			
EROSION ALONG TOE OF DAM	N/O			
SEEPAGE/LEAKAGE	yes - above outlet + up left D/S face of dam			
DEBRIS/BLOCKAGE	N/O			
UNUSUAL MOVEMENT	N/O			
DOWNSTREAM AREA	20' wide tailwater stream lined w/ small trees			
MISCELLANEOUS				
ADDITIONAL COMMENTS:				

Sugden Reservoir Dam  
Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

Potential Recommendation Notes

Removal?

~~Not controversial~~

Breach/Spillway Adjustments?

Repurposing?

flood control - poss. drawdown as flood prep

Fish/eel passage?

Ladder poss?

Steep/limited space for natural passage

Notes:

Owned by town?

But operated by lake association?

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**PHOTOS**

**PHOTOGRAPHS INSTRUCTION PAGE:**

*All photographs shall be color photographs. Photographs shall be clear and include scale references where applicable. Photographs shall include, but not be limited to the following:*

1. *Overview of dam from upstream*
2. *Overview of dam from downstream*
3. *Overview of upstream face from right abutment*
4. *Overview of upstream face from left abutment*
5. *Overview of dam crest from right abutment*
6. *Overview of dam crest from left abutment*
7. *Overview of downstream face from right abutment*
8. *Overview of downstream face from left abutment*
9. *Overview of spillway from upstream*
10. *Overview of spillway from downstream (tailrace or channel area)*
11. *Overview of right training wall*
12. *Overview of left training wall*
13. *Overview of weir*
14. *Overview of stilling basin*
15. *Overview of downstream channel*
16. *Overview of gatehouse exterior*
17. *Overview of gatehouse interior*
18. *Overview of operators*
19. *Outlet inlets and discharge points*
20. *Overview of reservoir*
21. *Areas of specific deficiencies (e.g., cracks, erosion, displacement, seeps, deterioration, etc.)*

*Each photograph shall include a caption indicating the subject of the photograph as well as highlighting any specific deficiencies pictured. All photographs shall be presented with no more than two (2) photos per page. Photo location and orientation shall be indicated on the site plan included in the section entitled "Figures". Alternatively, for clarity, a separate figure can be provided in this appendix to show figure locations.*

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

SKETCH

000019



**Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan**  
**VISUAL DAM ASSESSMENT**

**DAM SAFETY INSPECTION**

NAME OF DAM:	Browning Pond Dam	STATE ID #:	MA00695
AKA NAME:		WATERCOURSE NAME:	Seven Mile River
<b>DAM LOCATION INFORMATION</b>			
CITY/TOWN:	Spencer,	LAT. / LONG.:	42.3077862, -71.99710195
STATE:	MA	HAZARD CLASS:	Significant
<b>GENERAL DAM INFORMATION</b>			
TYPE OF DAM:	Earthen		
PURPOSE OF DAM:	Recreational, controversy over recreational access boat, fish, hike, swim?		
YEAR BUILT:	1700s?		
<b>INSPECTION SUMMARY</b>			
DATE OF INSPECTION:	11/27/18	NAME OF INSPECTOR:	Rachael Weiter
TIME OF INSPECTION:	-850	OTHER ATTENDEES:	Helene Farrell, Paul Dell Aquila
WEATHER CONDITIONS:	Clouds, Rain 35°F		
<b>GENERAL DAM DATA</b>			
PRIMARY SPILLWAY TYPE:	unknown under water	AUXILIARY SPILLWAY TYPE:	broad soft crest
NUMBER OF OUTLETS:	outlet 1	TYPE OF OUTLETS:	culvert under water
HAS THE DAM BEEN BREACHED OR OVERTOPPED?	appears yes - Paul will check		
IS THERE A FISH LADDER? (LIST TYPE IF PRESENT)	No		
DOES THE CREST SUPPORT A PUBLIC ROAD?	Yes - Browning pond road		
ROADS/DRIVEWAY IMMEDIATELY DOWNSTREAM OF DAM?	No		
ACCESS CONDITIONS TO THE SITE:	Road pull-offs		
SECURITY DEVICES?	None		

road slated for repair in near future  
Dam too?



Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
EMBANKMENT (D/S SLOPE)			
AREA INSPECTED	CONDITION	OBSERVATIONS	
	TYPE (EARTH, CONCRETE, MASONRY)	earth	
	WET AREAS (NO FLOW)	yes / difficult to tell in rain; lower in road	
	SEEPAGE (EARTH) OR LEAKAGE (CONCRETE)	unable to tell in rain	
	SLIDE, SLOUGH, SCARP	N/A	
	EMBANKMENT-ABUTMENT CONTACT	OK	
D/S SLOPE	SINKHOLE/ANIMAL BURROWS	veg - unable to determine	
	EROSION	N/A	
	UNUSUAL MOVEMENT	N/A	
	VEGETATION (PRESENCE/CONDITION)	large + small trees; brush	
	CONDITION OF JOINTS (CONCRETE)	N/A	
	ADDITIONAL COMMENTS:	Note: low water level	

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
EMBANKMENT (U/S SLOPE)		
AREA INSPECTED	CONDITION	OBSERVATIONS
TYPE (EARTH, CONCRETE, MASONRY)	Earth	
SLIDE, SLOUGH, SCARP	med; retained by vegetation	
SLOPE PROTECTION TYPE AND COND	N/A	
SINKHOLE/ANIMAL BURROWS	unable to determine - vegetation	
EMBANKMENT-ABUTMENT CONTACT	fl. good	
U/S EROSION	moderate, individual sites where pedestrian access/pollution	
UNUSUAL MOVEMENT	N/A	
VEGETATION (PRESENCE/CONDITION)	large trees, small trees, brush	
CONDITION OF JOINTS (CONCRETE)	N/A	
FRONTING SURFACE		
ADDITIONAL COMMENTS:	<u>gate @ right abutment; no gate;</u> boat launch <u>posts</u>	

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
EMBANKMENT (CREST)			
AREA INSPECTED	CONDITION	OBSERVATIONS	
SURFACE TYPE	po asphalt		
SURFACE CRACKING	yes	wide	wide
SINKHOLES, ANIMAL BURROWS	N/A		
VERTICAL ALIGNMENT (DEPRESSIONS)		sig. vertical change, especially about left	
HORIZONTAL ALIGNMENT	OK		
RUTS AND/OR PUDDLES	N/A		
VEGETATION (PRESENCE/CONDITION)	N/A		
ABUTMENT CONTACT	good		
CONDITION OF JOINTS (CONCRETE)	N/A		
ADDITIONAL COMMENTS:			

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	Browning Pond Dam	INSPECTION DATE
AREA INSPECTED	CONDITION	INSTRUMENTATION
1. PIEZOMETERS		OBSERVATIONS
2. OBSERVATION WELLS		
3. STAFF GAGE AND RECORDER		
4. WEIRS		
5. INCLINOMETERS		
6. SURVEY MONUMENTS		
7. DRAINS		
8. FREQUENCY OF READINGS		
9. LOCATION OF READINGS		
INSTR.		
ADDITIONAL COMMENTS:		
Comments:		
Date of Inspection:		
Initial Condition:		
Final Condition:		

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE
DOWNSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
1. WALL TYPE		
2. WALL ALIGNMENT		
3. WALL CONDITION		
4. HEIGHT: TOP OF WALL TO MUDLINE	min:	max:
5. SEEPAGE OR LEAKAGE		
6. ABUTMENT CONTACT		
7. EROSION/SINKHOLES BEHIND WALL		
D/S WALLS		
8. ANIMAL BURROWS		
9. UNUSUAL MOVEMENT		
10. WET AREAS AT TOE OF WALL		
11. VEGETATION		
12. SCOUR/EROSION AT BASE OF WALL		
ADDITIONAL COMMENTS:		
Benton 5000 ft		

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	Browning Pond Dam	INSPECTION DATE
UPSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
1. WALL TYPE		
2. WALL ALIGNMENT		
3. WALL CONDITION		
4. HEIGHT: TOP OF WALL TO MUDLINE	min: max:	avg: <i>WALL 2 m</i>
5. ABUTMENT CONTACT		
6. EROSION/SINKHOLES BEHIND WALL		
7. ANIMAL BURROWS		
8. UNUSUAL MOVEMENT		
9. VEGETATION		
10. SCOUR/EROSION AT BASE OF WALL		
ADDITIONAL COMMENTS:		

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
DOWNSTREAM AREA			
AREA INSPECTED	CONDITION	OBSERVATIONS	
ABUTMENT LEAKAGE	None noticed, observed		
FOUNDATION SEEPAGE	None noticed, water high		
SLIDE, SLOUGH, SCARP	No none observed		
WEIRS	N/A		
DRAINAGE SYSTEM	none observed		
INSTRUMENTATION	None obs.		
VEGETATION	Small trees, brush, grass, cattails - marshy		
ACCESSIBILITY	walky		
DOWNSTREAM HAZARD DESCRIPTION			
ADDITIONAL COMMENTS:			

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
Browning Pond Dam		
PRIMARY SPILLWAY	<i>Sp. crest</i>	
AREA INSPECTED	CONDITION	OBSERVATIONS
SPILLWAY TYPE		
WEIR TYPE		
SPILLWAY CONDITION		
TRAINING WALLS		
SPILLWAY CONTROLS AND CONDITION		
UNUSUAL MOVEMENT		
APPROACH AREA		
DISCHARGE AREA		
DEBRIS		
WATER LEVEL AT TIME OF INSPECTION		
ADDITIONAL COMMENTS:	<i>No damage observed.</i>	

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
AUXILIARY SPILLWAY		
AREA INSPECTED	CONDITION	OBSERVATIONS
SPILLWAY TYPE		
WEIR TYPE		
SPILLWAY CONDITION		
TRAINING WALLS		
SPILLWAY CONTROLS AND CONDITION		
SPILLWAY UNUSUAL MOVEMENT		
APPROACH AREA		
DISCHARGE AREA		
DEBRIS		
WATER LEVEL AT TIME OF INSPECTION		
ADDITIONAL COMMENTS:	<i>Don't know</i>	

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME		INSPECTION DATE	
		OUTLET WORKS	
AREA INSPECTED	CONDITION	OBSERVATIONS	
TYPE	Culvert, concrete headwalls		
INTAKE STRUCTURE	N/I - water high		
TRASHRACK	N/I		
PRIMARY CLOSURE	N/I		
SECONDARY CLOSURE	Unable to observe		
CONDUIT	concrete - cracked, spalling (minor)		
OUTLET STRUCTURE/HEADWALL	N/I		
OUTLET WORKS			
EROSION ALONG TOE OF DAM	N/I		
SEEPAGE/LEAKAGE	N/I - water high		
DEBRIS/BLOCKAGE	sinkhole in road / sinking of road formed. behind wetland /		
UNUSUAL MOVEMENT			
DOWNSTREAM AREA			
MISCELLANEOUS	Total culvert headwall - minor cracking, erosion under right wingwall some training walls - masonry w/ concrete - concrete + stones missing		
ADDITIONAL COMMENTS:			

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

Potential Recommendation Notes

Removal?

would be controversial

Breach/Spillway Adjustments?

Needs ~~sig.~~ larger outlet/spillway

Repurposing?

Too low

Fish/eel passage?

room for natural channel or very small ~~Denil~~ fish ladder

Notes:

thresholds  
no fish ladders  
no fish traps  
no fish screens  
no fish barriers

**Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan**  
**VISUAL DAM ASSESSMENT**

DAM SAFETY INSPECTION	
NAME OF DAM:	Buck Hill Cons. Dam STATE ID #:
AKA NAME:	WATERCOURSE NAME:
<u>DAM LOCATION INFORMATION</u>	
CITY/TOWN:	Spencer LAT. / LONG.:
STATE:	HAZARD CLASS:
<u>GENERAL DAM INFORMATION</u>	
TYPE OF DAM:	Recreational
PURPOSE OF DAM:	Recreational - boating, hiking, snowmobiling
YEAR BUILT:	
<u>INSPECTION SUMMARY</u>	
DATE OF INSPECTION:	11/27/18 NAME OF INSPECTOR: RLW
TIME OF INSPECTION:	9:45 OTHER ATTENDEES: HF, PD
WEATHER CONDITIONS:	Rain/snow, mostly cloudy, 34°F
<u>GENERAL DAM DATA</u>	
PRIMARY SPILLWAY TYPE:	horsehoe
AUXILIARY SPILLWAY TYPE:	
NUMBER OF OUTLETS:	5
TYPE OF OUTLETS:	
HAS THE DAM BEEN BREACHED OR OVERTOPPED?	Unknown
IS THERE A FISH LADDER? (LIST TYPE IF PRESENT)	N/A
DOES THE CREST SUPPORT A PUBLIC ROAD?	trail
ROADS/DRIVEWAY IMMEDIATELY DOWNSTREAM OF DAM?	driveways
ACCESS CONDITIONS TO THE SITE:	walk from road, parking nearby
SECURITY DEVICES?	N/A; possible bollards/gate prevent flying over ground

7970 town hall  
 8031 back@spfd

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
EMBANKMENT (D/S SLOPE)		
AREA INSPECTED	CONDITION	OBSERVATIONS
TYPE (EARTH, CONCRETE, MASONRY)	earth	
WET AREAS (NO FLOW)		surface wet from heavy rain - unknown
SEEPAGE (EARTH) OR LEAKAGE (CONCRETE)		possible - see ditch at toe of embankment
SLIDE, SLOUGH, SCARP	N/A	
EMBANKMENT-ABUTMENT CONTACT	good	
SINKHOLE/ANIMAL BURROWS	N/A - very likely	
EROSION	N/A	
UNUSUAL MOVEMENT	N/A	
VEGETATION (PRESENCE/CONDITION)	full grasses/brush	
CONDITION OF JOINTS (CONCRETE)	N/A	
ADDITIONAL COMMENTS:		

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAY ASSESSMENT

VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
EMBANKMENT (CREST)			
AREA INSPECTED	CONDITION	OBSERVATIONS	
CREST	SURFACE TYPE	grass	
	SURFACE CRACKING	N/I	
	SINKHOLES, ANIMAL BURROWS	N/I	
	VERTICAL ALIGNMENT (DEPRESSIONS)	N/I - good	
	HORIZONTAL ALIGNMENT	good	
	RUTS AND/OR PUDDLES	N/I	
	VEGETATION (PRESENCE/CONDITION)	grass - new / flattened	
	ABUTMENT CONTACT	good	
	CONDITION OF JOINTS (CONCRETE)	N/A	
ADDITIONAL COMMENTS:			
DRAINAGE SYSTEM			
WATER LEVEL			
STRUCTURE			
SOIL			
VEGETATION			
WATER SOURCE			
WATER USE			
WATER TREATMENT			
WATER CONSUMPTION			
WATER POLLUTION			
WATER WASTE			
WATER CONSERVATION			
WATER REUSE			
WATER RECHARGE			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			
WATER RESILIENCY			
WATER SECURITY			








# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
Buck Hill Conservation Dam			
INSTRUMENTATION			
AREA INSPECTED	CONDITION	OBSERVATIONS	
1. PIEZOMETERS			
2. OBSERVATION WELLS			
3. STAFF GAGE AND RECORDER			
4. WEIRS			
5. INCLINOMETERS			
6. SURVEY MONUMENTS			
7. DRAINS			
8. FREQUENCY OF READINGS			
9. LOCATION OF READINGS			
ADDITIONAL COMMENTS:			

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
DOWNSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
1. WALL TYPE		
2. WALL ALIGNMENT		
3. WALL CONDITION		
4. HEIGHT: TOP OF WALL TO MUDLINE		min:  max: 
5. SEEPAGE OR LEAKAGE		
6. ABUTMENT CONTACT		
7. EROSION/SINKHOLES BEHIND WALL		
8. ANIMAL BURROWS		
9. UNUSUAL MOVEMENT		
10. WET AREAS AT TOE OF WALL		
11. VEGETATION		
12. SCOUR/EROSION AT BASE OF WALL		    
ADDITIONAL COMMENTS:		

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
<i>Brek Hill Conservation Dam</i>			
UPSTREAM WALLS			
AREA INSPECTED	CONDITION	OBSERVATIONS	
	1. WALL TYPE		
	2. WALL ALIGNMENT		
	3. WALL CONDITION		
	4. HEIGHT: TOP OF WALL TO MUDLINE	min:	max:
	5. ABUTMENT CONTACT		
U/S WALLS	6. EROSION/SINKHOLES BEHIND WALL		
	7. ANIMAL BURROWS		
	8. UNUSUAL MOVEMENT		
	9. VEGETATION		
	10. SCOUR/EROSION AT BASE OF WALL		
ADDITIONAL COMMENTS:			

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
DOWNSTREAM AREA			
AREA INSPECTED	CONDITION	OBSERVATIONS	
D/S AREA	ABUTMENT LEAKAGE	N/I/O	
	FOUNDATION SEEPAGE	N/I/O - wet day	
	SLIDE, SLOUGH, SCARP	N/I/O	
	WEIRS	N/I/O	ditch cutting toe of dam - partly full of water
	DRAINAGE SYSTEM	N/I/O	
	INSTRUMENTATION	N/I/O	
	VEGETATION	N/I/O	grass, brush, trees (new, small)
	ACCESSIBILITY	N/I/O	walk
	DOWNSTREAM HAZARD DESCRIPTION	driveways & utility lines	
	ADDITIONAL COMMENTS:	very wet/marshy; no visible dam outlet but being occurring at potential outlet loc 'a' at toe of dam	

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
PRIMARY SPILLWAY			
AREA INSPECTED	CONDITION	OBSERVATIONS	
SPILLWAY TYPE	half/porous	Unknown due to Debris	
WEIR TYPE	Unknown "		
SPILLWAY CONDITION	N/A		
TRAINING WALLS	N/A		
SPILLWAY CONTROLS AND CONDITION	unknown //		
UNUSUAL MOVEMENT	clear except for underwater debris		
APPROACH AREA	D/S bolt?		
DISCHARGE AREA	large amount, covering plugging spillway		
DEBRIS	over spillway (ht unknown)		
WATER LEVEL AT TIME OF INSPECTION			
ADDITIONAL COMMENTS:		Informal trash rack made of stacked wire fence Debris left by bear?	

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
AUXILIARY SPILLWAY			
AREA INSPECTED	CONDITION	OBSERVATIONS	
SPILLWAY TYPE			
WEIR TYPE			
SPILLWAY CONDITION			
TRAINING WALLS			
SPILLWAY CONTROLS AND CONDITION			
UNUSUAL MOVEMENT			
APPROACH AREA			
DISCHARGE AREA			
DEBRIS			
WATER LEVEL AT TIME OF INSPECTION			
ADDITIONAL COMMENTS:			
Canyon Dam			

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME <i>Buck Hill Conservation Dam</i>		INSPECTION DATE
OUTLET WORKS		
AREA INSPECTED	CONDITION	OBSERVATIONS
TYPE		
INTAKE STRUCTURE		
TRASHRACK		
PRIMARY CLOSURE		
SECONDARY CLOSURE		
CONDUIT		
OUTLET STRUCTURE/HEADWALL		
EROSION ALONG TOE OF DAM		
SEEPAGE/LEAKAGE		
DEBRIS/BLOCKAGE		
UNUSUAL MOVEMENT		
DOWNSTREAM AREA		
MISCELLANEOUS		soil indicates poss. location <i>-bott</i>
ADDITIONAL COMMENTS:		<i>unable to observe due to high water, veg</i>

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

Potential Recommendation Notes

**Removal?**

controversial - rec  
owned by DCR, rented by YH

**Breach/Spillway Adjustments?**

Need to fix spillway  
Breach imposs - see above

**Repurposing?**

Raising for flood control would flood rec. property, trails

**Fish/eel passage?**

Could add ladder

Natural passage would require moving/elevating  
trails/adding bridges

**Notes:**

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**PHOTOS**

**PHOTOGRAPHS INSTRUCTION PAGE:**

*All photographs shall be color photographs. Photographs shall be clear and include scale references where applicable. Photographs shall include, but not be limited to the following:*

1. *Overview of dam from upstream*
2. *Overview of dam from downstream*
3. *Overview of upstream face from right abutment*
4. *Overview of upstream face from left abutment*
5. *Overview of dam crest from right abutment*
6. *Overview of dam crest from left abutment*
7. *Overview of downstream face from right abutment*
8. *Overview of downstream face from left abutment*
9. *Overview of spillway from upstream*
10. *Overview of spillway from downstream (tailrace or channel area)*
11. *Overview of right training wall*
12. *Overview of left training wall*
13. *Overview of weir*
14. *Overview of stilling basin*
15. *Overview of downstream channel*
16. *Overview of gatehouse exterior*
17. *Overview of gatehouse interior*
18. *Overview of operators*
19. *Outlet inlets and discharge points*
20. *Overview of reservoir*
21. *Areas of specific deficiencies (e.g., cracks, erosion, displacement, seeps, deterioration, etc.)*

*Each photograph shall include a caption indicating the subject of the photograph as well as highlighting any specific deficiencies pictured. All photographs shall be presented with no more than two (2) photos per page. Photo location and orientation shall be indicated on the site plan included in the section entitled "Figures". Alternatively, for clarity, a separate figure can be provided in this appendix to show figure locations.*

# **Wood-Pawcatuck Watershed Flood Resiliency Management Plan**

## **DAM INSPECTION FIELD ASSESSMENT**

SKETCH

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM SAFETY INSPECTION

NAME OF DAM:	Cedar Mill Pond Dam	STATE ID #:	MA01995
AKA NAME:	Cider Mill Pond Dam	WATERCOURSE NAME:	
DAM LOCATION INFORMATION			
CITY/TOWN:	Spencer	LAT. / LONG.:	
STATE:	MA	HAZARD CLASS:	
GENERAL DAM INFORMATION			
TYPE OF DAM:	Earth		
PURPOSE OF DAM:			
YEAR BUILT:			
INSPECTION SUMMARY			
DATE OF INSPECTION:	11/27/18	NAME OF INSPECTOR:	RLW
TIME OF INSPECTION:	1:00 PM	OTHER ATTENDEES:	INF, PD
WEATHER CONDITIONS:	Sunny, partly cloudy, breezy 38°-40°		
GENERAL DAM DATA			
PRIMARY SPILLWAY TYPE:	O	AUXILIARY SPILLWAY TYPE:	O
NUMBER OF OUTLETS:	1	TYPE OF OUTLETS:	
HAS THE DAM BEEN BREACHED OR OVERTOPPED?			
IS THERE A FISH LADDER? (LIST TYPE IF PRESENT)			
DOES THE CREST SUPPORT A PUBLIC ROAD?			
ROADS/DRIVEWAY IMMEDIATELY DOWNSTREAM OF DAM?			
ACCESS CONDITIONS TO THE SITE:			
SECURITY DEVICES?			

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
EMBANKMENT (CREST)			
AREA INSPECTED	CONDITION	OBSERVATIONS	
CREST	SURFACE TYPE		
	SURFACE CRACKING		
	SINKHOLES, ANIMAL BURROWS		
	VERTICAL ALIGNMENT (DEPRESSIONS)		
	HORIZONTAL ALIGNMENT		
	RUTS AND/OR PUDDLES		
	VEGETATION (PRESENCE/CONDITION)		
	ABUTMENT CONTACT		
	CONDITION OF JOINTS (CONCRETE)		
	ADDITIONAL COMMENTS:		WMS

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
DOWNSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
D/S WALLS	1. WALL TYPE	
	2. WALL ALIGNMENT	
	3. WALL CONDITION	
	4. HEIGHT: TOP OF WALL TO MUDLINE	min: max:
	5. SEEPAGE OR LEAKAGE	
	6. ABUTMENT CONTACT	
	7. EROSION/SINKHOLES BEHIND WALL	
	8. ANIMAL BURROWS	
	9. UNUSUAL MOVEMENT	
	10. WET AREAS AT TOE OF WALL	
	11. VEGETATION	
	12. SCOUR/EROSION AT BASE OF WALL	
ADDITIONAL COMMENTS:		✓ 100%

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
UPSTREAM WALLS			
AREA INSPECTED	CONDITION	OBSERVATIONS	
U/S WALLS	1. WALL TYPE		
	2. WALL ALIGNMENT		
	3. WALL CONDITION		
	4. HEIGHT: TOP OF WALL TO MUDLINE	min:	max: avg:
	5. ABUTMENT CONTACT		
	6. EROSION/SINKHOLES BEHIND WALL		
	7. ANIMAL BURROWS		
	8. UNUSUAL MOVEMENT		
	9. VEGETATION		
	10. SCOUR/EROSION AT BASE OF WALL		
ADDITIONAL COMMENTS:			

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
DOWNSTREAM AREA			
AREA INSPECTED	CONDITION	OBSERVATIONS	
	ABUTMENT LEAKAGE		
	FOUNDATION SEEPAGE		
	SLIDE, SLOUGH, SCARP		
	WEIRS		
D/S AREA	DRAINAGE SYSTEM		
	INSTRUMENTATION		
	VEGETATION		
	ACCESSIBILITY		
	DOWNSTREAM HAZARD DESCRIPTION		
ADDITIONAL COMMENTS:			

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
 VISUAL DAM ASSESSMENT

DAM NAME	CAMP D	INSPECTION DATE
PRIMARY SPILLWAY		
AREA INSPECTED	CONDITION	OBSERVATIONS
SPILLWAY TYPE		
WEIR TYPE		
SPILLWAY CONDITION		
TRAINING WALLS		
SPILLWAY CONTROLS AND CONDITION		
UNUSUAL MOVEMENT		
APPROACH AREA		
DISCHARGE AREA		
DEBRIS		
WATER LEVEL AT TIME OF INSPECTION		
ADDITIONAL COMMENTS:		
STABILITY	STRUCTURE	WATER LEVEL

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
<b>AUXILIARY SPILLWAY</b>			
<b>SPILLWAY INSPECTED</b>	AREA INSPECTED	CONDITION	OBSERVATIONS
	SPILLWAY TYPE		
	WEIR TYPE		
	SPILLWAY CONDITION		
	TRAINING WALLS		
	SPILLWAY CONTROLS AND CONDITION		
	UNUSUAL MOVEMENT		
	APPROACH AREA		
	DISCHARGE AREA		
	DEBRIS		
WATER LEVEL AT TIME OF INSPECTION			
ADDITIONAL COMMENTS:			

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME	EMPY	INSPECTION DATE
OUTLET WORKS		
AREA INSPECTED	CONDITION	OBSERVATIONS
TYPE		
INTAKE STRUCTURE		
TRASHRACK		
PRIMARY CLOSURE		
SECONDARY CLOSURE		
CONDUIT		
OUTLET STRUCTURE/HEADWALL		
OUTLET WORKS		
EROSION ALONG TOE OF DAM		
SEEPAGE/LEAKAGE		
DEBRIS/BLOCKAGE		
UNUSUAL MOVEMENT		
DOWNSTREAM AREA		
MISCELLANEOUS		
ADDITIONAL COMMENTS:		

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT**

**Potential Recommendation Notes**

**Removal?**

**Breach/Spillway Adjustments?**

**Repurposing?**

**Fish/eel passage?**

**Notes:**

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**PHOTOS**

**PHOTOGRAPHS INSTRUCTION PAGE:**

*All photographs shall be color photographs. Photographs shall be clear and include scale references where applicable. Photographs shall include, but not be limited to the following:*

1. *Overview of dam from upstream*
2. *Overview of dam from downstream*
3. *Overview of upstream face from right abutment*
4. *Overview of upstream face from left abutment*
5. *Overview of dam crest from right abutment*
6. *Overview of dam crest from left abutment*
7. *Overview of downstream face from right abutment*
8. *Overview of downstream face from left abutment*
9. *Overview of spillway from upstream*
10. *Overview of spillway from downstream (tailrace or channel area)*
11. *Overview of right training wall*
12. *Overview of left training wall*
13. *Overview of weir*
14. *Overview of stilling basin*
15. *Overview of downstream channel*
16. *Overview of gatehouse exterior*
17. *Overview of gatehouse interior*
18. *Overview of operators*
19. *Outlet inlets and discharge points*
20. *Overview of reservoir*
21. *Areas of specific deficiencies (e.g., cracks, erosion, displacement, seeps, deterioration, etc.)*

*Each photograph shall include a caption indicating the subject of the photograph as well as highlighting any specific deficiencies pictured. All photographs shall be presented with no more than two (2) photos per page. Photo location and orientation shall be indicated on the site plan included in the section entitled "Figures". Alternatively, for clarity, a separate figure can be provided in this appendix to show figure locations.*

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

SKETCH

Sketch of the dam site.



## **Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan VISUAL DAM ASSESSMENT**

## DAM SAFETY INSPECTION

**DAM SAFETY INSPECTION**

NAME OF DAM:	<u>Howe Mill Pond Dam</u>	STATE ID #:	<u>53</u>
AKA NAME:	<u> </u>		
<b>DAM LOCATION INFORMATION</b>			
CITY/TOWN:	<u>Spencer, MA</u>	LAT. / LONG.:	<u> </u>
STATE:	<u>MA</u>	HAZARD CLASS:	<u> </u>
<b>GENERAL DAM INFORMATION</b>			
TYPE OF DAM:	<u>Earth</u>		
PURPOSE OF DAM:	<u>Aesthetic / Historic / Cultural significance; former beach; picnic area</u>		
YEAR BUILT:	<u> </u>		
<b>INSPECTION SUMMARY</b>			
DATE OF INSPECTION:	<u>11/29/18</u>	NAME OF INSPECTOR:	<u>KLW</u>
TIME OF INSPECTION:	<u>930</u>	OTHER ATTENDEES:	<u>NF, PD</u>
WEATHER CONDITIONS:	<u>Sunny, windy, partly cloudy</u>		
<b>GENERAL DAM DATA</b>			
PRIMARY SPILLWAY TYPE:	<u>Stepped Masonry</u>	AUXILIARY SPILLWAY TYPE:	<u>concrete drop inlet</u>
NUMBER OF OUTLETS:	<u>0</u>	TYPE OF OUTLETS:	<u> </u>
HAS THE DAM BEEN BREACHED OR OVERTOPPED?	<u>unknown</u>		
IS THERE A FISH LADDER? (LIST TYPE IF PRESENT)	<u>No</u>		
DOES THE CREST SUPPORT A PUBLIC ROAD?	<u>No</u>		
ROADS/DRIVEWAY IMMEDIATELY DOWNSTREAM OF DAM?	<u>Public road</u>		
ACCESS CONDITIONS TO THE SITE:	<u>walk onto dam; open public parking across road</u>		
SECURITY DEVICES?	<u>Minimal protection from falls; no gates</u>		

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

VISUAL DAM ASSESSMENT

EMBANKMENT (D/S SLOPE)		
AREA INSPECTED	CONDITION	OBSERVATIONS
D/S SLOPE	TYPE (EARTH, CONCRETE, MASONRY)	earth
	WET AREAS (NO FLOW)	N/D
	SEEPAGE (EARTH) OR LEAKAGE (CONCRETE)	N/D
	SLIDE, SLOUGH, SCARP	N/D
	EMBANKMENT-ABUTMENT CONTACT	left - good; right shore lower than dam crest <del>weathered 3-4' of sinkholes present near base</del> N/D
	SINKHOLE/ANIMAL BURROWS	<del>One area - 4' wide</del>
	EROSION	N/D
	UNUSUAL MOVEMENT	
	VEGETATION (PRESENCE/CONDITION)	req - none; several large trees
	CONDITION OF JOINTS (CONCRETE)	N/D
ADDITIONAL COMMENTS:		

Charlton-Snencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
EMBANKMENT (CREST)			
AREA INSPECTED	CONDITION	OBSERVATIONS	
CREST	SURFACE TYPE	earth	
	SURFACE CRACKING	N/D	
	SINKHOLES, ANIMAL BURROWS	Multipe 3'-4' of sinkholes where large trees removed	
	VERTICAL ALIGNMENT (DEPRESSIONS)	N/D	
	HORIZONTAL ALIGNMENT	N/D	
	RUTS AND/OR PUDDLES	N/D	
	VEGETATION (PRESENCE/CONDITION)	grass - normal; large trees	
	ABUTMENT CONTACT	left - good; right - about 2' U/S area lower than dam crest	
	CONDITION OF JOINTS (CONCRETE)	N/D	
	ADDITIONAL COMMENTS:	Erosion behind corner of masonry training walls	

## Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME	HMPD	INSPECTION DATE
		INSTRUMENTATION
AREA INSPECTED	CONDITION	OBSERVATIONS
1. PIEZOMETERS		
2. OBSERVATION WELLS		
3. STAFF GAGE AND RECORDER		
4. WEIRS		
5. INCLINOMETERS		
6. SURVEY MONUMENTS		
7. DRAINS		
8. FREQUENCY OF READINGS		
9. LOCATION OF READINGS		
ADDITIONAL COMMENTS:		

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
DOWNSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
D/S WALLS	1. WALL TYPE	mortared stone masonry
	2. WALL ALIGNMENT	good - left. Right - wall to dam leaning outward at base
	3. WALL CONDITION	good except at ends & spillways; right - fair
	4. HEIGHT: TOP OF WALL TO MUDLINE	min: 2 ft max: 6'
	5. SEEPAGE OR LEAKAGE	N/A - left; right - heavy seepage in corner of wall / left - poor; right - poor; erosion around end left - no
	6. ABUTMENT CONTACT	
	7. EROSION/SINKHOLES BEHIND WALL	left NO; right - n/o
	8. ANIMAL BURROWS	N/A
	9. UNUSUAL MOVEMENT	
	10. WET AREAS AT TOE OF WALL	left - N/S; right - large wet area at corner
	11. VEGETATION	fens - left of spillway; fens + moss - right
	12. SCOUR/EROSION AT BASE OF WALL	left - n/o
ADDITIONAL COMMENTS:		<p>Visible missing stones right of Spillway</p> <p>Stump at end of wall holding bit disrupting wall</p> <p>100ft</p>

Charlton-Snencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
UPSTREAM WALLS			
AREA INSPECTED	CONDITION	OBSERVATIONS	
U/S WALLS	1. WALL TYPE <i>mortared stone masonry</i>	<i>left side of spillway - wall leaning out ~ 2" over 3 feet + good</i>	
	2. WALL ALIGNMENT	<i>fair; right - higher than abutment, erosion around base</i>	
	3. WALL CONDITION	<i>min: 1 ft max: 6-8 ft avg: 5-7 ft</i>	
	4. HEIGHT: TOP OF WALL TO MUDLINE	<i>yes - at corners of training walls - soil / less; also at right</i>	
	5. ABUTMENT CONTACT	<i>N/T</i>	
	6. EROSION/SINKHOLES BEHIND WALL	<i>N/T</i>	
	7. ANIMAL BURROWS	<i>N/T</i>	
	8. UNUSUAL MOVEMENT	<i>N/T</i>	
	9. VEGETATION	<i>small trees cut or growing at base of wall - few</i>	
	10. SCOUR/EROSION AT BASE OF WALL	<i>N/T</i>	
ADDITIONAL COMMENTS:			

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
AREA INSPECTED	CONDITION	PRIMARY SPILLWAY
		Observations
SPILLWAY TYPE	stepped masonry spillway	
WEIR TYPE	broad-crested wet	
SPILLWAY CONDITION	fair	masonry on D/S ends failing; erosion behind training wall/corner
TRAINING WALLS		
SPILLWAY CONTROLS AND CONDITION	N/D	
UNUSUAL MOVEMENT	N/D	
APPROACH AREA	clear of reg. debris	
DISCHARGE AREA	masonry spilling basin discharging to stone raceway	
DEBRIS	~10	
WATER LEVEL AT TIME OF INSPECTION	2-4"	over high point of weir
ADDITIONAL COMMENTS:	<i>Mill wheel support still erect in spillway; loose masonry at bottom of wheel slot</i>	

## Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT T

DAM NAME	INSPECTION DATE	
AUXILIARY SPILLWAY		
AREA INSPECTED	CONDITION	OBSERVATIONS
SPILLWAY TYPE	concrete drop inlet	
WEIR TYPE	broad crested concrete; small amount of grass & debris on weir	
SPILLWAY CONDITION	fair	
TRAINING WALLS	N/A	
SPILLWAY CONTROLS AND CONDITION	N/O	
UNUSUAL MOVEMENT	N/O	
SPILLWAY	approach becoming choked by grass & pond weed; poss. sediment deposits under road to masonry-lined raceway	
APPROACH AREA	None in outlet	
DISCHARGE AREA	~ 1' over weir	
DEBRIS	Debris of retaining wall right of inlet - covered by veg & fallen wood split rail fence on flood/earth embankment	
WATER LEVEL AT TIME OF INSPECTION		
ADDITIONAL COMMENTS:	<p>Concrete box forming inlet in good condition</p> <p>face of weir - condition uncertain</p> <p>outlet of drop inlet - 2 concrete curbs each ~ 6' x 5' wide</p> <p>local side of inlet protected by metal rail at edge +</p> <p>wood split rail fence on flood/earth embankment</p> <p>Bottom inlet + road</p> <ul style="list-style-type: none"> <li>- small animal burrows holes in embankt.</li> </ul>	

Masonry wingwalls @ culvert outlet misaligned, possibly unstable

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME	HM PD	INSPECTION DATE
OUTLET WORKS		
AREA INSPECTED	CONDITION	OBSERVATIONS
TYPE		
INTAKE STRUCTURE		
TRASHRACK		
PRIMARY CLOSURE		
SECONDARY CLOSURE		
CONDUIT		
OUTLET STRUCTURE/HEADWALL		
OUTLET WORKS		
EROSION ALONG TOE OF DAM		
SEEPAGE/LEAKAGE		
DEBRIS/BLOCKAGE		
UNUSUAL MOVEMENT		
DOWNSTREAM AREA		
MISCELLANEOUS		
ADDITIONAL COMMENTS:		

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT**

**Potential Recommendation Notes**

**Removal?**

*Not approp*

**Breach/Spillway Adjustments?**

**Repurposing?**

*Not likely*

**Fish/eel passage?**

*Ladders could be added to spillway but disrupt*

**Notes:**

*09/13/22*

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**PHOTOS**

HOTLINE

**PHOTOGRAPHS INSTRUCTION PAGE:**

*All photographs shall be color photographs. Photographs shall be clear and include scale references where applicable. Photographs shall include, but not be limited to the following:*

1. *Overview of dam from upstream*
2. *Overview of dam from downstream*
3. *Overview of upstream face from right abutment*
4. *Overview of upstream face from left abutment*
5. *Overview of dam crest from right abutment*
6. *Overview of dam crest from left abutment*
7. *Overview of downstream face from right abutment*
8. *Overview of downstream face from left abutment*
9. *Overview of spillway from upstream*
10. *Overview of spillway from downstream (tailrace or channel area)*
11. *Overview of right training wall*
12. *Overview of left training wall*
13. *Overview of weir*
14. *Overview of stilling basin*
15. *Overview of downstream channel*
16. *Overview of gatehouse exterior*
17. *Overview of gatehouse interior*
18. *Overview of operators*
19. *Outlet inlets and discharge points*
20. *Overview of reservoir*
21. *Areas of specific deficiencies (e.g., cracks, erosion, displacement, seeps, deterioration, etc.)*


*Each photograph shall include a caption indicating the subject of the photograph as well as highlighting any specific deficiencies pictured. All photographs shall be presented with no more than two (2) photos per page. Photo location and orientation shall be indicated on the site plan included in the section entitled "Figures". Alternatively, for clarity, a separate figure can be provided in this appendix to show figure locations.*

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

SKETCH

Sketch

Sketch Note: Sketches are not to scale.



Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM SAFETY INSPECTION

NAME OF DAM:	Howe Reservoir Dam	STATE ID #:	
AKA NAME:		WATERCOURSE NAME:	
DAM LOCATION INFORMATION			
CITY/TOWN:	Spencer	LAT. / LONG.:	
STATE:	MA	HAZARD CLASS:	
GENERAL DAM INFORMATION			
TYPE OF DAM:	Earth		
PURPOSE OF DAM:	NOT drinking water		
YEAR BUILT:			
INSPECTION SUMMARY			
DATE OF INSPECTION:	11/29/18	NAME OF INSPECTOR:	RLW
TIME OF INSPECTION:	21036	OTHER ATTENDEES:	HF, PD
WEATHER CONDITIONS:	Sunny, partly cloudy, windy		
GENERAL DAM DATA			
PRIMARY SPILLWAY TYPE:	Concrete bc weirs	AUXILIARY SPILLWAY TYPE:	/
NUMBER OF OUTLETS:	0	TYPE OF OUTLETS:	
HAS THE DAM BEEN BREACHED OR OVERTOPPED?	Unknown		
IS THERE A FISH LADDER? (LIST TYPE IF PRESENT)	No		
DOES THE CREST SUPPORT A PUBLIC ROAD?	No - formerly supported trail + bridge		
ROADS/DRIVEWAY IMMEDIATELY DOWNSTREAM OF DAM?	No		
ACCESS CONDITIONS TO THE SITE:	Walk/ski/ ATV/snowmobile		
SECURITY DEVICES?	N/A		

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
EMBANKMENT (D/S SLOPE)			
AREA INSPECTED	CONDITION	OBSERVATIONS	
D/S SLOPE	TYPE (EARTH, CONCRETE, MASONRY)	<i>earth</i>	
	WET AREAS (NO FLOW)	<i>small</i>	
	SEEPAGE (EARTH) OR LEAKAGE (CONCRETE)	<i>N/0</i>	
	SLIDE, SLOUGH, SCARP	<i>N/0</i>	
	EMBANKMENT-ABUTMENT CONTACT	<i>good</i>	
	SINKHOLE/ANIMAL BURROWS	<i>N/0</i>	
	EROSION	<i>N/0</i>	
	UNUSUAL MOVEMENT	<i>N/0</i>	
	VEGETATION (PRESENCE/CONDITION)	<i>grass - mowed, moss; large trees near abutment</i>	
	CONDITION OF JOINTS (CONCRETE)	<i>N/0</i>	
ADDITIONAL COMMENTS:			

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT


VISUAL DAM ASSESSMENT

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
INSTRUMENTATION			
AREA INSPECTED	CONDITION	OBSERVATIONS	
INSTR.			
1. PIEZOMETERS			
2. OBSERVATION WELLS			
3. STAFF GAGE AND RECORDER			
4. WEIRS			
5. INCLINOMETERS			
6. SURVEY MONUMENTS			
7. DRAINS			
8. FREQUENCY OF READINGS			
9. LOCATION OF READINGS			
ADDITIONAL COMMENTS:			

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME	INSPECTION DATE	
DOWNSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
D/S WALLS	1. WALL TYPE	
	2. WALL ALIGNMENT	
	3. WALL CONDITION	
	4. HEIGHT: TOP OF WALL TO MUDLINE	min: _____ max: _____
	5. SEEPAGE OR LEAKAGE	
	6. ABUTMENT CONTACT	
	7. EROSION/SINKHOLES BEHIND WALL	
	8. ANIMAL BURROWS	
	9. UNUSUAL MOVEMENT	
	10. WET AREAS AT TOE OF WALL	
	11. VEGETATION	
	12. SCOUR/EROSION AT BASE OF WALL	
ADDITIONAL COMMENTS:		

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME <i>H/RD</i>		INSPECTION DATE
UPSTREAM WALLS		
AREA INSPECTED	CONDITION	OBSERVATIONS
1. WALL TYPE		
2. WALL ALIGNMENT		
3. WALL CONDITION		
4. HEIGHT: TOP OF WALL TO MUDLINE	min: <i>24'</i>	max: <i>25'</i> avg: <i>24.5'</i>
5. ABUTMENT CONTACT		
U/S WALLS	6. EROSION/SINKHOLES BEHIND WALL	
	7. ANIMAL BURROWS	
	8. UNUSUAL MOVEMENT	
	9. VEGETATION	
	10. SCOUR/EROSION AT BASE OF WALL	
ADDITIONAL COMMENTS:		
<i>Comments: No visible signs of significant structural damage or instability. However, some minor erosion and vegetation growth are noted along the base and behind the wall.</i>		

Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
VISUAL DAM ASSESSMENT

DAM NAME		INSPECTION DATE	
DOWNSTREAM AREA			
AREA INSPECTED	CONDITION	OBSERVATIONS	
	ABUTMENT LEAKAGE	N/A	
	FOUNDATION SEEPAGE	N/A	
	SLIDE, SLOUGH, SCARP	N/A	
	WEIRS	N/A	
D/S AREA	DRAINAGE SYSTEM	N/A	
	INSTRUMENTATION	N/A	
	VEGETATION	Shrubs/trees	
	ACCESSIBILITY	walking	
	DOWNSTREAM HAZARD DESCRIPTION		
ADDITIONAL COMMENTS:			

Charlton-Snencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

VISUAL DAM ASSESSMENT

# Charlton-Spencer Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan

## VISUAL DAM ASSESSMENT

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

DAM NAME <i>HRD</i>		INSPECTION DATE	
OUTLET WORKS			
AREA INSPECTED	CONDITION	OBSERVATIONS	
TYPE			
INTAKE STRUCTURE			
TRASHRACK			
PRIMARY CLOSURE			
SECONDARY CLOSURE			
CONDUIT			
OUTLET STRUCTURE/HEADWALL			
EROSION ALONG TOE OF DAM			
SEEPAGE/LEAKAGE			
DEBRIS/BLOCKAGE			
UNUSUAL MOVEMENT			
DOWNSTREAM AREA			
MISCELLANEOUS			
ADDITIONAL COMMENTS:			

Wood-Pawcatuck Watershed Flood Resiliency Management Plan  
DAM INSPECTION FIELD ASSESSMENT

Potential Recommendation Notes

Removal? possible

Breach/Spillway Adjustments?

could be breached / spillway revised

Repurposing?

Potential flood control if gates installed @ spillway

Fish/eel passage?

Ladder could easily be added

Notes:

removing dam would connect ponds, possibly reduce beaver problems ~~but~~ or transfer thru D/S to Howe Mill Dam

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**PHOTOS**

**PHOTOGRAPHS INSTRUCTION PAGE:**

*All photographs shall be color photographs. Photographs shall be clear and include scale references where applicable. Photographs shall include, but not be limited to the following:*

1. *Overview of dam from upstream*
2. *Overview of dam from downstream*
3. *Overview of upstream face from right abutment*
4. *Overview of upstream face from left abutment*
5. *Overview of dam crest from right abutment*
6. *Overview of dam crest from left abutment*
7. *Overview of downstream face from right abutment*
8. *Overview of downstream face from left abutment*
9. *Overview of spillway from upstream*
10. *Overview of spillway from downstream (tailrace or channel area)*
11. *Overview of right training wall*
12. *Overview of left training wall*
13. *Overview of weir*
14. *Overview of stilling basin*
15. *Overview of downstream channel*
16. *Overview of gatehouse exterior*
17. *Overview of gatehouse interior*
18. *Overview of operators*
19. *Outlet inlets and discharge points*
20. *Overview of reservoir*
21. *Areas of specific deficiencies (e.g., cracks, erosion, displacement, seeps, deterioration, etc.)*

*Each photograph shall include a caption indicating the subject of the photograph as well as highlighting any specific deficiencies pictured. All photographs shall be presented with no more than two (2) photos per page. Photo location and orientation shall be indicated on the site plan included in the section entitled "Figures". Alternatively, for clarity, a separate figure can be provided in this appendix to show figure locations.*

**Wood-Pawcatuck Watershed Flood Resiliency Management Plan**  
**DAM INSPECTION FIELD ASSESSMENT**

**SKETCH**



## Attachment C

---

### Dam Assessment Scoring and Prioritization Results

## Dam Assessment Scoring and Prioritization

Dam ID Number	Dam Name	Impoundment Name	Latitude	Longitude	Current Uses	Ability to Maintain	Failure Risk (Priority Rating)	Flood Mitigation Potential	Stream Continuity Potential	Management Recommendations
Town of Charlton										
MA00101	Glen Echo Dam	Glen Echo Lake	42.156434	-71.99218	Flood Control; Lakeside Property	Yes	Moderate (Medium)	No		Repair/Maintain
MA00103	Little Nugget Lake Dam	Little Nugget Lake	42.170699	-71.949266	Recreation	Yes	Low (Low)	No		Consider adding AOP
MA01829	Lambs Pond Dam	Lambs Pond	42.17737	-71.975891	Recreation	Yes, but owner has not removed beaver dam at spillway	Moderate (Medium)	No		Remove to increase stream continuity and to address beaver problems, or Repair and remove beaver debris.
MA00100	Ashworth Dam	Upper Sibley Pond	42.14837	-72.00935	Unknown	Unknown	Unknown (Unknown)	No		Remove or No Action
MA00099	Lower Sibley Pond Dam	Lower Sibley Pond	42.14487	-72.00608	None Known	No	Severe (High)	No	Low	Remove
MA01827	Wee Laddie Pond Dam	Wee Laddie Pond	42.174911	-71.956704	None Known; Formerly used for irrigation and as an ice pond	No	Severe (High)	No	Low	Remove
MA01838	Farm Pond Dam	Dodge Pond	42.13594	-71.94515	Recreation	Unknown	Low (Low)	No		Repair/Maintain and Consider adding AOP
MA01835	McIntyres Pond Dam	McIntyre Pond	42.106299	-71.980322	Unknown	Unknown	Unknown (Unknown)	No		Consider removal; More information needed
MA01830	Rail Road Pond Dam	Rail Road Pond	42.174769	-71.976938	Supports Public Road (Old Spencer Road)	No	Severe (High)	No	Not Assessed	Remove
	Power Station Dam		42.147365	-71.98985	Former hydroelectric dam (once powered Charlton City)	No	Severe (High)	No	Not Assessed	Remove
MA03428	Carpenter Mill Pond Dam		42.145916	-71.990464	None Known	Unknown	Moderate (Medium)	No	Not Assessed	Consider removal; More information needed
	Dam 3		42.149948	-71.988338	Formerly associated with Charlton Woolen Mill	No	Severe (High)	No	Not Assessed	Remove
	Dam 4		42.148534	-71.988579	None Known; Formerly used for swimming lessons by Red Cross	No	Severe (High)		Not Assessed	Remove
Town of Spencer										
MA01997	Lac Marie Dam	Lac Marie Pond	42.291795	-72.001145	Recreation	Yes	Low (Low)	No	High	Consider adding AOP within limited space
MA02379	Muzzy Meadow Dam	Spencer Pond	42.241768	-71.991603	Aesthetics, Future Skating Pond/Trails	Yes	Moderate (Medium)	No	Low	No Action
MA02583	Moose Hill Pond Dam	Moose Hill Pond	42.271692	-71.959035	Flood Control, Emergency Water Supply	Yes	Low/Moderate (Low/Medium)	No		Consider adding AOP
MA00700	Cranberry Meadow Pond Dam	Cranberry Meadow Pond	42.192671	-72.001176	Recreation	Yes	Severe (High)	Yes	Low	Repair
MA00699	Lake Whittemore Dam	Lake Whittemore	42.254285	-71.989485	Recreation	Yes	Low/Moderate (Low/Medium)	Yes	Low	No Action
MA00698	Sugden (Reservoir) Dam	Sugden Reservoir	42.27283	-71.972491	Flood Control, Recreation	Yes	Moderate (Medium)	No		Consider modifying to allow drawdown for additional flood capacity; Consider adding AOP
MA00695	Browning Pond Dam	Browning Pond	42.37786	-71.997102	Recreation	No	Moderate (Medium)	No		Consider removal, or Repair/Maintain and add AOP
MA00901	Buck Hill Conservation Dam	Buck Hill Pond	42.289316	-71.9873	Conservation and Recreation	Yes	Moderate/Severe (Medium/High)	No		Repair/Maintain and consider adding AOP
MA01995	Cedar Millpond Dam (Cider Mill Pond Dam?)	Cider Mill Pond	42.245036	-71.994192	Supports Parking Lot	No	Low/Unknown (Low)	No	Low	More information needed
MA01175	Howe Mill Pond Dam	Howe Mill Pond (lower portion of Howe Pond)	42.21588	-71.999794	Recreation, Aesthetics, Cultural	Yes	Moderate (Medium)	No	Low	Repair/Maintain
MA02542	Howe Reservoir Dam	Howe Reservoir (upper portion of Howe Pond)	42.213324	-71.998913	Recreation	Yes	Moderate (Medium)	No	Low	Study Removal to possibly address beaver problems and provide stream continuity

## Appendix D

---

### Water and Wastewater Infrastructure Assessment Technical Memorandum



## MEMORANDUM

**TO:** Project Steering Committee

**FROM:** Kevin M. Flood, P.E., Kurt A. Mailman, P.E.  
Fuss & O'Neill, Inc.  
1550 Main Street, Suite 400  
Springfield, MA 01103

**DATE:** May 30, 2019

**RE:** **Water and Wastewater Infrastructure Vulnerability Assessment**  
Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan  
MVP Action Grant - Town of Charlton & Town of Spencer

---

### 1 Introduction

This memorandum summarizes the evaluation of existing water and wastewater infrastructure in Charlton and Spencer, Massachusetts that is at risk of inland flooding. Specifically, the existing wastewater collection systems, the wastewater treatment facilities, the public drinking water source wells, and the water distribution systems were evaluated for flood-related vulnerabilities under present day and projected future climate change conditions. This assessment is part of the *Integrated Water Infrastructure Vulnerability Assessment and Climate Resiliency Plan* project funded through the Massachusetts Municipal Vulnerability Preparedness (MVP) Program.

### 2 Data Collection

Spatial mapping and attribute data were compiled in GIS and Adobe PDF format as available and overlaid onto digital orthophotos to depict the water and wastewater distribution and collection systems within the two communities. Federal Emergency Management Agency (FEMA) Flood Insurance Rate Maps were overlaid onto GIS mapping for both communities to highlight existing flood hazard areas and their proximity to water and wastewater infrastructure. Mapped FEMA flood hazard areas and associated flood elevations were utilized to compare existing ground elevations and elevations of critical equipment in areas near water and wastewater infrastructure to assess potential flood-related vulnerabilities. Site-specific information including layouts, topography, elevations, equipment, and details for each of the sites evaluated were obtained from the municipalities and Central Massachusetts Regional Planning Commission (CMRPC).

### 3 Vulnerability Assessments

#### 3.1 Identification of Facilities Vulnerable to Flooding

Vulnerable facilities were identified based on their proximity to flood hazard areas identified on FEMA Flood Insurance Rate Maps. For the purpose of this assessment, vulnerable facilities are those facilities:

1. Located within or adjacent to the area inundated by the 1 percent annual chance (100-year) flood, the 0.2 percent annual chance (500-year) flood, or regulatory floodway, or
2. Facilities within or in close proximity and hydraulically connected to a mapped flood hazard area, with critical infrastructure located at or below the published base flood elevation, where available.

The elevation of adaptation measures (i.e., critical elevation) was determined from the 1 percent annual chance flood elevation reported on FEMA Flood Insurance Rate Maps (FIRMs) plus three feet of freeboard, which is consistent with recommended guidance for critical facilities as described in the New England Interstate Water Pollution Control Commission (NEIWPCC) *Storm Resiliency and Adaptation Needs for Wastewater Conveyance and Treatment and Technical Resource 16 (TR-16) Guides for the Design of Wastewater Treatment Works* for wastewater infrastructure and *EPA's Climate Resilient Water Utilities* initiative for water infrastructure. For the purpose of this assessment, the vulnerable wastewater and water infrastructure in both communities were considered critical or essential facilities. The three feet of freeboard is also intended to account for potential increases in the 1 percent chance flood elevation based on anticipated increases in peak streamflow under projected future climate change conditions.

Where base flood elevations were not determined by FEMA (e.g., Zone A), the 1 percent annual chance flood elevation was estimated from LIDAR ground elevations and the 1 percent annual chance flood hazard area boundary in the vicinity of the site, as depicted on the FEMA FIRM. Estimated flood elevations may need to be refined through the use of hydraulic modeling to support future design and permitting of proposed facility-specific adaptation measures.

### 3.2 Limited Visual Assessments

Limited visual assessments were performed of the vulnerable facilities identified in both communities, including water and wastewater collection and distribution systems, facilities, and critical equipment. The limited visual assessments consisted of site visits at the vulnerable facilities while accompanied by Town personnel. Critical water and wastewater facilities were visited, visual observations made, relative elevations recorded, and photographs taken to compile data at each site including, but not limited to, the following:

- Ground elevations (by LIDAR) around critical facilities and relative elevations of critical equipment and facility components
- Equipment locations
- Site information including erosion potential and accessibility during climatic events
- Structural components and general condition
- HVAC, controls
- Power supply and reliability
- Chemical storage
- Obvious inflow sources.

The assessment findings are summarized in the following sections for each Town, including a listing of vulnerable facilities and preliminary recommended adaptation measures, (conceptual designs and budgetary level opinions of construction cost).

## 4 Town of Charlton

### 4.1 Water System

The Town of Charlton's water system is supplied from Sturbridge and includes a water distribution system that services a portion of the municipality including along Route 20, Route 169 to the south and west, South Sturbridge Road, Stafford Street, Hammond Road, Timber Valley Road and Northside Road in a loop with Route 20, and the interconnection with Sturbridge.

The water system also has two storage tanks that contains almost a million gallons of storage to manage higher system demands and provide fire flows. Finally, there is infrastructure to the west of Northside Road that was installed but not used due to a permit denial to transfer water from Oxford. See **Figure 1** for the overall layout of the system.

#### 4.1.1 Water Availability

During initial discussions with each Town, we reviewed water supply and availability for the systems currently in place. Charlton receives water from Sturbridge and the supply is augmented by existing Storage Tanks that assist in meeting Peak supplies and providing fire protection. At this point, the Water and Sewer Superintendent believes there is sufficient water to serve the needs of the community and therefore no further investigation was completed.

### 4.2 Sewer System

The Town's wastewater system includes a Wastewater Treatment Facility (WWTF) that is just south of Route 20 between Route 169 and Carpenter Hill Road. The plant includes Rotating Biological Contactors (RBC's), clarification as well as disinfection prior to discharging to Cady Brook.

The collection system includes gravity sewer and force main throughout Town that totals almost 20 miles. Specific areas include the neighborhoods around Glen Echo Lake (4 pump stations in this area), and the area just north of the Massachusetts Turnpike near Stafford Street. The system is also south of Route 20 extending to the east near the existing schools in the area. The system also extends to the west along Route 20 ending adjacent to the Massachusetts Turnpike. See **Figure 2**.

The system also includes 10 pump stations; they are summarized in **Table 1** below.

**Table 1 - Summary of Wastewater Pump Stations in Charlton, MA**

<b>Station Number</b>	<b>Pump Station</b>	<b>Address</b>	<b>Generator Make</b>	<b>Model Number</b>	<b>Serial Number</b>	<b>Pump 1 GPM Volume Design</b>	<b>Pump 2 GPM Volume Design</b>	<b>Fuel Capacity</b>
8	Glen Echo Shore Dr.	149 Glen Echo Shore				176	176	
3	South Sturbridge Rd	10 S. Sturbridge Rd				120	120	30
1	Sturbridge Rd (MTA 5E)	Route 20 29 Sturbridge Rd	Caterpillar 508 634- 3400 SE	MDL CD0S0		150	150	85
Treatment Plant	Worcester Rd	8A Worcester Rd	Cummins 781 287- 7308	MDL 300REOZDD	S/N 2292368			1613
4	N. Main Street	53 N. Main Street	Cummins NE 781329- 1750	MDL 60 DGCB	S/N C	280	280	173
7	Burlingame Rd	63 Burlingame Rd	ONAN/Cu mmins	MDL DGDA 4958772	S/N E 010236004	220	220	194
2	J Hammond Rd (MTA 6W)	43 J Hammond Rd	Caterpillar 508 634- 3400	MDL CD 050		120	120	85
6	Muggett Hill Rd	143 Muggett Hill Rd				220	220	173
11	Vine Street	Vine Street	Cummins NE 7813291750	MDL 35.0 DGBB	S/N E0000982 42	220	220	100
9	Stevens Park Rd	65 Stevens Park				10	10	

#### 4.2.1 Vulnerable Facilities Identified in Charlton

The following were identified as vulnerable facilities given their proximity to mapped flood hazard areas as shown in **Figure 2**.

1. Old Worcester Road Pump Station (feeds into the North Main Street Pump Station) - This station is adjacent to areas prone to flooding and the station type (partially buried with all equipment below existing grade) results in critical equipment that could be affected if the areas flood.
2. North Main Street Pump Station - This station is adjacent to areas prone to flooding and the station type (partially buried with all equipment below existing grade) results in critical equipment that could be affected if the areas flood.
3. Muggett Hill Pump Station - This has flooded in the past and was converted from a Smith & Loveless partially buried station to a submersible pump station with a larger wetwell to handle additional flows.
4. South Sturbridge Road Pump Station - This facility is adjacent to Cady Brook and a former truck/equipment garage. During our visit, the area was quite wet and in a low lying area. The station was partially covered in water and the adjacent brook was running above normal elevation.
5. Stevens Park Road Pump Station - This facility is at the southern end of the lake adjacent to the road and at the bottom of a large slope that has significant runoff during wet weather events that has affected the pump station's critical components include the power and control cabinet, the security fencing and gate and the odor control equipment.
6. Route 20 (MTA 5E) Pump Station - This facility is just off Route 20 and adjacent to a 100 year flood zone. The station has critical components below grade that could flood in an extreme wet weather event.
7. J Hammond Road (MTA 6W) Pump Station - This station is at the east end of the collection system. This is adjacent to areas prone to flooding and have critical equipment below grade which could be affected.
8. Pressure Regulating Vault - This is in place along the edge of Route 20 just east of North Main Street which reportedly flooded in the past due to significant runoff in the area.

Ground elevations, 1% annual chance flood elevations, and critical elevations are summarized in the following table. One Hundred a Year flood elevations, if not available on FIRM Maps, are estimated based on location of outline for 100 year and 500 year elevations outlined on FEMA maps and comparing them to LIDAR elevations and contours shown on **Figure 1** and **Figure 2** located here:

LOCATION	LIDAR Ground Elev. (ft.)	1% Annual Chance Flood Elevation (ft.)	Critical Elevation (1% Annual Chance Flood Elevation + 3 Feet of Freeboard)
91 OLD WORCESTER ROAD	786.6	780.0*	783.0
53 NORTH MAIN STREET	860.2	855.0*	858.0
143 MUGGETT HILL ROAD	683.8	683.0*	686.0
SOUTH STURBRIDGE ROAD	645.2	645.0	648.0
STEVENS PARK ROAD	772.8	777.0*	780.0
ROUTE 20 PUMP STATION	637.0	638.0*	641.0
J HAMMOND ROAD	885.5	885.0*	888.0
PRESSURE REGULATING VAULT	820.0	817.0*	820.0

\*Estimated Flood Elevation - Base flood elevations not determined by FEMA for these locations (e.g., Zone A). Base flood elevations were estimated from LIDAR ground elevations and the 1 percent annual chance flood hazard area boundary depicted on the FEMA FIRM.



#### 4.2.2 Vulnerabilities Identified at Facilities in Charlton

Old Worcester Road Pump Station - This station is just south of an area designated as a 500 year floodplain, lies between two streams and is in a low-lying area on the south side of Old Worcester Road. The floor of the station itself is 50 inches below the current grade of 786.6 based on LIDAR elevations. Critical equipment below grade at approximate elevation of 782.4 +/- includes:

- Backup generator (1)
- Automatic transfer switch (2)
- power transformer (2)
- control panel, (3)
- the two pumps (3)
- Sump (4)



The floor of the station shows rust and there is distress at the joint between the wall and floor as seen in Photo (5).

The exterior of the station has a ventilation system for the wetwell. This is adjacent to the main electrical service for the station. See Photo (6).

The facility accepts flow from the Muggett Hill Station just to the south and east of this station and pumps wastewater west to the North Main Street Station.

Barriers are recommended to protect the station and its critical components below grade against flooding. Further, the main service outside should be protected against flooding. This can be accomplished through walls around the facility or by upgrading the facility and elevating critical components above grade in a new structure.



#### North Main Street Pump Station

This is another below grade station very similar to the Old Worcester Road Pump station. It receives flow from the Old Worcester Station before sending it to the Wastewater Treatment Facility. The station is directly adjacent to an existing stream and located between two areas designated as 500 year flood zones. The floor of the station itself is 50 inches below the current grade of 860.2 based on LIDAR elevations.



Critical equipment below grade at approximate elevation of 856.0 +/- includes:

- Backup generator (1)
- Automatic transfer switch (2)
- power transformer (2)
- control panel,
- the two pumps (3)
- Sump (4)



The exterior of the station has a ventilation system for the wetwell. This is adjacent to the main electrical service for the station. See Photo (5).

Barriers are recommended to protect the station and its critical



components below grade against flooding. Further, the main service outside should be protected against flooding. This can be accomplished by installing walls around the facility or by upgrading the facility and elevating critical components above grade in a new structure.

#### Muggett Hill Pump Station

The Muggett Hill Pump Station is located just south of Dodge Pond, a 500 year flood zone and adjacent to a tributary of the Quinebaug River which is in a 100 year



flood zone. The station used to be a partially buried pump station like the North Main Street and Old Worcester Road facilities, but there was significant flooding and the facility was damaged and then renovated. The station currently has a wetwell with submersible pumps (Photo 1). Above the wetwell, there is the main service and disconnects for the pumps installed in the wetwell (Photo 2) as well as a control panel for operating and monitoring alarms (Photo 3). The facility is surrounded by fencing and its ground elevations is 683.8 based on LIDAR information.

This facility still is in a vulnerable area prone to flooding. The facility will require further fortification by relocating the critical electrical equipment to a higher elevation to protect the power and controls from damage.

#### South Sturbridge Road Pump Station

This pump station is a wetwell submersible pump facility located just north of Route 20 and the entrance to the Wastewater Treatment Facility. It is located at the end of a parking



area for a truck company that has a variety of trucks and equipment parked on site. The Station is within a small fenced in area just north of Cady Brook and is within the 100 and 500 year floodplains delineated in **Figure 2**.

The facility has a panel for power and control beside the wetwell. It also has a ventilation and odor control system pulling air from the wetwell. Adjacent to the wetwell is an access manhole for the station's valve vault to access the force main leaving the station.

This facility is vulnerable to flooding given its proximity to Cady Brook and flood zones. The critical equipment, the electrical cabinet and Ventilation system should be raised to platforms above the 100 year flood elevation (El. 645) to protect them against damage during the 1 percent annual chance flood event.

#### Stevens Park Road Pump Station

This facility is at the southern end of Glen Echo Lake and it collects wastewater from homes in the area before pumping back to Route 31 (City Depot Road). The pump station is at the base of a large undeveloped woodland area which is just north of a solar field. The station also is at the low point in the road adjacent to a small stream that flows past it. The ground elevation in the area is 772.8 based on LIDAR information. The pump station is a wetwell submersible station with an electrical power/control panel, a ventilation system and it is surrounded by fencing for security.



Over the last few years, the surface runoff from the hill just to the south of the station (Photo 1 and Photo 2) and the road runoff from Steven's Park Road to the east have caused issues at the station. Specifically, the fence posts have heaved and the concrete pad for the electrical panel has lifted and stressed the conduit and cabinet sitting on top of the pad.

The Town has worked to limit the surface runoff from the road area by installing a small swale that collects runoff



and directs the flow in front of the existing station.

The runoff from the hill just south of the station still needs to be re-directed. The Town will look to submit an application for an MVP Action Grant to address this runoff and repair the pump station including the fencing around the facility and electrical power/control cabinet. Installing drains and bioswales around the facility is recommended to capture and redirect the runoff to the small stream adjacent to the station.


### Route 20 (MTA 5E) Pump Station

This station is located along the south side of Route 20 just west of State Route 169. This was one of two stations provided by the Massachusetts Transportation Authority (MTA) to provide sewers as a result of groundwater contamination. The facility is a dry pit submersible facility that has two levels; an upper level with normal power, backup power, an automatic transfer switch, and single phase power panels for lighting and other single phase uses. The elevation of the first floor is approximately 637.0+/- with the ground generally sloping toward the entrance.

Behind the facility is a groundwater well that enters the lower level of the building and is used to provide water to the facility's pumps for seal water.

The lower level has two Fairbanks Morse centrifugal pumps (Photo 4) that pull wastewater from the underground wetwell

(Photo 1) adjacent to the wellhouse and convey the wastewater to the east toward the wastewater treatment facility. The lower level also includes a hydropneumatic tank (Photo 5) to maintain pressure from the well water being supplied for seal water, a sump pump for any water that gets on the ground, ventilation through a large diameter (16 inch) PVC pipe from the upper level, a dehumidifier that drains to the sump and a unit heater.



This facility is within the 100 year floodplain that extends from Sibley's Pond to the south and east before connecting to Cady Brook. The most vulnerable components in the facility are in the lower level but the conduit and receptacles are protected and watertight.

A barrier is recommended to redirect flood flows away from the building and the entrance to limit the possibility of water entering the facility and causing damage.

### J Hammond Road (MTA 6W) Pump Station

This station is located on J. Hammond Road just north of the Massachusetts Turnpike (Route 90) adjacent to one of the service areas. This was the other station provided by the Massachusetts Transportation Authority (MTA) to provide sewers as a result of groundwater contamination.

The facility is a dry pit submersible facility that has three levels; an upper level with normal power, backup power, an automatic transfer switch, and single phase power panels for lighting and other single phase uses. The elevation of the first floor is approximately 895.5+/- with the ground generally sloping back from the road toward the entrance. Behind the facility is a groundwater



well that enters the second level of the building and is used to provide water to the facility's pumps for seal water.

The facility is 30 feet deep with the intermediate level (10 feet below first floor elevation) that includes a hydropneumatic tank (Photo 3) to maintain pressure from the well water being supplied for seal water. The lowest level (20 feet below grade) has two Fairbanks Morse centrifugal pumps (Photo 4) that pull wastewater from the underground wetwell adjacent to the wellhouse and convey the wastewater to the west toward the wastewater treatment facility.

The lower level also includes a sump pump for any water that gets on the ground, ventilation through a large diameter (16 inch) PVC pipe from the upper level, a dehumidifier that drains to the sump and a unit heater.




This facility is just south of a 500 year flood zone that runs to the east and south of Route 90 toward three other 500 year flood zones. The most vulnerable components in this facility are also in the lower levels but the conduits and receptacles are protected and watertight.

A barrier is recommended to redirect flood flows away from the building and the entrance to limit the possibility of water entering the facility and causing damage.

#### Pressure Regulating Vault

A Pressure Regulating Vault (PRV) for the water system on the north side of Route 20 that floods occasionally due to surface runoff and high groundwater levels. The vault is in front of commercial buildings just west of Stafford Lane and adjacent to a grass swale along Route 20.

Runoff should be redirected around the facility and the vault should be modified with a watertight cover to reduce the potential for flooding and water entering the structure.





## 5 Town of Spencer

### 5.1 Water System

Spencer's water system consists of two sources of supply, the Seven Mile River Wellfield and the Cranberry Wellfield. Each produces enough water to service the entire community. The Seven Mile Wellfield is adjacent to the Water Treatment Plant on Meadow Road and just east of the Seven Mile River and the regulatory floodway. The Cranberry Wellfield is off South Spencer Road and just south of the existing Wastewater Treatment Facility. See **Figure 3**.

The distribution system's spine runs along Route 9 from the edge of East Brookfield through the center of Town and out to the east to the Town of Leicester and Shaw Pond. There are also numerous feeds to the north and to the south from Route 9 for the distribution system. See **Figure 3**. There are two storage tanks, the Moose Hill Tank and the Highland Street Tank, within the system providing additional supply for peak demands, emergency supply and fire protection.

#### 5.1.1 Water Availability

Spencer has two sources of supply, the Cranberry and the Seven Mile River wells. Each well is capable of meeting daily demands within the system and the supplies are again enhanced by two existing storage tanks that help with meeting peak demands and providing fire protection. Having two wells, both capable of meeting demands and ample storage, resulted in no further investigation into assessing water availability in this study.

### 5.2 Wastewater System

The wastewater collection system is shown in **Figure 4**. The system is predominantly gravity fed with only one (1) pump station on Meadow Street adjacent to Fourth Avenue. This pump station carries an approximately 10 percent of the wastewater from the northern portion of Town down to the Wastewater Treatment Facility (WWTF) which is off Route 9 just to the east of the Podunk Turnpike.

#### 5.2.1 Vulnerable Facilities Identified in Spencer

The following were identified as vulnerable facilities given their proximity to mapped flood hazard areas as shown in **Figure 3** and **Figure 4**.

1. Seven Mile River Wellfield - The wellfield is located just west of the Seven Mile River and the existing water treatment plant. There is a small access road and it has been affected by beaver activity re-routing portions of the river and leading to flooding potential impacts on the power and control equipment adjacent to the well.
2. The Cranberry Wellfield – The wellfield is located south and east of the existing wastewater treatment facility of South Spencer Road. The wellfield includes 3 buildings; the building which houses the well and electrical equipment; and the building used to store and inject chemicals for the water supply including sodium hypochlorite and sodium hydroxide for pH adjustment. The third building is used for material and equipment storage.
3. The Wastewater Pump Station on Meadow Road - This facility is along the edge of the road and directly adjacent to the Seven Mile River and regulatory floodway as well as Fourth Avenue. Given it conveys (10%) of the flows to the wastewater treatment facility, this critical station, if flooded or disabled, could result in significant discharge of untreated wastewater to the river.



4. UV disinfection system at the discharge end of the Wastewater Treatment Facility - This equipment is in a low-lying area just south of the existing lagoons and just prior to the discharge to the Cranberry River.
5. Low-lying area off Adams Street near Spencer Pond - There is sewer pipe and water main in this area that could be affected by flooding or overflow of the Pond during extreme wet weather events.

Ground elevations, 1% annual chance flood elevations, and critical elevations are summarized below. One Hundred Year flood elevations, if not available on FIRM Maps, are estimated based on location of outline for 100 year and 500 year elevations outlined on FEMA maps and comparing them to LIDAR elevations and contours shown on **Figure 3** and **Figure 4** located here:


LOCATION	LIDAR Ground Elev. (ft.)	1% Annual Chance Flood Elevation (ft.)	Critical Elevation (1% Annual Chance Flood Elevation+3 Feet of Freeboard)
SEVEN MILE RIVER WELLFIELD	631.3	635.5	638.5
CRANBERRY WELLFIELD	634.6	642.0	645.0
MEADOW ROAD PUMP STATION	635.0	634.5	637.5
UV DISINFECTION SYSTEM AT WWTF	634.1	641.1	644.1
LOW LYING AREAS - ADAMS STREET	812.6	816.0*	819.0

\*Estimated Flood Elevation - Base flood elevations not determined by FEMA for these locations (e.g., Zone A). Base flood elevations were estimated from LIDAR ground elevations and the 1 percent annual chance flood hazard area boundary depicted on the FEMA FIRM.

### 5.2.2 Vulnerabilities Identified at Facilities in Spencer

#### Seven Mile River Wellfield

This is one of the two groundwater supplies for the Town. Each well is capable of providing enough supply for the entire community. This well is within the 100 year flood zone and regulatory floodway area associated with the Seven Mile River (See **Figure 3** for the Water System). The well is west of the Water Treatment Facility and in close proximity to the western edge (85 feet) of the River.



The well casing extends 6 feet 8 inches (See Photo 1) above the ground elevation of approximately 631.3 using LIDAR elevations. This is 2 feet 6 inches above the 100 year flood elevation of 635.5 based on FEMA mapping.



The power junction box and conduit is only 8 inches about the ground surface (Photo 2). This was surrounded by water during our visits and could be flooded/damaged during significant rain events and beaver activity that could lead to re-routing the river and expansion of the water to this area.




Raising the electrical junction box or relocating this box and installing watertight conduit would further protect this supply from not being available during flooding events.

#### The Cranberry Wellfield

This is the other groundwater Supply for the Town. The facility is located off of South Spencer Road and consists of three buildings; the wellhouse, the chemical treatment, and a storage facility for materials and equipment. The facility lies within the 100 year flood zone of the Cranberry River that wraps around the wellhouse facility.




The floor elevation for the wellhouse is approximately 634.6 which is over 7 feet above the 100 year flood elevation. The only electrical equipment which is susceptible to flooding is the MCC which rest on a housekeeping pad only 4 inches above the floor (Photo 1) and an electrical control cabinet which is 33 inches above the floor.



Just outside the building is the main power transformer for the site which rests on the ground (Photo 2). This would be adversely affected if the site was flooded. This should be raised to protect it against potential flooding.

The chemical feed building includes storage and containment for sodium hypochlorite (used for disinfection) and sodium hydroxide (used for pH adjustment). There are also cabinets for electrical power and control, chemical analyzers, and ventilation equipment.



All equipment is well above the floor except a junction box which is only 6 inches above the floor (Photo 3).

This junction box should be relocated to a higher elevation to protect wiring for the critical equipment in the building.

#### The Wastewater Pump Station on Meadow Road

This facility is on Meadow Road just south of Fourth Avenue. It lies on the west side of the road and is adjacent to the 100 year flood zone and regulatory floodway associated with the Seven Mile River. The elevation of the pump station is 635.0 +/- based on LIDAR elevations. This very close to the 100 year flood elevation in the area of 634.5 (See Photo 1). The station entrance is flush with the ground elevation in the area and there is critical equipment very close to the ground elevation. This includes the backup generator (6 inches off the




ground on a housekeeping pad) and the liquid propane storage tank (also on a concrete pad just 6 inches off the ground). See Photo 2.



Other critical components include:

- SCADA Control Panel (3 feet off the floor - Photo 3)
- Pump Control Panel (3 feet off the floor - Photo 4)
- Three Phase Panel (19 in. off floor - Photo 5)
- Auto. Transfer Switch (ATS) (17 in. off floor - Photo 5)
- Centrifugal Pumps (30 in. off floor - Photo 6)

Because the elevations of critical components of the pump station are very close to the 100 year flood elevation, fortification of the critical equipment including the backup generator, and propane storage tank as well as the items less than 3 feet off the floor should be considered. This would require the electrical cabinets, the ATS and the pumps be raised at least 3 feet above the floor.



#### UV Disinfection System at the Discharge of the Wastewater Treatment Facility

The Spencer Treatment Facility has a UV disinfection system for its wastewater prior to being discharged to the Cranberry River. The UV Disinfection System is at the end of the Treatment Facility and runs through a channel before being directed to the discharge for the plant.

Adjacent to the UV System is small control building that has power and control features for the system. This includes a power panel, a transformer for single phase power and a control panel for the UV system. The elevation




of the area is approximately 639.7 based on LIDAR elevations. All electrical components are at least 3.5 feet above the floor elevation and should not be affected by the 1 percent chance of flood.

The top of the channel for the UV system is 74 inches below the floor of the main building for the UV system or at an elevation of approximately 634.1. This is an estimated 7 feet above the 100 year flood elevation in the Cranberry River for this area. James LaPlante, WWTP Superintendent, has stated however, that he has seen waters at just below the top of the wall for the UV channel in the past during flooding and heavy rainfall events.

The Town has discussed the possibility of relocating this facility if additional treatment is required and added. Specifically, if tertiary treatment is added in lieu of the existing lagoons, the Town feels moving the UV system up closer to the plant would alleviate the potential for this system to be compromised, if flooding occurs.

In the meantime, the addition of a flood protection barrier is recommended to mitigate possible flooding in the area as seen in the past.

#### Low lying area off Adams Street near Spencer Pond



Adams Street

This area around the Spencer Pond has a sewer collection system and water main within Adams Street that could potentially be flooded or exposed during a major rainfall event that causes scour or erosion. Further, this area has a downstream culvert and gate structure on Charlton Road that could become blocked or plugged leading to water levels increasing in the Pond and causing

local flooding in this area.



Culvert and I/I Area

Finally, the area has been identified by others as having a significant Infiltration/Inflow problem based on studies and investigations completed previously. Any flooding could result in additional I/I entering the system which could be conveyed to the plant and adversely affect the wastewater treatment facility and lead to violations of the discharge permit.

This area should be monitored during heavy rainfall events to confirm water is flowing through the outlet culvert so as not to allow water levels to rise in the pond and local flooding to occur.


#### **6 Resiliency Recommendations - Charlton**

The following are recommendations for the critical facilities and equipment identified within the Town of Charlton. Each is discussed in more detail below and budgetary level opinions of cost are included for each facility in Appendix A.

#### Old Worcester Road Pump Station and North Main Street Pump Station

These pump stations are partially buried pump stations within Old Worcester Road pumping to North Main Street. The facilities are 50 inches below grade with all critical equipment including the pumps, generator, automatic transfer switch, transformer, and control panel included. Resiliency


recommendations to protect the facility from flooding given their proximity to flood zones range from providing a barrier around the structure to minimize floodwaters from entering the partially buried station to constructing a new above-ground facility and locating all critical components above the base flood elevation. For this effort, we have budgeted for providing a barrier around the existing structure. A conceptual layout of the proposed improvements is included in the sketch shown below.



#### Muggett Hill Pump Station

This station has flooded in the past and was converted from a partially buried station to a submersible pump station with a larger wetwell to handle additional flows with a local service, control panel and communications located on a stand over three (3) feet above ground. There is no generator for backup power. This facility is directly downstream from Dodge Pond and a 500 year flood zone.

Resiliency improvements for this site include providing drainage swales to guide runoff and floodwaters away from the structures and raising the electrical equipment to further fortify these critical items.





### South Sturbridge Road Pump Station

This facility is another wetwell pump station which is in a low lying area adjacent to a truck parking area and garage. The facility has a power/control panel and ventilation/odor control system above grade within the fenced in area. The station is adjacent to the 100 and 500 year flood zones for Cady Brook. There is no generator for backup power.



Resiliency improvements for this site include providing drainage swales to guide runoff and floodwaters away from the structures and raising the electrical equipment to further fortify these critical items.

Raise Electrical Components


### Stevens Park Road Pump Station

This facility is at the southern end of Glen Echo Lake adjacent to Stevens Park Road and at the bottom of a large slope that has significant runoff during wet weather events. This runoff has affected the pump station's critical components including the power and control cabinet, the security fencing and gate and the ventilation/odor control equipment.



Recommendations include:

- Re-direct runoff from the hill to the north of the station,
- Better define and guide street runoff from the road east of the station,
- Re-set electrical panel on new concrete pad,
- Re-set fencing around the facility to mitigate poles and fencing that have heaved,
- Re-set ventilation system in new concrete pad at higher elevation
- Grading improvements around station to accommodate new drainage work and improve water quality through bioswales




### Route 20 (MTA 5E) Pump Station

This facility is just off Route 20 and adjacent to a 100 year flood zone associated with Sibley's Pond to the west and draining towards Cady Brook which runs south.

The building has two stories with the upper level housing the generator, transfer switch, power and control panels and a transformer for single phase equipment. Most electrical panels are above the floor ( $>3$  feet) and conduit and receptacles are watertight. The lower level has the piping, pumps, a dehumidifier, unit heater and hydropneumatic tank and piping for the seal water for the pumps. All conduit and receptacles in this area are watertight.

Resiliency recommendations for this facility would include:

- Providing a protective barrier for the main entrance to minimize water entering the building
- Install a watertight hatch over the access entrance to the level of the facility
- Seal penetrations between main level and lower level (conduits and ventilation)




lower

### J Hammond Road (MTA 6W) Pump Station

This station is located just north of the Massachusetts Turnpike (Route 90) adjacent to one of the service areas. The facility is just south of a 500 year flood zone and is adjacent to a small stream which flows by the facility.

The building has three stories with the upper level housing the generator, transfer switch, power and control panels and a transformer for single phase equipment. Most electrical panels are above the floor ( $>3$  feet) and conduit and receptacles are watertight.




The middle level has piping from the groundwater well that feeds a hydropneumatic tank to maintain pressure for water being provided to the pumps for seal water. This level has conduits that extend to the lower level as well as a 16 inch PVC pipe used for ventilation for the lower level.

The lowest level (20 feet below grade) includes piping, pumps, a dehumidifier, unit heater, sump and pump and piping for the seal water for the pumps. All conduit and receptacles in this area are watertight.

Resiliency recommendations for this facility would include:


- Providing a protective barrier for the main entrance to minimize water entering the building
- Install a watertight hatch over the access entrance to the lower levels of the facility
- Seal penetrations between main level and lower levels (conduits and ventilation)



#### Pressure Regulating Vault

There is a Pressure Regulating Vault (PRV) for the water system on the north side of Route 20 in front of commercial buildings just west of Stafford Lane and adjacent to a grass swale along Route 20. This vault occasionally floods due to surface runoff and high groundwater levels.

Resiliency measures proposed include: 1) re-directing runoff in the area and 2) modifying the vault structure to minimize water and groundwater inflow.



Pressure Regulating Vault - Charlton Water System

## 7 Resiliency Recommendations - Spencer

The following are recommendations for the critical facilities and equipment identified within the Town of Spencer. Each is discussed in more detail below and budgetary level opinions of cost are included for each facility in Appendix B.

#### Seven Mile River Wellfield

This is one of two wells that provide all the water supply for the Town. It is located just west of the Seven Mile River and the associated 100 year flood zone and regulatory floodway. It is also west of the existing water treatment plant which it provides water to. There is a small access road to the wellhead off Smithville Road.



The well and its associated electrical equipment has been affected by beaver activity re-routing portions of the river and leading to potential flooding impacts on the power and control equipment adjacent to the well.

Raise Electrical Equipment