


*Massachusetts Coastal Infrastructure
Inventory and Assessment Project
Massachusetts Department of Conservation and Recreation
Office of Waterways*

Cape Ann

Gloucester
Rockport



July 6, 2009

Prepared for:

**Massachusetts Department of
Conservation and Recreation
Hingham, Massachusetts**

Presented by:

**Bourne Consulting Engineering
Franklin, Massachusetts**

Cape Ann

TABLE OF CONTENTS

Section I – Coastal Hazards Infrastructure and Assessment Program

INTRODUCTION

PURPOSE

DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES

DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS

Section II - Gloucester

Part A - Community Findings

- **COMMUNITY DESCRIPTION**
- **STRUCTURE INVENTORY**
- **SUMMARY OF FINDINGS**

Part B - Structure Assessment Reports

Part C - Structure Photographs

Part D - Structure Documents

- **CITY DOCUMENT LIST**
 - Document Table
- **MA DCR – DOCUMENT LIST**
 - Document Table
- **MA DEP – CH 91 DOCUMENT LIST**
 - Document Table
 - Copies of License Documents
- **USACE – PERMIT DOCUMENT LIST**
 - Document Table
 - Copies of Permit Documents

Cape Ann

Section III - Rockport

Part A - Community Findings

- COMMUNITY DESCRIPTION
- STRUCTURE INVENTORY
- SUMMARY OF FINDINGS

Part B - Structure Assessment Reports

Part C - Structure Photographs

Part D - Structure Documents

- TOWN DOCUMENT LIST
 - Document Table
- MA DCR – DOCUMENT LIST
 - Document Table
- MA DEP – CH 91 DOCUMENT LIST
 - Document Table
 - Copies of License Documents
- USACE – PERMIT DOCUMENT LIST
 - Document Table
 - Copies of Permit Documents

Section I

Coastal Hazards Infrastructure and Assessment Program

INTRODUCTION

PURPOSE

DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES

DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS

***Massachusetts Coastal Infrastructure
Inventory and Assessment Project
Coastal Hazards Commission***

Section I – Coastal Hazards Infrastructure and Assessment Program

INTRODUCTION

The Project and Client

The Commonwealth of Massachusetts has initiated a Coastal Hazards Commission (CHC) to identify the vulnerability of the state to coastal hazards. As one of five working groups working under the CHC, the 20-Yr Infrastructure Plan was to establish a prioritization for the repair of coastal structures. The focus areas of the Working Group include:

- Publicly owned infrastructure
- Infrastructure for which State is responsible
- Inventory of public hazards infrastructure
- Evaluation on conditions
- Development for a prioritization of work
- Estimation of capital and maintenance costs

The 20-Yr Infrastructure Working Group is led by Representative Frank Hynes with CZM as the lead State Agency overseeing the management of the project. The Massachusetts coastline has been broken up into 4 major regions consisting of the North Shore, Boston, South Coast, and the Cape and Islands. The South Shore (the Towns of Hull, Cohasset, Seekonk, Hingham, Plymouth, Kingston, Scituate and Duxbury) was previously evaluated by Bourne Consulting Engineering as a demonstration project in 2006.

Consultant Team

The consultant team that performed the demonstration project was led by Bourne Consulting Engineering (**BCE**) of Franklin, MA who was responsible for overall project management, specified areas of field assessments, and research. Assisting **BCE** was Applied Coastal Research and Engineering Inc. of Mashpee, MA, Childs Engineering Corporation, of Medfield, MA., and Waterfront Engineer LLC of Stratham, NH.

PURPOSE

Study Purpose

CZM seeks to identify the capacity of Massachusetts coastal structures to resist major coastal storms and prevent storm damage. In working toward this goal, CZM has initiated a program to perform an assessment of Commonwealth owned and/or maintained coastal structures. The first phase of this program was the performance of a demonstration project for coastal structures located on the South Shore. The demonstration project identified existing structures, their general conditions, ability to provide coastal protection and the probable cost for repairs. The information collected and developed has been incorporated into the MassGIS system to allow use for developing a 20 Year Coastal Infrastructure Plan.

The demonstration project served as a basis for the current statewide inventory assessment of all Commonwealth coastal structures and the needs for their maintenance and/or repair.

Goals of Study

The goals of the Massachusetts Coastal Infrastructure Inventory and Assessment Project include:

- To identify all the coastal structures the state either owns or has responsibility to maintain for the 4 regions included within the study
- Of the structures identified, determine the structure location and characteristics, the structure condition relative to providing coastal protection and the structure importance in relation to what it is protecting.
- To the degree possible, identify the structure elevation and the FIRM mapping flood elevation and category.
- To the degree possible, identify structure owner and available documents from local, state and federal agencies.
- To establish an estimated cost to rehabilitate the coastal structures to provide the level of project established in the structure's original design.
- Provide the information in a format compatible for incorporation into the MassGIS system

Limit of Study

Due to the time constraints and the amount of effort necessary to collect, process and compile the information, the following are identified as limitations of the information presented:

- All property ownership was taken as presumed. No legal investigation of ownership was performed during the project. Property ownership is based on town assessor maps. Where structures were located outshore of assessor map defined property lines, it was assumed to be Town land unless other information indicated otherwise. Where structures were located outshore of Mean Low Water, property is assumed to be State owned.
- The structure ownership was based on assessor maps and research at the local, state and federal levels. Where there was indication of public work on a structure on Town land or on private property, the structure was presumed to be Town owned. Where the structure was on state property, the structure was presumed to be state owned. Where ownership of the structure was not clear but was located on private property, the structure ownership was defined as unknown.
- The study included town and state owned structures as it was assumed that most town owned structures received state funding at some level for construction and/or maintenance.
 - Structures that were determined to be private were not included.
 - Undocumented structures considered to be on private land, but having the potential to have been publicly built and/or maintained, were identified as having an "unknown ownership".
- The prioritizing of structures was based primarily on risk to general infrastructure and density of housing. Infrastructure included was buildings. The study did not consider all infrastructure issues including:
 - No consideration on utility impacts – water, electrical, sewer, gas
 - No consideration of roadway and bridge protection
 - Evacuation routes were not considered within the investigation
 - Location of Emergency Shelters were not included in priority assessments
- Research was performed at the local, state and federal levels. The local research was limited to location and documenting available coastal structure contract drawings. Research at DCR was restricted to available historic construction plans for coastal structures at the MA-DCR Waterways office in Hingham, MA, and MA-DCR Division of Urban Parks and Recreation in

Boston, MA. No investigation of state archives was performed. Research at MA DEP Chapter 91 and USACE was limited to recorded permits and licenses found in their files. No investigation was performed at the Registry of Deeds.

DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES

The specific attributes that would be incorporated into the MassGIS system were developed based on the scope of work and the goals to be achieved. The following was established to standardize the data collection and presentation and to allow total flexibility for sorting by attributes in the final GIS database. The attributes identified below were input into a MS Access database which was used to manage the data from all eight communities within a single file.

Database Attributes

- **Attribute Descriptions/Definitions**

Structure Number: A unique structure number was given to each coastal structure. The number was based on existing numbering systems that include the State Department of Environmental Protection community number followed by the local community assessor's parcel numbering system. The last three digits of the number represent the structure within the parcel. Where structures extend over several parcels, the structure is referenced to a parcel that is approximately in the center of the structure. Where Town assessor's references include letters, those are also included within the structure number. Some communities have block numbering within their numbering system and these are included. Communities without block numbering still have the block numbering included but these are illustrated as all zeros for that specific segment.

Structures that are on Town property, which would otherwise not have a parcel number, are referenced to a parcel that is in the immediate vicinity of the coastal structure.

On this basis, the following is the general numbering convention:

CCC-MMM-BBB-PPP-SSS

Where:	CCC	DEP Community Number
	MMM	Community Map Number
	BBB	Block Number (000 if no block numbering system)
	PPP	Community Parcel Number
	SSS	Structure Number

Property Ownership: All property ownership was on a "presumed" basis as no legal verification of ownership was performed. The ownership of the property was classified under four basic areas which were private ownership (Private), Town ownership (Local), Commonwealth of Massachusetts ownership (State), federal government ownership (Federal) or unknown. Property ownership was based on Town assessor's maps. Where the location was located above Mean Low Water, and not within a defined parcel, the property ownership was presumed to be the Town unless documentation was found to indicate otherwise. Where a structure was located offshore of Mean Low Water, the property ownership was presumed to be federal.

Structure Ownership: The ownership of all structures is presumed as no verification of ownership was performed. Ownership of the structure was determined by research into historic state and federal

permits and the entity indicated on the permits as the applicant. Where no other information was found, the following was utilized:

- Structures located on private land but appearing to be significant structures were identified as owned by the Town or as "Unknown". Unknown was used where there was a question of local or private ownership.
- Structures on Town property were assumed to be owned by the Town
- Structures that were located off-shore were presumed to be federally owned
- Structures that were identified as being privately owned were eliminated from the database

Basis of Ownership: The basis of structure ownership was provided to give rationale to the structure ownership and identified the research resource that identified the ownership or the methodology otherwise used. The responses utilized were limited to the following:

- DPW – DPW Employee Interview
- DCR - Contract Drawings
- DEP – Ch 91 License
- USACE – Permits
- Property Ownership
- Offshore Structure

Structure Owner's Name: Ownerships names reflect the presumed owner of publicly owned structures. As this was for public structures only, the ownership was restricted to the community name, the state agency or the federal agency.

Earliest Structure Record: The year of the oldest document located for the structure. The information is determined from the document research performed on the structure from local, state and federal agencies. If no documents could be found than this entry is denoted as "Unknown". Where documentation of the structure could be found, the date from the oldest document was utilized.

Primary Structure / Secondary Structure: Many of the coastal structures consisted of combined structures which were rated separately. It was typically found that one structure was significantly more predominant (Ex. Bulkhead/Seawall) and was therefore identified as the Primary Structure while a smaller structure might exist in front (ex. Revetment) of it. The type, height and material of each structure are identified separately. The condition of each structure was based on the Primary Structure. Where there was no secondary structure, the fields were left blank.

Structure Type: The structure type was categorized into five basic coastal structure categories which were Bulkhead/Seawall, Revetment, Coastal Beach, Coastal Dune, and Jetty/Groin.

Structure Material: The identification of the coastal structure's material of construction was performed and represents the primary material. Stone structures consisted of both mortared and non-mortared conditions.

Structure Height: Each type of structure was categorized by its visible height in feet which was broken into four specific ranges which are:

< 5 feet 5 to 10 feet 10 to 15 feet >15 feet

Structure Condition: A preliminary assessment of the condition for each structure was performed by the field teams. This was by visual observation only and no detailed investigation was performed. The condition assessments were based on a predefined five level rating system that ranged from Rating A for Excellent Condition to Rating F for Critical Condition. A detailed listing of the conditions and their definitions can be seen in Exhibit A.

Priority Rating: In order to account for the need for protection at any one site, a five level priority rating system was established. This allowed for consideration of public infrastructure protection, density of residential housing for development of structure overall importance for coastal protection. The ratings range from Level 1 for no infrastructure or residence protection to Level 5 for critical inshore infrastructure protection and/or high density residential. The detailed listing and definitions for the priority categories can be seen in Exhibit B.

Structure Repair / Reconstruction Cost: A preliminary estimation of construction costs to maintain or repair structures was made based on the preliminary field assessment of the structures. A Repair Cost Matrix was developed based on structure type, condition, height and material and can be seen in Exhibit C. Once each structure's type, height, and material classifications were determined, the cost per foot for the structure was determine from the Repair Cost Matrix and multiplied by the length of the structure to obtain the estimated repair/restoration cost. The cost matrix repair costs include a 20 percent construction cost contingency as well as 10 percent costs for engineering and permitting.

Structure Length: The length of each structure is provided and utilized in the development of the repair/reconstruction costs. The lengths are given to the nearest foot and taken as the linear distance along the structure, as determined by the GPS location, which takes into account structure angles and curvature.

Structure Elevation: The elevation of structures was determined in feet from existing information where available. The datum used is NAVD 88 and elevations are to the nearest foot. From a previous study much of the south shore coastal structures had elevations defined based on LIDAR mapping data. Where available structure documentation with elevations was found, in areas with no LIDAR data, the information was included within the structure information. Where there was no LIDAR information or existing documentation, the item has been left blank.

LIDAR (Light Detection and Ranging) is technology that is currently being used for high-resolution topographic mapping by mounting a LIDAR sensor, integrated with Global Positioning System (GPS) and inertial measurement unit (IMU) technology, to the bottom of aircraft and measuring the pulse return rate to determine surface elevations.

FEMA Zone and Elevation: For each structure the FEMA Flood Insurance Rate Maps (FIRM) were researched for their Flood Zone designation and their Base Flood Elevation from the most recent FIRM maps for the specific Town. The elevations are provided in feet on the same datum as the FIRM maps (NGVD) with no adjustments or conversions.

Structure Comments: The engineering team provided a brief description and comment on the structure at the time of the field assessments which is provided in support of the condition rating that was given for the structure.

Pictures: At the time of the field assessments, digital photographs were taken to provide a general overview of the structure. The number of pictures was limited to a maximum of six. The first photograph for each structure is shown on the Structure Assessment Form. The list of all photographs is provided on the form.

Town Documents: Town documents represent the structure information that could be found in the Town's DPW/Engineering Department records. Where particular records could be found, a table of document information was developed and included within the database with limited descriptions.

MA - DCR Documents: MA-DCR documents represent the structure information that could be found within DCR – Waterways office in Hingham. Where particular records could be found, a table of document information was developed and included within the database with limited descriptions.

MA - DEP Chp. 91 Licenses: MA-DEP Chapter 91 license documents represent the structure information that could be found within MA-DEP Chp 91 records in Boston. Where particular records could be found, they were scanned as pdf files and attached to the structure through the GIS database information. In addition, a table of license document information was developed and included within the database with limited descriptions.

USACE Permits: USACE Permits represent the structure information that could be found within the Army Corp of Engineers regulatory office in Concord, MA. Where particular records could be found, they were scanned as pdf files and attached to the structure through the GIS database information. In addition, a table of license document information was developed and included within the database with limited descriptions.

DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS

A matrix to be used within the database has been developed to assess likely rehabilitation/repair costs to restore the coastal structures to their original design condition. No attempt was made to assess the level of exposure and associated level of protection that might be required to meet current design standards for these structures. These costs are only an estimation to bring these structures back to their original design intent based on 2006 construction costs.

The development of the cost matrix is based on the following:

Structure Condition Ratings -- The condition of the coastal structures was determined in the field by the survey crew which was led by an engineer with waterfront structure assessment and design experience. The definitions of the rating criteria utilized for the assessments are presented elsewhere.

The cost implications for each rating condition are as follows:

- **A Rating** Structures not requiring any maintenance, repair or rehabilitation cost and would not be expected to experience damage if subject to a major coastal storm event
- **B Rating** Structures requiring limited or no repair and would be expected to experience only minor damage if subject to a major coastal storm event. The value of these maintenance costs is assumed to be 10 percent of the construction cost.
- **C Rating** Structures requiring moderate to significant level of repair or reconstruction and would be expected to experience significant damage if subject to a major coastal storm event. The structure is presumed to be effective under a major storm event. The value of the repair costs is assumed to be 50 percent of the construction cost.
- **D Rating** Structures requiring significant level of rehabilitation or total reconstruction and would be expected to experience significant damage or possibly fail if subject to a major coastal storm event. The value of the repair costs is assumed to be 100 percent of the construction cost.

- **F Rating** Structures requiring complete reconstruction and would expect to provide little or no protection from a major coastal storm event. The value of the repair costs is assumed to be 100 percent of the construction cost plus a cost for removal/disposal of the original structure.

Height of Structure – Height of a structure is a major factor in the structure cost and therefore was identified as a significant factor in assessing rehabilitation/repair construction costs. The structures were broken down into four major categories which were:

< 5'	Structures that were less than five feet in height
5'-10'	Structures five to 10 feet in height
10'-15'	Structures over 10 feet to 15 feet in height
> 15'	Structures greater than 15 feet in height – assumed 20 feet typical

Length of Structure – Length is based on field GPS location with measurements rounded to the nearest foot.

Bulkhead / Seawall Structures – These structures are assumed to be constructed out of concrete, steel, stone or wood with each having its own criteria for establishing costs. For each structure type the following was assumed:

- **Concrete Seawalls** – These walls were assumed to be gravity structures with the volume of concrete used based on the bottom width being one-half of the structure height. Costs of construction were based on a per cubic yard estimate that varied from \$350 to \$630 per cubic yard depending on the structure height. Values for excavation and demolition of existing structure were also included.
- **Stone Seawalls** - These walls were treated the same as concrete seawalls and assumed to be gravity structures with the volume of the structure based on the bottom width being one-half of the structure height. Costs of construction were based on a per cubic yard estimate that varied from \$350 to \$630 per cubic yard depending on the structure height. Values for excavation and demolition of existing structure were also included.
- **Steel Bulkheads** – Steel bulkheads were presumed to be constructed with steel sheet piling. Tie back systems were presumed for structures 10 feet or greater in height. Shorter walls were assumed to have a cantilever design. The total depth of sheeting was presumed to be two times the exposed height. The cost for construction varied from \$40 per square foot to \$60 per square foot plus the cost of excavation and demolition.
- **Timber Bulkheads** – Timber bulkheads were presumed to be constructed with timber piles at eight foot on center, horizontal wales and vertical four inch sheathing. The unit costs for installed materials used were \$1,500 per pile and \$7.50 per bfm.

Revetment Structures – Revetment structures were presumed to be constructed of dry placed (no concrete) stone with a two on one slope and a horizontal toe and crown equal to the thickness layer established for each height condition. The total thickness of the revetment layers varied from six to ten feet with the cost of armor and under-layer stone assumed to be \$50 per ton and the crushed stone base to be \$15 per ton.

**MASSACHUSETTS COASTAL INFRASTRUCTURE
INVENTORY AND ASSESSMENT DEMONSTRATION PROJECT**

Groins and Jetties – Groins and jetties were assumed to be the same materials and construction as the revetment structures but would have two sides and therefore double the quantities.

Coastal Beaches – Costs for restoration of Coastal beaches presumed the placement of beach renourishment sands at a 1-on-20 slope over the existing beach conditions. The cost for deposition of sand assumed relatively close source of material and utilized \$20 per cubic yard for the material installed.

Coastal Dunes – Restoration of coastal dunes assumed a cross section of renourished sand with a one-on-four slope on one side of a 25 foot width at the defined dune height. The cost for deposition of sand assumed relatively close source of material and utilized \$20 per cubic yard for the material installed.

Contingency – A contingency of 20 percent was added to all costs to reflect the unknowns associated with this level of rehabilitation/repair estimating.

Engineering and Regulatory Approvals – A ten percent increase to the cost matrix prices was assessed to represent the engineering design and regulatory approval requirements for the restoration of these structures.

EXHIBIT A

Structure Condition Table – 5 Level Rating System

Preliminary Condition Assessment		Definition Based Upon Perceived Immediacy of Action and Potential to Cause Damage if Not Corrected	Level of Action Required
A	Excellent	Like new condition. Structure expected to withstand major coastal storm without damage. Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm	None
B	Good	Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure	Minor
C	Fair	Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide additional material for full protection and extended life	Moderate
D	Poor	Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.	Major
F	Critical	Conditions of structure/landform may warrant emergency stabilization as failure may result in potential loss of property and/or life. Landform eroded, loss of integrity Structure exhibits critical levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure provides little or no protection from a major coastal storm. Actions taken to totally reconstruct structure to regain full capacity. Landform stability is severely compromised, rate of erosion/material loss may be increasing, and landform does not provide adequate protection from a major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.	Immediate

EXHIBIT B

Priority Rating System - 5 Level Rating System

Preliminary Priority Level Assessment		Level Based Upon Perceived Immediacy of Action and Presence of Potential Risk to Inshore Structures if Not Corrected	Level of Action Required
I	None	No Inshore Structures or Residential Dwelling Units Present	Long Term Planning Considerations
II	Low Priority	Inshore Structures Present with Limited potential for Significant Infrastructure Damage	Future Project Consideration
III	Moderate Priority	Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)	Consider for Active Project Improvement Listing
IV	High Priority	High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)	Consider for Next Project Construction Listing
V	Immediate / Highest Priority	Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Conditions of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)	Consider For Immediate Action Due to Public Safety and Welfare Issues

**MASSACHUSETTS COASTAL INFRASTRUCTURE
INVENTORY AND ASSESSMENT DEMONSTRATION PROJECT**

CZM SOUTH SHORE COASTAL INFRASTRUCTURE INVENTORY AND ASSESMENT PROJECT

EXHIBIT C

REPAIR / REHABILITATION COSTING DATA

September 14, 2006

Cost per linear foot of structure

STRUCTURE TYPE	STRUCTURE MATERIALS	STRUCTURE HEIGHT	A	B	C	D	F
BULKHEAD/ SEAWALL	CONCRETE	Under 5 Feet	\$0	\$84	\$425	\$850	\$983
		5 To 10 Feet	\$0	\$152	\$759	\$1,518	\$1,782
		10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,970
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$4,752
	STEEL	Under 5 Feet	\$0	\$54	\$273	\$546	\$680
		5 To 10 Feet	\$0	\$185	\$825	\$1,650	\$1,848
		10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,772
		Over 15 Feet	\$0	\$343	\$1,716	\$3,432	\$3,795
	STONE	Under 5 Feet	\$0	\$84	\$425	\$850	\$983
		5 To 10 Feet	\$0	\$152	\$759	\$1,518	\$1,782
		10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,970
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$4,752
	WOOD	Under 5 Feet	\$0	\$86	\$431	\$862	\$994
		5 To 10 Feet	\$0	\$127	\$632	\$1,265	\$1,463
		10 To 15 Feet	\$0	\$161	\$804	\$1,608	\$1,872
		Over 15 Feet	\$0	\$202	\$1,008	\$2,017	\$2,380
COASTAL BEACH	SAND	Under 5 Feet	\$0	\$26	\$132	\$264	\$264
		5 To 10 Feet	\$0	\$127	\$634	\$1,267	\$1,267
		10 To 15 Feet	\$0	\$224	\$1,122	\$2,244	\$2,244
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$3,960
COASTAL DUNE	SAND	Under 5 Feet	\$0	\$18	\$93	\$186	\$186
		5 To 10 Feet	\$0	\$48	\$238	\$476	\$476
		10 To 15 Feet	\$0	\$79	\$395	\$790	\$790
		Over 15 Feet	\$0	\$132	\$660	\$1,320	\$1,320
REVTMENT	STONE	Under 5 Feet	\$0	\$66	\$333	\$664	\$730
		5 To 10 Feet	\$0	\$120	\$601	\$1,201	\$1,300
		10 To 15 Feet	\$0	\$157	\$781	\$1,564	\$1,696
		Over 15 Feet	\$0	\$247	\$1,234	\$2,468	\$2,666
GROIN	STONE	Under 5 Feet	\$0	\$132	\$664	\$1,328	\$1,460
		5 To 10 Feet	\$0	\$240	\$1,201	\$2,402	\$2,600
		10 To 15 Feet	\$0	\$314	\$1,564	\$3,128	\$3,392
		Over 15 Feet	\$0	\$494	\$2,468	\$4,937	\$5,333

NOTE: Repair / Rehabilitation Costs include 10% for engineering and regulatory approvals and 20 % construction contingency.

Section II

Gloucester

Section II – Community Findings – City of Gloucester

COMMUNITY DESCRIPTION

The City of Gloucester consists of a land area of 25.97 square miles out of a total area of 41.5 square miles and had a population of 30,273 in the 2000 census. The City is located on the North Shore of Massachusetts and its location can be seen on this report's cover. The estimated length of shoreline that is directly exposed to open ocean waves is 20 miles with the remaining shoreline semi-protected by offshore structures or landforms. The City is protected from major coastal storms by both natural and man-made shoreline structures that require maintenance to insure the long term protection of its coastline. The man-made and publicly owned structures that protect the City were investigated for their ability to provide adequate protection from major coastal storms. Structures have been identified as publicly owned, including coastal dunes and beaches, based on evidence of investment of public funds made to create/enhance/maintain these structures. The assessment did not include floating or pile supported structures as they are assumed not to provide any significant coastal protection from major storm events.

STRUCTURE INVENTORY

Within the City of Gloucester, there were 33 structures which had public or unknown ownership which provide significant coastal protection. The location of the structures can be seen in Sheets 1 through Sheet 8 in Section II-B of this report. The structures were categorized by their type and by their structural condition based on a preliminary field assessment. The distribution of structures by type and condition can be seen in the following table:

STRUCTURE TYPE AND QUANTITY - City of Gloucester

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Length
		A	B	C	D	F	
Bulkhead / Seawall	22	2	8	9	3		9335
Revetment	8		6	2			4070
Breakwater	3		1	2			3615
Groin / Jetty							
Coastal Dune							
Coastal Beach							
	33	2	15	13	3		17020

Within the above table, the total length of each type of structure is also provided. The structures are listed by the type which is providing the primary coastal protection. Many sites have multiple structure types at the same location (i.e. revetment in front of seawall). These secondary structures, although not identified within these tables, are included in the development of repair/rehabilitation costs.

The development of repair costs has been included by structure type and by condition. In the City of Gloucester's case there are a total of 31 structures which would require approximately \$ 18 million to bring all the coastal structures to "A" Rating. Most critical will be the structures in the "D" and "F" classifications as those are assumed to undergo some level of damage or failure during the next major coastal storm event. To reconstruct these structures, identified in the preliminary survey as being in poor condition, an estimated \$ 6.4 million would be required to upgrade the City's coastal protection.

STRUCTURE REPAIR / RECONSTRUCTION COST - City of Gloucester

Primary Structure (1)	Total Structures	Structure Condition Rating				F	Total Cost
		A	B	C	D		
Bulkhead / Seawall	22		\$ 1,158,254	\$ 4,026,891	\$ 6,393,420		\$ 11,578,565
Revetment	8		\$ 482,235	\$ 1,982,554			\$ 2,464,789
Breakwater	3		\$ 1,111,500	\$ 3,369,366			\$ 4,480,866
Groin / Jetty							\$ -
Coastal Dune							\$ -
Coastal Beach							\$ -
	33	\$ -	\$ 2,751,989	\$ 9,378,811	\$ 6,393,420	\$ -	\$ 18,524,220

Based on the limited research within the scope of this project research, the presumed ownership of the structures was established on an initial basis and would be subject to more intense review in future tasks. Structures identified as being owned privately were excluded from further consideration. Although ownership of the land on which the structure was located was a factor, the structure ownership was treated as a separate issue from land ownership. For the City of Gloucester, the breakdown of structures by assumed ownership is as follows:

STRUCTURE OWNERSHIP / REPAIR COST - City of Gloucester

Primary Structure (1)	Total Structures	Structure Condition Rating				F	Total Cost
		A	B	C	D		
Town Owned	26		\$ 1,137,450	\$ 7,142,698	\$ 6,393,420		\$ 14,673,568
Commonwealth of Massachusetts	5		\$ 434,729	\$ 2,236,113			\$ 2,670,842
Federal Government Owned	1		\$ 1,111,500				\$ 1,111,500
Unknown Ownership	1			\$ 68,310			\$ 68,310
	33	\$ -	\$ 2,683,679	\$ 9,447,121	\$ 6,393,420	\$ -	\$ 18,524,220

The identification of presumed ownership was not based on the investigation of legal documents but relied on property ownership and from construction and regulatory documents that were found. A more detailed investigation of legal documents and agreements would be required where structure ownership is disputed. A more detailed identification of structure type, length, condition and location can be found in Section II-B which contains Structure Assessment Reports for each individual structure found.

SUMMARY


The enclosed reports and associated documents reflects the City of Gloucester's coastal structure information that will eventually be input into a state-wide GIS database and will be accessible through MassGIS. This data, when compiled state-wide, will be critical in the development of both short term and long term planning for maintaining and improving Massachusetts coastal protection.

This database will also provide relatively quick access to identify available documentation for these structures as well as the ability to be updated as coastal structure improvements are made.

Section II - Gloucester

Part B

Structure Assessment Reports




COASTAL STRUCTURE LOCATION PLAN

CITY OF GLOUCESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150
SCALE: 1" = 150'-0"

BCE Bourne Consulting Engineering
3 Paul Street
Bourne, MA 01902
TEL (508) 533-0000 FAX (508) 533-0000




COASTAL STRUCTURE LOCATION PLAN

CITY OF GLOUCESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150
SCALE: 1" = 150'-0"





COASTAL STRUCTURE LOCATION PLAN

CITY OF GLOUCESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



BCE Bourne Consulting Engineering
3 Paul Road
Bourne, MA 01906
TEL: (508) 553-0000 FAX: (508) 553-0000



COASTAL STRUCTURE LOCATION PLAN

CITY OF GLOUCESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150



SCALE: 1" = 150'-0"



COASTAL STRUCTURE LOCATION PLAN

CITY OF GLOUCESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT


DECEMBER 2007

0 150



SCALE: 1" = 150'-0"






COASTAL STRUCTURE LOCATION PLAN

CITY OF GLOUCESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



SCALE: 1" = 150'-0"



COASTAL STRUCTURE LOCATION PLAN

CITY OF GLOUCESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150
SCALE: 1" = 150'-0"

BCE Bourne Consulting Engineering
3 And Over
Providence, RI 02904
TEL: (401) 552-0000 FAX: (401) 552-0000



FRESHWATER COVE

COASTAL STRUCTURE LOCATION PLAN

CITY OF GLOUCESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150



SCALE: 1" = 150'-0"



Structure Assessment Form

Town: Gloucester

Structure ID: 028-001-000-001-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Fort Point

Date:

6/5/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1954

Estimated Reconstruction/Repair Cost:

\$0.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
510		V2	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Over 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Over 15 Feet



Structure Summary :

Seawall is cast in place. Construction appears new. Behind the wall there is a playground and park. Riprap in front of the wall is approximately 25 feet wide. Stones are 6 feet by 2 feet by 3 feet, varying to 100 pound stone dumped riprap. No signs of scour or undermine. The top of the wall has drainage scuppers. The wall is 2 feet higher than grade at the back of the wall.

Condition

A

Rating

Excellent

Level of Action

None

Description

Like new condition. Structure expected to withstand major coastal storm without damage. Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

028-001-000-001-100-PHO1A.jpg

028-001-000-001-100-PHO2B.jpg

Structure Documents:

USACE

July 2001

City of Gloucester -

028-001-000-001-100-COE1A

MA-DCR

April 1954

Proposed Seawall at

028-001-000-001-100-DCR1A

MA-DCR

August 2000

Inspection of Stone

028-001-000-001-100-DCR1B

Structure Assessment FormStructure ID: **028-003-000-072-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Stacey Boulevard - West

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1952

Estimated Reconstruction/Repair Cost:

\$5,078,700.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
2025		V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

Stone mortared seawall with boardwalk, monuments, houses and road behind. There are areas with stone loss about every 100 feet with 5 feet width holes behind the top of the wall that are exposing the wall to the bottom. Small (100 to 200 pound) riprap has been placed in front of these areas.

*Condition***D***Rating***Poor***Level of Action***Major***Description*

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

*Priority***IV***Rating***High Priority***Action***Consider for Next Project Construction Listing***Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:**028-003-000-072-100-PHO1A.jpg****028-003-000-072-100-PHO1B.jpg****Structure Documents:****USACE****September 2****Reconstruction of****028-003-000-072-100-COE1A****MA-DCR****July 1952****Proposed Seawall****028-003-000-072-100-DCR1A****Gloucester****June 1955****Hurricane Damage****028-003-000-072-100-TWN1A**

Structure Assessment Form

Town: Gloucester

Structure ID: 028-003-000-072-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Stacey Boulevard - West

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1952

Estimated Reconstruction/Repair Cost:

\$0.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
280		V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

The newly constructed seawall is stone mortarted. The seawall is adjacent to a bridge over the channel to the Annisquam River. There is a roadway behind the structure.

Condition

A

Rating

Excellent

Level of Action

None

Description

Like new condition. Structure expected to withstand major coastal storm without damage. Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-003-000-072-200-PHO2A.jpg

Structure Documents:

USACE	September 2	Reconstruction of	028-003-000-072-200-COE2A
USACE	June 2002	City of Gloucester -	028-003-000-072-200-COE2B
MA-DCR	July 1952	Proposed Seawall	028-003-000-072-200-DCR2A
MA-DCR	May 1958	Proposed Wall	028-003-000-072-200-DCR2B
Gloucester	June 1955	Hurricane Damage	028-003-000-072-200-TWN2A

Structure Assessment Form

Town: Gloucester

Structure ID: 028-003-000-072-300

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Stacey Boulevard - East

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1952

Estimated Reconstruction/Repair Cost:

\$712,800.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
180		V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

The seawall is comprised of two parts. The bottom of the wall is five to six stones high with a cast in place wall on top of it. The stones are approximately 5 feet by 2 feet. There is settling of the boardwalk behind the wall and undermining holes visible.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-003-000-072-300-PHO3A.jpg

028-003-000-072-300-PHO3B.jpg

028-003-000-072-300-PHO3C.jpg

Structure Documents:

MA-DCR

July 1952

Proposed Seawall

028-003-000-072-300-DCR3A

MA-DCR

May 1958

Proposed Wall

028-003-000-072-300-DCR3B

MA-DCR

June 1958

Proposed Bank

028-003-000-072-300-DCR3C

Gloucester

June 1955

Hurricane Damage

028-003-000-072-300-TWN3A

Structure Assessment Form

Town: Gloucester

Structure ID: 028-003-000-072-400

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Stacey Boulevard - East

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1955

Estimated Reconstruction/Repair Cost:

\$752,123.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
1170		V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:	Primary Material:	Primary Height:
Bulkhead/ Seawall	Concrete	Over 15 Feet
Secondary Type:	Secondary Material:	Secondary Height:
Revetment	Stone	Over 15 Feet



Structure Summary :

Monuments, boardwalk, houses and road are behind the stone block seawall. Five to six stones high (5 feet by 2 feet) for about half the wall then cast in place at the top of the wall. No scour visible. Riprap is approximately 5 feet by 5 feet by 5 feet dumped and stops about 2 feet below the cast in place wall.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-003-000-072-400-PHO4A.jpg

028-003-000-072-400-PHO4B.jpg

Structure Documents:

MA-DCR

June 1955

Hurricane Damage

028-003-000-072-400-DCR4A

Gloucester

June 1955

Hurricane Damage

028-003-000-072-400-TWN4A

Structure Assessment Form

Town: Gloucester

Structure ID: 028-007-000-005-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lobster Pier

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1968

Estimated Reconstruction/Repair Cost:

\$559,746.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
275		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Steel

Primary Height:

10 to 15 Feet

Secondary Type:

Revetment

Secondary Material:

Concrete

Secondary Height:

10 to 15 Feet



Structure Summary :

Steel sheetpile wall fronted by dumped riprap. The top are half ton stones. Sheetpile has heavy corrosion at tidal zone. Erosion behind the concrete cap on the sheetpile (3 feet by 2 feet). No sign of cracking. Above is timber pier.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

028-007-000-005-100-PHO1A.jpg

028-007-000-005-100-PHO1B.jpg

028-007-000-005-100-PHO1C.jpg

Structure Documents:

USACE

January 198

Proposed Site

028-007-000-005-100-COE1A

DEP

August 21, 1

Plan Accompanying

028-007-000-005-100-LIC1A

DEP

June 22, 198

Plan Accompanying

028-007-000-005-100-LIC1B

Structure Assessment Form

Town: Gloucester

Structure ID: 028-007-000-016-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

St. Peter's Marina

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1980

Estimated Reconstruction/Repair Cost:

\$38,260.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
155		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Riprap is below timber pier. Concrete cap above the riprap. The stones are approximately 2 feet by 2 feet by 5 feet. No signs of movement or shifting.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

028-007-000-016-100-PHO1A.jpg

Structure Documents:

DEP

July 10, 198

Plan Accompanying

028-007-000-016-100-LIC1A

Structure Assessment Form

Town: Gloucester

Structure ID: 028-007-000-016-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Town Landing

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1954

Estimated Reconstruction/Repair Cost:

\$200,640.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
160		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall is comprised of 2 feet by 2 feet stones. Toe of the wall is exposed at low tide. Stones are shifted and settled. Half of the wall is cast in place wall with wave return face, and half has a concrete cap. Gangway to the town landing floats is connected.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

028-007-000-016-200-PHO2A.jpg

028-007-000-016-200-PHO2B.jpg

028-007-000-016-200-PHO2C.jpg

Structure Documents:

USACE

July 1954

Proposed Seawall

028-007-000-016-200-COE2A

DEP

July 23, 195

Construct Riprap and

028-007-000-016-200-LIC2A

Gloucester

1/9/2007

Illustrative Plan -

028-007-000-016-200-TWN2A

Structure Assessment FormStructure ID: **028-009-000-014-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Solomon Jacobs Park

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1972

Estimated Reconstruction/Repair Cost:

\$263,340.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
210		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

Top is concrete walkway and park. The dry set stone seawall is comprised of stones that are on average 2 feet by 2 feet by 6 feet. There is stone movement, shifting, and bowing out.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description***No Inshore Structures or Residential Dwelling Units Present****Structure Images:****028-009-000-014-100-PHO1A.jpg****028-009-000-014-100-PHO1B.jpg****Structure Documents:****USACE****May 26, 197****Proposed Shore and****028-009-000-014-100-COE1A**

Structure Assessment Form

Town: Gloucester

Structure ID: 028-053-000-016-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Head of the Harbor

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1979

Estimated Reconstruction/Repair Cost:

\$29,621.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
120		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Placed riprap with stones that are on average between 0.5 to 1 ton. 1 on 1 slope. There are no signs of movement or shifting. The stones are placed and locked in well. Park behind revetment.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

028-053-000-016-100-PHO1A.jpg

Structure Documents:

USACE

March 1979

Plan Accompanying

028-053-000-016-100-COE1A

DEP

February 19

Plans Accompanying

028-053-000-016-100-LIC1A

DEP

May 24, 197

Plan Accompanying

028-053-000-016-100-LIC1B

Structure Assessment Form

Town: Gloucester

Structure ID: 028-054-000-108-100

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

State Fish Pier

Date:

6/6/2007

Presumed Structure Owner:

State

Based On Comment:

Owner Name:

MA-DCR

Earliest Structure Record:

1976

Estimated Reconstruction/Repair Cost:

\$338,171.00

Length: 1370 Feet
 Top Elevation: Feet NAVD 88
 FIRM Map Zone: A2
 FIRM Map Elevation: 10 Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped riprap revetment circling the state pier. Unable to see materials under or behind wall. The slope is 1 on 2 to 1 on 1. Stones are 50 to 100 pounds. Riprap comes to grade level. Parking lot, building, and storage area behind. The timber pier off of it.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

028-054-000-108-100-PHO1A.jpg

028-054-000-108-100-PHO1B.jpg

028-054-000-108-100-PHO1C.jpg

Structure Documents:

USACE

June 9, 1976

Proposed Expansion

028-054-000-108-100-COE1A

MA-DCR

September 2

Gloucester State Fish

028-054-000-108-100-DCR1A

MA-DCR

State Fish Pier

028-054-000-108-100-DCR1B

DEP

May 1990

Plans Accompanying

028-054-000-108-100-LIC1A

Structure Assessment Form

Town: Gloucester

Structure ID: 028-054-000-108-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

State Fish Pier

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1976

Estimated Reconstruction/Repair Cost:

\$69,300.00

Length: 175 Feet Top Elevation: FIRM Map Zone: 10 FIRM Map Elevation: A2
 Feet Feet NAVD 88 Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone bulkhead with 2 feet by 2 feet stones with a concrete cap. Behind the wall is a parking lot and the Environmental Policy Organization Building. Some movement of stones. Chinking is still in place.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-054-000-108-200-PHO2A.jpg

Structure Documents:

USACE	June 9, 1976	Proposed Expansion	028-054-000-108-200-COE2A
MA-DCR	September 2	Gloucester State Fish	028-054-000-108-200-DCR2A
MA-DCR	N/A	State Fish Pier	028-054-000-108-200-DCR2B
DEP	May 1987	Plans Accompanying	028-054-000-108-200-LIC2A

Structure Assessment FormStructure ID: **028-058-000-040-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Cripple Cove Public Landing

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

2000

Estimated Reconstruction/Repair Cost:

\$10,210.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
85		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

Placed riprap with stones approximately 4 feet by 2 feet by 2 feet. The toe is exposed at low tide. On the top of the revetment is a walkway and park. No scour or movement visible.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:**028-058-000-040-100-PHO1A.jpg****Structure Documents:****USACE****July 2001****City of Gloucester -****028-058-000-040-100-COE1A****MA-DCR****August 2000****Inspection of Stone****028-058-000-040-100-DCR1A**

Structure Assessment Form

Town: Gloucester

Structure ID: 028-058-000-040-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Cripple Cove Public

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

2001

Estimated Reconstruction/Repair Cost:

\$50,160.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
200		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:	Primary Material:	Primary Height:
Bulkhead/ Seawall	Stone	10 to 15 Feet
Secondary Type:	Secondary Material:	Secondary Height:



Structure Summary :

Stone bulkhead with stone approximately 6 feet by 3 feet by 2 feet. The top of the wall is mortared. Some mortar is lost. Behind the wall is a playground, and in front is the gangway for a public landing. Some riprap at the toe. No scour visible.

<i>Condition</i>	B	<i>Priority</i>	I
<i>Rating</i>	Good	<i>Rating</i>	None
<i>Level of Action</i>	Minor	<i>Action</i>	Long Term Planning Considerations
<i>Description</i>	Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.	<i>Description</i>	No Inshore Structures or Residential Dwelling Units Present

Structure Images:

028-058-000-040-200-PHO2A.jpg

028-058-000-040-200-PHO2B.jpg

Structure Documents:

USACE

July 2001

City of Gloucester -

028-058-000-040-200-COE2A

Structure Assessment Form

Town: Gloucester

Structure ID: 028-064-000-061-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

East Main Street

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

2000

Estimated Reconstruction/Repair Cost:

\$42,636.00

Length: 170 Feet Top Elevation: FIRM Map Zone: A2 FIRM Map Elevation: 10 Feet NGVD
 Feet Feet NAVD 88

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block mortared seawall. The stones are approximately 1.5 feet in length by 1 foot in height. A sidewalk, road and houses are behind the wall. A sandy beach is in front of the wall. There is no sign of scour or undermine.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-064-000-061-100-PHO1A.jpg

Structure Documents:

USACE

April 2000

City of Gloucester -

028-064-000-061-100-COE1A

Structure Assessment Form

Town: Gloucester

Structure ID: 028-079-000-001-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Robinson Landing

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1965

Estimated Reconstruction/Repair Cost:

\$601,920.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
240		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall with 2 feet by 2 feet by 6 feet stones. The corner of the wall is unraveling. The back of the wall has erosion and undermining. There is a small park behind the seawall.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

028-079-000-001-100-PHO1A.jpg

Structure Documents:

MA-DCR

July 1965

Proposed Shore

028-079-000-001-100-DCR1A

MA-DCR

April 2000

Construction of Stone

028-079-000-001-100-DCR1B

Structure Assessment Form

Town: Gloucester

Structure ID: 028-130-000-011-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Rocky Neck Avenue

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$45,012.00

Length:

220

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V2

FIRM Map Elevation:

12

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Under 5 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

5 to 10 Feet



Structure Summary :

Precast concrete wall with riprap in front. Precast wall is 4 feet high by 4 feet wide. There is some cracking at the edges. Dumped riprap is 5 feet by 2 feet by 2 feet; in front is a sandy beach. Some undermining under and behind the wall. Behind is a walkway, small park, and road to Rocky Neck.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

V

Rating

Immediate / Highest Priority

Action

Consider For Immediate Action Due to Public Safety and Welfare Issues

Description

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-130-000-011-100-PHO1A.jpg

Structure Documents:

MA-DCR

May 1958

Proposed Seawall

028-130-000-011-100-DCR1A

Structure Assessment FormStructure ID: **028-130-000-011-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Rocky Neck Avenue

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$57,334.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
365		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

Placed stone riprap revetment. 5 feet by 2 feet by 2 feet at the top. 1 on 2 slope. Behind is parking lot and the only road to Rocky Neck. Toe is intact. No stone movement found. Mean high water is approximately half way up the slope.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***V***Rating***Immediate / Highest Priority***Action*

Consider For Immediate Action Due to Public Safety and Welfare Issues

Description

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:**028-130-000-011-200-PHO2A.jpg****Structure Documents:****DEP****August 11, 1****Plan Accompanying****028-130-000-011-200-LIC2A**

Structure Assessment FormStructure ID: **028-131-000-018-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Wonson Cove

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$125,235.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
165		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Mortared stone seawall with sidewalk and road behind it. The concrete cap is approximately 2 feet wide. Some cracks and loose mortar visible, but no scour.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***IV***Rating***High Priority***Action***Consider for Next Project Construction Listing***Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-131-000-018-100-PHO1A.jpg

Structure Documents:

MA-DCR**May 1958****Proposed Seawall****028-131-000-018-100-DCR1A**

Structure Assessment Form

Structure ID: 028-133-000-017-100

Key: community-map-block-parcel-structure

Property Owner:

Unknown

Location:

Niles Beach

Date:

6/6/2007

Presumed Structure Owner:

Unknown

Based On Comment:

Owner Name:

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$68,310.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
450		V2	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

The stone seawall is mortared. There is parking lot above the wall and a road behind the wall. No scour found. 2 feet by 1 foot stones. Sandy beach in front.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-133-000-017-100-PHO1A.jpg

028-133-000-017-100-PHO1B.jpg

Structure Documents:

Structure Assessment Form

Structure ID: 028-137-000-011-100

Key: community-map-block-parcel-structure

Property Owner:

Federal

Location:

Dog Bar Breakwater

Date:

6/6/2007

Presumed Structure Owner:

Federal

Based On Comment:

Owner Name:

USCG

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$1,111,500.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
2250	11	V2	20
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Breakwater

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

The breakwater is at the mouth of the Gloucester Harbor. The stones are 9 feet by 3 feet by 3 feet and rectangular. The riprap on the ocean side is placed and is 9 feet by 4 feet by 5 feet with a 1 on 1 slope. Five of the riprap stones have been pushed out of place by storm action.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

V

Rating

Immediate / Highest Priority

Action

Consider For Immediate Action Due to Public Safety and Welfare Issues

Description

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-137-000-011-100-PHO1A.jpg

028-137-000-011-100-PHO1B.jpg

028-137-000-011-100-PHO1C.jpg

Structure Documents:

Structure Assessment Form

Structure ID: 028-139-000-002-100

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

University of Massachusetts - Marine Station

Date:

6/6/2007

Presumed Structure Owner:

State

Based On Comment:

Owner Name:

University of Massachusetts

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$790,020.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
630	10	V2	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall with stones that average 7 feet by 2 feet by 2 feet. Erosion behind the wall and stones have shifted and settled. Slope 1 on 1 to 1 on 0.5 The wall is in better condition inshore.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

028-139-000-002-100-PHO1A.jpg

Structure Documents:

Structure Assessment FormStructure ID: **028-139-000-002-200**

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

University of Massachusetts - Marine Station

Date:

6/6/2007

Presumed Structure Owner:

State

Based On Comment:

Owner Name:

University of Massachusetts

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$131,670.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
105	7	V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block bulkhead with stones averaging 7 feet by 2 feet by 2 feet. Erosion behind wall and stones have shifted and settled. Slope 1 on 1 to 1 on 0.5. The stones have unraveled on the inshore end of the wall.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

028-139-000-002-200-PHO2A.jpg

Structure Documents:

Structure Assessment FormStructure ID: **028-139-000-002-300**

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

University of Massachusetts - Marine Station

Date:

6/6/2007

Presumed Structure Owner:

State

Based On Comment:

Owner Name:

University of Massachusetts

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$96,558.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
385	9	V2	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block bulkhead with stones averaging 7 feet by 2 feet by 2 feet. Erosion behind wall and stones have shifted and settled. Slope is 1 on 1 to 1 on 0.5.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

028-139-000-002-300-PHO3A.jpg

Structure Documents:

Structure Assessment Form

Town: Gloucester

Structure ID: 028-139-000-002-400

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

University of Massachusetts - Marine Station

Date:

6/6/2007

Presumed Structure Owner:

State

Based On Comment:

Owner Name:

University of Massachusetts

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$1,314,423.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
1065	7	V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped riprap with stones of varying size. The average stone size is 3 feet by 3 feet by 3 feet. The stones have unraveled, shifted and settled in many parts.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

028-139-000-002-400-PHO4A.jpg

028-139-000-002-400-PHO4B.jpg

Structure Documents:

Structure Assessment Form

Structure ID: 028-139-000-010-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Washington Street

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$758,670.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
605	7	V2	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall with stones approximately 7 feet by 3 feet by 2 feet. The stones have shifted and moved. The wall breaks for the boat ramp behind it. A good amount of hardware is heavily corroded.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-139-000-010-100-PHO1A.jpg

028-139-000-010-100-PHO1B.jpg

028-139-000-010-100-PHO1C.jpg

028-139-000-010-100-PHO1D.jpg

Structure Documents:

Structure Assessment FormStructure ID: **028-142-000-038-100**

Key: community-map-block-parcel-structure

Property Owner:

Location:

Date:

Local

Lanes Cove

6/7/2007

Presumed Structure Owner:

Based On Comment:

Local

Owner Name:

Earliest Structure Record:

Estimated Reconstruction/Repair Cost:

Gloucester

Unkown

\$796,290.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
635	4	V3	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Primary Material:

Primary Height:

Bulkhead/ Seawall

Stone

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

Stone bulkhead 5 feet by 3 feet by 3 feet. There is undermining, shifting, and settling located behind the breakwater in the cove. The south side has come unraveled and is falling into the water. There is erosion and heaving of stones. There is a storage area for fishing equipment and a park behind the bulkhead.

Condition

C

Priority

III

Rating

Fair

Rating

Moderate Priority

Level of Action

Moderate

Action

Consider for Active Project Improvement Listing

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:**Structure Documents:**

028-142-000-038-100.PHO1B.jpg

028-142-000-038-100-PHO1A.jpg

Structure Assessment Form

Structure ID: 028-142-000-038-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lanes Cove

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$401,280.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
320	4	V3	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stones are undermining, settling, shifting and rotating. They are approximately 4 feet by 2 feet by 2 feet. A storage area for fishing equipment and a parking lot are located above the middle structure in the cove.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

028-142-000-038-200-PHO2A.jpg

028-142-000-038-200-PHO2B.jpg

Structure Documents:

Structure Assessment FormStructure ID: **028-142-000-038-300**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lanes Cove

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$8,639.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
55	4	V3	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped riprap is approximately 200 pounds. Some erosion along the top. The toe is still intact.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

028-142-000-038-300-PHO3A.jpg

Structure Documents:

Structure Assessment Form

Town: **Gloucester**Structure ID: **028-142-000-038-400**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lanes Cove

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$1,135,464.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
460	9	V3	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Breakwater

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone breakwater with stones approximately 4 feet by 3 feet by 2 feet. The corners appear to have been unraveled and repaired using staples. The breakwater protects the cove behind it and the channel adjacent to it. There is a 20 foot landing behind the breakwater, followed by a 15 foot bulkhead. Inshore the stones have signs of rotation and movement.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

028-142-000-038-400-PHO4A.jpg

028-142-000-038-400-PHO4B.jpg

028-142-000-038-400-PHO4C.jpg

Structure Documents:

Structure Assessment Form

Structure ID: 028-142-000-052-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lanes Cove

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1988

Estimated Reconstruction/Repair Cost:

\$2,233,902.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
905	7	V3	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Breakwater

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

The stone breakwater is approximately 4 feet by 3 feet by 1 foot. There is some visible stone heave and bowing out, along with some settling and unraveling. The breakwater protects the cove and channel. Adjacent to the breakwater is a 20 foot wall connected to a 20 foot landing which is connected to a 15 foot wall. There is erosion along the inshore base. There is approximately 100 feet of dumped riprap.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

028-142-000-052-100-PHO1A.jpg

028-142-000-052-100-PHO1B.jpg

028-142-000-052-100-PHO1C.jpg

028-142-000-052-100-PHO1D.jpg

Structure Documents:

Gloucester

5/3/1988

Proposed Ramp

028-142-000-052-100-TWN1A

Structure Assessment FormStructure ID: **028-216-000-140-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Crescent Beach

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$34,155.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
225		V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Mortared stone seawall. Some areas with loss of mortar. No scour found. The top is approximately 2 feet wide. Cobble and sand beach fronting. There are two stair beach accesses.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

028-216-000-140-100-PHO1A.jpg**028-216-000-140-100-PHO1B.jpg**

Structure Documents:

Structure Assessment Form

Structure ID: 028-216-000-140-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Crescent Beach

Date:

6/6/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Gloucester

Earliest Structure Record:

1913

Estimated Reconstruction/Repair Cost:

\$668,131.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
855		V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

The stone riprap revetment has stones of approximately 5 feet by 3 feet by 2 feet size. The slope is 1 on 1.5. There is a good amount of erosion at the top. Some sections of understone have washed out leaving large gaps in the understone exposing geotextile. The toe is intact. There is a cobble beach in front of the revetment.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

028-216-000-140-200-PHO2A.jpg

028-216-000-140-200-PHO2B.jpg

028-216-000-140-200-PHO2C.jpg

Structure Documents:

Gloucester

3/21/1913

Proposed

028-216-000-140-200-TWN2A

Section II - Gloucester

Part C

Structure Photographs

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
028-001-000-001-100	028-001-000-001-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-001-000-001-100	028-001-000-001-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-003-000-072-100	028-003-000-072-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-003-000-072-100	028-003-000-072-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-003-000-072-200	028-003-000-072-200-PHO2A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-003-000-072-300	028-003-000-072-300-PHO3A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-003-000-072-300	028-003-000-072-300-PHO3B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-003-000-072-300	028-003-000-072-300-PHO3C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-003-000-072-400	028-003-000-072-400-PHO4A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-003-000-072-400	028-003-000-072-400-PHO4B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-007-000-005-100	028-007-000-005-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-007-000-005-100	028-007-000-005-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-007-000-005-100	028-007-000-005-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-007-000-016-100	028-007-000-016-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-007-000-016-200	028-007-000-016-200-PHO2A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-007-000-016-200	028-007-000-016-200-PHO2B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-007-000-016-200	028-007-000-016-200-PHO2C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-009-000-014-100	028-009-000-014-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-009-000-014-100	028-009-000-014-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-053-000-016-100	028-053-000-016-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-054-000-108-100	028-054-000-108-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-054-000-108-100	028-054-000-108-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
028-054-000-108-100	028-054-000-108-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-054-000-108-200	028-054-000-108-200-PHO2A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-058-000-040-100	028-058-000-040-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-058-000-040-200	028-058-000-040-200-PHO2A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-058-000-040-200	028-058-000-040-200-PHO2B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-064-000-061-100	028-064-000-061-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-079-000-001-100	028-079-000-001-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-130-000-011-100	028-130-000-011-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-130-000-011-200	028-130-000-011-200-PHO2A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-131-000-018-100	028-131-000-018-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-133-000-017-100	028-133-000-017-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-133-000-017-100	028-133-000-017-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-137-000-011-100	028-137-000-011-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-137-000-011-100	028-137-000-011-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-137-000-011-100	028-137-000-011-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-139-000-002-100	028-139-000-002-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-139-000-002-200	028-139-000-002-200-PHO2A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-139-000-002-300	028-139-000-002-300-PHO3A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-139-000-002-400	028-139-000-002-400-PHO4A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-139-000-002-400	028-139-000-002-400-PHO4B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-139-000-010-100	028-139-000-010-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-139-000-010-100	028-139-000-010-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

BCE Structure No	Document No	Contract Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
028-139-000-010-100	028-139-000-010-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-139-000-010-100	028-139-000-010-100-PHO1D.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-038-100	028-142-000-038-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-038-100	028-142-000-038-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-038-200	028-142-000-038-200-PHO2A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-038-200	028-142-000-038-200-PHO2B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-038-300	028-142-000-038-300-PHO3A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-038-400	028-142-000-038-400-PHO4A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-038-400	028-142-000-038-400-PHO4B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-038-400	028-142-000-038-400-PHO4C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-052-100	028-142-000-052-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-052-100	028-142-000-052-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-052-100	028-142-000-052-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-142-000-052-100	028-142-000-052-100-PHO1D.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-216-000-140-100	028-216-000-140-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-216-000-140-100	028-216-000-140-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-216-000-140-200	028-216-000-140-200-PHO2A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-216-000-140-200	028-216-000-140-200-PHO2B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
028-216-000-140-200	028-216-000-140-200-PHO2C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey


Massachusetts Coastal Infrastructure and Assessment



028-001-000-001-100-PHO1A



028-001-000-001-100-PHO1B




028-003-000-072-100-PHO1A



028-003-000-072-100-PHO1B




028-003-000-072-200-PHO2A



028-003-000-072-300-PHO3A



028-003-000-072-300-PHO3B



028-003-000-072-300-PHO3C



028-003-000-072-400-PHO4A

Massachusetts Coastal Infrastructure and Assessment



028-003-000-072-400-PHO4B



028-007-000-005-100-PHO1A



028-007-000-005-100-PHO1B



028-007-000-005-100-PHO1C



028-007-000-016-100-PHO1A



028-007-000-016-200-PHO2A



028-007-000-016-200-PHO2B



028-007-000-016-200-PHO2C



028-009-000-014-100-PHO1A

Massachusetts Coastal Infrastructure and Assessment



028-009-000-014-100-PHO1B



028-053-000-016-100-PHO1A



028-054-000-108-100-PHO1A



028-054-000-108-100-PHO1B



028-054-000-108-100-PHO1C



028-054-000-108-200-PHO2A



028-058-000-040-100-PHO1A



028-058-000-040-200-PHO2A



028-058-000-040-200-PHO2B

Massachusetts Coastal Infrastructure and Assessment



028-064-000-061-100-PHO1A



028-079-000-001-100-PHO1A



028-130-000-011-100-PHO1A



028-130-000-011-200-PHO2A



028-131-000-018-100-PHO1A



028-133-000-017-100-PHO1A



028-133-000-017-100-PHO1B



028-137-000-011-100-PHO1A



028-137-000-011-100-PHO1B


Massachusetts Coastal Infrastructure and Assessment



028-137-000-011-100-PHO1C



028-139-000-002-100-PHO1A



028-139-000-002-200-PHO2A




028-139-000-002-300-PHO3A



028-139-000-002-400-PHO4A



028-139-000-002-400-PHO4B



028-139-000-010-100-PHO1A



028-139-000-010-100-PHO1B



028-139-000-010-100-PHO1C

Massachusetts Coastal Infrastructure and Assessment



028-139-000-010-100-PHO1D



028-142-000-038-100-PHO1A



028-142-000-038-100-PHO1B



028-142-000-038-200-PHO2A



028-142-000-038-200-PHO2B



028-142-000-038-300-PHO3A



028-142-000-038-400-PHO4A



028-142-000-038-400-PHO4B



028-142-000-038-400-PHO4C

Massachusetts Coastal Infrastructure and Assessment



028-142-000-052-100-PHO1A



028-142-000-052-100-PHO1B



028-142-000-052-100-PHO1C



028-142-000-052-100-PHO1D



028-216-000-140-100-PHO1A



028-216-000-140-100-PHO1B



028-216-000-140-200-PHO2A



028-216-000-140-200-PHO2B



028-216-000-140-200-PHO2C

Section II - Gloucester

Part D

Structure Documents

CITY DOCUMENT LIST

MA DCR - DOCUMENT LIST

MA DEP – Ch 91 DOCUMENT LIST

- Copies of License Documents



USACE – PERMIT DOCUMENT LIST

- Copies of Permit Documents

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
028-003-000-072-100	028-003-000-072-100-TWN1A	1528	Gloucester	Gloucester	June 1955	Hurricane Damage Repairs - Fisherman Municipal Park and Stage Fort Park	2		Repair
028-003-000-072-200	028-003-000-072-200-TWN2A	1528	Gloucester	Gloucester	June 1955	Hurricane Damage Repairs - Fisherman's Municipal Park and Stage Fort Park	2		
028-003-000-072-300	028-003-000-072-300-TWN3A	1528	Gloucester	Gloucester	June 1955	Hurricane Damage Repairs - Fisherman's Municipal Park and Stage Fort Park	2		
028-003-000-072-400	028-003-000-072-400-TWN4A	1528	Gloucester	Gloucester	June 1955	Hurricane Damage Repairs - Fisherman's Municipal Park and Stage Fort Park	2		Repair
028-007-000-016-200	028-007-000-016-200-TWN2A		Gloucester	Gloucester	1/8/2007	Illustrative Plan - Saint Peter's Square	1	Rogers Street	Plan View of Square
028-142-000-052-100	028-142-000-052-100-TWN1A	40832	Gloucester	Gloucester	5/3/1988	Proposed Ramp	3	Lanes Cove Landing	
028-216-000-140-200	028-216-000-140-200-TWN2A	135-A	Gloucester	Gloucester	3/21/1913	Proposed Improvements at Stage Fort Park	1		Wall Concrete

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
028-001-000-001-100	028-001-000-001-100-DCR1A	1390	MA-DCR	Gloucester	April 1954	Proposed Seawall at Harbor Cove - Gloucester, MA - Prepared for DPW of MA - Division of Waterways	2	Harbor Cove - Fort Point	Seawall
028-001-000-001-100	028-001-000-001-100-DCR1B	3409	MA-DCR	Gloucester	August 2000	Inspection of Stone Bulkhead	5	Stacey Boulevard, Fort Square, Cripple Cove	Bulkhead
028-003-000-072-100	028-003-000-072-100-DCR1A	1261	MA-DCR	Gloucester	July 1952	Proposed Seawall Repairs - Annisquam Canal - Gloucester - Prepared for DPW of MA - Division of Waterways	1	Annisquam Canal - East Side	Seawall
028-003-000-072-200	028-003-000-072-200-DCR2A	1261	MA-DCR	Gloucester	July 1952	Proposed Seawall Repairs - Annisquam Canal - Gloucester, MA - Prepared for the DPW of Massachusetts - Division of Waterways	1	Annisquam Canal - East Side	Seawall
028-003-000-072-200	028-003-000-072-200-DCR2B	1900	MA-DCR	Gloucester	May 1958	Proposed Wall Repairs - Annisquam Canal - Gloucester, MA - Prepared for the DPW of Massachusetts - Division of Waterways	4	Annisquam Canal - East Side	Wall Repairs
028-003-000-072-300	028-003-000-072-300-DCR3A	1261	MA-DCR	Gloucester	July 1952	Proposed Seawall Repairs - Annisquam Canal - Gloucester, MA - Prepared for the DPW of MA - Division of Waterways	1	Annisquam Canal - East Side	Seawall
028-003-000-072-300	028-003-000-072-300-DCR3B	1900	MA-DCR	Gloucester	May 1958	Proposed Wall Repairs - Annisquam Canal - Gloucester, MA - Prepared for DPW of Massachusetts - Division of Waterways	4	Annisquam Canal - East Side	Wall Repairs
028-003-000-072-300	028-003-000-072-300-DCR3C	2047	MA-DCR	Gloucester	June 1958	Proposed Bank Protection - Annisquam Canal - Gloucester, MA - Prepared for DPW of Massachusetts - Division of Waterways	2	Annisquam Canal	Concrete Wall
028-003-000-072-400	028-003-000-072-400-DCR4A	1528	MA-DCR	Gloucester	June 1955	Hurricane Damage Repairs - Fishermen's Memorial Park and State Fort Park - Gloucester - Prepared for DPW of MA - Division of Waterways	1	Western Avenue	Seawall
028-054-000-108-100	028-054-000-108-100-DCR1A	3571	MA-DCR	Gloucester	September 2005	Gloucester State Fish Pier Survey - Topo Survey	6	2 State Pier	Pier Existing Conditions
028-054-000-108-100	028-054-000-108-100-DCR1B	GSFP-3	MA-DCR	Gloucester		State Fish Pier Development Plan	1	State Fish Pier	Riprap
028-054-000-108-200	028-054-000-108-200-DCR2A	3571	MA-DCR	Gloucester	September 2005	Gloucester State Fish Pier Survey - Topo Survey	6	2 State Pier	Pier Existing Conditions
028-054-000-108-200	028-054-000-108-200-DCR2B	GSFP-3	MA-DCR	Gloucester		State Fish Pier Development Plan	1	State Fish Pier	Riprap
028-058-000-040-100	028-058-000-040-100-DCR1A	3409	MA-DCR	Gloucester	August 2000	Inspection of Stone Bulkhead	5	Stacey Boulevard, Fort Square, Cripple Cove	Bulkhead
028-079-000-001-100	028-079-000-001-100-DCR1A	2472	MA-DCR	Gloucester	July 1965	Proposed Shore Protection - Seawall and Stone Revetment - Annisquam River - Gloucester - Prepared for DPW of MA - Division of Waterways	1	Annisquam River	Seawall and Stone Revetment
028-079-000-001-100	028-079-000-001-100-DCR1B	3415	MA-DCR	Gloucester	April 2000	Construction of Stone Bulkhead, Robinson's Landing	2000	East Main Street	Bulkhead
028-130-000-011-100	028-130-000-011-100-DCR1A	1935	MA-DCR	Gloucester	May 1958	Proposed Seawall Construction - Wonson's Cove - Gloucester - Prepared for DPW of MA - Division of Waterways	1	Wonson's Cove	Seawall
028-131-000-018-100	028-131-000-018-100-DCR1A	1935	MA-DCR	Gloucester	May 1958	Proposed Seawall Construction - Wonson's Cove - Gloucester - Prepared for DPW of MA - Division of Waterways	1	Wonson's Cove	Seawall

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
028-007-000-005-100	028-007-000-005-100-L/C1A	5404	DEP	Gloucester	August 21, 1988	Plan Accompanying Petition of Gloucester Housing Authority to Perform Certain Shore Line Stabilization Consisting of Solid Fill With Sloped Facing of Placed Stone - In Harbor Cove - Gloucester Harbor, Massachusetts	1	Duncan Street	Riprap Slope
028-007-000-005-100	028-007-000-005-100-L/C1B	1087	DEP	Gloucester	June 22, 1984	Plan Accompanying Petition of Gloucester Redevelopment Authority	2	Gloucester Inner Harbor	Rip Rap
028-007-000-018-100	028-007-000-018-100-L/C1A	872	DEP	Gloucester	July 10, 1980	Plan Accompanying Petition of the City of Gloucester to Construct and maintain a Wood Wharf and Maintain Existing Floats, Piles, Ramps and Riprap in Gloucester Harbor, City of Gloucester, Essex County, Massachusetts	2	Roger Street	Riprap Under Pier
028-007-000-018-200	028-007-000-018-200-L/C2A	3992	DEP	Gloucester	July 23, 1957	Construct Riprap and Solid Fill Harbor Cove, Gloucester Harbor	1	Harbor Cove	RipRap
028-053-000-018-100	028-053-000-018-100-L/C1A	771-	DEP	Gloucester	February 1982	Plans Accompanying Petition of the Gloucester Redevelopment Authority to Construct and Maintain Riprap Dike, Fill, Concrete Piers, Timber Pile Fenders, Extend Existing Drainage Lines and Dredge at Inner Harbor, Gloucester, County of Essex, Massachusetts	3	East Main Street and Parker Street	Riprap
028-053-000-018-100	028-053-000-018-100-L/C1B	569	DEP	Gloucester	May 24, 1979	Plan Accompanying Petition of the Gloucester Housing Authority	1	Gloucester Inner Harbor at Parker Street	Riprap
028-054-000-108-100	028-054-000-108-100-L/C1A	2511	DEP	Gloucester	May 1980	Plans Accompanying Petition of Massachusetts DEM Division of Waterways to Construct Finger Pier, Dredge, Fill and Place Riprap in Gloucester Harbor, City of Gloucester, County of Essex, MA	5	Inner Harbor	Fill and Riprap
028-054-000-108-200	028-054-000-108-200-L/C2A	1319	DEP	Gloucester	N/A	Plans Accompanying Petition of Head of the Harbor Nominee Trust to Construct and Maintain Floats, Ramp, and Piles in Gloucester Harbor City of Gloucester, Essex County, Massachusetts	3	Roger Street and East Main Street	Shows Existing Stone Riprap and Bulkhead
028-130-000-011-200	028-130-000-011-200-L/C2A	4854	DEP	Gloucester	August 11, 1984	Plan Accompanying Petition of the City of Gloucester, MA to Dispose of Surplus Clay, Boulder and Ledge Material in Smith Cove, Gloucester Harbor - Gloucester, MA	1	Smith Cove	Riprap Slope





PLAN ACCOMPANYING PETITION OF
GLOUCESTER HOUSING AUTHORITY
TO PERFORM CERTAIN SHORE LINE STABILIZATION
CONSISTING OF SOLID FILL WITH SLOPED
FACING OF PLACED STONE
- IN HARBOR COVE -
GLOUCESTER HARBOR MASSACHUSETTS
KEYS KROPPER ASSOC. BOSTON FEBRUARY 1968

LICENSE PLAN NO. 5404
APPROVED BY DEPARTMENT OF PUBLIC WORKS 2;
MASSACHUSETTS
AUGUST 21, 1968
(COMMISSIONER - DEPT
OF PUBLIC WORKS)
ASSOCIATE
COMMISSIONERS
Robert S. Foster
Charles L. Perkins

01-500-000-100-820

028-007-000-005-100

N/F
GLOUCESTER REDEVELOPMENT
AUTHORITY




NOTES:
ALL ELEVATIONS SHOWN
REFER TO NATIONAL
GEODETIC VERTICAL
DATUM (N.G.V.D.) 1929.

84w-030
PLAN ACCOMPANYING PETITION OF
GLOUCESTER REDEVELOPMENT
AUTHORITY
TO CONSTRUCT AND MAINTAIN A WHARF,
AND RIPRAP FILL
IN GLOUCESTER INNER HARBOR
CITY OF GLOUCESTER, COUNTY OF ESSEX,
MASSACHUSETTS
SHEET NO. 1 OF 2

David L. Dwyer
HARBOR COMMISSIONER'S LINE

LICENSE PLAN NO. 1087
Approved by Department of Environmental Quality Engineering
of Massachusetts June 22, 1984
Thomas F. Murphy COMMISSIONER
John G. Gagne, Jr. CHIEF ENGINEER
Robert W. Gagne DIVISION DIRECTOR




SECTION A-A

LICENSE PLAN NO. 1087


Approved by Department of Environmental Quality Engineering
JUNE 22, 1984

NOTES: 84w-030

1. ALL ELEVATIONS SHOWN
REFER TO NATIONAL
GEODETIC VERTICAL
DATUM (N.G.V.D.) 1929



0 20 40 / PLAN
1" = 40'



LOCUS MAP

Gloucester Grocers & Boat Supply Co.
Rogers St.
Gloucester

Wood Pile (TYP)

FLOOD
MHW
EBB
MLW

Gangway (3.85' x 32' ±)

EXISTING PILES

Captain Couragesous, Rest.

028-007-000-016-100

Rogers Street
William & Grace Budrow
Rogers St Gloucester

City of Gloucester

Town Landing
Line Shown On
Permit No. 1966;
E.S.D.R.D. Bk. 3149
Pg. 305

Gangway (3' x 32' ±)

Proposed Wood Wharf (FIXED)

153.38'

Existing Wood Floating

Wharf

Harbor Commissioners Line

HARBOR COVE



PLAN ACCOMPANYING PETITION OF
THE CITY OF GLOUCESTER
TO CONSTRUCT AND MAINTAIN A WOOD
WHARF AND MAINTAIN EXISTING FLOATS,
PILES, RAMPS, AND RIPRAP IN GLOUCESTER HARBOR, CITY OF GLOUCESTER,
ESSEX COUNTY, MASS.
SHEET 1 OF 2

LICENSE PLAN NO. 672


Approved by Department of Environmental Quality Engineering
JULY 10, 1980

[Signature]

COMMISSIONER
CHIEF ENGINEER



1" = 8'



79W-0098

LICENSE PLAN NO. 672

Approved by Department of Environmental Quality Engineering

JULY 10, 1980




CITY OF GLOUCESTER

SHEET 2 OF 2

028-007-000-016-200

ROGERS

STREET



SECTION A-A

SCALES VERT & HOR



ELEVATIONS ARE IN FEET AND
REFER TO MEAN LOW WATER

PLAN TO ACCOMPANY PETITION OF
CITY OF GLOUCESTER
TO CONSTRUCT RIPRAP AND SOLID FILL
HARBOR COVE, GLOUCESTER HARBOR

GLOUCESTER


JUNE 1957

LICENSE PLAN NO 3992
APPROVED BY DEPARTMENT OF PUBLIC WORKS
JULY 23 1957

Fred B. Dole

COMMISSIONER OF
PUBLIC WORKS



ASSOCIATE
COMMISSIONERS



YDS. TO BE DREDGED AND DEPOSITED AT SEA AT NEAREST APPROVED DUMPING GROUND.
APPROXIMATELY 7,500 C.U. YDS. OF EXCAVATED MATERIAL TO BE DEPOSITED ON SITE.

FILL:

APPROXIMATELY 7,500 C.U. YDS. EXCAVATED MATERIAL TO BE USED AS FILL.
APPROXIMATELY 29,700 C.U. YDS. OF BORROW MATERIAL TO BE USED AS FILL.



PLANS ACCOMPANYING PETITION OF THE GLOUCESTER REDEVELOPMENT AUTHORITY TO CONSTRUCT & MAINTAIN RIP RAP DIKE, FILL, CONCRETE PIERS, TIMBER PILE FENDERS, EXTEND EXISTING DRAINAGE LINES AND DREDGE, AT INNER HARBOR, GLOUCESTER, COUNTY OF ESSEX, MASSACHUSETTS



SCALE 1"=100'
0 50 100 200 80W-026

LICENSE PLAN NO. 771

Approved by Department of Environmental Quality Engineering
of Massachusetts **FEBRUARY 5, 1982**

John J. [Signature]
COMMISSIONER
CHIEF ENGINEER

028-053-000-016-100





ELEVATIONS BASED ON M.L.W. = 0.0'

LICENSE PLAN NO. 771


Approved by Department of Environmental Quality Engineering
FEBRUARY 5, 1982

PLANS ACCOMPANYING PETITION OF
THE GLOUCESTER REDEVELOPMENT AUTHORITY
TO CONSTRUCT & MAINTAIN RIP RAP
DIKE, FILL, CONCRETE PIERS, TIMBER
PILE FENDERS, EXTEND EXISTING
DRAINAGE LINES AND DREDGE, AT
INNER HARBOR, GLOUCESTER,






SECTION 'C' 1" = 20'



* ACTUAL DIMENSION TO BE DETERMINED UPON COMPLETION OF STATE FISH PIER CONSTRUCTION


PLAN 'D' 1" = 40'



SECTION 'D' 1" = 20'

LICENSE PLAN NO.


Approved by Department of Environmental Quality Engineering




PLANS ACCOMPANYING PETITION OF THE GLOUCESTER REDEVELOPMENT AUTHORITY TO CONSTRUCT & MAINTAIN RIP RAP DIKE, FILL, CONCRETE PIERS, TIMBER PILE FENDERS, EXTEND EXISTING DRAINAGE LINES AND DREDGE, AT INNER HARBOR. GLOUCESTER.

LICENSE PLAN NO. 771

028-053-000.016-100



Super R.L.S.




SOUNDINGS AND ELEVATIONS ARE IN FEET AND REFER TO MEAN LOW WATER

GLOUCESTER HOUSING AUTHORITY
MAPLEWOOD PARK
GLOUCESTER, MASS.


PROP. ROADWAY
WIDENING

PROP. LIMIT
OF SLOPE
ADE FLOOD CO.
R-417 MAIN ST.
GLOUCESTER, MASS.

HARBOR
COMMISSIONERS
LINE



APPROXIMATELY 510 CU. YDS. OF
FILL MATERIAL, INCLUDING
50 CU. YDS. OF RIPRAP.
TOTAL FILL BELOW M.H.W. = 56 CU. YDS.



PLAN ACCOMPANYING PETITION OF
THE GLOUCESTER HOUSING AUTHORITY
TO CONSTRUCT A 30" R.C. DRAIN
AND FILL A PORTION OF THE
GLOUCESTER INNER HARBOR
ESSEX COUNTY
GLOUCESTER, MASSACHUSETTS
MARCH, 1979

79W-0031


SHEET # OF 1

LICENSE PLAN NO. 569
Approved by Department of Environmental Quality of Massachusetts
MAY 24, 1979
COMMISSIONER
CHIEF ENGINEER

(A) - JAMES MONTAGNINO, TRUSTEE, HEAD OF HARBOR
11 PARKER ST., GLOUCESTER, MA.


(B) - PHILIP & LOIS BUDROSE
43 PARKER ST., GLOUCESTER, MA.

028-054-000-108-100



NOTES:

1. APPROXIMATELY 4,000 CY. OF GRANULAR FILL AND 7,000 CY. OF STONE RIPRAP TO BE PLACED AT PIER EXTENSION
2. APPROXIMATELY 46,000 CY. OF EARTH AND 2,000 CY. OF ROCK TO BE DREDGED FROM SITE
3. APPROXIMATELY 1,200 CY. OF STONE RIPRAP TO BE PLACED IN REHAB OF EXISTING RIPRAP



SHEET 1 OF 5 MAY, 1999

LICENSE PLAN NO. 2511


Approved by Department of Environmental Protection
of Massachusetts

COMMISSIONER
SECTION CHIEF

PLANS ACCOMPANYING PETITION OF MASS.
DEPT. OF ENVIRONMENTAL MANAGEMENT
DIVISION OF WATERWAYS TO CONSTRUCT
FINGER PIER, DREDGE, FILL AND PLACE
RIPRAP IN GLOUCESTER HARBOR, CITY OF
GLOUCESTER, COUNTY OF ESSEX, MA.
FAY, SPOFFORD & THORNDIKE, INC. ENGINEERS
LEXINGTON, MASS.

NOV 30 1990

028-054-000-108-100





LICENSE PLAN NO. 2511

Approved by Department of Environmental Protection

Date: **NOV 30 1990**


FAY, SPOFFORD & THORNDIKE, INC. ENGINEERS
LEXINGTON, MASS.





PIER EXTENSION SECTION A-A

0 10 20
SCALE IN FEET



TYPICAL PIER SECTION B-B


0 10 20
SCALE IN FEET


LICENSE PLAN NO. 2511

Approved by Department of Environmental Protection

Date: NOV 30 1990

FAY, SPOFFORD & THORNDIKE, INC. ENGINEERS
LEXINGTON, MASS.






DREDGE DISPOSAL SITE

0 5 10

SCALE IN MILES

NOTES:

1. EARTH DREDGE SIDESLOPES 10 HORIZONTAL TO 1 VERTICAL
2. ROCK DREDGE SIDESLOPES 1 HORIZONTAL TO 1 VERTICAL
3. APPROXIMATE VOLUME OF EARTH DREDGING IS 46,000 C.Y.
4. APPROXIMATE VOLUME OF ROCK DREDGING IS 2,000 C.Y.



TYPICAL DREDGE SECTION C-C

0 20 40 60


SCALE IN FEET

LICENSE PLAN NO. 2511

Approved by Department of Environmental Protection


Date: **NOV 30 1990**

FAY, SPOFFORD & THORNDIKE, INC. ENGINEERS
LEVINGTON, MASS



SHEET 4 OF 5 MAY 1991

028-054-000-108-100




LICENSE PLAN NO. 2511


Approved by Department of Environmental Protection

Date: **NOV 30 1990**

FAY, SPOFFORD & THORNDIKE, INC. ENGINEERS




©1987 MARITIME GROUP INC., GLOUCESTER, MA 01930



WINBURN INC.
77 MARGIN ST
PEABODY
01960

SANDY BAYS
LOBSTERS INC.
PO BOX 8
MAGNOLIA 01930



LOCUS
SCALE 1:25000
FROM USGS QUAD
GLOUCESTER, MA

PIER 7 REALTY TR
C/O MANUEL PERRY TR
5 RACKLIFF ST
GLOUCESTER 01930

ABUTTER'S
FLOATS



NOTE:

EXISTING FLOATS:
20-6'X16', 4-3'X16', 9-4'X20'
REMOVE: 5-4'X20', 4-6'X16'
RELOCATE EXISTING: 3-3'X16'
CONSTRUCT: 9-8'X20'
SEE SHEET 2 FOR PROPOSED PLAN

PILING COUNT:

20 NEW PILES
4 EXISTING UNLICENSED,
3 REMOVED, 1 REMAINING

PLAN




DATUM: MLV NOS
SHEET 1 OF 3

LICENSE PLAN NO. 1814

Approved by Department of Environmental Quality Engineering
of Massachusetts

Thomas F. McLaughlin
COMMISSIONER
DIVISION DIRECTOR
SECTION CHIEF



COMM OF MASS'TTS
STATE FISH PIER
GLOUCESTER 01930

PLANS ACCOMPANYING
PETITION OF
HEAD OF THE HARBOR
NOMINEE TRUST
TO CONSTRUCT & MAINTAIN
FLOATS, RAMP, & PILES
IN GLOUCESTER HARBOR
CITY OF GLOUCESTER, ESSEX COUNTY


028-054-000-108-200

©1987 MARITIME GROUP, GLOUCESTER, MA 01930

WINBURN INC.
77 MARGIN ST
PEABODY
01960

SANDY BAYS
LOBSTERS INC.
PO BOX 8
MAGNOLIA 01930

028-054-000-108-200



4X12 BACKERS IN WAY OF CLEATS-2 FT LONG MIN
2X12 FRAME

1X8 DECKING


20 LB STYROFOAM
BILLET FLOTATION



SECTION 'X'-'X'

1 0 2 4 6 8 10
SCALE IN FEET

3/8 DIA HD GALV
CHAIN BRIDLE



PLAN - 8 FT X 20 FT FLOATS

1 0 2 4 6 8 10
SCALE IN FEET

EXISTING STRUCTURE,
DECK, DOCK, & PILES
LIC. NO. 2815


EXISTING
UNLIC. FLOATS

LICENSE PLAN NO. 1319

Approved by Department of Environmental Quality Engineering
Date: MAY 22 1987

PROPOSED FLOATS

3 PILE
DOLPHIN



DECK
EL 13.0
MHW
EL 8.6
MLW
EL 0.0
ELW
EL -1.0

TYPICAL BOTTOM

WESTERLY ELEVATION

10 0 20 40 60 80 100
SCALE IN FEET

PLANS ACCOMPANYING PETITION OF
HEAD OF THE HARBOR
NOMINEE TRUST
TO CONSTRUCT & MAINTAIN
FLOATS, RAMP, & PILES
IN GLOUCESTER HARBOR
CITY OF GLOUCESTER, ESSEX COUNTY
MASSACHUSETTS

DATUM: MLW NOS

028-130-000-011-200

SECTION A-A

SCALE: HORIZ 1"=100'
VERT 1"=20'


C&G.S CHART NO. 243 LOCATION PLAN

1000 2000 FT.

SECTION B-B

SCALE: HORIZ 1"=100'
VERT 1"=20'

DEPARTMENT OF PUBLIC WORKS



PLAN

SCALE: 1"=100'

All Elevations Refer To Mean Low Water

ACCOMPANYING PETITION OF
CITY OF GLOUCESTER, MASS.
TO DISPOSE OF SURPLUS
BOULDER & LEDGE MATERIAL
IN
COVE, GLOUCESTER HARBOR
GLOUCESTER, MASS.

LICENSE PLAN NO. 4854
APPROVED BY DEPARTMENT OF PUBLIC WORKS OF
MASSACHUSETTS AUGUST 11, 1964


Francis W. Warrant
D. S. Dwight
R. C. Roselli
John H. Warrant

COMMISSIONER - DEPT.
OF PUBLIC WORKS

ASSOCIATE
COMMISSIONER

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
028-001-000-001-100	028-001-000-001-100-COE1A	200002537	USACE	Gloucester	July 2001	City of Gloucester - Fort Square Seawall	8	Fort Square	New Bulkhead and Repairs to Existing Bulkhead
028-003-000-072-100	028-003-000-072-100-COE1A	200002536	USACE	Gloucester	September 2000	Reconstruction of Stone Bulkhead - Stacy Boulevard, Gloucester Harbor, Gloucester	12	Stacy Boulevard	Stone Bulkhead Reconstruction
028-003-000-072-100	028-003-000-072-100-COE1B	200201357	USACE	Gloucester	June 2002	City of Gloucester - Stacy Boulevard	10	Stacy Boulevard - Annisquam Canal	Seawall
028-003-000-072-200	028-003-000-072-200-COE2A	200002536	USACE	Gloucester	September 2000	Reconstruction of Stone Bulkhead - Stacy Boulevard - Gloucester Harbor, Gloucester, MA	12	Stacy Boulevard	Stone Bulkhead Reconstruction
028-007-000-005-100	028-007-000-005-100-COE1A	19840164	USACE	Gloucester	January 1984	Proposed Site Construction on Gloucester Harbor at Gloucester, MA	1	Rogers Street and Parsons Street	Steel Bulkhead
028-007-000-015-200	028-007-000-015-200-COE2A	3256	USACE	Gloucester	July 1954	Proposed Seawall Harbor Cove - Gloucester Harbor, Gloucester, Massachusetts	1	Harbor Cove	Seawall
028-009-000-014-100	028-009-000-014-100-COE1A	73-121	USACE	Gloucester	May 26, 1972	Proposed Shore and Marine Work in Gloucester Harbor at Gloucester, County of Essex, State of Massachusetts	10	Harbor Loop	Riprap and Granite Wall
028-053-000-016-100	028-053-000-016-100-COE1A	79-233	USACE	Gloucester	March 1979	Plan Accompanying Application of the Gloucester Housing Authority to Construct a 30' R.C. Drain and Fill a Portion of the Gloucester Inner Harbor	1	East Main Street and Eastern Avenue	Riprap and Fill
028-054-000-108-100	028-054-000-108-100-COE1A	78-476	USACE	Gloucester	June 9, 1976	Proposed Expansion of Docking Facilities in Gloucester Inner Harbor at Gloucester, County of Essex, Massachusetts	7	State Pier	Wharf Extension, Riprap
028-054-000-108-200	028-054-000-108-200-COE2A	78-476	USACE	Gloucester	June 9, 1976	Proposed Expansion of Docking Facilities in Gloucester Inner Harbor at Gloucester, County of Essex, Massachusetts	7	State Pier	Wharf Extension and Riprap
028-058-000-040-100	028-058-000-040-100-COE1A	200002538	USACE	Gloucester	July 2001	City of Gloucester - Cripple Cove Seawall	6	East Main Street	Revetment and Seawall Repairs
028-058-000-040-200	028-058-000-040-200-COE2A	200002538	USACE	Gloucester	July 2001	City of Gloucester - Cripple Cove Seawall	8	East Main Street	Revetment and Seawall Repairs
028-064-000-061-100	028-064-000-061-100-COE1A	200000896	USACE	Gloucester	April 2000	City of Gloucester - Robinson's Landing	3	Smith Cove	Bulkhead

028-001-000-001-100




DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

LOCUS PLAN

AT: GLOUCESTER HARBOR
FORT SQUARE
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY, 2001 SHEET 1 OF 8

028-001-000-001-100



NOTES:

1. MLW = 0.0, MHW = 8.7, HTL = 10.1
2. SURVEY PROVIDED BY NVA, IN FEBRUARY, 2000 AND JULY, 2000.
3. PROPERTY LINES PER CITY OF GLOUCESTER ASSESSOR PLAN.
4. PROPOSED WORK INCLUDES RECONSTRUCTING 230 LF OF STONE BULKHEAD WITHIN THE EXISTING FOOTPRINT; CONSTRUCTING 289 LF OF STONE OR CONCRETE BULKHEAD APPROXIMATELY 10 FT SEAWARD OF THE EXISTING BULKHEAD. *in Stone Bulkhead.*
5. PROPOSED AREA OF FILL IS 2,800 SF, ALL OF WHICH IS BELOW THE HTL. THE ESTIMATED TOTAL FILLING VOLUME IS 1,200 CY OF WHICH 1,000 CY IS BELOW THE HTL.

DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1


50 0 50
SCALE IN FEET

**PROPOSED
WORK PLAN**

AT: GLOUCESTER HARBOR
FORT SQUARE
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY, 2001 SHEET 2 OF 8

028-001-000-001-100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



**TYPICAL
EXISTING BULKHEAD
SECTION**


STA. 0+00 TO 3+30
STA. 4+57 TO 5+20

AT: GLOUCESTER HARBOR
FORT SQUARE
COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: APRIL, 2001 SHEET 3 OF 8

028-001-000-001-100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

5 0 5
SCALE IN FEET

TYPICAL
EXISTING BULKHEAD
SECTION
STA. 3+30 TO 4+57


AT: GLOUCESTER HARBOR
FORT SQUARE
COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: APRIL 2001 SHEET 4 OF 8

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS

028-001-000-001-100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



**PROPOSED BULKHEAD
SECTION A-A**

STA. 0+00 TO 0+45
STA. 4+57 TO 5+20


AT: GLOUCESTER HARBOR
FORT SQUARE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: APRIL, 2001 SHEET 5 OF 8

028-001-000-001-100




DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



PROPOSED BULKHEAD SECTION B-B STA. 0+45 TO 1+80

AT: GLOUCESTER HARBOR
FORT SQUARE
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS
DATE: APRIL, 2001 SHEET 6 OF 8

028-001-000-001-100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

8 0 8
SCALE IN FEET

**PROPOSED BULKHEAD
SECTION C-C
STA. 1+80 TO 3+34**


AT: GLOUCESTER HARBOR
FORT SQUARE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: APRIL 2001 SHEET 7 OF 8

028-001-000-001-100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

5 0 5
SCALE IN FEET

**PROPOSED BULKHEAD
SECTION D-D
STA. 3+34 TO 4+57**


AT: GLOUCESTER HARBOR
FORT SQUARE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: APRIL, 2001 SHEET 8 OF 8

028-003-000-072 -100
028-003-000-072-200




DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

LOCUS PLAN

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 1 OF 12

028-003-000-072 -100
028-003-000-072 -200



NOTES:

1. DATUM: MLW=0.0; MHW=8.7; HTL=10.1
2. PROPOSED WORK INCLUDES RECONSTRUCTING 2,030 LF OF BULKHEAD OUTSIDE THE EXISTING FOOTPRINT AND REPAIRING OR RECONSTRUCTING 275 LF WITHIN THE EXISTING FOOTPRINT.
3. PROPOSED AREA OF FILL IS APPROXIMATELY 16,200 SF OF WHICH 6750 SF IS BELOW THE HTL. THE ESTIMATED TOTAL FILLING VOLUME IS APPROXIMATELY 5,800 CY, OF WHICH 760 CY IS BELOW THE HTL
4. SEE FIGURE 3 FOR PROPOSED WORK SECTIONS.

DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1


200 0 200
SCALE IN FEET

**EXISTING
CONDITIONS PLAN**

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 2 OF 12

028-003-000-072 -100
028-003-000-072-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

120 0 120
SCALE IN FEET

**PROPOSED
WORK PLAN**
STA. 0+00 TO 13+50


AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 3 OF 12

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS

028-003-000-072 -100

028-003-000-072-200



GLOUCESTER HARBOR

DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




PROPOSED WORK PLAN STA. 13+50 TO 23+05

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 4 OF 12

028-003-000-072 -100
028-003-000-072-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




**EXISTING
SECTION A-A
STA 0+00 TO 20+30**

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 5 OF 12

028-003-000-072 - 100

028-003-000-072 - 200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

5 0 5
SCALE IN FEET


EXISTING
SECTION B-B
STA 20+30 TO 21+55

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 6 OF 12

028-003-000-072 - 100

028-003-000-072 - 200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




**EXISTING
SECTION C-C
STA 21+55 TO 22+70**

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 7 OF 12

028-003-000-072 - 100
028-003-000-072 - 200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




EXISTING
SECTION D-D
STA 22+70 TO 23+05

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 8 OF 12

028-003-000-072 -100

028-003-000-072-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

5 0 5
SCALE IN FEET

PROPOSED
SECTION A-A
STA 0+00 TO 20+30

AT: GLOUCESTER HARBOR
STACY BOULEVARD

COUNTY: ESSEX


APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 9 OF 12

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS

028-003-000-072 -100

028-003-000-072-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

5 0 5
SCALE IN FEET

PROPOSED
SECTION B-B
STA 20+30 TO 21+55

AT: GLOUCESTER HARBOR
STACY BOULEVARD

COUNTY: ESSEX


APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 10 OF 12

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS

028-003-000-072 -100

028-003-000-072 -200



Not to Scale

DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



PROPOSED
SECTION C-C
STA 21+55 TO 22+70


AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 11 OF 12

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS

028-003-000-072 - 100

028-003-000-072-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




**PROPOSED
SECTION B-B
STA 22+70 TO 23+05**

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS
DATE: SEPT 2000 SHEET 12 OF 12

NOT TO SCALE

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS




LOCUS PLAN

AT: ANNISQUAM RIVER
COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

DATE: JUNE 2002 SHEET 1 OF 10



MATCH LINE - SEE SHEET 3

DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

20 0 20
SCALE IN FEET

EXISTING CONDITIONS PLAN

AT: ANNISQUAM RIVER
COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

DATE: JUNE 2002 SHEET 2 OF 10



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




EXISTING CONDITIONS PLAN

AT: ANNISQUAM RIVER
COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

DATE: JUNE 2002 SHEET 3 OF 10



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




SECTION A
STA 20+30 to 21+55

AT: ANNISQUAM RIVER
COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

DATE: JUNE 2002 SHEET 4 OF 10

028-003-000-072 -100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




SECTION B
STA 21+55 to 22+69

AT: ANNISQUAM RIVER
COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

DATE: JUNE 2002 SHEET 5 OF 10



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




SECTION C
STA 22+69 to 23+09

AT: ANNISQUAM RIVER
COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

DATE: JUNE 2002 SHEET 6 OF 10

028-003-000-072 -100



MATCH LINE - SEE SHEET 8

DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

20 0 20
SCALE IN FEET


PROPOSED WORK PLAN

AT: ANNISQUAM RIVER
COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

DATE: JUNE 2002 SHEET 7 OF 10

VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1


20 0 20
SCALE IN FEET

PROPOSED WORK PLAN

AT: ANNISQUAM RIVER
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

DATE: JUNE 2002 SHEET 8 OF 10

028-003-000-072 -100




DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



**PROPOSED
SECTION A
STA. 20+30 to 21+58**

AT: ANNISQUAM RIVER
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

DATE: JUNE 2002 SHEET 9 OF 10




DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



**PROPOSED
SECTION B**
STA 21+58 to 23+09

AT: ANNISQUAM RIVER
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA.

028-003-000-0721 -100
028-003-000 072 - 200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

LOCUS PLAN


AT: GLOUCESTER HARBOR
STACY BOULEVARD

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 1 OF 12

028-003-000-072L-100
028-003-000-072-200



NOTES:

1. DATUM: MLW=0.0; MHW=8.7; HTL=10.1
2. PROPOSED WORK INCLUDES RECONSTRUCTING 2,030 LF OF BULKHEAD OUTSIDE THE EXISTING FOOTPRINT AND REPAIRING OR RECONSTRUCTING 275 LF WITHIN THE EXISTING FOOTPRINT.
3. PROPOSED AREA OF FILL IS APPROXIMATELY 16,200 SF OF WHICH 6750 SF IS BELOW THE HTL. THE ESTIMATED TOTAL FILLING VOLUME IS APPROXIMATELY 5,800 CY, OF WHICH 760 CY IS BELOW THE HTL.
4. SEE FIGURE 3 FOR PROPOSED WORK SECTIONS.

DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1


200 0 200
SCALE IN FEET

**EXISTING
CONDITIONS PLAN**

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 2 OF 12

028-003-000-072 -100
028-003-000-072 -200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




PROPOSED WORK PLAN STA. 0+00 TO 13+50

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 3 OF 12

028-003-000-072-200
028-003-000-072-100



GLoucester Harbor

DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




**PROPOSED
WORK PLAN
STA. 13+50 TO 23+05**

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 4 OF 12

028-003-000-072 -200
028-003-000-072 -100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




EXISTING
SECTION A-A
STA 0+00 TO 20+30

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 5 OF 12

028-003-000-072 - 100
028-003-000-072 - 200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




EXISTING
SECTION B-B
STA 20+30 TO 21+55

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 6 OF 12

028-003-000-072 -100
028-003-000-072 -200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




EXISTING
SECTION C-C
STA 21+55 TO 22+70

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 7 OF 12

028-003-000-072 - 100
028-003-000-072 - 200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1


5 0 5
SCALE IN FEET

EXISTING
SECTION D-D
STA 22+70 TO 23+05

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 8 OF 12

028-003-000-072 - 200
028-003-000-072 - 100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1




**PROPOSED
SECTION A-A
STA 0+00 TO 20+30**

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 9 OF 12

028-003-000-072-200
028-003-000-072-100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



**PROPOSED
SECTION B-B
STA 20+30 TO 21+55**


AT: GLOUCESTER HARBOR
STACY BOULEVARD

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 10 OF 12

028-003-000-072 - 200
028-003-000-072 -100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



PROPOSED
SECTION C-C
STA 21+55 TO 22+70


AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT. 2000 SHEET 11 OF 12

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS

028-003-000-072 - 200

028-003-000-072 - 100



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

5 0 5
SCALE IN FEET

PROPOSED
SECTION B-B
STA 22+70 TO 23+05

AT: GLOUCESTER HARBOR
STACY BOULEVARD
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: SEPT 2000 SHEET 12 OF 12

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS

028-007-000-005-100

Latitude 42°-52'

Longitude 70°-40'

GLOUCESTER

MAIN ST

ROGERS ST

Inner Harbor

Outer Harbor

FORT POINT

ROCKY NECK

South Cove

EAST MAIN ST

MOUNT ALABANY

RTE 128

LOCATION MAP

1000 0 1000
SCALE IN FEET

SCALE IN FEET



SCALE IN FEET

1984


0 100
SCALE IN FEET

X NOTE: SUNKEN BOATS
TO BE REMOVED
UNDER DEMONSTRATION

0920028

NEW ENGLAND DIV.

028-007-000-016-200





APP 02252

0 3 8 0 6 8 7

028-009-000-014-101

LOCATION PLAN
TAKEN FROM
U.S. DEPT. OF INTERIOR G. S.
GLOUCESTER (MASS) QUADRANGLE

0 1000 2000 3000 4000 5000
SCALE OF FEET




Proposed **SHORE & MARINE WORK**
in **GLOUCESTER HARBOR**
at **GLOUCESTER**
County of **ESSEX** *State of* **MASS**
Application by **US COAST GUARD**
FIRST DISTRICT
BOSTON, MASS.

038 0688

028-009-000-014-100

145





Proposed SHORE & MARINE WORK
in GLOUCESTER HARBOR
of GLOUCESTER
County of ESSEX State of MASS
Application by U S COAST GUARD
FIRST DISTRICT
BOSTON MASS

Sheet 2 of 7

Date 4/72

0 3 3 0 6 8 9



028-009-000-014-100



**Proposed SHORE & MARINE WORK
in GLOUCESTER HARBOR
at GLOUCESTER
County of ESSEX State of MASS
Application by US COAST GUARD
FIRST DISTRICT
BOSTON MASS
Sheet 3 of 7 Date 4/72**

038 0690


038-009-000-014-100



Proposed SHORE & MARINE WORK
in GLOUCESTER HARBOR
at GLOUCESTER
County of ESSEX State of MASS
Application by US COAST GUARD
FIRST DISTRICT
BOSTON MASS
Sheet 4 of 7
Date 4/72


033 0691

038-009-000-014-100



DOLPHIN PLAN

SCALE: 1" = 10' 0"



DOLPHIN ELEVATION

SCALE: 1" = 10' 0"





Proposed SHORE & MARINE WORK
in GLOUCESTER HARBOR
of GLOUCESTER

County of ESSEX State of MASS
Application by US COAST GUARD
FIRST DISTRICT
BOSTON MASS

0 3 8 0 6 9 2



028-009-000-014-100



Proposed SHORE & MARINE WORK
in GLOUCESTER HARBOR
at GLOUCESTER
County of ESSEX State of MASS
Application by U.S. COAST GUARD

0 3 8 0 6 9 3

038-009-000-014-100



Dredged Sections Under Boat Float

Proposed SHORE & MARINE WORK
in GLOUCESTER HARBOR
of GLOUCESTER
County of ESSEX State of MASS
Application by U.S. COAST GUARD
FIRST DISTRICT
BOSTON MASS


Sheet 7 of 7

Date 4/72

A hand-drawn map of Gloucester, Massachusetts, showing the harbor, inner harbor, and surrounding streets. The map includes labels for 'GLOUCESTER', 'MAIN ST.', 'GLOUCESTER HARBOR', 'INNER HARBOR', 'LOCUS', 'SOUTH COVE', and 'EAST GLOUCESTER'. A compass rose indicates North (N) and a scale bar shows 12° 57' and 20° 40'.

SCALE - FEET
0 3000
SEE U.S. GEOLOGICAL SURVEY
GLOUCESTER QUADRANGLE

*SOUNDINGS ARE IN FEET AND
TENTHS AND SNOW DEPTHS BELOW
THE PLANE OF MEAN LOW WATER*







PLAN ACCOMPANYING PETITION OF
U.S. COAST GUARD
TO CONSTRUCT DOCK, PIERS,
WALLS, RIPRAP SLOPE & FILL
IN
GLOUCESTER HARBOR
GLOUCESTER, MASS.
OCTOBER, 1972

057-000-014-100

038 0695

028-009-000-014-100




SECTION THRU EXISTING GRANITE WALL D-D


SCALE - FEET
0 5 10
1" = 10'

0 3 8 0 6 9 6

028-009-000-014-100




ELEVATION OF BOAT HOIST PIERS



SECTION THRU BOAT HOIST PIERS


E-E

SCALE - FEET





146 1677

028-053-000-016-100



SOUNDINGS ARE IN FEET AND
REFER TO MEAN LOW WATER



PLAN ACCOMPANYING APPLICATION OF
THE GLoucester HOUSING AUTHORITY


TO CONSTRUCT A 30" R.C. DRAIN
AND FILL A PORTION OF THE
GLoucester INNER HARBOR

ESSEX COUNTY
GLoucester, MASSACHUSETTS


MARCH, 1979

END - 1 OF 1


028-054-000-108-100
028-054-000-108-200



028-054-000-108-100
028-054-000-108-200




SECTION A-A




SECTION B-B

Horiz. 0 20 40 Feet
Vert. 0 10 20 Feet
SCALES FOR SECTION VIEWS



VICINITY PLAN




PLAN


PURPOSE: PRIVATE WHARF EXTENSION
DATUM: MEAN LOW WATER

AREA 'A'
PROPOSED WHARF EXTENSION
IN GLOUCESTER INNER HARBOR
AT GLOUCESTER
COUNTY OF ESSEX STATE: MASS
APPLICANT:
COMMONWEALTH OF MASSACHUSETTS
DEQE

028-054-000-108-200



PLAN



SECTION A-A

PURPOSE: PUBLIC BERTHING FACILITIES
DATUM: MEAN LOW WATER


AREA "B"

PROPOSED BERTHING FACILITIES
IN GLOUCESTER INNER HARBOR
AT GLOUCESTER


COUNTY OF ESSEX STATE MASS
APPLICANT:
COMMONWEALTH OF MASSACHUSETTS
DEQE

SHEET 2 OF 3 DATE: 6/9/76

028-054-000-108-100
028-054-000-108-200




PLAN



VICINITY PLAN

FROM USGS QUAD SHEET (GLOUCESTER)



SECTION A-A



AREA "C"

PROPOSED BERTHING FACILITIES
IN GLOUCESTER INNER HARBOR
AT GLOUCESTER

PURPOSE: PUBLIC BERTHING FACILITIES
DATUM: MEAN LOW WATER

COUNTY OF ESSEX STATE: MASS
APPLICANT:
COMMONWEALTH OF MASSACHUSETTS
DEQE

028-054-000-108-100
028-054-000-108-200



NOTES: 1/ DREDGE TO EL. -10.0.

2/ EST. DREDGED MATERIAL 4,000 Cu. yds.

3/ TYPE OF MATERIAL TO BE DREDGED IS ORGANIC SILT, SED. SAMPLE NO.'s 2420 & 2421.

4/ METHOD OF HANDLING WILL BE MECHANICAL.

5/ THE DISPOSAL SITE IS LOCATED AT ST. JOSEPH'S CEM. IN AMESBURY OR OTHER SATISFACTORY LAND DISPOSAL.

6/ SOUNDINGS ARE IN FEET AND TENTHS AND REFER TO DEPTHS BELOW THE PLANE OF MEAN LOW WATER.

PROPOSED EXPANSION OF DOCKING FACILITIES


IN GLOUCESTER INNER HARBOR
AT GLOUCESTER, MASS.
COUNTY OF ESSEX STATE MASS

APPLICATION BY
COMMONWEALTH OF MASSACHUSETTS
BBC/DEQE

SHEET 1 OF 1

AUG. 10, 1978

028-054-000-108-100
028-054-000-150-820




GLOUCESTER COMMUNITY
PIER ASSOCIATION
PIER IMPROVEMENTS

10 50 100 200
SCALE: FEET


LEGEND
NEW FACILITIES
RENOVATED FACILITIES

028-054-000-108-100
028-054-000-108-200



UTM GRID AND 1973 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET

SCALE 1:24 000




GLoucester, MA
N4233.75—W7037.51

1973


028-054-000-108-100

028-054-000-108-200




028-054-000-108-100

028-054-000-108-200





SECTION A-A



SECTION B-B

Horiz. 0 20 40 Feet
Vert. 0 10 20 Feet
SCALES FOR SECTION VIEWS



PLAN

PURPOSE: PRIVATE WHARF EXTENSION
DATUM: MEAN LOW WATER

AREA 'A'


PROPOSED WHARF EXTENSION
IN GLOUCESTER INNER HARBOR
AT GLOUCESTER

COUNTY OF ESSEX STATE: MASS
APPLICANT:
COMMONWEALTH OF MASSACHUSETTS
DEQE


SHEET 1 OF 3 DATE: 6/9/76

028-054-000-108-100

028-054-000-108-200



PLAN



SECTION A-A

PURPOSE: PUBLIC BERTHING FACILITIES
 DATUM: MEAN LOW WATER


AREA "B"

PROPOSED BERTHING FACILITIES
 IN GLOUCESTER INNER HARBOR
 AT GLOUCESTER


COUNTY OF ESSEX STATE MASS
 APPLICANT:
 COMMONWEALTH OF MASSACHUSETTS
 DEGE

SHEET 2 OF 3 DATE: 6/9/76

028-054-000-108-100
028-054-000-108-200




PLAN



VICINITY PLAN

FROM USGS QUAD SHEET (GLOUCESTER)

2203



SECTION A-A


AREA "C"

PROPOSED BERTHING FACILITIES
IN GLOUCESTER INNER HARBOR
AT GLOUCESTER

PURPOSE: PUBLIC BERTHING FACILITIES
DATUM: MEAN LOW WATER

COUNTY OF ESSEX STATE: MASS
APPLICANT:
COMMONWEALTH OF MASSACHUSETTS
DEQE

028-054-000-108-100
028-054-000-108-200



NOTES: 1/ DREDGE TO EL. -10.0.

2/ EST. DREDGED MATERIAL 4,000 Cu. yds.

3/ TYPE OF MATERIAL TO BE DREDGED IS ORGANIC SILT, SED. SAMPLE NO.'s 2420 & 2421.

4/ METHOD OF HANDLING WILL BE MECHANICAL.

5/ THE DISPOSAL SITE IS LOCATED AT ST. JOSEPH'S CEM. IN AMESBURY OR OTHER SATISFACTORY LAND DISPOSAL.

6/ SOUNDINGS ARE IN FEET AND TENTHS AND REFER TO DEPTHS BELOW THE PLANE OF MEAN LOW WATER.

PROPOSED EXPANSION OF DOCKING FACILITIES


IN GLOUCESTER INNER HARBOR
AT GLOUCESTER, MASS.
COUNTY OF ESSEX STATE MASS

APPLICATION BY
COMMONWEALTH OF MASSACHUSETTS
BBC/DEQE



SHEET 1 OF 1

AUG. 10, 1978

028-054-000-108-100
028-054-000-108-200




028-054-000-108-100
028-054-000-108-200



UTM GRID AND 1973 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET


SCALE 1:24 000



GLOUCESTER, MA
N4233.75—W7037.51

1973

028-058-000-040-100
028-058-000-040-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

LOCUS PLAN


AT: GLOUCESTER HARBOR
CRIPPLE COVE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY 2001 SHEET 1 OF 6

028-058-000-040-100
028-058-000-040-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

40 0 40
SCALE IN FEET


PROPOSED WORK PLAN

AT: GLOUCESTER HARBOR
CRIPPLE COVE
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY 2001 SHEET 2 OF 6

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS

028-058-000-040-100
028-058-000-040-200




DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

6 0 6
SCALE IN FEET

PROPOSED REVETMENT REPAIR SECTION A-A

AT: GLOUCESTER HARBOR
CRIPPLE COVE
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS
DATE: JULY 2001 SHEET 3 OF 6

028-058-000-040-100
028-058-000-040-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



**PROPOSED
BULKHEAD REPAIR
STA. 0+00 TO 1+47
SECTION B-B**


AT: GLOUCESTER HARBOR
CRIPPLE COVE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY 2001 SHEET 4 OF 6

028-058-000-040-100
028-058-000-040-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



**PROPOSED
BULKHEAD REPAIR
STA. 1+47 TO 2+35
SECTION C-C**


AT: GLOUCESTER HARBOR
CRIPPLE COVE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY 2001 SHEET 5 OF 6

028-058-000-040-100
028-058-000-040-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

6 0 6
SCALE IN FEET

**PROPOSED
BULKHEAD REPAIR
STA. 2+35 TO 2+78
SECTION D-D**


AT: GLOUCESTER HARBOR
CRIPPLE COVE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY 2001 SHEET 6 OF 6

028-058-000-040-100
028-058-000-040-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

LOCUS PLAN


AT: GLOUCESTER HARBOR
CRIPPLE COVE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY 2001 SHEET 1 OF 6

028-058-000-040-100
028-058-000-040-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

40 0 40
SCALE IN FEET

PROPOSED WORK PLAN


AT: GLOUCESTER HARBOR
CRIPPLE COVE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY 2001 SHEET 2 OF 6

028-058-000-040-100
028-058-000-040-200




DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



PROPOSED REVETMENT REPAIR SECTION A-A

AT: GLOUCESTER HARBOR
CRIPPLE COVE
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS
DATE: JULY 2001 SHEET 3 OF 6

028-058-000-040-100
028-058-000-040-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



**PROPOSED
BULKHEAD REPAIR
STA. 0+00 TO 1+47
SECTION B-B**


AT: GLOUCESTER HARBOR
CRIPPLE COVE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY 2001 SHEET 4 OF 6

028-058-000-040-100
028-058-000-040-200




DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1



**PROPOSED
BULKHEAD REPAIR
STA. 1+47 TO 2+35
SECTION C-C**

AT: GLOUCESTER HARBOR
CRIPPLE COVE
COUNTY: ESSEX
APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS
DATE: JULY 2001 SHEET 5 OF 6

028-058-000-040-100
028-058-000-040-200



DATUM: MLW = 0.0
MHW = 8.7
HTL = 10.1

6 0 6
SCALE IN FEET

**PROPOSED
BULKHEAD REPAIR
STA. 2+35 TO 2+78
SECTION D-D**


AT: GLOUCESTER HARBOR
CRIPPLE COVE

COUNTY: ESSEX

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MASSACHUSETTS

DATE: JULY 2001 SHEET 6 OF 6

028-064-000-061-100



DATUM: MLW=0.0
MHW=8.7
HTL=11.2



SCALE IN METERS
1:25,000

LOCUS PLAN

Robinson's Landing

AT: SMITH COVE
GLOUCESTER HARBOR

COUNTY: ESSEX, MA


APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA

DATE: APRIL 2000


SHEET 1

NUCCI VINE ASSOCIATES, INC. NEWBURYPORT, MASSACHUSETTS

028-664-000-061-100



EXISTING SECTION A-A
SCALE: 1"=10'



PROPOSED SECTION A-A
SCALE: 1"=10'

DATUM: MLW=0.0
MHW=8.7
HTL=11.2

10 0 10
SCALE IN FEET

SECTIONS ROBINSON'S LANDING

AT: SMITH COVE
GLOUCESTER HARBOR

COUNTY: ESSEX, MA

APPLICATION BY:
CITY OF GLOUCESTER
GLOUCESTER, MA

DATE: APRIL 2000

SHEET 3

Section III

Rockport

Section III – Community Findings – Town of Rockport

COMMUNITY DESCRIPTION

The Town of Rockport consists of a land area of 7.07 square miles out of a total area of 17.59 square miles and had a population of 7,767 in the 2000 census. The Town is located on the North Shore of Massachusetts and its location can be seen on this report's cover. The estimated length of shoreline that is directly exposed to open ocean waves is 14 miles with the remaining shoreline semi-protected by offshore structures or landforms. The town is protected from major coastal storms by both natural and man-made shoreline structures that require maintenance to insure the long term protection of its coastline. The man-made and publicly owned structures that protect the Town were investigated for their ability to provide adequate protection from major coastal storms. Structures have been identified as publicly owned, including coastal dunes and beaches, based on evidence of investment of public funds made to create/enhance/maintain these structures. The assessment did not include floating or pile supported structures as they are assumed not to provide any significant coastal protection from major storm events.

STRUCTURE INVENTORY

Within the Town of Rockport, there were 22 structures which had public or unknown ownership which provide significant coastal protection. The location of the structures can be seen in Sheets 1 through Sheet 4 in Section III-B of this report. The structures were categorized by their type and by their structural condition based on a preliminary field assessment. The distribution of structures by type and condition can be seen in the following table:

STRUCTURE TYPE AND QUANTITY - Town of Rockport

Primary Structure (1)	Total		Structure Condition Rating				Total Length
	Structures	A	B	C	D	F	
Bulkhead / Seawall	13	2	8	3			8188
Revetment	5			1	3	1	2655
Breakwater	4		2	1	1		1995
Groin / Jetty							
Coastal Dune							
Coastal Beach							
	22	2	10	5	4	1	12838

Within the above table, the total length of each type of structure is also provided. The structures are listed by the type which is providing the primary coastal protection. Many sites have multiple structure types at the same location (i.e. revetment in front of seawall). These secondary structures, although not identified within these tables, are included in the development of repair/rehabilitation costs.

The development of repair costs has been included by structure type and by condition. In the Town of Rockport's case there are a total of 20 structures which would require approximately \$ 21.9 million to bring all the coastal structures to "A" Rating. Most critical will be the structures in the "D" and "F" classifications as those are assumed to undergo some level of damage or failure during the next major coastal storm event. To reconstruct these structures, identified in the preliminary survey as being in poor condition, an estimated \$ 4.4 million would be required to upgrade the Town's coastal protection.

STRUCTURE REPAIR / RECONSTRUCTION COST - Town of Rockport

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Bulkhead / Seawall	13		\$ 1,442,258	\$ 12,541,980			\$ 13,984,238
Revetment	5			\$ 1,727,880	\$ 2,734,809	\$65,010	\$ 4,527,699
Breakwater	4		\$ 370,810	\$ 1,382,304	\$ 1,579,776		\$ 3,332,890
Groin / Jetty							\$ -
Coastal Dune							\$ -
Coastal Beach							\$ -
	22	\$ -	\$ 1,813,068	\$ 15,652,164	\$ 4,314,585	\$ 65,010	\$ 21,844,827

Based on the limited research within the scope of this project research, the presumed ownership of the structures was established on an initial basis and would be subject to more intense review in future tasks. Structures identified as being owned privately were excluded from further consideration. Although ownership of the land on which the structure was located was a factor, the structure ownership was treated as a separate issue from land ownership. For the Town of Rockport, the breakdown of structures by assumed ownership is as follows:

STRUCTURE OWNERSHIP / REPAIR COST - Town of Rockport

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Town Owned	22		\$ 1,813,068	\$ 15,652,164	\$ 4,314,585	\$ 65,010	\$ 21,844,827
Commonwealth of Massachusetts							\$ -
Federal Government Owned							\$ -
Unknown Ownership							\$ -
	22	\$ -	\$ 1,813,068	\$ 15,652,164	\$ 4,314,585	\$ 65,010	\$ 21,844,827

The identification of presumed ownership was not based on the investigation of legal documents but relied on property ownership and from construction and regulatory documents that were found. A more detailed investigation of legal documents and agreements would be required where structure ownership is disputed. A more detailed identification of structure type, length, condition and location can be found in Section III-B which contains Structure Assessment Reports for each individual structure found.

SUMMARY

The enclosed reports and associated documents reflects the Town of Rockport's coastal structure information that will eventually be input into a state-wide GIS database and will be accessible through MassGIS. This data, when compiled state-wide, will be critical in the development of both short term and long term planning for maintaining and improving Massachusetts coastal protection.

This database will also provide relatively quick access to identify available documentation for these structures as well as the ability to be updated as coastal structure improvements are made.

Section III - Rockport

Part B

Structure Assessment Reports




COASTAL STRUCTURE LOCATION PLAN

TOWN OF ROCKPORT
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



SCALE: 1" = 150'-0"




COASTAL STRUCTURE LOCATION PLAN

TOWN OF ROCKPORT
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007


0 150
SCALE: 1" = 150'-0"





COASTAL STRUCTURE LOCATION PLAN

TOWN OF ROCKPORT
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



BCE Bourne Consulting Engineering
3 Pond Street
Rockport, MA 01966
TEL: (508) 635-0000 FAX: (508) 635-0000



COASTAL STRUCTURE LOCATION PLAN

TOWN OF ROCKPORT
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



SCALE: 1" = 150'-0"

BCE *Bourne Consulting Engineering*
2 Acad Street
Bourne, MA 01909
TEL: (508) 535-4000 FAX: (508) 535-5000

Structure Assessment Form

Town: **Rockport**Structure ID: **062-016-000-026-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Pigeon Cove

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$50,160.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
200	6	V2	25
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

The stone block bulkhead is approximately 5 feet by 2 feet by 2 feet. Some settling of stones. The top is used for storage of fishing equipment and parking. No sign of scour throughout.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with **Limited** potential for Significant Infrastructure Damage

Structure Images:

062-016-000-026-100-PHO1A.jpg**062-016-000-026-100-PHO1B.jpg**

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-016-000-026-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Pigeon Cove

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$314,000.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
1000	31	V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Breakwater

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone mound breakwater with a 1 on 1 slope on both sides. Stone size 5 feet by 3 feet by 2 feet. The crest is 9 feet across. The breakwater protects the cove and houses behind it. The outshore face has been unraveled at one area 5 feet long.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

V

Rating

Immediate / Highest Priority

Action

Consider For Immediate Action Due to Public Safety and Welfare Issues

Description

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-016-000-026-200-PHO2A.jpg

062-016-000-026-200-PHO2B.jpg

Structure Documents:

Structure Assessment FormTown: **Rockport**Structure ID: **062-016-000-026-300**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Pigeon Cove

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$203,346.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
130	7	V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped riprap; approximately 200 pound stones. In between is a boat railway. The stones are unraveled and settled.

*Condition***D***Rating***Poor***Level of Action***Major***Description*

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

*Priority***III***Rating***Moderate Priority***Action*

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

062-016-000-026-300-PHO3A.jpg**062-016-000-026-300-PHO3B.jpg**

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-016-000-026-400**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Pigeon Cove Breakwater

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$1,579,776.00

Length: Top Elevation: FIRM Map Zone: FIRM Map Elevation:

320

7

V2

15

Feet

Feet NAVD 88

Feet NGVD

Primary Type:

Breakwater

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone breakwater has stones that are approximately 9 feet by 3 feet by 2 feet. The middle section has unraveled and failed about 40 feet. It is built on ledge to help protect the cove behind it and the channel adjacent to it.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

V

Rating

Immediate / Highest Priority

Action

Consider For Immediate Action Due to Public Safety and Welfare Issues

Description

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-016-000-026-400-PHO4A.jpg

062-016-000-026-400-PHO4B.jpg

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-017-000-017-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Old Granite Peir

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$1,727,880.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
1400	35	V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone riprap revetment with two sections approximately 30 feet long have unraveled due to storm damage. The understone is exposed. The top has areas of erosion. There is some movement and settling of the stones throughout. There is a crushed stone parking area on top.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-017-000-017-100-PHO1A.jpg

062-017-000-017-100-PHO1B.jpg

062-017-000-017-100-PHO1C.jpg

Structure Documents:

Structure Assessment FormTown: **Rockport**Structure ID: **062-017-000-019-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Old Granite Pier

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unkown

Estimated Reconstruction/Repair Cost:

\$269,280.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
680	4	V2	23
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

Stone bulkhead with stones approximately 8 feet by 3 feet by 3 feet. The top is concrete and crushed stones are used for boat storage. Some stones have been stapled together. A few stones are missing at the tidal zone.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

062-017-000-019-100-PHO1A.jpg

062-017-000-019-100-PHO1B.jpg

062-017-000-019-100-PHO1C.jpg

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-017-000-054-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Back Beach

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$2,320,296.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
940	15	V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

The stone riprap is approximately 5 feet by 3 feet by 3 feet. The toe is still in place and buried. Some sections of the stone have settled and caved in. Behind the riprap is a road and houses; in front of the riprap is a beach. The middle of the revetment has been washed out and replaced and filled in with cobble. The ends are still intact.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-017-000-054-100-PHO1A.jpg

062-017-000-054-100-PHO1B.jpg

Structure Documents:

Structure Assessment FormStructure ID: **062-021-000-017-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Long Beach

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$10,928,280.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
3400	16	V2	17
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Over 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Over 15 Feet**Structure Summary :**

The concrete seawall has a wave return face. It is 3 feet wide at the top. Many homes are close behind the wall and a sandy beach in front. Minor cracks and spalling on the wall. There are many visible repairs. There are a few sink holes behind the wall and the walkway is heaving. The riprap is one stone high starting at the wall and continuing out 20 feet. The riprap is on average 6 feet by 3 feet by 3 feet.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***IV***Rating***High Priority***Action***Consider for Next Project Construction Listing***Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:**062-021-000-017-100-PHO1A.jpg****062-021-000-017-100-PHO1B.jpg****Structure Documents:****MA-DCR****September 1****Proposed Seawall****062-021-000-017-100-DCR1A**

Structure Assessment FormStructure ID: **062-022-000-309-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Old Garden Beach

Date:

3/13/2009

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$10,454.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
33		V2	28
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Under 5 Feet**Structure Summary :**

Stone blocks that are approximately 4 feet by 2 feet by 2 feet set six courses high. No shifting or rotating visible in stones. Mortar is intact. Minor erosion behind wall, which has been repaired. In front of wall is beach rocks used as riprap. Rocks are scattered and minor scour is visible.

Condition
Rating
Level of Action
Description

B**Good****Minor**

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority
Rating
Action
Description

II**Low Priority****Future Project Consideration**

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:**062-022-000-309-100-PHO1A.JPG****Structure Documents:**

Structure Assessment Form

Town: **Rockport**Structure ID: **062-022-000-309-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Old Garden Beach

Date:

3/13/2009

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unkown

Estimated Reconstruction/Repair Cost:

\$65,010.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
50		V2	28
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped stone approximately 4 feet in diameter in front of a pumping station. Stones are scattered creating many voids. There is heavy erosion in the coastal bank behind the revetment.

Condition

F

Rating

Critical

Level of Action

Immediate

Description

Conditions of structure/landform may warrant emergency stabilization as failure may result in potential loss of property and/or life. Landform eroded, loss of integrity. Structure exhibits critical levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure provides little or no protection from a major coastal storm. Actions taken to totally reconstruct structure to regain full capacity. Landform stability is severely compromised, rate of erosion/material loss may be increasing, and landform does not provide adequate protection from a major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-022-000-309-200-PHO2A.JPG

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-026-000-026A-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Granite Street

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$524,700.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
265	8	V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone bulkhead with parking lot and building behind. Stones are approximately 9 feet by 3 feet by 2 feet. Some movement of stones and sink holes behind walk and at the corners of the wall. No sign of scour. Some stone movement at jetty.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

062-026-000-026A-100-PHO1A.jpg

062-026-000-026A-100-PHO1B.jpg

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-035-000-001A-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

White Wharf

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$1,089,000.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
550	16	V2	18
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone bulkhead with stones that are 5 feet by 2 feet by 2 feet. There is no visible scour. Some settling of stones and erosion and cracking at the top. The wall never had or has lost chinking stones. Some stones have been stapled together. The out shore face was built twice as high then steps down. Adjacent to it is a channel for a small cove. The higher section has been mortared. There looks to have been recent repairs.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-035-000-001A-100-PHO1A.jpg

062-035-000-001A-100-PHO1B.jpg

062-035-000-001A-100-PHO1C.jpg

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-035-000-018C-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Middle Wharf

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unkown

Estimated Reconstruction/Repair Cost:

\$82,764.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
330	4	V2	18
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

The stone bulkhead has stones that are approximately 5 feet by 2 feet by 2 feet. There is no visible scour. Some settling of stones and erosion at the top. The wall never had or has lost chinking stones. Some stones have been stapled together. The top has concrete that is cracking.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***IV***Rating***High Priority***Action***Consider for Next Project Construction Listing***Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-035-000-018C-100-PHO1A.jpg**062-035-000-018C-100-PHO1B.jpg**

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-035-000-021E-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lumber Wharf

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$251,460.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
635	6	V2	18
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone bulkhead with stones that are 5 feet by 2 feet by 2 feet. There is no visible scour. Some settling of stones and erosion and cracking at the top. The wall never had or has lost chinking stones. Some stones have been stapled together. The outshore face was built twice as high then steps down. Adjacent to it is a channel for a small cove. The higher section has been mortared.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-035-000-021E-100-PHO1A.jpg

062-035-000-021E-100-PHO1B.jpg

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-035-000-053-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Beach Street

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$0.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
130	9	AO	2
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

The stone wall is mortared with stones approximately 7 feet by 2 feet by 2 feet in size. There is a ramp that goes to the beach. The wall is protecting the road behind and there is a sandy beach in front. No scour or erosion is visible.

Condition

A

Rating

Excellent

Level of Action

None

Description

Like new condition. Structure expected to withstand major coastal storm without damage. Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-035-000-053-100-PHO1A.jpg

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-035-000-054-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Beach Street

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$0.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
120	10	AO	2
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone wall with concrete mortar. Stones are 4 feet by 2 feet by 2 feet. Appears to be recently repaired. Behind the wall there is a road and houses; in front, there is a sandy beach. There is a stair access to the beach.

Condition

A

Rating

Excellent

Level of Action

None

Description

Like new condition. Structure expected to withstand major coastal storm without damage. Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-035-000-054-100-PHO1A.jpg

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-036-000-002-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Headlands Breakwater

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$56,810.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
115	11	V2	20
Feet	Feet NAVD 88		Feet NGVD

Primary Type:	Primary Material:	Primary Height:
Breakwater	Stone	Over 15 Feet
Secondary Type:	Secondary Material:	Secondary Height:



Structure Summary :

Small breakwater that protects the mouth of Rockport Harbor. Stones are approximately 5 feet by 5 feet by 5 feet. Some stone movement and voids are visible.

<i>Condition</i>	B
<i>Rating</i>	Good
<i>Level of Action</i>	Minor
<i>Description</i>	Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

<i>Priority</i>	V
<i>Rating</i>	Immediate / Highest Priority
<i>Action</i>	Consider For Immediate Action Due to Public Safety and Welfare Issues
<i>Description</i>	Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-036-000-002-100-PHO1A.jpg

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-036-000-033-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

T-Wharf

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

1998

Estimated Reconstruction/Repair Cost:

\$376,200.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
950	12	V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

The stone bulkhead with a parking lot above it and floats attached to it with average stone size of 4 feet by 2 feet. Some stone movement and unraveling. There is no visible scour. The west side has concrete on top of the wall that is cracking at sections.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

062-036-000-033-100-PHO1A.jpg**062-036-000-033-100-PHO1B.jpg****062-036-000-033-100-PHO1C.jpg**

Structure Documents:

USACE**November 1****Bradley Wharf and T-****062-036-000-033-100-COE1A****DEP****July 26, 199****Town of Rockport****062-036-000-033-100-LIC1A**

Structure Assessment Form

Town: **Rockport**Structure ID: **062-036-000-054-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Rockport Harbor

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$211,167.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
135	18	V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Riprap against a cast in place concrete boat ramp. Stone size is approximately 100 to 200 pounds. Section loss and stones are unraveled in a few sections. The boatramp is undermined and cracking halfway up.

Condition
Rating
Level of Action
Description

D

Poor

Major

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority
Rating
Action
Description

I

None

Long Term Planning Considerations

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

062-036-000-054-100-PHO1A.jpg

Structure Documents:

Structure Assessment Form

Town: **Rockport**Structure ID: **062-036-000-067-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Bradley Wharf

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

1998

Estimated Reconstruction/Repair Cost:

\$267,300.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
675	10	V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone bulkhead with stones that are approximately 6 feet by 3 feet by 2 feet. Some settling and movement of stones. Parking lot and fishing equipment storage above. No scour or undermine visible.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***III***Rating***Moderate Priority***Action*

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

062-036-000-067-100-PHO1A.jpg**062-036-000-067-100-PHO1B.jpg**

Structure Documents:

USACE**November 1****Bradley Wharf and T-****062-036-000-067-100-COE1A****DEP****July 26, 199****Town of Rockport****062-036-000-067-100-LIC1A**

Structure Assessment Form

Town: **Rockport**Structure ID: **062-036-000-077-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Inner Breakwater

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$1,382,304.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
560	12	V2	18
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Breakwater

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

The breakwater is located at the mouth of Rockport Harbor. The stones are approximately 5 feet by 5 feet by 3 feet on average. Some movement has occurred among the stones, along with some section loss.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

V

Rating

Immediate / Highest Priority

Action

Consider For Immediate Action Due to Public Safety and Welfare Issues

Description

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-036-000-077-100-PHO1A.jpg

Structure Documents:

Structure Assessment Form

Structure ID: 062-036-000-078-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Bearskin Neck

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Rockport

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$134,640.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
340	20	V2	18
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone bulkhead with stones that are approximately 5 feet by 2 feet by 2 feet. No sign of movement or settling. Above is a parking lot and small park. The bulkhead is attached to a breakwater. There is no visible scour. The bulkhead is built on a ledge.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

IV

Rating

High Priority

Action

Consider for Next Project Construction Listing

Description

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

062-036-000-078-100-PHO1A.jpg

062-036-000-078-100-PHO1B.jpg

062-036-000-078-100-PHO1C.jpg

062-036-000-078-100-PHO1D.jpg

Structure Documents:

Section III - Rockport

Part C

Structure Photographs

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
062-016-000-026-100	062-016-000-026-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-016-000-026-100	062-016-000-026-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-016-000-026-200	062-016-000-026-200-PHO2A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-016-000-026-200	062-016-000-026-200-PHO2B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-016-000-026-300	062-016-000-026-300-PHO3A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-016-000-026-300	062-016-000-026-300-PHO3B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-016-000-026-400	062-016-000-026-400-PHO4A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-016-000-026-400	062-016-000-026-400-PHO4B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-017-000-017-100	062-017-000-017-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-017-000-017-100	062-017-000-017-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-017-000-017-100	062-017-000-017-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-017-000-019-100	062-017-000-019-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-017-000-019-100	062-017-000-019-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-017-000-019-100	062-017-000-019-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-017-000-054-100	062-017-000-054-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-017-000-054-100	062-017-000-054-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-021-000-017-100	062-021-000-017-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-021-000-017-100	062-021-000-017-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-022-000-309-100	062-022-000-309-100-PHO1A.jpg		Bourne Consulting Engineering		May-09	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-022-000-309-200	062-022-000-309-200-PHO2A.jpg		Bourne Consulting Engineering		May-09	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-026-000-026A-100	062-026-000-026A-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-026-000-026A-100	062-026-000-026A-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
062-035-000-001A-100	062-035-000-001A-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-035-000-001A-100	062-035-000-001A-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-035-000-001A-100	062-035-000-001A-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-035-000-018C-100	062-035-000-018C-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-035-000-018C-100	062-035-000-018C-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-035-000-021E-100	062-035-000-021E-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-035-000-021E-100	062-035-000-021E-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-035-000-053-100	062-035-000-053-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-035-000-054-100	062-035-000-054-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-002-100	062-036-000-002-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-033-100	062-036-000-033-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-033-100	062-036-000-033-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-033-100	062-036-000-033-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-054-100	062-036-000-054-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-067-100	062-036-000-067-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-067-100	062-036-000-067-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-077-100	062-036-000-077-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-078-100	062-036-000-078-100-PHO1A.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-078-100	062-036-000-078-100-PHO1B.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-078-100	062-036-000-078-100-PHO1C.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
062-036-000-078-100	062-036-000-078-100-PHO1D.jpg		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

Massachusetts Coastal Infrastructure and Assessment



062-016-000-026-100-PHO1A



062-016-000-026-100-PHO1B



062-016-000-026-200-PHO2A



062-016-000-026-200-PHO2B



062-016-000-026-300-PHO3A



062-016-000-026-300-PHO3B



062-016-000-026-400-PHO4A



062-016-000-026-400-PHO4B



062-017-000-017-100-PHO1A

Massachusetts Coastal Infrastructure and Assessment



062-017-000-017-100-PHO1B



062-017-000-017-100-PHO1C




062-017-000-019-100-PHO1A



062-017-000-019-100-PHO1B



062-017-000-019-100-PHO1C




062-017-000-054-100-PHO1A



062-017-000-054-100-PHO1B



062-021-000-017-100-PHO1A



062-021-000-017-100-PHO1B


Massachusetts Coastal Infrastructure and Assessment



062-022-000-309-100-PHO1A



062-022-000-309-200-PHO2A




062-026-000-026A-100-PHO1A



062-026-000-026A-100-PHO1B



062-035-000-001A-100-PHO1A




062-035-000-001A-100-PHO1B



062-035-000-001A-100-PHO1C



062-035-000-018C-100-PHO1A



062-035-000-018C-100-PHO1B

Massachusetts Coastal Infrastructure and Assessment



062-035-000-021E-100-PHO1A



062-035-000-021E-100-PHO1B




062-035-000-053-100-PHO1A



062-035-000-054-100-PHO1A




062-036-000-002-100-PHO1A




062-036-000-033-100-PHO1A



062-036-000-033-100-PHO1B



062-036-000-033-100-PHO1C




062-036-000-054-100-PHO1A


Massachusetts Coastal Infrastructure and Assessment



062-036-000-067-100-PHO1A



062-036-000-067-100-PHO1B




062-036-000-077-100-PHO1A



062-036-000-078-100-PHO1A



062-036-000-078-100-PHO1B



062-036-000-078-100-PHO1C



062-036-000-078-100-PHO1D

Section III - Rockport

Part D

Structure Documents

TOWN DOCUMENT LIST

MA DCR - DOCUMENT LIST

MA DEP – Ch 91 DOCUMENT LIST

- Copies of License Documents

USACE – PERMIT DOCUMENT LIST

- Copies of Permit Documents

TOWN: ROCKPORT
SOURCE: Town of Rockport
LOCATION: TOWN
DATE OF RESEARCH: JULY 2007

No Town Documents for the Town of Rockport

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
------------------	-------------	--------------------------------	--------	--------------	------	-------	--------	----------	-------------

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
062-021-000-017-100	062-021-000-017-100-DCR1A	1959	MA-DCR	Rockport	September 1958	Proposed Seawall and Revetment - Long Beach - Rockport, Massachusetts - Prepared for the DPW of Massachusetts - Division of Waterways	5	Long Beach	Seawall and Revetment



TOWN: ROCKPORT
 SOURCE: DEP
 LOCATION: BOSTON, MA
 DATE OF RESEARCH: JULY 2007

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
062-036-000-033-100	062-036-000-033-100-LIC1A	7918	DEP	Rockport	July 26, 1999	Town of Rockport D.P.W. To License and Maintain Improvements to Bradley Wharf and T-Wharf in Rockport Harbor	5	Bradley T-Wharf	Bulkhead
062-036-000-067-100	062-036-000-067-100-LIC1A	7918	DEP	Rockport	July 26, 1999	Town of Rockport D.P.W. to License and Maintain Improvements to Bradley Wharf and T-Wharf in Rockport Harbor	5	Bradley T-Wharf	Bulkhead

- CHANNEL/BASIN LINE
- TOP OF WHARF
- BOTTOM OF WHARF
- WHARF BOLLARD
- EXIST. MOORING LOCATION
- NEW MOORING PILES
- EXISTING MOORING PILE
- PROPERTY LINE
- SECT. FENDER PILE



Richard L. Silveira
12/4/98



062-036-000-067-100
062-036-000-033-100

1098-9134

ACCOMPANYING PETITION OF
OWN OF ROCKPORT D.P.W.
LICENSE AND MAINTAIN IMPROVEMENTS TO
RADLEY WHARF AND T-WHARF
ROCKPORT HARBOR
OCKPORT, MA.
DATE NOV 10 1998


TIBBETTS ENGINEERING CORP. NEW BEDFORD, MA.

LICENSE PLAN NO. 7918
Approved by Department of Environmental Protection
JUL 26 1999



CIVIL ENGR
Richard L. Silveira
12/4/98

062-036-000-067-100
062-036-000-033-100



TIBBETTS ENGINEERING CORP. NEW BEDFORD, MA.


PLAN ACCOMPANYING PETITION OF
TOWN OF ROCKPORT D.P.W.
TO LICENSE AND MAINTAIN IMPROVEMENTS TO
BRADLEY WHARF AND T-WHARF
IN ROCKPORT HARBOR

LICENSE PLAN NO. 7918

Approved by Department of Environmental Protection


Date: **MAY 26 1999**

1098-9134




SECTION A-A

SCALE: 1"=20'



SECTION B-B

SCALE: 1"=20'



SECTION D-D

SCALE: 1"=20'



CIVIL ENGR
Richard L. Silveira
12/4/98

062-036-000-067-100
062-036-000-033-100

1298-9661


TIBBETTS ENGINEERING CORP. NEW BEDFORD, MA.

PLAN ACCOMPANYING PETITION OF
TOWN OF ROCKPORT D.P.W.
TO LICENSE AND MAINTAIN IMPROVEMENTS TO
BRADLEY WHARF AND T-WHARF
IN ROCKPORT HARBOR
ROCKPORT MA

LICENSE PLAN NO. 7918

Approved by Department of Environmental Protection

Date JUL 26 1999




SECTION C-C
GEOTECHNICAL PROFILE
SCALE: 1"=20'




CIVIL ENGR
Richard L. Silveira
12/4/98

062-036-000-067-100
062-036-000-033-100



TOP PILE ATTACHMENT DETAIL
DETAIL #2
N.T.S.



DETAIL #1
N.T.S.

TIBBETTS ENGINEERING CORP. NEW BEDFORD, MA.

ACCOMPANYING PETITION OF
OWN OF ROCKPORT D.P.W.
O' LICENSE AND MAINTAIN IMPROVEMENTS TO
RADLEY WHARF AND T-WHARF
ROCKPORT HARBOR
OCKPORT, MA.

LICENSE PLAN NO. 7918

Approved by Department of Environmental Protection

JUL 26 1999


1098-9134

LOCUS

7715



Civil Engineer
Richard L. Silveira
12/4/98





062-036-000-067-100
 062-036-000-033-100

098-9134

ACCOMPANYING PETITION OF
 OWN OF ROCKPORT D.P.W.
 TO LICENSE AND MAINTAIN IMPROVEMENTS TO
 BRADLEY WHARF AND T-WHARF
 IN ROCKPORT HARBOR
 ROCKPORT, MA.
 DATE NOV 10 1998


TIBBETTS ENGINEERING CORP. NEW BEDFORD, MA.

LICENSE PLAN NO. 7918
 Approved by Department of Environmental Protection
 JUL 26 1999




Date: **APR 2 1962**

1098-9134




SECTION A-A

SCALE 1"=20'



SECTION B-B

SCALE 1"=20'



SECTION D-D

SCALE 1"=20'



CIVIL ENGR
Richard L. Silveira
12/4/98


062-036-000-067-100
062-036-000-033-100

TIBBETTS ENGINEERING CORP. NEW BEDFORD, MA.



PLAN ACCOMPANYING PETITION OF
TOWN OF ROCKPORT D.P.W.
TO LICENSE AND MAINTAIN IMPROVEMENTS TO
RADLEY WHARF AND T-WHARF
ROCKPORT HARBOR
ROCKPORT MA

LICENSE PLAN NO. 7918
Approved by Department of Environmental Protection
Date JUL 26 1999

1296-9661



CIVIL ENGR
Richard L. Silveira
12/4/98



TIBBETTS ENGINEERING CORP. NEW BEDFORD, MA.

ACCOMPANYING PETITION OF
OWN OF ROCKPORT D.P.W.
O LICENSE AND MAINTAIN IMPROVEMENTS TO
RADLEY WHARF AND T-WHARF
ROCKPORT HARBOR
ROCKPORT, MA.


LICENSE PLAN NO. 7918
Approved by Department of Environmental Protection
JUL 26 1999

062-036-000-067-100
062-036-000-033-100


1098-9134

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
062-036-000-033-100	062-036-000-033-100-COE1A	198803348	USACE	Rockport	November 10, 1988	Bradley Wharf and T-Wharf Repairs	6	Bradley Wharf	Sheet Pile and Riprap Repairs
062-036-000-067-100	062-036-000-067-100-COE1A	198803348	USACE	Rockport	November 10, 1988	Bradley Wharf and T-Wharf Repairs	6	Bradley Wharf	Sheet Pile and Riprap Repairs


062-036-000-033-100



(10117PER.DWG) 10117.080 J.D.




062-036-000-067-100
062-036-000-033-100



(10117PER.DWG) 10117.080 J.D.


062-036-000-0107-100

062-036-000-033-100




(10117PER.DWG) 10117.080 J.D.

0602-036-000-033-100



(10117PER.DWG) 10117.080 J.D.


062-036-000-067-100
062-036-000-033-100




<p>tibbetta engineering corp. 716 COUNTY STREET TAUNTON, MA 02780 (508) 822-6934</p>	<p>BRADLEY WHARF AND T-WHARF REPAIRS SECTIONS AND DETAILS</p>	<p>DATE: NOV. 10, 1998</p> <p>APPLICATION BY: TOWN OF ROCKPORT D.P.W.</p>
<p>SHEET 6 OF 6</p>	<p>SECTION 6 OF 6</p>	<p>SHEET 6 OF 6</p>

062-036-000-067-100


062-036-000-033-100





DATE: NOV. 10, 1998	BRADLEY WHARF AND T-WHARF REPAIRS	tibbette engineering corp. 716 COUNTY STREET TAUNTON, MA. 02780 (508) 822-6934
SHEET OF 2 6	APPLICATION BY: TOWN OF ROCKPORT D.P.W.	AT: ROCKPORT IN: ROCKPORT HARBOR ESSEX COUNTY STATE OF MASSACHUSETTS


062-036-000-067-100
062-036-000-033-100



(10117PER.DWG) 10117.080 J.D.

062-036-000-0107-100


062-036-000-033-100



DATE: NOV. 10, 1998	BRADLEY WHARF AND T-WHARF REPAIRS SHEET PILE CELL PLAN	tbetta engineering corp. 716 COUNTY STREET TAUNTON, MA. 02780 (508) 822-6934
SHEET OF 4 6	APPLICATION BY: TOWN OF ROCKPORT D.P.W.	AT: ROCKPORT HARBOR IN: ESSEX COUNTY STATE OF MASSACHUSETTS

(10117PER.DWG) 10117.080 J.D.

062-036-000-067-100
062-036-000-033-100



(10117PER.DWG) 10117.080 J.D.

062-036-000-067-100
062-036-000-033-100

