

***South Shore Coastal Infrastructure Inventory  
and Assessment Demonstration Project  
Coastal Hazards Commission***

**Town of Hingham**



**Prepared for:  
Office of Coastal Zone Management  
Boston, MA**

**February 28, 2007**

**Presented by:  
Bourne Consulting Engineering  
Franklin, Massachusetts**

**In Association With:  
Applied Coastal Research & Engineering, Inc.  
Alpha Land Surveying & Engineering Associates**

## **TABLE OF CONTENTS**

### **TABLE OF CONTENTS**

#### **Section I – Coastal Hazards Infrastructure and Assessment Program**

##### **INTRODUCTION**

##### **PURPOSE**

##### **DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES**

##### **DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS**

#### **Section II – Community Findings**

##### **COMMUNITY DESCRIPTION**

##### **STRUCTURE INVENTORY**

##### **SUMMARY OF FINDINGS**

#### **Section III – Structure Assessment Reports**

#### **Section IV – Structure Photographs**

#### **Section V – Structure Documents**

##### **TOWN DOCUMENT LIST**

- Document Table

##### **MA DCR – DOCUMENT LIST**

- Document Table

##### **MA DEP – Chp. 91 DOCUMENT LIST**

- Document Table
- Copies of License Documents

##### **USACE – PERMIT DOCUMENT LIST**

- Document Table
- Copies of Permit Documents

## **Section I**

### **Town of Hingham**

### **Coastal Hazards Infrastructure and Assessment Program**

***South Shore Coastal Infrastructure  
Inventory and Assessment Demonstration Project  
Coastal Hazards Commission***

**Section I – Coastal Hazards Infrastructure and Assessment Program**

**INTRODUCTION**

**The Project and Client**

The Commonwealth of Massachusetts has initiated a Coastal Hazards Commission (CHC) to identify the vulnerability of the state to coastal hazards. As one of five working groups working under the CHC, the 20-Yr Infrastructure Plan was to establish a prioritization for the repair of coastal structures. The focus areas of the Working Group include:

- Publicly owned infrastructure
- Infrastructure for which State is responsible
- Inventory of public hazards infrastructure
- Evaluation on conditions
- Development for a prioritization of work
- Estimation of capital and maintenance costs

The 20-Yr Infrastructure Working Group is led by Representative Frank Hynes with CZM as the lead State Agency overseeing the management of the project. The region included in the demonstration project was identified as the South Shore and included the eight communities of Hingham, Hull, Cohasset, Scituate, Marshfield, Duxbury, Kingston and Plymouth.

**Consultant Team**

The consultant team that performed the demonstration project was led by Bourne Consulting Engineering (*BCE*) of Franklin, MA who was responsible for overall project management, research and field assessments. Assisting *BCE* was Applied Coastal Research and Engineering, Inc. of Mashpee, MA who was responsible for field assessments and GIS data conversion. Alpha Land Surveying and Engineering of Middleboro, MA also supported the Team with field GPS survey.

**PURPOSE**

**Study Purpose**

CZM seeks to identify the capacity of Massachusetts coastal structures to resist major coastal storms and prevent storm damage. In working toward this goal, CZM has initiated a program to perform an assessment of Commonwealth owned and/or maintained coastal structures. The first phase of this program is the performance of a demonstration project for coastal structures located on the South Shore. The demonstration project will identify existing structures, their general conditions, ability to provide coastal protection and the probable cost for repairs. The information collected and developed will be incorporated into the MassGIS system to allow use for developing a 20 Year Coastal Infrastructure Plan.

As this is a demonstration project, it will serve as the basis for development of a statewide inventory and assessment of all Commonwealth coastal structures and the needs for their maintenance and/or repair. Incorporated into this project will be the identification of issues and limitations of the investigation and



assessment to achieve the overall goals and what should be included in future investigations/assessments of coastal structures for the other regions.

#### Goals of Study

The goals of the South Shore Coastal Infrastructure Inventory and Assessment Project include:

- To be used as the model to go forward for assessment of coastal structures for the remainder of the coastal regions
- To identify areas of research and/or assessment that need to be modified for future phases that were not included within the demonstration project
- Complete the study with the final report by November 15, 2006 for submission to the Coastal Hazards Commission
- To identify all the coastal structures the state either owns or has responsibility to maintain for the eight communities included within the study
- Of the structures identified, determine the structure location and characteristics, the structure condition relative to providing coastal protection and the structure importance in relation to what it is protecting.
- To the degree possible, identify the structure elevation and the FIRM mapping flood elevation and category.
- To the degree possible, identify structure owner and available documents from local, state and federal agencies.
- To establish an estimated cost to rehabilitate the coastal structures to provide the level of project established in the structure's original design.
- Provide the information in a format compatible for incorporation into the MassGIS system

#### Limit of Study

Due to the time constraints and the amount of effort necessary to collect, process and compile the information, the following are identified as limitations of the information presented:

- All property ownership was taken as presumed. No legal investigation of ownership was performed during the project. Property ownership is based on town assessor maps. Where structures were located outshore of assessor map defined property lines, it was assumed to be Town land unless other information indicated otherwise. Where structures were located outshore of Mean Low Water, property is assumed to be State owned.
- The structure ownership was based on assessor maps and research at the local, state and federal levels. Where there was indication of public work on a structure on Town land or on private property, the structure was presumed to be Town owned. Where the structure was on state property, the structure was presumed to be state owned. Where ownership of the structure was not clear but was located on private property, the structure ownership was defined as unknown.
- The study included town and state owned structures as it was assumed that most town owned structures received state funding at some level for construction and/or maintenance.
  - Federal structures were identified but no assessment of conditions or priority was performed.
  - Structures that were determined to be private were not included.
  - Undocumented structures considered to be on private land, but having the potential to have been publicly built and/or maintained, were identified as having an "unknown ownership".

***SOUTH SHORE COASTAL INFRASTRUCTURE  
INVENTORY AND ASSESSMENT DEMONSTRATION PROJECT***

- The prioritizing of structures was based primarily on risk to general infrastructure and density of housing. Infrastructure included was buildings. The study did not consider all infrastructure issues including:
  - No consideration on utility impacts – water, electrical, sewer, gas
  - No consideration of roadway and bridge protection
  - Evacuation routes were not considered within the investigation
  - Location of Emergency Shelters were not included in priority assessments
- Research was performed at the local, state and federal levels. The local research was limited to location and documenting available coastal structure contract drawings. Research at DCR was restricted to available historic construction plans for coastal structures at the MA-DCR Waterways office in Hingham, MA. No investigation of state archives was performed. Research at MA DEP Chp 91 and USACE was limited to recorded permits and licenses found in their files. No investigation was performed at the Registry of Deeds.

## **DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES**

The specific attributes that would be incorporated into the MassGIS system were developed based on the scope of work and the goals to be achieved. The following was established to standardize the data collection and presentation and to allow total flexibility for sorting by attributes in the final GIS database. The attributes identified below were input into a MS Access database which was used to manage the data from all eight communities within a single file.

### **Database Attributes**

- Attribute Descriptions/Definitions

**Structure Number:** A unique structure number was given to each coastal structure. The number was based on existing numbering systems that include the State Department of Environmental Protection community number followed by the local community assessor's parcel numbering system. The last three digits of the number represent the structure within the parcel. Where structures extend over several parcels, the structure is referenced to a parcel that is approximately in the center of the structure. Where Town assessor's references include letters, those are also included within the structure number. Some communities have block numbering within their numbering system and these are included. Communities without block numbering still have the block numbering included but these are illustrated as all zeros for that specific segment.

Structures that are on Town property, which would otherwise not have a parcel number, are referenced to a parcel that is in the immediate vicinity of the coastal structure.

On this basis, the following is the general numbering convention:

### **CCC-MMM-PPP-BBB-SSS**

Where:	CCC	DEP Community Number
	MMM	Community Map Number
	BBB	Block Number (000 if no block numbering system)
	PPP	Community Parcel Number
	SSS	Structure Number

Property Ownership: All property ownership was on a “presumed” basis as no legal verification of ownership was performed. The ownership of the property was classified under four basic areas which were private ownership (Private), Town ownership (Local), Commonwealth of Massachusetts ownership (State), federal government ownership (Federal) or unknown. Property ownership was based on Town assessor’s maps. Where the location was located above Mean Low Water, and not within a defined parcel, the property ownership was presumed to be the Town unless documentation was found to indicate otherwise. Where a structure was located offshore of Mean Low Water, the property ownership was presumed to be the state.

Structure Ownership: The ownership of all structures is presumed as no verification of ownership was performed. Ownership of the structure was determined by research into historic state and federal permits and the entity indicated on the permits as the applicant. Where no other information was found, the following was utilized:

- Structures located on private land but appearing to be significant structures were identified as owned by the Town or as “Unknown”. Unknown was used where there was a question of local or private ownership.
- Structures on Town property were assumed to be owned by the Town
- Structures that were located off-shore were presumed to be federally owned
- Structures that were identified as being privately owned were eliminated from the database

Basis of Ownership: The basis of structure ownership was provided to give rationale to the structure ownership and identified the research resource that identified the ownership or the methodology otherwise used. The responses utilized were limited to the following:

- DPW – DPW Employee Interview
- DCR - Contract Drawings
- DEP – Ch 91 License
- USACE – Permits
- Property Ownership
- Offshore Structure

Structure Owner's Name: Ownerships names reflect the presumed owner of publicly owned structures. As this was for public structures only, the ownership was restricted to the community name, the state agency or the federal agency.

Earliest Structure Record: The year of the oldest document located for the structure. The information is determined from the document research performed on the structure from local, state and federal agencies. If no documents could be found than this entry is denoted as ‘Unknown’. Where documentation of the structure could be found, the date from the oldest document was utilized.

Primary Structure / Secondary Structure: Many of the coastal structures consisted of combined structures which were rated separately. It was typically found that one structure was significantly more predominant (Ex. Bulkhead/Seawall) and was therefore identified as the Primary Structure while a smaller structure might exist in front (ex. Revetment) of it. The type, height and material of each structure are identified separately. The condition of each structure was based on the Primary Structure. Where there was no secondary structure, the fields were left blank.

Structure Type: The structure type was categorized into five basic coastal structure categories which were Bulkhead/Seawall, Revetment, Coastal Beach, Coastal Dune, and Jetty/Groin.

**Structure Material:** The identification of the coastal structure's material of construction was performed and represents the primary material. Stone structures consisted of both mortared and non-mortared conditions.

**Structure Height:** Each type of structure was categorized by its visible height in feet which was broken into four specific ranges which are:

< 5 feet              5 to 10 feet              10 to 15 feet              >15 feet

**Structure Condition:** A preliminary assessment of the condition for each structure was performed by the field teams. This was by visual observation only and no detailed investigation was performed. The condition assessments were based on a predefined five level rating system that ranged from Rating A for Excellent Condition to Rating F for Critical Condition. A detailed listing of the conditions and their definitions can be seen in Exhibit A.

**Priority Rating:** In order to account for the need for protection at any one site, a five level priority rating system was established. This allowed for consideration of public infrastructure protection, density of residential housing for development of structure overall importance for coastal protection. The ratings range from Level 1 for no infrastructure or residence protection to Level 5 for critical inshore infrastructure protection and/or high density residential. The detailed listing and definitions for the priority categories can be seen in Exhibit B.

**Structure Repair / Reconstruction Cost:** A preliminary estimation of construction costs to maintain or repair structures was made based on the preliminary field assessment of the structures. A Repair Cost Matrix was developed based on structure type, condition, height and material and can be seen in Exhibit C. Once each structure's type, height, and material classifications were determined, the cost per foot for the structure was determine from the Repair Cost Matrix and multiplied by the length of the structure to obtain the estimated repair/restoration cost. The cost matrix repair costs include a 20 percent construction cost contingency as well as 10 percent costs for engineering and permitting.

**Structure Length:** The length of each structure is provided and utilized in the development of the repair/reconstruction costs. The lengths are given to the nearest foot and taken as the linear distance along the structure, as determined by the GPS location, which takes into account structure angles and curvature.

**Structure Elevation:** The elevation of structures was determined in feet from existing information where available. The datum used is NAVD 88 and elevations are to the nearest foot. From a previous study much of the south shore coastal structures had elevations defined based on LIDAR mapping data. Where available structure documentation with elevations was found, in areas with no LIDAR data, the information was included within the structure information. Where there was no LIDAR information or existing documentation, the item has been left blank.

LIDAR (Light Detection and Ranging) is technology that is currently being used for high-resolution topographic mapping by mounting a LIDAR sensor, integrated with Global Positioning System (GPS) and inertial measurement unit (IMU) technology, to the bottom of aircraft and measuring the pulse return rate to determine surface elevations.

**FEMA Zone and Elevation:** For each structure the FEMA Flood Insurance Rate Maps (FIRM) were researched for their Flood Zone designation and their Base Flood Elevation from the most recent FIRM maps for the specific Town. The elevations are provided in feet on the same datum as the FIRM maps (NGVD) with no adjustments or conversions.



Structure Comments: The engineering team provided a brief description and comment on the structure at the time of the field assessments which is provided in support of the condition rating that was given for the structure.

Pictures: At the time of the field assessments, digital photographs were taken to provide a general overview of the structure. The number of pictures were limited to a maximum of six. The first photograph for each structure is shown on the Structure Assessment Form. The list of all photographs is provided on the form.

Town Documents: Town documents represent the structure information that could be found in the Town's DPW/Engineering Department records. Where particular records could be found, a table of document information was developed and included within the database with limited descriptions.

MA - DCR Documents: MA-DCR documents represent the structure information that could be found within DCR – Waterways office in Hingham. Where particular records could be found, a table of document information was developed and included within the database with limited descriptions.

MA - DEP Chp. 91 Licenses: MA-DEP Chapter 91 license documents represent the structure information that could be found within MA-DEP Chp 91 records in Boston. Where particular records could be found, they were scanned as pdf files and attached to the structure through the GIS database information. In addition, a table of license document information was developed and included within the database with limited descriptions.

USACE Permits: USACE Permits represent the structure information that could be found within the Army Corp of Engineers regulatory office in Concord, MA. Where particular records could be found, they were scanned as pdf files and attached to the structure through the GIS database information. In addition, a table of license document information was developed and included within the database with limited descriptions.

## **DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS**

A matrix to be used within the database has been developed to assess likely rehabilitation/repair costs to restore the coastal structures to their original design condition. No attempt was made to assess the level of exposure and associated level of protection that might be required to meet current design standards for these structures. These costs are only an estimation to bring these structures back to their original design intent based on 2006 construction costs.

The development of the cost matrix is based on the following:

Structure Condition Ratings – The condition of the coastal structures was determined in the field by the survey crew which was led by an engineer with waterfront structure assessment and design experience. The definitions of the rating criteria utilized for the assessments is presented elsewhere.

The cost implications for each rating condition are as follows:

- **A Rating** Structures not requiring any maintenance, repair or rehabilitation cost and would not be expected to experience damage if subject to a major coastal storm event
- **B Rating** Structures requiring limited or no repair and would be expected to experience only minor damage if subject to a major coastal storm event. The

value of these maintenance costs is assumed to be 10 percent of the construction cost.

- **C Rating** Structures requiring moderate to significant level of repair or reconstruction and would be expected to experience significant damage if subject to a major coastal storm event. The structure is presumed to be effective under a major storm event. The value of the repair costs is assumed to be 50 percent of the construction cost.
- **D Rating** Structures requiring significant level of rehabilitation or total reconstruction and would be expected to experience significant damage or possibly fail if subject to a major coastal storm event. The value of the repair costs is assumed to be 100 percent of the construction cost.
- **F Rating** Structures requiring complete reconstruction and would expect to provide little or no protection from a major coastal storm event. The value of the repair costs is assumed to be 100 percent of the construction cost plus a cost for removal/disposal of the original structure.

**Height of Structure** – Height of a structure is a major factor in the structure cost and therefore was identified as a significant factor in assessing rehabilitation/repair construction costs. The structures were broken down into four major categories which were:

< 5'	Structures that were less than five feet in height
5'-10'	Structures five to 10 feet in height
10'-15'	Structures over 10 feet to 15 feet in height
> 15'	Structures greater than 15 feet in height – assumed 20 feet typical

**Length of Structure** – Length is based on field GPS location with measurements rounded to the nearest foot.

**Bulkhead / Seawall Structures** – These structures are assumed to be constructed out of concrete, steel, stone or wood with each having its own criteria for establishing costs. For each structure type the following was assumed:

- **Concrete Seawalls** – These walls were assumed to be gravity structures with the volume of concrete used based on the bottom width being one-half of the structure height. Costs of construction were based on a per cubic yard estimate that varied from \$350 to \$630 per cubic yard depending on the structure height. Values for excavation and demolition of existing structure were also included.
- **Stone Seawalls** - These walls were treated the same as concrete seawalls and assumed to be gravity structures with the volume of the structure based on the bottom width being one-half of the structure height. Costs of construction were based on a per cubic yard estimate that varied from \$350 to \$630 per cubic yard depending on the structure height. Values for excavation and demolition of existing structure were also included.
- **Steel Bulkheads** – Steel bulkheads were presumed to be constructed with steel sheet piling. Tie back systems were presumed for structures 10 feet or greater in height. Shorter walls were assumed to have a cantilever design. The total depth of sheeting was presumed to be two times the exposed height. The cost for construction varied from \$40 per square foot to \$60 per square foot plus the cost of excavation and demolition.

***SOUTH SHORE COASTAL INFRASTRUCTURE  
INVENTORY AND ASSESSMENT DEMONSTRATION PROJECT***

- **Timber Bulkheads** – Timber bulkheads were presumed to be constructed with timber piles at eight foot on center, horizontal wales and vertical four inch sheathing. The unit costs for installed materials used were \$1,500 per pile and \$7.50 per bfm.

**Revetment Structures** – Revetment structures were presumed to be constructed of dry placed (no concrete) stone with a two on one slope and a horizontal toe and crown equal to the thickness layer established for each height condition. The total thickness of the revetment layers varied from six to ten feet with the cost of armor and under-layer stone assumed to be \$50 per ton and the crushed stone base to be \$15 per ton.

**Groins and Jetties** – Groins and jetties were assumed to be the same materials and construction as the revetment structures but would have two sides and therefore double the quantities.

**Coastal Beaches** – Costs for restoration of Coastal beaches presumed the placement of beach renourishment sands at a 1-on-20 slope over the existing beach conditions. The cost for deposition of sand assumed relatively close source of material and utilized \$20 per cubic yard for the material installed.

**Coastal Dunes** – Restoration of coastal dunes assumed a cross section of renourished sand with a one-on-four slope on one side of a 25 foot width at the defined dune height. The cost for deposition of sand assumed relatively close source of material and utilized \$20 per cubic yard for the material installed.

**Contingency** – A contingency of 20 percent was added to all costs to reflect the unknowns associated with this level of rehabilitation/repair estimating.

**Engineering and Regulatory Approvals** – A ten percent increase to the cost matrix prices was assessed to represent the engineering design and regulatory approval requirements for the restoration of these structures.

## **EXHIBIT A**

**Structure Condition Table – 5 Level Rating System**

<b>Preliminary Condition Assessment</b>		<b>Definition Based Upon Perceived Immediacy of Action and Potential to Cause Damage if Not Corrected</b>	<b>Level of Action Required</b>
<b>A</b>	<b>Excellent</b>	<p>Like new condition. Structure expected to withstand major coastal storm without damage.</p> <p>Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm</p>	<b>None</b>
<b>B</b>	<b>Good</b>	<p>Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present.</p> <p>Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure</p>	<b>Minor</b>
<b>C</b>	<b>Fair</b>	<p>Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure.</p> <p>Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide additional material for full protection and extended life</p>	<b>Moderate</b>
<b>D</b>	<b>Poor</b>	<p>Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm.</p> <p>Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.</p>	<b>Major</b>
<b>F</b>	<b>Critical</b>	<p>Conditions of structure/landform may warrant emergency stabilization as failure may result in potential loss of property and/or life. Landform eroded, loss of integrity</p> <p>Structure exhibits critical levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure provides little or no protection from a major coastal storm. Actions taken to totally reconstruct structure to regain full capacity.</p> <p>Landform stability is severely compromised, rate of erosion/material loss may be increasing, and landform does not provide adequate protection from a major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.</p>	<b>Immediate</b>



**EXHIBIT B**

**Priority Rating System - 5 Level Rating System**

<b>Preliminary Priority Level Assessment</b>		<b>Level Based Upon Perceived Immediacy of Action and Presence of Potential Risk to Inshore Structures if Not Corrected</b>	<b>Level of Action Required</b>
<b>I</b>	None	No Inshore Structures or Residential Dwelling Units Present	Long Term Planning Considerations
<b>II</b>	Low Priority	Inshore Structures Present with Limited potential for Significant Infrastructure Damage	Future Project Consideration
<b>III</b>	Moderate Priority	Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)	Consider for Active Project Improvement Listing
<b>IV</b>	High Priority	High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)	Consider for Next Project Construction Listing
<b>V</b>	Immediate / Highest Priority	Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Conditions of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. ( >10 dwellings impacted / 100 feet of shoreline )	Consider For Immediate Action Due to Public Safety and Welfare Issues

**SOUTH SHORE COASTAL INFRASTRUCTURE  
INVENTORY AND ASSESSMENT DEMONSTRATION PROJECT**

**CZM SOUTH SHORE COASTAL INFRASTRUCTURE INVENTORY AND ASSESMENT PROJECT**

**EXHIBIT C**

September 14, 2006

**REPAIR / REHABILITATION COSTING DATA**

Cost per linear foot of structure

STRUCTURE TYPE	STRUCTURE MATERIALS	STRUCTURE HEIGHT	STRUCTURE CONDITION RATING				
			A	B	C	D	E
BULKHEAD/ SEAWALL	CONCRETE	Under 5 Feet	\$0	\$84	\$425	\$850	\$983
		5 To 10 Feet	\$0	\$152	\$759	\$1,518	\$1,782
		10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,970
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$4,752
	STEEL	Under 5 Feet	\$0	\$54	\$273	\$546	\$680
		5 To 10 Feet	\$0	\$165	\$825	\$1,650	\$1,848
		10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,772
		Over 15 Feet	\$0	\$343	\$1,716	\$3,432	\$3,795
	STONE	Under 5 Feet	\$0	\$84	\$425	\$850	\$983
		5 To 10 Feet	\$0	\$152	\$759	\$1,518	\$1,782
		10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,970
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$4,752
	WOOD	Under 5 Feet	\$0	\$86	\$431	\$862	\$994
		5 To 10 Feet	\$0	\$127	\$632	\$1,265	\$1,463
		10 To 15 Feet	\$0	\$161	\$804	\$1,608	\$1,872
		Over 15 Feet	\$0	\$202	\$1,008	\$2,017	\$2,380
COASTAL BEACH	SAND	Under 5 Feet	\$0	\$26	\$132	\$264	\$264
		5 To 10 Feet	\$0	\$127	\$634	\$1,267	\$1,267
		10 To 15 Feet	\$0	\$224	\$1,122	\$2,244	\$2,244
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$3,960
COASTAL DUNE	SAND	Under 5 Feet	\$0	\$18	\$93	\$186	\$186
		5 To 10 Feet	\$0	\$48	\$238	\$476	\$476
		10 To 15 Feet	\$0	\$78	\$395	\$790	\$790
		Over 15 Feet	\$0	\$132	\$660	\$1,320	\$1,320
REVTMENT	STONE	Under 5 Feet	\$0	\$66	\$333	\$664	\$730
		5 To 10 Feet	\$0	\$120	\$601	\$1,201	\$1,300
		10 To 15 Feet	\$0	\$157	\$781	\$1,564	\$1,696
		Over 15 Feet	\$0	\$247	\$1,234	\$2,468	\$2,666
GROIN	STONE	Under 5 Feet	\$0	\$157	\$664	\$1,328	\$1,460
		5 To 10 Feet	\$0	\$157	\$1,201	\$2,402	\$2,600
		10 To 15 Feet	\$0	\$157	\$1,564	\$3,128	\$3,392
		Over 15 Feet	\$0	\$157	\$2,468	\$4,937	\$5,333

NOTE: Repair / Rehabilitation Costs include 10% for engineering and regulatory approvals and 20 % construction contingency.

## **Section II**

### **Town of Hingham**

### **Community Findings**

## **Section II – Community Findings – Town of Hingham**

### **COMMUNITY DESCRIPTION**

The Town of Hingham consists of a land area of 22.5 square miles out of a total area of 25.0 square miles and had a population of 19,882 in the 2000 census. The Town is located on the South Shore of Massachusetts and its location can be seen on this report's cover. The estimated length of shoreline is 10 miles that are protected by the Hull peninsula from open ocean waves. The Town is protected from major coastal storms by both natural and man-made shoreline structures that require maintenance to insure the long term protection of its coastline. The man-made and publicly owned structures that protect the Town were investigated for their ability to provide adequate protection from major coastal storms. Structures have been identified as publicly owned, including coastal dunes and beaches, based on evidence of investment of public funds made to create/enhance/maintain these structures. The assessment did not include floating or pile supported structures as they are assumed not to provide any significant coastal protection from major storm events.

### **STRUCTURE INVENTORY**

Within the Town of Hingham, there were 34 structures which had public, state or unknown ownership which provide significant coastal protection. The location of the structures can be seen in Sheets 1 through Sheet 4 in Section III of this report. The structures were categorized by their type and by their structural condition based on a preliminary field assessment. The distribution of structures by type and condition can be seen in the following table:

**STRUCTURE TYPE AND QUANTITY - Town of Hingham**

Primary Structure (1)	Total	Structure Condition Rating					Total Length
	Structures	A	B	C	D	F	(feet)
Bulkhead / Seawall	19	2	8	7	2		6260
Revetment	13		6	5	2		6214
Groin / Jetty	2		1	1			155
Coastal Dune							
Coastal Beach							
	34	2	15	13	4		12629

Within the above table, the total length of each type of structure is also provided. The structures are listed by the type which is providing the primary coastal protection. Many sites have multiple structure types at the same location (i.e. revetment in front of seawall). These secondary structures, although not identified within these tables, are included in the development of repair/rehabilitation costs.

The development of repair costs has been included by structure type and by condition. In the Town of Hingham's case there are a total of 32 structures which would require approximately \$6.8 million to bring all the coastal structures to "A" Rating. Most critical will be the structures in the "D" and "F" classifications as those are assumed to undergo some level of damage or failure during the next major coastal storm event. To reconstruct these structures, identified in the preliminary survey as being in poor condition, an estimated \$1.4 million would be required to upgrade the Town's coastal protection.

**STRUCTURE REPAIR / RECONSTRUCTION COST - Town of Hingham**

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Bulkhead / Seawall	19		\$ 554,076	\$ 3,105,264	\$ 473,616		\$ 4,132,956
Revetment	13		\$ 501,039	\$ 1,134,168	\$ 894,340		\$ 2,529,547
Groin / Jetty	2		\$ 10,210	\$ 108,108			\$ 118,318
Coastal Dune							\$ -
Coastal Beach							\$ -
	34	\$-	\$ 1,065,325	\$ 4,347,540	\$ 1,367,956	\$ -	\$ 6,780,821

Based on the limited research within the scope of this project research, the presumed ownership of the structures was established on an initial basis and would be subject to more intense review in future tasks. Structures identified as being owned privately were excluded from further consideration. Although ownership of the land on which the structure was located was a factor, the structure ownership was treated as a separate issue from land ownership. For the Town of Hingham the breakdown of structures by assumed ownership is as follows:

**STRUCTURE OWNERSHIP / REPAIR COST - Town of Hingham**

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Town Owned	26		\$ 995,183	\$ 3,982,750	\$ 473,616		\$ 5,451,549
Commonwealth of Massachusetts	6		\$ 55,292	\$ 244,079	\$ 894,340		\$ 1,193,711
Federal Government Owned							\$ -
Unknown Ownership	2		\$ 14,850	\$ 120,711			\$ 135,561
							\$ -
	34	\$-	\$ 1,065,325	\$ 4,347,540	\$ 1,367,956	\$ -	\$ 6,780,821

The identification of presumed ownership was not based on the investigation of legal documents but relied on property ownership and from construction and regulatory documents that were found. A more detailed investigation of legal documents and agreements would be required where structure ownership is disputed. A more detailed identification of structure type, length, condition and location can be found in Section III which contains Structure Assessment Reports for each individual structure found.

**SUMMARY**

The enclosed reports and associated documents reflects the Town of Hingham's coastal structure information that will eventually be input into a state-wide GIS database and will be accessible through MassGIS. This data, when compiled state-wide, will be critical in the development of both short term and long term planning for maintaining and improving Massachusetts coastal protection.


This database will also provide relatively quick access to identify available documentation for these structures as well as the ability to be updated as coastal structure improvements are made.

## **Section III**

### **Town of Hingham**

### **Structure Assessment Reports**





**COASTAL STRUCTURE LOCATION PLAN**


**TOWN OF HINGHAM**

**SOUTH SHORE COASTAL INFRASTRUCTURE INVENTORY  
AND ASSESSMENT DEMONSTRATION PROJECT**

AUGUST 2006



**BCE** Bourne Consulting Engineering  
100 West Street, Suite 200  
Hingham, MA 02043  
TEL: (508) 885-3333 FAX: (508) 885-3373



## COASTAL STRUCTURE LOCATION PLAN

### TOWN OF HINGHAM


SOUTH SHORE COASTAL INFRASTRUCTURE INVENTORY  
AND ASSESSMENT DEMONSTRATION PROJECT

AUGUST 2006









COASTAL STRUCTURE LOCATION PLAN

TOWN OF HINGHAM

SOUTH SHORE COASTAL INFRASTRUCTURE INVENTORY  
AND ASSESSMENT DEMONSTRATION PROJECT

AUGUST 2006



**BCE** Bourne Consulting Engineering  
100 West County Road  
Bourne, MA 01905  
TEL: (508) 866-4333 FAX: (508) 866-4334

## Structure Assessment Form

Town: **Hingham**Structure ID: **034-011-000-005-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Scudder St.

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

DCR – Contract Drawings

Owner Name:

Hingham

Earliest Structure Record:

1955

Estimated Reconstruction/Repair Cost:

\$157,865.00

Length: **1005** Top Elevation:  FIRM Map Zone: **V4** FIRM Map Elevation: **14**  
 Feet Feet NAVD 88 Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Placed rip rap slope along steep earth bank. 45 degree slope toed into cobble beach. 5 feet wide crest. Stone size is 1 to 3 ton.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

III

*Rating*

Moderate Priority

*Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

## Structure Images:

034-011-000-005-100-PHO1A.jpg

034-011-000-005-100-PHO1B.jpg

034-011-000-005-100-PHO1C.jpg

## Structure Documents:

MA DPW

JUN 1955

PROPOSED SHORE

034-011-000-005-100-DCR1A

MA DPW

SEP 1956

PROPOSED SHORE

034-011-000-005-100-DCR1B

MA DPW

APR 1957

PROPOSED SHORE

034-011-000-005-100-DCR1C

MA DPW

034-011-000-005-100-TWN1A

MA DPW

034-011-000-005-100-TWN1B

MA DPW

034-011-000-005-100-TWN1C



## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-016-000-183-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Bell Air Rd.

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

DCR – Contract Drawings

Owner Name:

Hingham

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$31,878.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
210		V4	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

5 to 10 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:



Structure Summary :

Concrete seawall (30 inches high) behind placed rip rap slope. Concrete wall is tilted outshore slightly with some cracking. Revetment with 1 to 1 slope. Top is jumbled due to placing of concrete wall. Toed in well.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

IV

*Rating*

High Priority

*Action*

Consider for Next Project Construction Listing

*Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings ( 1-10 dwellings impacted / 100 feet of shoreline)

## Structure Images:

034-016-000-183-100-PHO1A.jpg

034-016-000-183-100-PHO1B.jpg

034-016-000-183-100-PHO1C.jpg

034-016-000-183-100-PHO1D.jpg

034-016-000-183-100-PHO1E.jpg

## Structure Documents:

MA DPW

SEP 1958

PROPOSED SHORE

034-016-000-183-100-DCR1A

MA DPW

MAR 1960

CROW POINT,

034-016-000-183-100-DCR1B

MA DEQE

SEP 1972

PROPOSED SHORE

034-016-000-183-100-DCR1C

MA DPW

034-016-000-183-100-TWN1A

MA DPW

034-016-000-183-100-TWN1B

MA DPW

APR 11 198

034-016-000-183-100-TWN1C

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-016-000-183-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Bell Air Rd.

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

DCR - Contract Drawings

Owner Name:

Hingham

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$182,582.00

Length:

1520

Top Elevation:

Feet

Feet NAVD 88

FIRM Map Zone:

V4

FIRM Map Elevation:

15

Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Placed rip rap slope (1 vertical to 2 horizontal) using 1000 to 2000 lb stones. Toed into cobble beach. Earth slope continues up inshore of revetment.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

IV

*Rating*

High Priority

*Action*

Consider for Next Project Construction Listing

*Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings ( 1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

Structure Documents:

## Structure Assessment Form

Town: **Hingham**Structure ID: **034-017-000-099-100**

Key: community-map-block-parcel-structure

Property Owner:

**Local**

Location:

**Bell Air Rd.**

Date:

**8/16/2006**

Presumed Structure Owner:

**Local**

Based On Comment:

**Property Ownership**

Owner Name:

**Hingham**

Earliest Structure Record:

**0**

Estimated Reconstruction/Repair Cost:

**\$40,379.00**

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
<b>266</b>		<b>V4</b>	<b>15</b>
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

**Bulkhead/ Seawall**

Primary Material:

**Concrete**

Primary Height:

**5 to 10 Feet**

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Concrete seawall with wave return face. Minor spalling and deterioration of outshore face. Weep drains about 8 feet on center.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***III***Rating***Moderate Priority***Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)

## Structure Images:

**034-017-000-099-100-PHO1A.jpg****034-017-000-099-100-PHO1B.jpg****034-017-000-099-100-PHO1C.jpg**

## Structure Documents:

**MA DPW****JUL 1966****PROPOSED SHORE****034-017-000-099-100-DCR1A****MA DPW****034-017-000-099-100-TWN1A****MA DPW****JUL 1966****PROPOSED SHORE****034-017-000-099-100-COE1A**

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-017-000-100-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Bell Air Rd.

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$10,210.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
65		V4	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Groin/ Jetty

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Placed rip rap groin with 1 to 2 high side slopes. Crest about 5 feet wide. Approximately 1000 lb stones.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

III

*Rating*

Moderate Priority

*Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)

Structure Images:

034-017-000-100-100-PHO1A.jpg

Structure Documents:

MA DPW

JUL 1966

PROPOSED SHORE

034-017-000-100-100-DCR1A

MA DPW

034-017-000-100-100-TWN1A

MA DPW

JUL 1966

PROPOSED SHORE

034-017-000-100-100-COE1A



## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-017-000-113-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Downer Ave.

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$322,575.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
425		V4	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



## Structure Summary :

Stone seawall mortared with concrete. Base of wall has concrete mortar washed out (approximately mean high water). Patching of asphalt behind seawall where fill loss has occurred. Road located approximately 5 feet behind and multiple houses beyond road.

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

IV

*Rating*

High Priority

*Action*

Consider for Next Project Construction Listing

*Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings ( 1-10 dwellings impacted / 100 feet of shoreline)

## Structure Images:

034-017-000-113-100-PHO1A.jpg

034-017-000-113-100-PHO1B.jpg

## Structure Documents:



**Structure Assessment Form**

Structure ID: 034-027-000-059-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Causeway Rd.

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$309,672.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
204		A5	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

Structure appeared to have been built as stone seawall. Currently toppled and loose. Salt water trapped behind to form pond. Appeared built to protect wetlands and house around pond. Revetment on east (outshore) side of structure.

**Condition**

D

**Rating**

Poor

**Level of Action**

Major

**Description**

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

**Priority**

III

**Rating**

Moderate Priority

**Action**

Consider for Active Project Improvement Listing

**Description**

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

**Structure Images:**

034-027-000-059-100-PHO1A.jpg

034-027-000-059-100-PHO1B.jpg

**Structure Documents:**

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-030-000-011-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Martins Lane

Date:

8/16/2006

Presumed Structure Owner:

Unknown

Based On Comment:

Owner Name:

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$14,850.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
225		A3	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Low revetment slope with 200 to 1000 lb. stones. Located at mean high water.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

I

*Rating*

None

*Action*

Long Term Planning Considerations

*Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

034-030-000-011-100-PHO1A.jpg

034-030-000-011-100-PHO1B.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**Structure ID: **034-030-000-011-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Martins Lane

Date:

Presumed Structure Owner:

Unknown

Based On Comment:

Owner Name:

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$120,711.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
284		A3	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:	Primary Material:	Primary Height:
Bulkhead/ Seawall	Stone	Under 5 Feet
Secondary Type:	Secondary Material:	Secondary Height:



Structure Summary :

Mortared stone block seawall with wetlands outshore and town road inshore. Horizontal movement of top stones near south end (overhaul lower portion of wall). Fill loss along inshore face of wall.

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

III

*Rating*

Moderate Priority

*Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)

Structure Images:

034-030-000-011-200-PHO2A.jpg

034-030-000-011-200-PHO2B.jpg

034-030-000-011-200-PHO2C.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-034-000-000-100

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

Stodders Neck

Date:

8/16/2006

Presumed Structure Owner:

State

Based On Comment:

Property Ownership

Owner Name:

Commonwealth of Mass.

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$375,976.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
313		A4	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped rip rap scattered across earth slope at mean high water. Stone size 50 to 300 lb.

Two placed rip rap structures in length with 1000 to 2000 lb. stones. These are satisfactory condition.

*Condition*

D

*Rating*

Poor

*Level of Action*

Major

*Description*

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

*Priority*

I

*Rating*

None

*Action*

Long Term Planning Considerations

*Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

034-034-000-000-100-PHO1A.jpg

034-034-000-000-100-PHO1B.jpg

034-034-000-000-100-PHO1C.jpg

Structure Documents:



**Structure Assessment Form**

Structure ID: 034-035-000-001-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Stodders Neck

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$55,255.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
460		V5	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Placed rip rap slope (1 vertical by 2 horizontal) at top of coastal beach. Portions are toed in (about half of length). No evidence of scour.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

I

*Rating*

None

*Action*

Long Term Planning Considerations

*Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

034-035-000-001-100-PHO1A.jpg

034-035-000-001-100-PHO1B.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**Structure ID: **034-036-000-106-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Weymouth Back River

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$664,620.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
530		A4	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Concrete seawall forming wharves formerly for Hingham Shipyard concrete ramps between wharves. Heavy spalling & deterioration of concrete with exposed and corroded reinforcing.

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

I

*Rating*

None

*Action*

Long Term Planning Considerations

*Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

034-036-000-106-100-PHO1A.jpg

034-036-000-106-100-PHO1B.jpg

Structure Documents:

MA DPW

MA DPW

034-036-000-106-100-TWN1A

034-036-000-106-100-TWN1B

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-036-000-106-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Weymouth Back River

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$136,937.00

Length: 228 Feet    Top Elevation:    FIRM Map Zone: A4    FIRM Map Elevation: 12 Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped rip rap slope along bank. Stone size 100 to 1000 lbs.

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

III

*Rating*

Moderate Priority

*Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)

Structure Images:

034-036-000-106-200-PHO2A.jpg

034-036-000-106-200-PHO2B.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-036-000-106-300

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Weymouth Back River

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$0.00

Length:

161

Top Elevation:

Feet

Feet NAVD 88

FIRM Map Zone:

A4

FIRM Map Elevation:

12

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Concrete seawall with timber fender system. Minor cracking in concrete cap. Wall face is not even (constructed that way).

*Condition*

A

*Rating*

Excellent

*Level of Action*

None

*Description*

Like new condition. Structure expected to withstand major coastal storm without damage. Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm.

*Priority*

III

*Rating*

Moderate Priority

*Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)

Structure Images:

034-036-000-106-300-PHO3A.jpg

Structure Documents:



## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-039-000-008-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Otis St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$258,258.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
430		V4	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



## Structure Summary :

Placed rip rap slope (45 degree) along coastal bank with park and road directly inshore. Slope toed into beach. Stone size 500 to 2000lb. Northern 100 feet is smaller stone and loose with some erosion.

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

II

*Rating*

Low Priority

*Action*

Future Project Consideration

*Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

## Structure Images:

034-039-000-008-100-PHO1A.jpg

034-039-000-008-100-PHO1B.jpg

## Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-039-000-009-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Otis St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$494,894.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
824		V4	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Placed rip rap slope (45 degree) about 10 feet high. Toed into beach, but some locations are scoured out. Some stones loose or dislodged. Fill at top of wall washed out. Top of wall not well defined. Road directly behind revetment.

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

III

*Rating*

Moderate Priority

*Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)

Structure Images:

034-039-000-009-100-PHO1A.jpg

034-039-000-009-100-PHO1B.jpg

034-039-000-009-100-PHO1C.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-045-000-002-100

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

Lincoln St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

State

Based On Comment:

Property Ownership

Owner Name:

Commonwealth of Mass.

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$55,292.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
352		A4	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped rip rap slope (1 vertical by 3 horizontal) with stone size from 100 to 2000 lb. Minor erosion at top of revetment.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

IV

*Rating*

High Priority

*Action*

Consider for Next Project Construction Listing

*Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings ( 1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

034-045-000-002-100-PHO1A.jpg

034-045-000-002-100-PHO1B.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-045-000-002-200

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

Lincoln St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

State

Based On Comment:

Property Ownership

Owner Name:

Commonwealth of Mass.

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$0.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
189		A4	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Over 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Over 15 Feet



Structure Summary :

Concrete bridge pier foundation in excellent condition. Placed rip rap slope (1 vertical by 1 horizontal) between bridge pier abutments. 500 to 2000 lb stones.

*Condition*

A

*Rating*

Excellent

*Level of Action*

None

*Description*

Like new condition. Structure expected to withstand major coastal storm without damage. Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm.

*Priority*

V

*Rating*

Immediate / Highest Priority

*Action*

Consider For Immediate Action Due to Public Safety and Welfare Issues

*Description*

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:

034-045-000-002-200-PHO2A.jpg

034-045-000-002-200-PHO2B.jpg

034-045-000-002-300-PHO2C.jpg

Structure Documents:



## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-045-000-002-300

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

Lincoln St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

State

Based On Comment:

Property Ownership

Owner Name:

Commonwealth of Mass.

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$135,971.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
174		A3	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Placed stone block slope (2 to 3 ton) on earth and crushed stone slope. Gaps between stones and some erosion above top of revetment. Portions are dumped stones.

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

II

*Rating*

Low Priority

*Action*

Future Project Consideration

*Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

034-045-000-002-300-PHO3A.jpg

Structure Documents:



## Structure Assessment Form

Town: **Hingham**Structure ID: **034-045-000-002-400**

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

Lincoln St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

State

Based On Comment:

Property Ownership

Owner Name:

Commonwealth of Mass.

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$108,108.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
90		A3	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Groin/ Jetty

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped stone blocks piled about 4 feet above mean high water.

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

I

*Rating*

None

*Action*

Long Term Planning Considerations

*Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

034-045-000-002-500-PHO4A.jpg

034-045-000-002-500-PHO4B.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-046-000-001-100

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

Lincoln St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

State

Based On Comment:

Property Ownership

Owner Name:

Commonwealth of Mass.

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$518,364.00

Length:

210

Top Elevation:

Feet

Feet NAVD 88

FIRM Map Zone:

A4

FIRM Map Elevation:

12

Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Earth slope (near vertical) with small stones at base of slope. Stone size 4 inches to 12 inches and dumped poorly.

*Condition*

D

*Rating*

Poor

*Level of Action*

Major

*Description*

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

*Priority*

IV

*Rating*

High Priority

*Action*

Consider for Next Project Construction Listing

*Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings ( 1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

034-046-000-001-100-PHO1A.jpg

034-046-000-001-100-PHO1B.jpg

034-046-000-001-100-PHO1C.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-050-000-050-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Summer St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

DEP - Ch 91 License

Owner Name:

Hingham

Earliest Structure Record:

1986

Estimated Reconstruction/Repair Cost:

\$35,195.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
293	9	V4	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Concrete

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Public boat ramp (concrete) with revetment on south side and precast barriers on north side (some revetment). Some cracking of concrete ramp. Exposed, corroded reinforcing at top of ramp (approximately mean high water). Toe of ramp buried in sand.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

I

*Rating*

None

*Action*

Long Term Planning Considerations

*Description*

No Inshore Structures or Residential Dwelling Units Present

## Structure Images:

034-050-000-050-100-PHO1A.jpg

034-050-000-050-100-PHO1B.jpg

034-050-000-050-100-PHO1C.jpg

## Structure Documents:

DEP CH.91

OCT 22 198

PLAN

034-050-000-050-100-LIC1A

TOWN

JUN 1986

PROPOSED

034-050-000-050-100-COE1A

TOWN

MAR 1994

BOAT RAMP

034-050-000-050-100-COE2A

## Structure Assessment Form

Town: **Hingham**Structure ID: **034-050-000-050-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Summer St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

DEP - Ch 91 License

Owner Name:

Hingham

Earliest Structure Record:

1986

Estimated Reconstruction/Repair Cost:

\$131,168.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
523	9	V4	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall (dryset) for park and town landing. Some fill loss inshore of seawall. No noted movement or bulging.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

II

*Rating*

Low Priority

*Action*

Future Project Consideration

*Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

## Structure Images:

034-050-000-050-200-PHO2A.jpg

034-050-000-050-200-PHO2B.jpg

034-050-000-050-200-PHO2C.jpg

## Structure Documents:

DEP CH.91

OCT 22 198

PLAN

034-050-000-050-200-LIC2A

DEP CH.91

JAN 5 1990

PLANS

034-050-000-050-200-LIC2B



## Structure Assessment Form

Town: **Hingham**Structure ID: **034-050-000-051-100**

Key: community-map-block-parcel-structure

Property Owner:

**Local**

Location:

**Otis St. (Rt. 3A)**

Date:

**8/16/2006**

Presumed Structure Owner:

**Local**

Based On Comment:

**Property Ownership**

Owner Name:

**Hingham**

Earliest Structure Record:

**0**

Estimated Reconstruction/Repair Cost:

**\$108,108.00**

Length:

**180**

Top Elevation:

**Feet****Feet NAVD 88**

FIRM Map Zone:

**A3**

FIRM Map Elevation:

**11****Feet NGVD**

Primary Type:

**Revetment**

Primary Material:

**Stone**

Primary Height:

**5 to 10 Feet**

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Dumped rip rap along coastal bank. Coastal beach outshore. Stone size varied from 4 inches diameter to 8 inches diameter.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description***No Inshore Structures or Residential Dwelling Units Present**

Structure Images:

**034-050-000-051-100-PHO1A.jpg****034-050-000-051-100-PHO1B.jpg**

Structure Documents:

**TOWN****FEB 2001****HINGHAM BEACH****034-050-000-051-100-COE1A**



**Structure Assessment Form**Town: **Hingham**Structure ID: **034-051-000-001-100**

Key: community-map-block-parcel-structure

Property Owner:

**Local**

Location:

**Summer St. (Rt. 3A)**

Date:

**8/16/2006**

Presumed Structure Owner:

**Local**

Based On Comment:

**Property Ownership**

Owner Name:

**Hingham**

Earliest Structure Record:

**0**

Estimated Reconstruction/Repair Cost:

**\$77,748.00**

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
<b>310</b>	<b>15</b>	<b>A3</b>	<b>11</b>
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

**Bulkhead/ Seawall**

Primary Material:

**Stone**

Primary Height:

**10 to 15 Feet**

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall (dryset) with 30 inch wide concrete cap and railing. Minor fill loss inshore of seawall.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

**034-051-000-001-100-PHO1A.jpg****034-051-000-001-100-PHO1B.jpg**

Structure Documents:

**DEP CH.91****APR 10 200****PLANS****034-051-000-001-100-LIC1A**

## Structure Assessment Form

Town: **Hingham**Structure ID: **034-051-000-001-200**

Key: community-map-block-parcel-structure

Property Owner:

**Local**

Location:

**Summer St. (Rt. 3A)**

Date:

**8/16/2006**

Presumed Structure Owner:

**Local**

Based On Comment:

**Property Ownership**

Owner Name:

**Hingham**

Earliest Structure Record:

**0**

Estimated Reconstruction/Repair Cost:

**\$163,944.00**

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
<b>108</b>	<b>8</b>	<b>A3</b>	<b>11</b>
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

**Bulkhead/ Seawall**

Primary Material:

**Stone**

Primary Height:

**5 to 10 Feet**

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall (dry set). Eastern portion failed previously and repaired with dumped rip rap (1 to 3 ton stones). Median strip between seawall and Route 3A. Remaining seawall is stable, although heavy fill loss inshore.

*Condition***D***Rating***Poor***Level of Action***Major***Description*

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

*Priority***III***Rating***Moderate Priority***Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

**034-051-000-001-200-PHO2A.jpg****034-051-000-001-200-PHO2B.jpg**

Structure Documents:

**DEP CH.91****APR 10 200****PLANS****034-051-000-001-200-LIC2A**

**Structure Assessment Form**

Property Owner:

Local

Location:

Summer St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$57,182.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
228	10		
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Structure Summary :

Same as adjacent structure with inclusion of dumped rip rap at base of wall. Stone size is 100 to 1000 lb. Slope is 8 feet wide by 5 feet high.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

II

*Rating*

Low Priority

*Action*

Future Project Consideration

*Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

034-051-000-001-300-PHO3A.jpg

034-051-000-001-300-PHO3B.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-051-000-001-400

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Summer St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$24,077.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
96	15	A3	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Bulkhead/ Seawall

Secondary Material:

Stone

Secondary Height:



Structure Summary :

Concrete wall constructed on top of mortared stone foundation for Route 3A. Outshore face is satisfactory condition, constructed 1970.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

IV

*Rating*

High Priority

*Action*

Consider for Next Project Construction Listing

*Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings ( 1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

034-051-000-001-400-PHO4A.jpg

Structure Documents:



## Structure Assessment Form

Town: **Hingham**Structure ID: **034-051-000-003-100**

Key: community-map-block-parcel-structure

Property Owner:

**Local**

Location:

**Summer St. (Rt. 3A)**

Date:

**8/16/2006**

Presumed Structure Owner:

**Local**

Based On Comment:

**DEP - Ch 91 License**

Owner Name:

**Hingham**

Earliest Structure Record:

**2001**

Estimated Reconstruction/Repair Cost:

**\$283,404.00**

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
<b>226</b>	<b>15</b>	<b>A3</b>	<b>11</b>
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

**Bulkhead/ Seawall**

Primary Material:

**Stone**

Primary Height:

**10 to 15 Feet**

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall (dryset) that leans inshore noticeably (possible constructed this way). 3 foot wide concrete slabs directly inshore of wall which are broken and deteriorated along outshore face. Significant fill loss behind seawall (5 feet wide by 2 to 4 feet diameter). Building and park directly inshore.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***III***Rating***Moderate Priority***Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)

Structure Images:

**034-051-000-003-100-PHO1A.jpg****034-051-000-003-100-PHO1B.jpg**

Structure Documents:

**DEP CH.91****APR 10 200****PLANS****034-051-000-003-100-LIC1A**



## Structure Assessment Form

Town: **Hingham**Structure ID: **034-051-000-004-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Summer St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$481,536.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
384		A5	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:



## Structure Summary :

12 inch wide concrete seawall with revetment slope outshore. Concrete seawall is mixture of cast in place sections and stacked precast sections. Peastone fill inshore. Concrete is spalling at top with precast sections moved or loose. Revetment is 100 lb to 1000 lb stones dumped along face (1 vertical to 2 horizontal)

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

III

*Rating*

Moderate Priority

*Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)

## Structure Images:

034-051-000-004-100-PHO1A.jpg

034-051-000-004-100-PHO1B.jpg

034-051-000-004-100-PHO1C.jpg

## Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-051-000-005-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Summer St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$112,860.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
450	13	A3	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall (dryset) with route 3A rotary directly inshore. 2 feet wide by 1 foot high concrete cap. Some fill loss behind seawall in median strip. (1 foot wide by 1 to 2 foot diameter)

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

IV

*Rating*

High Priority

*Action*

Consider for Next Project Construction Listing

*Description*

High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings ( 1-10 dwellings impacted / 100 feet of shoreline)

Structure Images:

034-051-000-005-100-PHO1A.jpg

034-051-000-005-100-PHO1B.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-051-000-005B-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Summer St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$315,744.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
416	8	A3	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall (dryset) with paved walkway inshore. Heavy fill loss behind. A few stones appeared to be "pushed" outshore (horizontal movement). Very western end along side Route 3A.

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

II

*Rating*

Low Priority

*Action*

Future Project Consideration

*Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

034-051-000-005B-100-PHO1A.jpg

Structure Documents:

## Structure Assessment Form

Town: **Hingham**Structure ID: **034-051-000-005B-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Summer St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

DEP - Ch 91 License

Owner Name:

Hingham

Earliest Structure Record:

1990

Estimated Reconstruction/Repair Cost:

\$78,784.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
519	10	A3	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall (dryset) around filled wharf. Heavy fill loss at outshore end. Patching with dumped stone (1 inch or less) and concrete to fill washed out areas. Minor movement of stones noted.

*Condition*

B

*Rating*

Good

*Level of Action*

Minor

*Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority*

III

*Rating*

Moderate Priority

*Action*

Consider for Active Project Improvement Listing

*Description*

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted / 100 feet of shoreline)

Structure Images:

034-051-000-005B-200-PHO2A.jpg

034-051-000-005B-200-PHO2B.jpg

Structure Documents:

DEP CH.91

DEC 27 198

PLANS

034-051-000-005B-200-LIC2A



## Structure Assessment Form

Town: **Hingham**

Structure ID: 034-051-000-059-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Summer St. (Rt. 3A)

Date:

8/16/2006

Presumed Structure Owner:

Local

Based On Comment:

Property Ownership

Owner Name:

Hingham

Earliest Structure Record:

0

Estimated Reconstruction/Repair Cost:

\$916,674.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
731	10	A3	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

Stone block seawall (dry set) around park area. Major fill loss behind seawall (4 feet wide by 1 to 2 foot deep). Many voids (typical 6 inches by 2 to 4 feet long)

*Condition*

C

*Rating*

Fair

*Level of Action*

Moderate

*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*

II

*Rating*

Low Priority

*Action*

Future Project Consideration

*Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

034-051-000-059-100-PHO1A.jpg

034-051-000-059-100-PHO1B.jpg

034-051-000-059-100-PHO1C.jpg

Structure Documents:



## **Section IV**

### **Town of Hingham**

### **Structure Photographs**

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
034-011-000-005-100	034-011-000-005-100-PHO1A.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-011-000-005-100	034-011-000-005-100-PHO1B.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-011-000-005-100	034-011-000-005-100-PHO1C.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-016-000-183-100	034-016-000-183-100-PHO1A.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-016-000-183-100	034-016-000-183-100-PHO1B.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-016-000-183-100	034-016-000-183-100-PHO1C.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-016-000-183-100	034-016-000-183-100-PHO1D.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-016-000-183-100	034-016-000-183-100-PHO1E.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-017-000-099-100	034-017-000-099-100-PHO1A.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-017-000-099-100	034-017-000-099-100-PHO1B.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-017-000-099-100	034-017-000-099-100-PHO1C.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-017-000-113-100	034-017-000-113-100-PHO1A.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-017-000-113-100	034-017-000-113-100-PHO1B.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-027-000-059-100	034-027-000-059-100-PHO1A.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-027-000-059-100	034-027-000-059-100-PHO1B.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-030-000-011-100	034-030-000-011-100-PHO1A.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-030-000-011-100	034-030-000-011-100-PHO1B.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-030-000-011-200	034-030-000-011-200-PHO2A.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-030-000-011-200	034-030-000-011-200-PHO2B.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-030-000-011-200	034-030-000-011-200-PHO2C.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-034-000-000-100	034-034-000-000-100-PHO1A.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-034-000-000-100	034-034-000-000-100-PHO1B.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-034-000-000-100	034-034-000-000-100-PHO1C.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
034-035-000-001-100	034-035-000-001-100-PHO1A.jpg		Bourne Consulting Engineering	HINGHAM	August 2006	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

[illegible]






## South Shore Coastal Infrastructure and Assessment



034-011-000-005-100-PHO1A.JPG



034-011-000-005-100-PHO1B.JPG



034-011-000-005-100-PHO1C.JPG



034-016-000-183-100-PHO1A.JPG



034-016-000-183-100-PHO1B.JPG




034-016-000-183-100-PHO1C.JPG



## South Shore Coastal Infrastructure and Assessment



034-016-000-183-100-PHO1D.JPG



034-016-000-183-100-PHO1E.JPG



034-017-000-010-100-PHO1A.JPG



034-017-000-099-100-PHO1A.JPG



034-017-000-099-100-PHO1B.JPG



034-017-000-099-100-PHO1C.JPG



## South Shore Coastal Infrastructure and Assessment




034-017-000-100-100-PHO1A.JPG



034-017-000-113-100-PHO1A.JPG



034-017-000-113-100-PHO1B.JPG



034-027-000-059-100-PHO1A.JPG



034-027-000-059-100-PHO1B.JPG



034-030-000-011-100-PHO1A.JPG



## South Shore Coastal Infrastructure and Assessment



034-030-000-011-100-PHO1B.JPG



034-030-000-011-200-PHO2A.JPG



034-030-000-011-200-PHO2B.JPG



034-030-000-011-200-PHO2C.JPG



034-034-000-000-100-PHO1A.JPG



034-034-000-000-100-PHO1B.JPG



## South Shore Coastal Infrastructure and Assessment



034-034-000-000-100-PHO1C.JPG



034-035-000-001-100-PHO1A.JPG



034-035-000-001-100-PHO1B.JPG



034-036-000-106-100-PHO1A.JPG



034-036-000-106-100-PHO1B.JPG



034-036-000-106-200-PHO2A.JPG



## South Shore Coastal Infrastructure and Assessment



034-036-000-106-200-PHO2B.JPG



034-036-000-106-300-PHO3A.JPG



034-039-000-008-100-PHO1A.JPG



034-039-000-008-100-PHO1B.JPG



034-039-000-009-100-PHO1A.JPG



034-039-000-009-100-PHO1B.JPG



## South Shore Coastal Infrastructure and Assessment




034-039-000-009-100-PHO1C.JPG



034-045-000-002-100-PHO1A.JPG



034-045-000-002-100-PHO1B.JPG



034-045-000-002-200-PHO2A.JPG



034-045-000-002-200-PHO2B.JPG



034-045-000-002-200-PHO2C.JPG




## South Shore Coastal Infrastructure and Assessment



034-045-000-002-300-PHO3A.JPG



034-045-000-002-400-PHO4A.JPG



034-045-000-002-400-PHO4B.JPG



034-046-000-001-100-PHO1A.JPG




034-046-000-001-100-PHO1B.JPG



034-046-000-001-100-PHO1C.JPG




## South Shore Coastal Infrastructure and Assessment



034-050-000-050-100-PHO1A.JPG



034-050-000-050-100-PHO1B.JPG



034-050-000-050-100-PHO1C.JPG



034-050-000-050-200-PHO2A.JPG



034-050-000-050-200-PHO2B.JPG



034-050-000-050-200-PHO2C.JPG



## South Shore Coastal Infrastructure and Assessment



034-050-000-051-100-PHO1A.JPG



034-050-000-051-100-PHO1B.JPG



034-051-000-001-100-PHO1A.JPG



034-051-000-001-100-PHO1B.JPG



034-051-000-001-200-PHO2A.JPG



034-051-000-001-200-PHO2B.JPG




## South Shore Coastal Infrastructure and Assessment




034-051-000-001-300-PHO3A.JPG



034-051-000-001-300-PHO3B.JPG




034-051-000-001-400-PHO4A.JPG



034-051-000-003-100-PHO1A.JPG



034-051-000-003-100-PHO1B.JPG



034-051-000-004-100-PHO1A.JPG




## South Shore Coastal Infrastructure and Assessment



034-051-000-004-100-PHO1B.JPG



034-051-000-004-100-PHO1C.JPG




034-051-000-005-100-PHO1A.JPG



034-051-000-005-100-PHO1B.JPG




034-051-000-005B-100-PHO1A.JPG



034-051-000-005B-200-PHO2A.JPG


## South Shore Coastal Infrastructure and Assessment



034-051-000-005B-200-PHO2B.JPG



034-051-000-059-100-PHO1A.JPG



034-051-000-059-100-PHO1A.JPG

## **Section V**

### **Town of Hingham**

### **Structure Research**

#### TOWN DOCUMENT LIST

#### MA DCR - DOCUMENT LIST

#### MA DEP – Chp 91 DOCUMENT LIST

- Copies of License Documents

#### USACE – PERMIT DOCUMENT LIST

- Copies of Permit Documents



BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
034-011-000-005-100	034-011-000-005-100-TWN1A	1527	MA DPW	HINGHAM			*	MERRILL STREET	STONE MOUND CONSTRUCTION
034-011-000-005-100	034-011-000-005-100-TWN1B	1655	MA DPW	HINGHAM			*	MERRILL STREET	SHORE PROTECTION, STONE MOUND
034-011-000-005-100	034-011-000-005-100-TWN1C	1754	MA DPW	HINGHAM			*	MERRILL STREET	SHORE PROTECTION, STONE MOUND
034-016-000-183-100	034-016-000-183-100-TWN1A	1858	MA DPW	HINGHAM			*	INTERSECTION OF BELAIR ROAD AND BELAIR DRIVE	STONE MOUND, VICINITY OF BELAIR ROAD
034-016-000-183-100	034-016-000-183-100-TWN1B	2097	MA DPW	HINGHAM			*	INTERSECTION OF BELAIR ROAD AND BELAIR DRIVE	SHORE PROTECTION, STONE MOUND
034-016-000-183-100	034-016-000-183-100-TWN1C	2783	MA DPW	HINGHAM	APR 11 1983		*	INTERSECTION OF HOWE STREET AND JARVIS AVE	SHORE PROTECTION, STONE MOUND
034-017-000-098-100	034-017-000-098-100-TWN1A	2545	MA DPW	HINGHAM			*	INTERSECTION OF PARKER DRIVEWAY AND CUSHING AVE	SHORE PROTECTION, CONCRETE SEAWALL
034-017-000-100-100	034-017-000-100-100-TWN1A	2545	MA DPW	HINGHAM			*	INTERSECTION OF PARKER DRIVEWAY AND CUSHING AVE	SHORE PROTECTION, CONCRETE SEAWALL
034-038-000-106-100	034-038-000-106-100-TWN1A	3087	MA DPW	HINGHAM			*	PRIVATE SHIPYARD ADJACENT TO LINCOLN STREET	READVERTISED AS CONT. NO 3178
034-038-000-106-100	034-038-000-106-100-TWN1B	3198	MA DPW	HINGHAM			5	PRIVATE SHIPYARD ADJACENT TO LINCOLN STREET	COMMUNITY PIER REHABILITATION (READVERTISED TO 3087)

TOWN: HINGHAM

SOURCE: MA-DCR - OFFICE OF WATERWAYS

LOCATION: MA-DCR - OFFICE OF WATERWAYS, HINGHAM, MA

DATE OF RESEARCH: AUGUST 2006

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
034-011-000-005-100	034-011-000-005-100-DCR1A	1527	MA DPW	HINGHAM	JUN 1955	PROPOSED SHORE PROTECTION, STONE MOUND CONSTRUCTION, CROW POINT, HINGHAM	1	PARKER'S DRIVE, EAST OF CUSHING DRIVE	ORIG. CONST.
034-011-000-005-100	034-011-000-005-100-DCR1B	1655	MA DPW	HINGHAM	SEP 1956	PROPOSED SHORE PROTECTION, STONE MOUND CONSTRUCTION, CROW POINT, HINGHAM	1	MALCOLM STREET EAST 300 FEET	
034-011-000-005-100	034-011-000-005-100-DCR1C	1754	MA DPW	HINGHAM	APR 1957	PROPOSED SHORE PROTECTION, STONE MOUND CONSTRUCTION, CROW POINT, HINGHAM	1	MALCOLM STREET WEST 150 FEET	
034-016-000-183-100	034-016-000-183-100-DCR1A	1858	MA DPW	HINGHAM	SEP 1958	PROPOSED SHORE PROTECTION, BELAIR ROAD, CROW POINT	1	EAST OF INTERSECTION OF BELAIR ROAD AND BELAIR DRIVE	STONE MOUND, VICINITY OF BELAIR ROAD
034-016-000-183-100	034-016-000-183-100-DCR1B	2097	MA DPW	HINGHAM	MAR 1980	CROW POINT, VICINITY BELAIR ROAD	1	NORTH-EASTERN END COASTAL SEGMENT BELAIR ROAD	SHORE PROTECTION, STONE MOUND
034-016-000-183-100	034-016-000-183-100-DCR1C	2763	MA DECE	HINGHAM	SEP 1972	PROPOSED SHORE PROTECTION, STONE MOUND, CROW POINT	1	INTERSECTION OF HOWARD ROAD AND JARVIS AVE	ORIG. CONST.
034-017-000-099-100	034-017-000-099-100-DCR1A	2545	MA DPW	HINGHAM	JUL 1986	SEAWALL, CROW POINT	1	INTERSECTION OF PARKER DRIVEWAY AND CUSHING AVE	SHORE PROTECTION, CONCRETE SEAWALL, INCLUDES GROIN EAST END OF STRUCTURE
034-017-000-100-100	034-017-000-100-100-DCR1A	2545	MA DPW	HINGHAM	JUL 1988	PROPOSED SHORE PROTECTION, CONCRETE SEAWALL, CROW POINT	1	INTERSECTION OF PARKER DRIVEWAY AND CUSHING AVE	SHORE PROTECTION, CONCRETE SEAWALL, INCLUDES GROIN EAST END OF STRUCTURE



TOWN: HINGHAM

SOURCE: MA-DEP CHAPTER 91 LICENSE




LOCATION: MA-DEP MAIN OFFICE, BOSTON, MA

DATE OF RESEARCH: AUGUST 2006

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
034-050-000-050-100	034-050-000-050-100-LIC1A	1549	DEP CH.91	HINGHAM	OCT 22 1988	PLAN ACCOMPANYING PETITION OF TOWN OF HINGHAM TO DEMOLISH EXISTING LAUNCH RAMP. TO CONSTRUCT AND MAINTAIN NEW RAMP IN THE TIDEWATERS OF HINGHAM HARBOR	2	TOWN PIER AND BOAT RAMP, SOUTHERN TERMINUS OF OTIS STREET	
034-050-000-050-200	034-050-000-050-200-LIC2A	1549	DEP CH.91	HINGHAM	OCT 22 1988	PLAN ACCOMPANYING PETITION OF TOWN OF HINGHAM TO DEMOLISH EXISTING LAUNCH RAMP. TO CONSTRUCT AND MAINTAIN NEW RAMP IN THE TIDEWATERS OF HINGHAM HARBOR	2	TOWN PIER AND BOAT RAMP, SOUTHERN TERMINUS OF OTIS STREET	
034-050-000-050-200	034-050-000-050-200-LIC2B	2227	DEP CH.91	HINGHAM	JAN 5 1990	PLANS ACCOMPANYING THE PETITION OF TOWN OF HINGHAM TO REPAIR AND MAINTAIN EXISTING SEAWALL, WALKWAY & SOLID FILL, HINGHAM HARBOR	2	SOUTHERN TERMINUS OF OTIS STREET	
034-051-000-001-100	034-051-000-001-100-LIC1A	8777	DEP CH.91	HINGHAM	APR 10 2001	PLANS ACCOMPANYING THE PETITION OF HINGHAM HARBOR DEVELOPMENT COMMITTEE RECONSTRUCTION OF BULKHEADS AT 4 SUMMER STREET, HINGHAM, MA	8	4 SUMMER STREET	
034-051-000-001-200	034-051-000-001-200-LIC2A	8777	DEP CH.91	HINGHAM	APR 10 2001	PLANS ACCOMPANYING THE PETITION OF HINGHAM HARBOR DEVELOPMENT COMMITTEE RECONSTRUCTION OF BULKHEADS AT 4 SUMMER STREET, HINGHAM, MA	8	4 SUMMER STREET	
034-051-000-003-100	034-051-000-003-100-LIC1A	8777	DEP CH.91	HINGHAM	APR 10 2001	PLANS ACCOMPANYING THE PETITION OF HINGHAM HARBOR DEVELOPMENT COMMITTEE RECONSTRUCTION OF BULKHEADS AT 4 SUMMER STREET, HINGHAM, MA	8	4 SUMMER STREET	
034-051-000-005B-200	034-051-000-005B-200-LIC2A	2211	DEP CH.91	HINGHAM	DEC 27 1989	PLANS ACCOMPANYING THE PETITION OF TOWN OF HINGHAM TO REPAIR AND MAINTAIN SEAWALL AND WALKWAY HINGHAM HARBOR, COUNTY OF PLYMOUTH, MA SEPTEMBER 1989, NUCCI VINE ASSOCIATES, INC.	2	BETWEEN BARNES WHARF AND STEAMBOAT WHARF	

034-50-50-200

034-50-50-100



PLAN ACCOMPANYING PETITION OF:  
**TOWN OF HINGHAM**  
 TO DEMOLISH EXISTING LAUNCH RAMP, TO  
 CONSTRUCT & MAINTAIN NEW RAMP  
**IN THE TIDEWATERS OF HINGHAM HARBOR**  
**TOWN OF HINGHAM**  
**COUNTY OF PLYMOUTH**  
**STATE OF MASSACHUSETTS**

#### LIST OF ABUTTERS

1. THOMAS F. KEHOE - III
2. TRUSTEES OF HINGHAM BATHING BEACH


86-001

LICENSE PLAN NO. 1549

Approved by Department of Environmental Quality Engineer  
 of Massachusetts


*[Signature]* COMMISSIONER  
*[Signature]* DIVISION DIRECTOR  
*[Signature]* SECTION CHIEF

1052




SECTION A-A

N.T.S.




SECTION C-C

N.T.S.



PLAN OF RECONSTRUCTED RAMP

N.T.S.



LICENSE PLAN NO. 1549

Approved by Department of Environmental Quality Engineering

Date: OCTOBER 22, 1986



86-00-1

2082



**NOTES:**

1. DATUM: MLW=0, MHW=9.5, ELW=-1.0
2. TOWN OF HINGHAM OWNS TOWN LANDING SITE
3. LICENSE NO. 2756 (1903) LICENSED THE SEAWALL FROM APPROXIMATE STATION 0+76 TO STATION 2+60+ AND 2425 CUBIC YARDS OF FILL DISPLACING MEAN TIDE.
4. NO DREDGING OR FILLING PROPOSED. PROJECT TO LICENSE 3000± CUBIC YARDS DISPLACING MEAN TIDE, NOT LICENSED IN 1903.
5. WALL TO BE REPAIRED & MAINTAINED STA 0+00 TO 4+85



PLANS ACCOMPANYING THE PETITION OF  
TOWN OF HINGHAM  
TO REPAIR AND MAINTAIN EXISTING  
SEAWALL, WALKWAY & SOLID FILL  
HINGHAM HARBOR  
COUNTY OF PLYMOUTH, MA  
OCTOBER 23, 1989  
NUCCI VINE ASSOCIATES, INC.

SHEET 1 OF 2

LICENSE PLAN NO. 2227

Approved by Department of Environmental Protection  
of Massachusetts


COMMISSIONER

SECTION CHIEF


JAN - 5 1990

034-50-50-200





**SECTION 1-1**  
**SHALLOW SEAWALL REPAIR**



**NOTES:**

1. PEASTONE OVERLAY  
STA 1+00 TO STA 2+65±
2. CHINK WALL AS REQUIRED  
STA 1+00 TO STA 4+85±

**SECTION 2-2**

SHEET 2 OF 2

PLANS ACCOMPANYING THE PETITION OF  
TOWN OF HINGHAM  
TO REPAIR AND MAINTAIN EXISTING  
SEAWALL AND WALKWAY & SOLID FILL  
HINGHAM HARBOR  
COUNTY OF PLYMOUTH, MA  
OCTOBER 23, 1989  
NUCCI VINE ASSOCIATES, INC.


**LICENSE PLAN NO. 2227**

Approved by Department of Environmental Protection


Date: **JAN - 5 1990**

031-50-50-200 09-297

- 1) REPAIR OF 244 FT. OF GRANITE BULKHEAD.
- 2) RECONSTRUCTION OF 470 FT. OF GRANITE BULKHEAD.
- 3) CONSTRUCTION OF 36 FT. OF GRANITE BULKHEAD TO  
PLACE EXISTING REVETMENT.
- 4) RELOCATION OF PRIOR AUTHORIZED GANGWAY AND FLOAT.



LOCUS MAP



SITE PLAN

PLANS ACCOMPANYING PETITION OF:  
HINGHAM HARBOR DEVELOPMENT COMMITTEE  
RECONSTRUCTION OF BULKHEADS  
AT 4 SUMMER STREET HINGHAM, MA


LICENSE PLAN NO. 8777

Approved by Department of Environmental Protection  
of Massachusetts


APR 10 2001

*James C. Davis*  
*James C. Davis*  
*James C. Davis*

034-51-1-100 034-51-1-200 034-51-3-100



034-663-100  
034-661-200  
034-661-100



NOTES:  
*[Signature]*  
 12/19/00  
 SURVEY PERFORMED BY NUCCI  
 & ASSOCIATES, INC. JULY 2000.


### WHARF PLAN

**LICENSE PLAN NO. 8777**  
 Approved by Department of Environmental Protection  
 Date: **APR 10 2001**

**DATUM:**  
 MTL=11.5  
 MHW=9.5  
 MLW=0.0









PROPOSED SECTION 1  
STATION 0+00 TO 1+09  
SCALE: 1"=4'


LICENSE PLAN NO. 8777  
Approved by Department of Environmental Protection  
Date APR 10 2001




PROPOSED SECTION 2  
STATION 1+09 TO 1+45  
SCALE: 1"=4'



*Peter J. Williams*  
12/1/00  
SHEET 3 OF 8




PROPOSED SECTION 3  
STATION 1+45 TO 2+15  
SCALE: 1"=4'





PROPOSED SECTION 4  
STATION 2+15 TO 2+80  
SCALE: 1"=4'

LICENSE PLAN NO. 8777  
Approved by Department of Environmental Protection  
Date: APR 10 2001



*Peter J. Williams*  
12/2/00

034-51-1-100  
034-51-1-200  
034-51-1-300  
4 of 8



*Peter J. Williams*  
14/19/00

PROPOSED SECTION 5  
STATION 2+80 TO 4+20  
SCALE: 1"=4'

**LICENSE PLAN NO. 8777**  
Approved by Department of Environmental Protection  
Date: APR 10 2001




034-51-1-200 034-51-3-100



PROPOSED SECTION 6  
STATION 4+20 TO 4+40


SCALE: 1"=4'



**LICENSE PLAN NO. 8777**

Approved by Department of Environmental Protection


Date APR 10 2001



12/19/00 SHEET 6 OF 8


034-51-1-100 034-51-1-100





0315-10






# HINGHAM HARBOR

EXTREME LOW WATER

MLW



LOCUS PLAN

STEAMBOAT WHARF

LIC. NO.  
407

LIC. NO.  
641

BARNES WHARF

## NOTES:

1. DATUM : MLW = 0.0; MHW = 9.5; ELW = -1.0
2. TOWN OF HINGHAM OWNS STEAMBOAT AND BARNES WHARVES AND LAND BETWEEN TO RECEIVE REPAIRS.
3. ALL REPAIRS TO EXISTING WALL TO BE INKIND. SHALLOW REPAIRS (SECTION 2-2) TO BE PERFORMED ALONG LENGTH OF WALL, EXCEPT WITHIN AREAS DESIGNATED AS REMOVE AND RESET (SECTION 1-1).
4. NO DREDGING OR FILLING PROPOSED.

EXISTING SEAWALL

REMOVE & RESET  
REPAIRS (TYP)

LIMIT OF UNLICENSED STRUCTURE  
SEAWALL REPAIRS (450 L.F.)

MHW

2

2

8' WALKWAY

EXISTING  
SIDEWALK

BRUSH

BRUSH

0 40 80  
SCALE IN FEET

SITE PLAN

SUMMER STREET

SHEET 1 OF 2

LICENSE PLAN NO. 2241

Approved by Department of Environmental Protection  
of Massachusetts

COMMISSIONER


CHIEF DIRECTOR

SECTION CHIEF


DEC 27 1989 DATE

PLANS ACCOMPANYING THE PETITION OF  
TOWN OF HINGHAM  
TO REPAIR AND MAINTAIN  
SEAWALL AND WALKWAY  
HINGHAM HARBOR  
COUNTY OF PLYMOUTH, MA  
SEPTEMBER 1989  
NUCCI VINE ASSOCIATES, INC.

034-51-5B-200




SECTION 1-1  
REMOVE & RESET SEAWALL REPAIR



SECTION 2-2  
SHALLOW SEAWALL REPAIR

0 2' 4'  
SCALE



*David B. Vine*

SHEET 2 OF 2

PLANS ACCOMPANYING THE PETITION OF  
TOWN OF HINGHAM  
TO REPAIR AND MAINTAIN  
SEAWALL AND WALKWAY  
HINGHAM HARBOR  
COUNTY OF PLYMOUTH, MA  
SEPTEMBER 1989  
NUCCI VINE ASSOCIATES, INC

**LICENSE PLAN NO. 2211**

Approved by Department of Environmental Protection

Date: DEC 27 1989

034-51-5B-200

TOWN: HINGHAM

SOURCE: U.S. - ARMY CORPS OF ENGINEERS

LOCATION: U.S.A.C.E. - NEW ENGLAND DISTRICT, CONCORD, MA

DATE OF RESEARCH: AUGUST 2006

BCE Structure No	Document No	Permit/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
034-017-000-099-100	034-017-000-099-100-COE1A	NED00 86-239	MA DPW	HINGHAM	JUL 1986	PROPOSED SHORE PROTECTION, CONCRETE SEAWALL, STONE GROIN, SAND FILL, HINGHAM BAY	1	INTERSECTION OF PARKER DRIVEWAY AND CUSHING AVE	SHORE PROTECTION, CONCRETE SEAWALL, INCLUDES GROIN EAST END OF STRUCTURE
034-017-000-100-100	034-017-000-100-100-COE1A	2545	MA DPW	HINGHAM	JUL 1986	PROPOSED SHORE PROTECTION, CONCRETE SEAWALL, STONE GROIN, SAND FILL, HINGHAM BAY	1	INTERSECTION OF PARKER DRIVEWAY AND CUSHING AVE	SHORE PROTECTION, CONCRETE SEAWALL, INCLUDES GROIN EAST END OF STRUCTURE
034-050-000-050-100	034-050-000-050-100-COE1A	MA-HULL-86-376	TOWN	HINGHAM	JUN 1986	PROPOSED RECONSTRUCTION LAUNCH RAMP	2	OFF OTIS STREET, EAST OF IRON HORSE PARK	BOAT RAMP REPAIR
034-050-000-050-100	034-050-000-050-100-COE2A	189400032	TOWN	HINGHAM	MAR 1994	BOAT RAMP REPAIRS	2	OFF OTIS STREET, EAST OF IRON HORSE PARK	
034-050-000-051-100	034-050-000-051-100-COE1A	200100339	TOWN	HINGHAM	FEB 2001	HINGHAM BEACH BANK STABILIZATION	4	OFF OTIS STREET, ADJACENT TO THE BATH HOUSE	NEW RIP RAP
034-051-001-000-100	034-051-001-000-100-COE1A	200302469	TOWN	HINGHAM	SEPT 2000	WHITNEY WHARF, HINGHAM HARBOR	9	OTIS STREET, HINGHAM HARBOR	SEAWALL REPAIRS
034-051-001-000-200	034-051-001-000-200-COE1A	200302469	TOWN	HINGHAM	SEPT 2000	WHITNEY WHARF, HINGHAM HARBOR	9	OTIS STREET, HINGHAM HARBOR	SEAWALL REPAIRS
034-051-003-000-100	034-051-003-000-100-COE1A	200302469	TOWN	HINGHAM	SEPT 2000	WHITNEY WHARF, HINGHAM HARBOR	9	OTIS STREET, HINGHAM HARBOR	SEAWALL REPAIRS




USACE

NEED 66-239

034-017-099-000-100

034-017-100-000-100



NOTE:  
ELEVATIONS ARE IN FEET  
AND TENTHS AND REFER  
TO THE PLANE OF MEAN  
LOW WATER.  
LOCATION OF PROPOSED  
WORK SHOWN IN RED.




PROFILE OF GROIN  
SCALE 1" = 20'

EXISTING ROADWAY  
EXISTING STONE MOUND TO  
BE REMOVED AND REBUILT IN  
PROPOSED STONE GROIN  
BACKFILL BEHIND WALL WITH  
SUITABLE EXCAVATED MATERIAL  
AND GRAVEL BORROW



TYPICAL SECTION  
SCALE 1" = 8'



SECTION A-A  
SCALE 1" = 10'


PROPOSED SHORE PROTECTION  
SEA WALL - STONE GROIN - SAND FILL  
HINGHAM BAY  
HINGHAM


APPLICATION BY  
DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS  
DIVISION OF WATERWAYS  
AUGUST 1966  
*John C. Hennessey*  
DEPUTY CHIEF ENGINEER FOR WATERWAYS

ACC. NO. 04558





USACE # MA-HW-86-276  
 034-050-000-050-100






**SECTION A-A**



**SECTION B-B**



**PLAN OF RECONSTRUCTED RAMP**

PURPOSE: TO REPLACE & MAINTAIN  
A TOWN  
LAUNCH RAMP.

DATUM: MLW = 0.0  
ADJACENT PROPERTY OWNERS  
THOMAS F. KENDE III  
TRUSTEES OF HINGHAM BATHING  
BEACH

**BOAT LAUNCH RAMP**

NOT TO SCALE

TOWN OF HINGHAM  
HINGHAM, MA.


**PROPOSED RECONSTRUCTED  
LAUNCH RAMP**

IN: HINGHAM HARBOR  
AT: HINGHAM

COUNTY OF: PLYMOUTH, STATE: MA.  
APPLICATION BY: TOWN OF HINGHAM  
REV: K-4-DY  
SHEET 3 OF 3 DATE 10-21-85



USACE 1994 000 32  
034-050-000-050-100



**NOTES:**



1. PROJECT TO EXCAVATE APPROX. 300 CUBIC YARDS SOIL BY LAND OPERATED CLAM SHELL DRAG LINE, DISPOSING MATERIAL AT TOWN LANDFILL, ALL BELOW MHW & HTL.
2. DATUM MLW=0.0, MHW=9.0, HIGH TIDE LEVEL(HTL)=11.0
3. BURIED STRUCTURE & ANCHORAGE LIMIT PER RECONSTRUCTION OF BOAT RAMP DEQE LIC. No. 1549 (1986) & NO 1709 (1987)

**SITE PLAN**

BOAT RAMP REPAIRS  
HINGHAM HARBOR  
HINGHAM MASSACHUSETTS  
PLYMOUTH COUNTY

APPLICATION BY:  
TOWN OF HINGHAM  
SHEET 2 OF 3 REV: 3/18/94






#### SECTIONS

BOAT RAMP REPAIRS  
HINGHAM HARBOR  
HINGHAM MASSACHUSETTS  
PLYMOUTH COUNTY

APPLICATION BY:  
TOWN OF HINGHAM  
SHEET 3 OF 3 12/10/93

USACE 200100339  
034-050-000-051-100



SCALE: 1" = 2083'

DATUM: MLW = 0.0  
MHW = 9.5  
AHTL = 12.0

# LOCUS PLAN HINGHAM BEACH BANK STABILIZATION


AT: OTIS STREET HINGHAM  
COUNTY: PLYMOUTH

APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA

DATE: FEB. 2001 SHEET 1 OF 4




TOWN BEACH




AT: OTIS STREET HINGHAM  
COUNTY: PLYMOUTH  
APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA  
DATE: FEB. 2001 SHEET 2 OF 4

SITE PLAN  
HINGHAM BEACH  
BANK STABILIZATION


DATUM:  
MLW = 0.0  
MHW = 9.5  
AHTL = 12.0




NOT A CONTRACT DOCUMENT. FOR INFORMATION PURPOSES ONLY.



<p><b>TYPICAL SECTION</b></p> <p><b>HINGHAM BEACH</b></p> <p><b>BANK STABILIZATION</b></p>		<p>AT: OTIS STREET HINGHAM</p> <p>COUNTY: PLYMOUTH</p> <p>APPLICATION BY:</p> <p>TOWN OF HINGHAM</p> <p>210 CENTRAL STREET</p> <p>HINGHAM, MA</p>
<p>DATUM:</p> <p>MLW = 0.0</p> <p>MHW = 9.5</p> <p>AHTL = 12.0</p>		<p>NUCCI VINE ASSOCIATES, INC. HINGHAM, MASSACHUSETTS</p>



**TYPICAL SECTION**  
SCALE 1" = 3'



*[Signature]*  
4/20/01  
0 10 20  
SCALE IN FEET

DATUM: MLW = 0.0  
MHW = 9.5  
AHTL = 12.0

**TYPICAL SECTION**  
  
**HINGHAM BEACH  
BANK STABILIZATION**



AT: OTIS STREET HINGHAM  
COUNTY: PLYMOUTH

APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA


DATE: APR. 2001 SHEET 4 OF 4




USACE 200302469  
 034-051-001-000-200  
 034-051-001-000-700  
 034-051-003-000-100




<p>DATUM: MLW = 0.0          MHW = 9.5          HTL = 11.5</p>	<p>WHARF PLAN</p>	<p>AT: WHITNEY WHARF, HINGHAM HBR.          COUNTY: PLYMOUTH          APPLICATION BY:          TOWN OF HINGHAM          210 CENTRAL STREET          HINGHAM, MA.          DATE: 9/29/00 SHEET 2 OF 10</p>
--	-------------------	---



DATE: 9/29/00 SHT 2A OF 10



PROPOSED SECTION 1  
STATION 0+00 TO 1+09  
SCALE: 1"=4'



*Peter J. Williams*



DATUM: MLW = 0.0  
MHW = 9.5  
HTL = 11.5


SECTION 1

AT: WHITNEY WHARF, HINGHAM HBR.  
COUNTY: PLYMOUTH


APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA.

DATE: SEPT. 2000 SHEET 3 OF 10





PROPOSED SECTION 2  
STATION 1+09 TO 1+45  
SCALE: 1"=4'




DATUM: MLW = 0.0  
MHW = 9.5  
HTL = 11.5

SECTION 2


AT: WHITNEY WHARF, HINGHAM HBR.  
COUNTY: PLYMOUTH

APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA.

DATE: SEPT. 2000 SHEET 4 OF 10



PROPOSED SECTION 3  
STATION 1+45 TO 2+15  
SCALE: 1"=4'



*Peter J. Williams*



DATUM: MLW = 0.0  
MHW = 9.5  
HTL = 11.5

SECTION 3


AT: WHITNEY WHARF, HINGHAM HBR.  
COUNTY: PLYMOUTH

APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA.

DATE: SEPT. 2000 SHEET 5 OF 10







PROPOSED SECTION 5  
STATION 2+80 TO 4+20  
SCALE: 1"=4'





DATUM: MLW = 0.0  
MHW = 9.5  
HTL = 11.5

## SECTION 5

AT: WHITNEY WHARF, HINGHAM HBR.  
COUNTY: PLYMOUTH

APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA.

DATE: 9/29/00 SHEET 7 OF 10




PROPOSED SECTION 6  
STATION 4+20 TO 4+40  
SCALE: 1"=4'

DATUM: MLW = 0.0  
MHW = 9.5  
HTL = 11.5


# SECTION 6

AT: WHITNEY WHARF, HINGHAM HBR.  
COUNTY: PLYMOUTH  
APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA.

DATE: 9/29/00 SHEET 8 OF 10



PROPOSED SECTION 7  
STATION 4+40 TO 5+35  
SCALE: 1"=4'



DATUM: MLW = 0.0  
MHW = 9.5  
HTL = 11.5


SECTION 7

AT: WHITNEY WHARF, HINGHAM HBR.  
COUNTY: PLYMOUTH


APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA.

DATE: SEPT. 2000 SHEET 9 OF 10





PROPOSED SECTION 8  
STATION 5+35 TO 7+45  
SCALE: 1"=4'



DATUM: MLW = 0.0  
MHW = 9.5  
HTL = 11.5

SECTION 8

AT: WHITNEY WHARF, HINGHAM HBR.  
COUNTY: PLYMOUTH

APPLICATION BY:  
TOWN OF HINGHAM  
210 CENTRAL STREET  
HINGHAM, MA.

DATE: SEPT. 2000 SHEET 10 of 10

