


*Massachusetts Coastal Infrastructure
Inventory and Assessment Project
Massachusetts Department of Conservation and Recreation
Office of Waterways*

North Shore - North

Manchester
Beverly
Salem



July 6, 2009

Prepared for:

**Massachusetts Department of
Conservation and Recreation
Hingham, Massachusetts**

Presented by:

**Bourne Consulting Engineering
Franklin, Massachusetts**

In Association With:

Waterfront Engineers

North Shore - North

TABLE OF CONTENTS

Section I – Coastal Hazards Infrastructure and Assessment Program

INTRODUCTION

PURPOSE

DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES

DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS

Section II – Manchester

Part A - Community Findings

- COMMUNITY DESCRIPTION
- STRUCTURE INVENTORY
- SUMMARY OF FINDINGS

Part B - Structure Assessment Reports

Part C - Structure Photographs

Part D - Structure Documents

- TOWN DOCUMENT LIST
 - Document Table
- MA DCR – DOCUMENT LIST
 - Document Table
- MA DEP – CH 91 DOCUMENT LIST
 - Document Table
 - Copies of License Documents
- USACE – PERMIT DOCUMENT LIST
 - Document Table
 - Copies of Permit Documents

North Shore - North

Section III – Beverly

Part A - Community Findings

- COMMUNITY DESCRIPTION
- STRUCTURE INVENTORY
- SUMMARY OF FINDINGS

Part B - Structure Assessment Reports

Part C - Structure Photographs

Part D - Structure Documents

- CITY DOCUMENT LIST
 - Document Table
- MA DCR – DOCUMENT LIST
 - Document Table
- MA DEP – CH 91 DOCUMENT LIST
 - Document Table
 - Copies of License Documents
- USACE – PERMIT DOCUMENT LIST
 - Document Table
 - Copies of Permit Documents

Section IV – Salem

Part A - Community Findings

- COMMUNITY DESCRIPTION
- STRUCTURE INVENTORY
- SUMMARY OF FINDINGS

MASSACHUSETTS COASTAL INFRASTRUCTURE INVENTORY AND ASSESSMENT PROJECT

North Shore - North

Part B - Structure Assessment Reports

Part C - Structure Photographs

Part D - Structure Documents

- CITY DOCUMENT LIST

- Document Table

- MA DCR – DOCUMENT LIST

- Document Table

- MA DEP – CH 91 DOCUMENT LIST

- Document Table
- Copies of License Documents

- USACE – PERMIT DOCUMENT LIST

- Document Table
- Copies of Permit Documents

Section I

Coastal Hazards Infrastructure and Assessment Program

INTRODUCTION

PURPOSE

DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES

DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS

Massachusetts Coastal Infrastructure Inventory and Assessment Project Coastal Hazards Commission

Section I – Coastal Hazards Infrastructure and Assessment Program

INTRODUCTION

The Project and Client

The Commonwealth of Massachusetts has initiated a Coastal Hazards Commission (CHC) to identify the vulnerability of the state to coastal hazards. As one of five working groups working under the CHC, the 20-Yr Infrastructure Plan was to establish a prioritization for the repair of coastal structures. The focus areas of the Working Group include:

- Publicly owned infrastructure
- Infrastructure for which State is responsible
- Inventory of public hazards infrastructure
- Evaluation on conditions
- Development for a prioritization of work
- Estimation of capital and maintenance costs

The 20-Yr Infrastructure Working Group is led by Representative Frank Hynes with CZM as the lead State Agency overseeing the management of the project. The Massachusetts coastline has been broken up into 4 major regions consisting of the North Shore, Boston, South Coast, and the Cape and Islands. The South Shore (the Towns of Hull, Cohasset, Seekonk, Hingham, Plymouth, Kingston, Scituate and Duxbury) was previously evaluated by Bourne Consulting Engineering as a demonstration project in 2006.

Consultant Team

The consultant team that performed the demonstration project was led by Bourne Consulting Engineering (**BCE**) of Franklin, MA who was responsible for overall project management, specified areas of field assessments, and research. Assisting **BCE** was Applied Coastal Research and Engineering Inc. of Mashpee, MA, Childs Engineering Corporation, of Medfield, MA., and Waterfront Engineer LLC of Stratham, NH.

PURPOSE

Study Purpose

CZM seeks to identify the capacity of Massachusetts coastal structures to resist major coastal storms and prevent storm damage. In working toward this goal, CZM has initiated a program to perform an assessment of Commonwealth owned and/or maintained coastal structures. The first phase of this program was the performance of a demonstration project for coastal structures located on the South Shore. The demonstration project identified existing structures, their general conditions, ability to provide coastal protection and the probable cost for repairs. The information collected and developed has been incorporated into the MassGIS system to allow use for developing a 20 Year Coastal Infrastructure Plan.

The demonstration project served as a basis for the current statewide inventory assessment of all Commonwealth coastal structures and the needs for their maintenance and/or repair.

Goals of Study

The goals of the Massachusetts Coastal Infrastructure Inventory and Assessment Project include:

- To identify all the coastal structures the state either owns or has responsibility to maintain for the 4 regions included within the study
- Of the structures identified, determine the structure location and characteristics, the structure condition relative to providing coastal protection and the structure importance in relation to what it is protecting.
- To the degree possible, identify the structure elevation and the FIRM mapping flood elevation and category.
- To the degree possible, identify structure owner and available documents from local, state and federal agencies.
- To establish an estimated cost to rehabilitate the coastal structures to provide the level of project established in the structure's original design.
- Provide the information in a format compatible for incorporation into the MassGIS system

Limit of Study

Due to the time constraints and the amount of effort necessary to collect, process and compile the information, the following are identified as limitations of the information presented:

- All property ownership was taken as presumed. No legal investigation of ownership was performed during the project. Property ownership is based on town assessor maps. Where structures were located outshore of assessor map defined property lines, it was assumed to be Town land unless other information indicated otherwise. Where structures were located outshore of Mean Low Water, property is assumed to be State owned.
- The structure ownership was based on assessor maps and research at the local, state and federal levels. Where there was indication of public work on a structure on Town land or on private property, the structure was presumed to be Town owned. Where the structure was on state property, the structure was presumed to be state owned. Where ownership of the structure was not clear but was located on private property, the structure ownership was defined as unknown.
- The study included town and state owned structures as it was assumed that most town owned structures received state funding at some level for construction and/or maintenance.
 - Structures that were determined to be private were not included.
 - Undocumented structures considered to be on private land, but having the potential to have been publicly built and/or maintained, were identified as having an "unknown ownership".
- The prioritizing of structures was based primarily on risk to general infrastructure and density of housing. Infrastructure included was buildings. The study did not consider all infrastructure issues including:
 - No consideration on utility impacts – water, electrical, sewer, gas
 - No consideration of roadway and bridge protection
 - Evacuation routes were not considered within the investigation
 - Location of Emergency Shelters were not included in priority assessments
- Research was performed at the local, state and federal levels. The local research was limited to location and documenting available coastal structure contract drawings. Research at DCR was restricted to available historic construction plans for coastal structures at the MA-DCR Waterways office in Hingham, MA, and MA-DCR Division of Urban Parks and Recreation in

Boston, MA. No investigation of state archives was performed. Research at MA DEP Chapter 91 and USACE was limited to recorded permits and licenses found in their files. No investigation was performed at the Registry of Deeds.

DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES

The specific attributes that would be incorporated into the MassGIS system were developed based on the scope of work and the goals to be achieved. The following was established to standardize the data collection and presentation and to allow total flexibility for sorting by attributes in the final GIS database. The attributes identified below were input into a MS Access database which was used to manage the data from all eight communities within a single file.

Database Attributes

- Attribute Descriptions/Definitions

Structure Number: A unique structure number was given to each coastal structure. The number was based on existing numbering systems that include the State Department of Environmental Protection community number followed by the local community assessor's parcel numbering system. The last three digits of the number represent the structure within the parcel. Where structures extend over several parcels, the structure is referenced to a parcel that is approximately in the center of the structure. Where Town assessor's references include letters, those are also included within the structure number. Some communities have block numbering within their numbering system and these are included. Communities without block numbering still have the block numbering included but these are illustrated as all zeros for that specific segment.

Structures that are on Town property, which would otherwise not have a parcel number, are referenced to a parcel that is in the immediate vicinity of the coastal structure.

On this basis, the following is the general numbering convention:

CCC-MMM-BBB-PPP-SSS

Where:	CCC	DEP Community Number
	MMM	Community Map Number
	BBB	Block Number (000 if no block numbering system)
	PPP	Community Parcel Number
	SSS	Structure Number

Property Ownership: All property ownership was on a "presumed" basis as no legal verification of ownership was performed. The ownership of the property was classified under four basic areas which were private ownership (Private), Town ownership (Local), Commonwealth of Massachusetts ownership (State), federal government ownership (Federal) or unknown. Property ownership was based on Town assessor's maps. Where the location was located above Mean Low Water, and not within a defined parcel, the property ownership was presumed to be the Town unless documentation was found to indicate otherwise. Where a structure was located offshore of Mean Low Water, the property ownership was presumed to be federal.

Structure Ownership: The ownership of all structures is presumed as no verification of ownership was performed. Ownership of the structure was determined by research into historic state and federal

permits and the entity indicated on the permits as the applicant. Where no other information was found, the following was utilized:

- Structures located on private land but appearing to be significant structures were identified as owned by the Town or as "Unknown". Unknown was used where there was a question of local or private ownership.
- Structures on Town property were assumed to be owned by the Town
- Structures that were located off-shore were presumed to be federally owned
- Structures that were identified as being privately owned were eliminated from the database

Basis of Ownership: The basis of structure ownership was provided to give rationale to the structure ownership and identified the research resource that identified the ownership or the methodology otherwise used. The responses utilized were limited to the following:

- DPW – DPW Employee Interview
- DCR - Contract Drawings
- DEP – Ch 91 License
- USACE – Permits
- Property Ownership
- Offshore Structure

Structure Owner's Name: Ownerships names reflect the presumed owner of publicly owned structures. As this was for public structures only, the ownership was restricted to the community name, the state agency or the federal agency.

Earliest Structure Record: The year of the oldest document located for the structure. The information is determined from the document research performed on the structure from local, state and federal agencies. If no documents could be found than this entry is denoted as "Unknown". Where documentation of the structure could be found, the date from the oldest document was utilized.

Primary Structure / Secondary Structure: Many of the coastal structures consisted of combined structures which were rated separately. It was typically found that one structure was significantly more predominant (Ex. Bulkhead/Seawall) and was therefore identified as the Primary Structure while a smaller structure might exist in front (ex. Revetment) of it. The type, height and material of each structure are identified separately. The condition of each structure was based on the Primary Structure. Where there was no secondary structure, the fields were left blank.

Structure Type: The structure type was categorized into five basic coastal structure categories which were Bulkhead/Seawall, Revetment, Coastal Beach, Coastal Dune, and Jetty/Groin.

Structure Material: The identification of the coastal structure's material of construction was performed and represents the primary material. Stone structures consisted of both mortared and non-mortared conditions.

Structure Height: Each type of structure was categorized by its visible height in feet which was broken into four specific ranges which are:

< 5 feet 5 to 10 feet 10 to 15 feet >15 feet

Structure Condition: A preliminary assessment of the condition for each structure was performed by the field teams. This was by visual observation only and no detailed investigation was performed. The condition assessments were based on a predefined five level rating system that ranged from Rating A for Excellent Condition to Rating F for Critical Condition. A detailed listing of the conditions and their definitions can be seen in Exhibit A.

Priority Rating: In order to account for the need for protection at any one site, a five level priority rating system was established. This allowed for consideration of public infrastructure protection, density of residential housing for development of structure overall importance for coastal protection. The ratings range from Level 1 for no infrastructure or residence protection to Level 5 for critical inshore infrastructure protection and/or high density residential. The detailed listing and definitions for the priority categories can be seen in Exhibit B.

Structure Repair / Reconstruction Cost: A preliminary estimation of construction costs to maintain or repair structures was made based on the preliminary field assessment of the structures. A Repair Cost Matrix was developed based on structure type, condition, height and material and can be seen in Exhibit C. Once each structure's type, height, and material classifications were determined, the cost per foot for the structure was determine from the Repair Cost Matrix and multiplied by the length of the structure to obtain the estimated repair/restoration cost. The cost matrix repair costs include a 20 percent construction cost contingency as well as 10 percent costs for engineering and permitting.

Structure Length: The length of each structure is provided and utilized in the development of the repair/reconstruction costs. The lengths are given to the nearest foot and taken as the linear distance along the structure, as determined by the GPS location, which takes into account structure angles and curvature.

Structure Elevation: The elevation of structures was determined in feet from existing information where available. The datum used is NAVD 88 and elevations are to the nearest foot. From a previous study much of the south shore coastal structures had elevations defined based on LIDAR mapping data. Where available structure documentation with elevations was found, in areas with no LIDAR data, the information was included within the structure information. Where there was no LIDAR information or existing documentation, the item has been left blank.

LIDAR (Light Detection and Ranging) is technology that is currently being used for high-resolution topographic mapping by mounting a LIDAR sensor, integrated with Global Positioning System (GPS) and inertial measurement unit (IMU) technology, to the bottom of aircraft and measuring the pulse return rate to determine surface elevations.

FEMA Zone and Elevation: For each structure the FEMA Flood Insurance Rate Maps (FIRM) were researched for their Flood Zone designation and their Base Flood Elevation from the most recent FIRM maps for the specific Town. The elevations are provided in feet on the same datum as the FIRM maps (NGVD) with no adjustments or conversions.

Structure Comments: The engineering team provided a brief description and comment on the structure at the time of the field assessments which is provided in support of the condition rating that was given for the structure.

Pictures: At the time of the field assessments, digital photographs were taken to provide a general overview of the structure. The number of pictures was limited to a maximum of six. The first photograph for each structure is shown on the Structure Assessment Form. The list of all photographs is provided on the form.

Town Documents: Town documents represent the structure information that could be found in the Town's DPW/Engineering Department records. Where particular records could be found, a table of document information was developed and included within the database with limited descriptions.

MA - DCR Documents: MA-DCR documents represent the structure information that could be found within DCR – Waterways office in Hingham. Where particular records could be found, a table of document information was developed and included within the database with limited descriptions.

MA - DEP Chp. 91 Licenses: MA-DEP Chapter 91 license documents represent the structure information that could be found within MA-DEP Chp 91 records in Boston. Where particular records could be found, they were scanned as pdf files and attached to the structure through the GIS database information. In addition, a table of license document information was developed and included within the database with limited descriptions.

USACE Permits: USACE Permits represent the structure information that could be found within the Army Corp of Engineers regulatory office in Concord, MA. Where particular records could be found, they were scanned as pdf files and attached to the structure through the GIS database information. In addition, a table of license document information was developed and included within the database with limited descriptions.

DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS

A matrix to be used within the database has been developed to assess likely rehabilitation/repair costs to restore the coastal structures to their original design condition. No attempt was made to assess the level of exposure and associated level of protection that might be required to meet current design standards for these structures. These costs are only an estimation to bring these structures back to their original design intent based on 2006 construction costs.

The development of the cost matrix is based on the following:

Structure Condition Ratings – The condition of the coastal structures was determined in the field by the survey crew which was led by an engineer with waterfront structure assessment and design experience. The definitions of the rating criteria utilized for the assessments are presented elsewhere.

The cost implications for each rating condition are as follows:

- **A Rating** Structures not requiring any maintenance, repair or rehabilitation cost and would not be expected to experience damage if subject to a major coastal storm event
- **B Rating** Structures requiring limited or no repair and would be expected to experience only minor damage if subject to a major coastal storm event. The value of these maintenance costs is assumed to be 10 percent of the construction cost.
- **C Rating** Structures requiring moderate to significant level of repair or reconstruction and would be expected to experience significant damage if subject to a major coastal storm event. The structure is presumed to be effective under a major storm event. The value of the repair costs is assumed to be 50 percent of the construction cost.
- **D Rating** Structures requiring significant level of rehabilitation or total reconstruction and would be expected to experience significant damage or possibly fail if subject to a major coastal storm event. The value of the repair costs is assumed to be 100 percent of the construction cost.

- **F Rating** Structures requiring complete reconstruction and would expect to provide little or no protection from a major coastal storm event. The value of the repair costs is assumed to be 100 percent of the construction cost plus a cost for removal/disposal of the original structure.

Height of Structure – Height of a structure is a major factor in the structure cost and therefore was identified as a significant factor in assessing rehabilitation/repair construction costs. The structures were broken down into four major categories which were:

< 5'	Structures that were less than five feet in height
5'-10'	Structures five to 10 feet in height
10'-15'	Structures over 10 feet to 15 feet in height
> 15'	Structures greater than 15 feet in height – assumed 20 feet typical

Length of Structure – Length is based on field GPS location with measurements rounded to the nearest foot.

Bulkhead / Seawall Structures – These structures are assumed to be constructed out of concrete, steel, stone or wood with each having its own criteria for establishing costs. For each structure type the following was assumed:

- **Concrete Seawalls** – These walls were assumed to be gravity structures with the volume of concrete used based on the bottom width being one-half of the structure height. Costs of construction were based on a per cubic yard estimate that varied from \$350 to \$630 per cubic yard depending on the structure height. Values for excavation and demolition of existing structure were also included.
- **Stone Seawalls** – These walls were treated the same as concrete seawalls and assumed to be gravity structures with the volume of the structure based on the bottom width being one-half of the structure height. Costs of construction were based on a per cubic yard estimate that varied from \$350 to \$630 per cubic yard depending on the structure height. Values for excavation and demolition of existing structure were also included.
- **Steel Bulkheads** – Steel bulkheads were presumed to be constructed with steel sheet piling. Tie back systems were presumed for structures 10 feet or greater in height. Shorter walls were assumed to have a cantilever design. The total depth of sheeting was presumed to be two times the exposed height. The cost for construction varied from \$40 per square foot to \$60 per square foot plus the cost of excavation and demolition.
- **Timber Bulkheads** – Timber bulkheads were presumed to be constructed with timber piles at eight foot on center, horizontal wales and vertical four inch sheathing. The unit costs for installed materials used were \$1,500 per pile and \$7.50 per bfm.

Revetment Structures – Revetment structures were presumed to be constructed of dry placed (no concrete) stone with a two on one slope and a horizontal toe and crown equal to the thickness layer established for each height condition. The total thickness of the revetment layers varied from six to ten feet with the cost of armor and under-layer stone assumed to be \$50 per ton and the crushed stone base to be \$15 per ton.

**MASSACHUSETTS COASTAL INFRASTRUCTURE
INVENTORY AND ASSESSMENT DEMONSTRATION PROJECT**

Groins and Jetties – Groins and jetties were assumed to be the same materials and construction as the revetment structures but would have two sides and therefore double the quantities.

Coastal Beaches – Costs for restoration of Coastal beaches presumed the placement of beach renourishment sands at a 1-on-20 slope over the existing beach conditions. The cost for deposition of sand assumed relatively close source of material and utilized \$20 per cubic yard for the material installed.

Coastal Dunes – Restoration of coastal dunes assumed a cross section of renourished sand with a one-on-four slope on one side of a 25 foot width at the defined dune height. The cost for deposition of sand assumed relatively close source of material and utilized \$20 per cubic yard for the material installed.

Contingency – A contingency of 20 percent was added to all costs to reflect the unknowns associated with this level of rehabilitation/repair estimating.

Engineering and Regulatory Approvals – A ten percent increase to the cost matrix prices was assessed to represent the engineering design and regulatory approval requirements for the restoration of these structures.

EXHIBIT A

Structure Condition Table – 5 Level Rating System

Preliminary Condition Assessment		Definition Based Upon Perceived Immediacy of Action and Potential to Cause Damage if Not Corrected	Level of Action Required
A	Excellent	Like new condition. Structure expected to withstand major coastal storm without damage. Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm	None
B	Good	Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure	Minor
C	Fair	Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide additional material for full protection and extended life	Moderate
D	Poor	Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.	Major
F	Critical	Conditions of structure/landform may warrant emergency stabilization as failure may result in potential loss of property and/or life. Landform eroded, loss of integrity Structure exhibits critical levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure provides little or no protection from a major coastal storm. Actions taken to totally reconstruct structure to regain full capacity. Landform stability is severely compromised, rate of erosion/material loss may be increasing, and landform does not provide adequate protection from a major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.	Immediate

EXHIBIT B

Priority Rating System - 5 Level Rating System

Preliminary Priority Level Assessment		Level Based Upon Perceived Immediacy of Action and Presence of Potential Risk to Inshore Structures if Not Corrected	Level of Action Required
I	None	No Inshore Structures or Residential Dwelling Units Present	Long Term Planning Considerations
II	Low Priority	Inshore Structures Present with Limited potential for Significant Infrastructure Damage	Future Project Consideration
III	Moderate Priority	Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)	Consider for Active Project Improvement Listing
IV	High Priority	High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)	Consider for Next Project Construction Listing
V	Immediate / Highest Priority	Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Conditions of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)	Consider For Immediate Action Due to Public Safety and Welfare Issues

**MASSACHUSETTS COASTAL INFRASTRUCTURE
INVENTORY AND ASSESSMENT DEMONSTRATION PROJECT**

CZM SOUTH SHORE COASTAL INFRASTRUCTURE INVENTORY AND ASSESSMENT PROJECT

EXHIBIT C

September 14, 2006

REPAIR / REHABILITATION COSTING DATA

Cost per linear foot of structure

STRUCTURE TYPE	STRUCTURE MATERIALS	STRUCTURE HEIGHT	STRUCTURE CONDITION RATING				
			A	B	C	D	F
BULKHEAD/ SEAWALL	CONCRETE	Under 5 Feet	\$0	\$84	\$425	\$850	\$983
		5 To 10 Feet	\$0	\$152	\$759	\$1,518	\$1,782
		10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,970
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$4,752
	STEEL	Under 5 Feet	\$0	\$54	\$273	\$546	\$680
		5 To 10 Feet	\$0	\$165	\$825	\$1,650	\$1,848
		10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,772
		Over 15 Feet	\$0	\$343	\$1,716	\$3,432	\$3,795
	STONE	Under 5 Feet	\$0	\$84	\$425	\$850	\$983
		5 To 10 Feet	\$0	\$152	\$759	\$1,518	\$1,782
		10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,970
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$4,752
	WOOD	Under 5 Feet	\$0	\$86	\$431	\$862	\$994
		5 To 10 Feet	\$0	\$127	\$632	\$1,265	\$1,463
		10 To 15 Feet	\$0	\$181	\$804	\$1,608	\$1,872
		Over 15 Feet	\$0	\$202	\$1,008	\$2,017	\$2,380
COASTAL BEACH	SAND	Under 5 Feet	\$0	\$26	\$132	\$264	\$264
		5 To 10 Feet	\$0	\$127	\$634	\$1,267	\$1,267
		10 To 15 Feet	\$0	\$224	\$1,122	\$2,244	\$2,244
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$3,960
COASTAL DUNE	SAND	Under 5 Feet	\$0	\$18	\$93	\$186	\$186
		5 To 10 Feet	\$0	\$48	\$238	\$476	\$476
		10 To 15 Feet	\$0	\$79	\$395	\$790	\$790
		Over 15 Feet	\$0	\$132	\$660	\$1,320	\$1,320
REVTMENT	STONE	Under 5 Feet	\$0	\$66	\$333	\$664	\$730
		5 To 10 Feet	\$0	\$120	\$601	\$1,201	\$1,300
		10 To 15 Feet	\$0	\$157	\$781	\$1,564	\$1,696
		Over 15 Feet	\$0	\$247	\$1,234	\$2,468	\$2,666
GROIN	STONE	Under 5 Feet	\$0	\$132	\$664	\$1,328	\$1,460
		5 To 10 Feet	\$0	\$240	\$1,201	\$2,402	\$2,600
		10 To 15 Feet	\$0	\$314	\$1,564	\$3,128	\$3,392
		Over 15 Feet	\$0	\$494	\$2,468	\$4,937	\$5,333

NOTE: Repair / Rehabilitation Costs include 10% for engineering and regulatory approvals and 20 % construction contingency.

Section II

Manchester

Section II – Community Findings – Town of Manchester

COMMUNITY DESCRIPTION

The Town of Manchester consists of a land area of 7.84 square miles out of a total area of 18.25 square miles and had a population of 5228 in the 2000 census. The Town is located on the North Shore of Massachusetts and its location can be seen on this report's cover. The estimated length of shoreline that is directly exposed to open ocean waves is 12 miles with the remaining shoreline semi-protected by offshore structures or landforms. The Town is protected from major coastal storms by both natural and man-made shoreline structures that require maintenance to insure the long term protection of its coastline. The man-made and publicly owned structures that protect the Town were investigated for their ability to provide adequate protection from major coastal storms. Structures have been identified as publicly owned, including coastal dunes and beaches, based on evidence of investment of public funds made to create/enhance/maintain these structures. The assessment did not include floating or pile supported structures as they are assumed not to provide any significant coastal protection from major storm events.

STRUCTURE INVENTORY

Within the Town of Manchester, there were 21 structures which had public or unknown ownership which provide significant coastal protection. The location of the structures can be seen in Sheets 1 through Sheet 5 in Section II-B of this report. The structures were categorized by their type and by their structural condition based on a preliminary field assessment. The distribution of structures by type and condition can be seen in the following table:

STRUCTURE TYPE AND QUANTITY - Town of Manchester

Primary Structure (1)	Total Structures	Structure Condition Rating				F	Total Length
	A	B	C	D			
Bulkhead / Seawall	12		3	8	1		2490
Revetment	9		1	5	2	1	4585
Breakwater							
Groin / Jetty							
Coastal Dune							
Coastal Beach							
	21		4	13	3	1	7075

Within the above table, the total length of each type of structure is also provided. The structures are listed by the type which is providing the primary coastal protection. Many sites have multiple structure types at the same location (i.e. revetment in front of seawall). These secondary structures, although not identified within these tables, are included in the development of repair/rehabilitation costs.

The development of repair costs has been included by structure type and by condition. In the Town of Manchester's case there are a total of 21 structures which would require approximately \$ 9.3 million to bring all the coastal structures to "A" Rating. Most critical will be the structures in the "D" and "F" classifications as those are assumed to undergo some level of damage or failure during the next major coastal storm event. To reconstruct these structures, identified in the preliminary survey as being in poor condition, an estimated \$ 6.3 million would be required to upgrade the Town's coastal protection.

STRUCTURE REPAIR / RECONSTRUCTION COST - Town of Manchester

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Bulkhead / Seawall	12	\$	205,920	\$	1,978,112	\$	2,373,782
Revetment	9	\$	135,762	\$	724,522	\$786,621	\$ 6,987,097
Breakwater							\$ -
Groin / Jetty							\$ -
Coastal Dune							\$ -
Coastal Beach							\$ -
	21	\$ -	\$ 341,682	\$ 2,702,634	\$ 5,529,942	\$ 786,621	\$ 9,360,879

Based on the limited research within the scope of this project research, the presumed ownership of the structures was established on an initial basis and would be subject to more intense review in future tasks. Structures identified as being owned privately were excluded from further consideration. Although ownership of the land on which the structure was located was a factor, the structure ownership was treated as a separate issue from land ownership. For the Town of Manchester, the breakdown of structures by assumed ownership is as follows:

STRUCTURE OWNERSHIP / REPAIR COST - Town of Manchester

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Town Owned	21	\$	341,682	\$	2,702,634	\$ 5,529,942	\$ 786,621 \$ 9,360,879
Commonwealth of Massachusetts							\$ -
Federal Government Owned							\$ -
Unknown Ownership							\$ -
	21	\$ -	\$ 341,682	\$ 2,702,634	\$ 5,529,942	\$ 786,621	\$ 9,360,879

The identification of presumed ownership was not based on the investigation of legal documents but relied on property ownership and from construction and regulatory documents that were found. A more detailed investigation of legal documents and agreements would be required where structure ownership is disputed. A more detailed identification of structure type, length, condition and location can be found in Section II-B which contains Structure Assessment Reports for each individual structure found.

SUMMARY


The enclosed reports and associated documents reflects the Town of Manchester's coastal structure information that will eventually be input into a state-wide GIS database and will be accessible through MassGIS. This data, when compiled state-wide, will be critical in the development of both short term and long term planning for maintaining and improving Massachusetts coastal protection.

This database will also provide relatively quick access to identify available documentation for these structures as well as the ability to be updated as coastal structure improvements are made.

Section II - Manchester

Part B

Structure Assessment Reports



COASTAL STRUCTURE LOCATION PLAN


TOWN OF MANCHESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



SCALE: 1" = 150'-0"



Bourne Consulting Engineering
Professional Engineers
P.E. (NH) 03-000 P.E. (MA) 03-000



COASTAL STRUCTURE LOCATION PLAN



SCALE: 1" = 150'-0"



COASTAL STRUCTURE LOCATION PLAN

TOWN OF MANCHESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007


0 150



SCALE: 1" = 150'-0"




SHEET 3



COASTAL STRUCTURE LOCATION PLAN

TOWN OF MANCHESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



BCE *Bourne Consulting Engineering*
3 West Street
Providence, RI 02903
TEL (401) 533-0000 FAX (401) 533-0000



COASTAL STRUCTURE LOCATION PLAN

TOWN OF MANCHESTER
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150



SCALE: 1" = 150'-0"



Structure Assessment Form

Town: **Manchester**Structure ID: **039-001-000-095-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lobster Lane

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$72,072.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
120	25	V2	17
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone revetment at the top of beach, in fair condition. The toe is unravelled and there is a lawn area behind the revetment.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

039-001-000-095-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-006-000-029-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Black Beach

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$514,140.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
410	6	V2	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared stone rubble seawall along the road, in fair condition. The concrete toe is exposed in some areas. Some overtopping damage with recent pavement patching is apparent and some missing mortar causing backfill loss.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-006-000-029-100-PHO1A.JPG

039-006-000-029-100-PHO1B.JPG

039-006-000-029-100-PHO1C.JPG

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-007-000-026-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Black Beach

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$366,366.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
305	9	V2	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone revetment with significant overtopping crest damage, in poor condition, causing reduced protection for the roadway.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-007-000-026-100-PHO1A.JPG

Structure Documents:

Structure Assessment FormStructure ID: **039-007-000-026-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Black Beach

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

1973

Estimated Reconstruction/Repair Cost:

\$151,536.00

Length:

200

Top Elevation:

Feet **Feet NAVD 88**

FIRM Map Zone:

V2

FIRM Map Elevation:

14**Feet NGVD**

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Under 5 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Under 5 Feet

Structure Summary :

A cast in place concrete seawall with toe stone revetment adjacent to the road that may fail in a storm. There is apparent overtopping with the wall footing exposed. There is an under cut void up to 1.5 feet high at the west end.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-007-000-026-200-PHO2A.JPG

Structure Documents:

MA-DCR**March 1973****Proposed Shore****039-007-000-026-200-DCR2A**

Structure Assessment Form

Town: **Manchester**Structure ID: **039-007-000-026-300**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Black Beach

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$39,917.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
120		V2	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone rubble revetment adjacent of the road, in fair condition. There is overtopping damage with dislodged crest stones.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-007-000-026-300-PHO3A.JPG

Structure Documents:

Structure Assessment FormStructure ID: **039-008-000-003-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Ocean Street White Beach

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$189,750.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
125	9	V2	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

A mortared rubble stone seawall in poor condition. The upper wall failed in 2 locations, approximately 25 linear feet each. There are numerous horizontal cracks to indicate it likely to fail more significantly in another storm. It appears to be a relatively new wall.

*Condition***D***Rating***Poor***Level of Action***Major***Description*

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description***No Inshore Structures or Residential Dwelling Units Present****Structure Images:****039-008-000-003-100-PHO1A.JPG****Structure Documents:**

Structure Assessment Form

Town: **Manchester**Structure ID: **039-008-000-003-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Ocean Street White Beach

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$786,621.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
605	10	V2	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone revetment along top of beach with typical overtopping damage. The middle 1/3 of the revetment is totally destroyed and random stones are scattered. Anticipate future damage to the adjacent road unless it is rebuilt.

Condition

F

Rating

Critical

Level of Action

Immediate

Description

Conditions of structure/landform may warrant emergency stabilization as failure may result in potential loss of property and/or life. Landform eroded, loss of integrity. Structure exhibits critical levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure provides little or no protection from a major coastal storm. Actions taken to totally reconstruct structure to regain full capacity. Landform stability is severely compromised, rate of erosion/material loss may be increasing, and landform does not provide adequate protection from a major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-008-000-003-200-PHO2A.JPG

039-008-000-003-200-PHO2B.JPG

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-016-000-034-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Mascomono Park

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$363,370.00

Length: Top Elevation:

465

FIRM Map Zone:

A2

FIRM Map Elevation:

9

Feet

Feet NAVD 88

Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone rubble revetment in fair condition at the edge of the park . There is some erosion and crest stone movement.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description***No Inshore Structures or Residential Dwelling Units Present**

Structure Images:

039-016-000-034-100-PHO1A.JPG**039-016-000-034-100-PHO1B.JPG**

Structure Documents:

DEP**March 20, 20****Plan Accompanying****039-016-000-034-100-LIC1A**

Structure Assessment Form

Town: **Manchester**

Structure ID: 039-016-000-022-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Proctor Street

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$181,830.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
145		V2	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared rubble stone seawall with granite block cap adjacent to the street, in fair condition in a residential area. Some cap stones are loose. There is some mortar loss and one missing toe stone adjacent to the road.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-016-000-022-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-016-000-034-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Mascomono Park

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$413,820.00

Length:

330

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

A2

FIRM Map Elevation:

9

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A granite block wall in fair condition at park entrance road. There is differential stone movement, block settling, wall bulges and a slight offshore lean to the wall.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-016-000-034-200-PHO2A.JPG

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-016-000-036-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Mascomono Park

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$73,260.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
185		A2	9
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A dry rubble stone wall with granite block cap in satisfactory condition. It is adjacent to Beach Street with two areas of bituminous sidewalk with some slight subsidence.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-016-000-036-100-PHO1A.JPG

Structure Documents:

Structure Assessment FormStructure ID: **039-016-000-036-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Mascomono Park

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$199,267.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
255		A2	9
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

An armor stone revetment in overall fair condition. Some stones have settled locally and there is crest erosion. The armor is set on 1 inch crushed stone which is washing out. There is localized damage in the park lawn area.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

039-016-000-036-200-PHO2A.JPG

039-016-000-036-200-PHO2B.JPG

039-016-000-036-200-PHO2C.JPG

Structure Documents:

DEP

March 20, 20

Plan Accompanying

039-016-000-036-200-LIC2A

Structure Assessment Form

Structure ID: 039-017-000-024-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Singing Beach

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

1947

Estimated Reconstruction/Repair Cost:

\$4,973,826.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
2015	16	V2	18
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

A stone revetment that is failing. It has a single layer of placed stone armor on exposed geogrid over undersized stone underlayer. There is some loss of small underlayer stone which is typical. There are some armorstone subsidence areas due to underlayer loss. It is in poor condition and may fail in a storm.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-017-000-024-100-PHO1A.JPG

039-017-000-024-100-PHO1B.JPG

039-017-000-024-100-PHO1C.JPG

Structure Documents:

MA-DCR

January 194

Proposed Shore

039-017-000-024-100-DCR1A

MA-DCR

April 1965

Proposed Shore

039-017-000-024-100-DCR1B

Structure Assessment Form

Town: **Manchester**Structure ID: **039-018-000-025-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lobster Cove

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$68,006.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
160	13	V2	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared stone block wall on concrete footing adjacent to a street, in satisfactory condition. There is some mortar loss and some concrete cracking.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description***No Inshore Structures or Residential Dwelling Units Present**

Structure Images:

039-018-000-025-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-022-000-016-100**

Key: community-map-block-parcel-structure

Property Owner:

Location:

Date:

Local

Tucks Point

6/22/2007

Presumed Structure Owner:

Based On Comment:

Local

Owner Name:

Earliest Structure Record:

Estimated Reconstruction/Repair Cost:

Manchester

Unknown

\$53,130.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
125		V2	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Primary Material:

Primary Height:

Bulkhead/ Seawall

Stone

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared rubble stone wall with granite cap in fair condition. There are a few areas with missing mortar and the mortar is typically cracked. The wall forms an access to park pier.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

039-022-000-016-100-PHO1A.JPG

039-022-000-016-100-PHO1B.JPG

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-022-000-017-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Tucks Point

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$49,896.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
150		V2	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A granite block revetment with toe undercut at west end. There is a void up to 8 inches high under the toe for approximately 10 feet. Overall, it is in fair condition. The park toilet building is nearby.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-022-000-017-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Property Owner:

Local

Location:

West Main Beach

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$551,760.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
440		V2	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A cast in place concrete seawall adjacent to the road in fair condition. The face of wall is cracked with exposed embedded stones at a few locations. Some repair patching is apparent and this wall may actually be a concrete veneer over stone wall or cyclopean concrete.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

039-022-000-034-100-PHO1A.JPG

039-022-000-034-100-PHO1B.JPG

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-045-000-023-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Town Hall

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$69,300.00

Length: Top Elevation: FIRM Map Zone: FIRM Map Elevation:

175

A2

9

Feet

Feet NAVD 88

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A dry set granite block wall with concrete cap in satisfactory condition. There is minor deteriorating of the concrete cap and some loss of bedding under stone steps, with the steps in poor condition. A police station is approximately 100 feet away.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

039-045-000-023-100-PHO1A.JPG

039-045-000-023-100-PHO1B.JPG

Structure Documents:

Structure Assessment FormStructure ID: **039-045-000-023-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Town Hall

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$63,360.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
160		A2	9
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A cast in place concrete seawall in satisfactory condition. There are a few cracks in cap. A police station is approximately 100 feet away.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***III***Rating***Moderate Priority***Action*

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

039-045-000-023-200-PHO2A.JPG**039-045-000-023-200-PHO2B.JPG**

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-045-000-023-300**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Town Hall - Wall at Central Street

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$43,890.00

Length: Top Elevation:

35

FIRM Map Zone:

A3

FIRM Map Elevation:

9

Feet

Feet NAVD 88

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone seawall at Central street, skim coated with mortar above high waterand with a granite cap. The wall acts as a stream dam for the adjacent stream and there is seepage between stones. In fair condition.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

039-045-000-023-300-PHO3A.JPG

Structure Documents:

Structure Assessment Form

Town: **Manchester**Structure ID: **039-045-000-024-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Town Hall Parking Lot

Date:

6/22/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Manchester

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$135,762.00

Length: **550** Top Elevation: **9** FIRM Map Zone: **A2** FIRM Map Elevation: **9**
 Feet Feet NAVD 88 Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone revetment with large stone face parallel with slope in good condition. This structure is adjacent to the wastewater treatment plant.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***III***Rating***Moderate Priority***Action*

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

039-045-000-024-100-PHO1A.JPG

Structure Documents:

DEP**August 21, 1****Plan Accompanying****039-045-000-045-100-LIC1A**

Section II - Manchester

Part C

Structure Photographs

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
039-001-000-095-100	039-001-000-095-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-006-000-029-100	039-006-000-029-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-006-000-029-100	039-006-000-029-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-006-000-029-100	039-006-000-029-100-PHO1C.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-007-000-026-100	039-007-000-026-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-007-000-026-200	039-007-000-026-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-007-000-026-300	039-007-000-026-300-PHO3A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-008-000-003-100	039-008-000-003-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-008-000-003-200	039-008-000-003-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-008-000-003-200	039-008-000-003-200-PHO2B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-016-000-022-100	039-016-000-022-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-016-000-034-100	039-016-000-034-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-016-000-034-100	039-016-000-034-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-016-000-034-200	039-016-000-034-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-016-000-035-100	039-016-000-035-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-016-000-035-200	039-016-000-035-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-016-000-035-200	039-016-000-035-200-PHO2B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-016-000-035-200	039-016-000-035-200-PHO2C.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-017-000-024-100	039-017-000-024-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-017-000-024-100	039-017-000-024-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-017-000-024-100	039-017-000-024-100-PHO1C.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-018-000-025-100	039-018-000-025-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
039-022-000-016-100	039-022-000-016-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-022-000-016-100	039-022-000-016-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-022-000-017-100	039-022-000-017-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-022-000-034-100	039-022-000-034-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-022-000-034-100	039-022-000-034-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-045-000-023-100	039-045-000-023-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-045-000-023-100	039-045-000-023-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-045-000-023-200	039-045-000-023-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-045-000-023-200	039-045-000-023-200-PHO2B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-045-000-023-300	039-045-000-023-300-PHO3A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
039-045-000-024-100	039-045-000-024-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

Massachusetts Coastal Infrastructure and Assessment



039-001-000-095-100-PHO1A



039-006-000-029-100-PHO1A



039-006-000-029-100-PHO1B



039-006-000-029-100-PHO1C



039-007-000-026-100-PHO1A



039-007-000-026-200-PHO2A



039-007-000-026-300-PHO3A



039-008-000-003-100-PHO1A



039-008-000-003-200-PHO2A

Massachusetts Coastal Infrastructure and Assessment



039-008-000-003-200-PHO2B



039-016-000-022-100-PHO1A



039-016-000-034-100-PHO1A



039-016-000-034-100-PHO1B



039-016-000-034-200-PHO2A



039-016-000-036-100-PHO1A



039-016-000-036-200-PHO2A



039-016-000-036-200-PHO2B



039-016-000-036-200-PHO2C


Massachusetts Coastal Infrastructure and Assessment



039-017-000-024-100-PHO1A



039-017-000-024-100-PHO1B



039-017-000-024-100-PHO1C



039-018-000-025-100-PHO1A



039-022-000-016-100-PHO1A



039-022-000-016-100-PHO1B



039-022-000-017-100-PHO1A



039-022-000-034-100-PHO1A



039-022-000-034-100-PHO1B

Massachusetts Coastal Infrastructure and Assessment



039-045-000-023-100-PHO1A



039-045-000-023-100-PHO1B



039-045-000-023-200-PHO2A



039-045-000-023-200-PHO2B



039-045-000-023-300-PHO3A



039-045-000-024-100-PHO1A

Section II - Manchester

Part D

Structure Documents

TOWN DOCUMENT LIST

MA DCR - DOCUMENT LIST

MA DEP – Ch 91 DOCUMENT LIST

- Copies of License Documents

USACE – PERMIT DOCUMENT LIST

- Copies of Permit Documents

TOWN: MANCHESTER
SOURCE: Town of Manchester
LOCATION: TOWN
DATE OF RESEARCH: JULY 2007

No Town Documents for the Town of Manchester

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
------------------	-------------	--------------------------------	--------	--------------	------	-------	--------	----------	-------------

TOWN: MANCHESTER

SOURCE: MA-DCR

LOCATION: MA-DCR BOSTON and HINGHAM, MA

DATE OF RESEARCH: JULY 2007

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
039-007-000-026-200	039-007-000-026-200-DCR2A	2771	MA-DCR	Manchester	March 1973	Proposed Shore Protection - Kettle Cove - Ocean Street Seawall Reconstruction	1	Ocean Street	Seawall
039-017-000-024-100	039-017-000-024-100-DCR1A	961	MA-DCR	Manchester	January 1947	Proposed Shore Protection - Singing Beach - Manchester - Prepared for the DPW of Massachusetts - Division of Waterways	1	Singing Beach	Riprap
039-017-000-024-100	039-017-000-024-100-DCR1B	2460	MA-DCR	Manchester	April 1965	Proposed Shore Protection - Stone Revetment - Singing Beach - Manchester - Prepared for the DPW of Massachusetts - Division of Waterways	1	Singing Beach	Stone Revetment

TOWN: MANCHESTER
 SOURCE: DEP
 LOCATION: BOSTON, MA
 DATE OF RESEARCH: JULY 2007

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
039-016-000-034-100	039-016-000-034-100-LIC1A	11715	DEP	Manchester	March 20, 2007	Plan Accompanying Petition of Town of Manchester - Masconomo Park, Beach Street, Manchester, MA 01944 to License and Maintain Existing Riprap	4	Masconomo Park	Riprap
039-016-000-036-200	039-016-000-036-200-LIC2A	11715	DEP	Manchester	March 20, 2007	Plan Accompanying Petition of Town of Manchester Masconomo Park, Beach Street Manchester, MA to License and Maintain Existing Riprap	4	Manchester Harbor	Riprap
039-045-000-024-100	039-045-000-045-100-LIC1A	2226	DEP	Manchester	August 21, 1940	Plan Accompanying Petition of Town of Manchester to Maintain Extend and Fill Solid a Dike in the Inner Harbor	1	Inner Harbor	Dike

EXISTING
RIP-RAP TO
BE LICENSED

BEACH STREET

MANCHESTER
HARBOR


LIMIT OF 100-YEAR FLOOD ZONE
(ZONE A-2) (BASED ON ELEVATION 9)

MASCONOMO PARK

MANCHESTER HARBOR



SITE PLAN VIEW
GRAPHIC SCALE



1 INCH = 100 FEET

PLAN ACCOMPANYING PETITION OF:
TOWN OF MANCHESTER
MASCONOMO PARK, BEACH STREET
MANCHESTER, MA 01944

TO LICENSE AND MAINTAIN EXISTING
RIP-RAP

IN MANCHESTER HARBOR, MANCHESTER, MA
ESSEX COUNTY, MA

PAGE 1 OF 4 DATE 08/08/06

LICENSE PLAN NO. 11715

Approved by Department of Public Works
of Manchester

MAR 20 2007

Bar
A. G. Pera

LOCUS PLAN
MANCHESTER QUAD
N.T.S.

N/F
Estate of
John A. Nahata


N/F
Christos G.
Nahata

N/F
John A.
Barthel


039-016-000-036-200
039-016-000-034-100

106-1777

039-016-000-036-200
039-016-000-034-100



SITE PLAN VIEW
GRAPHIC SCALE



1 INCH = 50 FEET

PAGE 2 OF 4 DATE 08/08/06

PLAN ACCOMPANYING PETITION OF:
TOWN OF MANCHESTER
MASCONOMO PARK, BEACH STREET
MANCHESTER, MA 01944

TO LICENSE AND MAINTAIN EXISTING
RIP-RAP

IN MANCHESTER HARBOR, MANCHESTER, MA
ESSEX COUNTY, MA

LICENSE PLAN NO. 11715
Approved by Department of Environmental Protection
Date: **MAR 20 2007**

039-016-000-036-200
039-016-000-034-100

LIMIT OF 100-YEAR FLOOD ZONE
(ZONE A-2) (BASED ON ELEVATION 9)

BEACH STREET


TBM & MAG NAIL SET IN SIDEWALK
ELEVATION=10.32 (NGVD 29)

MANCHESTER HARBOR

MEAN HIGH WATER LINE
ELEVATION=4.43 (NGVD 29)



SITE PLAN VIEW
GRAPHIC SCALE



1 INCH = 50 FEET

PLAN ACCOMPANYING PETITION OF:
TOWN OF MANCHESTER
MASCONOMO PARK, BEACH STREET
MANCHESTER, MA 01944

PAGE 3 OF 4 DATE 08/08/06

TO LICENSE AND MAINTAIN EXISTING
IP-RAP

LICENSE PLAN NO. 11715
Approved by Department of Environmental Protection
Date: **MAR 20 2007**

EXISTING GRADE

EXISTING RIP-RAP
TO BE LICENSED

MHW

MLW

8
4
0
-4
-8

0 20 40 60 80 100 120

SECTION A-A

SCALE

H: 1" = 20'

V: 1" = 20'

EXISTING GRADE

EXISTING RIP-RAP
TO BE LICENSED

MHW

MLW

4
0
-4
-8

0 20 40 60 80 100

SECTION B-B

SCALE

H: 1" = 20'

V: 1" = 20'

CROSS SECTIONS
GRAPHIC SCALE



1 INCH = 20 FEET



PLAN ACCOMPANYING PETITION OF
TOWN OF MANCHESTER
ECONOMO PARK, BEACH STREET
MANCHESTER, MA 01944

TO LICENSE AND MAINTAIN EXISTING
RIP-RAP

IN MANCHESTER HARBOR, MANCHESTER, MA
ESSEX COUNTY, MA

PAGE 4 OF 4 DATE 08/08/06

LICENSE PLAN NO. 11715

Approved by Department of Environmental Protection

MAR 20 2007

039-016-000-036-200
039-016-000-034-100

EXISTING
RIP-RAP TO
BE LICENSED

BEACH STREET

MANCHESTER
HARBOR


LIMIT OF 100-YEAR FLOOD ZONE
(ZONE A-2) (BASED ON ELEVATION 9)

MASCONOMO PARK

MANCHESTER HARBOR



SITE PLAN VIEW
GRAPHIC SCALE



1INCH=100 FEET

PAGE 1 OF 4 DATE 08/08/06

LICENSE PLAN NO. 11715

Approved by Department of Public Works

of Massachusetts

MAR 20 2007

Signature

PLAN ACCOMPANYING PETITION OF:
TOWN OF MANCHESTER
MASCONOMO PARK, BEACH STREET
MANCHESTER, MA 01944

TO LICENSE AND MAINTAIN EXISTING
RIP-RAP

IN MANCHESTER HARBOR, MANCHESTER, MA
ESSEX COUNTY, MA

LOCUS PLAN
MANCHESTER QUAD
N.T.S.

N/F
Estate Of
Johanna
Nahata


N/F
Christos G.
Nahata

N/F
John A.
Barlett


039-016-000-036-200
039-016-000-034-100

006-1777

039-016-000-036-200
039-016-000-034-100



SITE PLAN VIEW
GRAPHIC SCALE



1 INCH = 50 FEET

PAGE 2 OF 4 DATE 08/08/06

PLAN ACCOMPANYING PETITION OF:
TOWN OF MANCHESTER
MASCONOMO PARK, BEACH STREET
MANCHESTER, MA 01944

TO LICENSE AND MAINTAIN EXISTING
RIP-RAP

IN MANCHESTER HARBOR, MANCHESTER, MA
ESSEX COUNTY, MA

LICENSE PLAN NO. 11715

Approved by Department of Environmental Protection
Date:

MAR 20 2007

LIMIT OF 100-YEAR FLOOD ZONE
(ZONE A-2) (BASED ON ELEVATION 9)

BEACH STREET


M.L.W. - 4.51'

MANCHESTER HARBOR

MEAN HIGH WATER LINE
ELEVATION=4.43 (NGVD
29)



SITE PLAN VIEW
GRAPHIC SCALE



1 INCH = 50 FEET

PLAN ACCOMPANYING PETITION OF:
TOWN OF MANCHESTER
MASCONOMO PARK, BEACH STREET
MANCHESTER, MA 01944

TO LICENSE AND MAINTAIN EXISTING
IP-RAP

PAGE 3 OF 4 DATE 08/08/06

LICENSE PLAN NO. 11715

Approved by Department of Environmental Protection

Date: **MAR 20 2007**

039-016-000-036-200
039-016-000-034-100

EXISTING GRADE

EXISTING RIP-RAP
TO BE LICENSED

MHW

MLW

0 20 40 60 80 100 120

SECTION A-A

SCALE

H: 1" = 20'

V: 1" = 20'

EXISTING GRADE

EXISTING RIP-RAP
TO BE LICENSED

MHW

MLW

0 20 40 60 80 100

SECTION B-B

SCALE

H: 1" = 20'

V: 1" = 20'

CROSS SECTIONS
GRAPHIC SCALE



1 INCH = 20 FEET



PLAN ACCOMPANYING PETITION OF
TOWN OF MANCHESTER
ECONOMO PARK, BEACH STREET
MANCHESTER, MA 01944

TO LICENSE AND MAINTAIN EXISTING
RIP-RAP

IN MANCHESTER HARBOR, MANCHESTER, MA
ESSEX COUNTY, MA

PAGE 4 OF 4 DATE 08/08/06


LICENSE PLAN NO. 11715

Approved by Department of Environmental Protection

MAR 20 2007

039-016-000-036-200
039-016-000-034-100

039-045-000-024-100



PLAN ACCOMPANYING PETITION OF
TOWN OF MANCHESTER
 TO MAINTAIN EXTEND
 AND FILL SOLID A DIKE IN
THE INNER HARBOR
MANCHESTER

RAYMOND CALLEN, CIVIL ENGINEER
 MANCHESTER, MASS.
 JULY 31, 1940

NO 2226
 APPROVED BY DEPARTMENT OF PUBLIC WORKS
 AUG 21, 1940

[Signature] COMMISSIONER OF PUBLIC WORKS
[Signature] ASSOCIATE COMMISSIONERS
[Signature] DIRECTOR DIVISION

TOWN: MANCHESTER
SOURCE: US ACOE
LOCATION: CONCORD, MA
DATE OF RESEARCH: AUGUST 2007

No USACE Permits for the Town of Manchester

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
------------------	-------------	--------------------------------	--------	--------------	------	-------	--------	----------	-------------

Section III

Beverly

Section III – Community Findings – City of Beverly

COMMUNITY DESCRIPTION

The City of Beverly consists of a land area of 15.44 square miles out of a total area of 22.75 square miles and had a population of 39,862 in the 2000 census. The City is located on the North Shore of Massachusetts and its location can be seen on this report's cover. The estimated length of shoreline that is directly exposed to open ocean waves is 7 miles with the remaining shoreline semi-protected by offshore structures or landforms. The City is protected from major coastal storms by both natural and man-made shoreline structures that require maintenance to insure the long term protection of its coastline. The man-made and publicly owned structures that protect the City were investigated for their ability to provide adequate protection from major coastal storms. Structures have been identified as publicly owned, including coastal dunes and beaches, based on evidence of investment of public funds made to create/enhance/maintain these structures. The assessment did not include floating or pile supported structures as they are assumed not to provide any significant coastal protection from major storm events.

STRUCTURE INVENTORY

Within the City of Beverly, there were 20 structures which had public or unknown ownership which provide significant coastal protection. The location of the structures can be seen in Sheets 1 through Sheet 3 in Section III-B of this report. The structures were categorized by their type and by their structural condition based on a preliminary field assessment. The distribution of structures by type and condition can be seen in the following table:

STRUCTURE TYPE AND QUANTITY - City of Beverly

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Length
		A	B	C	D	F	
Bulkhead / Seawall	16		4	10	2		4805
Revetment							
Breakwater							
Groin / Jetty	3		3				520
Coastal Dune							
Coastal Beach	1		1				755
	20		8	10	2		6080

Within the above table, the total length of each type of structure is also provided. The structures are listed by the type which is providing the primary coastal protection. Many sites have multiple structure types at the same location (i.e. revetment in front of seawall). These secondary structures, although not identified within these tables, are included in the development of repair/rehabilitation costs.

The development of repair costs has been included by structure type and by condition. In the City of Beverly's case there are a total of 20 structures which would require approximately \$ 6.8 million to bring all the coastal structures to "A" Rating. Most critical will be the structures in the "D" and "F" classifications as those are assumed to undergo some level of damage or failure during the next major coastal storm event. To reconstruct these structures, identified in the preliminary survey as being in poor condition, an estimated \$ 1.5 million would be required to upgrade the City's coastal protection.

STRUCTURE REPAIR / RECONSTRUCTION COST - City of Beverly

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Bulkhead / Seawall	16		\$ 418,361	\$ 4,561,101	\$ 1,474,268		\$ 6,453,730
Revetment							\$ -
Breakwater							\$ -
Groin / Jetty	1		\$ 153,290				\$ 153,290
Coastal Dune							\$ -
Coastal Beach	3		\$ 169,422				\$ 169,422
	20	\$ -	\$ 741,073	\$ 4,561,101	\$ 1,474,268	\$ -	\$ 6,776,442

Based on the limited research within the scope of this project research, the presumed ownership of the structures was established on an initial basis and would be subject to more intense review in future tasks. Structures identified as being owned privately were excluded from further consideration. Although ownership of the land on which the structure was located was a factor, the structure ownership was treated as a separate issue from land ownership. For the City of Beverly, the breakdown of structures by assumed ownership is as follows:

STRUCTURE OWNERSHIP / REPAIR COST - City of Beverly

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Town Owned	20		\$ 669,465	\$ 4,561,101	\$ 1,474,268		\$ 6,704,834
Commonwealth of Massachusetts							\$ -
Federal Government Owned							\$ -
Unknown Ownership							\$ -
	20	\$ -	\$ 669,465	\$ 4,561,101	\$ 1,474,268	\$ -	\$ 6,704,834

The identification of presumed ownership was not based on the investigation of legal documents but relied on property ownership and from construction and regulatory documents that were found. A more detailed investigation of legal documents and agreements would be required where structure ownership is disputed. A more detailed identification of structure type, length, condition and location can be found in Section III-B which contains Structure Assessment Reports for each individual structure found.

SUMMARY


The enclosed reports and associated documents reflects the City of Beverly's coastal structure information that will eventually be input into a state-wide GIS database and will be accessible through MassGIS. This data, when compiled state-wide, will be critical in the development of both short term and long term planning for maintaining and improving Massachusetts coastal protection.

This database will also provide relatively quick access to identify available documentation for these structures as well as the ability to be updated as coastal structure improvements are made.

Section III - Beverly

Part B


Structure Assessment Reports



COASTAL STRUCTURE LOCATION PLAN

CITY OF BEVERLY
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150
SCALE: 1" = 150'-0"





COASTAL STRUCTURE LOCATION PLAN

CITY OF BEVERLY
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150



SCALE: 1" = 150'-0"





COASTAL STRUCTURE LOCATION PLAN

CITY OF BEVERLY
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150



SCALE: 1" = 150'-0"



Structure Assessment Form

Town: **Beverly**

Structure ID: 005-001-000-085-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Harbor Center East

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1981

Estimated Reconstruction/Repair Cost:

\$1,197,068.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
215		V4	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Over 15 Feet

Secondary Type:

Bulkhead/ Seawall

Secondary Material:

Wood

Secondary Height:

10 to 15 Feet



Structure Summary :

A dry rubble stone wall with timber fender piles in poor condition. The top of the wall is leaning out. There is concrete rubble backfilled and under building, horizontal timbers behind piles and a portion with a mass concrete overlay repair. Sandbags fill a sinkhole at the building, 2 feet by 5 feet, and another sinkhole is filled with crushed stone. The building appears to be on the pile supported pier.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

V

Rating

Immediate / Highest Priority

Action

Consider For Immediate Action Due to Public Safety and Welfare Issues

Description

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:

005-001-000-085-100-PHO1A.JPG

005-001-000-085-100-PHO1B.JPG

005-001-000-085-100-PHO1C.JPG

Structure Documents:

USACE

July 1982

Proposed Riprap

005-001-000-085-100-COE1A

DEP

November 1

Plan Accompanying

005-001-000-085-100-LIC1A

Structure Assessment Form

Town: **Beverly**

Structure ID: 005-001-000-086-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Beverly Harbor

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$277,200.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
70		V4	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A rubble stone seawall with mortared stone cap in poor condition. The stones appear to be moving with dislodged stones that are loose, typically with no chinking and rounded unstable stones. A parking lot is behind this structure.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

V

Rating

Immediate / Highest Priority

Action

Consider For Immediate Action Due to Public Safety and Welfare Issues

Description

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:

005-001-000-086-100-PHO1A.JPG

Structure Documents:

DEP

March 23, 19

Plan Accompanying

005-001-000-086-100-LIC1A

DEP

November 1

Plan Accompanying

005-001-000-086-100-LIC1B

Structure Assessment FormStructure ID: **005-001-000-087-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Beverly Harbor

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$485,100.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
245		V4	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

A granite block seawall with concrete cap in satisfactory condition. There are a few fallen blocks (small). There is a sinkhole at the pier abutment 1 foot by 4 feet. The harbormaster office is adjacent to wall, resulting in the high priority rating.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***V***Rating***Immediate / Highest Priority***Action*

Consider For Immediate Action Due to Public Safety and Welfare Issues

Description

Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Condition of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)

Structure Images:**005-001-000-087-100-PHO1A.JPG****005-001-000-087-100-PHO1B.JPG****Structure Documents:**

Structure Assessment Form

Town: **Beverly**

Structure ID: 005-002-000-091-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Quincy Park East

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$18,810.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
15		V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A concrete parged seawall in satisfactory condition overall, but there is exposed rebar at the toe and concrete deterioration. There are several houses near the wall.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

005-002-000-091-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Beverly**

Structure ID: 005-002-000-094-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Quincy Park West

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$10,032.00

Length:

40

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V2

FIRM Map Elevation:

16

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A concrete seawall with wave return face in satisfactory condition. There are several houses near the wall.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

005-002-000-094-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Beverly**Structure ID: **005-002-000-118-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Water Street

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1947

Estimated Reconstruction/Repair Cost:

\$61,230.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
195		V4	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Groin/ Jetty

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A quarry stone groin over sewer outfall in satisfactory condition, but it is functioning adequately. There are a few smaller dislodged stones along the crest.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

005-002-000-118-100-PHO1A.JPG

Structure Documents:

USACE**June 1952****Proposed Dredging****005-002-000-118-100-COE1A****MA-DCR****February 19****Proposed Stone****005-002-000-118-100-DCR1A**

Structure Assessment Form

Town: **Beverly**

Structure ID: 005-004-000-040-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Ward Two Playground

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$920,700.00

Length:

465

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

A2

FIRM Map Elevation:

10

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared stone rubble wall above beach in fair condition. There is some localized cracking, one small cap stone missing at stairs, localized missing mortar but no signs of wall movement. This is a high retaining wall with a playground behind.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

005-004-000-040-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Beverly**Structure ID: **005-005-000-459-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Washington Street

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1954

Estimated Reconstruction/Repair Cost:

\$79,332.00

Length:

50

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V2

FIRM Map Elevation:

16

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Under 5 Feet

Structure Summary :

A granite block seawall with mortared joints and a toe stone revetment; both fair condition. There are mortar repairs on the wall. There are houses in the vicinity.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

005-005-000-459-100-PHO1A.JPG

Structure Documents:

MA-DCR**November 1****Proposed Shore****005-005-000-459-100-DCR1A****MA-DCR****July 1958****Proposed Shore****005-005-000-459-100-DCR1B**

Structure Assessment Form

Town: **Beverly**Structure ID: **005-005-000-462-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Independence Park

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1947

Estimated Reconstruction/Repair Cost:

\$95,634.00

Length:

630

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V2

FIRM Map Elevation:

16

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared granite block park seawall in satisfactory condition. The railing is missing along the length of the wall.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

005-005-000-462-100-PHO1A.JPG

Structure Documents:

MA-DCR**February 19****Proposed Stone****005-005-000-462-100-DCR1A**

Structure Assessment Form

Town: **Beverly**

Structure ID: 005-005-000-462-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Wilson Avenue

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1952

Estimated Reconstruction/Repair Cost:

\$59,660.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
190		V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Groin/ Jetty

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A quarry stone groin in generally satisfactory condition with some unravelling of armor stone at outer end. This groin retains sand and covers a drain outfall. There is a house nearby.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

005-005-000-462-200-PHO2A.JPG

Structure Documents:

USACE

June 1952

Proposed Dredging

005-005-000-462-200-COE2A

Structure Assessment Form

Town: BeverlyStructure ID: 005-005-000-462-300

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Wilson Avenue

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$22,770.00

Length:

30

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V2

FIRM Map Elevation:

16

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A granite block seawall in fair condition with some missing mortar and chinking. There is a sinkhole behind the wall, 2 feet by 5 feet by 1 foot deep and a house nearby.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

005-005-000-462-300-PHO3A.JPG

Structure Documents:

Structure Assessment Form

Town: **Beverly**Structure ID: **005-006-000-031-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Ocean Avenue

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1954

Estimated Reconstruction/Repair Cost:

\$50,160.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
40		V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:



Structure Summary :

A concrete seawall with footing exposed and undercut in areas. The toe stone is unravelled. The stairs end 3 feet above current beach level, indicating significant sand loss. Fair overall condition with concerns of possible damage or failure due to footing undermining. There are houses in the vicinity.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

005-006-000-031-100-PHO1A.JPG

Structure Documents:

MA-DCR**November 1****Proposed Shore****005-006-000-031-100-DCR1A**

Structure Assessment Form

Town: **Beverly**

Structure ID: 005-006-000-035-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Abbott Street

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$75,240.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
60		V2	16
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A granite block seawall with mortared joints and some mortar missing; in fair condition. There are houses in the vicinity.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

005-006-000-035-100-PHO1A.JPG

Structure Documents:

MA-DCR

July 1958

Proposed Shore

005-006-000-035-100-DCR1A

Structure Assessment Form

Town: **Beverly**Structure ID: **005-007-000-007A-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Bay View Avenue

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$138,600.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
70		V2	25
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A granite block seawall with dislodged cap blocks at the east end for 6 linear feet. No other signs of distress and it is founded on bedrock. In fair condition.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

005-007-000-007A-100-PHO1A.JPG

Structure Documents:

Structure Assessment FormStructure ID: **005-012-000-238-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lyons Park Beach

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1957

Estimated Reconstruction/Repair Cost:

\$304,247.00

Length:

985

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V4

FIRM Map Elevation:

14

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

5 to 10 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

10 to 15 Feet

Structure Summary :

A concrete and stone park seawall (mortared stone with concrete cap) in satisfactory condition. One portion of the seawall is all concrete, some minor cracking cap, some minor spalling at the east end on the cap. A stone toe revetment is adjacent at the west end.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

005-012-000-238-100-PHO1A.JPG

Structure Documents:

MA-DCR**March 1957****Proposed Shore****005-012-000-238-100-DCR1A**

Structure Assessment Form

Property Owner:

Local

Location:

Lyons Park

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1957

Estimated Reconstruction/Repair Cost:

\$32,400.00

Length: Top Elevation:

135

Feet

Feet NAVD 88

FIRM Map Zone:

V2

FIRM Map Elevation:

16

Feet NGVD

Primary Type:

Groin/ Jetty

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A quarry stone groin in a park setting, in satisfactory condition.*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***III***Rating***Moderate Priority***Action*

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

005-012-000-238-200-PHO2A.JPG

Structure Documents:

MA-DCR**March 1957****Proposed Shore****005-012-000-238-200-DCR2A**

Structure Assessment Form

Structure ID: 005-012-000-238-300

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lyons Park Beach

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Harbor Master

Owner Name:

Beverly

Earliest Structure Record:

1957

Estimated Reconstruction/Repair Cost:

\$169,422.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
755		V4	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Coastal Beach

Primary Material:

Sand

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A reported beach nourishment with sand typically in place, but no sand and exposed toe stone revetment at the western end.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

005-012-000-238-300-PHO3A.JPG

Structure Documents:

MA-DCR

March 1957

Proposed Shore

005-012-000-238-300-DCR3A

Structure Assessment Form

Town: **Beverly**

Structure ID: 005-013-000-050A-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Woodbury

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$25,502.00

Length:

60

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V4

FIRM Map Elevation:

14

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared rubble stone street end wall in fair condition with some cracked mortar, holes in mortar, and one sinkhole behind that is 1 foot by 3 foot by 1.5 feet deep in pavement.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

005-013-000-050A-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Property Owner:

Local

Location:

Ober Street

Date:

3/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

Unkown

Estimated Reconstruction/Repair Cost:

\$8,448.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
100		V4	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared rubble stone wall with irregular batter, in overall satisfactory condition.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

005-013-000-213A-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: BeverlyStructure ID: 005-013-000-219-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lynch Park

Date:

6/7/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Beverly

Earliest Structure Record:

1963

Estimated Reconstruction/Repair Cost:

\$2,744,887.00

Length:

1730

Top Elevation:

Feet Feet NAVD 88

FIRM Map Zone:

V4 and V2

FIRM Map Elevation:

14,15,16

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Under 5 Feet

Structure Summary :

A mortared stone rubble park seawall with granite block cap stones in fair condition. There are some mortar joints cracked, one area with some 12 inch riprap and erosion areas inshore of wall.

*Condition***C***Rating*

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***I***Rating*

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

005-013-000-219-100-PHO1A.JPG005-013-000-219-100-PHO1B.JPG

Structure Documents:

MA-DCRAugust 1963Proposed Shore005-013-000-219-100-DCR1A

Section III - Beverly

Part C

Structure Photographs

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
005-001-000-085-100	005-001-000-085-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-001-000-085-100	005-001-000-085-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-001-000-085-100	005-001-000-085-100-PHO1C.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-001-000-086-100	005-001-000-086-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-001-000-087-100	005-001-000-087-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-001-000-087-100	005-001-000-087-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-002-000-091-100	005-002-000-091-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-002-000-094-100	005-002-000-094-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-002-000-118-100	005-002-000-118-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-004-000-040-100	005-004-000-040-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-005-000-459-100	005-005-000-459-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-005-000-462-100	005-005-000-462-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-005-000-462-200	005-005-000-462-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-005-000-462-300	005-005-000-462-300-PHO3A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-006-000-031-100	005-006-000-031-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-006-000-035-100	005-006-000-035-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-007-000-007A-100	005-007-000-007A-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-012-000-238-100	005-012-000-238-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-012-000-238-200	005-012-000-238-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-012-000-238-300	005-012-000-238-300-PHO3A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-013-000-050A-100	005-013-000-050A-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-013-000-213A-100	005-013-000-213A-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
005-013-000-219-100	005-013-000-219-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
005-013-000-219-100	005-013-000-219-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

Massachusetts Coastal Infrastructure and Assessment



005-001-000-085-100-PHO1A



005-001-000-085-100-PHO1B



005-001-000-085-100-PHO1C



005-001-000-086-100-PHO1A



005-001-000-087-100-PHO1A



005-001-000-087-100-PHO1B



005-002-000-091-100-PHO1A



005-002-000-094-100-PHO1A



005-002-000-118-100-PHO1A

Massachusetts Coastal Infrastructure and Assessment



005-004-000-040-100-PHO1A



005-005-000-459-100-PHO1A



005-005-000-462-100-PHO1A



005-005-000-462-200-PHO2A



005-005-000-462-300-PHO3A




005-006-000-031-100-PHO1A



005-006-000-035-100-PHO1A



005-007-000-007A-100-PHO1A



005-012-000-238-100-PHO1A

Massachusetts Coastal Infrastructure and Assessment



005-012-000-238-200-PHO2A



005-012-000-238-300-PHO3A



005-013-000-050A-100-PHO1A



005-013-000-213A-100-PHO1A



005-013-000-219-100-PHO1A



005-013-000-219-100-PHO1B

Section III - Beverly

Part D

Structure Documents

CITY DOCUMENT LIST

MA DCR - DOCUMENT LIST

MA DEP – Ch 91 DOCUMENT LIST

- Copies of License Documents

USACE – PERMIT DOCUMENT LIST

- Copies of Permit Documents

CITY: BEVERLY
SOURCE: City of Beverly
LOCATION: CITY
DATE OF RESEARCH: JULY 2007

No City Documents for the City of Beverly

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
------------------	-------------	--------------------------------	--------	--------------	------	-------	--------	----------	-------------

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
005-002-000-118-100	005-002-000-118-100-DCR1A	967	MA-DCR	Beverly	February 1947	Proposed Stone Jetties - Beverly Shore - Adjacent to Lohrop Street - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	1	Wilson Avenue and Water Street	Groins
005-005-000-459-100	005-005-000-459-100-DCR1A	1447	MA-DCR	Beverly	November 1954	Proposed Shore Protection - Seawall Repairs and Earth Fill - Beverly Harbor Shore - Washington and Ocean Streets - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	4	Washington and Ocean Street	Seawall Repairs
005-005-000-459-100	005-005-000-459-100-DCR1B	1960	MA-DCR	Beverly	July 1958	Proposed Shore Protection - Stone Mound and Seawall Reconstruction - Vicinity of Abbott Street - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	1	Central Street to Abbott Street	Stone Mound and Seawall
005-005-000-462-100	005-005-000-462-100-DCR1A	967	MA-DCR	Beverly	February 1947	Proposed Stone Jetties - Beverly Shore - Adjacent to Lohrop Street - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	1	Wilson Avenue and Water Street	Groins
005-006-000-031-100	005-006-000-031-100-DCR1A	1447	MA-DCR	Beverly	November 1954	Proposed Shore Protection - Seawall Repairs and Earth Fill - Beverly Harbor Shore - Washington and Ocean Streets - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	4	Washington and Ocean Streets	Seawall Repairs
005-006-000-035-100	005-006-000-035-100-DCR1A	1960	MA-DCR	Beverly	July 1958	Proposed Shore Protection - Stone Mound and Seawall Reconstruction - Vicinity of Abbott Street - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	1	Central Street to Abbott Street	Stone Mound and Seawall
005-012-000-238-100	005-012-000-238-100-DCR1A	1744	MA-DCR	Beverly	March 1957	Proposed Shore Protection - Stone Groin and Seawall Repairs - Dane Street Beach - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	1	Dane Street Beach	Groins and Seawall
005-012-000-238-200	005-012-000-238-200-DCR2A	1744	MA-DCR	Beverly	March 1957	Proposed Shore Protection - Stone Groin and Seawall Repairs - Dane Street Beach - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	1	Dane Street Beach	Groins and Seawall
005-012-000-238-300	005-012-000-238-300-DCR3A	1744	MA-DCR	Beverly	March 1957	Proposed Shore Protection - Stone Groin and Seawall Repairs - Dane Street Beach - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	1	Dane Street Beach	Groins and Seawall
005-013-000-219-100	005-013-000-219-100-DCR1A	2358	MA-DCR	Beverly	August 1963	Proposed Shore Protection - Seawall Repairs - Lynch Park - Beverly - Proposed Shore Protection - Stone Groin and Seawall Repairs - Dane Street Beach - Beverly - Prepared for the DPW of Massachusetts - Division of Waterways	1	Lynch Park	Seawall Repairs

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
005-001-000-085-100	005-001-000-085-100-LIC1A	798	DEP	Beverly	November 1981	Plan Accompanying Petition of the City of Beverly - To Construct a Granite Block Retaining Wall, Platform, Ramp, Pile Held Floats, to Dredge, and to Fill in Beverly Harbor, Beverly, Massachusetts	2	Water Street	Granite Retaining Wall
005-001-000-086-100	005-001-000-086-100-LIC1A	798	DEP	Beverly	November 1981	Plan Accompanying Petition of the City of Beverly to Construct a Granite Block Retaining Wall, Platform, Ramp, Pile Held Floats, to Dredge, and to Fill in Beverly Harbor, Beverly, Mass.	2	Cabot Street	Granite Block Retaining Wall
005-001-000-086-100	005-001-000-086-100-LIC1B	932	DEP	Beverly	November 12, 1982	Plan Accompanying Petition of The City of Beverly to Construct a Rip-Rap Slope, Ramp, Pile Held Floats, To Dredge and To Fill in Beverly Harbor, Beverly, Mass	2	Cabot Street	Rip-Rap Slope

BEVERLY

HARBOR

Webkon Realty Assoc.,
William Kostas & Edward
L. Gerry, et al., Trustees
(1 Water St., Bev., Ma.)

Rest. Bldg.

Exist. Gran.
Bk. Ret.
Wall



Richards Realty Trust
Joan A. Page & Patricia
F. Pelonzi, Trustees
(5 Foster St., Bev., Ma.)

STREET

CABOT

(Rte. 1-A)

FLOOD



Alan F. Taubert

(Sheet 1 of 2 sheets)

81W-084

PLAN:



PLAN ACCOMPANYING PETITION OF THE
CITY OF BEVERLY

To construct a Granite Block Ret.
wall, platform, ramp, Pile held floats,
to dredge, and to fill in Beverly
Harbor, Beverly, Mass.

County of Essex, Mass.

Rev.: Mar. 23, 1981

Scale: 1" = 60'

LICENSE PLAN NO. 798



Approved by Department of Environmental Quality Engineers
of Massachusetts NOVEMBER 18, 1981

John J. [Signature]


COMMISSIONER
CHIEF ENGINEER

BEVERLY

HARBOR



005-001-000-086-100




Alan F. Taubert

(Sheet 1 of 2 sheets)

81W-084

PLAN:



PLAN ACCOMPANYING PETITION OF THE
CITY OF BEVERLY

To construct a Granite Block Ret.
wall, platform, ramp, Pile held floats,
to dredge, and to fill in Beverly
Harbor, Beverly, Mass.

County of Essex, Mass.

Rev.: Mar. 23, 1981



Scale: 1" = 60'

LICENSE PLAN NO. 798

Approved by Department of Environmental Quality Engineers
of Massachusetts NOVEMBER 18, 1981


John J. Skim

COMMISSIONER
CHIEF ENGINEER




Alan Taubert

SECTION "C-C" (Scale: 1"=10')



SECTION "A-A" (N.T.S.)



(Sheet 2 of 2 sheets)

LICENSE PLAN NO. 798

Approved by Department of Environmental Quality Engineer



NOVEMBER 18, 1981

005-001-000-086-100

BEVERLY

HARBOR


8" 005-001-000-086-100



WEBKON REALTY ASSOC.
(1 Water St., Beverly, MA.)

RICHARDS REALTY TRUST
(5 Foster St., Beverly, MA.)

CABOT STREET
(Rtc. 1-A)



(Sheet 1 of 2 sheets)


82W-111
PLAN ACCOMPANYING PETITION OF THE
CITY OF BEVERLY

To construct a Rip-Rap Slope, ramp,
pile held floats, to Dredge and
to fill in Beverly Harbor,
Beverly, Mass.

County of Essex, Mass.

Scale: 1" = 60'


Aug. 15, 1980
Rev: Mar. 23, 1981
Rev: July 27, 1982



LICENSE PLAN NO. 932
Approved by Department of Environmental Quality Engineer
of Massachusetts
NOVEMBER 12, 1982
COMMISSIONER
CHIEF ENGINEER
John Lantry

005-001-000-086-100


20' FLOAT 20' FLOAT 20' FLOAT 20' FLOAT 20' FLOAT 20' FLOAT 10' 105'± (To High Tide)




SECTION 'B-B'

0 15 30
(Scale: 1"=30')

82w-111



SECTION 'A-A' (Scale: 1"=10')



(Sheet 2 of 2 sheets)
REVISED - July 27, 1982



LICENSE PLAN NO. 932

Approved by Department of Environmental Quality Engineer

NOVEMBER 12, 1982

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
005-001-000-085-100	005-001-000-085-100-COE1A	82-469	USACE	Beverly	July 1982	Proposed Riprap Slops, Fill, Ramp and Pile Held Floats	2	Water Street	Proposed Riprap Slope
005-002-000-118-100	005-002-000-118-100-COE1A	52-165	USACE	Beverly	June 1952	Proposed Dredging and Jetty Construction - Beverly Harbor - Beverly, Massachusetts - Application by the DPW of Massachusetts - Division of Waterways	1	Lothrop Street	Jetty Construction
005-005-000-462-200	005-005-000-462-200-COE2A	52-165	USACE	Beverly	June 1952	Proposed Dredging and Jetty Construction - Beverly Harbor - Beverly, Massachusetts - Application by the DPW of Massachusetts - Division of Waterways	1	Lothrop Street	Jetty Construction

005-001-000 35-100



PLAN:



(SCALE IN FEET)

RIP-RAP SLOPE

PROPOSED GRANITE BLOCK WALL
FILL, RAMP & PILE HELD FLOATS

PURPOSE: PARKING AND
RECREATION FACILITY
DATUM: MEAN LOW WATER
ADJACENT PROPERTY OWNERS:
① RICHARDS REALTY TRUST
② WEBKON REALTY ASSOC.

IN: Beverly Harbor
AT: Beverly, Mass.
County of Essex
Application by: The City of Beverly
Sheet 1 of 2 sheets

State of Mass.
Revised: 7/1/81
Date: 8/15/80

Revised 7/27/82

Revised 7/27/82

BOSTON, MASS.







OWNERS

- A - SOUTH BRIDGE, DORCHESTER AVENUE, DORCHESTER, MASS.
 B - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 C - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 D - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 E - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 F - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 G - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 H - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 I - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 J - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 K - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 L - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 M - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 N - 100 W. BRIDGE STREET, DORCHESTER, MASS.
 O - 100 W. BRIDGE STREET, DORCHESTER, MASS.

NOTE

NOTE

OVER 20000 TUBES INSTALLED IN ORDER TO BE
EXPOSED TO AN EXTENSIVE SURVEY OF
THE RADIATION EXPOSURE RATES OF
THE RADIATION EXPOSURE RATES OF
50000. CUMULATIVE RADIATION EXPOSURE
EXPOSED BY THE RADIATION EXPOSURE
AND DISPOSAL OF THE RADIATION EXPOSURE
EXPOSURE RATES IN ORDER
TO EXPOSURE ARE IN ORDER AND TENDING
THE SHOW EXPOSURE BELOW THE RADIATION
EXPOSURE LOW WATER, MINUS RADIATION
EXPOSURE ABOVE THE RADIATION
EXPOSURE



**PROPOSED DREDGING & JETTY CONSTRUCTION
BEVERLY HARBOR
BEVERLY - MASS.
APPLICATION BY
DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS
DIVISION OF WATERWAYS
JUNE 1952**

Ernest Hansen

094 7794
005-005-000-462-200
005-002-000-118-100






66 JUN 14 3 39 PM '52
BOSTON, MASS.

OWNERS

1. SOUTH COAST STEVEDORE SERVICE, OFFICERS, AGENTS
2. J. M. HENNING & SONS, OFFICERS, AGENTS
3. J. M. HENNING & SONS, OFFICERS, AGENTS
4. J. M. HENNING & SONS, OFFICERS, AGENTS
5. J. M. HENNING & SONS, OFFICERS, AGENTS
6. J. M. HENNING & SONS, OFFICERS, AGENTS
7. J. M. HENNING & SONS, OFFICERS, AGENTS
8. J. M. HENNING & SONS, OFFICERS, AGENTS
9. J. M. HENNING & SONS, OFFICERS, AGENTS
10. J. M. HENNING & SONS, OFFICERS, AGENTS
11. J. M. HENNING & SONS, OFFICERS, AGENTS
12. J. M. HENNING & SONS, OFFICERS, AGENTS
13. J. M. HENNING & SONS, OFFICERS, AGENTS
14. J. M. HENNING & SONS, OFFICERS, AGENTS
15. J. M. HENNING & SONS, OFFICERS, AGENTS
16. J. M. HENNING & SONS, OFFICERS, AGENTS
17. J. M. HENNING & SONS, OFFICERS, AGENTS
18. J. M. HENNING & SONS, OFFICERS, AGENTS
19. J. M. HENNING & SONS, OFFICERS, AGENTS
20. J. M. HENNING & SONS, OFFICERS, AGENTS

NOTE

AREA SHOWN CHASE MATCHED IN 1952 TO BE
DREDGED TO AN AVERAGE DEPTH OF FIVE
FEET BELOW EXISTING SURFACE. QUANTITY OF
MATERIAL TO BE DREDGED APPROXIMATELY
50,000 CUBIC YARDS. MATERIAL TO BE
DREDGED BY THE HYDRAULIC METHOD
AND DISPOSED OF ON SHORE IN AREA
SHOWN MATCHED IN 1952.
SOUNDINGS ARE IN FEET AND TENTHS
AND SHOWN DEPTHS BELOW THE PLANE
OF MEAN LOW WATER. MINOR POINTS
SHOWN ELEVATIONS ABOVE THE SAME
PLANE.



PROPOSED DREDGING & JETTY CONSTRUCTION
BEVERLY HARBOR
BEVERLY - MASS.
APPLICATION BY
DEPARTMENT OF PUBLIC WORKS OF MASSACHUSETTS
DIVISION OF WATERWAYS
JUNE 1952

Edward J. H. H. H.

Section IV

Salem

Section IV – Community Findings – City of Salem

COMMUNITY DESCRIPTION

The City of Salem consists of a land area of 8.1 square miles out of a total area of 18.05 square miles and had a population of 40,407 in the 2000 census. The City is located on the North Shore of Massachusetts and its location can be seen on this report's cover. The estimated length of shoreline that is directly exposed to open ocean waves is 2 miles with the remaining shoreline semi-protected by offshore structures or landforms. The City is protected from major coastal storms by both natural and man-made shoreline structures that require maintenance to insure the long term protection of its coastline. The man-made and publicly owned structures that protect the City were investigated for their ability to provide adequate protection from major coastal storms. Structures have been identified as publicly owned, including coastal dunes and beaches, based on evidence of investment of public funds made to create/enhance/maintain these structures. The assessment did not include floating or pile supported structures as they are assumed not to provide any significant coastal protection from major storm events.

STRUCTURE INVENTORY

Within the City of Salem, there were 42 structures which had public or unknown ownership which provide significant coastal protection. The location of the structures can be seen in Sheets 1 through Sheet 8 in Section IV-B of this report. The structures were categorized by their type and by their structural condition based on a preliminary field assessment. The distribution of structures by type and condition can be seen in the following table:

STRUCTURE TYPE AND QUANTITY - City of Salem

Primary Structure (1)	Total Structures	Structure Condition Rating				F	Total Length
		A	B	C	D		
Bulkhead / Seawall	28		14	9	5		6540
Revetment	14		6	6	2		8030
Breakwater							
Groin / Jetty							
Coastal Dune							
Coastal Beach							
	42		20	15	7		14570

Within the above table, the total length of each type of structure is also provided. The structures are listed by the type which is providing the primary coastal protection. Many sites have multiple structure types at the same location (i.e. revetment in front of seawall). These secondary structures, although not identified within these tables, are included in the development of repair/rehabilitation costs.

The development of repair costs has been included by structure type and by condition. In the City of Salem's case there are a total of 42 structures which would require approximately \$ 11.7 million to bring all the coastal structures to "A" Rating. Most critical will be the structures in the "D" and "F" classifications as those are assumed to undergo some level of damage or failure during the next major coastal storm event. To reconstruct these structures, identified in the preliminary survey as being in poor condition, an estimated \$ 6.7 million would be required to upgrade the City's coastal protection.

STRUCTURE REPAIR / RECONSTRUCTION COST - City of Salem

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Bulkhead / Seawall	28		\$ 521,347	\$ 1,946,182	\$ 3,519,912		\$ 5,987,441
Revetment	14		\$ 950,174	\$ 1,563,414	\$ 3,206,115		\$ 5,719,703
Breakwater							\$ -
Groin / Jetty							\$ -
Coastal Dune							\$ -
Coastal Beach							\$ -
	42	\$ -	\$ 1,471,521	\$ 3,509,596	\$ 6,726,027	\$ -	\$ 11,707,144

Based on the limited research within the scope of this project research, the presumed ownership of the structures was established on an initial basis and would be subject to more intense review in future tasks. Structures identified as being owned privately were excluded from further consideration. Although ownership of the land on which the structure was located was a factor, the structure ownership was treated as a separate issue from land ownership. For the City of Salem, the breakdown of structures by assumed ownership is as follows:

STRUCTURE OWNERSHIP / REPAIR COST - City of Salem

Primary Structure (1)	Total Structures	Structure Condition Rating					Total Cost
		A	B	C	D	F	
Town Owned	29		\$ 1,398,631	\$ 2,696,001	\$ 6,726,027		\$ 10,820,659
Commonwealth of Massachusetts	2		\$ 64,178	\$ 355,555			\$ 419,733
Federal Government Owned							\$ -
Unknown Ownership	11		\$ 8,712	\$ 458,040			\$ 466,752
	42	\$ -	\$ 1,471,521	\$ 3,509,596	\$ 6,726,027	\$ -	\$ 11,707,144

The identification of presumed ownership was not based on the investigation of legal documents but relied on property ownership and from construction and regulatory documents that were found. A more detailed investigation of legal documents and agreements would be required where structure ownership is disputed. A more detailed identification of structure type, length, condition and location can be found in Section IV-B which contains Structure Assessment Reports for each individual structure found.

SUMMARY


The enclosed reports and associated documents reflects the City of Salem's coastal structure information that will eventually be input into a state-wide GIS database and will be accessible through MassGIS. This data, when compiled state-wide, will be critical in the development of both short term and long term planning for maintaining and improving Massachusetts coastal protection.

This database will also provide relatively quick access to identify available documentation for these structures as well as the ability to be updated as coastal structure improvements are made.

Section IV - Salem


Part B

Structure Assessment Reports



COASTAL STRUCTURE LOCATION PLAN

CITY OF SALEM
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



BCE Bourne Consulting Engineering
1000 Main Street
Salem, MA 01970
TEL: (508) 552-0000 FAX: (508) 552-0000




COASTAL STRUCTURE LOCATION PLAN

CITY OF SALEM
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



SCALE: 1" = 150'-0"

BCE *Bourne Consulting Engineering*
2000 Main Street
 Suite 100
 Salem, MA 01970
 Tel: (508) 552-0000 Fax: (508) 552-0000



COASTAL STRUCTURE LOCATION PLAN

CITY OF SALEM
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007





COASTAL STRUCTURE LOCATION PLAN

CITY OF SALEM
 COASTAL INFRASTRUCTURE INVENTORY
 AND ASSESSMENT PROJECT
 DECEMBER 2007




SCALE: 1" = 150'-0"

BCE Bourne Consulting Engineering
 3 Reed Street
 Bourne, MA 01906
 TEL: (508) 635-0000 FAX: (508) 635-0000




COASTAL STRUCTURE LOCATION PLAN

CITY OF SALEM
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007



**BCE**
Bourne Consulting Engineering
1000 N. Commercial Ave.
Salem, OR 97301
TEL: (503) 533-4000 FAX: (503) 533-4000



COASTAL STRUCTURE LOCATION PLAN

CITY OF SALEM
COASTAL INFRASTRUCTURE INVENTORY
AND ASSESSMENT PROJECT
DECEMBER 2007

0 150



SCALE: 1" = 150'-0"



SHEET 8

Structure Assessment Form

Town: Salem

Structure ID: 064-027-000-471-100

Key: community-map-block-parcel-structure

Property Owner:

Location:

Date:

Local

Franklin Street Park

7/12/2007

Presumed Structure Owner:

Based On Comment:

Local

Owner Name:

Earliest Structure Record:

Estimated Reconstruction/Repair Cost:

Salem

Unknown

\$398,376.00

Length:

Top Elevation:

FIRM Map Zone:

FIRM Map Elevation:

600

A2

10

Feet

Feet NAVD 88

Feet NGVD

Primary Type:

Primary Material:

Primary Height:

Revetment

Stone

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A dumped stone revetment in front of a park lawn, with over topping erosion typical. There is significant erosion.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

Structure Documents:

064-027-000-471-100-PHO1A.JPG

Structure Assessment Form

Town: SalemStructure ID: 064-028-000-018-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Kernwood Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

1967

Estimated Reconstruction/Repair Cost:

\$321,321.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
<u>535</u>		<u>A2</u>	<u>10</u>
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A dumped rubble stone and concrete debris revetment and a dumped rubble stone and debris revetment also alongside boat ramp and edge of parking lot. There is some localized unravelling of revetments.

*Condition*C*Rating*Fair*Level of Action*Moderate*Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority*II*Rating*Low Priority*Action*Future Project Consideration*Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-028-000-018-100-PHO1A.JPG

Structure Documents:

USACEJuly 1967Proposed Access064-028-000-018-100-COE1A

Structure Assessment Form

Town: **Salem**

Structure ID: 064-031-000-233-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lafayette Street

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$271,682.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
820		V3	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Bulkhead/ Seawall

Secondary Material:

Stone

Secondary Height:

Under 5 Feet



Structure Summary :

A flat face placed stone revetment parallel to slope, in good condition, but with localized crest erosion at west end. The mortared granite block cap wall has minor mortar loss and cracking. The wall is in satisfactory condition. Adjacent to the main road.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-031-000-233-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Property Owner:

Local

Location:

Old Railroad Bed

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$88,862.00

Length:

360

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

14

Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A dumped stone revetment with overgrown tree/shrub covered crest; in satisfactory condition.*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description***No Inshore Structures or Residential Dwelling Units Present**

Structure Images:

064-031-000-233-200-PHO2A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-033-000-556-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Glover Street

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$17,002.00

Length: Top Elevation:

40

Feet

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

14

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared granite block seawall leaning offshore at the top. A few blocks are dislodged, and sinkholes (5 feet long by 2 feet wide and 2 feet deep) and (3 feet long by 1 foot wide and 1 foot deep) are visible. It may fail in a major storm event. A large sewer main passes under wall. In fair condition.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-033-000-556-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Salem**

Structure ID: 064-033-000-743-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Forest River Park

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$46,754.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
110		V3	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A cast in place concrete seawall along the municipal pool wall with previously broken areas and patched in several locations. There is exposed electrical conduit at base of the wall in one location.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

064-033-000-743-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-033-000-743-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Forest River Park

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$840,180.00

Length:

335

Top Elevation:

Feet Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

14

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared rubble stone seawall that is undercut and likely to fail soon on the south side. It is in the park with lawn and is a low priority risk.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-033-000-743-200-PHO2A.JPG

064-033-000-743-200-PHO2B.JPG

Structure Documents:

Structure Assessment FormTown: **Salem**Structure ID: **064-033-000-743-300**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Forest River Park

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$446,292.00

Length:

525

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

14

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A cast in place concrete seawall with toe undercut at the east end. A section of wall is broken and leaning offshore, approximately 40 linear feet long, with other sections also leaning offshore. This is a park area.

*Condition***D***Rating***Poor***Level of Action***Major***Description*

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-033-000-743-300-PHO3A.JPG**064-033-000-743-300-PHO3B.JPG**

Structure Documents:

Structure Assessment FormStructure ID: **064-033-000-748-100**

Key: community-map-block-parcel-structure

Property Owner:

Unknown

Location:

Ocean Avenue

Date:

6/29/2007

Presumed Structure Owner:

Unknown

Based On Comment:

Owner Name:

Unknown

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$420,090.00

Length: Top Elevation: FIRM Map Zone: FIRM Map Elevation:

335

V3

14

Feet Feet NAVD 88

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone seawall with concrete cap wall in fair condition. The cap has minor hairline cracking and typical scaling. There is missing mortar from lower face stones and the stone steps are severely damaged. The street is adjacent with houses in the vicinity.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-033-000-748-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Structure ID: 064-033-000-750-100

Key: community-map-block-parcel-structure

Property Owner:

Unknown

Location:

Willow Avenue

Date:

6/29/2007

Presumed Structure Owner:

Unknown

Based On Comment:

Owner Name:

Unknown

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$37,950.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
50		V3	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:

**Structure Summary :**

A mortared granite block seawall above the beach. Some mortar is cracked and missing, and a stone dislodged. It is in fair condition. At a street end with some houses in the vicinity.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-033-000-750-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: SalemStructure ID: 064-034-000-435-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Peabody Street

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$1,049,400.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
<u>265</u>	<u></u>	<u>A2</u>	<u>10</u>
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A granite block seawall with missing stones, misalignment and bulges; in poor condition. One sinkhole 2 feet long by 6 feet wide and 4 feet deep. Remnants of steel sheet pile toe wall with corrosion holes through the sheets. Located on a vacant lot.

*Condition*D*Rating*Poor*Level of Action*Major*Description*

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

*Priority*I*Rating*None*Action*Long Term Planning Considerations*Description*No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-034-000-435-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Salem**

Structure ID: 064-034-000-435-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

South River Annex

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$180,180.00

Length:

105

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

A2

FIRM Map Elevation:

10

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Steel

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A steel U sheetpile bulkhead with cast in place concrete cap in fair condition. There are high water corrosion holes in webs and flanges at the tie rod elevation.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-034-000-435-200-PHO2A.JPG

Structure Documents:

DEP

June 11, 194

Plan Accompanying

064-034-000-435-200-LIC2A

Structure Assessment Form

Town: **Salem**

Structure ID: 064-034-000-455-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Lafayette Place

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$301,501.00

Length:

910

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

14

Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Bulkhead/ Seawall

Secondary Material:

Concrete

Secondary Height:

Under 5 Feet



Structure Summary :

A granite block revetment with concrete cap wall. A longitudinal buckle in revetment slope paving is apparent mid slope, along with joint mortar loss on the lower half of the slope. There is some pavement subsidence behind cap wall, approximately 1 inch, and a few localized areas of cap wall spalling. Adjacent to a street and in satisfactory condition.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-034-000-455-100-PHO1A.JPG

Structure Documents:

DEP

July 31, 194

Plan Accompanying

064-034-000-455-100-LIC1A

Structure Assessment Form

Town: Salem

Structure ID: 064-035-000-388-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Daniel Street

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

1997

Estimated Reconstruction/Repair Cost:

\$65,340.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
165		V3	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared granite block seawall with parapet wall at a street end. Some lower blocks dislodged and patching repairs are apparent. There is a parking lot behind wall and some mortar cracks in parapet wall. The condition is satisfactory.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-035-000-388-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Salem**Structure ID: **064-036-000-473-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Collins Cove Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$174,570.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
230		V3	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared granite block wall with concrete cap. The mortar is cracked, some mortar is missing and toe concrete is exposed. One stone has fallen out near east end. There is a lawn behind wall.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description***No Inshore Structures or Residential Dwelling Units Present**

Structure Images:

064-036-000-473-100-PHO1A.JPG

Structure Documents:

MA-DCR**September 1****Proposed Shore****064-036-000-473-100-DCR1A****DEP****June 1985****Plan Accompanying****064-036-000-473-100-LIC1A****DEP****September 2****Plan Accompanying****064-036-000-473-100-LIC1B**

Structure Assessment Form

Town: Salem

Structure ID: 064-036-000-473-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Collins Cove Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$147,147.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
245		V3	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A granite block revetment in front of a park baseball field. Crest stones have rotated, and there is some loss of joint fill stones with localized crest subsidence. It is in fair condition.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-036-000-473-200-PHO2A.JPG

Structure Documents:

DEP	September 2	Plan Accompanying	064-036-000-473-200-LIC2A
DEP	August 9, 19	Plan Accompanying	064-036-000-473-200-LIC2B
DEP	June 12, 198	Plan Accompanying	064-036-000-473-200-LIC2C

Structure Assessment FormStructure ID: **064-036-000-473-300**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Collins Cove Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$299,284.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
395		V3	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Under 5 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Under 5 Feet

Structure Summary :

A precast wave return concrete seawall with rubble stone toe protection that has unravelled in some areas. There are some voids under the concrete wall. It is at a park, and in fair condition.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-036-000-473-300-PHO3A.JPG

Structure Documents:

MA-DCR**September 1****Proposed Shore****064-036-000-473-300-DCR3A**

Structure Assessment FormStructure ID: **064-036-000-473-400**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Collins Cove Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$74,382.00

Length:

175

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

13

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared rubble stone wall with missing mortar, with a sinkhole 20 feet by 4 feet, also a sinkhole in street patched, and a sinkhole in pavement 8 feet by 3 feet. It is in fair condition. Located at a street end park.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-036-000-473-400-PHO4A.JPG

Structure Documents:

MA-DCR**September 1****Proposed Shore****064-036-000-473-400-DCR4A**

Structure Assessment Form

Town: Salem

Structure ID: 064-036-000-474-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Collins Street

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$695,970.00

Length:

555

Top Elevation:

Feet

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

13

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared rubble stone wall with 4 foot high concrete cap with some mortar loss. There is some cap cracking and spalling. It is in fair condition with some damage to the stairs. The street is located behind the wall.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-036-000-474-100-PHO1A.JPG

Structure Documents:

MA-DCR

September 1

Proposed Shore

064-036-000-474-100-DCR1A

Structure Assessment Form

Town: **Salem**Structure ID: **064-037-000-042-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Hubon Street

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$37,950.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
25		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared granite block wall that is failing, leaning offshore and stones are falling out with sinkholes behind. The building on top of wall immediately adjacent to the north end has cracks in concrete block joints at building corner over wall.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

064-037-000-042-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-041-000-300-100

Key: community-map-block-parcel-structure

Property Owner:

Unknown

Location:

Turner Street

Date:

7/12/2007

Presumed Structure Owner:

Unknown

Based On Comment:

Owner Name:

Unknown

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$8,712.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
40		V3	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Under 5 Feet



Structure Summary :

A mortared granite block wall with granite block revetment, in satisfactory condition. Some revetment stones may have rotated. The revetment is in fair condition.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-041-000-300-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-041-000-307-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Hardy Street

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$6,270.00

Length:

25

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

13

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A dry set granite block wall at a street end, in satisfactory condition with a few chinking stones missing.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-041-000-307-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Salem**

Structure ID: 064-041-000-330-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Daniels Court

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$3,267.00

Length:

15

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

13

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

Under 5 Feet



Structure Summary :

A mortared granite block seawall with rubble toe stone revetment at a street end. The wall is in satisfactory condition and the revetment in fair condition.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-041-000-330-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-042-000-003-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Szetela Lane

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$2,807,739.00

Length: Top Elevation: FIRM Map Zone: FIRM Map Elevation:

1795

V3

13

Feet

Feet NAVD 88

Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A dumped stone rubble revetment with unravelled areas. It has crest over topping erosion and a lawn and path behind.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-042-000-003-100-PHO1A.JPG

064-042-000-003-100-PHO1B.JPG

Structure Documents:

DEP

September 1

Plan Accompanying

064-042-000-003-100-LIC1A

Structure Assessment Form

Town: **Salem**

Structure ID: 064-043-000-001-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Winter Island

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$21,252.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
140		V3	13
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared stone seawall with concrete cap. There is some mortar deterioration, efflorescence and vegetation. There is also some concrete cap deterioration/spalls. It is in a park and in satisfactory condition.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-043-000-001-100-PHO1A.JPG

Structure Documents:

Structure Assessment FormStructure ID: **064-043-000-001-200**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Winter Island

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

1995

Estimated Reconstruction/Repair Cost:

\$192,535.00

Length:

780

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

13

Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A placed stone revetment along park shore and boat ramp, in good condition.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-043-000-001-200-PHO2A.JPG

Structure Documents:

DEP**June 1995****Plan to Accompany****064-043-000-001-200-LIC2A**

Structure Assessment Form

Town: **Salem**

Structure ID: 064-043-000-001-300

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Winter Island

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$162,162.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
270		V2	14
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A dumped rubble stone revetment with a lawn area behind. There is some soil erosion along crest and dislodged stones. It is in fair condition.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-043-000-001-300-PHO3A.JPG

Structure Documents:

Structure Assessment Form

Town: **Salem**Structure ID: **064-043-000-001-400**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Winter Island

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$418,070.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
535		V2	18
Feet	Feet NAVD 88		Feet NGVD

Primary Type:	Primary Material:	Primary Height:
Revetment	Stone	10 to 15 Feet
Secondary Type:	Secondary Material:	Secondary Height:



Structure Summary :

A small stone placed revetment in fair condition. There is a park lawn behind with some toe unravelling. Some overtopping erosion with two localized unravelled areas, approximately 10 feet by 15 feet each.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-043-000-001-400-PHO4A.JPG

064-043-000-001-400-PHO4B.JPG

Structure Documents:

Structure Assessment FormStructure ID: **064-043-000-001-500**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Winter Island

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$159,159.00

Length:

265

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V2

FIRM Map Elevation:

18

Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A placed stone revetment with toe typically unravelled and crest unravelled with over-topping erosion. There is a park shrub area behind and the revetment is in fair condition.

*Condition***C***Rating***Fair***Level of Action***Moderate***Description*

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-043-000-001-500-PHO5A.JPG

Structure Documents:

Structure Assessment Form

Town: **Salem**

Structure ID: 064-044-000-037-100

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

Salem State College Marine Lab

Date:

6/29/2007

Presumed Structure Owner:

State

Based On Comment:

Owner Name:

Salem State College Marine Lab

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$355,555.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
455		A4	11
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A tidal dam at Cat Cove. A stone dike with concrete cap and with some steel sheet pile at the weir structure. It is missing some revetment joint concrete between stones and there is some scaling on concrete, and one spill. In fair condition.

Condition

C

Rating

Fair

Level of Action

Moderate

Description

Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide addition material for full protection and extended life.

Priority

III

Rating

Moderate Priority

Action

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

064-044-000-037-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-044-000-037-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Cat Cove

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$100,320.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
400		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A cast in place concrete seawall with cantilever sidewalk in satisfactory condition. There are a few cracks and scaling. The wall cap has some spalls and delamination with rebar exposed. The wall is adjacent to the road.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-044-000-037-200-PHO2A.JPG

Structure Documents:

Structure Assessment Form

Town: **Salem**Structure ID: **064-044-000-037-300**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Cat Cove

Date:

6/29/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$101,970.00

Length:

250

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

A2

FIRM Map Elevation:

10

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

10 to 15 Feet

Structure Summary :

A mortared stone seawall with concrete cap, cracks in cap, and a sidewalk subsidence behind the wall. The wall continues inland away from water along the road and is not mapped. It has a toe stone revetment. Both are in satisfactory condition.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***III***Rating***Moderate Priority***Action*

Consider for Active Project Improvement Listing

Description

Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)

Structure Images:

064-044-000-037-300-PHO3A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-044-000-037-400

Key: community-map-block-parcel-structure

Property Owner:

State

Location:

Cat Cove

Date:

6/29/2007

Presumed Structure Owner:

State

Based On Comment:

Owner Name:

Salem State College

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$64,178.00

Length: Top Elevation: FIRM Map Zone: FIRM Map Elevation:

260

A2

10

Feet

Feet NAVD 88

Feet NGVD

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

Over 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A stone revetment with smaller toe stone and possible a repair overlay of smaller stone. It is near a driveway and lab buildings. It is in satisfactory condition.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-044-000-037-400-PHO4A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-044-000-146-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Columbus Avenue

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$71,346.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
470		A2	10
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared rubble stone wall with some cracked mortar; in satisfactory condition. There are 6 small sinkholes in the bituminous walk, approximately 6 inches in diameter. There is a walk and grass strip, then road behind.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-044-000-146-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Salem**

Structure ID: 064-045-000-079-100

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Beach Avenue

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$15,206.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
180		V2	15
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared stone seawall with concrete cap in good condition. A sidewalk and street are behind with one cap spall and some mortar cracking.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-045-000-079-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: **Salem**Structure ID: **064-045-000-089-100**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Willows Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$32,525.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
385		V3	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

Under 5 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A cast in place concrete seawall at top of beach in good condition. The sidewalk and street are behind. There is one vertical crack with a few minor spalls.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***II***Rating***Low Priority***Action***Future Project Consideration***Description*

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-045-000-089-100-PHO1A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-045-000-089-200

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Willows Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

2007

Estimated Reconstruction/Repair Cost:

\$1,146,090.00

Length:	Top Elevation:	FIRM Map Zone:	FIRM Map Elevation:
755		V3	12
Feet	Feet NAVD 88		Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared stone rubble seawall with concrete and granite cap. It is under repair. There are sinkholes and it is leaning offshore. There are some stones displaced and it is in poor condition.

Condition

D

Rating

Poor

Level of Action

Major

Description

Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm. Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm. Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-045-000-089-200-PHO2A.JPG

Structure Documents:

Salem

April 2007

Seawall Plan &

064-045-000-089-200-TWN

Structure Assessment FormTown: **Salem**Structure ID: **064-045-000-089-300**

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Willows Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$20,493.00

Length:

135

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V3

FIRM Map Elevation:

12

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A mortared rubble stone wall in satisfactory condition. The lawn and path are behind the wall.

*Condition***B***Rating***Good***Level of Action***Minor***Description*

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

*Priority***I***Rating***None***Action***Long Term Planning Considerations***Description*

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-045-000-089-300-PHO3A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-045-000-089-400

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Willows Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$12,276.00

Length: Top Elevation: FIRM Map Zone: FIRM Map Elevation:

60

V2

15

Feet

Feet NAVD 88

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Stone

Primary Height:

Under 5 Feet

Secondary Type:

Revetment

Secondary Material:

Stone

Secondary Height:

5 to 10 Feet



Structure Summary :

A granite block seawall with granite block placed stone revetment with concrete infill. It is in satisfactory condition and includes the pier abutment.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-045-000-089-400-PHO4A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-045-000-089-500

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Willows Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

1958

Estimated Reconstruction/Repair Cost:

\$13,794.00

Length:

55

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V2

FIRM Map Elevation:

15

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A cast in place concrete seawall with repair mass concrete in front of the original spalled concrete. It is in a park area and is in satisfactory condition.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-045-000-089-500-PHO5A.JPG

Structure Documents:

MA-DCR

September 1

Proposed Shore

064-045-000-089-500-DCR5A

Structure Assessment Form

Town: **Salem**

Structure ID: 064-045-000-089-600

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Willows Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$48,576.00

Length:

320

Feet

Top Elevation:

Feet NAVD 88

FIRM Map Zone:

V2

FIRM Map Elevation:

15

Feet NGVD

Primary Type:

Bulkhead/ Seawall

Primary Material:

Concrete

Primary Height:

5 to 10 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A cast in place concrete seawall with park road behind. It has weathered concrete, with some cracks and toe exposed at south end. It is in satisfactory condition.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

II

Rating

Low Priority

Action

Future Project Consideration

Description

Inshore Structures Present with Limited potential for Significant Infrastructure Damage

Structure Images:

064-045-000-089-600-PHO6A.JPG

Structure Documents:

Structure Assessment Form

Town: Salem

Structure ID: 064-045-000-089-700

Key: community-map-block-parcel-structure

Property Owner:

Local

Location:

Willows Park

Date:

7/12/2007

Presumed Structure Owner:

Local

Based On Comment:

Owner Name:

Salem

Earliest Structure Record:

Unknown

Estimated Reconstruction/Repair Cost:

\$31,416.00

Length: 200 Feet Top Elevation: FIRM Map Zone: V2 FIRM Map Elevation: 15 Feet NGVD
 Feet Feet NAVD 88

Primary Type:

Revetment

Primary Material:

Stone

Primary Height:

10 to 15 Feet

Secondary Type:

Secondary Material:

Secondary Height:



Structure Summary :

A rubble stone revetment in front of park lawn area in satisfactory condition.

Condition

B

Rating

Good

Level of Action

Minor

Description

Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure.

Priority

I

Rating

None

Action

Long Term Planning Considerations

Description

No Inshore Structures or Residential Dwelling Units Present

Structure Images:

064-045-000-089-700-PHO7A.JPG

Structure Documents:

Section IV - Salem

Part C

Structure Photographs

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
064-027-000-471-100	064-027-000-471-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-028-000-018-100	064-028-000-018-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-031-000-233-100	064-031-000-233-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-031-000-233-200	064-031-000-233-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-033-000-556-100	064-033-000-556-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-033-000-743-100	064-033-000-743-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-033-000-743-200	064-033-000-743-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-033-000-743-200	064-033-000-743-200-PHO2B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-033-000-743-300	064-033-000-743-300-PHO3A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-033-000-743-300	064-033-000-743-300-PHO3B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-033-000-748-100	064-033-000-748-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-033-000-750-100	064-033-000-750-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-034-000-435-100	064-034-000-435-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-034-000-435-200	064-034-000-435-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-034-000-455-100	064-034-000-455-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-035-000-388-100	064-035-000-388-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-036-000-473-100	064-036-000-473-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-036-000-473-200	064-036-000-473-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-036-000-473-300	064-036-000-473-300-PHO3A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-036-000-473-400	064-036-000-473-400-PHO4A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-036-000-474-100	064-036-000-474-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-037-000-042-100	064-037-000-042-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
064-041-000-300-100	064-041-000-300-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-041-000-307-100	064-041-000-307-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-041-000-330-100	064-041-000-330-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-042-000-003-100	064-042-000-003-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-042-000-003-100	064-042-000-003-100-PHO1B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-043-000-001-100	064-043-000-001-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-043-000-001-200	064-043-000-001-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-043-000-001-300	064-043-000-001-300-PHO3A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-043-000-001-400	064-043-000-001-400-PHO4A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-043-000-001-400	064-043-000-001-400-PHO4B.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-043-000-001-500	064-043-000-001-500-PHO5A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-044-000-037-100	064-044-000-037-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-044-000-037-200	064-044-000-037-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-044-000-037-300	064-044-000-037-300-PHO3A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-044-000-037-400	064-044-000-037-400-PHO4A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-044-000-146-100	064-044-000-146-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-045-000-079-100	064-045-000-079-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-045-000-089-100	064-045-000-089-100-PHO1A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-045-000-089-200	064-045-000-089-200-PHO2A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-045-000-089-300	064-045-000-089-300-PHO3A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-045-000-089-400	064-045-000-089-400-PHO4A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-045-000-089-500	064-045-000-089-500-PHO5A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
064-045-000-089-600	064-045-000-089-600-PH06A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey
064-045-000-089-700	064-045-000-089-700-PH07A.JPG		Bourne Consulting Engineering		October 2007	DIGITAL IMAGE	1	Structure Location	Structure Condition Photo at Time of Survey

Massachusetts Coastal Infrastructure and Assessment



064-027-000-471-100-PHO1A



064-028-000-018-100-PHO1A



064-031-000-233-100-PHO1A



064-031-000-233-200-PHO2A



064-033-000-556-100-PHO1A



064-033-000-743-100-PHO1A



064-033-000-743-200-PHO2A



064-033-000-743-200-PHO2B



064-033-000-743-300-PHO3A

Massachusetts Coastal Infrastructure and Assessment



064-033-000-743-300-PHO3B



064-033-000-748-100-PHO1A



064-033-000-750-100-PHO1A



064-034-000-435-100-PHO1A



064-034-000-435-200-PHO2A



064-034-000-455-100-PHO1A



064-035-000-388-100-PHO1A



064-036-000-473-100-PHO1A



064-036-000-473-200-PHO2A

Massachusetts Coastal Infrastructure and Assessment



064-036-000-473-300-PHO3A



064-036-000-473-400-PHO4A



064-036-000-474-100-PHO1A



064-037-000-042-100-PHO1A



064-041-000-300-100-PHO1A



064-041-000-307-100-PHO1A



064-041-000-330-100-PHO1A



064-042-000-003-100-PHO1A



064-042-000-003-100-PHO1B

Massachusetts Coastal Infrastructure and Assessment



064-043-000-001-100-PHO1A



064-043-000-001-200-PHO2A



064-043-000-001-300-PHO3A



064-043-000-001-400-PHO4A



064-043-000-001-400-PHO4B



064-043-000-001-500-PHO5A



064-044-000-037-100-PHO1A



064-044-000-037-200-PHO2A



064-044-000-037-300-PHO3A


Massachusetts Coastal Infrastructure and Assessment




064-044-000-037-400-PHO4A



064-044-000-146-100-PHO1A



064-045-000-079-100-PHO1A



064-045-000-089-100-PHO1A



064-045-000-089-200-PHO2A




064-045-000-089-300-PHO3A



064-045-000-089-400-PHO4A



064-045-000-089-500-PHO5A



064-045-000-089-600-PHO6A



064-045-000-089-700-PHO7A

Section IV - Salem

Part D

Structure Documents

CITY DOCUMENT LIST

MA DCR - DOCUMENT LIST

MA DEP – Ch 91 DOCUMENT LIST

- Copies of License Documents

USACE – PERMIT DOCUMENT LIST


- Copies of Permit Documents

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
064-045-000-086-200	064-045-000-086-200-TWN		Salem	Salem	April 2007	Seawall Plan & Profile; Seawall Improvement Project; Salem Willows Park	2	Willows Park, Salem	Vine Associates full size drawings generally depicting seawall reconstruction at Salem Willows Park - field observation included this project is currently under construction.

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
064-036-000-473-100	064-036-000-473-100-DCR1A	1998	MA-DCR	Salem	September 1958	Proposed Shore Protection - Salem, Massachusetts - New Concrete Wall and Repairs to Existing Stone Seawall - Collins Cove - Prepared for the DPW of Massachusetts - Division of Waterways	3	Collins Cove	Seawalls
064-036-000-473-300	064-036-000-473-300-DCR3A	1998	MA-DCR	Salem	September 1958	Proposed Shore Protection - Salem, Massachusetts - New Concrete Wall and Repairs to Existing Stone Seawall - Collins Cove - Prepared for the DPW of Massachusetts - Division of Waterways	19983	Collins Cove	Seawalls
064-036-000-473-400	064-036-000-473-400-DCR4A	1998	MA-DCR	Salem	September 1958	Proposed Shore Protection - Salem, MA - New Concrete Seawall and Repairs to Existing Stone Seawall - Collins Cove - Prepared for the DPW of Massachusetts - Division of Waterways	3	Collins Cove	Seawalls
064-036-000-474-100	064-036-000-474-100-DCR1A	1998	MA-DCR	Salem	September 1958	Proposed Shore Protection - Salem, MA - New Concrete Wall and Repairs to Existing Stone Seawall - Collins Cove - Prepared for the DPW of Massachusetts - Division of Waterways	3	Collins Cove	Seawalls
064-045-000-089-500	064-045-000-089-500-DCR5A	1999	MA-DCR	Salem	September 1958	Proposed Shore Protection - Salem, MA - Concrete Seawall at Pier - Prepared for the DPW of Massachusetts - Division of Waterways	4	Salem Willows	Seawall

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
064-034-000-435-200	064-034-000-435-200-LIC2A	2372	DEP	Salem	June 11, 1941	Plan Accompanying Petition of City of Salem To Construct a Steel Sheet Pile Bulkhead, Concrete Conduit, Tide Gate Chamber and Solid Filling in South River	1	South River	Bulkhead
064-034-000-455-100	064-034-000-455-100-LIC1A	2219	DEP	Salem	July 31, 1940	Plan Accompanying Petition of City of Salem For Riprap Fills and Pier Palmers Cove	2	Palmers Cove	Riprap
064-036-000-473-100	064-036-000-473-100-LIC1A	1254	DEP	Salem	June 1995	Plan Accompanying Petition of City of Salem, Massachusetts - To Construct and Maintain Stone Riprap in Collins Cove, City of Salem, County of Essex, Mass.	1	Collins Cove	Riprap
064-036-000-473-100	064-036-000-473-100-LIC1B	2002	DEP	Salem	September 27, 1938	Plan Accompanying Petition of Salem to Build Wall and Fill Flats	1	Collins Cove	Seawall
064-036-000-473-200	064-036-000-473-200-LIC2A	2002	DEP	Salem	September 27, 1938	Plan Accompanying petition of City of Salem to build Wall and Fill Flats Collins Cove	1	Collins Cove	Revelment
064-036-000-473-200	064-036-000-473-200-LIC2B	2102	DEP	Salem	August 9, 1939	Plan Accompanying Petition of City of Salem To Build Wall, Float and Fill Flats Collins Cove	2	Collins Cove	Revelment
064-036-000-473-200	064-036-000-473-200-LIC2C	1254	DEP	Salem	June 12, 1985	Plan Accompanying Petition of City of Salem, Mass to Construct and Maintain Stone Riprap in Collins Cove	1	Collins Cove	Riprap
064-042-000-003-100	064-042-000-003-100-LIC1A	2525	DEP	Salem	September 1, 1942	Plan Accompanying Petition of City of Salem to Make Solid Fill in Collins Cove	1	Collins Cove	Revelment
064-043-000-001-200	064-043-000-001-200-LIC2A	4729	DEP	Salem	June 1995	Plan to Accompany Petition of Commonwealth of Massachusetts Public Access Board - To Construct and to Maintain Concrete Boat Ramp, Riprap, Piles and Float Systems at Winter Island in Salem Harbor, City of Salem, Essex County, Massachusetts	3	East of Cat Cove	Riprap

064-034-000-435-200



PLAN ACCOMPANYING PETITION OF
CITY OF SALEM
TO CONSTRUCT A STEEL SHEET PILE
BULKHEAD, CONCRETE CONDUIT, TIDE
GATE CHAMBER AND SOLID FILLING IN
SOUTH RIVER
SALEM, MASS.


Scotford & Thorndike, Engineers, Boston, Mass.
MAY 1941

NO. 2372
APPROVED BY DEPARTMENT OF PUBLIC WORKS
JUNE 11, 1941

Paul C. Ryan
COMMISSIONER OF PUBLIC WORKS
Richard W. Hartz
ASSOCIATE COMMISSIONERS
DIRECTOR - DIVISION OF WATERWAYS

064-034-000-455-100

SHEET 1 OF 2 SHEETS







IN ACCOMPANYING PETITION OF
CITY OF SALEM
OR RIPRAP FILL & PIER
PALMERS COVE
SALEM, MASS.

NO. 2219
APPROVED BY DEPARTMENT OF PUBLIC WORKS
JULY 31, 1940


[Signature]
COMMISSIONER OF PUBLIC WORKS
[Signature]
ASSOCIATE COMMISSIONERS
[Signature]
DIRECTOR - DIVISION OF WATERWAYS

[Signature]
CITY ENGINEER

064-036-000-473-100



PLAN
SCALE 1"=100'



ELEVATIONS
SCALE 1"=40'




84W-203

PERMITTING PETITION OF
CITY OF SALEM, MASS.
TO CONSTRUCT AND MAINTAIN
STONE RIPRAP
IN COLLINS COVE

LICENSE PLAN NO. 1254
Approved by Department of Environmental Quality Engineering
of Massachusetts June 18, 1985
[Signature]
COMMISSIONER
CHIEF ENGINEER

064-036-000-473-100
064-036-000-473-200

SHEET 1 OF 1 SHEETS



PLAN ACCOMPANYING PETITION OF
CITY OF SALEM
TO BUILD WALL & FILL FLATS
COLLINS COVE
SALEM, MASS.

NO. 2002
APPROVED BY DEPARTMENT OF PUBLIC WORKS
SEPTEMBER 27, 1938




Up Kallahan
Richard K. Hale COMMISSIONER OF PUBLIC WORKS

Frank O. Mason
CITY ENGINEER

Walter P. [Signature] ASSOCIATE COMMISSIONERS

064-036-000-473-100
064-036-000-473-200

SHEET 1 OF 1 SHEETS



PLAN ACCOMPANYING PETITION OF
CITY OF SALEM
TO BUILD WALL & FILL FLATS
COLLINS COVE
SALEM, MASS.

NO. 2002
APPROVED BY DEPARTMENT OF PUBLIC WORKS
SEPTEMBER 27, 1938


Up Kallabary
Richard H. Hale
COMMISSIONER OF PUBLIC WORKS
Frank O. Mason
CITY ENGINEER
W. H. P. [unclear]
ASSOCIATE COMMISSIONERS

064-0316-000-473-200


SHEET 1 OF 2 SHEETS



SECTION A-A ELEVATION
SCALE 1" = 4' 5" FT.



PLAN
SCALE 1" = 200' FT.
DATUM M.L.W.



KEY MAP
SCALE 1" = 1000' FT.
FROM U.S. CHART NO. 240



PLAN ACCOMPANYING PETITION OF

CITY OF SALEM

TO BUILD WALL, FLOAT & FILL FLATS
COLLINS COVE
SALEM, MASS.

Frank C. Phynore
CITY ENG.





NO. 2102
APPROVED BY DEPARTMENT OF PUBLIC WORKS
AUGUST 9, 1939

COMMISSIONER OF PUBLIC WORKS
ASSOCIATE COMMISSIONERS
DIRECTOR - DIVISION OF WATERWAYS

Charles C. Gifford
Wm. W. Kistner

SLEETS 2 OF 2 SHEETS






84W-203
 PETITION OF
CITY OF SALEM, MASS.
 TO CONSTRUCT AND MAINTAIN
 STONE RIPRAP
 IN COLLINS COVE, CITY
 OF SALEM, COUNTY OF ESSEX, MASS.



LICENSE PLAN NO. 1254
 Approved by Department of Environmental Quality Engineering
 of Massachusetts June 12, 1985
 Commissioner
 Chief Engineer

064-036-000-473-200

064-042-000-003-100



ELEVATIONS ABOVE MLW





NAMES OF OWNERS

BOSTON & MAINE R.R.	NORTH STATION, BOSTON, MASS.
ABRAHAM LIVINGSTON	271 LAFAYETTE ST., SALEM, MASS.
FRANKLIN B. BAKER ETAL	5 WARREN AVE., DANVERS, MASS.
JOHN J. O'BRIEN	25 WISTERIA ST., SALEM, MASS.
WILLIAM H. BAGLEY	11 FORT AVE., SALEM, MASS.
JOHN A. WILLIAMS	13 FORT AVE., SALEM, MASS.
WILLIAM A. HARRIGAN ETAL	BLOCK HOUSE SQ., SALEM, MASS.

PLAN ACCOMPANYING PETITION OF
CITY OF SALEM
TO MAKE SOLID FILL IN COLLINS COVE
SALEM, MASS.

NO. 2525
APPROVED BY DEPARTMENT OF PUBLIC WORKS
SEPTEMBER 1, 1942

Frederick A. Thompson COMMISSIONER OF PUBLIC WORKS
George W. Gahagan ASSOCIATE COMMISSIONER
Chas. E. Sullivan DIRECTOR DIVISION



PLAN TO ACCOMPANY PETITION OF
COMMONWEALTH OF MASSACHUSETTS
PUBLIC ACCESS BOARD

TO CONSTRUCT AND TO MAINTAIN CONCRETE BOAT
RAMP, RIP-RAP, PILES & FLOAT SYSTEMS AT
WINTER ISLAND IN SALEM HARBOR, CITY OF
SALEM, ESSEX COUNTY, MASSACHUSETTS
NOVEMBER, 1994

COASTAL ENGINEERING CO., INC.
ORLEANS, MASSACHUSETTS

~~LICENSE PLAN NO. 4729~~ SHT. 1 OF 3 SHTS.


Approved by Department of Environmental Protection
of Massachusetts

COMMISSIONER
DIVISION DIRECTOR
SECTION CHIEF

SECTION CHIEF





LICENSE PLAN NO. 4729
Approved by Department of Environmental Protection
Date: **JUN 26 1995**



SHT. 2 OF 3 SHT

COASTAL ENGINEERING CO., INC.

NOVEMBER , 1994



LICENSE PLAN NO. 4729
Approved by Department of _____

Approved by Department of Environmental Protection
Date: JUN 23 1995

Date: JUN 26 1995

COASTAL ENGINEERING CO., INC.
ORLEANS, MASSACHUSETTS 01901

BCE Structure No	Document No	Contract/ Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description
064-028-000-018-100	064-028-000-018-100-COE1A	67-221	USACE	Salem	July 1967	Proposed Access Ramp and Facilities - Danvers River - Salem, Massachusetts - Application by DPW of Massachusetts - Division of Waterways	2	Kernwood Avenue	Revetment

067 0198


064-028-000-018-100

SHEET 1 OF 2

NOTE

ELEVATIONS ARE IN FEET
AND TENTHS ABOVE THE
PLANE OF MEAN LOW WATER
MINUS FIGURES SHOW DEPTHS
BELOW THE SAME PLANE


LOCATION OF PROPOSED
WORK SHOWN IN RED



KEY PLAN

1:20000

0 500 1000 1500 2000



**PROPOSED ACCESS RAMP
& FACILITIES
DANVERS RIVER
SALEM, MASS**
Application By
DEPARTMENT OF PUBLIC WORKS
OF MASSACHUSETTS
DIVISION OF WATERWAYS

PLAN

SCALE 1"=80'




JULY 1967

John J. Harmon
DEPUTY CHIEF

067 0199

064-028-000-018-100

SHEET 2 OF 2



PROPOSED ACCESS RAMP
& FACILITIES
DANVERS RIVER
SALEM MASS
Application By
DEPARTMENT OF PUBLIC WORKS
OF MASSACHUSETTS
DIVISION OF WATERWAYS

JULY 1967

DEPUTY CHIEF

ENGINEER WATERWAYS

ACC. NO. 04656-B