



TIDE Gateway

Tidegate Inventory and Data Evaluation Gateway

Final Report

April
2016

Revised
December
2017

Prepared by:

Geosyntec 
consultants

12/17 Revised by MassBays

Prepared for:



Contents

| | |
|------------------------------------------|----|
| I. INTRODUCTION | 1 |
| A. Project Background | 1 |
| B. Scope | 1 |
| II. DATA INVENTORY AND GEODATABASE | 3 |
| A. Initial Data Inventory..... | 3 |
| B. Field Protocols and Inspections | 3 |
| C. Final Geodatabase | 7 |
| D. Training..... | 7 |
| E. Data Analysis and Findings..... | 8 |
| General Findings and Statistics | 8 |
| Condition Findings..... | 8 |
| Restoration Findings..... | 13 |
| Miscellaneous Findings | 17 |
| III. TIDEGateway | 22 |
| IV. RECOMMENDATIONS | 23 |

List of Appendices

Appendix A. Initial Data Request

Appendix B. Data Inventory Updates and Preliminary Data Dictionary

Appendix C. Municipal Contact Summary

Appendix D. Field Data Collection & Database Update Protocols

Appendix E. Initial Tide Gate Site Visit List

Appendix F. Field Visit and Database Update Log

Appendix G. Exploratory Data Analysis Findings

Appendix H. List of Current Data Gaps

Appendix I. Selected Field Photograph Findings Log

List of Tables

Table 1. Field visit personnel log

Table 2. Summary of tide gates visited by region

Table 3. Tide gate and culvert condition findings

Table 4. Selected tidal restriction restoration findings

Table 5. Action item locations

Table 6. Miscellaneous observations of interest

List of Figures

Figure 1. MassBays Program Planning Area

Figure 2. Initial data inventory development flow chart

Figure 3. Field protocol and field visit flow chart

Figure 4. Depiction of tide gates visited during field effort or added-on based on RC correspondence



List of Acronyms


| | |
|----------|--------------------------------------------------|
| CZM | Massachusetts Office of Coastal Zone Management |
| AC | Advisory Committee |
| DEM | Digital Elevation Model |
| DER | Massachusetts Division of Ecological Restoration |
| MassBays | Massachusetts Bays National Estuary Program |
| NOAA | National Oceanic and Atmospheric Administration |
| QA | Quality Assurance |
| RTK | Real Time Kinematic |
| ZOI | Zone of Influence |

I. INTRODUCTION

A. Project Background

The purpose of TIDEGateway is to serve as a comprehensive and easy-to-use web-based platform for information and planning tools related to tide gates in the Massachusetts Bays region (Figure 1). The TIDEGateway includes:

- Geodatabase containing all known tide gate information, including locations, attributes, and related documents. The geodatabase contains a robust source tracking tool and interface which enables users to add new tide gates or modify existing tide gates when new information becomes available.
- Geospatial viewer which incorporates wetland delineation and allows users to locate and assess existing tide gates in relation to wetland ecology and FEMA floodplains, the better to inform the management of these structures.



TIDEGateway provides a fully integrated suite of GIS maps, attributes, data, modeling projections and planning tools.

B. Scope

The purpose of this report is twofold: 1) to summarize the project approach and results of all tasks that were performed during development of the TIDEGateway geodatabase and geospatial viewer, and 2) to provide recommendations and next steps.

Project tasks were performed under the direction of the Massachusetts Bay National Estuary Program (MassBays), the Massachusetts Office of Coastal Zone Management (CZM), their Regional Coordinators (RCs), and an Advisory Committee (AC) comprised of the National Oceanic and Atmospheric Administration (NOAA), Massachusetts Division of Ecological Restoration (DER) and others.

What is a Tide Gate?

For the TIDEGateway project, tide gates are defined as “*any conveyance of tidal flow with the ability to passively or actively manipulate water flow.*” This definition includes self-regulating tide gates, manually controlled devices, or passive control structures such as flappers. Structures not included in this definition include, but are not limited to, conveyances installed for the sole purpose of conveying storm drainage.





Figure 1. MassBays Program Planning Area

II. DATA INVENTORY AND GEODATABASE

The sections below summarize the methods used to perform the initial data inventory and to develop the geodatabase. An analysis of findings is also presented.

A. Initial Data Inventory

The initial data inventory involved the steps summarized in the flow chart below (Figure 2).




Figure 2. Initial data inventory development flow chart

The steps presented in Figure 2 are explained in detail in the following previously submitted project update memorandums:

- Gather existing information: “TIDEGateway – Initial Data Request for Data Inventory” dated 4/1/2015 (Appendix A).
- Obtain input from RC’s and develop preliminary attribute list: “TIDEGateway – Data Inventory Updates and Discussion Points” dated 5/8/2015 (Appendix B).
- Obtain additional data from municipal contacts: “TIDEGateway – Data Inventory Municipal Contact Summary” dated 9/9/2015 (Appendix C).

B. Field Protocols and Inspections

Upon completion of the initial data inventory, the field data collection phase of the project commenced as summarized in the flow chart below (Figure 4).




Figure 3. Field protocol and field visit flow chart

- Field Protocols:** Field protocols for tide gate data collection were developed to provide a consistent methodology for MassBays, CZM and its partner agencies. The protocols include sections on safety, initial site selection and planning, data collection and entry, and upload and quality assurance (QA) procedures. The field protocols were designed to be performed in the absence of a GPS unit or other specialized equipment. The field protocols for tide gate data collection are included as Appendix D of this document.
- Field Preparation:** A list of tide gates selected for field visit was developed based on the initial tide gate data inventory. The list was developed with input from the AC and included a distribution of tide gates across all of the MassBays regions. Tide gates were primarily selected for field visits based on data availability (i.e. tide gates with the least amount of existing data were prioritized over tide gates with the most existing data). Appendix E provides the initial field visit list. The list was compiled on 10/12/2015 and organizes the tide gates by a unique identifier, town, and region. The list includes a “comments” column describing the reason each tide gate was selected (or was not selected) for a field visit.
- Field Visits:** Field visits were then performed in each MassBays region between 11/2/2015 and 12/18/2015 over the course of five field days. Regional CZM staff, MassBays RC’s, and/or members of the AC were present during each field day to provide input and to allow for training of agency staff on the field protocols for tide gate data collection. A field visit personnel log is provided in Table 1.

Table 1. Field visit personnel log

| Day | Region | Name | Organization |
|------------|----------------------------|-------------------|---------------------------------------------|
| 11/2/2015 | Metro Boston | Lisa Engler | CZM |
| | | Franz Ingelfinger | DER |
| | | David Roman | Geosyntec |
| | | Bob Hartzel | Geosyntec |
| 11/3/2015 | Metro Boston & South Shore | Jason Burtner | CZM |
| | | David Roman | Geosyntec |
| | | Hayley O'Grady | Geosyntec |
| 11/4/2015 | Metro Boston & South Shore | Jason Burtner | CZM |
| | | David Roman | Geosyntec |
| | | Hayley O'Grady | Geosyntec |
| 12/2/2015 | Upper & Lower North Shore | Bob Boeri | CZM |
| | | Kathryn Glenn | CZM |
| | | Barbara Warren | Salem Sound Coastwatch |
| | | Peter Phippen | MassBays |
| | | David Roman | Geosyntec |
| 12/18/2015 | Cape Cod | Steve McKenna | CZM |
| | | Jo Ann Muramoto | MassBays / Association to Preserve Cape Cod |
| | | April Wobst | Association to Preserve Cape Cod |
| | | David Roman | Geosyntec |
| | | Taylor Walter | Geosyntec |

Once the field investigations were complete, additional tide gates were added and/or modified based on RC correspondence. For example, three tide gates were added at the Parker River National Wildlife Refuge area per correspondence with U.S. Fish and Wildlife Service. A summary of tide gates and “add-ons” by region is listed by Table 2 and shown by Figure 4. In total, 49 individual tide gates were visited in the field and an additional 18 were modified or added. Refer to Appendix F for a comprehensive list based on unique identifier of all tide gates that were visited or added to the database as part of the field data collection effort.

Table 2. Summary of tide gates visited by region

| Region | Field Visits | Add-On's | Total |
|-------------------|--------------|-----------|-----------|
| Cape Cod | 6 | 1 | 7 |
| South Shore | 19 | 0 | 19 |
| Metro Boston | 13 | 13 | 26 |
| Lower North Shore | 6 | 0 | 6 |
| Upper North Shore | 5 | 4 | 9 |
| Totals | 49 | 18 | 67 |

- **Data Upload and Quality Assurance (QA):** Once field visits were complete, all collected data was uploaded to TIDEGateway and QA review was performed on all entries. The QA review included review of naming conventions, spatial locations, photo uploads and captions, and consistency/quality of data entries (grammar, units, typos, etc.).




Figure 4. Depiction of tide gates visited during field effort or added-on based on RC correspondence

C. Final Geodatabase

The final tide gate geodatabase is accessible at www.tidegateway.com and contains the following features:

- **Attribute Access:** Information for each tide gate can be accessed in tabular form by using the “Tide Gate Geodatabase” button if the tide gate name or town is known. Alternatively, tide gate data can be accessed spatially by using the “Interactive Tide Gate Map” button. Finally, if a tide gate’s unique identifier is known, its data can be directly accessed via URL. For example, tide gate Scituate-04 has a Unique ID of 77 and can be accessed via the following URL: http://www.tidegateway.com/editattribute.aspx?UNIQUE_ID=77. Full attribute information for each tide gate is presented in a printable “fact sheet” type format.
- **Fully Editable Data and Source Tracking:** All tide gate attributes can be directly edited once a user enters in their name, organization, email address, and data entry reason. Requiring users to enter in their contact information enables the database to track which attributes are modified and why. The database logs this information by means of a “tidegate source and change history” log. For example, if a modification was made to the Tide Gate Type for a specific tide gate, the database will indicate when the information was modified, by who, and the reason for the modification. Tide gates can also be deleted from and added to the database. Refer to Part III.D of the field protocols document for an explanation of tide gate naming conventions and instructions for entering specific attributes (Appendix D).
- **Downloadable Data:** The entire geodatabase can be downloaded at any time in a comma delimited (.CSV) file. This enables users to provide analysis in external software packages such as Microsoft Excel or to be imported into GIS-based packages via latitude and longitude coordinates. The database is also available through the Massachusetts Ocean Resource Information System (MORIS) at <http://www.mass.gov/eea/agencies/czm/program-areas/mapping-and-data-management/moris/>
- **External Data Files:** Each tide gate is also linked to a SharePoint folder containing additional information including monitoring data, operations and maintenance plans, permits, and other relevant files or reports. All scanned field logs have been uploaded to the relevant SharePoint folder for each tide gate.
- **Documentation:** Additional documentation on TIDEGateway can be accessed directly from www.tidegateway.com.

D. Training

As previously discussed, training of RC’s and other personnel on implementation of the field protocols was performed on a region to region basis during the field inspections (see Table 1). Geosyntec provided additional training to staff of MassBays, CZM and other partners on the geospatial tool and how to update, modify, and add tide gate attributes and external files via TIDEGateway.

E. Data Analysis and Findings

General Findings and Statistics

Once the geodatabase was complete, an analysis of tide gate attributes was performed. This section summarizes general findings. Refer to Appendix G for complete findings, including figures and maps. Additionally, refer to Appendix H for a listing of current data gaps by field in the geodatabase as of January 19, 2016.

- **Counts:** The geodatabase contains 137 tide gates at 100 sites (37 sites contain two or more tide gates). Regionally, the metro Boston region has the most tide gates in the geodatabase (62) and the upper north shore region has the fewest (9). At the municipal level, Revere has the most tide gates in the geodatabase (21) and Marshfield has the second most (11).
- **Type:** Flap gates are the most common type of tide gate in the geodatabase (61 tide gates, 44%); 26 tide gate types are unknown.
- **Material and Size:** A majority of tide gates are comprised of metal (79 tide gates, 58%) and 19 are comprised of wood. Tide gate sizes vary widely throughout each region and generally range from an average diameter of 2.6 feet for circular tide gates to an average diameter of 5.4 feet for rectangular tide gates. There are 69 records of rectangular tide gates in the database compared to 26 records for circular tide gates.
- **Purpose and Status:** Most tide gates are in active use (109, 80%), while 24 are inactive, proposed, or removed. 51 tide gates are solely installed for flood protection, while only 14 serve a dual role of flood protection and restoration.
- **Operator Type:** Most tide gate operators are public. A larger proportion of private operators are present in Cape Cod than in other regions.
- **Culvert Material and Size:** Reinforced concrete is the most common culvert material (62 total, 45%). Other culvert material types include corrugated metal, ductile iron pipe, and granite block.
- **Restriction Surface:** Roughly half of the tidal restrictions in the geodatabase are the result of roadway crossings (67 total, 49%). Other restriction types include footpaths, railroad crossings, retaining walls, dams, and berms.

Condition Findings

The below comments provide a summary of general tide gate and culvert condition; refer to Appendix G for complete findings including figures and maps:

- **Tide Gate Condition:** A condition value was assigned to 38 distinct tide gates. Condition was generally good, although 32% of assigned tide gates were assigned a fair or poor value. Tide gate condition appeared to be evenly distributed across each region. The largest proportion of tide gates in fair or poor condition was located in the Metro Boston area.
- **Culvert Condition:** A condition value was assigned to 42 culverts associated with tide gates. Culvert condition was generally not as good as that of the tide gates, with 48% of assessed culverts assessed as fair or poor condition. Culvert condition appeared to be evenly distributed

across each region, although the largest proportion of culverts in fair or poor condition was located in the Metro Boston area.

Refer to Table 3 for a complete listing of tide gates and culverts found to be in poor or fair condition during the field assessments performed in November and December 2015 along with accompanying comments. Additionally, photographs of relevant comments for selected tide gates and culverts are provided by Appendix I¹. Reasons for tide gates or culverts to be assessed as “fair” or “poor” condition ranged widely; common reasons are listed below:

- **Common tide gate condition findings:** Inoperable (sealed shut, missing required float, etc.), doesn’t form seal (i.e., leaking observed), deformation, waterlogged and rotten wood, excessive corrosion, not secure in place (e.g., bolts falling off).
- **Common culvert condition findings:** Collapsing and/or deformed culvert, excessive sedimentation, culvert pipe bell separation, general deterioration. Additionally, a number of headwalls were observed to be in poor or fair condition. These findings were coupled with culvert condition findings to ensure proper tracking. Headwall findings were generally related to general deterioration including collapsing, spalling, cracking, exposed rebar, and scour. One recommendation for future work will be to include headwall specific fields in the geodatabase to enable better tracking of these structures.

¹ Note: A complete photograph log of tide gates can be accessed from [TIDEGateway.com](http://www.tidegateway.com). Tide gate records can be directly accessed based on “UNIQUE ID”. For example, UNIQUE ID 77:
http://www.tidegateway.com/login.aspx?ReturnUrl=%2feditattribute.aspx%3fUNIQUE_ID%3d77&UNIQUE_ID=77

Table 3. Tide gate and culvert condition findings²

| UNIQUE ID | TIDEGATE ID | REGION | TIDE GATE CONDITION | TIDE GATE COMMENTS | CULVERT CONDITION | CULVERT COMMENTS |
|-----------|---------------|-------------------|---------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 12 | Orleans-02A | CAPE COD | Fair | There were two tidal control structures located at the site. The first control structure was a rectangular metal flap gate installed on the downstream end of the restriction (Orleans-02A). Orleans-02A was in good condition and appeared to have been recently replaced as evidenced by new mounting hardware. At the time of the site visit (12/18/2015), the tide gate was inoperable and was sealed completely shut by fine grained sediment deposited in the channel. Dredging was required to restore proper functionality of the tide gate and to allow passage of upstream flow. | Good | The upstream and downstream ends of the 1' diameter CMP culvert appeared to be in good condition. There was another corrugated circular plastic culvert with a diameter of approximately 10" downstream of the restriction at the Namequoit Road crossing where the channel entered Paw Wah Pond. Scour and bank undercutting were observed along the channel between the restriction and Namequoit Road. It was unclear if the scour had been caused by tidal exchange, stormwater flows from the upstream impoundment, or some combination thereof. |
| 14 | Sandwich-01 | CAPE COD | Fair | The square metal flap gate was located on the seaward opening of the culvert and was in fair condition. It appeared that the tide gate had recently been bolted back onto the culvert as evidenced by new mounting hardware; however, the metal comprising the flap gate was deformed and did not appear to form a tight seal against the culvert opening. A 3-5" gap was observed from which tidal exchange could occur. In addition, the bottom half of the tide gate was corroded and its operation was impeded by heavy algae growth. It was unclear if the tide gate would be able to fully open in the event of a storm event to pass heavy upstream flows. | Poor | The circular ductile iron culvert appeared to be in good condition; minimal to no corrosion was observed. The downstream end of the culvert was located at the bottom of an embankment comprised of well graded and recently installed gravel. The upstream end of the culvert was located at the bottom of a wooden retaining wall in poor condition. The retaining wall was beginning to collapse at multiple locations, excessive wood rot was observed, and upland vegetation was observed growing through the retaining wall - further compromising its structural integrity. |
| 132 | Beverly-01B | LOWER NORTH SHORE | Fair | Beverly-01B was located on the eastern end of the spillway and was a steel sluice gate operated by a handwheel. Grease was observed on the handwheel, so it appeared that the gate was periodically operated. The tide gate was in fair condition; the metal sluice gate was badly corroded and was leaking. | Good | There was no culvert at this location, the restriction was a concrete dam built in 1904. The approximate spillway dimensions were as follows: width 31'; height 5.5'. The spillway appeared to be in good condition with no visible signs of deterioration. |
| 24 | Manchester-01 | LOWER NORTH SHORE | Good | There was a metal sluice gate with an electric actuator at this location. The tide gate was rusty but appeared to be in good condition with no evidence of corrosion. The actuator also appeared to be in good condition and appeared to be approximately 15 to 25 years old. Actuator and tide gate were located behind a chain link fence with a padlock; however, it was not locked at the time of the site visit. It appeared that power to the actuator was not locked out and could potentially be operated by anyone from the general public. | Poor | The culvert underneath the roadway was semi-circular granite block. It appeared to be in good condition on the downstream end; however, the upstream headwall was in poor condition - A chunk of the headwall had fallen into the channel, exposed rebar was observed, and a vertical crack was forming in the top middle of the headwall that extended almost down to the top of the culvert opening. |
| 25 | Salem-01A | LOWER NORTH SHORE | Good | There were three identical tide gates at this location - Salem-01A was located to the northwest, Salem-01B was located in the middle, and Salem-01C was located to the southeast. The tide gates were all rectangular wooden sluice gates with electric actuators. Access to the tide gates and actuators was limited by a locked chain link fence, so tide gate dimensions are approximate. All three tide gates appeared to be in good condition - the wood was weathered, but did not appear to be rotten and the actuators appeared to have been installed in the last 5-15 years and appeared to be operable. | Fair | There were three identical granite block culvert openings on the upstream side (all approximately 6' wide by 4' high) and two granite block culvert openings on the downstream side (approximately 10' wide by 10' high each). The granite block culvert appeared to be in good condition. Spalling and general deterioration of the upstream headwall was observed. In addition, the cribbing retaining the riprap embankment on the southwest upstream wingwall was collapsing. The downstream headwall appeared to be in good condition; however, sections of the bridge deck were being supported by wooden blocks. |
| 130 | Salem-01B | LOWER NORTH SHORE | Good | See above comment (Unique ID 130). | Fair | See above comment (Unique ID 130). |
| 131 | Salem-01C | LOWER NORTH SHORE | Good | See above comment (Unique ID 130). | Fair | See above comment (Unique ID 130). |
| 36 | Hull-02A | METRO BOSTON | Fair | Tide gate was a metal sluice gate operated by a manual jack screw. The tide gate appeared to be in fair condition; however, it appeared that it was inoperable and rusted in place. Significant rusting of the hinges and main structure of the tide gate was observed. | Fair | There were no apparent structural issues observed at the concrete box culvert; however, the headwalls on both the upstream and downstream end of the culvert were in poor condition. Significant spalling and exposed rebar was observed on both the upstream and downstream headwalls. Further, the access rungs leading from the top of the headwall down to the tide gate were corroded. |

² Table contains tide gate and culvert pairs that were found to be in fair or poor condition during the field inspections performed November through December 2015.

| UNIQUE ID | TIDEGATE ID | REGION | TIDE GATE CONDITION | TIDE GATE COMMENTS | CULVERT CONDITION | CULVERT COMMENTS |
|-----------|----------------|--------------|---------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 122 | Hull-02B | METRO BOSTON | Good | Tide gate was a large wooden flap gate chained in place at the mouth of the culvert. Tide gate appeared to be in good condition. | Fair | See above comment (Unique ID 36). |
| 38 | Hull-04 | METRO BOSTON | Unknown | Wedged flapper in manhole. Installed as part of MassDOT roadway project. Tide gate was inaccessible, diameter and shape assumed based on observed downstream culvert outfall. | Fair | Outfall to culvert was located below high water mark approximately 150' downstream of the tide gate. A metal (rebar) trash grate was installed at the outlet. The culvert was in fair condition - the culvert bell/segments were beginning to decouple and gaps were observed in the joints. It appeared that the cause of the decoupling was lowering of the beach profile (i.e. longshore sediment transport). |
| 42 | Quincy-04 | METRO BOSTON | Unknown | Flap gate was located within stormwater infrastructure pipe. At the time of the site visit, the manhole was not accessible. | Poor | Reinforced concrete culvert was 36" at downstream end and 12" at upstream end. Outfall was located approximately 100' feet north of Bayswater Road on the beach and was partially exposed at low tide. Downstream end of culvert was severely deteriorated: most of the joints had separated and large 1'-2' gaps were observed in the pipe. Upstream end of culvert which entered the marsh off of Winthrop Street was in fair condition, but was partially buried and appeared to have the potential to get buried or silted in if not frequently maintained. |
| 84 | Quincy-06 | METRO BOSTON | Good | Tide gate was recently installed and appeared to be in good condition and operable. | Fair | Downstream end of culvert was plastic (HDPE) and upstream end of culvert was corrugated metal. Downstream end of culvert appeared to be in good condition; however, upstream end was partially buried, thereby potentially limiting stormwater conveyance capacity. |
| 58 | Weymouth-02 | METRO BOSTON | Poor | Large wooden flap gate was in poor condition. The bottom half of the tide gate was rotting. The tide gate was installed in such a way that a seal was not created against the headwall thereby allowing some level of tidal exchange at all tidal levels. The tide gate hinges appeared to be operable; however, the tide gate was so waterlogged that it was not possible to fully open. | Fair | Stone culvert appeared to be in fair condition. Longitudinal cracks were observed on upstream end of the headwall. Upstream end of the headwall had a steel trash screen installed across the culvert mouth. The bottom portion of the trash rack was corroded. |
| 63 | Cohasset-02 | SOUTH SHORE | Not Applicable | It appeared that the previous tide gate fell off or was removed from the hinge located on the stone headwall. The metal hinge was corroding and did not appear to be robust. | Fair | Deformation of the corrugated metal culvert was observed on its downstream end indicating that it was potentially beginning to collapse. Significant spalling and cracking was also observed on the downstream concrete headwall. |
| 28 | Duxbury-01 | SOUTH SHORE | Fair | The metal circular flap gate was operational; however, the bottom 10% of the flapper was beginning to corrode away. | Fair | The culvert ran through a rip rap seawall. The culvert was cast iron, covered in barnacles, and appeared to be in fair condition. The upstream end of the culvert was unable to be assessed as it was obstructed by collapsing riprap. A vertical crack was forming on the face of the downstream concrete headwall which extended appx. 3 foot down to the tide gate. In addition, the concrete wing walls were beginning to crack. |
| 68 | Marshfield-01A | SOUTH SHORE | Fair | There were two tide gates installed at this location. A metal self-regulating tide (SRT) gate was installed to the west (Marshfield-01A) and a metal flap gate was installed to the east (Marshfield-01B). The self-regulating tide gate was in fair condition and was inoperable; the bottom float which allows the tide gate to open was missing. As a result, it appeared that the gate was currently operating as a flap gate and limiting upstream tidal exchange. A hand operated winch and strap had been installed to operate the SRT and the strap was weathered. Additionally, the SRT's breather was clogged with debris and some leakage was observed around the flange connection to the headwall. | Good | Both culverts appeared to be in good condition. The upstream wingwall was in good condition, but appeared to be starting to slightly separate from the headwall. |

| UNIQUE ID | TIDEGATE ID | REGION | TIDE GATE CONDITION | TIDE GATE COMMENTS | CULVERT CONDITION | CULVERT COMMENTS |
|-----------|----------------|-------------------|---------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 72 | Marshfield-05A | SOUTH SHORE | Poor | There were two wooden flap gates at this location. Marshfield-05A was located to the north and Marshfield-05B was located to the south. The wood on both tide gates was heavily rotted and waterlogged with rusty wooden hinges. The northern tide gate was inoperable and was stuck shut; it appeared that the hinges were corroded shut. Additionally, the bolts securing the tide gate to the headwall were wearing through the wood. The southern tide gate was operable. Gaps were observed in the wooden backing behind each tide gate and it appeared that both tide gates did not create a watertight seal at high tide, thus enabling some level of upstream tidal flushing. | Poor | There were two identical oval CMP culverts for each tide gate. Both culverts appeared to be in poor condition. The culverts were separating from the concrete headwall and significant deterioration and rust was observed. The northern culvert (downgradient of the inoperable tide gate) was approximately half full of sediment presumably since the tide gate was rusted shut; presumably not letting sediment from upstream stormwater flows out. Both the upstream and downstream headwalls were also in poor condition and deterioration / spalling was observed in multiple areas. Finally, it appeared that the downstream headwall's weep holes had been filled with concrete. |
| 124 | Marshfield-05B | SOUTH SHORE | Fair | See above comment (Unique ID 72). | Poor | See above comment (Unique ID 72). |
| 74 | Scituate-01A | SOUTH SHORE | Poor | There were two tidal control structures at the site. A metal flap gate was installed on the downstream portion of the culvert (Scituate-01A). The downstream metal flap gate was in poor condition. It was rusted open approximately 3 to 4 inches, the bolts affixing it to the concrete headwall were corroded, and it appeared that someone had attempted to remove the tide gate as evidenced by loosened nuts (i.e., the nuts had been backed off the bolts). | Fair | The reinforced concrete pipe was in fair condition. It appeared that the mouth of the pipe was beginning to separate from the weir wall on the upstream side of the restriction. In addition, erosion was observed around the upstream concrete weir, presumably from stormwater runoff from the adjacent road, tidal influence, or some combination thereof. Erosion was also observed around the downstream headwall. The downstream headwall was in poor condition and appeared to "leaning" towards the channel towards the top, indicating mobilization of soils behind it. Additionally, spalling of the headwall was observed. |
| 123 | Scituate-01B | SOUTH SHORE | Good | There were two tidal control structures at the site. A concrete weir with wooden stop logs was installed on the upstream portion of the restriction (Scituate-01B). The upstream concrete weir and wooden stop logs appeared to be in good condition. | Fair | See above comment (Unique ID 74). |
| 79 | Gloucester-01A | UPPER NORTH SHORE | Good | There were three tide gates at the site. Gloucester-01A was an old sluice gate with a manual jack screw located at the bottom of the eastern portion of the headwall. All three of the tide gates appeared to be in good condition at the time of the site visit. Gloucester-01A was rusty, but corrosion was not evident and it appeared that the manual gear had recently been maintained and greased. | Fair | The culvert material was corrugated metal piping and was a semi-circle with an approximate width of 13 ft and an approximate height of 12 ft. The upstream portion of the culvert appeared to be in good condition with no apparent deterioration; however, the downstream portion was slightly separating from the headwall in places. Additionally, portions of the downstream culvert were jagged and appeared to pose a potential safety hazard. |
| 116 | Gloucester-01B | UPPER NORTH SHORE | Good | There were three tide gates at the site. Gloucester-01B was a newer combination metal sluice / flap gate. The sluice gate was able to operated via jack screw to be installed either at the invert of the headwall or towards the top. It was located towards the top of the headwall during the site visit, enabling low level tidal flushing through the bottom opening. All three of the tide gates appeared to be in good condition at the time of the site visit. | Fair | See above comment (Unique ID 79). |
| 133 | Gloucester-01C | UPPER NORTH SHORE | Good | There were three tide gates at the site. Gloucester-01C was a metal flap gate installed in the middle portion of the headwall. All three of the tide gates appeared to be in good condition at the time of the site visit. | Fair | See above comment (Unique ID 79). |

Restoration Findings

The comments below summarize an analysis of findings related to restoration attributes in the geodatabase. Refer to Appendix G for complete findings including figures and maps.

- **Upstream Wetland Area:** Upstream wetland area estimates were obtained from previous tidal restriction atlases and are available for 21 sites in the geodatabase. Average total wetland area upstream of tide gate impoundments was 165 acres with a maximum of 1,400 acres (Tide Gate ID: Salem-02).
- **Restoration Status:** Restoration status for sites in the geodatabase was generally unknown or null (73 sites). However, 16 sites have restoration that is either completed, in progress, or proposed.
- **Extent of Tidal Influence:** As part of the field investigations, the extent of upstream and downstream tidal influence was approximated based on visible staining (see Appendix D). Out of the 67 tide gates that were visited, the extent of upstream and downstream tidal influence was collected at 17 individual tide gates. Results indicate that upstream tidal influence was less than downstream tidal influence by approximately 0.5 feet to 1.5 feet. The extent of upstream tidal influence was found to be greater than downstream tidal influence at Manchester-01; however, it is hypothesized that upstream staining at this site was a direct result of stormwater discharge. It is recommended that a Real Time Kinematic (RTK) GPS be used at select sites in the future to further improve accuracy of these findings to enable a more robust analysis.
- **Invasive Species:** Invasive species (e.g., *Phragmites*) were observed at a majority of sites that were visited (75%).

Refer to Table 4 for a listing of selected sites that were identified either in the geodatabase comments or during the field assessments performed in November and December 2015 to have restoration potential. Selected sites include commentary on general conditions of the upstream marsh, the presence of invasive species, observed low-lying properties, and other miscellaneous observations. Photographs documenting these observations for selected sites are provided in Appendix I.

Table 4. Selected tidal restriction restoration findings

| UNIQUE ID | TIDEGATE ID | REGION | INVASIVE COMMENTS | RESTORATION COMMENTS |
|-----------|----------------|-------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 72 | Marshfield-05A | SOUTH SHORE | Abundant <i>Phragmites</i> upstream. | No known restoration efforts or studies had been performed. Low lying properties including a dirt road and house were observed directly adjacent to the upstream impoundment. |
| 124 | Marshfield-05B | SOUTH SHORE | Abundant <i>Phragmites</i> upstream. | See above comment (Unique ID 72). |
| 84 | Quincy-06 | METRO BOSTON | Flap gate limited all tidal flow. As a result, freshwater grasses and <i>Phragmites</i> were observed upstream. | At the time of the site visit, no known restoration efforts had been undertaken. The upstream area was large and appeared to have significant restoration potential. A number of homes were observed adjacent to the impoundment which might limit restoration options due to potential flooding. |
| 147 | Rowley-01A | UPPER NORTH SHORE | <i>Phragmites</i> abundant-- treated 3-5 year cycle, loosestrife present but somewhat in check by beetles. | Restoration is possible and is currently being evaluated by USFWS. Extensive data are being collected for future modeling scenarios. |
| 7 | Eastham-01 | CAPE COD | <i>Phragmites</i> dominated the upstream and downstream portions of the restriction. Small patches of high marsh were observed downstream of the restriction. | The area appeared to have good restoration potential with minimal to no low-lying infrastructure observed. Note flap gate had been removed or fell off culvert at time of site visit (12/18/2015). |
| 14 | Sandwich-01 | CAPE COD | The downstream portion of the marsh was comprised of a mixture of high marsh and <i>Phragmites</i> while the upstream portion of the marsh was predominately <i>Phragmites</i> . Upland vegetation was also observed along the railway embankment including wild cherry and sumac. | The site appeared to have good restoration potential; however, upgradient infrastructure (i.e. houses) were observed. |
| 74 | Scituate-01A | SOUTH SHORE | The impoundment was comprised primarily of high marsh and was fringed by <i>Phragmites</i> . | Houses were observed around the marsh; however, they appeared to be elevated. |

| UNIQUE ID | TIDEGATE ID | REGION | INVASIVE COMMENTS | RESTORATION COMMENTS |
|-----------|--------------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 123 | Scituate-01B | SOUTH SHORE | The impoundment was comprised primarily of high marsh and was fringed by <i>Phragmites</i> . | See above comment (Unique ID 74). |
| 12 | Orleans-02A | CAPE COD | The upstream impoundment appeared to be an entirely freshwater system as evidenced by cattails, Atlantic white cedar, and freshwater sedge. | The site had good restoration potential with minimal low lying infrastructure observed; however, restoration might be limited by the requirement to preserve Atlantic white cedar. |
| 135 | Orleans-02B | CAPE COD | See above comment (Unique ID 12). | See above comment (Unique ID 12). |
| 63 | Cohasset-02 | SOUTH SHORE | The upstream impoundment was dominated by high marsh and was fringed with <i>Phragmites</i> . | Unknown if any restoration efforts had been performed at the site. Future restoration considering upsizing the culvert would need to investigate low lying areas including adjacent farm land directly to the south of the impoundment. |
| 6 | Dennis-01 | CAPE COD | The upstream impoundment was mainly comprised of high marsh and was fringed with <i>Phragmites</i> . Upland vegetation was also observed directly to the south of the upstream culvert opening. | It appeared that the site would be a candidate for restoration; however, a potentially low lying barn and field was observed to the west of the restriction. |
| 42 | Quincy-04 | METRO BOSTON | The upstream marsh had a mixture of <i>Spartina alterniflora</i> and <i>Spartina patens</i> and was bordered by <i>Phragmites</i> . | The marsh was previously studied for potential restoration by DER; however, it was concluded that low lying infrastructure would be a challenge. Future restoration would likely need to consider sizing culvert to accommodate the balance between stormwater outflows and tidal flushing. |
| 40 | Quincy-02 | METRO BOSTON | There was a narrow channel on the upstream end of the restriction lined with an approximately 2' wide layer of salt marsh grass. From there, the salt marsh grass transitioned into mowed grass and <i>Phragmites</i> . | It appeared that no restoration efforts had been made at this location. There was an abundance of low lying infrastructure located at the upstream end of the restriction including houses, deck stairways, and concrete retaining walls. |

| UNIQUE ID | TIDEGATE ID | REGION | INVASIVE COMMENTS | RESTORATION COMMENTS |
|-----------|-------------|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 58 | Weymouth-02 | METRO BOSTON | Upstream area varied significantly. <i>Phragmites</i> , upland vegetation, and <i>Spartina alterniflora</i> islands were observed. Vegetation was indicative of some level of salt water influence, but not enough volume to inundate the marsh top which was mainly comprised of upland vegetation. It appeared that the marsh had potentially subsided over time. | Large upstream wetland area with good restoration potential. A marina worker indicated that upstream residents had complained of flooding in the past, but it was unclear if the flooding was a result of tidal inundation, stormwater influence, or a combination. |
| 77 | Scituate-04 | SOUTH SHORE | Upstream impoundment was predominately comprised of <i>Phragmites</i> . Appeared that there was little to no tidal influence. | Would potentially be a good restoration candidate - minimal low lying infrastructure was observed; however, upstream area is used by the town as a drinking water well field. |
| 36 | Hull-02A | METRO BOSTON | Upstream marsh appeared to be relatively healthy with a mixture of low and high marsh species. <i>Phragmites</i> were observed at the fringes. | Previous water level logging was performed determine the relative extent of upstream restriction. Low lying properties including a cellular tower and guy wires were observed within and around the impoundment. |
| 122 | Hull-02B | METRO BOSTON | Upstream marsh appeared to be relatively healthy with a mixture of low and high marsh species. <i>Phragmites</i> were observed at the fringes. | See above comment (Unique ID 36). |

Miscellaneous Findings

Refer to Table 5 for a listing of tide gates where future action items were identified based on review of the geodatabase and field assessment results. Action items include, but are not limited to: determine exact location of tide gates, obtain water level and relevant files from RCs or other local contacts, perform a re-visit of structures that could not be accessed during the field assessments (i.e., locked, etc.), etc.

Finally, refer to Table 6 for a listing of miscellaneous observations of interest that were identified during the field assessments. These observations vary widely and include sites where various wildlife or fish species were observed, potential overwash areas, and other miscellaneous comments.

An accompanying photo log of these observations is provided in Appendix I.

Table 5. Action item locations

| UNIQUE ID | TIDEGATE ID | REGION | GENERAL COMMENTS AND MISC. FOLLOWUPS |
|-----------|---------------|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 4 | Brewster-02 | CAPE COD | Bridge replacement occurred from 2005-2008. Old flap gate may have been removed. Next steps: Determine if tide gate still exists at this location. |
| 12 | Orleans-02A | CAPE COD | Access to the site was located at the low point of Namequoit Road where a small conveyance channel enters Paw Wah Pond. The site was located approximately 100 feet up the channel to the north from the road. Orleans Conservation Trust (OCT) upgraded the system with NRCS. DER has tide data and a copy of OCT's management plan for the upstream Namaquoit Bog. Follow-up: Obtain data from DER. |
| 135 | Orleans-02B | CAPE COD | See above comment (Unique ID 12). |
| 91 | Swampscott-01 | LOWER NORTH SHORE | Location of tide gate approximate based on review of aerial imagery (Google Earth, Bing bird's eye). Follow up: Determine exact tide gate location and perform field visit. |
| 92 | Swampscott-02 | LOWER NORTH SHORE | Location of tide gate approximate based on review of aerial imagery (Google Earth, Bing bird's eye). Follow up: Determine exact tide gate location and perform field visit. |
| 93 | Swampscott-03 | LOWER NORTH SHORE | Location of tide gate approximate based on review of aerial imagery (Google Earth, Bing bird's eye). Follow up: Determine exact tide gate location and perform field visit. |
| 96 | Chelsea-01A | METRO BOSTON | Location of tide gate approximate based on review of aerial imagery (Google Earth, Bing bird's eye). Follow up: Determine exact tide gate location and perform field visit. |
| 119 | Chelsea-01B | METRO BOSTON | Location of tide gate approximate based on review of aerial imagery (Google Earth, Bing bird's eye). Follow up: Determine exact tide gate location and perform field visit. |
| 95 | Chelsea-02 | METRO BOSTON | Lat/Lon location could not be determined from municipal SharePoint contact. Additional clarification necessary to determined location. Follow up: Determine exactly tide gate location and perform field visit. |
| 36 | Hull-02A | METRO BOSTON | Site was easily accessible by walking northwards along a paved berm for approximately 500 feet off of Nantasket Road. Next steps: obtain preliminary water level data previously collected at the site from Jason Burtner (CZM). |
| 122 | Hull-02B | METRO BOSTON | See above comment (Unique ID 36). |

| UNIQUE ID | TIDEGATE ID | REGION | GENERAL COMMENTS AND MISC. FOLLOWUPS |
|-----------|----------------|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 38 | Hull-04 | METRO BOSTON | Tide gate is located in a locked subsurface vault adjacent to the intersection between Ocean Avenue and Main Street. At the time of the site visit, the tide gate could not be accessed. Additionally, upstream culvert was not located due to a dense Phragmites stand. Next steps: Contact Hull DPW to obtain access to tide gate for further investigation and locate upstream culvert during vegetation die off period. |
| 39 | Quincy-01A | METRO BOSTON | Tide gates are located under Quincy Shore Drive, a short walk south of Caddy Memorial Park. Follow up: Obtain additional site data: O&M, Engineering Plans, and Permits from when Tide Gates were installed. |
| 120 | Quincy-01B | METRO BOSTON | See above comment (Unique ID 39). |
| 121 | Quincy-01C | METRO BOSTON | See above comment (Unique ID 39). |
| 40 | Quincy-02 | METRO BOSTON | The tide gate is located directly off of Edgewater Drive adjacent to the seawall and is located within a locked vault with an electrical enclosure sitting on top. Field crew was unable to access the interior of the vault. Next steps: Reach out to Town of Quincy and request a follow up visit for site access. Also ask how the tide is managed and ask if there are any O&M plans, permits, or plans associated with the tide gate. |
| 42 | Quincy-04 | METRO BOSTON | Tide gate was located in a manhole adjacent to Winthrop Street and was not accessible. Follow-up with DER to obtain elevation data and with Town of Quincy to gain access to manhole to inspect tide gate. |
| 87 | Weymouth-05 | METRO BOSTON | Review of aerials indicates that tide gate potentially located closer to shore, located in close proximity to tide gate unique id 89. Follow up: Determine exact tide gate location and perform field visit. |
| 89 | Weymouth-07 | METRO BOSTON | Review of aerials indicates that tide gate potentially located closer to shore, located in close proximity to tide gate unique id 87. Follow up: Determine exact tide gate location and perform field visit. |
| 62 | Cohasset-01 | SOUTH SHORE | Field crew was advised that access to site is on private property and access is challenging. As a result, this site was not accessed. Next steps: Jason Burtner of MA CZM indicated that he has data on this site including tide gate attributes and photos. |
| 68 | Marshfield-01A | SOUTH SHORE | Site is located directly off of Town pier Road and easily accessible. Next Steps: Jason Burtner of MACZM can provide permitting drawings and other relevant files and site information to further flesh out attributes. |
| 125 | Marshfield-01B | SOUTH SHORE | See above comment (Unique ID 68). |
| 69 | Marshfield-02A | SOUTH SHORE | See above comment (Unique ID 68). |

| UNIQUE ID | TIDEGATE ID | REGION | GENERAL COMMENTS AND MISC. FOLLOWUPS |
|-----------|----------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 112 | Marshfield-02B | SOUTH SHORE | See above comment (Unique ID 68). |
| 71 | Marshfield-04A | SOUTH SHORE | Site is located directly off of Dyke Road and easily accessible. Note that Jason Burtner can provide permitting drawings and other relevant files and site information to further flesh out attributes. |
| 126 | Marshfield-04B | SOUTH SHORE | See above comment (Unique ID 71). |
| 127 | Marshfield-04C | SOUTH SHORE | See above comment (Unique ID 71). |
| 128 | Marshfield-04D | SOUTH SHORE | See above comment (Unique ID 71). |
| 150 | Ipswich-01 | UPPER NORTH SHORE | Tide gate located at the Parker River National Wildlife Refuge at a berm not accessible by the general public. USFWS must be contacted to obtain access. Follow ups: Nancy Pau and USFWS can provide additional details with a field visit including tide gate and culvert dimensions, invert elevations, and upstream acreage. |
| 147 | Rowley-01A | UPPER NORTH SHORE | See above comment (Unique ID 150). |
| 148 | Rowley-02 | UPPER NORTH SHORE | See above comment (Unique ID 150). |
| 149 | Rowley-03 | UPPER NORTH SHORE | See above comment (Unique ID 150). |

Table 6. Miscellaneous observations of interest

| UNIQUE ID | TIDEGATE ID | REGION | MISCELANOUS COMMENTS |
|-----------|----------------|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 6 | Dennis-01 | CAPE COD | An abundance of live mussels was observed within the channel at the upstream end of the culvert. |
| 25 | Salem-01A | LOWER NORTH SHORE | The marsh immediately upstream appeared to be healthy and was comprised of a mixture of low and high marsh. Multiple invasive striped anemones were observed on the mudflat approximately 100 feet downstream of the downstream bridge opening. |
| 130 | Salem-01B | LOWER NORTH SHORE | See above comment (Unique ID 25). |
| 131 | Salem-01C | LOWER NORTH SHORE | See above comment (Unique ID 25). |
| 42 | Quincy-04 | METRO BOSTON | A sewer manhole was located adjacent to the upstream end of the culvert in the marsh. Gravel had recently been placed around the manhole and evidence of previous scour was observed suggesting a history of overwash and stormwater inflows. |
| 63 | Cohasset-02 | SOUTH SHORE | Area on the upstream side of the flapper was used for grazing years ago. The upstream channel was full of killifish. |
| 65 | Cohasset-04 | SOUTH SHORE | Resident indicated that upstream impoundment used to be a pond; however, indicated that Town of Cohasset drains it for winter ice skating. Mowed cattails were observed throughout the upstream impoundment. |
| 69 | Marshfield-02A | SOUTH SHORE | Many killifish were observed on the downstream side of the tide gate. |
| 112 | Marshfield-02B | SOUTH SHORE | See above comment (Unique ID 69). |

III. TIDEGateway

Information gathered through this effort are compiled online at TIDEGateway.com, accessible with password only. The site includes an Interactive Tide Gate Map, a Tide Gate Inventory, and Field Inspection Protocols.

Interactive Tide Gate Map: This viewer was designed as a web-based map interface that displays the geospatial data layers (for example, wetlands, land use, and ecological resources layers). The viewer was developed on the GeoCortex Essentials platform hosted on Geosyntec’s Internet Information Services server, and utilizes services published to Geosyntec’s ArcGIS Server.

Tide Gate Inventory: A listing of all tide gates in the database, hyperlinked to background materials – inspection reports, photos, and permits – available for that gate.

Field Inspection Protocols: Full protocols used for site visits and data-gathering efforts.

All data are also available through MORIS³, folder: Infrastructure and Transportation, layer: Massachusetts Tide Gate Inventory.

³ <https://www.mass.gov/service-details/massachusetts-ocean-resource-information-system-moris>

IV. RECOMMENDATIONS

This section provides recommendations for next steps. Recommendations are intended to be used as a framework for future work and planning efforts as it relates to further improving and expanding TIDEGateway.

- **Update geodatabase data dictionary with headwall specific attributes:** A number of headwalls were observed to be in poor or fair condition during the field assessments. These findings were coupled with culvert condition findings to ensure that data were stored and tracked. Headwall findings were generally related to general deterioration including collapsing, spalling, cracking, exposed rebar, and scour. An engineering analysis to add headwall-specific fields to the geodatabase would provide a more complete means to track overall condition of infrastructure at each site to better inform planning. A number of headwall specific fields can be included such as: qualitative condition, type (e.g., wingwall), and height.
- **Expand geodatabase format to include pipe and headwall geometry:** The geodatabase is currently comprised of “point” features representing locations of individual tide gates. Geodatabase geometry could be expanded to include separate geometry for pipes (“line features”), and headwalls (“area features”). Expanding geometry to be more representative of real-world conditions will enable more robust future modeling and data analysis on a site-by-site basis. For example, a user would be able to zoom in and visualize culvert alignments.
- **Perform field visits at all sites in the geodatabase:** As previously discussed, the field protocols were developed to be performed rapidly and without any specialized equipment. Performing field visits of all tide gates in the geodatabase will ensure continuity (e.g., uniform photographs) and improve attribute accuracy which will result in more informed future data analysis and subsequent management actions. Refer to Appendix E and Appendix F for detailed lists identifying sites that were visited during the field assessments in the fall of 2015.
- **Improve accuracy of elevation data via RTK GPS:** As previously discussed, elevation data including tide gate invert and extent of upstream and downstream tidal influence were collected in the field using staining as an indicator. In order to collect these attributes, measuredowns (i.e. top of headwall to invert of tide gate or staining mark) were obtained via a surveyors rod and transformed into elevations (in NAVD88) referencing LiDAR data. Utilizing an RTK GPS or survey equipment at high-priority sites would ensure more accurate elevations to better inform future planning decisions.
- **Natural resource and infrastructure management agencies should collaborate to communicate with operators/owners of tide gates and culverts found to be in poor or fair condition:** As presented in Section II, approximately 32% of tide gates and 48% of culverts visited during the field assessments were found to be in poor or fair condition, respectively. Informing owners/operators (i.e., municipalities, etc.) of these findings will enable additional structural and operational assessments to be performed at their discretion. Refer to Table 3 for a complete list of all tide gates and culverts found to be in poor or fair condition and Appendix I for accompanying selected photos.
- **Perform evaluation of potential restoration sites:** It is recommended that Table 4 and accompanying photographs found in Appendix I be used as a starting point to evaluate and develop a methodology to prioritize potential future restoration sites.
- **Perform miscellaneous identified follow-ups:** Perform miscellaneous follow-ups identified by Table 6. These include follow-ups to determine exact location of tide gates, obtaining relevant files from RC’s and other local contacts, performing re-visits of structures that could not be accessed during the field assessments, etc.

- **Continue to perform outreach:** Continue with municipal and RC outreach to obtain information on site attributes. In particular, RC's can now upload tide gate specific files and data to TIDEGateway including water level monitoring data, permit, operation and maintenance plans, and other relevant files.
- **Configure geodatabase to provide live summary statistics:** The geodatabase is currently stored in a live Microsoft SQL server database and is configured to output a raw comma delimited file of live tide gate information. To improve this functionality, the live geodatabase can be linked to an external software package such as Tableau Software to automatically generate summary statistics and data visualizations at a pre-determined interval such as those presented as Appendix G. Automatically generated visualizations and statistics will provide managers with a constantly updated snapshot of existing tide gate information.
- **Expand field protocols:** There are a number of useful ways that the field protocols can be expanded to include additional analysis items of interest. For example, the protocols could be expanded to include a methodology for assessing salt marshes that have become degraded by reduced tidal flushing.
- **Develop a management plan template and recommended schedule for reviewing and updating plans:** Management plans should incorporate and reflect changing environmental conditions..
- **Develop construction cost estimates of selected tide gates:** In order to better inform future management of tide gates, it is recommended that planning level construction cost estimates of selected tide gates such as those in poor or fair condition be developed. Construction cost estimates would take a number of factors into account and could be developed at varying levels of complexity. For example, prioritization of sites for development of construction costs could be based on anticipated value of upstream infrastructure.
- **Expand tide gate data inventory to entire state of Massachusetts:** The tide gate geodatabase currently includes the MassBays planning regions and does not include tide gates in the Buzzards Bay area. The 2002 tidal restriction atlas for Buzzards Bay could be used as a starting point for expanding TIDEGateway into this region. Expanding to include Buzzards Bay would make TIDEGateway a resource for the entire Massachusetts coastline.
- **Expand TIDEGateway to include all tidal restrictions and not just tide gates:** TIDEGateway could easily be expanded to include all tidal restrictions. This would enable ease of future analysis, planning, and decision making to be performed from one platform. The database infrastructure for TIDEGateway has already been developed and implemented so expansion to include additional tidal restrictions would be straightforward.
- **Develop resiliency network to better inform site specific operation:** One additional way to leverage and expand the functionality of TIDEGateway would be to develop a site-specific resiliency network to enable optimal management of critical tide gates in the MassBays planning region. There are a number of ways that this could be performed; one avenue would be to monitor existing conditions (monitoring buoys, etc.), compute regional and site-specific risk based on anticipated storm surge and resulting upstream impacts, display information on a real-time dashboard accessible via TIDEGateway, and recommend risk mitigation actions. Recommended risk mitigation actions could be relatively simple (e.g., "close tide gate by 2pm in advance of predicted storm"). The resiliency network could also inform coastal managers when risk has decreased and remind them to open tide gates following storm events to enable tidal flushing.

Appendix A:

Initial Data Request

Memorandum

Date: 1 April 2015

To: Lisa Engler, MassBays Program
MassBays and CZM Regional Coordinators

From: Robert Hartzel, Geosyntec Consultants
David Roman, Geosyntec Consultants

Subject: TIDEGateway – Initial Data Request for Data Inventory

The purpose of this memorandum is to (1) summarize anticipated data needs for initial development of the TIDEGateway geodatabase under the “Data Inventory” task of the Tide Gate Inventory and Assessment Project, and (2) set the stage for a conference call amongst MassBays and CZM regional coordinators. The memorandum provides a brief overview of the data inventory task and summarizes anticipated data needs.

Data Inventory Task Summary: The initial purpose of the data inventory task will be to compile existing information about tide gate gates within the MassBays region into a comprehensive bibliography. Once complete, Geosyntec will review all available data and in coordination with MassBays and CZM, and develop a targeted list of applicable metadata categories and individual attributes of interest for each tide gate. Once a targeted list of attributes is developed, the initial TIDEGateway GIS data layer (i.e., geodatabase) will be developed based on gathered existing information. Major task deliverables will be a searchable bibliography of existing documents, an initial geodatabase and associated metadata, and a protocol for updating and maintaining the geodatabase.

Existing Information: Geosyntec currently has the following tide gate information from existing data sources:

- Tidal Restriction Atlases (PDF Form): Cape Cod, South Shore, North Shore;
- List of Tide Gates in MassBays Program, Cape Cod Region (7/29/2014);
- Preliminary list of municipal contacts within the MassBays region; and
- Additional site-specific information obtained from various published reports, maps and news articles (e.g., 2014 USEPA map of Rumney Marsh Restoration Areas)

Summary of Anticipated Data Needs: In order to complete the data inventory task, data from a variety of sources will be required. The intent of the initial data collection task is to coordinate with MassBays and CZM regional coordinators to obtain the most updated information that is available prior to coordination with municipal officials and other resources. The preferred data delivery medium which will increase efficiency and minimize any data entry errors is in the form of existing geodatabase files (i.e., shapefiles, etc.), spreadsheets, or other database type formats. However, additional file formats are also welcome, including paper maps, PDF documents, records of verbal communication with Town officials, field notes, etc.

Anticipated categories of data include:

- **Tide Gate Location:** Lat/Long or other means (i.e., paper map, road crossing location, etc.);
- **Tide Gate Attributes:**
 - Type (control/operational mechanism) and dimensions
 - Condition/Age
 - Upstream and downstream natural resources and water quality characteristics (e.g., upstream affected salt marsh area and total affected area)
 - Nearby infrastructure, adjacent low-lying topography and/or development,
 - Vertical data, including controlling elevations of water, historic upstream and/or downstream water level data (i.e., data logger or other records), tide gate invert elevations, road berm reference elevations, etc.
 - Existing state and federal permits for tide gate
 - Owner and current operational management
- **Restoration Status** (planned or recent)
- **Other**

As a starting point for discussion, and to help focus data collection efforts, the attached spreadsheet includes a very preliminary listing of tide gates by town. Most of this information is from the Tidal Restriction Atlases (*Note: The North Shore Atlas provides very little site-specific information compared to the other 2 atlases*). For this project, tide gates are defined as any conveyance of tidal flow with the ability to passively or actively manipulate water flow. This definition includes self-regulating tide gates, manually controlled devices, or passive control structures such as flappers. Structures not included in this definition may include, but are not limited to, conveyances installed for the sole purpose of carrying storm drainage.

Please review the attached list and provide any additional information you have in whatever format is most convenient. We will arrange a conference call after April 20 to discuss the existing data, data needs, and questions resulting from the process.

| Region | Town | Tidal Restriction Atlas ID # | Upstream Affected Salt Marsh Area (acres) | Upstream Total Affected Area (acres) | Lat (N) | Long (W) | Location (Water Body, Road) | Type of Engineered Flood Control Structure / Description | Restoration Status | Owner / Operator | Permit Status | Other | |
|-------------|--------------|------------------------------|-------------------------------------------|--------------------------------------|---------------|------------------------------------------|-------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------|-------|--|
| CAPE COD | Barnstable | BA-16 | 0 | 3.04 | 41 38' 13" | 70 17' 58" | Halls Creek, Marchant Mill Road | stoplogs | | | | | |
| | Barnstable | BA-17 | 0 | 19.31 | 41 38' 15" | 70 16' 89" | Stewart's Creek, Ocean Avenue | stoplogs | | | | | |
| | Brewster | BR-3 | 0 | 3.75 | 41 45' 25" | 70 07' 46" | Quivert Creek, cranberry bog berm | flapper gate | | | | | |
| | Chatham | CH-6 | 0 | 34.58 | 41 42' 13" | 69 58' 16" | Frost Fish Creek, Rt. 28/earthen berm | Infrastructure for stoplogs, used for many years and in disrepair. | | | | | |
| | Dennis | DE-3 | 3.14 | 4.11 | 41 40' 28" | 70 10' 11" | Unnamed channel, Wheatfield Lane | tide gate | | | | | |
| | Eastham | EA-7 | 1.71 | 6.93 | 41 49' 04" | 69 58' 03" | Abelino's Creek, Gov. Prence Road | tide gate | | | | | |
| | Eastham | EA-9 | 6.31 | 16.51 | 41 52' 58" | 70 00' 02" | | tide gate | | | | | |
| | Falmouth | FA-2 | 0.75 | 1.64 | 41 32' 75" | 70 35' 34" | Little Pond, Grand Avenue | stoplogs | | | | | |
| | Harwich | none listed | | | | | | | | | | | |
| | Mashpee | none listed | | | | | | | | | | | |
| | Orleans | OR-6 | 0 | 10.03 | 41 45' 42" | 69 58' 18" | Pah Wah Pond, earthen berm | stoplogs | | | | | |
| | Provincetown | none listed | | | | | | | | | | | |
| | Sandwich | SA-5 | 0 | 2.07 | 41 45' 47" | 70 29' 43" | Penn Central Railroad restriction of Dock Creek | 3-foot pipe has a metal flapper-type tide gate on the seaward opening, restricting flow to 6-inch gap between pipe and gate (see Atlas). Tide gate is | | | | | |
| | Sandwich | SA-9 | 0 | 79.71 | 41 44' 95" | 70 26' 41" | Ploughed Neck Road restriction of Long Creek/Cow River | tide gate; stoplogs | Restoration feasibility study was produced in June 2013 by the Cape Cod Conservation District, as part of the Cape Cod Water Resources Restoration Project. | | | | |
| | Truro | TR-3 | 0 | 152.38 | | | Truro Center Road/Route 6A (Wilder Dike) | The seaward of two tidal restrictions on the Pamet River. This restriction is located at the Wilder Dike that supports Truro Center Road at Route 6A. The dike is fitted with a clamper valve (tide gate) at the Pilgrim Lake connects to Cape Cod Bay via a small channel with flow controlled by structures including a culvert with two flapper valves (coordinates for upstream side). | Funding is being sought by the town and DER. | | | | |
| TR-6 | | 0 | 322.05 | 42 02' 04" | 70 07' 02" | Pilgrim Lake, Rt. 6A/Rt. 6 | | Upstream of Pilgrim Lake is what was once a vast intertidal salt marsh system known as Salt Meadow, delineated by the Wetlands Conservancy Program as 94.52 acres of shrub swamp and 50.94 acres of shallow marsh. In addition to sites TR-6 and TR-7 that restrict tidal flow into Pilgrim Lake, Salt Meadow is further restricted by 2 infrastructure crossings. First, by the extension of High Head Rd. that serves as a jeep trail to the beach, and second by a dike lying to the east of the jeep trail. If tidal flow is restored to the Pilgrim Lake system, most intertidal wetland benefits would be realized in the Salt Meadow wetland. These 2 upstream crossings should be included in restoration discussions. | | | | | |
| TR-7 | | 0 | | 42 03' 17" | 70 07' 10" | Pilgrim Lake, High Head Road | weir and box culvert with stoplogs | | | | | | |
| Wellfleet | WE-5 | 0 | 19.33 | 41 55' 84" | 70 01' 78" | Commercial St. restriction of Mayo Creek | 1-way duckbill valve in flapper gate | Feasibility study done in 2009-2010. Town working group convened in 2014 to plan restoration. | | | | | |
| | WE-6 | 0.81 | approx. 100 | 41 55' 87" | 70 03' 87" | Herring River, Chequessett Neck Road | Flapper-type tide gates in two of the culverts and an adjustable sluice gate in a third culvert | Planning and permitting largely complete; fundraising for restoration construction is ongoing. Construction could occur in the next 5 years if funds are obtained. | | | | | |
| Yarmouth | none listed | | | | | | | | | | | | |
| SOUTH SHORE | Braintree | | | | | | | | | | | | |
| | Cohasset | COBB2 | | | 42 15' 00.73" | 70 47' 21.40" | Treats Pond, Atlantic Avenue | culvert with flapper gate | | | | | |
| | | COBB4 | | | 42 15' 26.68" | 70 48' 46.23" | Richardson Brook, Jerusalem Road | culvert with flapper gate | | | | | |
| | | COBB6 | | | 42 15' 14.87" | 70 48' 37.23" | Inner Little Harbor, Nichols Road | tidegate | | | | | |
| | | COBB9 | | | 42 14' 23.03" | 70 47' 41.71" | James Brook, Spring Street | culvert with flapper gate | | | | | |
| | | COBB13 | | | 42 14' 23.23" | 70 47' 40.67" | James Brook, Summer Street | 2 flapper gates | | | | | |
| | Duxbury | DUBB18 | | | 42 02' 28.71" | 70 40' 11.09" | Duxbury Harbor, Long Point Lane | dike with flapper gate | | | | | |
| | Hingham | HIHH9A | | | 42 14' 59.55" | 70 54' 02.54" | Broad Cove, Rt. 3A at police station | wooden flapper gate (poor condition) | | | | | |
| | | HIHH10 | | | 42 14' 37.49" | 70 53' 01.45" | Home Meadow, Water Street | tide gate | | | | | |
| | | HIHH12 | | | 42 15' 29.36" | 70 52' 28.15" | Worlds End, Martins Road | flapper gate (replaced with box culvert in 2010/2011) | | | | | |
| | | HIWR19 | | | 42 15' 06.68" | 70 51' 38.15" | Turkey Hill Run, Rockland Street | flapper gate | | | | | |
| | Hull | HUHB1 | | | 42 16' 56.29" | 70 52' 47.33" | Hull Bay, Newport Road | wall with pumped outlet (with duckbill) | | | | | |
| | | HUHB2 | | | 42 16' 42.98" | 70 52' 38.86" | Hull Bay, Nantasket Road | tide gate (manual) | | | | | |
| | | HUWR3 | | | 42 15' 37.36" | 70 50' 41.05" | Straits Pond, Rt. 22B | 2 tide gates | tide gates replaced in 2010 | | | | |
| | Kingston | none listed | | | | | | | | | | | |
| | Marshfield | MAGH4A | | | 42 05' 23.21" | 70 38' 42.54" | Green Harbor, Town Pier Road | tide gate and flapper | | | | | |
| | | MAGH4B | | | 42 05' 21.18" | 70 38' 40.60" | Green Harbor, Town Pier Road | tide gate and flapper | | | | | |
| | | MASR16 | | | 42 05' 35.53" | 70 42' 01.41" | South River, Rt. 139 (Library Plaza) | culvert with tide gate | | | | | |
| Norwell | none listed | | | | | | | | | | | | |
| Plymouth | none listed | | | | | | | | | | | | |
| Quincy | | | | | | Black's Creek tide gates | | | | | | | |
| | | | | | | Edgewater Drive Sea Wall/Tide Gates | 2 tide gates | | | | | | |
| Scituate | SCSH2A | | | 42 11' 11.56" | 70 43' 30.16" | Scituate Harbor, Kent Street | flapper gate | | | | | | |
| | SCHR5 | | | 42 10' 36.54" | 70 44' 52.65" | Herring River, Driftway | culvert with flapper gate | | | | | | |
| | SCBB11 | | | 42 13' 31.69" | 70 46' 26.47" | Musquashcut Brook, Hatherly Road | electric tide gate | | | | | | |
| | SCHR20 | | | 42 10' 17.53" | 70 45' 00.86" | Herring River, earthen dike | earthen dike with flapper gate | | | | | | |
| | SCSH25 | | | 42 12' 22.50" | 70 43' 22.82" | Cedar Point, Jericho road | culvert with flapper gate | | | | | | |
| Weymouth | WEWF1 | | | 42 14' 18.40" | 70 56' 57.25" | Philips Creek, Pearl Street | large wooden flapper gate | | | | | | |
| NORTH SHORE | Beverly | | | | | | | | | | | | |
| | Boston | | | | | | | | | | | | |
| | Cambridge | | | | | | | | | | | | |
| | Chelsea | | | | | | Pearl Street tide gate | | | | | | |
| | Danvers | | | | | | | | | | | | |
| | Essex | | | | | | | | | | | | |
| | Everett | | | | | | | | | | | | |
| | Gloucester | | | | 42°35' 58.27" | 70°40' 37.92" | Mill Pond Tide Gate | 2 tide gates | new tide gates installed in 2011 | | | | |
| | Ipswich | | | | | | | | | | | | |
| | Lynn | | | | | | | | | | | | |
| | Manchester | | | | | | | mouth of Sawmill Brook | | | | | |
| | Marblehead | | | | | | | | | | | | |
| | Medford | | | | | | | | | | | | |
| | Nahant | | | | | | | | | | | | |
| | Newbury | | | | | | | | | | | | |
| | Newburyport | | | | | | | | | | | | |
| | Peabody | | | | | | | | | | | | |
| | Revere | | | | | | | Route 1A Tidegate #1 | | missing top floats need to be replaced for flood control | | | |
| | | | | | | | | Route 1A Tidegate #2 | | missing top floats need replacement; obstructed culvert | | | |
| | | | | | | | | Route 1A Tidegate #3 | | crushed culvert outlet needs replacement | | | |
| | | | | | | | | Route 1A Tidegate #4 | | grated vault covers stolen from 1-4 need replacement | | | |
| | | | | | | | | Route 1A Tidegate #5 | undersized culvert (24") with 48" SRT; replacement with a larger culvert needed | | | | |
| | | | | | | | | Route 1A Tidegate #6 | completely obstructed 600' culvert | | | | |
| | | | | | | | | Linden Brook tide gate | | | | | |
| | | | | | | | | Townline Brook tide gates | | | | | |
| | Rockport | | | | | | | Copeland Circle tide gate | | | | | |
| | | | | | | | | Central County Ditch tidegate | | not being operated properly to maximize restoration; needs bottom float installation | | | |
| | | | | | | | Oak Island tidegate | Vandalized SRT was replaced with new combo gate in 2013 | | | | | |
| Rowley | | | | | | | | | | | | | |
| Salem | | | | | | | | | | | | | |
| Salisbury | | | | | | | Town Creek | 2 new (2013) culverts with tide gates | | | | | |
| | | | | | | | Ballard Street tidegate | leaking temporary tide gate | future restoration project under design | | | | |
| Saugus | | | | | | | Former Bristow Street tidegate | temporary blocked culvert - missing tide gate | future project under design to restore marsh | | | | |
| | | | | | | | Seagirt Avenue Marsh tidegate | obstructed culvert and ditch - missing tide gate | | | | | |
| Somerville | | | | | | | | | | | | | |
| Swampscott | | | | | | | | | | | | | |
| Winthrop | | | | | | | Winthrop Parkway tide gates (near Leverett Street), regulate flow to Belle Isle | | | | | | |

Appendix B:

Initial Data Inventory Updates

Memorandum

Date: 8 May 2015

To: Lisa Engler, MassBays Program
MassBays and CZM Regional Coordinators

From: Robert Hartzel, Geosyntec Consultants
David Roman, Geosyntec Consultants

Subject: TIDEGateway – Data Inventory Updates and Discussion Points

Attachments:

1. Preliminary Bibliography
2. List of Existing Attributes and Data Gaps
3. Preliminary Data Dictionary
4. Example Fact Sheet from Proposal

The purpose of this memorandum is to provide a status update regarding initial development of the TIDEGateway geodatabase under the “Data Inventory” task of the Tide Gate Inventory and Assessment Project and to provide a listing of key points for discussion with the Regional Coordinators (RC’s) during the meeting on Thursday 5/14/2015. Specific items covered as part of this memorandum include:

- Summary of Data Collection Efforts;
- Summary of Available Data and Identified Data Gaps;
- Preliminary List of Proposed Attributes for Inclusion in TIDEGateway; and
- Discussion Points and Requested RC Input.

Summary of Data Collection Efforts

An initial data request to all RC’s on 4/1/2015 in a memorandum titled “TIDEGateway – Initial Data Request for Data Inventory”. Since then, a number new data sources and information have been incorporated into the initial database and bibliography. In total, the initial database currently has fifteen (15) data sources covering all 5 MassBays planning regions, summarized as [Attachment 1](#) of this memorandum. The bibliography will be continually updated as new information is received and incorporated into the database.

Summary of Available Data and Identified Data Gaps

Most of the preliminary database is comprised of entries from the existing tidal atlases (e.g., South Shore, Cape Cod). However, a number of entries have been added and improved upon with added detail provided by the RC’s. As part as the ongoing QA/QC process, a number of attributes (i.e. columns) from separate data sources have been merged (e.g., Restriction ID, Tide Gate Type, etc.) where applicable.

The preliminary database currently has entries for 77 tide gates and is split into 51 different attributes from the combined 17 data sources. Refer to [Attachment 2](#) of this memorandum for a detailed listing of all attributes in the database. The attachment lists all attribute names in “raw” form directly from the data source, lists the number of blank (i.e. missing) entries, and tabulates the overall completion percentage.

The following general observations have been made regarding the existing data:

- General information such as location, Town, and type of flood structure is generally complete.
- The database generally contains a good level of qualitative data such as restoration status, comments, and other general information.
- The database currently lacks quantitative data such as tide gate dimensions, material, shape, etc.

Preliminary List of Proposed Attributes

Using information from the initial database, a preliminary list of attributes (“Data Dictionary”) that will comprise the TIDEGateway geodatabase was developed and is presented as [Attachment 3](#) of this memorandum. The attribute list is presented based on category (e.g., tide gate characteristics, natural resources, etc.) and provides additional information such as field names, domain values, and descriptive language. Note that all attributes in the initial database have not been included in the preliminary list of proposed attributes (e.g., USGS Quad Number). However, this information will be saved in a table that can be easily appended to the main geodatabase based on a common unique identifier.

Some additional attributes have been incorporated into the preliminary list to enable collection of vital information during field data collection. For example, attributes that will be critical for development of the geospatial analysis tool have been incorporated, such as controlling elevation and culvert characteristics.

Discussion Points and Requested RC Input

In particular, we are seeking input from the RCs on the following items:

1. Data collection next steps strategy discussion
 - a. Best and most efficient means to address existing data gaps?
 - b. Coordination with municipal staff
 - c. Other suggestions?
2. Input on preliminary data dictionary
 - a. Any additional items that RC’s would like to see incorporated into the TIDEGateway geodatabase?
3. Initial thoughts on preferred information to be included on fact sheets to be generated for each tide gate?
 - a. See [Attachment 4](#) for the example fact sheet (from Geosyntec’s project proposal)
4. Field data collection methods
 - a. Controlling elevation data collection
 - b. Private vs. public property access issues
 - c. Field data collection preference – paper form versus electronic data collection?
5. General comments

ATTACHMENT 1:
Preliminary Bibliography

| Source ID | Description | Date | Source | Accessed On | Accessed From | Comments | | | | | | Link |
|-----------|-----------------------------------------------------------------------------------------------------------------------|-----------|--------------------------------------------------------------|-------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------------|--------------|-------------------|-------------------|---------------------------|
| | | | | | | | Cape Cod | South Shore | Metro Boston | Lower North Shore | Upper North Shore | |
| 1 | Atlas of Tidal Restrictions on the South Shore of Massachusetts | 12/1/2001 | Metropolitan Area Planning Council | 4/17/2015 | http://maps.massgis.state.ma.us/czm/moris/pdfs/habitatlas/south_shore_atlas.pdf | Detailed information on restrictions and tide gates in tabular form | 0 | 1 | 1 | 0 | 0 | Source 1 |
| 2 | Cape Cod Atlas of Tidally Restricted Salt Marshes | 12/1/2001 | Cape Cod Commission | 4/17/2015 | http://www.capecodcommission.org/resources/coastalresources/TidalAtlas.pdf | Detailed information on restrictions and tide gates in tabular form | 1 | 0 | 0 | 0 | 0 | Source 2 |
| 3 | Atlas of Tidally Restricted Marshes - North Shore of Massachusetts | 12/1/1996 | Massachusetts Wetlands Restoration & Banking Program | 4/21/2015 | http://www.mass.gov/envir/massbays/pdf/moris/north_shore_tidally_restricted_marshes_atlas.pdf | No available information in tabular form | 0 | 0 | 0 | 1 | 1 | Source 3 |
| 4 | List of Tide Gates in MassBays Program, Cape Cod region | 7/29/2014 | Jo Ann Muramoto, Association to Preserve Cape Cod | 4/21/2015 | N/A | Updated list of Tide Gates sources from Cape Cod Atlas | 1 | 0 | 0 | 0 | 0 | Source 4 |
| 5 | Great Marsh Restoration Plan Data | 4/3/2015 | Franz Ingelfinger, Division of Ecological Restoration MA DFG | 4/3/2015 | Personal email communication on 4/3/15 | Two kmz files: (1) sites within the Great Marsh Restoration Plan in North Coastal area, and (2) potential restoration sites which were investigated during planning effort. Files in polygon form with Site ID, perimeter, and area. | 0 | 0 | 0 | 0 | 1 | Source 5 |
| 6 | South Shore Tide Gate Info | 4/14/2015 | Sara Grady, MassBays National Estuary Program | 4/14/2015 | Personal email communication on 4/14/15 | Edits to initial data request spreadsheet dated 4/7/2015 | 0 | 1 | 0 | 0 | 0 | Source 6 |
| 7 | Rumney Marsh Restoration: Status of Restorations Completed to Date and Potential Future Projects Involving Tide Gates | 4/8/2015 | Edward Reiner, USEPA New England | 4/8/2015 | Personal email communication on 4/8/2015 | Power point presentation; includes locations of tide gates and conditions; see source 12 | 0 | 0 | 1 | 0 | 0 | Source 7 |
| 8 | Tide Gates_draft 04012015_forRCs Eric H | 4/17/2015 | Eric Hutchins, NOAA | 4/17/2015 | Personal email communication on 4/17/2015 | Edits to initial data request spreadsheet dated 4/7/2015 | 0 | 1 | 1 | 0 | 1 | Source 8 |
| 9 | Tide Gates_draft 04012015_forRCs_FI_Notes | 4/17/2015 | Franz Ingelfinger, Division of Ecological Restoration MA DFG | 4/17/2015 | Personal email communication on 4/17/2015 | (1) Edits to initial data request spreadsheet dated 4/7/2015; (2) kmz file with tide gate locations | 1 | 1 | 0 | 0 | 0 | Source 9 |
| 10 | Tide Gates_draft 04012015_forRCs_FI_Notes-LowerNorth Shore | 4/17/2015 | Barbara Warren, Salem Sound Coastwatch | 4/17/2015 | Personal email communication on 4/17/2015 | (1) Edits to initial data request spreadsheet dated 4/7/2015 (2) kmz file with tide gate locations | 0 | 0 | 0 | 1 | 0 | Source 10 |
| 11 | Letter of support for removal of culvert boards at Namskaket Salt Marsh on the Brewster/Orleans town line. | 4/21/2015 | Jo Ann Muramoto, Association to Preserve Cape Cod | 4/21/2015 | Personal email communication on 4/21/2015 | APCC letter to remove flash boards on two box culverts installed January 2007 in upstream section of Namskaket Salt Marsh in Brewster/Orleans | 1 | 0 | 0 | 0 | 0 | Source 11 |
| 12 | Rumney Marsh GIS data | 4/23/2015 | Jori Bonner, USEPA New England | 4/23/2015 | Personal email communication on 4/23/2015 | (1) GIS data with tide gate locations, restoration areas, and land fill in Rumney Marsh; (2) pdf of restoration areas and tidal restrictions in Rumney Marsh; (3) table of tide gate info (useful info, same tide gate info as pdf) | 0 | 0 | 1 | 0 | 0 | Source 12 |
| 13 | Tide Gate Info | 4/22/2015 | Lisa Engler, Mass CZM (Boston Harbor Region) | 4/22/2015 | Personal email communication on 4/22/2015 | Information about 3 tide gates (2 proposed) in Boston region; including attachments | 0 | 1 | 1 | 0 | 0 | Source 13 |
| 14 | The City of Salem Climate Change Vulnerability Assessment & Adaptation Plan | 12/1/2014 | Kathryn Glenn, Mass CZM (North Shore) | 4/23/2015 | http://salem.com/Pages/SalemMA_DPCD/studies | Salem Climate Change Plan - does not go into detail, lists approx. location of two tide gates. | 0 | 0 | 0 | 1 | 0 | Source 14 |
| 15 | RE Data Gathering - Tide Gate Inventory and Assessment | 4/22/2015 | Peter Phippen, MVPC | 4/22/2015 | Personal email communication on 4/22/2015 | Confirmation on location of 2 tide gates. | 0 | 0 | 0 | 0 | 1 | Source 15 |

ATTACHMENT 2:

List of Existing Attributes and Data Gaps

| Attribute ID | Raw Attribute Name | Number of Blank Entries | Complete (%) |
|--------------|------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| 1 | Unique ID (Geo) | 0 | 100% |
| 2 | Region | 0 | 100% |
| 3 | Town | 0 | 100% |
| 4 | County | 55 | 29% |
| 5 | Tidal Restriction Atlas ID # | 33 | 57% |
| 6 | Lat (N) | 31 | 60% |
| 7 | Long (W) | 31 | 60% |
| 8 | Lat (dec) | 11 | 86% |
| 9 | Long (dec) | 11 | 86% |
| 10 | USGS Quad | 52 | 32% |
| 11 | Location (Water Body, Road) | 2 | 97% |
| 12 | Water Level Controlling Elevation (tide gate invert elevations, etc.) | 76 | 1% |
| 13 | Type of Engineered Flood Control Structure / Description | 3 | 96% |
| 14 | Restoration Status | 43 | 44% |
| 15 | Owner / Operator | 48 | 38% |
| 16 | Permit Status | 77 | 0% |
| 17 | Other | 76 | 1% |
| 18 | Priority Code | 52 | 32% |
| 19 | Anadromous Fishway | 34 | 56% |
| 20 | Contiguous Open Space | 34 | 56% |
| 21 | Shellfish Area | 34 | 56% |
| 22 | Flood Structure | 52 | 32% |
| 23 | ACEC | 34 | 56% |
| 24 | Potential Upstream Benefits | 52 | 32% |
| 25 | Feasibility | 52 | 32% |
| 26 | Culvert Shape | 52 | 32% |
| 27 | Number of openings | 52 | 32% |
| 28 | # of Piers | 52 | 32% |
| 29 | Structure Material | 52 | 32% |
| 30 | Structure Condition | 52 | 32% |
| 31 | Surface | 52 | 32% |
| 32 | Ponded water on seaward side of restriction | 52 | 32% |
| 33 | Ponded water on upstream side of restriction | 52 | 32% |
| 34 | Proximity to Low Lying Area | 52 | 32% |
| 35 | Date of site visit | 52 | 32% |
| 36 | Site Photo | 52 | 32% |
| 37 | Comments | 52 | 32% |
| 38 | Wetland Area Affected | 53 | 31% |
| 39 | Size of upstream affected area (salt marsh acres) | 59 | 23% |
| 40 | Size of upstream affected area (total affected acres) | 58 | 25% |
| 45 | Does the affected area include Priority Habitat or Rare Species (PH) or Estimated Habitat of Rare Wildlife (WH)? | 59 | 23% |
| 46 | Are there restricted sites upstream of this site (site number)? | 59 | 23% |
| 48 | Restriction Width (feet) | 59 | 23% |
| 49 | Restriction Length (feet) | 59 | 23% |
| 51 | Notes | 59 | 23% |

| Category | Field Name | Domain Value(s) | Description |
|---------------------------|------------------|----------------------------------------|-------------------------------------------------|
| General | UNIQUE_ID | # | Unique Identifier |
| | REGION | (e.g., South Shore, etc.) | MassBays Planning Region |
| | TOWN | - | Town |
| | LAT | # | Latitude |
| | LON | # | Longitude |
| | OPERATOR | - | Owning / Maintaining Agency |
| | PERMITS | - | Existing State or Federal Permits |
| | GEN_COMMENTS | - | General Comments |
| Tide Gate Characteristics | TYPE | Flapper / Sluice / SRT / Etc. | Tide Gate Type |
| | CNTRL_MECH | Actuator / Hinge / Other / Etc. | Tide Gate Control Mechanism |
| | GEOMETRY | Round / Rectangular / Other | Tide Gate Geometry |
| | TG_DIAMETER | # | Tide Gate Diameter (IF Rectangular THEN length) |
| | TG_HEIGHT | # | Tide Gate Height (If Rectangular) |
| | CNTRL_EL | # | Controlling Elevation |
| | INV_EL | # | Invert Elevation (measuredown) |
| | TG_MATERIAL | Wooden / Alumimum / Etc. | Tide Gate Material |
| | TG_CONDITION | Good / Fair / Poor | Qualitative condition assessment |
| | NO_GATES | # | Number of Tide Gates |
| | INSTALL_DATE | # | Installation Date |
| | STATUS | Active / Proposed / Abandoned / Uknown | Operational Status |
| | OP_COMMENTS | (e.g., closed before storm) | Operational Notes |
| | TG_COMMENTS | - | Misc. Tide Gate Comments |
| Culvert Characteristics | RESTRICT_TYPE | Dike / Berm / Dam / Etc. | Restriction type |
| | RESTRIC_SURF | Roadway / Earthen / Etc. | Restriction Surface |
| | CUL_GEOMETRY | Round / Rectangular / Other | Culvert Geometry |
| | CUL_DIAMETER | # | Culvert Diameter (IF Rectangular THEN length) |
| | CUL_HEIGHT | # | Culvert Height (IF Rectangular ELSE N/A) |
| | CUL_MATERIAL | Concrete / Stone / CMP / Etc. | Culvert Material |
| | CUL_MAT_BOT | Riprap / Sand / Stone / Etc. | Culvert Bottom Material |
| | CUL_CONDITION | Good/Fair/Poor | Qualitative Condition Assessment |
| | NO_PIPES | # | Number of Culverts |
| | CUL_COMMENTS | - | Misc. Culvert Comments |
| Natural Resources | ACEC | Y/N | Area of Critical Environmental Concern |
| | SHELLFISH | Y/N | Shellfish Area |
| | RARE_SPECIES | Y/N | Rare Species Area |
| | PRIORITY_HABITAT | Y/N | Priority Habitat Area |
| | ANDR_FISH | Y/N | Andronomous Fishway |
| | WQ_DATA | Y/N | Water Quality Available |
| Restoration Consideration | US_TOTAL | # | Total Upstream Affected Area |
| | US_MARSH | # | Total Upstream Affected Salt Marsh Area |
| | FEASIBILITY | H/M/L | Restoration feasibility |
| | US_INFRA | Y/N | Upstream Infrastructure |
| | REST_STATUS | (e.g., Removal pending) | Restoration Status |
| | REST_COMMENTS | - | Misc. Restoration Comments |
| Miscellaneous | VISIT_DATE | Date | Date of last site visit |
| | PHOTOID_1 | # | Site Visit Photo ID 1 |
| | PHOTOID_2 | # | Site Visit Photo ID 2 |
| | PHOTOID_3 | # | Site Visit Photo ID 3 |
| | PHOTOID_4 | # | Site Visit Photo ID 4 |
| | VISIT_COMMENTS | - | Misc. Site Visit Comments |
| Source Data | SOURCE_1 | # | Primary Source ID |
| | SOURCE_2 | # | Secondary Source ID |
| | SOURCE_3 | # | Tertiary Source ID |
| | SOURCE_4 | # | Fourth Source ID |

ATTACHMENT 3:
Preliminary Data Dictionary

| Category | Field Name | Domain Value(s) | Description |
|---------------------------|------------------|----------------------------------------|-------------------------------------------------|
| General | UNIQUE_ID | # | Unique Identifier |
| | REGION | (e.g., South Shore, etc.) | MassBays Planning Region |
| | TOWN | - | Town |
| | LAT | # | Latitude |
| | LON | # | Longitude |
| | OPERATOR | - | Owning / Maintaining Agency |
| | PERMITS | - | Existing State or Federal Permits |
| | GEN_COMMENTS | - | General Comments |
| Tide Gate Characteristics | TYPE | Flapper / Sluice / SRT / Etc. | Tide Gate Type |
| | CNTRL_MECH | Actuator / Hinge / Other / Etc. | Tide Gate Control Mechanism |
| | GEOMETRY | Round / Rectangular / Other | Tide Gate Geometry |
| | TG_DIAMETER | # | Tide Gate Diameter (IF Rectangular THEN length) |
| | TG_HEIGHT | # | Tide Gate Height (If Rectangular) |
| | CNTRL_EL | # | Controlling Elevation |
| | INV_EL | # | Invert Elevation (measuredown) |
| | TG_MATERIAL | Wooden / Alumimum / Etc. | Tide Gate Material |
| | TG_CONDITION | Good / Fair / Poor | Qualitative condition assessment |
| | NO_GATES | # | Number of Tide Gates |
| | INSTALL_DATE | # | Installation Date |
| | STATUS | Active / Proposed / Abandoned / Uknown | Operational Status |
| | OP_COMMENTS | (e.g., closed before storm) | Operational Notes |
| | TG_COMMENTS | - | Misc. Tide Gate Comments |
| Culvert Characteristics | RESTRICT_TYPE | Dike / Berm / Dam / Etc. | Restriction type |
| | RESTRIC_SURF | Roadway / Earthen / Etc. | Restriction Surface |
| | CUL_GEOMETRY | Round / Rectangular / Other | Culvert Geometry |
| | CUL_DIAMETER | # | Culvert Diameter (IF Rectangular THEN length) |
| | CUL_HEIGHT | # | Culvert Height (IF Rectangular ELSE N/A) |
| | CUL_MATERIAL | Concrete / Stone / CMP / Etc. | Culvert Material |
| | CUL_MAT_BOT | Riprap / Sand / Stone / Etc. | Culvert Bottom Material |
| | CUL_CONDITION | Good/Fair/Poor | Qualitative Condition Assessment |
| | NO_PIPES | # | Number of Culverts |
| | CUL_COMMENTS | - | Misc. Culvert Comments |
| Natural Resources | ACEC | Y/N | Area of Critical Environmental Concern |
| | SHELLFISH | Y/N | Shellfish Area |
| | RARE_SPECIES | Y/N | Rare Species Area |
| | PRIORITY_HABITAT | Y/N | Priority Habitat Area |
| | ANDR_FISH | Y/N | Andronomous Fishway |
| | WQ_DATA | Y/N | Water Quality Available |
| Restoration Consideration | US_TOTAL | # | Total Upstream Affected Area |
| | US_MARSH | # | Total Upstream Affected Salt Marsh Area |
| | FEASIBILITY | H/M/L | Restoration feasibility |
| | US_INFRA | Y/N | Upstream Infrastructure |
| | REST_STATUS | (e.g., Removal pending) | Restoration Status |
| | REST_COMMENTS | - | Misc. Restoration Comments |
| Miscellaneous | VISIT_DATE | Date | Date of last site visit |
| | PHOTOID_1 | # | Site Visit Photo ID 1 |
| | PHOTOID_2 | # | Site Visit Photo ID 2 |
| | PHOTOID_3 | # | Site Visit Photo ID 3 |
| | PHOTOID_4 | # | Site Visit Photo ID 4 |
| | VISIT_COMMENTS | - | Misc. Site Visit Comments |
| Source Data | SOURCE_1 | # | Primary Source ID |
| | SOURCE_2 | # | Secondary Source ID |
| | SOURCE_3 | # | Tertiary Source ID |
| | SOURCE_4 | # | Fourth Source ID |

ATTACHMENT 4:

Example Fact Sheet

COBB13: Cohasset, MA

Fact Sheet Date: 1/02/2015

General

Location: 88 Summer St., Cohasset MA
Lat/Long: 42.239640 / -70.794937
Permits: Unknown
Owner: Town of Cohasset

Tide Gate Characteristics

Type (Year Installed): Flapper (1985)
Control Mechanism: Passive backflow prevention
Controlling Elevation: 14' AMSL
Shape (Dimensions): Round (15" dia.)
Condition: Fair
Misc. Notes: Moderate rusting


Restriction Characteristics

Type (Year Installed): Concrete Pipe (1960)
Shape (Dimensions): Circular (15" dia.)
Condition: Good
Misc. Notes: Misc. trash / debris observed


Natural Resources

Water Quality: No data available
Wetland Notes: Abundant upstream Phragmites
Shellfish Resource Area: Yes
ACEC: No
Anadromous Fishway: Potential

Geospatial Analysis Tool Summary Results



Maps / Photos



Location Map



Photo of tide gate dated 6/25/2015



Photo of upstream impoundment dated 6/25/2015

Appendix C:

Municipal Contact Summary

Memorandum

Date: 9 September 2015

To: Lisa Engler, MassBays Program
MassBays and CZM Regional Coordinators

From: Robert Hartzel, Geosyntec Consultants
David Roman, Geosyntec Consultants
Taylor Walter, Geosyntec Consultants

Subject: TIDEGateway – Data Inventory Municipal Contact Summary

Attachments: 1. Municipal Tracking Sheet

The purpose of this memorandum is to provide a brief summary of the efforts and findings from the municipal contact portion of the TIDEGateway “Data Inventory” task. The purpose of the task was to collect and update the TIDEGateway geodatabase with additional information from town personnel prior to initiating field data collection. All 50 towns within the MassBays planning region were contacted via phone and email from July through August 2015.

Preparation

Prior to initiating the task, contacts were identified for each town including Conservation Administrators, Department of Public Works representatives, and other relevant personnel. In order to streamline the process, a SharePoint based website was created with functionality to enable identified town contacts to edit existing tide gate attributes (or add new tide gates). The SharePoint website had the additional benefit of providing an easy way to track all new data entries and provide QA/QC.

Once the SharePoint framework was created, an introductory email was sent to all identified town contacts. The introductory email included:

- A brief introduction to the TIDEGateway project and the project definition of a Tide Gate;
- The number of Tide Gates assumed for that specific town;
- A town specific SharePoint link for data entry; and
- Attached maps showing locations of known tide gates within each town.

Data Collection Summary

After sending the introductory email, Geosyntec made a follow-up phone call to a contact in each town. The purpose of the call was to provide additional guidance on how to update tide gate information on the SharePoint website, ensure that the proper personnel had been contacted, and to answer any questions. Many towns responded to voicemails left by Geosyntec made efforts to return calls, provided additional

contact information, and forwarded the introductory email to other people in their network to update the SharePoint information.

The table below details the Data Inventory response gathered during July and August 2015. Refer to **Attachment 1** of this memorandum for a list of all towns contacted during this task, including contact names and information, tracking information, and miscellaneous notes.

| Data Inventory Town Response Summary | |
|-------------------------------------------------|----|
| Number of Towns Contacted Via Email | 50 |
| Number of Towns Contacted Via Call | 50 |
| Number of Towns that Answered or Returned Calls | 40 |
| Number of Towns with Responses | 44 |
| Number of Towns that Updated SharePoint | 15 |
| Number of Updated Tide Gate Records | 25 |
| Number of New Tide Gates | 9 |

Notes:

1. *Four towns (Danvers, Dennis, Newbury, and Newburyport) did not provide a response and did not have any verified tide gates.*
2. *The towns of Kingston and Salem did not provide a response and had 3 and 1 presumed tide gates, respectively.*

In general, information provided by town contacts was informative and provided improvements to the data contained in the TIDEGateway geodatabase. A wide variety of attributes were updated for each of the 25 modified tide gate records. For example, town contacts:

- Verified tide gate operators;
- Identified relevant permits;
- Added various operational and general comments;
- Verified and updated tide gate and culvert dimensions and materials; and
- Verified operational purpose (e.g., flood protection), indicated if an operational plan was present.

Note that some municipalities provided feedback about structures that did not fit under into this project's working definition of a Tide Gate (e.g., conveyances installed for the sole purpose of carrying storm drainage). The City of Boston indicated that they did not have any Tide Gates that fit the working definition, but indicated that they had as many as 200 backflow prevention type devices. The Town of Lynn also indicated an existing device in their town which also do not meet this project's definition of a tide gate. A Lynn representative indicated on an entry in the SharePoint Site that "the purpose of the Tide Gate is to inhibit flow of tide from entering into sewer drain system".

Once information was received by towns, QA/QC was performed where all data were reviewed for consistency (e.g., location, units, typos, etc.) prior to being integrated into the geodatabase.

ATTACHMENT 1:
Municipal Tracking Sheet

| Region | Town | Tide Gates? | # Of TGs | Conservation Agent (or other Town contact) | Public Works/Highway/Engineering Dept. | Other Contact Name / Info | Initial Contact Email Sent? | E-mail Send Date | Follow-up Call Made? | Call Date | Did Town Respond? | Updated Sharepoint? | Notes |
|-------------------|--------------|-------------|----------|----------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|-----------------------------------------------------|-----------------------------|------------------|----------------------|----------------------|-------------------|---------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CAPE COD | Barnstable | YES | 2 | Rob Gatewood Conservation Administrator conservation@town.barnstable.ma.us 508-862-4093 | Dale Saad, Senior Project Manager DPW; dale.saad@town.barnstable.ma.us ; 508-790-6400 x4941 | | YES | 7/9/2015 | YES | 7/23/2015 | YES | YES | Dale Saad was indicated as the best contact and he was left a voicemail. |
| CAPE COD | Bourne | NO | 0 | Brandon Mullaney, BMullaney@townofbourne.com 508-759-0615 Option 6 | Mike Leitzel, Town Engineer; MLeitzel@townofbourne.com; 508-759-0615 Opt. 2 | | YES | 7/9/2015 | YES | 8/4/2015 | YES | NO | Brandon Mullaney indicated over the phone Bourne does not have any Tide Gates. |
| CAPE COD | Brewster | YES | 2 | Jim Gallagher, Conservation Administrator conservation@town.brewster.ma.us 508-896-3701 X1135 | Robert Bersin, PE, Supt. dpw@town.brewster.ma.us 508-896-3212 | | YES | 7/9/2015 | YES | 7/23/2015 | YES | YES | Jim Gallagher updated some information over phone. He indicated he may be able to update in the future. |
| CAPE COD | Dennis | YES | 1 | Joseph Rodericks, Town Engineer, jrodricks@town.dennis.ma.us; 508-760-6166x364 | David S. Johansen, Director of DPW, djohansen@town.dennis.ma.us; 508-760-6220 | | YES | 7/9/2015 | YES | 7/23/2015 | NO | NO | Joseph Rodericks and David Johansen were both left a voicemail message but no response was received. |
| CAPE COD | Eastham | YES | 2 | Jeff Thibodeau Environmental Planner/Conservation Administrator conservation@eastham-ma.gov 508-240-5971 | Neil Andres Superintendent nandres@eastham-ma.gov 508-240-5973 | | YES | 7/9/2015 | NO | | YES | YES | Neil Andres, Superintendent, updated the sharepoint site to show 2 inactive Tide Gates |
| CAPE COD | Orleans | YES | 2 | Nathan Sears, Natural Resources, nsears@town.orleans.ma.us; 508-240-3755 | Mark Budnick Manager highway@town.orleans.ma.us 508-240-3700 X470 | | YES | 7/9/2015 | YES | 7/22/2015 & 8/6/2015 | YES | NO | Mark Budnick emailed Lisa Engler about the Tide Gates in Orleans but did not follow up after additional voicemail and intro email were sent to him. |
| CAPE COD | Provincetown | NO | 0 | Brian Carlson 508-487-7000 X537 | Richard J. Waldo Director of Public Works rwaldo@provincetown-ma.gov 508-487-7060 | | YES | 7/9/2015 | YES | 7/22/2015 | YES | NO | Jane, DPW secretary, indicated that no Tide Gates exist. |
| CAPE COD | Sandwich | YES | 3 | Mark Galkowski; naturalresources@townofsandwich.net 508-833-8054 | Paul Tilton Director dpw@townofsandwich.net 508-833-8002 | | YES | 7/9/2015 | YES | 8/4/2015 | YES | YES | Mark Galkowski updated the sharepoint site. |
| CAPE COD | Truro | YES | 3 | Patricia Pajaron, Conservation Agent (508) 349-7004 x32 | Paul Morris; dpwdirector@truro-ma.gov Michael; dpwclerk@truro-ma.gov 508-349-2140 | | YES | 7/9/2015 | YES | 8/4/2015 | YES | YES | Voicemail left for Patricia Parjaron. Spoke with Michael at the DPW and sent him the initial intro email for him to fill out. Sharepoint was updated by anonymous. |
| CAPE COD | Wellfleet | YES | 2 | Hilary Greenberg | Mark Vincent Director mark.vincent@wellfleet-ma.gov 508-349-0315 | paul lindberg DPW paul.lindberg@wellfleet-ma.gov | YES | 7/9/2015 | YES | 8/3/2015 | YES | NO | Paul Lindberg returned a call to indicate he would update the sharepoint however the update did not occur. |
| CAPE COD | Yarmouth | NO | 0 | Kerry Muldoon Conservation Administrator kmuldoon@yarmouth.ma.us 508-398-2231 ext 1288 | Robert Angell, Assistant Director rangell@yarmouth.ma.us 508-775-2516 | natural resources group - Bill/Carl 508-760-4800 | YES | 7/9/2015 | YES | 7/22/2015 | YES | NO | Tim Parsons in Natural Resources confirmed that no Tide Gates exist in Yarmouth. |
| LOWER NORTH SHORE | Beverly | YES | 1 | Amy Maxner in Planning Department 978-921-6000 | Michael Collins 978-921-6053 mcollins@beverlyma.gov | | YES | 7/9/2015 | Yes | 7/23/2015 | YES | NO | The Tide Gate at Shoe Pond might be private. No new information available and no sharepoint update occurred. |
| LOWER NORTH SHORE | Danvers | NO | 0 | Susan Fletcher 978-777-0001 x3099 sfletcher@mail.danvers-ma.org | Aaron Cilluffo 978-762-0230 acilluffo@mail.danvers-ma.org | | YES | 7/9/2015 | YES | 7/23/2015 | NO | NO | Calls placed but no response was received via email or additional messages. |
| LOWER NORTH SHORE | Lynn | NO | 0 | Judith Lewin Callahan (781) 598-4000 X 6816 jlwin@lynnma.gov | J.T. Gaucher 781-268-8000 jtgaucher@lynnma.gov | RaeAnna Hughes, Water and Sewer Department | YES | 7/9/2015 | YES | 7/23/2015 | YES | YES | RaeAnna Hughes indicated in sharepoint that the tidegate stopped tidal flow from entering the storm sewer. This is not considered for this project. |
| LOWER NORTH SHORE | Manchester | YES | 1 | Chris Bertonic 978-526-4397 bertonic@manchester.ma.us | Carol Murray 978-526-1242 murrayc@manchester.ma.us | Mary Rielly riellym@manchester.ma.us | YES | 7/9/2015 | YES | 7/23/2015 | YES | YES | Sharepoint was updated by anonymous indicating that 1 Tide Gate does exist. |

| Region | Town | Tide Gates? | # Of TGs | Conservation Agent (or other Town contact) | Public Works/Highway/Engineering Dept. | Other Contact Name / Info | Initial Contact Email Sent? | E-mail Send Date | Follow-up Call Made? | Call Date | Did Town Respond? | Updated Sharepoint? | Notes |
|-------------------|------------|-------------|----------|-------------------------------------------------------------------------------|---------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|-----------------------------|------------------|----------------------|-----------|-------------------|---------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|
| LOWER NORTH SHORE | Marblehead | NO | 0 | William Lanphear 781-631-1529 conservation@marblehead.org | David Donahue 978-631-1750 highway@marblehead.org | | YES | 7/9/2015 | YES | 7/23/2015 | YES | NO | Amy McHugh, Water and Sewer Department, was indicated as the best contact. A call and email was sent but no response. |
| LOWER NORTH SHORE | Nahant | NO | 0 | Ellen Steeves esteeves@partners.org 781-581-0088 | Timothy T. Lowe tlowe@nahant.org 781-581-0026 | | YES | 7/9/2015 | YES | 7/23/2015 | YES | NO | Ellen Steeves indicated that no Tide Gates exist. |
| LOWER NORTH SHORE | Peabody | NO | 0 | Lucia DelNegro 978-538-5782 Lucia.DelNegro@peabody-ma.gov | Robert J. Langley 978-536-7123 Robert.Langley@peabody-ma.gov | William Paulitc - Engineer at DPW | YES | 7/9/2015 | YES | 8/5/2015 | YES | NO | William Paulitc, Engineer at DPW, indicated that no Tide Gates exist. |
| LOWER NORTH SHORE | Salem | YES | 3 | Tom Devine 978-619-5685 tdevine@salem.com | John Tomasz 978-744-3302 jtomasz@salem.com | David Knowlton, Engineering Department; (978) 619-5673 | YES | 7/9/2015 | YES | 8/3/2015 | NO | NO | Left voicemail and sent emails for Tom Devine and David Knowlton but no responses were received. |
| LOWER NORTH SHORE | Swampscott | YES | 3 | Nelson Kessler 781-596-8829 | Gino Cresta Jr. 781-596-8860 gcresta@town.swampscott.ma.us | | YES | 7/9/2015 | YES | 7/22/2015 | YES | NO | Gino Cresta indicated that 3 Tide Gates exist and would update the sharepoint but no update occurred. |
| METRO BOSTON | Boston | YES | 2 | Charlotte Moffat charlotte.moffat@cityofboston.gov 617-635-3850 | Joanne Massaro publicworks@cityofboston.gov 617-635-4900 | | YES | 7/9/2015 | NO | | YES | NO | Charlotte Moffat indicated that Charlie Jewellsaid none of the Boston Water and Sewer Commission's tidegates have two-way movement |
| METRO BOSTON | Braintree | NO | 0 | Kelly Phelan, Conservation Planner 781 794-8233 kphelan@braintreema.gov | Marlene Michonski, Office Manager 781-843-8097 mmichonski@braintreema.gov | | YES | 7/9/2015 | YES | 7/17/2015 | YES | NO | Kelly Phelan indicated that no Tide Gate exist within Braintree's town limits. |
| METRO BOSTON | Chelsea | YES | 2 | John DePriest JDePriest@chelseama.gov 617-466-4180 | Joe Foti 617-466-4200 | | YES | 7/9/2015 | YES | 7/23/2015 | YES | YES | Andrew B. DeSantis updated sharepoint and indicated that 2 tidegates exist. May also have ties with Revere. |
| METRO BOSTON | Everett | YES | 1 | Michael Gove Michael.Gove@ci.everett.ma.us 617-394-2262 | Tony Sousa Tony.Sousa@ci.everett.ma.us 617-394-2385 | | YES | 7/9/2015 | YES | 7/23/2015 | YES | YES | Mike Gove updated Sharepoint with a Tide Gate that is not functional. |
| METRO BOSTON | Hingham | YES | 6 | Abby Pearsall piersalla@hingham-ma.gov 781-741-1445 | Randy Sylvester 781-741-1430 | | YES | 7/9/2015 | YES | 7/23/2015 | YES | YES | Sharepoint was updated and indicated that 1/6 Tide Gates were inactive. |
| METRO BOSTON | Hull | YES | 4 | Anne Herbst aberbst@town.hull.ma.us 781-925-8102 | Joseph Stigliani, DPW Director; 781-925-0051; jstigliani@town.hull.ma.us | | YES | 7/9/2015 | YES | 7/23/2015 | YES | YES | Anne Herbst updated sharepoint for the town of Hull. |
| METRO BOSTON | Milton | NO | 0 | Kathy Bowen kbowen@townofmilton.org | John Thompson, Town Engineer; 617-898-4900x4869; jthompson@townofmilton.org | | YES | 7/9/2015 | YES | 7/23/2015 | YES | NO | John Thompson indicated over the phone that no Tide Gates existed to the best of his knowledge. |
| METRO BOSTON | Quincy | YES | 6 | Shawn Hardy shardy@quincyma.gov 617-376-1367 | Daniel Raymondi draymondi@quincyma.gov 617-376-1900 | Peter Hoyt - DPW - phoyt@quincyma.gov Karen White - DPW Secretary - kwhite@quincyma.gov | YES | 7/9/2015 | YES | 8/3/2015 | YES | NO | Peter Hoyt is the tidegate administrator for the town of Quincy. He indicated that he would update the Sharepoint survey with his team. No update occurred. |
| METRO BOSTON | Revere | YES | 11 | Andrew DeSantis 781-286-8181 | Joan LeBlanc joanleblanc@earthlink.net 781-286-8149 | | YES | 7/9/2015 | YES | 7/31/2015 | YES | NO | Andrew DeSantis indicated he would sharepoint to his ability and also forwarded the email around the department. No update was seen for Revere. |
| METRO BOSTON | Saugus | YES | 3 | Frank McKinnon 781-231-4129 fmckinnon@saugus-ma.gov | James Waugh 781-231-4145 jwaugh@saugus-ma.gov | Brendan O'regan - DPW Director 781-231-4144 boregan@saugus-ma.gov | YES | 7/9/2015 | YES | 7/30/2015 | YES | NO | Bredan O'Regan, DPW Director, indicated over the phone that he was not aware of any tidegates within the town limits. |

| Region | Town | Tide Gates? | # Of TGs | Conservation Agent (or other Town contact) | Public Works/Highway/Engineering Dept. | Other Contact Name / Info | Initial Contact Email Sent? | E-mail Send Date | Follow-up Call Made? | Call Date | Did Town Respond? | Updated Sharepoint? | Notes |
|-------------------|------------|-------------|----------|-----------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|---------------------------------------------------------|-----------------------------|------------------|----------------------|-------------------------|-------------------|---------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| METRO BOSTON | Weymouth | YES | 3 | Mary Ellen Schloss mschloss@weymouth.ma.us 781-340-5007 | Kenan Connell 781-337-5100 | Braydon Marot, Weymouth DPW Engineering Department | YES | 7/9/2015 | YES | 8/3/2015 | YES | YES | Braydon Marot - project engineer updated one tidegate in weymouth - no other information was provided for 2nd tidegate. Potentially a 3rd tidegate indicated by Mary Ellen. |
| METRO BOSTON | Winthrop | YES | 2 | Marsha Allen conservation@town.winthrop.ma.us 617-539-5821 | Steven Calla scalla@town.winthrop.ma.us 617-846-1341 | | YES | 7/9/2015 | YES | 8/4/2015 | YES | NO | Marsha called back - requested to resend email over and she will forward to DPW. |
| SOUTH SHORE | Cohasset | YES | 5 | Paul Shea paulshea@cape.com (781) 383-4182 | Brian Joyce bjoyce@cohassetma.org 781-383-0273 | Nancy Noonan (781) 383-4182x118 conservation department | YES | 7/9/2015 | YES | 7/23/2015 | YES | YES | Paul Shea and Brian Joyce were both left voicemails. Anonymous Updated Sharepoint. |
| SOUTH SHORE | Duxbury | YES | 0 | Conservation-Administrator@town.duxbury.ma.us (781) 934-1100; EXT. 5471 | Peter Buttkus Director Buttkus@Town.Duxbury.MA.US 781-934-1100 x5501 or x5502 | Bruce O'neill - Highway Department DPW | YES | 7/9/2015 | YES | 7/23/2015 | YES | NO | Bruce O'Neill indicated that no tidegates exist in Duxbury. One used to exist at blue fish river but no longer exists. |
| SOUTH SHORE | Hanover | NO | 0 | Amy Walkey, Conservation Agent, 781-826-5000x1019; | Victor Diniak 781-826-3189; office@hanoverdpw.org | | YES | 7/9/2015 | YES | 7/23/2015 & 8/4/2015 | YES | NO | Amy Walkey indicated that no Tide Gates exist in Hanover. |
| SOUTH SHORE | Kingston | YES | 1 | Maureen Thomas Conservation - 781-585-0537; mthomas@kingstonmass.org | <u>Found email but no name</u> richards@kingstonmass.org | | YES | 7/9/2015 | YES | 8/4/2015 | NO | NO | Email sent out to Maureen Thomas but no response was heard. |
| SOUTH SHORE | Marshfield | YES | 5 | Jay Wennemer Conservation Agent jwennemer@townofmarshfield.org 781-834-5573 | Rod Procaccino Rprocaccino@townofmarshfield.org 781-834-5575 | | YES | 7/9/2015 | NO | | YES | YES | Jay & Rod Responded and updated Sharepoint |
| SOUTH SHORE | Norwell | NO | 0 | Nancy Hemingway, Conservation Agent, 781-659-8022; nhemingway@townofnorwell.net | Paul Foulsham pfoulsham@townofnorwell.net 781-659-8042 | | YES | 7/9/2015 | YES | 7/23/2015 | YES | NO | Nancy Hemingway indicated that no Tide Gates exist in Norwell. |
| SOUTH SHORE | Pembroke | NO | 0 | Mary Guiney; 781-293-4674; mguiney@townofpembrokemass.org | Eugene Fulmine; Director of Public Works; 781-293-5620; efulminejr@townofpembrokemass.org | | YES | 7/9/2015 | NO | | YES | YES | Department of Public Works indicated Pembroke has no existing or proposed tide gates. |
| SOUTH SHORE | Plymouth | NO | 0 | David Gould dgould@townhall.plymouth.ma.us 508-747-1620 (ext. 139) | Jonathan Beder Director JBeder@townhall.plymouth.ma.us (508) 830-4162 x105 | | YES | 7/9/2015 | YES | 7/22/2015 | YES | NO | David Gould indicated over a phone call that no Tide Gates exist in the town of Plymouth. |
| SOUTH SHORE | Scituate | YES | 5 | Patrick Gallivan Conservation Agent (781) 545-8721 | Kevin Cafferty kcafferty@scituatema.gov 781-545-8731 | | YES | 7/9/2015 | YES | 8/3/2015 | YES | NO | 3 Separate calls placed to Scituate. DPW Secretary forwarded intro email to entire engineering department. |
| UPPER NORTH SHORE | Amesbury | NO | 0 | Laurie Pierce laurie@amesburyma.gov | Robert Desmarais, Director of Public Works; 978-388-8116; | John Lopez - conservation district - 978-388-8110 | YES | 7/9/2015 | YES | 8/4/2015 | YES | NO | John Lopez Confirmed over the phone that no Tide Gates exist. |
| UPPER NORTH SHORE | Essex | NO | 0 | Deborah Cunningham, Administrative Clerk Bill Decie, Agent 978-768-2509; conservation@essexma.org | Mandy Davis Admin Clerk adavis@essexma.org (978)768-6262 | | YES | 7/9/2015 | YES | 8/5/2015 | YES | NO | Town of Essex indicated over the phone that no Tide Gates exist. |
| UPPER NORTH SHORE | Gloucester | YES | 1 | Lisa Press lpress@gloucester-ma.gov (978) 281-9781 | Mark Cole, Michael Hale 978 281-9785 | Ken Whittaker - Conservation | YES | 7/9/2015 | YES | 7/23/2015 | YES | NO | Left a message for Ken Whittaker - Conservation and sent out info email to Mike Hale |
| UPPER NORTH SHORE | Ipswich | NO | 0 | David Pancoast 978-356-6661; | Rick Clarke DPW Director 978 356-6612 | Alicia Gelin AliciaG@ipswich-ma.gov | YES | 7/9/2015 | YES | 7/23/2015 | YES | NO | Alicia Gelin Indicated that no Tide Gates exist. |
| UPPER NORTH SHORE | Newbury | NO | 0 | Doug Packer 978-465-0862 ext. 310; conscm@townofnewbury.org | James Sarrette Foreman 978 465-0112 | | YES | 7/9/2015 | YES | 7/23/2015 | NO | NO | Doug Packer was left a voicemail but there was no response. |

| Region | Town | Tide Gates? | # Of TGs | Conservation Agent (or other Town contact) | Public Works/Highway/Engineering Dept. | Other Contact Name / Info | Initial Contact Email Sent? | E-mail Send Date | Follow-up Call Made? | Call Date | Did Town Respond? | Updated Sharepoint? | Notes |
|-------------------|-------------|-------------|----------|--------------------------------------------------------------------------------------------|-------------------------------------------------------|----------------------------------------------------------|-----------------------------|------------------|----------------------|-------------------------|-------------------|---------------------|----------------------------------------------------------------------------------------------------------------|
| UPPER NORTH SHORE | Newburyport | NO | 0 | Julia Godtfredsen jgodtfredsen@cityofnewburyport.com 978-465-4400 ext.6; | (978) 465-4420 DPW # dps@cityofnewburyport.com | John-Eric White - Engineer DPW - 978-465-4464 ex 1710 | YES | 7/9/2015 | YES | 7/23/2015 & 8/6/2015 | NO | NO | Left message for Julia, and John, and Eric but no response was received. |
| UPPER NORTH SHORE | Rockport | NO | 0 | Geralyn Falco 978-546-5005 gfalco@town.rockport.ma.us | Tim Olson 978-546-3525; tolson@rockportma.gov | | YES | 7/9/2015 | YES | 7/25/2015 | YES | NO | Tim Olson responded to voicemail and his old email address was bad and said that no Tide Gates exist. |
| UPPER NORTH SHORE | Rowley | NO | 0 | Brent Baeslack 978-948-2330; Conservation@TownofRowley.org | Patrick Snow 978-948-2441 highway@townofrowley.org | | YES | 7/9/2015 | YES | 8/4/2015 | YES | NO | Brent Baeslack indicated that no Tide Gates exist in Rowley. |
| UPPER NORTH SHORE | Salisbury | YES | 1 | Michelle Rowden (Cons. Agent); 978-499-0358; conservation@salisburyma.gov 978-463-0656; | Don Levesque (Hwy Dept.) dlevesque@salisburyma.gov | | NO | N/A | NO | | YES | NO | Michelle Rowden indicated that over the phone that 1 Tide Gate exists but did not have extraneous information. |

Appendix D:

Field Data Collection Protocols



**Field Data Collection &
Database Update Protocols**

October 2015

Contents

| | |
|-------------------------------------------------------|----|
| Contents | 2 |
| I. INTRODUCTION | 3 |
| A. Background | 3 |
| B. Scope | 3 |
| C. Definitions | 3 |
| II. SAFETY | 5 |
| III. PROTOCOLS | 6 |
| A. Tide Gate Selection | 6 |
| B. Pre-Visit Planning | 6 |
| C. Data Collection and Entry | 7 |
| D. Supplemental Data Collection Instructions | 8 |
| Tide Gate Naming Convention | 8 |
| Photograph Documentation | 8 |
| Tide Gate Type and Control Mechanism | 8 |
| Tide Gate Condition | 9 |
| Culvert Condition | 9 |
| Extent of Existing Tidal Influence (Upstream) | 10 |
| Extent of Existing Tidal Influence (Downstream) | 11 |
| Tide Gate Invert Elevation | 11 |
| E. Post-Visit Procedures and Data Upload | 12 |

List of Appendices


- A. Blank Tide Gate Data Entry Instruction Form

I. INTRODUCTION

A. Background

The purpose of TIDEGateway is to serve as a comprehensive and easy-to-use web-based platform for information and planning tools related to tide gates in the MassBays region. The components of TIDEGateway include:

- Comprehensive geodatabase containing all known tide gate information, including locations, attributes, and related documents. The geodatabase contains a robust source tracking tool and interface which enables users to add new tide gates or modify existing tide gates when new information becomes available.
- Geospatial viewer which incorporates wetland delineation and allows users to locate and assess existing tide gates in relation to wetland ecology and FEMA floodplains, the better to inform the management of these structures.



TIDEGateway provides a fully integrated suite of GIS maps, attributes, data, modeling projections and planning tools.

B. Scope

The purpose of this document is to provide protocols for field data collection and for updating TIDEGateway. This reference documentation will ensure that information in the geodatabase can be readily updated and maintained by users.

C. Definitions

Tide Gates:

For this document, tide gates are defined as “*any conveyance of tidal flow with the ability to passively or actively manipulate water flow.*” This definition includes self-regulating tide gates, manually controlled devices, or passive control structures such as flappers. Structures not included in this definition include, but are not limited to, conveyances installed for the sole purpose of carrying storm drainage.

Vertical Datum:

All vertical measurements referred to by this document should be converted and recorded based on the North American Vertical Datum of 1988 (NAVD88).

Existing Extent of Tidal Influence:

The existing extent of tidal influence is defined here as the elevation (in NAVD88) that most closely matches the water surface elevation at the mean high water spring (MHWS) upstream and downstream of the tide control structure under existing conditions.

Tide Gate Invert Elevation:

The lowest interior point of a tide gate (i.e. bottom) where tidal exchange can occur.

II. SAFETY

There are potential safety hazards associated with performing field work at tidally influenced areas. Individuals planning to conduct a tide gate field assessment based on these protocols should develop a site-specific Task Hazard Analysis (THA) or Health and Safety Plan (HASP) in accordance with their organization's policies. The safety precautions listed below are suggested for consideration in THA and HASP preparation:

- **Conditions** – Field activities should only be performed when conditions are safe. Do not attempt to perform activities during foul weather, abnormally high tide, or storm surge conditions. Always check the forecast prior to commencing field work.
- **Accessibility** – Field personnel should never enter the water or take unnecessary risks to access unsafe locations or negotiate challenging terrain to reach advantageous vantage points. If a tide gate is inaccessible due to access limitations or safety concerns, record it as not observable, note the specific reason(s), and move on to the next site.
- **Buddy System** – Field work should always be performed with a “buddy” and there should always be an additional person(s) in the office to act as an external safety contact. Site arrivals and departures should be communicated to the external safety contact.
- **Gear** – All field personnel performing work close to the water's edge should wear a buoyant life jacket or vest and be closely monitored by their “buddy”. A reflective safety vest should be worn at all sites. In addition, bug spray and sunscreen should be available and applied as needed.

III. PROTOCOLS

The field data collection process involves four major activities including site selection, preparation, data collection, data upload procedures. The below sections provide step-by-step instructions for each of these activities. Note that in some instances, field data collection might not be required. For example, a new attribute might become available that does not require field verification. In this instance, Section B can be skipped and the user can proceed directly to Steps C and D to input the data directly into TIDEGateway.

A. Tide Gate Selection

Site selection will be largely contingent on the person(s), organization, or town conducting the inspection(s). For the purposes of these field protocols, the following guidelines are suggested for selection of sites:

- Tide gates with numerous or critical missing attributes (e.g. type, diameter, etc.);
- Tide gates that were not visited by Geosyntec in Fall 2015 during the field data collection phase (this information can be readily found based on the TIDEGateway "VISIT_DATE" attribute);
- Tide gates that are discovered, newly installed, or modified; or
- Instances where existing information needs to be verified based on new information.

Note: Existing information and attributes of tide gates already included in the TIDEGateway geodatabase can be filtered by Town for review and printing at www.tidegateway.com.

B. Pre-Visit Planning

Once tide gates have been selected for field verification and prior to leaving the office, field personnel should know where they are going, understand the information to be collected, and have the appropriate gear to complete the task. In particular, the following preparation steps are recommended:

1. Access TIDEGateway at www.tidegateway.com and print and review existing information and attributes for all tide gates that are planned to be visited. Area maps can also be printed for individual tide gates or groups of tide gates based on a user-specified scale (i.e. zoom). The existing information and attributes for each tide gate can be printed directly from TIDEGateway.
2. Obtain approval from any private landowners if tide gates are located on private property and are not accessible by known easements or the right of way.
3. Review the data entry instruction form (**Appendix A**), existing attributes for each tide gate to be visited, and the protocols in this document to become familiar with all attributes and how they are collected.
4. Prepare a THA or HASP and review suggested safety procedures (Section II, above).
5. Identify a buddy, and inform direct supervisor or external safety contact prior to leaving and provide them with a planned schedule and site visit locations.
6. Use online or municipal-level paper maps to determine the best travel routes and identify any potential accessibility or safety issues (e.g., tide gate located on a busy road).
7. Gather required equipment and gear; see below for a suggested list:

- Digital camera and spare batteries
- Field data collection form for each tide gate
- Navigation & reference site maps
- Pencils & permanent markers
- Waterproof field notebook
- Data entry forms
- 100 foot field tape (i.e. reel) & standard 25 foot tape measure
- Folding 6 foot engineer's ruler and/or telescoping surveyor's rod
- Reflective vest
- Sunscreen and insect repellent
- Life jacket
- Mapping grade Global Positioning System (GPS), preferably Real Time Kinematic (RTK) (optional)
- Biodegradable flagging (optional)

Note: A GPS unit is listed as optional on the gear list. The field protocols have been designed to be performed in the absence of a GPS unit or specialized equipment

C. Data Collection and Entry

The below steps are recommended to be followed while on site:

1. Arrive on site, implement safety procedures, and gain orientation to the site.
2. Inform external safety contact of arrival on site.
3. Proceed with data collection per individualized data entry forms for each tide gate obtained from www.tidegateway.com.
4. Use **Appendix A** as a reference while collecting information on various tide gate attributes. Detailed supplemental instructions for several attributes are included below.
5. Collect and record data on as many attributes as possible following the prompts on the data entry form.
6. Prior to departing the site, inform external safety contact of departure.

Note: A user has the option of logging on directly to TIDEGateway while on site and updating information while in the field. It is recommended that backup, hard-copy notes and data entry forms be kept in case of internet connectivity issues, inclement weather, or other unforeseen issues.

D. Supplemental Data Collection Instructions

Tide Gate Naming Convention

There are three distinct tide gate identification fields present in TIDEGateway:

1. TIDEGateway's editable unique identification field ("TIDEGATE_NAME") based on town location;
2. A sequential numeric identifier automatically populated by the geodatabase and not editable by a user ("UNIQUE_ID"); and
3. The original tidal restriction atlas identifier assigned to a tide gate if applicable ("ORIG_ATLAS_ID") and not editable by a user.

Since the latter two identification fields are not editable, this section focuses on the "TIDEGATE_ID" field. The TIDEGATE_ID field is comprised of three parts based on the town name, sequential number of tide gates in each town, and sequential lettering if there are multiple tide gates at one location (i.e. restriction). For example, if there are 2 tide gates in a town, tide gates in the existing geodatabase are named as Town-01 and Town-02. If there are multiple tide gates at one location (e.g., multiple culverts going through the same restriction berm), sequential letters are appended to the tide gate number. For example, if tide gate 02 in town has three tide gates, the tide gates would be named Town-02A, Town-02B, and Town-03B.

Refer to Part E of this Section for instructions on how to edit or add new tide gates to the geodatabase.

Photograph Documentation

At least four standard photos should be taken at each site as shown below. In addition, there is an option to take up to 8 optional miscellaneous photos.

- Photo 1 - tide gate from downstream location;
- Photo 2 - tide gate / culvert from upstream location
- Photo 3 - area upstream of the tide gate from top of restriction (i.e. berm);
- Photo 4 - area downstream of the tide gate from top of restriction (i.e. berm); and
- Photos 5 through 12 - additional informative photo(s) of field personnels' choosing.

These photos will be accessible as individual hyperlinks on the TIDEGateway map view for each tide gate. See Section E for photo upload instructions.

Tide Gate Type and Control Mechanism

There are a number of different tide gate types and control mechanisms that can be entered into the geodatabase listed by **Appendix A**. Refer to the below captioned photos¹ for typical examples of tide gate types and control mechanisms that will be found in the field during data collection.

¹ Photograph sources from left to right, top to bottom: 1) Ed Reiner, EPA (http://www3.epa.gov/region1/neaeb2012/pdfs/1130_BR3_EdReiner.pdf); 2) Wicked Local (<http://www.wickedlocal.com/article/20110824/News/308249567>); 3) Online marine registry (www.omreg.net); 4) URI EDC (http://www.edc.uri.edu/restoration/html/tech_sci/restsalt.htm); 5) Golden Harvest (http://www.goldenharvestinc.com/products/tide_and_estuary/); 6) Ed Reiner, EPA



Electric Actuator with Manual Hand Wheel in Foreground



Manual Hand Crank



Adjustable Concrete Stop Logs



Self-Regulating Tide Gate with Counterweights



Sluice Gate (actuator not pictured)



Top-Hinged Flapper Gate with no Control Mechanism

Tide Gate Condition

The purpose of the condition assessment is to provide a qualitative (i.e. best judgment) assessment of the tide gate's condition (Good, Fair, Poor) based on a visual inspection. The guidelines below can be used to determine condition entered as the "TG_Condition" attribute:

- **Good** – Minimal signs of disrepair, appears to be in good operating condition.
- **Fair** – Moderate signs of disrepair (rust, cracking, minor blockage), appears to be generally operable.
- **Poor** – Severe signs of disrepair (broken hinges, blocked or rusted closed), appears to be inoperable.

Culvert Condition

The purpose of the condition assessment is to provide a qualitative (i.e. best judgment) assessment of the culvert's condition (Good, Fair, Poor) based on a visual inspection. The guidelines below can be used to determine condition entered as the "CUL_Condition" attribute:

- **Good** – Minimal sign of disrepair, appears to be in good operating condition.

- **Fair** – Moderate signs of disrepair (minor debris accumulation, cracking or spalling), appears to generally be in operable condition.
- **Poor** – Severe signs of disrepair (severe debris accumulation, collapsed or partially collapsed).

Extent of Existing Tidal Influence (Upstream)

The extent of existing tidal influence is defined here as the elevation (in NAVD88) that most closely matches the water surface elevation at MHWS upstream of the tide control structure under existing conditions.

The steps outlined below provide a methodology to rapidly assess the existing extent of tidal influence of each tide gate using observed high water marks (i.e. staining) at culvert headwalls or restriction embankments as an indicator. This methodology is intended to provide *planning level* information (i.e., for general use only) in the absence of more precise information such as water level monitoring data, hydrologic/hydraulic modeling, etc. Within the TIDEGateway analysis tool, the *assessed* extent existing of tidal influence is converted into a polygon representing the planning level extent of existing tidal influence. This polygon is useful for management planning functions, for example to assess restoration potential by comparing the existing area of tidal influence to the existing extent of upstream wetlands.

Notes:

1. If it is readily apparent based on the high water indicator that there is no tidal influence upstream of the tide gate (i.e., flap gate or tide gate is completely closed, culvert is completely blocked, etc.), field assessment of the tidal influence attribute is not necessary and the field can be left blank. Record the reason why this attribute is blank in the "TG_Comments" field.

2. It is recommended that the assessment of tidal elevation extent be carried out as closely as possible to spring tide conditions (and preferably at or near high tide). This will provide additional validation of the indicator. Note that in severely restricted sites, the time of high tide can lag an hour or more behind the forecasted downstream high tide.

The following steps can be used to determine a planning level extent of tidal influence using headwall / embankment staining as an indicator:

1. Walk to the upstream side of the tidal restriction.
2. If there is an upstream headwall or riprap embankment directly adjacent to the restriction, note if any staining (i.e. high water mark) is observed.
 - a. If staining is observed, assess the tidal restriction and make a determination if the staining appears to be caused by tidal exchange. This might be readily apparent based on the presence of some common low marsh species such as *Spartina alterniflora* or readily observable tidal exchange through the restriction (e.g., culvert).
 - b. Best judgment should be used when selecting the reference staining elevation. For example, it is possible that multiple levels of staining marks might be observable. If multiple marks or bands of staining are observed, it is likely that the marking will be lighter in the upper portion of the stained area, presumably due to less frequent inundation events such as storm surge or higher than average spring tides. If this is the case, it is recommended that the darkest portion of the stained area be selected to represent the zone of MHWS.



2. Once staining or a high water mark is identified, two methodologies can be employed to determine the extent of tidal influence in the NAVD88 datum.
 - a. If available, record the staining elevation with a Real Time Kinematic (RTK) GPS unit. Enter the elevation into the "EX_TIDAL_INF_US" field of the TIDEGateway geodatabase in NAVD88 feet. Note that it is important that the utilized GPS unit is set to collect data in NAVD88. Depending on the model, a datum conversion might need to be performed.
 - b. If an RTK GPS is unavailable, take a measure down using a folding engineer's ruler and/or telescoping surveyor's rod to the elevation of the staining from a prominent point observable from aerial imagery such as the top of a headwall or embankment. This measure down can then be later be post-processed into an elevation based on the Light Detection and Ranging (LiDAR) datasets readily available from the Massachusetts Office of Geographic Information (MassGIS) website.
 - i. Once a determination of surface elevation is made via LiDAR, determine the extent of tidal influence based on staining using the equation: Tidal Influence ("EX_TIDAL_INF_US") = LiDAR Elevation minus Measuredown.
 - ii. The final elevation would be entered into the "EX_TIDAL_INF_US" field of the TIDEGateway geodatabase in NAVD88 feet.

Extent of Existing Tidal Influence (Downstream)

The extent of existing tidal influence is defined here as the elevation (in NAVD88) that most closely matches the water surface elevation at MHWS downstream of the tide control structure under existing conditions.

In order to assess the extent of existing downstream tidal influence, replicate the steps provided above at the downstream side of the tide gate and enter findings into the "EX_TIDAL_INF_DS" field of the TIDEGateway geodatabase in NAVD88 feet.

Tide Gate Invert Elevation

The invert elevation is defined here as the lowest interior point of a tide gate (i.e. bottom) where tidal exchange can occur. Two methods can be used to determine the invert elevation in the NAVD88 datum:

1. If available, record the invert elevation of the tide gate with a RTK GPS unit. Enter the elevation into the "INV_EL" field of the TIDEGateway geodatabase in NAVD88 feet. Note that it is important that the utilized GPS unit is set to collect data in NAVD88. Depending on the model, a datum conversion might need to be performed.
2. If an RTK GPS is unavailable, take a measure down to the invert elevation of the tide gate using a folding engineer's ruler and/or telescoping surveyor's rod from a prominent point observable from aerial imagery such as the top of a headwall or embankment. This measure down can then be later be post-processed into an elevation based on the MassGIS LiDAR dataset.
 - a. Once a determination of surface elevation is made via LiDAR, determine the invert elevation using the equation: Invert Elevation ("INV_EL") = LiDAR Elevation minus Measuredown.
 - b. The final elevation would be entered into the "INV_EL" field of the TIDEGateway geodatabase in NAVD88 feet.

E. Post-Visit Procedures and Data Upload

Note: Final QA/QC and data upload to TIDEGateway can be performed from any personal computer with a compatible web browser such as Microsoft's Internet Explorer or Google's Chrome by logging into www.tidegateway.com.

Once data have been collected and entered into the data collection form for each tide gate, the process of performing QA/QC and uploading information to TIDEGateway can commence. Follow the steps below to upload data to the geodatabase using TIDEGateway's editing tool.

1. Transfer information for each tide gate from the data collection form to the web interface in TIDEGateway.
2. Use the web interface to upload photographs for each tide gate.
3. The editing interface has been configured to be self-explanatory and easy to navigate.
4. The interface has built in QA/QC checks to ensure consistency and minimize any input errors. These checks include: bounded data fields, constrained units, automatic naming of photos, etc.
5. Once information is updated, a final check should be performed to detect any general errors, especially: the tide gate location, all fields have been completed to the extent practical, photos are properly uploaded and named.



Attachment A:

Blank Tide Gate Data Entry Instruction Form

Tide Gate Data Entry Instruction Form

| Attribute | Description | Data Entry Instructions | Response |
|--------------------------------------|--------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| Initial Data Entry Attributes | | | |
| MODIFICATION_DATE | Data Modification Date | The geodatabase will automatically populate when data or revisions are made. | |
| SOURCE_REASON | Field Visit or Data Entry Reason | Record reason for site visit or data entry (e.g., field visit to obtain updated attributes; revisions to tide gate based on new available information). | |
| SOURCE_NAME | Name of Data Entry Source | Record name of the person performing data updates. | |
| SOURCE_AFFILITATION | Affiliation of Data Entry Source | Record affiliation of the person performing data updates. | |
| SOURCE_EMAIL | Email of Data Entry Source | Record email of the person performing data updates. | |
| General Site Characteristics | | | |
| TIDEGATE_NAME | Unique Tide Gate Identifier | If adding a new tide gate, utilize the naming convention outlined by the <u>field protocols</u> . | |
| UNIQUE_ID | Unique Numeric Identifier | Unique ID to be auto populated by TIDEGateway upon upload. | |
| ORIG_ATLAS_ID | Original Tidal Restriction Atlas ID | Original Tide Atlas Reference Identifier. For reference purposes only; do not update. | |
| TOWN | Town | Record the Town that the tide gate is located in. | |
| LAT | Latitude (decimal) | Record the latitude of the tide gate. This can be done using a GPS unit, a smartphone, or back in the office using an online service such as Google Earth. | |
| LON | Longitude (decimal) | Record the longitude of the tide gate. This can be done using a GPS unit, a smartphone, or back in the office using an online service such as Google Earth. | |
| WATER_BODY | Reference Water Body at Tide Gate Location | If known, record the reference water body that the tide gate impounds. | |
| OPERATOR_TYPE | Operator Type | If known, record if the operator of the tide gate is a public or private entity. | |
| OPERATOR | Owning / Maintaining Agency | If known, record the entity responsible for maintaining the tide gate. | |
| PERMITS | Existing State or Federal Permits | If known, record if there are any permits associated with the tide gate. | |



| Attribute | Description | Data Entry Instructions | Response |
|----------------------------------|-----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| GEN_COMMENTS | General Comments | Record any general comments about the site (e.g., challenging access). This field can also be used to add any observations regarding next steps or missing data (e.g., need keys to access tide gates, need to track down O&M plan, etc.) | |
| Tide Gate Characteristics | | | |
| TYPE | Tide Gate Type | Record the type of tide gate using the provided options on the form (flap gate, sluice gate, self-regulating tide gate, stop logs, or tide gate). If unsure what type of tide gate it is, select "Tide Gate" as the default entry and indicate identifying comments in the "Tide Gate Comments" field. See field protocols for typical examples. | |
| CNTRL_MECH | Tide Gate Control Mechanism | If applicable, record the tide gate control mechanism using the provided options on the form (N/A, counterweights, electric actuator, manual gear). For example a Self-Regulating Tide Gate will be controlled by counterweights, a sluice gate will typically be controlled by an electric actuator or manual gear, and a flap gate will not have a control mechanism. See field protocols for typical examples. | |
| GEOMETRY | Tide Gate Geometry | Record the shape of the tide gate (rectangular or round). | |
| TG_DIAMETER | Tide Gate Diameter | Record the diameter of the tide gate in feet. If the tide gate is rectangular in shape, record the width of the tide gate in feet. | |
| TG_HEIGHT | Tide Gate Height | If the tide gate is circular, leave this field blank. If the tide gate is rectangular, record the height of the tide gate in feet. | |
| EX_TIDAL_INF_US | Extent of Existing Upstream Tidal Influence | Perform the procedures outlined by the field protocols to determine the extent of existing upstream tidal influence of the tide gate in NAVD88 feet based on staining. | |
| EX_TIDAL_INF_DS | Extent of Existing Downstream Tidal Influence | Perform the procedures outlined by the field protocols to determine the extent of existing downstream tidal influence of the tide gate in NAVD88 feet based on staining. | |
| INV_EL | Tide Gate Invert Elevation | Perform the procedures outlined by the field protocols to determine the invert elevation of the tide gate in NAVD88 feet. | |
| TG_MATERIAL | Tide Gate Material | Record the construction material of the tide gate (metal, concrete, wood, other). If other material, indicate in comments (e.g., aluminum). | |

| Attribute | Description | Data Entry Instructions | Response |
|--------------------------------|-------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| EL_COMMENTS | Elevation Comments | Record any comments used to determine tidal influence or invert elevation values. For example, measureddown values and LiDAR values can be recorded here for reference. Alternatively, comments can be added if other methods were used to determine elevations (e.g., plans, RTK GPS, etc.) | |
| TG_CONDITION | Tide Gate Condition | Record the qualitative (i.e. best judgment) condition of the tide gate (Good, Fair, Poor, Unknown) based on a visual inspection. See field protocols for guidelines. | |
| INSTALL_DATE | Installation Date | If known, record the installation date of the tide gate. | |
| STATUS | Operational Status | Record the current status of the tide gate (Active, Proposed, Inactive, Unknown, Removed). | |
| OP_PURPOSE | Purpose | If known, record the operational purpose of the tide gate (flood protection, flood protection and restoration, restoration, other). | |
| OP_PLAN | Operational Plan | If known, indicate if an operational plan is present for the tide gate. | |
| OP_COMMENTS | Operational Notes | Indicate any known operational notes about the tide gates. This can include the responsible party for operating the tide gate, references to any O&M manuals, permits, or other comments. For example, close prior to storm, open incrementally every year to enable incremental restoration, etc. | |
| TG_COMMENTS | Tide Gate Comments | Record any miscellaneous tide gate comments. This can include extraneous information on the tide gate condition, or operational status (e.g., hinge is broken and tide gate no longer appears to be operating). | |
| Culvert Characteristics | | | |
| RESTRIC_SURF | Restriction type | Indicate the restriction medium in which the tide gate is installed (beach, berm, dam, footpath, railroad, retaining wall, roadway, other). | |
| CUL_GEOMETRY | Culvert Geometry | Record the shape of the culvert (rectangular or round). | |
| CUL_DIAMETER | Culvert Diameter | Record the diameter of the culvert in feet. If the culvert is rectangular in shape, record the width of the tide gate in feet | |
| CUL_HEIGHT | Culvert Height | If the culvert is circular, leave this field blank. If the culvert is rectangular, record the height of the culvert in feet. | |
| CUL_MATERIAL | Culvert Material | Record the material of the culvert (concrete, corrugated metal, granite block, other). If other material, indicate in comments (i.e., vitrified clay). | |
| CUL_MAT_BOT | Culvert Bottom Material | If known, record the bottom material of the culvert (riprap, sand, stone, other). | |

| Attribute | Description | Data Entry Instructions | Response |
|-------------------------------------------|-------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| CUL_CONDITION | Culvert Condition | Record the qualitative (i.e. best judgment) condition of the culvert based on a visual inspection (Good, Fair, Poor, Unknown). See field protocols for guidelines. | |
| CUL_COMMENTS | Culvert Comments | Record any miscellaneous culvert comments. This can include extraneous information on the culvert condition, or operational status (e.g., accumulated sediment observed). | |
| Miscellaneous Site Characteristics | | | |
| INVASIVE_SP | Invasive Species | Indicate if any invasive species are observed upstream of the tide gate (Yes or No). | |
| INVASIVE_COMMENTS | Invasive Species Comments | Indicate type of invasive species if known and any comments (e.g., abundant phragmites, purple loosestrife, etc.). | |
| US_TOTAL | Total Upstream Affected Area | This is the total affected area upstream of the tide gate based on tidal atlas data and is for reference purposes only. | |
| US_MARSH | Total Upstream Affected Salt Marsh Area | This is the total affected salt marsh area upstream of the tide gate based on tidal atlas data and is for reference purposes only. | |
| REST_STATUS | Restoration Status | If known and applicable, indicate the restoration status of the impounded area (Proposed, In-Progress, Complete). | |
| REST_COMMENTS | Misc. Restoration Comments | Record any miscellaneous restoration comments (e.g., <i>S. alterniflora</i> establishing itself on west bank) | |
| OTHER_COMMENTS | Additional Comments | Record any additional comments. | |
| Photograph Documentation | | | |
| PHOTOID_1 | Tide Gate Photo (from downstream) | If accessible, record photo of tide gate standing downstream. | |
| PHOTOID_2 | Tide Gate / Culvert Photo (from upstream) | If accessible, record photo of tide gate or culvert standing downstream. | |
| PHOTOID_3 | Downstream Photo | If accessible, record a photo from the top of the restriction (i.e. berm) and looking downstream. | |
| PHOTOID_4 | Upstream Photo | If accessible, record a photo from the top of the restriction (i.e. berm) and looking upstream. | |
| PHOTOID_5 through 12 | Additional Photo(s) | If accessible or desired, record up to eight (8) additional informative photos of interest of the site. | |
| PHOTO_COMMENTS | Photo Comments | Record any photo comments (e.g., no safe means to photograph the tide gate, etc.). | |



| Attribute | Description | Data Entry Instructions | Response |
|----------------------------|-------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|----------|
| External Data Files | | | |
| EXTERNAL_DATA | Hyperlink(s) to External Data | Upload relevant files (e.g., water level, published studies, permit documents, operation and maintenance plans, engineering drawings, etc.). | |

Appendix E:

Initial Site Visit List

| UNIQUE_ID | TIDEGATE_ID | ORIG_ATLAS_ID | TOWN | REGION | Site Visit (Yes, No, Maybe) | Site Visit Reason / Comments |
|-----------|---------------|---------------|------------|-------------------|-----------------------------|------------------------------|
| 1 | Barnstable-01 | BA-16 | Barnstable | CAPE COD | YES | Per DER Guidance (9/27/2015) |
| 6 | Dennis-01 | DE-3 | Dennis | CAPE COD | YES | Per DER Guidance (9/27/2015) |
| 7 | Eastham-01 | EA-7 | Eastham | CAPE COD | YES | Per DER Guidance (9/27/2015) |
| 12 | Orleans-02 | OR-6 | Orleans | CAPE COD | YES | Per DER Guidance (9/27/2015) |
| 14 | Sandwich-01 | SA-5 | Sandwich | CAPE COD | YES | Per DER Guidance (9/27/2015) |
| 22 | Beverly-01 | | Beverly | LOWER NORTH SHORE | YES | Yes, need more attributes. |
| 24 | Manchester-01 | | Manchester | LOWER NORTH SHORE | YES | Yes, need more attributes. |
| 25 | Salem-01 | | Salem | LOWER NORTH SHORE | YES | Yes, need more attributes. |
| 33 | Hingham-05 | HIWR19 | Hingham | METRO BOSTON | YES | Yes, need more attributes. |
| 36 | Hull-02 | HUHB2 | Hull | METRO BOSTON | YES | Yes, need more attributes. |
| 38 | Hull-04 | HUAH6 | Hull | METRO BOSTON | YES | Yes, need more attributes. |
| 39 | Quincy-01 | | Quincy | METRO BOSTON | YES | Per DER Guidance (9/27/2015) |
| 40 | Quincy-02A | | Quincy | METRO BOSTON | YES | Yes, need more attributes. |
| 108 | Quincy-02B | | Quincy | METRO BOSTON | YES | Yes, need more attributes. |
| 41 | Quincy-03 | | Quincy | METRO BOSTON | YES | Yes, need more attributes. |
| 42 | Quincy-04 | | Quincy | METRO BOSTON | YES | Yes, need more attributes. |

| UNIQUE_ID | TIDEGATE_ID | ORIG_ATLAS_ID | TOWN | REGION | Site Visit (Yes, No, Maybe) | Site Visit Reason / Comments |
|-----------|----------------|---------------|------------|-------------------|-----------------------------|-----------------------------------------------------------------------------------------|
| 84 | Quincy-06 | | Quincy | METRO BOSTON | YES | Per DER Guidance (9/27/2015) |
| 58 | Weymouth-02 | WEWF1 | Weymouth | METRO BOSTON | YES | Per DER Guidance (9/27/2015) |
| 62 | Cohasset-01 | COBB2 | Cohasset | SOUTH SHORE | YES | Yes, need more attributes. |
| 63 | Cohasset-02 | COBB4 | Cohasset | SOUTH SHORE | YES | Yes, need more attributes. |
| 65 | Cohasset-04A | COBB9 | Cohasset | SOUTH SHORE | YES | Per DER Guidance (9/27/2015) |
| 111 | Cohasset-04B | COBB9 | Cohasset | SOUTH SHORE | YES | Per DER Guidance (9/27/2015) |
| 28 | Duxbury-01 | DUDB18 | Duxbury | SOUTH SHORE | YES | Yes, need more attributes. |
| 72 | Marshfield-05 | | Marshfield | SOUTH SHORE | YES | Yes, need more attributes. |
| 74 | Scituate-01 | SCSH2A | Scituate | SOUTH SHORE | YES | Yes, need more attributes. |
| 75 | Scituate-02 | SCHR5 | Scituate | SOUTH SHORE | YES | Yes, need more attributes. |
| 77 | Scituate-04 | SCHR20 | Scituate | SOUTH SHORE | YES | Yes, need more attributes. |
| 79 | Gloucester-01A | | Gloucester | UPPER NORTH SHORE | YES | Yes, need more attributes. |
| 116 | Gloucester-01B | | Gloucester | UPPER NORTH SHORE | YES | Yes, need more attributes. |
| 80 | Salisbury-01A | | Salisbury | UPPER NORTH SHORE | YES | Yes, need more attributes. |
| 117 | Salisbury-01B | | Salisbury | UPPER NORTH SHORE | YES | Yes, need more attributes. |
| 81 | Boston-01 | | Boston | METRO BOSTON | MAYBE | Boston, pleasure Bay upstream. Unsure if site visit warranted. Attributes not populated |

| UNIQUE_ID | TIDEGATE_ID | ORIG_ATLAS_ID | TOWN | REGION | Site Visit (Yes, No, Maybe) | Site Visit Reason / Comments |
|-----------|---------------|---------------|------------|--------------|-----------------------------|-----------------------------------------------------------------------------------------|
| 82 | Boston-02 | | Boston | METRO BOSTON | MAYBE | Boston, pleasure Bay upstream. Unsure if site visit warranted. Attributes not populated |
| 44 | Revere-01 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 45 | Revere-02 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 46 | Revere-03 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 47 | Revere-04 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 48 | Revere-05 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 49 | Revere-06 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 50 | Revere-07 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 51 | Revere-08A | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 109 | Revere-08B | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 110 | Revere-08C | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 52 | Revere-09 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 53 | Revere-10 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 54 | Revere-11 | | Revere | METRO BOSTON | MAYBE | Attributes already partially populated |
| 55 | Saugus-01 | | Saugus | METRO BOSTON | MAYBE | Attributes already partially populated |
| 56 | Saugus-02 | | Saugus | METRO BOSTON | MAYBE | Inactive tide gate |
| 57 | Saugus-03 | | Saugus | METRO BOSTON | MAYBE | Inactive tide gate |
| 2 | Barnstable-02 | BA-17 | Barnstable | CAPE COD | NO | Per DER Guidance (9/27/2015) |

| UNIQUE_ID | TIDEGATE_ID | ORIG_ATLAS_ID | TOWN | REGION | Site Visit (Yes, No, Maybe) | Site Visit Reason / Comments |
|-----------|---------------|---------------|-----------|----------|-----------------------------|------------------------------------------------------------------------------|
| 3 | Brewster-01 | BR-7/OR-1 | Brewster | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 4 | Brewster-02 | BR-3 | Brewster | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 5 | Chatham-01 | CH-6 | Chatham | CAPE COD | NO | Per DER Guidance (9/27/2015) [Originally Yes, but Town not in project scope] |
| 8 | Eastham-02 | EA-9 | Eastham | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 9 | Falmouth-01 | FA-2 | Falmouth | CAPE COD | NO | Per DER Guidance (9/27/2015) [Originally Yes, but Town not in project scope] |
| 10 | Harwich-01 | HA-8 | Harwich | CAPE COD | NO | Per DER Guidance (9/27/2015) [Originally Yes, but Town not in project scope] |
| 11 | Orleans-01 | OR-3 | Orleans | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 15 | Sandwich-02 | | Sandwich | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 16 | Sandwich-03 | SA-9 | Sandwich | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 17 | Truro-01 | TR-3 | Truro | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 18 | Truro-02A | TR-6 | Truro | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 103 | Truro-02B | TR-6 | Truro | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 19 | Truro-03 | TR-7 | Truro | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 20 | Wellfleet-01 | WE-5 | Wellfleet | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 21 | Wellfleet-02A | WE-6 | Wellfleet | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 104 | Wellfleet-02B | WE-6 | Wellfleet | CAPE COD | NO | Per DER Guidance (9/27/2015) |
| 105 | Wellfleet-02C | WE-6 | Wellfleet | CAPE COD | NO | Per DER Guidance (9/27/2015) |

| UNIQUE_ID | TIDEGATE_ID | ORIG_ATLAS_ID | TOWN | REGION | Site Visit (Yes, No, Maybe) | Site Visit Reason / Comments |
|-----------|---------------|---------------|------------|-------------------|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 90 | Lynn-01A | | Lynn | LOWER NORTH SHORE | NO | Potentially just stormwater infrastructure upstream |
| 118 | Lynn-01B | | Lynn | LOWER NORTH SHORE | NO | Potentially just stormwater infrastructure upstream |
| 26 | Salem-02A | | Salem | LOWER NORTH SHORE | NO | Potentially just stormwater infrastructure upstream |
| 106 | Salem-02B | | Salem | LOWER NORTH SHORE | NO | Potentially just stormwater infrastructure upstream |
| 83 | Salem-03 | | Salem | LOWER NORTH SHORE | NO | Potentially just stormwater infrastructure upstream |
| 91 | Swampscott-01 | | Swampscott | LOWER NORTH SHORE | NO | Inactive |
| 92 | Swampscott-02 | | Swampscott | LOWER NORTH SHORE | NO | Attributes already partially populated |
| 93 | Swampscott-03 | | Swampscott | LOWER NORTH SHORE | NO | Inactive |
| 27 | Chelsea-01 | | Chelsea | METRO BOSTON | NO | Potentially just stormwater infrastructure upstream - questionable location |
| 95 | Chelsea-02 | | Chelsea | METRO BOSTON | NO | Potentially just stormwater infrastructure upstream. Lat/Lon location could not be determined from municipal SharePoint contact. Additional clarification necessary to determined location. |
| 96 | Chelsea-03A | | Chelsea | METRO BOSTON | NO | Potentially just stormwater infrastructure upstream. Lat/Lon location could not be determined from municipal SharePoint contact. Additional clarification necessary to determined location. |

| UNIQUE_ID | TIDEGATE_ID | ORIG_ATLAS_ID | TOWN | REGION | Site Visit (Yes, No, Maybe) | Site Visit Reason / Comments |
|-----------|-------------|---------------|----------|--------------|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 119 | Chelsea-03B | | Chelsea | METRO BOSTON | NO | Potentially just stormwater infrastructure upstream. Lat/Lon location could not be determined from municipal SharePoint contact. Additional clarification necessary to determined location. |
| 94 | Everett-01 | | Everett | METRO BOSTON | NO | Inactive |
| 29 | Hingham-01 | HIHH9A | Hingham | METRO BOSTON | NO | Per DER Guidance (9/27/2015) |
| 30 | Hingham-02 | HIHH8 | Hingham | METRO BOSTON | NO | Per DER Guidance (9/27/2015) |
| 31 | Hingham-03 | HIHH10 | Hingham | METRO BOSTON | NO | Per Jason Email (9/29/2015) - Removed |
| 32 | Hingham-04 | HIHH12 | Hingham | METRO BOSTON | NO | Per DER Guidance (9/27/2015) |
| 34 | Hingham-06 | | Hingham | METRO BOSTON | NO | Per Jason Email (9/29/2015) - Plans & Permits available |
| 35 | Hull-01 | HUHB1 | Hull | METRO BOSTON | NO | Primarily a pumping station |
| 37 | Hull-03A | HUWR3 | Hull | METRO BOSTON | NO | Per DER Guidance (9/27/2015) |
| 107 | Hull-03B | HUWR3 | Hull | METRO BOSTON | NO | Per DER Guidance (9/27/2015) |
| 43 | Quincy-05 | | Quincy | METRO BOSTON | NO | Proposed |
| 85 | TEST | 2 | Boston | METRO BOSTON | NO | test tide gate |
| 100 | Weymouth-01 | | Weymouth | METRO BOSTON | NO | Attributes already mostly populated |
| 59 | Weymouth-03 | | Weymouth | METRO BOSTON | NO | Proposed tide gate |
| 86 | Weymouth-04 | | Weymouth | METRO BOSTON | NO | Attributes already partially populated |
| 87 | Weymouth-05 | | Weymouth | METRO BOSTON | NO | Attributes already partially populated |
| 88 | Weymouth-06 | | Weymouth | METRO BOSTON | NO | Attributes already partially populated |

| UNIQUE_ID | TIDEGATE_ID | ORIG_ATLAS_ID | TOWN | REGION | Site Visit (Yes, No, Maybe) | Site Visit Reason / Comments |
|-----------|----------------|---------------|------------|--------------|-----------------------------|-----------------------------------------------------------------------------|
| 89 | Weymouth-07 | | Weymouth | METRO BOSTON | NO | Attributes already partially populated |
| 98 | Weymouth-08 | | Weymouth | METRO BOSTON | NO | Attributes already mostly populated |
| 99 | Weymouth-09 | | Weymouth | METRO BOSTON | NO | Attributes already mostly populated |
| 60 | Winthrop-01 | | Winthrop | METRO BOSTON | NO | Potentially just stormwater infrastructure upstream - questionable location |
| 61 | Winthrop-02 | | Winthrop | METRO BOSTON | NO | Proposed tide gate |
| 64 | Cohasset-03A | COBB6 | Cohasset | SOUTH SHORE | NO | Per DER Guidance (9/27/2015) |
| 101 | Cohasset-03B | COBB6 | Cohasset | SOUTH SHORE | NO | Per DER Guidance (9/27/2015) |
| 102 | Cohasset-03C | COBB6 | Cohasset | SOUTH SHORE | NO | Per DER Guidance (9/27/2015) |
| 66 | Cohasset-05 | COBB9 | Cohasset | SOUTH SHORE | NO | Per DER Guidance (9/27/2015) |
| 67 | Kingston-01 | KITB8 | Kingston | SOUTH SHORE | NO | Per DER Guidance (9/27/2015) |
| 68 | Marshfield-01 | MAGH4A | Marshfield | SOUTH SHORE | NO | Attributes already mostly populated |
| 69 | Marshfield-02A | MAGH4B | Marshfield | SOUTH SHORE | NO | Attributes already mostly populated |
| 112 | Marshfield-02B | MAGH4B | Marshfield | SOUTH SHORE | NO | Attributes already mostly populated |
| 113 | Marshfield-02C | MAGH4B | Marshfield | SOUTH SHORE | NO | Attributes already mostly populated |
| 114 | Marshfield-02D | MAGH4B | Marshfield | SOUTH SHORE | NO | Attributes already mostly populated |
| 70 | Marshfield-03 | MASR16 | Marshfield | SOUTH SHORE | NO | Per DER Guidance (9/27/2015) |
| 71 | Marshfield-04 | MAGH18 | Marshfield | SOUTH SHORE | NO | Per DER Guidance (9/27/2015) |
| 76 | Scituate-03A | SCBB11 | Scituate | SOUTH SHORE | NO | Per DER Guidance (9/27/2015) |

| UNIQUE_ID | TIDEGATE_ID | ORIG_ATLAS_ID | TOWN | REGION | Site Visit (Yes, No, Maybe) | Site Visit Reason / Comments |
|-----------|--------------|---------------|----------|-------------|-----------------------------|----------------------------------------------------------------|
| 115 | Scituate-03B | SCBB11 | Scituate | SOUTH SHORE | NO | Per DER Guidance (9/27/2015) |
| 78 | Scituate-05 | SCSH25 | Scituate | SOUTH SHORE | NO | Per Jason Burtner Email (9/29/2015) - Service report available |

Appendix F:

Field Visit and Database Update Log

| VISIT DAY | ID | NAME | TOWN | REGION | COUNT | ADDED | REMOVED | NAME CHANGE | COMMENT |
|-----------|-----|----------------|------------|-------------------|-------|-------|---------|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|
| 11/2/2015 | 39 | Quincy-01A | Quincy | METRO BOSTON | 1 | N | N | Y | CHANGED TO QUINCY-01A FROM QUINCY-01 |
| 11/2/2015 | 120 | Quincy-01B | Quincy | METRO BOSTON | 1 | Y | N | N | QUINCY-01B |
| 11/2/2015 | 121 | Quincy-01C | Quincy | METRO BOSTON | 1 | Y | N | N | QUINCY-01C |
| 11/2/2015 | 40 | Quincy-02 | Quincy | METRO BOSTON | 1 | N | N | Y | CHANGED TO QUINCY-02 FROM QUINCY-02A |
| 11/2/2015 | 108 | | Quincy | METRO BOSTON | 1 | N | Y | N | TG DOESN'T EXIST [JUST 1 TIDE GATE AT QUINCY-02 LOCATION] |
| 11/2/2015 | 42 | Quincy-04 | Quincy | METRO BOSTON | 1 | N | N | N | |
| 11/2/2015 | 41 | Quincy-03 | Quincy | METRO BOSTON | 1 | N | N | N | |
| 11/2/2015 | 58 | Weymouth-02 | Weymouth | METRO BOSTON | 1 | N | N | N | |
| 11/2/2015 | 84 | Quincy-06 | Quincy | METRO BOSTON | 1 | N | N | N | |
| 11/3/2015 | 38 | Hull-04 | Hull | METRO BOSTON | 1 | N | N | N | |
| 11/3/2015 | 36 | Hull-02A | Hull | METRO BOSTON | 1 | N | N | Y | CHANGED TO HULL-02A FROM HULL-02 |
| 11/3/2015 | 122 | Hull-02B | Hull | METRO BOSTON | 1 | Y | N | N | HULL-02B |
| 11/3/2015 | 63 | Cohasset-02 | Cohasset | SOUTH SHORE | 1 | N | N | N | |
| 11/3/2015 | 62 | Cohasset-01 | Cohasset | SOUTH SHORE | 1 | N | N | N | |
| 11/3/2015 | 65 | Cohasset-04A | Cohasset | SOUTH SHORE | 1 | | | | |
| 11/3/2015 | 111 | | Cohasset | SOUTH SHORE | 1 | N | Y | N | TG DOESN'T EXIST [JUST 1 TIDE GATE AT COHASSET-04 LOCATION] |
| 11/3/2015 | 75 | Scituate-02 | Scituate | SOUTH SHORE | 1 | N | N | N | TG DOESN'T APPEAR TO EXIST AT LOCATION - LISTED AS "REMOVED" IN DATABASE |
| 11/3/2015 | 74 | Scituate-01A | Scituate | SOUTH SHORE | 1 | N | N | Y | Changed to Scituate-01A from Scituate-01 |
| 11/3/2015 | 123 | Scituate-01B | Scituate | SOUTH SHORE | 1 | Y | N | N | Scituate-02B |
| 11/4/2015 | 33 | Hingham-05 | Hingham | METRO BOSTON | 1 | N | N | N | WRONG LOCATION IN INITIAL DATABASE - MOVED PER FIELD OBSERVATIONS |
| 11/4/2015 | 77 | Scituate-04 | Scituate | SOUTH SHORE | 1 | N | N | N | |
| 11/4/2015 | 72 | Marshfield-05A | Marshfield | SOUTH SHORE | 1 | N | N | Y | CHANGED TO MARSHFIELD-05A FROM MARSHFIELD-05 |
| 11/4/2015 | 124 | Marshfield-05B | Marshfield | SOUTH SHORE | 1 | Y | N | N | MARSHFIELD-05B |
| 11/4/2015 | 68 | Marshfield-01A | Marshfield | SOUTH SHORE | 1 | N | N | Y | CHANGED TO MARSHFIELD-01A FROM MARSHFIELD-01 [WRONG LOCATION - MOVED TO THE NORTH - USED TO BE CO-LOCATED WITH MARSHFIELD-02 IN DATABASE - CORRECTED] |
| 11/4/2015 | 125 | Marshfield-01B | Marshfield | SOUTH SHORE | 1 | Y | N | N | MARSHFIELD-01B [WRONG LOCATION - MOVED TO THE NORTH - USED TO BE CO-LOCATED WITH MARSHFIELD-02 IN DATABASE - CORRECTED] |
| 11/4/2015 | 69 | Marshfield-02A | Marshfield | SOUTH SHORE | 1 | N | N | N | |
| 11/4/2015 | 112 | Marshfield-02B | Marshfield | SOUTH SHORE | 1 | N | N | N | |
| 11/4/2015 | 71 | Marshfield-04A | Marshfield | SOUTH SHORE | 1 | N | N | Y | CHANGED TO MARSHFIELD-04A FROM MARSHFIELD-04 |
| 11/4/2015 | 126 | Marshfield-04B | Marshfield | SOUTH SHORE | 1 | Y | N | N | MARSHFIELD-04B |
| 11/4/2015 | 127 | Marshfield-04C | Marshfield | SOUTH SHORE | 1 | Y | N | N | MARSHFIELD-04C |
| 11/4/2015 | 128 | Marshfield-04D | Marshfield | SOUTH SHORE | 1 | Y | N | N | MARSHFIELD-04D |
| 11/4/2015 | 28 | Duxbury-01 | Duxbury | SOUTH SHORE | 1 | N | N | N | |
| 12/2/2015 | 25 | Salem-01A | Salem | LOWER NORTH SHORE | 1 | N | N | Y | CHANGED SALEM-01 TO SALEM-01A |
| 12/2/2015 | 130 | Salem-01B | Salem | LOWER NORTH SHORE | 1 | Y | N | N | SALEM-01B |
| 12/2/2015 | 131 | Salem-01C | Salem | LOWER NORTH SHORE | 1 | Y | N | N | SALEM-01C |
| 12/2/2015 | 22 | Beverly-01A | Beverly | LOWER NORTH SHORE | 1 | N | N | Y | CHANGED BEVERLY-01 TO BEVERLY 01A |
| 12/2/2015 | 132 | Beverly-01B | Beverly | LOWER NORTH SHORE | 1 | Y | N | N | BEVERLY-01B |
| 12/2/2015 | 24 | Manchester-01 | Manchester | LOWER NORTH SHORE | 1 | N | N | N | |
| 12/2/2015 | 79 | Gloucester-01A | Gloucester | UPPER NORTH SHORE | 1 | N | N | N | |

Note: Visit day N/A indicates that record was not visited in the field but was modified after the field effort.

| VISIT DAY | ID | NAME | TOWN | REGION | COUNT | ADDED | REMOVED | NAME CHANGE | COMMENT |
|------------|-----|----------------|------------|-------------------|-------|-------|---------|-------------|--------------------------------------------------------------------------------------------------------------------|
| 12/2/2015 | 116 | Gloucester-01B | Gloucester | UPPER NORTH SHORE | 1 | N | N | N | |
| 12/2/2015 | 133 | Gloucester-01C | Gloucester | UPPER NORTH SHORE | 1 | Y | N | N | GLOUCESTER-01C |
| 12/2/2015 | 80 | Salisbury-01A | Salisbury | UPPER NORTH SHORE | 1 | N | N | N | |
| 12/2/2015 | 117 | Salisbury-01B | Salisbury | UPPER NORTH SHORE | 1 | N | N | N | |
| 12/18/2015 | 14 | Sandwich-01 | Sandwich | CAPE COD | 1 | N | N | N | [WRONG LOCATION - CHANGED COORDINATES IN DATABASE TO CORRECT LOCATION] |
| 12/18/2015 | 1 | Barnstable-01 | Barnstable | CAPE COD | 1 | N | N | N | |
| 12/18/2015 | 6 | Dennis-01 | Dennis | CAPE COD | 1 | N | N | N | |
| 12/18/2015 | 12 | Orleans-02A | Orleans | CAPE COD | 1 | N | N | Y | CHANGED TO ORLEANS-02A FROM ORLEANS-02 |
| 12/18/2015 | 135 | Orleans-02B | Orleans | CAPE COD | 1 | Y | N | N | |
| 12/18/2015 | 7 | Eastham-01 | Eastham | CAPE COD | 1 | N | N | N | |
| N/A | 137 | Harwich-02 | Harwich | CAPE COD | 1 | Y | N | N | ADDED PER L. ENGLER EMAIL ON 10/29/2015. |
| N/A | 138 | Quincy-07 | Quincy | METRO BOSTON | 1 | Y | N | N | ADDED PER L. ENGLER EMAIL ON 10/29/2015 [REACHED OUT TO E. REINER ON 12/28/2015 REQUESTING ADDITIONAL INFORMATION] |
| N/A | 110 | Revere-08A | Revere | METRO BOSTON | 1 | N | N | Y | CHANGED FROM REVERE-08C TO REVERE-08A. MODIFICATIONS PER L. ENGLER EMAIL DATED 10/21/2015. |
| N/A | 109 | Revere-08B | Revere | METRO BOSTON | 1 | N | N | N | MODIFICATIONS PER L. ENGLER EMAIL DATED 10/21/2015. |
| N/A | 51 | Revere-08C | Revere | METRO BOSTON | 1 | N | N | Y | CHANGED FROM REVERE-08A TO REVERE-08C. MODIFICATIONS PER L. ENGLER EMAIL DATED 10/21/2015. |
| N/A | 139 | Revere-08D | Revere | METRO BOSTON | 1 | Y | N | N | ADD PER MODIFICATIONS FROM L. ENGLER EMAIL DATED 10/21/2015 |
| N/A | 140 | Revere-08E | Revere | METRO BOSTON | 1 | Y | N | N | ADD PER MODIFICATIONS FROM L. ENGLER EMAIL DATED 10/21/2015 |
| N/A | 141 | Revere-08F | Revere | METRO BOSTON | 1 | Y | N | N | ADD PER MODIFICATIONS FROM L. ENGLER EMAIL DATED 10/21/2015 |
| N/A | 142 | Revere-08G | Revere | METRO BOSTON | 1 | Y | N | N | ADD PER MODIFICATIONS FROM L. ENGLER EMAIL DATED 10/21/2015 |
| N/A | 143 | Revere-08H | Revere | METRO BOSTON | 1 | Y | N | N | ADD PER MODIFICATIONS FROM L. ENGLER EMAIL DATED 10/21/2015 |
| N/A | 144 | Revere-08I | Revere | METRO BOSTON | 1 | Y | N | N | ADD PER MODIFICATIONS FROM L. ENGLER EMAIL DATED 10/21/2015 |
| N/A | 145 | Revere-08J | Revere | METRO BOSTON | 1 | Y | N | N | ADD PER MODIFICATIONS FROM L. ENGLER EMAIL DATED 10/21/2015 |
| N/A | 146 | Revere-08K | Revere | METRO BOSTON | 1 | Y | N | N | ADD PER MODIFICATIONS FROM L. ENGLER EMAIL DATED 10/21/2015 |
| N/A | 50 | Revere-07 | Revere | METRO BOSTON | 1 | N | N | N | UPDATED ATTRIBUTES PER L. ENGLER EMAIL DATED 10/21/2015 |
| N/A | 147 | Rowley-01 | Rowley | UPPER NORTH SHORE | 1 | Y | N | N | NEW TIDE GATE PER NANCY PAU OF USFWS |
| N/A | 148 | Rowley-02 | Rowley | UPPER NORTH SHORE | 1 | Y | N | N | NEW TIDE GATE PER NANCY PAU OF USFWS |
| N/A | 149 | Rowley-03 | Rowley | UPPER NORTH SHORE | 1 | Y | N | N | NEW TIDE GATE PER NANCY PAU OF USFWS |
| N/A | 150 | Ipswich-01 | Ipswich | UPPER NORTH SHORE | 1 | Y | N | N | NEW TIDE GATE PER NANCY PAU OF USFWS |


Note: Visit day N/A indicates that record was not visited in the field but was modified after the field effort.

Appendix G:


Exploratory Data Analysis Findings

| | | | | | | | | | | |
|-----------------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose, and Status | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-----------------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|


Tide Gate Type



Operational Purpose



Status




- Tide Gate Type**
- Tide Gate
- Flap Gate
- Multiple
- Self Regulating
- Sluice Gate
- Stop Logs


- Operational Purpose**
- Unknown or Null
- Flood Prot. & Rest.
- Flood Protection
- Other

- Status**
- Unknown or Null
- Active
- Inactive
- Proposed
- Removed


| | | | | | | | | | | |
|-----------------------------------------------|-----------------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose, and Status | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-----------------------------------------------|-----------------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|



| | | | | | | | | | | |
|-----------------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose, and Status | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-----------------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|



| | | | | | | | | | | |
|-----------------------------------------------|----------------------------|----------------------------------------------------------------|-------------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose, and Status | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-----------------------------------------------|----------------------------|----------------------------------------------------------------|-------------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|



| | | | | | | | | | | |
|-----------------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|------------------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose, and Status | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-----------------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|------------------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|



| Tide Gate Type | Tide Gate Material | | | |
|--------------------|--------------------|-----------|----------|-----------|
| | Unknown | Metal | Other | Wood |
| Tide Gate | 15 | 10 | 1 | |
| Flap Gate | 11 | 32 | 5 | 13 |
| Multiple | 2 | 4 | | |
| Self Regulating | | 16 | | |
| Sluice Gate | 1 | 16 | | 2 |
| Stop Logs | 4 | 1 | | 4 |
| Grand Total | 33 | 79 | 6 | 19 |




TIDEGateway Exploratory Data Analysis: General Findings

(Draft Final Report – February 2016)


| | | | | | | | | | | |
|----------------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|-------------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose, and Sta.. | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|----------------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|-------------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|




| | | | | | | | | | | |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|-------------------------|-------------------|-----------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose.. | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|-------------------------|-------------------|-----------------------------------|---------------------------|--------------------------|



| | | | | | | | | | | |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|--------------------------|-----------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose.. | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|--------------------------|-----------------------------------|---------------------------|--------------------------|



| | | | | | | | | | | |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|------------------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose.. | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|------------------------------------------|---------------------------|--------------------------|




TIDEGateway Exploratory Data Analysis: General Findings

(Draft Final Report – February 2016)

| | | | | | | | | | | |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|----------------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose.. | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|----------------------------------|--------------------------|

| Tide Gate Type | Culvert Material | | | | | | Number of Records |
|--------------------|------------------|-----------|------------------|-------------------|---------------|----------|-------------------|
| | Unknown | Concrete | Corrugated Metal | Ductile Iron Pipe | Granite Block | Other | |
| Tide Gate | 14 | 8 | 1 | | 2 | 1 | |
| Flap Gate | 15 | 28 | 12 | 1 | 1 | 4 | |
| Multiple | 2 | 3 | 1 | | | | |
| Self Regulating | 7 | 9 | | | | | |
| Sluice Gate | 3 | 10 | 1 | 1 | 4 | | |
| Stop Logs | 3 | 4 | 2 | | | | |
| Grand Total | 44 | 62 | 17 | 2 | 7 | 5 | |


| | | | | | | | | | | |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|
| Tide Gate Overview: Type, Purpose.. | Tide Gate Counts by Region | Sites with tide gates by region (ie, some sites have multiple) | Top 10 Towns with Tide Gates | Tide Gate Material Findings | Average Tide Gate Diameter and Shape by Region | Tide Gate Status | Tide Gate Purpose | Tide Gate Operator Type by Region | Culvert Material Findings | Restriction Surface Type |
|-------------------------------------|----------------------------|----------------------------------------------------------------|------------------------------|-----------------------------|------------------------------------------------|------------------|-------------------|-----------------------------------|---------------------------|--------------------------|




- Unknown
- Beach
- Berm
- Dam
- Footpath
- Other
- Railroad
- Retaining wall
- Roadway

| | | |
|---------------------------------|-------------------------------|-----------------------------|
| Tide Gate and Culvert Condition | Tide Gate Condition by Region | Culvert Condition By Region |
|---------------------------------|-------------------------------|-----------------------------|

Tide Gate Condition







Culvert Condition







- Tide Gate Condition
 - Poor
 - Fair
 - Good
 - Unknown or Null
- Culvert Condition
 - Poor
 - Fair
 - Good
 - Unknown or Null

TIDEGateway Exploratory Data Analysis: Condition Findings

(Draft Final Report - February 2016)










TIDEGateway Exploratory Data Analysis: Restoration Findings

(Draft Final Report - February 2016)

| Restoration Status | Invasive Species Observed? |
|--------------------|----------------------------|
|--------------------|----------------------------|



- Restoration Status
- Unknown or Null
 - Complete
 - In-Progress
 - Not Applicable
 - Proposed



Appendix H:

List of Current Data Gaps

(Updated 1/19/2016)

| Raw Attribute Name | Alias | Number of Blank Entries | Complete (%) |
|--------------------|----------------------------------------|-------------------------|--------------|
| UNIQUE_ID | #N/A | 0 | 100% |
| TIDEGATE_ID | Tide Gate Name | 0 | 100% |
| TOWN | Town | 0 | 100% |
| WATER_BODY | Reference Water Body | 18 | 87% |
| TYPE | Tide Gate Type | 3 | 98% |
| ORIG_ATLAS_ID | Original Tidal Restriction Atlas ID | 77 | 45% |
| LAT | Latitude (decimal) | 1 | 99% |
| LON | Longitude (decimal) | 1 | 99% |
| OPERATOR_TYPE | Operator Type (Public versus Private) | 33 | 76% |
| OPERATOR | Owning / Maintaining Agency | 61 | 56% |
| PERMITS | Existing State or Federal Permits | 98 | 29% |
| GEN_COMMENTS | General Comments | 54 | 61% |
| CNTRL_MECH | Tide Gate Control Mechanism | 21 | 85% |
| GEOMETRY | Tide Gate Geometry | 43 | 69% |
| TG_DIAMETER | Tide Gate Diameter (ft) | 67 | 52% |
| TG_HEIGHT | Tide Gate Height (ft) | 87 | 37% |
| EX_TIDAL_INF_US | Extent of Existing U/S Tidal Influence | 120 | 14% |
| EX_TIDAL_INF_DS | Extent of Existing D/S Tidal Influence | 116 | 17% |
| INV_EL | Tidegate Invert Elevation (NAVD88) | 115 | 17% |
| TG_MATERIAL | Tide Gate Material | 34 | 76% |
| TG_CONDITION | Condition (Qualitative) | 72 | 48% |
| INSTALL_DATE | Installation Date | 102 | 27% |
| STATUS | Operational Status | 4 | 97% |
| OP_PURPOSE | Operational Purpose | 57 | 59% |
| OP_PLAN | Operational Plan Present? | 80 | 42% |
| OP_COMMENTS | Operational Notes | 76 | 45% |
| TG_COMMENTS | Misc. Tide Gate Comments | 29 | 79% |
| RESTRIC_SURF | Restriction Type | 36 | 74% |
| CUL_GEOMETRY | Culvert Geometry | 35 | 75% |
| CUL_DIAMETER | Culvert Diameter (ft) | 66 | 53% |
| CUL_HEIGHT | Culvert Height (ft) | 100 | 28% |
| CUL_MATERIAL | Culvert Material | 45 | 68% |
| CUL_MAT_BOT | Culvert Bottom Material | 87 | 37% |
| CUL_CONDITION | Condition (Qualitative) | 73 | 47% |
| CUL_COMMENTS | Misc. Culvert Comments | 62 | 55% |
| INVASIVE_SP | Invasive species present upstream? | 65 | 53% |
| INVASIVE_COMMENTS | Invasive species comments | 75 | 46% |
| US_TOTAL | Total Upstream Affected Area | 100 | 28% |
| US_MARSH | Total Upstream Salt Marsh Area | 81 | 42% |
| REST_STATUS | Restoration Status | 73 | 47% |
| REST_COMMENTS | Misc. Restoration Comments | 84 | 40% |
| PHOTOID_1 | Photo 1: Tide Gate from Downstream | 105 | 24% |
| PHOTOID_2 | Photo 2: Tide Gate from Upstream | 112 | 19% |
| PHOTOID_3 | Photo 3: Downstream View | 110 | 21% |
| PHOTOID_4 | Photo 4: Upstream View | 111 | 20% |

| Raw Attribute Name | Alias | Number of Blank Entries | Complete (%) |
|---------------------|------------------------|-------------------------|--------------|
| PHOTOID_5 | Photo 5 | 112 | 19% |
| PHOTOID_6 | Photo 6 | 115 | 17% |
| PHOTOID_7 | Photo 7 | 119 | 14% |
| PHOTOID_8 | Photo 8 | 127 | 9% |
| PHOTOID_9 | Photo 9 | 133 | 4% |
| PHOTOID_10 | Photo 10 | 134 | 4% |
| PHOTOID_11 | Photo 11 | 137 | 1% |
| PHOTOID_12 | Photo 12 | 138 | 1% |
| PHOTO_ANNOTATION_1 | Annotation | 108 | 22% |
| PHOTO_ANNOTATION_2 | Annotation | 111 | 20% |
| PHOTO_ANNOTATION_3 | Annotation | 110 | 21% |
| PHOTO_ANNOTATION_4 | Annotation | 111 | 20% |
| PHOTO_ANNOTATION_5 | Annotation | 112 | 19% |
| PHOTO_ANNOTATION_6 | Annotation | 115 | 17% |
| PHOTO_ANNOTATION_7 | Annotation | 119 | 14% |
| PHOTO_ANNOTATION_8 | Annotation | 127 | 9% |
| PHOTO_ANNOTATION_9 | Annotation | 133 | 4% |
| PHOTO_ANNOTATION_10 | Annotation | 134 | 4% |
| PHOTO_ANNOTATION_11 | Annotation | 137 | 1% |
| PHOTO_ANNOTATION_12 | Annotation | 138 | 1% |
| PHOTO_COMMENTS | General Photo Comments | 110 | 21% |
| OTHER_COMMENTS | Other Comments | 96 | 31% |

Appendix I:

Selected Field Photograph Findings Log

Selected Condition Photographs

Photo ID: 1218151233a_12_1

Unique ID: 12

Site ID: Orleans-02A

Comments: At the time of the site visit (12/18/2015), the tide gate was inoperable and was sealed completely shut by fine grained sediment deposited in the channel. Dredging was required to restore proper functionality of the tide gate and to allow passage of upstream flow.



Photo ID: 1218150907_14_1

Unique ID: 14

Site ID: Sandwich-01

Comments: The metal comprising the flap gate was deformed and did not appear to form a tight seal against the culvert opening. A 3-5" gap was observed from which tidal exchange could occur. In addition, the bottom half of the tide gate was corroded and its operation was impeded by heavy algae growth. It was unclear if the tide gate would be able to fully open in the event of a storm event to pass heavy upstream flows.



Selected Condition Photographs

Photo ID: 1218150914_14_2

Unique ID: 14

Site ID: Sandwich-01

Comments: The upstream end of the culvert was located at the bottom of a wooden retaining wall in poor condition. The retaining wall was beginning to collapse at multiple locations, excessive wood rot was observed, and upland vegetation was observed growing through the retaining wall - further compromising its structural integrity.



Photo ID: 1202150858g_22_6

Unique ID: 22

Site ID: Beverly-01B

Comments: Beverly-01B was located on the eastern end of the spillway and was a steel sluice gate operated by a handwheel. Grease was observed on the handwheel, so it appeared that the gate was periodically operated. The tide gate was in fair condition; the metal sluice gate was badly corroded and was leaking.



Selected Condition Photographs

Photo ID: 1202150941b_24_8

Unique ID: 24

Site ID: Manchester-01

Comments: The upstream headwall was in poor condition. A chunk of the headwall had fallen into the channel, exposed rebar was observed, and a vertical crack was forming in the top middle of the headwall that extended almost down to the top of the culvert opening.



Photo ID: 1202150754_25_2

Unique ID: 25

Site ID: Salem-01

Comments: Spalling and general deterioration of the upstream headwall was observed.



Selected Condition Photographs

Photo ID: 1103151055_36_9

Unique ID: 36

Site ID: Hull-02

Comments: Tide gate was a metal sluice gate operated by a manual jack screw. The tide gate appeared to be in fair condition; however, it appeared that it was inoperable and rusted in place. Significant rusting of the hinges and main structure of the tide gate was observed.



Photo ID: 1103151108_36_5

Unique ID: 36

Site ID: Hull-02

Comments: There were no apparent structural issues observed at the concrete box culvert; however, the headwalls on both the upstream and downstream end of the culvert were in poor condition. Significant spalling and exposed rebar was observed on both the upstream and downstream headwalls. Further, the access rungs leading from the top of the headwall down to the tide gate were corroded.



Selected Condition Photographs

Photo ID: 1103151012_38_7

Unique ID: 38

Site ID: Hull-04

Comments: Outfall to culvert was located below high water mark approximately 150' downstream of the tide gate. A metal (rebar) trash grate was installed at the outlet. The culvert was in fair condition - the culvert bell/segments were beginning to decouple and gaps were observed in the joints. It appeared that the cause of the decoupling was lowering of the beach profile (i.e. longshore sediment transport).



Photo ID: 1102151010a_42_6

Unique ID: 42

Site ID: Quincy-04

Comments: Outfall was located approximately 100' feet north of Bayswater Road on the beach and was partially exposed at low tide. Downstream end of culvert was severely deteriorated: most of the joints had separated and large 1'-2' gaps were observed in the pipe.



Selected Condition Photographs

Photo ID: IMG_1724_84_2

Unique ID: 84

Site ID: Quincy-06

Comments: Downstream end of culvert was plastic (HDPE) and upstream end of culvert was corrugated metal. Downstream end of culvert appeared to be in good condition; however, upstream end was partially buried, thereby potentially limiting stormwater conveyance capacity.



Photo ID: 1102151114a_58_1

Unique ID: 58

Site ID: Weymouth-01

Comments: Large wooden flap gate was in poor condition. The bottom half of the tide gate was rotting. The tide gate was installed in such a way that a seal was not created against the headwall thereby allowing some level of tidal exchange at all tidal levels. The tide gate hinges appeared to be operable; however, the tide gate was so waterlogged that it was not possible to fully open.



Selected Condition Photographs

Photo ID: 1103151227a_63_8

Unique ID: 63

Site ID: Cohasset-02

Comments: Deformation of the corrugated metal culvert was observed on its downstream end indicating that it was potentially beginning to collapse. Significant spalling and cracking was also observed on the downstream concrete headwall.



Photo ID: 1104151236_28_6

Unique ID: 28

Site ID: Duxbury-01

Comments: The metal circular flap gate was operational; however, the bottom 10% of the flapper was beginning to corrode away.



Selected Condition Photographs

Photo ID: 1104151131_68_1

Unique ID: 68

Site ID: Marshfield-01A

Comments: The self-regulating tide gate was in fair condition and was inoperable; the bottom float which allows the tide gate to open was missing. As a result, it appeared that the gate was currently operating as a flap gate and limiting upstream tidal exchange. A hand operated winch and strap had been installed to operate the SRT and the strap was weathered. Additionally, the SRT's breather was clogged with debris and some leakage was observed around the flange connection to the headwall.



Photo ID: 1104151019_72_1

Unique ID: 72

Site ID: Marshfield-05

Comments: There were two wooden flap gates at this location. The wood on both tide gates was heavily rotted and waterlogged with rusty wooden hinges. The northern tide gate was inoperable and was stuck shut; it appeared that the hinges were corroded shut. Additionally, the bolts securing the tide gate to the headwall were wearing through the wood. Gaps were observed in the wooden backing behind each tide gate and it appeared that both tide gates did not create a watertight seal at high tide, thus enabling some level of upstream tidal flushing.



Selected Condition Photographs

Photo ID: 1104151035b_72_2

Unique ID: 72

Site ID: Marshfield-05

Comments: There were two identical oval CMP culverts for each tide gate. Both culverts appeared to be in poor condition. The culverts were separating from the concrete headwall and significant deterioration and rust was observed. The northern culvert (downgradient of the inoperable tide gate) was approximately half full of sediment presumably since the tide gate was rusted shut; presumably not letting sediment from upstream stormwater flows out. Both the upstream and downstream headwalls were also in poor condition and deterioration / spalling was observed in multiple areas.



Photo ID: 1103151347_74_7

Unique ID: 74

Site ID: Scituate-01A

Comments: The downstream metal flap gate was in poor condition. It was rusted open approximately 3 to 4 inches, the bolts affixing it to the concrete headwall were corroded, and it appeared that someone had attempted to remove the tide gate as evidenced by loosened nuts (i.e., the nuts had been backed off the bolts).



Selected Condition Photographs

Photo ID: 1103151338_74_2

Unique ID: 74

Site ID: Scituate-01B

Comments: The reinforced concrete pipe was in fair condition. It appeared that the mouth of the pipe was beginning to separate from the weir wall on the upstream side of the restriction. In addition, erosion was observed around the upstream concrete weir, presumably from stormwater runoff from the adjacent road, tidal influence, or some combination thereof.



Photo ID: 1202151017a_79_5

Unique ID: 79

Site ID: Gloucester-01

Comments: The upstream portion of the culvert appeared to be in good condition with no apparent deterioration; however, the downstream portion was slightly separating from the headwall in places. Additionally, portions of the downstream culvert were jagged and appeared to pose a potential safety hazard.



Selected Restoration Photographs

Photo ID: 1104151046a_72_7

Unique ID: Marshfield-05

Site ID: 72

Comments: No known restoration efforts or studies had been performed. Low lying properties including a dirt road and house were observed directly adjacent to the upstream impoundment. Abundant phragmites upstream.



Photo ID: IMG_1723_84_4

Unique ID: 84

Site ID: Quincy-06

Comments: Flap gate limited all tidal flow. As a result, freshwater grasses and Phragmites were observed upstream. At the time of the site visit, no known restoration efforts had been undertaken. The upstream area was large and appeared to have significant restoration potential. A number of homes were observed adjacent to the impoundment which might limit restoration options due to potential flooding.



Selected Restoration Photographs

Photo ID: 1218151315f_7_5

Unique ID: Eastham-01

Site ID: 07

Comments: Phragmites dominated the upstream and downstream portions of the restriction. Small patches of high marsh were observed downstream of the restriction. The area appeared to have good restoration potential with minimal to no low-lying infrastructure observed. Note flap gate had been removed or fell off culvert at time of site visit (12/18/2015).



Photo ID: 1218150917_14_4

Unique ID: 14

Site ID: Sandwich-01

Comments: The downstream portion of the marsh was comprised of a mixture of high marsh and phragmites while the upstream portion of the marsh was predominately phragmites. Upland vegetation was also observed along the railway embankment including wild cherry and sumac. The site appeared to have good restoration potential; however, upgradient infrastructure (i.e. houses) were observed.



Selected Restoration Photographs

Photo ID: 1103151338b_74_4

Unique ID: Scituate-01

Site ID: 74

Comments: The impoundment was comprised primarily of high marsh and was fringed by phragmites. Houses were observed around the marsh; however, they appeared to be elevated.



Photo ID: 1218151246_12_6

Unique ID: 12

Site ID: Orleans-02

Comments: The upstream impoundment appeared to be an entirely freshwater system as evidenced by cattails, Atlantic white cedar, and freshwater sedge. The site had good restoration potential with minimal low lying infrastructure observed; however, restoration might be limited by the requirement to preserve Atlantic white cedar.



Selected Restoration Photographs

Photo ID: 1103151228a_63_4

Unique ID: 63

Site ID: Cohasset-02

Comments: The upstream impoundment was dominated by high marsh and was fringed with Phragmites. Unknown if any restoration efforts had been performed at the site. Future restoration considering upsizing the culvert would need to investigate low lying areas including adjacent farm land directly to the south of the impoundment.



Photo ID: 1218151246_12_6

Unique ID: 6

Site ID: Dennis-01

Comments: The upstream impoundment was mainly comprised of high marsh and was fringed with phragmites. Upland vegetation was also observed directly to the south of the upstream culvert opening. It appeared that the site would be a candidate for restoration; however, a potentially low lying barn and field was observed to the west of the restriction.



Selected Restoration Photographs

Photo ID: 1102151018_42_4

Unique ID: 42

Site ID: Quincy-04

Comments: The upstream marsh had a mixture of *Spartina Alterniflora* and *Patens* and was bordered by *Phragmites*. The marsh was previously studied for potential restoration by MADER; however, it was concluded that low lying infrastructure would be a challenge. Future restoration would likely need to consider sizing culvert to accommodate the balance between stormwater outflows and tidal flushing.



Photo ID: 1102150925a_40_4

Unique ID: 40

Site ID: Quincy-02

Comments: There was a narrow channel on the upstream end of the restriction lined with an approximately 2' wide layer of salt marsh grass. From there, the salt marsh grass transitioned into mowed grass and *phragmites*. It appeared that no restoration efforts had been made at this location. There was an abundance of low lying infrastructure located at the upstream end of the restriction including houses, deck stairways, and concrete retaining walls.



Selected Restoration Photographs

Photo ID: 1102151128b_58_4

Unique ID: 58

Site ID: Weymouth-02

Comments: Upstream area varied significantly. Phragmites, upland vegetation, and *Spartina Alterniflora* islands were observed. Vegetation was indicative of some level of salt water influence, but not enough volume to inundate the marsh top which was mainly comprised of upland vegetation. It appeared that the marsh had potentially subsided over time. Large upstream wetland area with good restoration potential. A marina worker indicated that upstream residents had complained of flooding in the past, but it was unclear if the flooding was a result of tidal inundation, stormwater influence, or a combination.



Photo ID: 1104151001a_77_5

Unique ID: 77

Site ID: Scituate-04

Comments: Upstream impoundment was predominately comprised of phragmites. Appeared that there was little to no tidal influence. Would potentially be a good restoration candidate - minimal low lying infrastructure was observed; however, upstream area is used by the town as a drinking water well field.



Selected Restoration Photographs

Photo ID: 1103151113_36_4

Unique ID: 36

Site ID: Hull-02

Comments: Upstream marsh appeared to be relatively healthy with a mixture of low and high marsh species. Phragmites were observed at the fringes. Previous water level logging was performed determine the relative extent of upstream restriction. Low lying properties including a cellular tower and guy wires were observed within and around the impoundment.



Selected Miscellaneous Photographs

Photo ID: 1218151138b_06_6

Unique ID: 06

Site ID: Dennis-01

Comments: An abundance of live mussels was observed within the channel at the upstream end of the culvert.



Photo ID: 1202150813_25_8

Unique ID: 25

Site ID: Salem-01

Comments: Multiple invasive striped anemones were observed on the mudflat approximately 100 feet downstream of the downstream bridge opening.



Selected Miscellaneous Photographs

Photo ID: 1102151023_42_5

Unique ID: 42

Site ID: Quincy-04

Comments: A sewer manhole was located adjacent to the upstream end of the culvert in the marsh. Gravel had recently been placed around the manhole and evidence of previous scour was observed suggesting a history of overwash and stormwater inflows.



Photo ID: 1103151228b_63_5

Unique ID: 63

Site ID: Cohasset-02

Comments: The upstream channel was full of killifish.



Selected Miscellaneous Photographs

Photo ID: 1103151258_65_3

Unique ID: 65

Site ID: Cohasset-04

Comments: Resident indicated that upstream impoundment used to be a pond; however, indicated that Town of Cohasset drains it for winter ice skating. Mowed cattails were observed throughout the upstream impoundment.



Photo ID: 1104151149_69_5

Unique ID: 69

Site ID: Marshfield-02

Comments: Many killifish were observed on the downstream side of the tide gate.

