

# DEPARTMENT OF TELECOMMUNICATIONS & ENERGY

PIPELINE ENGINEERING AND SAFETY DIVISION

## INCIDENT REPORT

9 Rockwood Street, Walpole, Massachusetts April 13, 2004

### PIPELINE ENGINEERING AND SAFETY DIVISION

### Accident File

Location: Walpole, Massachusetts

Date of Accident: April 13, 2004

Gas Company: Bay State Gas Company

Property Damage: Over \$150,000 \*

Injuries: 0

Report Issued - June 2006

<sup>\*</sup> Estimated by Bay State Gas Company

### TABLE OF CONTENTS

I.	<u>INTRO</u>	DDUCTION 1	_
	A.	Scope of this Investigation	_
	B.	Overview of Incident	1
II.	THE I	DIVISION INVESTIGATION 3	3
	A.	Description of the Site	3
	B.	Description of the Scene	1
	C.	Bay State Gas Company	5
		1. <u>Service History</u>	5
		2. <u>Leakage History of the Service Line</u>	5
		3. <u>Leakage History of the Main</u>	5
	*	4. <u>Leak Repairs on Rockwood Street</u>	5
		5. Operating Pressure	6
		6. Odor Testing	7
		7. <u>Corrosion Control Records</u>	7
	$\mathbf{D}_{i}$	The Homeowner	7
	E.	The Walpole Fire Department	8
	F.	Examination of the Pipe Sections	9
		a w	
III.	FIND	INGS AND CONCLUSIONS	<u>C</u>
	A.	<u>Findings</u>	1
	В.	Conclusions	2

#### I. <u>INTRODUCTION</u>

#### A. Scope of this Investigation

The Massachusetts Department of Telecommunications and Energy

("Department"), Division of Pipeline Engineering and Safety ("Division"), pursuant to

G.L. c. 164, § 105A and a Federal Certification Agreement as provided for in 49 U.S.C.§

60105, has investigated a natural gas ("gas") release at 9 Rockwood Street, Walpole, that

occurred on April 13, 2004 ("incident"). The incident contributed to a fire and \$150,000

in property damage to the dwelling as estimated by Bay State Gas Company ("BSG")

(Exh. 1). The pipeline involved was owned and operated by BSG.

As part of the Department's annual certification process by the United States Department

of Transportation ("U.S. DOT"), the Department must report to the US DOT

"each accident or incident...involving a fatality, personal injury requiring hospitalization, or property damage or loss of more than an amount the Secretary establishes... and any other accident the [Department] considers significant, and a summary of the investigation by the [Department] of the cause and circumstances surrounding the accident or incident.

49 U.S.C. § 60105(c).

1

Incident means any of the following events:

<sup>(1)</sup> An event that involves a release of gas from a pipeline or liquefied natural gas or gas from an LNG facility and,

<sup>(</sup>i) A death, or personal injury necessitating in-patient hospitalization; or

<sup>(</sup>ii) Estimated property damage, including cost of gas lost, of the operator or others, or both, of \$50,000 or more.

<sup>(2)</sup> An event that results in an emergency shutdown of an LNG facility.

<sup>(3)</sup> An event that is significant in the judgment of the operator, even though it did not meet the criteria of paragraphs (1) or (2)." 49 C.F.R. § 191.3.

Incident Report 9 Rockwood Street, Walpole MA - April 13, 2004

The purpose of this report is to inform U.S. DOT as to the circumstances surrounding, and as to the cause of the Incident.

The Department has established procedures for determining the nature and extent of violations of codes and regulations pertaining to safety of pipeline facilities and the transportation of gas, including but not limited to, 220 C.M.R. §§ 101.00 through 113.00. See 220 C.M.R. § 69.00 et seq.

The Division also enforces the U.S. DOT safety standards for gas pipeline systems as set forth in 49 C.F.R. Part 192 (Part 192).

#### B. Overview of Incident

On April 13, 2004, at approximately 4:53 p.m., the Walpole Fire Department received a fire alarm for 9 Rockwood Street, Walpole. The homeowner both discovered and reported the fire. The fire department responded and arrived at 4:56 p.m. (Exh. 2). Upon arriving, fire was observed exiting the right rear basement window.

The homeowner had been removing the old siding and installing Styrofoam insulation to the exterior of the structure. He was working on the opposite side of the wall of the fire origin.

The fire fighters entered the building through the rear basement door. Seconds after putting the fire out there was an explosion. Two Walpole fire fighters that were in the structure at the time of the explosion suffered minor injuries and were taken to the hospital. The force of the explosion blew out windows and the garage door. It also

Incident Report 9 Rockwood Street, Walpole MA - April 13, 2004

moved the rear wall off the foundation. The Walpole Fire Department shut off the underground curb valve using a wrench. They then extinguished the fire.

The fire department notified BSG at 5:06 p.m. BSG notified the Division by telephone at approximately 5:55 p.m.<sup>2</sup> that a fire and explosion occurred at 9 Rockwood Street, Walpole.

#### II. THE DIVISION INVESTIGATION

#### A. <u>Description of the Site</u>

The residential single family home located at 9 Rockwood Street, Walpole was a wood frame two level with a split foyer. The exterior consisted of wood shingles. The fire originated in a utility room located at the right rear of the structure. The utility room housed the gas furnace, gas hot water heater, gas meter and service regulator<sup>3</sup>, the electric service panel and several appliances. (Exh. 3). The gas service line<sup>4</sup> entered the utility room underground through the foundation sidewall.

In a letter to all operators, the Director of the Division has requested that operators inform the Department of any incident promptly, but no more that two hours after discovery of an incident.

A service regulator is a valve which reduces the pressure in the service line from the pressure in the main to the pressure provided to the customer.

A service line is a distribution line that transports gas from a common source of supply to a customer meter. 49 C.F.R. § 192.3.

The one inch coated steel service was installed on October 25, 1960 by Brockton Taunton Gas Company. The two inch coated steel gas main<sup>5</sup> was also installed in 1960. The operating pressure at the time of the incident was 48.9 psig<sup>6</sup> recorded at the Walpole telemeter station at 7:00 p.m.

#### B. <u>Description of the Scene</u>

On April 13, 2004, at approximately 6:45 p.m., an investigator from the Division arrived at 9 Rockwood Street, Walpole, to investigate the explosion. Representatives from BSG, the Walpole Fire Department, and the State Fire Marshal office were already at the scene.

The house had extensive fire damage in the utility room and the surrounding area (Exh. 4). The electric panel and wiring had been completely burned. The gas meter had melted and the service regulator was partially melted (Exhs. 5,6). Most of the basement windows and the garage door had been blown out (Exh. 7). The rear house wall was off the foundation (Exh. 8).

The Division investigator requested that BSG leak survey the service line to 9

Rockwood Street and the main in front of the house. No leaks were found by this survey.

A main is a distribution line that serves as a common source of supply for more than one service line. 49 C.F.R. § 192.3.

PSIG – pounds per square inch guage refers to the pressure expressed in pounds exerted on one square inch of surface area. The designation "Guage" indicates the readings are already adjusted to ignore the surrounding atmospheric pressure, which is 14.7 psi at sea level. If psig guage were not connected to any pressure source it would read zero even thought it is actually sensing 14.7 psi at sea level.

BSG and their consultant, Surveys and Analysis Inc., had already leak surveyed the rest of the main and the surrounding area. BSG reported no leakage in the area (Exh. 9).

The Division investigator requested that the gas service line be pressure tested from the street area to inside the house. The gas meter, regulator, and piping inside the house could not be part of the test due to their damaged condition. The service line was sealed inside the house and disconnected from the main. The pressure test was conducted at 50 psig for 16 minutes (Exh. 10 & 11). There was no pressure drop observed, indicating no leakage.

The Walpole Fire Department took possession of the gas meter, regulator and inlet piping.

### C. Bay State Gas Company

#### 1. <u>Service History</u>

Bay State Gas Company's records from 1997 to 2004 indicate that there were no service calls for gas odors or equipment maintenance. The records indicate that the service was locked and unlocked in 1999. On April 23, 2003, BSG replaced the meter. The work order for this date indicates that a leak survey was completed and the results were negative (Exh.12).

### 2. <u>Leakage History of the Service Line</u>

Bay State Gas Company's records indicate that the service line was leak surveyed on June 6, 2003, the results were negative.

Federal safety regulations require that services be leak surveyed at 3 year intervals<sup>7</sup> (Exh.13).

#### 3. <u>Leakage History of the Main</u>

Bay State Gas Company's records indicate that the main was leak surveyed July 23, 2003, the results were negative. The main was also surveyed on January 25, 2004, as part of the companies' special winter survey, the results were negative. Federal safety regulations require that mains be leak surveyed at 3 year intervals (Exh.14).

#### 4. Leak Repairs on Rockwood Street

In 1983 two leak clamps were installed in front of 7 Rockwood Street. Bay State Gas Company's records indicate that on February 11, 2003 these two clamps leaked and were replaced (Exh.15).

#### 5. Operating Pressure

Bay State Gas Company's records indicate that the pressure at the time of the fire and explosion (17:00) was 50.222 psi. The pressure was recorded at Industrial Road Walpole. The pressure at 19:00 was 48.933 psi (Exh. 16).

A leakage survey with leak detector equipment must be conducted outside business districts as frequently as necessary, but at least once every 5 calendar years at intervals not exceeding 63 months. However, for cathodically unprotected distribution lines subject to § 192.465(e) on which electrical surveys for corrosion are impractical, a leakage survey must be conducted at least once every 3 calendar years at intervals not exceeding 39 months. 49 C.F.R. § 192.723.

#### 6. Odor Testing

Bay State records indicate that an odorant test was conducted on April 14, 2004 at 16 Rockwood Street, Walpole. The level at which there was a distinct odor of gas was .09% gas-in-air (Exh. 17). Massachusetts safety regulations require that gas be odorized so that it can be detected at a level of 0.15% gas-in-air or less.<sup>8</sup>

#### 7. Corrosion Control Records

Bay State stated that there are no corrosion monitoring records, for its interior piping at 9 Rockwood Street. Bay State does not perform corrosion monitoring of interior company owned piping. Federal safety regulations require inspections of above ground piping every 3 years.<sup>9</sup>

#### D. The Homeowner

Three people lived in the house. The homeowner stated that he was installing rigid insulation on the exterior of the house in preparation for the house to be sided by a contractor. The work being done on the date of the incident was under the deck/porch behind the house, out of the rain. The existing siding was being removed before the insulation was installed.

He stated that he heard a hissing noise and entered the house to investigate. Once inside, he said he saw flickering or shadows in the utility room. He saw this between the crack in the bi-fold door. Upon entering the utility room, he saw a fire in the corner, on the floor, under

<sup>8</sup> See 220 C.M.R. § 101.06 (20) (a): "Odorization of Gas."

<sup>(</sup>a) Each operator must inspect each pipeline or portion of pipeline that is exposed to the atmosphere for evidence of atmospheric corrosion, as follows: If the pipeline is located onshore, then the frequency of inspection is "at least once every 3 calendar years, but with intervals not exceeding 39 months."

49 C.F.R. § 192.481.

where the gas service line enters the house (Exh. 18, at 2). He stated that it looked like the cement floor was on fire (id.). This is also where the gas regulator is located. He stated that the fire was yellow, about knee high, confined to the corner and was lazy. He said that there was no noticeable smoke or noise (id.). The area he was viewing is small, between the freezer, the foundation wall and the food shelves. He then went to the garage to get a bucket to fill with water. While filling the bucket with water in the downstairs bathroom, he heard the smoke alarm sound. He again looked into the utility room and saw that the flames were now 4-5 feet high. After getting his phone from the kitchen, he left the house. He then called the Walpole Fire Department. He went around to the back of the house and smashed the utility room window with a rock. He tried to spray water on the fire with a garden hose, but was not able to get much water out of the hose. At this point, he said, the fire was hitting the ceiling and there was a lot of smoke. The owner also stated that the heating system is on an automatic setback thermostat. It was set to come on at 4:30 p.m. every workday.

#### E. The Walpole Fire Department

Four WFD firefighters entered the house, in full gear, through the rear basement door. Once inside, they saw the utility room fully engulfed in fire. They stated that the large amount of smoke made it dark. They said that the wires running along the back of the house at the ceiling were popping due to insulation melting. They sprayed water on this area to knock the fire down. They then sprayed the entire utility room and the fire went out.

A few seconds later, there was an explosion, accompanied by a flash. At this time, the WFD realized that gas had been feeding the fire. The curb valve on the gas service line was

used to shut off the gas by the WFD. Using a tool that they had on the fire truck, they were able to reach the valve down in the valve box. The fire was then extinguished. Two of the four WFD firefighters went to the hospital to be checked because they were in the explosion area. Neither one was admitted.

#### F. <u>Examination of the Pipe Sections</u>

Massachusetts Material Research, Inc. ("MMR") conducted the failure analysis of the interior piping and fittings from 9 Rockwood Street. The pipe was recovered by the D.T.E. and stored at the Walpole Police Department evidence room before being taken to MMR. The piping and fittings consisted of sections of high pressure piping and a valve, which were located upstream of the regulator. The low pressure piping from the regulator to the meter inlet, the regulator vent pipe, and the meter were also part of the evidence sent MMR. The purpose of the testing was to document the condition of all the interior facilities and to attempt to determine a cause of the incident.

MMR performed debris analysis, leak testing, radiographic examination, microscopic examination, fracture surface conditions and chemical analysis. In addition, MMR evaluated the structure of the facilities in the heat affected areas.

Copies of the MMR report can be obtained by contacting: Veda-Anne Ulcickas, Massachusetts Materials Research, Inc., P.O. Box 810, 1500 Century Drive, West Boylston, MA 01583.

Based on the test results, MMR concluded the following:

- Leak testing of the submitted incident components (except for the incident meter and regulator) produced only leakage consistent with a fire-exposed piping system. The shutoff valve and the regulator "T" fitting exhibited no leakage during this testing.
- Chemical analysis of soot samples from the incident piping and regulator revealed the presence of a long chain aliphatic hydrocarbon similar to mineral spirits, and the presence of an aliphatic ester oil (commonly found in paint products). Both substances are flammable.
- Examination of fractures located on the incident regulator revealed that substance containing these aliphatic compounds that had spilled onto the regulator was not present on the fractures. In fact, this spilled substance was present on the regulator vent side rim surface on both sides of two regions of the vent fracture, but did not spill onto the fracture at either region. This indicates that the substance spilled prior to the vent-side fracture occurring.
- Scene photographs taken by the Walpole Fire Department show the charred remains of wooden shelving and a large can under the regulator after the fire. The can appears large enough to have caused the dent on the vent side of the regulator. This indicates that the dent was caused as a result of the shelving collapse after the fire was already in progress.
- From this evidence, combined with the witness statement that at the beginning of the incident a fire was located underneath the regulator and made the cement floor appear to be burning, it is logical to conclude that a substance related to painting (i.e., paint thinner or similar), spilled onto the regulator and dripped onto the utility room floor. This substance then ignited.
- A gas fire due to a damaged regulator would present a very different appearance from the "lazy" fire described by the homeowner. Were regulator damage the cause of the fire, a gas "jet" would escape at inlet supply line pressure. If ignited, such a flame would be torch-like, not lazy, and would be seen to emanate from the damaged region instead of being located on the cement floor of the utility room.

#### III. FINDINGS AND CONCLUSIONS

#### A. Findings

- (1) Brockton Taunton Gas Company installed a two-inch diameter steel main under Rockwood Street, Walpole in 1960.
- (2) A one-inch diameter coated steel service line connected the house at 9 Rockwood Street to the two-inch main on Rockwood Street.
- (3) Bay State Gas Company installed the service line on October 25, 1960.
- (4) The customer meter and regulator were located inside the house.
- (5) The service had 30 inches of cover at the main in the street.
- (6) There is no history of service calls to 9 Rockwood Street, Walpole.
- (7) Bay State Gas Company was at 9 Rockwood Street, Walpole for routine maintenance on June 23, 2003.
- (8) There is no history of leaks on the service to 9 Rockwood Street, Walpole or on the main in front of 9 Rockwood Street, Walpole.
- (9) The odorant levels of the gas were in compliance with state and federal regulations.
- (10) Corrosion on the interior piping was consistent with exposure to water and combustion gases of a fire.
- (11) At the time of the fire and explosion, the homeowner was working on the opposite side of the wall from where the fire originated and where the gas facilities were located.
- (12) The homeowner both discovered and reported the fire.
- (13) At the time the Walpole Fire Department entered the house, they were unaware that the gas service line existed and entered the house in full fire fighting equipment.
- (14) Leakage found during the testing on the interior piping was consistent with damage caused by fire exposure.

- (15) There was wood shelving above the regulator on both walls and plastic shelving next to the regulator. The shelving had miscellaneous items including cans of food.
- (16) Residue on the piping and regulator was from a flammable substance.
- (17) Residue of the flammable substance was not present on the fracture surfaces of the regulator.

#### B. Conclusions

The MMR report states that "Chemical analysis of soot samples from the incident piping and regulator revealed the presence of a long chain aliphatic hydrocarbon similar to mineral spirits, and the presence of an aliphatic ester oil (commonly found in paint products). Both substances are flammable. Examination of fractures located on the incident regulator revealed that substance containing these aliphatic compounds that had spilled onto the regulator was not present on the fractures."

The Division concludes that there was a spill of a flammable liquid onto the regulator and the floor. The flammable liquid then ignited. This fire apparently caused, among other things, the shelving near the regulator to collapse. The damage to the regulator was probably caused by a falling object. The fire and damage allowed gas to leak from the regulator. The explosion was caused by the accumulation of gas in the utility room after the initial fire was extinguished, and after the damage to the regulator occurred.

### EXHIBIT LIST FOR 9 ROCKWOOD STREET INCIDENT REPORT

- 1. Report of Utilities Service Incident
- 2. Walpole Fire Department Report
- 3. Schematic of Utility Room
- 4. Damage in the Utility Room
- 5. The Gas Meter
- 6. The Gas Regulator
- 7. The Front of the House
- 8. The Rear of the House at the Utility Room.
- 9. Leak Surveys Conducted on April 13, 2004
- 10. Work Order Showing Pressure Test
- 11. Pressure Gauge
- 12. Work Order for Meter Change and Leak Survey
- 13. Service Line Leak Survey on June 6, 2003
- 14. Main Leak Surveys July 23, 2003 and Winter Leak Survey January 25, 2004
- 15. Work Order of Leak Repair on February 11, 2003
- 16. Record of Pressure at the Time of the Incident
- 17. Record of Odor Test
- 18. Fire Investigation Summary Report

Report of Utilities Service Incident

### The Commonwealth of Massachusetts

### Department of Telecommunications and Energy

Company: BAY STATE GAS COMPANY

Date: April 13, 2004

### Report of Utilities Service Incident

Type of Incident:

Outage

Accident

Other

Fire / Explosion

Service Affected:

GAS

Location of Incident:

Initial Outage:

9 Rockwood Street, Walpole, MA 02081

Date and Time of Incident:

Service Restored:

April 13, 2004

5:05 PM

Description of Incident:

Fire and explosion. Single family wood frame residential dwelling.

Personal Injury or Property Damage:

No inpatient hospitalization.

Estimate \$150,000 property damage

**Duration of Incident:** 

Customers Affected:

One (1)

**Customer Hours:** 

Comments:

Fire and explosion. Single family wood frame residential dwelling.

State Fire Marshall investigating. Cause and origin undetermined at this time.

Date Reported:

4/13/2004

Reported By:

Gail Rooslet

Time Reported:

5:55 PM

Received By:

Paul Grieco

Walpole Fire Department Report

Incident Type *  [111   Building fire   Incident Type   Incide	Basic
Street address   9	]-[00]
Their FDID Their Incident Number    Their FDID Their Incident Number   Their I	Suffix
Adjacent to Directions  C Incident Type *  Ill Building fire Incident Type  D Aid Given or Received*  1 XMutual aid received 2 Automatic aid recv. 3 Mutual aid given 4 Automatic aid given 5 Other aid given  Their Incident Number  Apt./Suite/Room City  Midnight is 0000  E 2 Shift  Check boxes if dates are the same as Alarm Alarm Alarm always required same as Alarm Alar	
C Incident Type *  Incident Type  D Aid Given or Received   21208   Their State   Their State   Their State   Their Incident Number   Their Incident N	
C Incident Type *  Ill Building fire  Incident Type  D Aid Given or Received *  1 XMutual aid received 2 Automatic aid recv. 3 Mutual aid given Their State  Alarm *  Controlled 13 2004 16:53:00  Arrival *  Controlled 13 2004 16:56:00  Controlled 13 2004 16:56:00  Last Unit Cleared, required except for wildland fires  Special Study ID#	t & Alarms
Incident Type  D Aid Given or Received   1 X Mutual aid received  2 Automatic aid recv.  3 Mutual aid given  4 Automatic aid given  5 Other aid given  Their Incident Number  Their Incident Number  Their Incident Number  Alarm   Al	1 Option
Arrival * Q4 13 2004 16:56:00 E3    Mutual aid received   21208	01 E District
2 Automatic aid recv. 3 Mutual aid given 4 Automatic aid given 5 Other aid given Their FDID Their State  CONTROLLED Optional, Except for wildland fires Last Unit CLEARED, required except for wildland fires Special	
3 Mutual aid given 4 Automatic aid given 5 Other aid given Last Unit CLEARED, required except for wildland fires Special Study ID#	al Studies
5 Other aid given  Their Incident Number  Last Unit  La	al Option
N None Cleared 04 13 2004 23.0000	Special Study Value
Taken * G1 Resources * G2 Estimated Dollar Losse	
Check this box and skip this LOSSES: Required for all fires if 1	nown. Optional
Section if an Apparatus or personnel form is used.   Section if an Apparatus or personnel property \$   1,   325	000 None
Primary Action Taken (1)  Suppression 0009 0026 contents \$   , 000 ,	000
11 Extinguish Additional Action Taken (2)  EMS PRE-INCIDENT VALUE: Optional	
Other Property \$   ,   325 ,	000
Additional Action Taken (3)  Check box if resource counts include aid received resources.  Contents \$   ,   000 ,	000
Completed Modules H1* Casualties None H3 Hazardous Materials Release I Mixed Us	e Property
☐ Deaths Injuries N None 10 Assemb	ly use ion use
Civil Fire Cas4 Service 2 Propane gas: <21 lb. tank (as in home BBQ grill) 33 Medica	
Fire Serv. Cas5 Civilian 3 Gasoline: vehicle fuel tank or portable container 51 Row of 4 Kerosene: fuel burning equipment or portable storage 53 Enclose	stores
H2 Detector Required for Confined Fires. 5 Diesel fuel/fuel oil: vehicle fuel tank or portable 58 Bus. &	Residential
Wildland Fire-8   1 Detector alerted occupants   0 Industrial   60 Industrial   60 Industrial	rial use ry use
Personnel-10   2  Detector did not alert them 8   Paint: from paint cans totaling < 55 gallons   65   Farm U	se mixed use
Please complete the HarMat Form  341 Clinic, clinic type infirmary 539 Household goods, sale	
342 Doctor/dentist office 579 Motor vehicle/boat s	
161 Restaurant or cafeteria 419 X 1-or 2-family dwelling 599 Business office	
162 Bar/Tavern or nightclub 213 Elementary school or kindergarten 429 Multi-family dwelling 429 Laboratory/science	
215 High school or junior high 449 Commercial hotel or motel 700 Manufacturing plant	
211 Care facility for the aged 464 Dormitory/barracks 882 Non-residential part	cing garage
331 Hospital 519 Food and beverage sales 891 warehouse	
Outside 936   Vacant lot 937   Industrial plant ya 938   Graded/care for plot of land 984   Industrial plant ya	rd
655 Crops or orchard 946 Lake, river, stream  Lookup and enter a Property Use of	.ru
807 Outdoor storage area 960 Other street Property Use 419	
919 Dump or sanitary landfill 961 Highway/divided highway 931 Open land or field 962 Residential street/driveway NFIRS-1 Revise	

1 X Enclosed Building 2 Portable/mobile structure 3 Open structure 4 Air supported structure 5 Tent 6 Open platform (e.g. piers) 7 Underground structure (work areas) 8 Oconnective structure (e.g. fences)	Under construction  Occupied & operating  Idle, not routinely used  Under major renovation  Vacant and secured  Vacant and unsecured  Being demolished  Other  Undetermined	Height Count the ROOF as part of the highest story  OO2 Total number of stories at or above grade  Total number of stories below grade	Structure Fire  OR  OR  Lenght in feet Width in feet
J1 Fire Origin *    Delow Grade   Count     Story of fire origin    J2 Fire Spread * 1   Confined to object of origin   2   Confined to room of origin   3   Confined to floor of origin   4   Confined to building of origin   5   Beyond building of origin	Number of Stor Damaged By Flat the ROOF as part of the hi Number of stories w/ minor (1 to 24% flame damage)  Number of stories w/ signif (25 to 49% flame damage)  Number of stories w/ heavy (50 to 74% flame damage)  Number of stories w/ extrem (75 to 100% flame damage)	me To F  Independent story damage	rial Contributing Most  Clame Spread  if no flame spread e as material first ignited ble to determine  Section L  ontributing most to flame spread  material contributing flame spread  Required only if item contributing code is 00 or<70
In area of the fire)  N None Present Skip to section M  1 X Present  U Undetermined  L2 Detector Type  1 X Smoke  2 Heat  3 Combination smoke - heat  4 Sprinkler, water flow detection  5 More than 1 type present  O Other  U Undetermined	L3 Detector Power  1	Required  1 Alerte 2 Occupa 3 X There 4 Failed U Undete  Required  1 Power 2 Improp 1 Jack ( 5 Batter 6 Batter  1 Other	failure, shutoff or disconnect per installation or placement tive of maintenance, includes cleaning ry missing or disconnected by discharged or dead
M1 Presence of Automatic Extinguishment  N X None Present  1	System Required if fi.  1 Operate 2 Operate 3 Fire t 4 Failed 0 Other U Undete:  M4 Number Heads Required	tic Extinguishment Coperation The was within designed range and & effective (Go to Med & not effective (Note of Small to activate The operate (Go to Med & operate) The operating The operating The operated  Sprinkler heads operating The operation operated	1 System shut off 2 Not enough agent discharged 3 Agent discharged but did not reach fire 4 Wrong type of system 5 Fire not in area protected 6 System components damaged 7 Lack of maintenance 8 Manual Intervention 0 Other U Undetermined

21307 MA 04 13 20  FDID * State * Incident Date *	04 1 04-0000724 000  Change Fire
B Property Details  B1 0001 Not Residential  Estimated Number of residential living units building of origin whether or not all units became involved	On-site material (1)  3 Packaged goods for sale Repair or service
B2 001 Buildings not involved  Number of buildings involved  .  B3 None  Acres burned (outside fires) Less than one acre	On-site material (2).  3 Packaged goods for safe Repair or service  1 Bulk storage or warehousing Processing or manufacturing Packaged goods for sale Repair or service  3 Repair or service
D Ignition  D1 62   Heating room or area,  Area of fire origin *	Cause of Ignition  Check box if this is an exposure report.  Skip to section G  Check all applicable boxes  1
D2 UU Undetermined  Heat source *  D3 UU Undetermined E	4 Act of nature 5 X Cause under investigation U Cause undetermined after investigation  Fractors Contributing To Ignition  3 Unattended person 4 Possibly mental disabled 5 Physically Disabled 6 Multiple persons involved
Ttem first ignited * 1 Check Box if fire spread was confined to object of origin  D4 Type of material first ignited Required only if item first ignited code is 00 or <70	Factor Contributing To Ignition (1)  Factor Contributing To Ignition (2)  Estimated age of person envolved  1 Male 2 Female
None If Equipment was not involved, Skip to Section G  Equipment Involved  Brand	G Fire Suppression Factors  Equipment Power Source  Equipment Portability  1 Portable  2 Stationary  G Fire Suppression Factor (1)  Fire suppression factor (2)
Serial # mm	ortable equipment normally can be oved by one person, is designed to express in multiple locations, and sequires no tools to install.
None  1 Not involved in ignition, but burned 2 Involved in ignition, but did not burn 3 Involved in ignition and burned	Dobile Property Type & Make    Pre-Fire Plan Available   Some of the information presented in this report may be based upon reports   from other Agencies     Arson report attached   Police report attached   Coroner report attached   Other reports   Other reports
Moblie property model  License Plate Number State VIN	Year  Number  NFIRS-2 Revision 01/19/99

		Business name (if app	olicable)		Area Code	Phone Number	
Check This Box if same address as incident location. Then skip the three duplicate address lines.	Mr.,Ms., Mrs. First	Name Prefix Street or Hig	MI ihway	Last Name		Street Type	Suffix Suffix
☐ More people ir	Post Office Box  State Zip Code  avolved? Check th	is box and attach	Apt./Suite/Room  Supplemental I	Coity	as necessary		
Then c	s person involved? heck this box and skip st of this section.	9 Rockwood S Business name (if App			508 -	668 - 33	12
Check this box if same address as incident location. Then skip the three duplicate address lines.	Mr., Ms., Mrs. First  9 Number  Post Office Box  MA 02081  State zip Code			Last Name  Walpole City		ST Street Type	Suffix Suffix
L Remarks Local Option Single family h gas explosion t taken to the ho released. Fire Fire investigat continue.	forces 4 fires ospital with a is under inve	fighters to be non life threa estigation by	blown out of tening injust the State Fi	of the building ries. Both mer re Marshalls	g. Two III were trea Office and	rerighters v ated and d the Walpol	vere
300							
Evidence from	the scene tak	en into fire c	department c	ıstody.			
Evidence from  Items taken we Bailey, Jr., 0	re gas meter	assembly, regu			ing. Take	n by Timoth	у ғ.
Items taken we	re gas meter	assembly, regu			ing. Take	n by Timoth	y F.
Items taken we	re gas meter	assembly, regu			ing. Take	n by Timoth	y F.
Items taken we	re gas meter 4.13.04 2200 on	assembly, regu	elator and a	ssociated pip	ing. Take	n by Timoth	y F.

21307 FDID +	MA State *	4 13 2004 Incident Date	1 Station	04-0000724 Incident Number ★	000 Exposure *	Complete Narrative
--------------	------------	-------------------------	--------------	---------------------------------	----------------	-----------------------


#### Narrative:

Single family home involved in fire on arrival. Four 1 3/4" handlines in operation. Interior gas explosion forces 4 firefighters to be blown out of the building. Two firefighters were taken to the hospital with non life threatening injuries. Both men were treated and released. Fire is under investigation by the State Fire Marshalls Office and the Walpole Fire investigators. Fire detail in place until the morning when the investigation will continue.

Evidence from the scene taken into fire department custody.

Items taken were gas meter assembly, regulator and associated piping. Taken by Timothy F. Bailey, Jr., 04.13.04 2200 hours.

Schematic of Utility Room




Schematic of utility room in basement.

Utility Room



The Gas Meter



The Gas Regulator



Damage to the Front of the House



The Rear of the House near the Utility Room



Leak Surveys Conducted on April 13, 2004

4/13/04

Daniel D. Wile Surveys and ANALYSIS, FINC 538 Hart Ford Turnpike SHREWSBURY, MA. 01545

AT 7:08, 4/13/04, I SURVEYED


ALL BLDNGS AND HOMES ON ROCKWOOD ST

AND NEAL ST. ALL TESTS WERE NEGATIVE IN

ENTIRE AREA. I CONCLUSION, ALL SERVICES and

ALL MAINS WERE NEGATIVE.

Dancel




Work Order Showing Pressure Test









### **Manual Distribution Work Order** identification: Work Order # Street Name House # Other Identifying Information Filled Out By Customer Name Phone Work: Leak Priority Scheduled Date Work Description **Employee Assigned** Cause of Leak **BSG Crew Assigned**







ISTributi	ion Department	
Daily	Crew Sheet	

Date	Vehicle #
4-13-04	5184

Leader	<b>Emp</b>	#
	Emp	
	Emp	#
	<b>Emp</b>	#

	Name
353	R. KELLEY
786	M. BRADY
1080	11. WAYSLOW


Work Order	Ctract #	Address	Town Code	Job Time	Pay Rate
Number	Street #	Street Name	Code	Tille	nate
5550006	9	Ruck wood 35	WA	8	1.5
		ş ,			
₩'r					,
		20			\$
					90
8			Total	8	

Comments:	
CUT OFF STRUCK AT MAIN & THEERS & CAPPEN. PRESSUL	E FESTER
14 c.s stavice AT Fold 19 gr. 16 mikis. 10:11 Pm -10:	33 PM,
BALTESTES MAIN & SERVICES IN AREA.	
B. STEGR J. MUPPAG, S. WILBER B. WALDN, M. PETERSO R. KELLEG K. WAYSLOW & M. BRADG WERE THERE, ST. CREW ARRIVES AT 6:30 PM + OLERET AT 17:30 PM.	or Il. PARKES.
R. Killey IL. wayslow & M. BRADY WERE THERE,	
STI CREW ALRIVER AT 6:30 PM + ChETET AT 11:30 PM.	


Pressure Gauge of Pressure Test




Work Order for Meter Change and Leak Survey




Service Line Leak Survey on June 6, 2003



Main Leak Survey – July 23, 2003 Winter Leak Survey - January 25, 2004



Main Survey July 23, 2003




BROCKTON TAUNTON GAS CO. 25.72 mile: 10-2/

Work Order of Leak Repair on February 11, 2003

### Attachment DTE 1-10

610117X PRO SCAN



### **Distribution Work Order**



MAR 2 8"2003". Identification: Location Phone COMPLETED# At House To House Street Name ROCKWOOD ST 5103221-1 Unit# Apt. # Suite # Work Phone Initiated Date WALPOLE 01/27/2003 To Lot At Pole To Pole At Intersection Customer Account # Initiated Time 12:28 Kit and Grid # To Intersection CCS Number Source 0 - 0 - 0LEAK SURVEY **Customer Name** Entered By **Digging Conditions** Source Name NEIL DULMAINE-S& Work: Work Code Work Description Estimated Units Scheduled Date LRMX MAIN - LEAK REPAIR 1 01/27/2003 Leak Priority **Employee Assigned** CLASS 2 GILES, DAVID G. BROWNE **Outgoing Comments** Cause of Leak **BSG Crew Assigned** CLASS 2\* LEAK - 65% - 2003 399 Dig Safe # Contr. Crew Assigned Job Priority Pipe Data: Other Data: New Pipe **Exposed Pipe Retired Pipe** Anode Inst. Pipe Size Flow Limiter Installed Pipe Type CIS. Flow Limiter Tagged C- TAR Coat Type Curb Cock Installed Pressure INT Meter Barner Meter Fit Installed Length Cut SML SML Inside Depth 28" 100 Outside 1960 Year Soap Test LN (F) P - VP Pipe Cond. LN-F-P-VP LN-F-P-VP Pressure Test Coat Cond. G-(MD)- ED G-MD-ED G-MD-ED Pounds/ Pit Depth Square Inch # of Fits Elpsd. PSI Fit Size A SHEET Rate Class Patch Size 12 Length X Restoration Needed Wichh Restoration Done Bill to Customer?

	MEASURS	S TO CLAM	MPS ALA	READY ON MAP
Line of Main _				
Restoration	n Data:			Permit Data:
Sand Gravel Base Coat Cold Patch Hot Patch Flow Fill Infra-Red Concrete Loam & Seed Other Size Signature	Required Done	Date Done		Dig Safe: Ticket # Date Effective 1 30 03 05000
Stamps:		Completed Date    2 - 1/ - 0.3   Completed Units   /	Depunce.  Date S	Started -11-03 sure  BROWNE

UNCLUII.

Record of Pressure at the Time of the Incident

June 3, 2004

SCADA Report

RTU State: MASSACH

RTU Name: MEDG

RTU Owner: BSG\_

RTU Description: MDG-Medway Gate From Calendar Date: 2004-04-01

To Calendar Date: 2004-04-15

Calendar Date	Calendar Hour	Current Reading	Average Reading	Maximum Reading	Minimum Reading
2004-04-12	6	55.333	58.12	63.6	55.333
2004-04-12	7	48.8	51.527	55.2	48.8
2004-04-12	8	50.0	47.995	50.0	46.889
2004-04-12	9	53.511	52.196	53.511	50.4
2004-04-12	10	56.356	54.795	56.356	53.422
2004-04-12	11	57.156	56.541	57.156	56.089
2004-04-12	12	56.889	56.889	56.889	56.889
2004-04-12	13	58.756	58.036	58.756	57.733
2004-04-12	14	59.111	59.111	59.111	59.111
2004-04-12	15	57.511	58.698	59.6	57.511
2004-04-12	16	58.222	58.222	58.222	58.222
2004-04-12	17	57.911	57.911	57.911	57.911
2004-04-12	18	57.022	57.022	57.022	57.022
2004-04-12	19	56.756	56.756	56.756	56.756
2004-04-12	20	56.133	56.133	56.133	56.133
2004-04-12	21	55.156	55.427	56.178	55.156
2004-04-12	22	56.489	56.059	56.489	55.467
2004-04-12	23	58.178	57.52	58.178	57.156
2004-04-13	0	60.089	58.632	60.089	58.044
2004-04-13	1	62.0	61.723	62.0	60.933
2004-04-13	2	62.489	62.558	72.311	62.444
2004-04-13	3	62.444	62.444	62.444	62.444
2004-04-13	4	62.0	62.0	62.0	62.0
2004-04-13	5	59.333	60.691	61.467	59.333
2004-04-13	6	53.911	57.199	59.111	53.911
2004-04-13	7	49.511	51.65	53.689	49.511
2004-04-13	8	49.111	48.555	49.111	48.089
2004-04-13	9	52.089	50.248	52.089	48.889
2004-04-13	10	54.089	52.693	54.089	52.444
2004-04-13	11	50.889	53.122	53.956	50.889
2004-04-13	12	50.533	51.385	52.578	50.533
2004-04-13	13	51.244	50.843	51.244	50.178
2004-04-13	14	53.467	52.714	53.467	51.422
2004-04-13	15	52.044	53.331	54.089	52.044
2004-04-13	16	50.667	51.225	51.244	50.667
2004-04-13	17	50.222	50.314	50.533	50.222
2004-04-13	18	49.289	49.776	50.311	49.289
2004-04-13	19	48.933	48.933	48.933	48.933
2004-04-13	20	49.422	49.281	49.422	49.067
2004-04-13	21	51.333	50.855	51.333	50.267
2004-04-13	22	53.956	53.117	53.956	52.222
2004-04-13	23	53.956	53.956	53.956	53.956
2004-04-14	0	53.956	53.956	53.956	53.956
2004-04-14	1	53.956	53.956	53.956	53.956
2004-04-14	2	53.956	53.956	53.956	53.956
2004-04-14	3	53.956	53.956	53.956	53.956
2004-04-14	4	53.956	53.956	53.956	53.956
2004-04-14	5	53.956	53.956	53.956	53.956
2004-04-14	6	53.956	53.956	53.956	53.956
2004-04-14	7	53.956	53.956	53.956	53.956
2004-04-14	8	53.956	53.956	53.956	53.956
2004-04-14	9	53.956	53.956	53.956	53.956
?004-04-14	10	57.156	59.025	68.4	53.956
2004-04-14	11	56.133	56.575	57.156	56.133

Record of Odor Test

1	$\overline{}$	1	
l	1,	1	
		J	

DATE         % GAS IN AIR         LBS/ MMCF         LOCATION OF POINT         LOCATION OF LOCATION         TYPE OF OF TEST           4-14-04         .09         .50         W.MEDWAY         WALPOLE         NATURAL           4-15-04         .09         .55         BROCKTON         HOLBROOK         "           4-15-04         .09         .55         BROCKTON         EASTON         "           4-15-04         .09         .55         BROCKTON         DUXBURY         "           4-15-04         .09         .55         BROCKTON         EASTON         "           4-15-04         .09         .55         BROCKTON         SCITUATE         "           4-28-04         .09         .55         BROCKTON         SCITUATE         "           4-28-04         .09         .55         BROCKTON         BRIDGEWATER         "           4-28-04         .10         .50         W.MEDWAY         BRARON         "           4-28-04         .10         .50         W.MEDWAY         WRENTHAM         "           4-28-04         .10         .50         W.MEDWAY         WALPOLE         "           4-28-04         .10         .50         W.MEDWAY <td< th=""><th></th><th></th><th></th><th></th><th>ODORIZATION RECORD</th><th>RECORD</th><th>ALCONTE OF A</th><th><u>z.</u></th></td<>					ODORIZATION RECORD	RECORD	ALCONTE OF A	<u>z.</u>
W GAS IN AIR LBS/ LOCATION OF LOCATION  MMCF HOINT WALPOLE  1.09 .50 W.MEDWAY WALPOLE  1.09 .55 BROCKTON HOLBROOK  1.09 .55 BROCKTON HALIFAX  1.09 .55 BROCKTON BRIDGEWATER  1.09 .55 BROCKTON BRIDGEWATER  1.09 .55 BROCKTON BRIDGEWATER  1.09 .47 CANTON SCITUATE  1.09 .47 CANTON SHARON  1.10 .50 W.MEDWAY FRANKLIN  1.10 .50 W.MEDWAY WRENTHAM  1.10 .50 W.MEDWAY WALPOLE  1.10 .50 W.MEDWAY WALPOLE  1.10 .50 W.MEDWAY WALPOLE  1.11 SHARON  1.12 SHARON  1.13 SHARON  1.14 SHARON  1.15 W.MEDWAY WALPOLE  1.16 .50 W.MEDWAY WALPOLE  1.17 SHARON  1.18 SHARON  1.19 .50 W.MEDWAY WALPOLE  1.19 .50 W.MEDWAY WALPOLE  1.19 .55 BROCKTON  1.11 MANSFFIELD  1.12 W.MEDWAY HANOVER  1.13 SHARON  1.14 SHARON  1.15 W.MEDWAY WALPOLE  1.15 BROCKTON  1.16 SHARON  1.17 SHARON  1.18 SHARON  1.19 SHARON  1.10 S							- 4	MONTH OF April 2004
% GAS IN AIR LBS/ LOCATION OF LOCATION MMCF MMCF POINT WALPOLE  .09 .50 W.MEDWAY WALPOLE  .09 .55 BROCKTON HOLBROOK  .09 .55 BROCKTON HALIFAX  .05 .55 BROCKTON BRIDGEWATER  .09 .55 BROCKTON BRIDGEWATER  .09 .47 CANTON BRIDGEWATER  .10 .50 W.MEDWAY FRANKLIN  .10 .50 W.MEDWAY WRENTHAM  .10 .50 W.MEDWAY WRENTHAM  .10 .50 W.MEDWAY WALPOLE  .09 .36 TAUNTON MANSFFIELD  .09 .55 BROCKTON HANOVER  .09 .55 BROCKTON MANSFFIELD  .09 .55 BROCKTON HANOVER  .09 .55 BROCKTON MANSFFIELD  .09 .55 BROCKTON HANOVER  .55 BROCKTON HANOVER			0	OORANT			- 1	
.09 .50 W.MEDWAY WALPOLE .09 .55 BROCKTON HOLBROOK .09 .36 TAUNTON EASTON .04 .55 BROCKTON DUXBURY .05 .55 BROCKTON HALIFAX .05 .55 BROCKTON SCITUATE .09 .55 BROCKTON E.BRIDGEWATER .09 .55 BROCKTON BRIDGEWATER .09 .47 CANTON BRIDGEWATER .10 .50 W.MEDWAY FRANKLIN .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFFIELD .09 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	DATE			LOCATION OF INJECTION POINT	LOCATION OF TEST	TYPE OF GAS		TESTER
.09         .55         BROCKTON         HOLBROOK           .09         .36         TAUNTON         EASTON           .04         .55         BROCKTON         DUXBURY           .05         .55         BROCKTON         HALIFAX           .05         .55         BROCKTON         SCITUATE           .09         .55         BROCKTON         SERIDGEWATER           .09         .55         BROCKTON         BRIDGEWATER           .09         .47         CANTON         BRIDGEWATER           .09         .47         CANTON         BRIDGEWATER           .10         .50         W.MEDWAY         FRANKLIN           .10         .50         W.MEDWAY         WRENTHAM           .10         .50         W.MEDWAY         WALPOLE           .10         .50         W.MEDWAY         WALPOLE           .09         .50         W.MEDWAY         WALPOLE           .09         .50         W.MEDWAY         WALPOLE           .09         .50         W.MEDWAY         FOXBORO           .04         .55         BROCKTON         NORWELL	4-14-04	.09	.50	W.MEDWAY	WALPOLE	NATURAL	1 1	HANNON
.09 .36 TAUNTON EASTON .04 .55 BROCKTON DUXBURY .05 .55 BROCKTON HALIFAX .05 .55 BROCKTON SCITUATE .09 .55 BROCKTON E.BRIDGEWATER .09 .55 BROCKTON BRIDGEWATER .09 .47 CANTON RANDOLPH .10 .50 W.MEDWAY FRANKLIN .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFFIELD .04 .55 BROCKTON NORWELL	4-15-04	.09	.55	BROCKTON	HOLBROOK	п	100	HANNON
.04 .55 BROCKTON DUXBURY .05 .55 BROCKTON HALIFAX .05 .55 BROCKTON SCITUATE .09 .55 BROCKTON E.BRIDGEWATER .09 .55 BROCKTON BRIDGEWATER .09 .47 CANTON SHARON .10 .50 W.MEDWAY FRANKLIN .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFIELD .09 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-15-04	.09	.36	TAUNTON	EASTON	e		HANNON
.05 .55 BROCKTON HALIFAX .05 .55 BROCKTON SCITUATE .09 .55 BROCKTON EBRIDGEWATER .09 .55 BROCKTON BRIDGEWATER .09 1.14 SHARON SHARON .10 .50 W.MEDWAY FRANKLIN .10 .50 W.MEDWAY BELLINGHAM .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WALFOLK .10 .50 W.MEDWAY WALFOLE .09 .36 TAUNTON MANSFIELD .09 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-15-04	.04	.55	BROCKTON	DUXBURY	11		BATCHELOR
.05 .55 BROCKTON SCITUATE .09 .55 BROCKTON E.BRIDGEWATER .09 .55 BROCKTON BRIDGEWATER .09 1.14 SHARON SHARON .10 .50 W.MEDWAY FRANKLIN .10 .50 W.MEDWAY BELLINGHAM .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WALFOLK .10 .50 W.MEDWAY WALFOLE .09 .36 TAUNTON MANSFIELD .09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-16-04	.05	.55	BROCKTON	HALIFAX	t.		BATCHELOR
.09 .55 BROCKTON E.BRIDGEWATER .09 .55 BROCKTON BRIDGEWATER .09 .114 SHARON SHARON .09 .47 CANTON RANDOLPH .10 .50 W.MEDWAY FRANKLIN .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY WALPOLE .10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFFIELD .09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON NORWELL	4-23-04	.05	.55	BROCKTON	SCITUATE	н		BATCHELOR
1.14 SHARON SHARON 1.09 1.14 SHARON SHARON 1.09 4.7 CANTON RANDOLPH 1.10 50 W.MEDWAY FRANKLIN 1.10 50 W.MEDWAY WRENTHAM 1.10 50 W.MEDWAY NORFOLK 1.10 50 W.MEDWAY WALPOLE 1.09 36 TAUNTON MANSFFIELD 1.04 55 BROCKTON HANOVER 1.05 55 BROCKTON NORWELL	4-28-04	.09	.55	BROCKTON	E.BRIDGEWATER			HANNON
.09 .47 CANTON RANDOLPH .10 .50 W.MEDWAY FRANKLIN .10 .50 W.MEDWAY BELLINGHAM .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY NORFOLK .10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFIELD .09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON NORWELL	4-28-04	0.09	1 14	SHARON	SHARON	=		HANNON
.10 .50 W.MEDWAY FRANKLIN .10 .50 W.MEDWAY BELLINGHAM .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY NORFOLK .10 .50 W.MEDWAY NORFOLK .10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFFIELD .09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-28-04	.09	.47	CANTON	RANDOLPH			HANNON
.10 .50 W.MEDWAY BELLINGHAM .10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY NORFOLK .10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFIELD .09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-28-04	.10	.50	W.MEDWAY	FRANKLIN	11		BORKOWSKI
.10 .50 W.MEDWAY WRENTHAM .10 .50 W.MEDWAY NORFOLK .10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFIELD .09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-28-04	.10	.50	W.MEDWAY	BELLINGHAM	11	1	BORKOWSKI
.10 .50 W.MEDWAY NORFOLK .10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFIELD .09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-28-04	.10	.50	W.MEDWAY	WRENTHAM	Ħ		BORKOWSKI
.10 .50 W.MEDWAY WALPOLE .09 .36 TAUNTON MANSFFIELD .09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-28-04	.10	.50	W.MEDWAY	NORFOLK	н	- 3	BORKOWSKI
.09 .36 TAUNTON MANSFFIELD .09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-28-04	.10	.50	W.MEDWAY	WALPOLE	п		BORKOWSKI
.09 .50 W.MEDWAY FOXBORO .04 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-28-04	.09	.36	TAUNTON	MANSFFIELD	n		BORKOWSKI
.04 .55 BROCKTON HANOVER .05 .55 BROCKTON NORWELL	4-28-04	.09	.50	W.MEDWAY	FOXBORO	1		BORKOWSKI
.05 .55 BROCKTON	4-30-04	.04	.55	BROCKTON	HANOVER	n		BATCHELOR
	4-30-04	.05	.55	BROCKTON	NORWELL			BATCHELOR

Fire Investigation Summary Report

Case Number: 2004-117-0499

Controlling Case Number: None

Case Type: F30 Fire - Accidental

Report Creator: Mark P Varkas

Lead Investigator(s): Mark P Varkas Team: South

FIU Requested By: Chief Hartman, Dep. Chief Bailey from Walpole Fire Department

FIU Requested On:

Date and Time of 04/13/2004 at approximately 16:53 PM

Incident:

Address/ Location of 9 Rockwood Rd. Walpole, MA

Incident:

#### **Property Investigated**

Type of Investigation: Fire

Type of Property: Residential

#### **Protection Systems:**

Smoke Detector: Operational

Comments: Two story split level wood framed residence. The exterior of the home consisted

of wood shingles with an asphalt shingled roof. It should be noted that the owner had hired a contractor to vinyl side the home. The home owner was in the process of removing wood shingles and attaching a styrofoam insulation in preparation of the vinyl siding. The home owner, Jeffrey Preston, both discovered and reported the fire. The fire originated in a utility type room in the basement at the CD corner of the home. This room housed the gas fed furnace and hot water heater as well as the gas meter and regulator. Three Walpole Fire Fighters sustained injuries as the result of a natural gas explosion. All three were in the basement attempting to extinguish the fire when the explosion occurred.

#### Fire Source

Cause of Fire: Accidental

Ignition: See explanation section below.

Material Ignited: Available combustibles, wood and plastic shelving. Natural gas was involved in

this fire/explosion.

Explanation:

On Tuesday, April 13, 2004 at approx. 1653 hours the Walpole Fire Department received a report of a fire at 9 Rockwood Rd. The call was made by the home owner, Jeffrey Preston. Mr. Preston was home at the time of this incident. He both discovered and reported the fire. An alarm was struck and the Walpole Fire Department responded. Captain Smith, Walpole Fire, was in command of the first company to arrive at the fire site. Chief Hartman and Deputy Chief Bailey, Walpole Fire, took overall command of suppression operations upon their arrival at the scene.

The site of the alarm is a split level wood framed residence. The exterior of the home consisted of wood shingles with an asphalt shingled roof. There was a one car garage under at side A. There was a enclosed deck at side C. It should be noted that the home owner had contracted a company to have the home vinyl sided. The homeowner was removing wood shingles and attaching a styrofoam insulation to the exterior of the home in preparation for the vinyl siding. The fire originated in a utility type room in the basement at the CD corner. This room housed the gas fed furnace, hot water heater as well as the gas

meter and regulator. There also was a large stand up freezer and a small refrigerator in this room. Seconds after members of the Fire Department entered the basement there was a natural gas explosion which knocked several windows and the garage door out of place. The force of the explosion moved the side C wall of the home off of the foundation. Thee Walpole Fire Fighters who were in the basement at the time suffered non life threatening injuries.

Arriving units observed flames to be exiting a basement window at side C of the home in an overlapping fashion. This window was closest to the rear of the home and led to the aforementioned utility type room. Entry was made into the basement via the rear door. Seconds after applying water to the area of the fire there was an explosion. The fire for the most part was contained to this basement utility type room.

On the same date at approx. 1800 hours I received a call from Tpr. Stewart, the on call Officer, for the State Police Fire and Explosion Investigation Section. Tpr. Stewart advised me of the fire in Walpole and further advised me that the Walpole Fire Department was requesting an investigator respond in order to assist in the origin and cause investigation.

I did respond to the fire site and I met with Deputy Chief Bailey and Fire Fighter Headd. Deputy Chief Bailey and Fire Fighter Headd updated me as to the incident. Fire Fighter Headd as well as being a Fire Investigator for Walpole Fire was also on the first engine company to arrive at the fire site. Also present were representatives of Bay State Gas, as well as Paul Grieco of the Department of Telecommunications and Energy. Thomas Madigan, of EFI, Private Fire Investigation Company was also present. Thomas Madigan, (EFI), was representing Bay State Gas. The Walpole Building Inspector, Gus Brown was also on site. At this time we initiated an investigation into the origin and cause of this incident. As the result of this joint investigation this Officer is of the belief that this incident was accidental in nature and most probably the result of an object falling onto the regulator in the utility type room causing a small gas leak and fire. Due to the fire the gas leak increased resulting in the eventual explosion. The gas related items including the meter and regulator located in the utility room have been secured at the Walpole Fire Department pending further analysis in an effort to determine if a gas leak proceeded the fire. All interested parties will be contacted re this testing.

This Officer, Deputy Chief Bailey and Fire Fighter Headd had conversation with Jeffrey and Lois Preston. They told us that they reside at the home with their seven year old daughter and that Jeffrey was the only one home at the time of the incident. Jeffrey explained to us that they were going to have the home vinyl sided and in preparation of this work he was in the process of removing the wood shingles and attaching sheets of insulation to the home. He stated that he was working at the rear of the home, side C. He stated that he had just nailed up a sheet of insulation when he heard a hissing sound. He stated that he went into the basement and into the utility room and saw a small fire on the floor in the corner of the room behind the regulator. He stated that it was a small fire and that he did not see anything on the floor burning. He said that it looked like the cement was burning. He stated that there was no smoke and he did not smell anything. He stated that he went to get some water as he felt he could put the fire out. He stated that when he got back the fire had increased and he decided to call the Fire Department. Mr. Preston told us that he was working at the exterior wall of the utility room.

This investigation then proceeded into the home and traced fire damage from least damage to heaviest fire damage. This process led us to the aforementioned utility room at the CD corner of the home. Once in the room we again traced fire damage from least damage to heaviest fire damage which led us to the CD corner of this room behind the regulator and to the right of the freezer. All fire damage was directional to this corner of the room. The freezer was heavily damaged from direct flame impingement and heat on the side closest to this corner. There were small wooden shelves attached to the open studs on both walls in this corner. The shelving was heavily charred and had fallen off of the wall leaving only the brackets. There also was a large plastic shelving unit to the right of the regulator and under the window where first in Fire Fighters saw the flames. This plastic shelving unit sustained heavy fire damage. The damage appeared to be heavier on the side closest to the regulator. The gas meter and regulator sustained heavy fire damage. The floor joists above this corner sustained the heaviest charring and this charring lessened the further away from this corner we observed. Again it appeared that all fire damage

was directional to this corner. The hot water heater and furnace sustained damage from fire extension. The open flame from the hot water heater although not at the point of origin quite possibly could have been the ignition source if in fact a gas leak proceeded the fire.

This investigation sifted and cleared the corner of debris. This debris for the most part consisted of food products and paints that were being stored on the plastic and wooden shelving. This included several canned goods. We secured items that we located in the debris that we believed were related to the gas meter and or regulator.

It should be noted that we also secured any electrical wiring that we observed. We did observe a power strip that had melted into the rear of the freezer. This strip sat on the foundation behind the freezer and was plugged into an outlet on the side B wall. We noted that the freezer, the refrigerator and a stereo receiver were plugged into the strip. It should be noted that we observed numerous wires at ceiling level. State Electrical Investigator, Ed Noonan, responded to the scene and made observations of the wiring. He further documented the electrical panel and the service. It should be noted that the main feed into the panel had burnt away. This damage was from fire extension.

Paul Grieco had Bay State Gas run a check of the line from the street to the foundation of the home. This revealed no leaks. We did not feel running a test for leaks inside the basement at this time would help this investigation as the gas related components had suffered significant fire damage from the fire and or explosion. We did note a dent on top of the regulator.

The Walpole Fire Department posted a Fire Fighter at the fire site overnight in the event of any rekindles and or hot spots.

This investigation returned to the scene the next day re the furtherance of this investigation. Fire Fighter Headd and Cherella took us through the scene explaining their observations and actions in suppressing this fire. We cleared the utility room of any further debris. We looked at the motor section of the freezer and felt that any damage to this area of the freezer was from fire extension. We had a subsequent conversation with the Prestons. We brought them into the utility room and they told us that there was an approx. eight inch opening between the corner of the freezer and the plastic shelving. It was from this opening that they could see into the corner where the regulator and meter were. They both stated that there was nothing stored at floor level in this area as they kept this area clear because of the regulator and meter. It should be noted that the regulator sat approx. eighteen inches from both the side C and side D walls. It was further approx. eighteen inches off of the floor.

As mentioned earlier in this report the gas related components located in this corner of the basement have been secured at the Walpole Fire Department. The power strip and wiring was also secured. Paul Grieco is attempting to have the gas related items tested by an independent party in an effort to determine if a fire proceeded the gas leak or a gas leak proceeded the fire. All interested parties will be contacted if this testing is done.

All involved in this investigation agree as to the point of origin of this fire/explosion and further feel that further testing of the gas related components could possibly shed some light as to what came first the fire or the gas leak. This Officer, not speaking for all involved in the investigation is of the belief that it is conceivable that Mr. Preston while hammering nails into the side C wall knocked an item off of the wooden shelving which fell onto and damaged the regulator enough to cause a small gas leak. There were available ignition sources in close proximity to the regulator including the open flame from the hot water heater. Mr. Prestons statements of hearing a hissing noise and then observing a small fire with no odor and in his words no smoke would be consistent with this event occurring.

This Officer is requesting that this case be closed with an accidental fire cause. This Officer will submit a supplement report pending any testing done to the items secured.

#### Evidence

Gathered By: Fire Department

#### Description / Explanation / Comments:

Gas meter, regulator and piping feeds located in utility room at CD corner of basement.

Power strip and remaining wiring located behind freezer.

#### **Photos**

Taken By: Other (see comments)

#### Description / Explanation / Comments:

Sgt. Bennett - State Police Crime Scene Services.

Thomas Madigan - EFI

Walpole Fire Bay State Gas

#### K-9

K-9 Not Used

#### **Occupants**

See Report, See Report -- 9 Rockwood Rd. Walpole, MA 00000 DOB: Unknown, SSN: Unknown, Phone: Unknown

#### Injuries

Cherella, Brian, Walpole Fire Fighter -- Walpole Fire Department Walpole, MA 00000 DOB: Unknown, SSN: Unknown, Phone: Unknown, Injury Status: Injured -- Fire Fighter

Donoghue, Brian, Walpole Fire Fighter -- Walpole Fire Department Walpole, MA 00000 DOB: Unknown, SSN: Unknown, Phone: Unknown, Injury Status: Injured -- Fire Fighter

Smith, Steve, Walpole Fire Captain -- Walpole Fire Department Walpole, MA 00000 DOB: Unknown, SSN: Unknown, Phone: Unknown, Injury Status: Injured -- Fire Fighter

#### Owner

Preston, Jeffrey W. -- 9 Rockwood Rd. Walpole, MA 00000 DOB: 12-30-59,

Preston, Lois Z. -- 9 Rockwood Rd. Walpole, MA 00000 DOB: 02-15-59,

### Reported By

Preston, Jeffrey W. -- 9 Rockwood Rd. Walpole, MA 00000 DOB: 12-30-59,

### Discovered By

Preston, Jeffrey W. -- 9 Rockwood Rd. Walpole, MA 00000 DOB: 12-30-59,

#### Witnesses

No Known Witnesses