

Plainville, MA

# Whiting Pond Bypass Culvert at West Bacon St

*MassDOT P12007-973-MUN-BRI*

*June 2021*

## CULVERT EVALUATION REPORT

---



315 Norwood Park South  
2nd Floor  
Norwood, Massachusetts 02062  
781.255.1982  
[www.BETA-Inc.com](http://www.BETA-Inc.com)

# **Whiting Pond Bypass Culvert at West Bacon St**

Plainville, MA

*MassDOT P12007-973-MUN-BRI*

## **CULVERT EVALUATION REPORT**

---

Prepared by: **BETA GROUP, INC.**

Prepared for: Town of Plainville

June 2021

## TABLE OF CONTENTS

1.0	Project Locus.....	1
2.0	Objective of Report .....	2
3.0	Calculation Methods and Assumptions.....	2
4.0	Project Area Location and Culvert Description.....	2
5.0	Culvert Condition .....	3
6.0	Data Collection .....	3
7.0	HY-8 Model – Existing Culverts.....	4
8.0	Conclusions and Recommendations .....	7
8.1.	Structure .....	7
8.2.	Flood Impacts.....	7
8.3.	Cost Estimate .....	7

## LIST OF TABLES

Table 6-1: Data Sources .....	3
Table 6-2: Hydrologic Data .....	4
Table 7-1 Existing Crossing Summary Table.....	6

## LIST OF FIGURES

Figure 1-1: Project Locus – USGS .....	1
Figure 7-1 HY-8 Model Input Data.....	4
Figure 7-2 HY-8 Existing Model Overview.....	5
Figure 7-3 Existing West 6.75'x4.5' Barrel .....	5
Figure 7-4 Existing East 6.75'x4.5' Barrel.....	6


## LIST OF APPENDICES

Appendix A – Structures Inspection Field Report
Appendix B – Photo Survey
Appendix C – StreamStats Data
Appendix D – FEMA and FIS Study DATA
Appendix E – Hydrologic Data/Climate Change Adjustment
Appendix F – Order of Magnitude Construction Costs



## 1.0 PROJECT LOCUS

Figure 1-1: Project Locus – USGS



## 2.0 OBJECTIVE OF REPORT

This report is provided to document the existing condition, capacity and vulnerable of this culvert to climate change. It is meant to evaluate potential issues such structural stability and flooding issues associated with higher current rainfall depths. This information will be utilized to prioritize capital improvement projects for the protection of public infrastructure, roadway and utilities, potentially improve the environment and connectivity of the stream.

The culvert was analyzed for the 25- and 100-year storm events for capacity and flooding purposes

## 3.0 CALCULATION METHODS AND ASSUMPTIONS

The hydrologic and hydraulic flow calculations were completed stormwater runoff is analyzed using the following:

- Flood Insurance Study revised June 9, 2014
- Flood Insurance Rate Map Norfolk County, Massachusetts 25021C0339F effective July 16, 2015 provided by Federal Emergency Management Agency
- Culvert information was obtained via a field observation completed in May 2021.
- StreamStats flows data (workspace ID: MA20210504144106929000) (see Appendix C)
- HY-8 Culvert Hydraulic Analysis Program provided by the Federal Highway Administration
- Technical Paper No. 40 (TP-40) Rainfall Frequency Atlas of the United States
- NOAA Atlas 14 Point Precipitation Frequency Estimates

Note FEMA information for the outlets

## 4.0 PROJECT AREA LOCATION AND CULVERT DESCRIPTION

Plainville Pond has two outlets. The first is a culvert system located on the south side of the Pond with an inlet 54 inch wide by 72-inch-deep box that transitions to twin 30-inch RCPs that outlet into a stream off the southwest corner of the parking lot on the southwest quadrant of the intersection of South Street and West Bacon Street. The second is a dam control structure off Ten Mile River north of the Plainville Pond. FEMA labels the first outlet as Ten Mile River and the second as Whiting Pond Bypass. This evaluation is of the culvert that crosses West Bacon Street from the stream from the second outlet

Whiting Pond Bypass flows out of the north end of Plainville Pond, 840± ft south, then passes under West Bacon Street and then another 840± ft to Wetherells Pond.

This structure consists of a two-span granite masonry culvert, which was completed in 1844. The out-to-out length of the structure is approximately 45'-6" with 6'-9" wide spans, 4'-6" high. The pier has a width of about 3'-6". The depth of fill over the structure is about 6". The depth of flow at the time of inspection was approximately 8" at each entrance while flowing southward.

The roadway width from edge of pavement to edge of pavement is 29'-0". There is a 4'-6" wide sidewalk on the north side and a shoulder area on the south side. There is an entrance to a cemetery directly before the culvert, on the south side of the east approach

There are overhead wires on the north side. There is an elevated manhole present in the brush to the northeast side of the culvert (See Photo 13). Guardrail is present on the north side, while the south side

has a fence present over the culvert. The waterway on both sides contains some debris and heavy vegetation.

## 5.0 CULVERT CONDITION

The overall condition of the structure is fair with some deficiencies noted. There are voids, loose and/or missing mortar joints, and loose and/or missing chinking stones typical throughout. There is cracking and active leakage on the roof of the masonry slab, present in each span. The south side of the west span has a 1/8" wide crack that is fully through the clapper (Photo 12). There are voids along the water line at each abutment, with a 29" deep void at the northeast abutment corner (Photo 11). The northwest abutment corner has voids up to 27" deep and is slightly displaced up to 4" (Photo 10).

The pier also exhibits typical areas of voids, loose and/or missing mortar joints, and loose and/or missing chinking stones. There is a gap between the slab and the pier, measuring at 6" max. The wingwalls also have deteriorated mortar joints and loose and/or missing chinking stones.

The embankments on both sides have overgrowth into the channel. There is debris present throughout, which is worse in the west span (See Photo 9). At the south end of the pier there is a tree growing with vegetation blocking flow (See Photo 8).

The roadways at either approach are in good condition, but the roadway over the culvert is in poor condition. The roadway over the culvert is at a higher elevation than the approaches (Photo 15 and 16). This change in elevation creates a speed bump for travel over the structure. The north sidewalk is in poor condition with numerous cracks and settlement (Photo 16). The south shoulder area also has settlement (Photo 18). The safety rails over the structure are in poor condition. The guardrail on the north side is not secure throughout and exhibits corrosion at the base of the posts. The metal fence on the south side is heavily corroded and is leaning off towards the river.

## 6.0 DATA COLLECTION

The following are the data sources and hydrologic data use for this evaluation

Table 6-1: Data Sources

Data Type	Source	Details
Culvert Data	BETA Group, Inc. (2021)	Field Measurements
Structural Evaluation	BETA Group, Inc. (2021)	
Project Locus	USGS	
Aerial Mapping	Google Earth (2020)	
Flood Data	Flood Insurance Rate Map (FIRM) Zone AE –elevation 200	Community Panel No. 25021C 0339F
Stream Profile	FEMA – FIS Norfolk County, MA	Ten Mile River Flood Profile 208P
StreamStats Report	USGS (2020)	Workspace ID: MA20210504144936011000

**Table 6-2: Hydrologic Data**

Hydraulic Design Data			
Drain Area	3.32 sq. mi.	Design Flood Discharge	384 cfs*
Bank Full Width	23.3 ft	Design Flood Frequency	25-year
Base (100-year) Flood Data*			
Base Flood Discharge*	552 cfs*	Base Flood Elevation	199 (NGVD)
Flood of Record			
Discharge	Unknown	Maximum Elevation	Unknown
Frequency	Unknown	Date	March 1968

\*Adjusted for Climate Change

## 7.0 HY-8 MODEL – EXISTING CULVERTS

Field measurements were taken to develop a basic hydraulic model using HY-8 program. The results indicate that the combination of the two culverts is insufficient to convey the 25-year storm flows (384 cfs – Streamstats data modified for climate change). The following figures and table show that the road overtops during the design (25-year storm).

Note elevations are based on an assumed datum.

**Figure 7-1 HY-8 Model Input Data**

The screenshot shows the 'Crossing Data - Ten Mile River at West Bacon St' window. It is divided into two main panels: 'Crossing Properties' on the left and 'Culvert Properties' on the right. The 'Crossing Properties' panel has a 'Name' field set to 'Mile River at West Bacon St'. It contains three expandable sections: 'DISCHARGE DATA' with fields for Discharge Method (Minimum, Design, and Maximum), Minimum Flow (103.000 cfs), Design Flow (382.000 cfs), and Maximum Flow (552.000 cfs); 'TAILWATER DATA' with fields for Channel Type (Trapezoidal Channel), Bottom Width (16.000 ft), Side Slope (H:V) (3.000), Channel Slope (0.0003 ft/ft), Manning's n (0.035), Channel Invert Elevation (9.900 ft), and Rating Curve (View...); and 'ROADWAY DATA' with fields for Roadway Profile Shape (Constant Roadway Elevation), First Roadway Station (0.000 ft), Crest Length (28.000 ft), Crest Elevation (16.400 ft), and Roadway Surface (Paved). The 'Culvert Properties' panel has a list of culverts with 'West Barrel' and 'East Barrel' selected. It includes buttons for 'Add Culvert', 'Duplicate Culvert', and 'Delete Culvert'. Below this is another table with sections: 'CULVERT DATA' (Name: West Barrel, Shape: Concrete Box, Material: Concrete, Span: 6.750 ft, Rise: 4.500 ft, Embedment Depth: 0.000 in, Manning's n: 0.024, Culvert Type: Straight, Inlet Configuration: Square Edge (90°) Headwall, Inlet Depression?: No); and 'SITE DATA' (Site Data Input Option: Culvert Invert Data, Inlet Station: 146.500 ft, Inlet Elevation: 10.000 ft, Outlet Station: 100.000 ft).



Figure 7-2 HY-8 Existing Model Overview






Figure 7-3 Existing West 6.75'x4.5' Barrel



**Figure 7-4 Existing East 6.75'x4.5' Barrel**



**Table 7-1 Existing Crossing Summary Table**

Headwater Elevation (ft)	Total Discharge (cfs)	West Barrel Discharge (cfs)	East Barrel Discharge (cfs)	Roadway Discharge (cfs)	Iterations
13.09	103.00	74.14	74.14	0.00	2
13.10	147.90	74.68	74.68	0.00	36
14.29	192.80	128.82	128.82	0.00	3
14.29	237.70	128.84	128.84	0.00	18
14.54	282.60	141.36	141.36	0.00	7
15.60	327.50	196.63	196.63	0.00	3
15.60	372.40	196.64	196.64	0.00	19
15.60	382.00	196.64	196.64	0.00	10
16.63	462.20	235.12	235.12	4.89	7
16.93	507.10	246.76	246.76	12.90	5
17.23	552.00	257.57	257.57	37.32	6
16.40	452.75	226.37	226.37	0.00	Overtopping

FEMA Flood maps indicate that the flood elevation is above the road elevation and equal on both sides of the road. The outlet to the downstream lake is the controlling restriction for the 100-year storm event.

## 8.0 CONCLUSIONS AND RECOMMENDATIONS

### 8.1. STRUCTURE

The overall condition of the structure is fair and the roadway over the culvert is poor. Based on the 2019 MassDOT report and the recent inspection findings, BETA recommends that the following items be addressed:

- Replace the roof slab to lower the roadway elevation over the structure to align with the approach roadway elevations. The existing hydraulic opening should remain.
- Replace the north sidewalk as it is heavily fragmented and allows water to leak into the structure. This should be done to preserve the integrity of the substructure.
- The north guardrail and the south fence should be replaced with a crash tested guardrail to maintain safety conditions.
- Fill in all voids in the masonry abutments, pier, and wingwalls.
- Replace all missing and/or loose chinking stones in the masonry abutments, pier, and wingwalls.
- Repoint all masonry joints to the masonry abutments, pier, and wingwalls.
- Scale back vegetation and remove debris in river on both sides to focus and control water flow.

Inspections should be conducted at intervals not exceeding 12 months to monitor overall culvert conditions.

### 8.2. FLOOD IMPACTS

The flood elevations are impacted by the elevation of Wetherellis Pond and the associated dam controls. This evaluation did not consider impacts associated with the dam outlet.

If there is adequate outlet capacity to the Wetherillis dam the HY-8 model indicates that the existing culverts are of sufficient size to convey the design storm (25 year) without over topping the road.

The culvert cannot convey the 100-year storm event flows without overtopping the road.

### 8.3. COST ESTIMATE

#### BUDGETARY COST ESTIMATE

##### Repairs

Construction:	\$180,000
Engineering:	\$45,000
Total:	\$225,000



# **APPENDIX A**

## **Structures Inspection Field Report**

---

# Town of Plainville, Massachusetts

## Bridge/Culvert Inspection Checklist

P-12-007

### General:

Street Name: West Bacon Street Waterway: Whiting Pond Bypass Culvert ID: P-12-007

### Inspectors:

Name: Peter Kotowski Position: Senior Structural Engineer  
Name: Brandon Nelson Position: Staff Engineer  
Name: Position:

### Inspection Conditions:

Date: 5/12/2021 Weather: Sunny Temp: 59°F

### General Information:

Bridge Type: 2-Span Granite Block Construction Date: 1844  
Hydraulic Opening Height (Feet): 4'-7" Out-To-Out Length (Feet): 17  
Hydraulic Opening Width/Span Length (Feet): (2) 6'-9" Spans = 13'-6" (Total) Depth of Fill Over Culvert Inches: 6"  
Depth of Flow During Inspection: 8" Direction of Flow: South  
Utilities Carried By Structure: Sewer & Water  
Drainage Structures: Catch Basin in SE Approach

Recommendations: Replace roof slab to improve vert. clearance; Replace north sidewalk; install crash-tested guard rail, fill masonry voids, replace chinking stones, repoint, remove overgrown veg.

### Abutments/Culvert Sidewalls:

North Sidewall: NA

South Sidewall: NA

Center Pier: Typ. Voids at waterline; Missing and loose chinking stone (typical); 29" deep void @ NE corner

Channel Walls: Typ. Voids at waterline; Missing and loose chinking stone (typical); 27" deep void @ NW corner

Abutment North Sidewall Rating: NA Abutment South Sidewall Rating: NA

Center Pier Rating: 6 Channel Wall Rating: 6

### Superstructure/Culvert Roof:

Condition Notes: Active water leakage & staining typical in both barrels; full width crack in west barrel (no stone movement)

Rating: 5

### Culvert Floor/Channel

Scour: Debris: Floor/Channel Rating: 5

Floor/Channel Notes: Minor scour noted; undercuts of embankment; overgrown veg.; minor stream aggradation in west barrel

# Town of Plainville, Massachusetts

## Bridge/Culvert Inspection Checklist

P-12-007

### Training/Wingwalls:

North East Wall:	Wingwall	North West Wall Type:	Masonry	North West Wall Rating:	6
North East Wall:	Loose/Missing chinking stone & mortart detioration is typical				
North West Wall:	Wingwall	North West Wall Type:	Masonry	North West Wall Rating:	6
North West Wall:	Loose/Missing chinking stone & mortart detioration is typical				
South East Wall:	Wingwall	South East Wall Type:	Masonry	South East Wall Rating:	6
South East Wall:	Loose/Missing chinking stone & mortart detioration is typical				
South West Wall:	Wingwall	South West Wall Type:	Masonry	South West Wall Rating:	6
South West Wall:	Loose/Missing chinking stone & mortart detioration is typical				
Head Wall:	NA	Head Wall Type:	NA	Head Wall Rating:	NA
Head Wall Notes:	NA				

### Roadway Condition:

Culvert/Bridge Roadway Condition:	N. Sidewalk widespread cracking; Minor cracking	Culvert/Roadway (Feet):	29.0'
Culvert/Bridge Roadway Settlement:	Raised over structure; N. Sdwk settlement	Culvert/Roadway Rating:	4
Culvert/Bridge Roadway Alignment:	Straight		
North Roadway Approach Condition:	NA	North Roadway (Feet):	NA
North Roadway Approach Settlement:	NA	North Roadway Rating:	NA
North Roadway Approach Alignment:	NA		
South Roadway Approach Condition:	NA	South Roadway (Feet):	NA
South Roadway Approach Settlement:	NA	South Roadway Rating:	NA
South Roadway Approach Alignment:	NA		
East Roadway Approach Condition:	Good - Newly Paved	East Roadway (Feet):	29.0'
East Roadway Approach Settlement:	NA - newly paved	East Roadway Rating:	7
East Roadway Approach Alignment:	Entrance to cemetary		
West Roadway Approach Condition:	Good - Newly Paved	West Roadway (Feet):	29.0'
West Roadway Approach Settlement:	NA - Newly Paved	West Roadway Rating:	7
West Roadway Approach Alignment:	Straight		

### Safety Barrier

Bridge Rail Type:	Metal Pipe
Bridge Rail Condition:	Poor - Hvy corr. of bolts & Conn's.; S. rail leaning; Unstable
Bridge Rail Rating:	1
Approach Rail Notes:	No transitions; N. barrier non-standard & in poor condition





## **APPENDIX B**

### **Photo Survey**

---



Photo 1 Looking Southwest: North Bridge Elevation



Photo 2 Looking Southwest: Center Pier at North Side





Photo 3 Looking South: West Span



Photo 4 Looking South: East Span





Photo 5 Looking West: Northwest Wingwall



Photo 6 Looking South: Northeast Wingwall





Photo 7 Looking North: South Bridge Elevation



Photo 8 Looking South: Center Pier at South Side





Photo 9 Looking North: West Barrel



Photo 10 Looking West: Northwest Corner Voids





Photo 11 Looking East: Northeast Corner Voids



Photo 12 Looking North: Crack in Roof on South Side of West Span





Photo 13 Looking Southeast: Elevated Manhole



Photo 14 Looking East: West Approach





Photo 15 Looking West: East Approach



Photo 16 Looking East: North Sidewalk Area





Photo 17 Looking Northeast: North Railing



Photo 18 Looking South: South Railing

## **APPENDIX C**

### **StreamStats Data**

---




# West Bacon St Culvert - StreamStats Report

Region ID: MA

Workspace ID: MA20210504144936011000

Clicked Point (Latitude, Longitude): 42.00280, -71.33846

Time: 2021-05-04 10:49:52 -0400



## Basin Characteristics

Parameter Code	Parameter Description	Value	Unit
DRNAREA	Area that drains to a point on a stream	3.32	square miles
ELEV	Mean Basin Elevation	280	feet
LC06STOR	Percentage of water bodies and wetlands determined from the NLCD 2006	7.46	percent
BSLDEM10M	Mean basin slope computed from 10 m DEM	5.893	percent

## Peak-Flow Statistics Parameters [Peak Statewide 2016 5156]

Parameter Code	Parameter Name	Value	Units	Min Limit	Max Limit
DRNAREA	Drainage Area	3.32	square miles	0.16	512
ELEV	Mean Basin Elevation	280	feet	80.6	1948
LC06STOR	Percent Storage from NLCD2006	7.46	percent	0	32.3

## Peak-Flow Statistics Flow Report [Peak Statewide 2016 5156]

PII: Prediction Interval-Lower, Plu: Prediction Interval-Upper, SEp: Standard Error of Prediction, SE: Standard Error (other -- see report)

Statistic	Value	Unit	PII	Plu	SEp
50-percent AEP flood	103	ft <sup>3</sup> /s	52.6	202	42.3
20-percent AEP flood	171	ft <sup>3</sup> /s	86.2	339	43.4
10-percent AEP flood	224	ft <sup>3</sup> /s	110	455	44.7
4-percent AEP flood	302	ft <sup>3</sup> /s	144	635	47.1
2-percent AEP flood	366	ft <sup>3</sup> /s	169	795	49.4
1-percent AEP flood	435	ft <sup>3</sup> /s	194	974	51.8
0.5-percent AEP flood	510	ft <sup>3</sup> /s	221	1180	54.1
0.2-percent AEP flood	617	ft <sup>3</sup> /s	255	1490	57.6

*Peak-Flow Statistics Citations*

**Zarriello, P.J.,2017, Magnitude of flood flows at selected annual exceedance probabilities for streams in Massachusetts: U.S. Geological Survey Scientific Investigations Report 2016–5156, 99 p. (<https://dx.doi.org/10.3133/sir20165156>)**

## Bankfull Statistics Parameters [Bankfull Statewide SIR2013 5155]

Parameter Code	Parameter Name	Value	Units	Min Limit	Max Limit
DRNAREA	Drainage Area	3.32	square miles	0.6	329
BSLDEM10M	Mean Basin Slope from 10m DEM	5.893	percent	2.2	23.9

## Bankfull Statistics Flow Report [Bankfull Statewide SIR2013 5155]

PII: Prediction Interval-Lower, Plu: Prediction Interval-Upper, SEp: Standard Error of Prediction, SE: Standard Error (other -- see report)

Statistic	Value	Unit	SEp
Bankfull Width	23.3	ft	21.3
Bankfull Depth	1.31	ft	19.8
Bankfull Area	30.2	ft^2	29
Bankfull Streamflow	79.4	ft^3/s	55

*Bankfull Statistics Citations*

**Bent, G.C., and Waite, A.M.,2013, Equations for estimating bankfull channel geometry and discharge for streams in Massachusetts: U.S. Geological Survey Scientific Investigations Report 2013–5155, 62 p., (<http://pubs.usgs.gov/sir/2013/5155/>)**

USGS Data Disclaimer: Unless otherwise stated, all data, metadata and related materials are considered to satisfy the quality standards relative to the purpose for which the data were collected. Although these data and associated metadata have been reviewed for accuracy and completeness and approved for release by the U.S. Geological Survey (USGS), no warranty expressed or implied is made regarding the display or utility of the data for other purposes, nor on all computer systems, nor shall the act of distribution constitute any such warranty.

USGS Software Disclaimer: This software has been approved for release by the U.S. Geological Survey (USGS). Although the software has been subjected to rigorous review, the USGS reserves the right to update the software as needed pursuant to further analysis and review. No warranty, expressed or implied, is made by the USGS or the U.S. Government as to the functionality of the software and related material nor shall the fact of release constitute any such warranty. Furthermore, the software is released on condition that neither the USGS nor the U.S. Government shall be held liable for any damages resulting from its authorized or unauthorized use.

USGS Product Names Disclaimer: Any use of trade, firm, or product names is for descriptive purposes only and does not imply endorsement by the U.S. Government.

Application Version: 4.5.2

StreamStats Services Version: 1.2.22

NSS Services Version: 2.1.1

## **APPENDIX D**

### **FEMA and FIS Study Information**

---

## FEMA FLOOD INSURANCE STUDY (FIS) INFORMATION

Flooding in the Town of Plainville can occur anytime; however, major flooding usually occurs during the spring as a result of heavy rain combined with snowmelt or late summer-early fall due to tropical storms. The greatest flood in the memory of town officials occurred in March 1968. During that flood, overflow from Turnpike Lake flooded sections of U. S. Route 1 and Shepard Street, and the Ten Mile River flooded part of West Bacon Street.

In Plainville, with the exception of the Ten Mile River and the Whiting Pond Bypass, peak discharges for floods with 10-, 2-, 1- and 0.2-percent-annual-chance recurrence intervals were estimated by use of formula developed by S. William Wandle, Jr. (Reference 90). Discharges for the Ten Mile River and the Whiting Pond Bypass were estimated by the USDA NRCS during the preparation of an Federal Insurance Agency (currently FEMA) Type 15 study of the adjoining Town of North Attleborough (Reference 116). Near the corporate limits, peak discharge of the Ten Mile River does not relate to drainage area because of flow diversion into the Whiting Pond Bypass.

With the exception of the Ten Mile River and the Whiting Pond Bypass, water-surface elevations of floods of the selected recurrence intervals in Plainville were computed using USGS step-backwater computer program E431 (Reference 160). The elevations for the Ten Mile River and the Whiting Pond Bypass were computed at the time of the USDA NRCS Flood Insurance Study of the Town of North Attleboro (Reference 116). Elevations obtained for the Ten Mile River using USDA NRCS field data in the USGS computer program verify those obtained by the USDA NRCS. The flood elevations of Lake Mirimichi were used as starting elevations for Turtle Brook. The starting elevations on Brook No. 1 were determined by dam computations.


FLOODING SOURCE AND LOCATION	DRAINAGE AREA (SQUARE MILES)	PEAK DISCHARGES (CUBIC FEET PER SECOND)			
		10-PERCENT ANNUAL CHANCE	2-PERCENT ANNUAL CHANCE	1-PERCENT ANNUAL CHANCE	0.2-PERCENT ANNUAL CHANCE
SUCKER BROOK					
At confluence with Massapoag Lake	1.10	63	92	104	141
TEN MILE RIVER					
At Plainville downstream corporate limits	4.23	86	150	200	390
At confluence with Whiting Pond Bypass	3.48	94	180	230	420



# National Flood Hazard Layer FIRMeTte



71°20'30"W 42°0'19"N



0 250 500 1,000 1,500 2,000 Feet 1:6,000

Basemap: USGS National Map: Orthoimagery: Data refreshed October, 2020

## Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS		Without Base Flood Elevation (BFE) Zone A, V, A99
		With BFE or Depth Zone AE, AO, AH, VE, AR
		Regulatory Floodway
OTHER AREAS OF FLOOD HAZARD		0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile Zone X
		Future Conditions 1% Annual Chance Flood Hazard Zone X
		Area with Reduced Flood Risk due to Levee. See Notes. Zone X
		Area with Flood Risk due to Levee Zone D
OTHER AREAS		NO SCREEN Area of Minimal Flood Hazard Zone X
		Effective LOMRs
GENERAL STRUCTURES		Area of Undetermined Flood Hazard Zone D
		Channel, Culvert, or Storm Sewer
		Levee, Dike, or Floodwall
OTHER FEATURES		20.2 Cross Sections with 1% Annual Chance
		Water Surface Elevation
		Coastal Transect
		Base Flood Elevation Line (BFE)
		Limit of Study
MAP PANELS		Jurisdiction Boundary
		Coastal Transect Baseline
		Profile Baseline
		Hydrographic Feature
		Digital Data Available
		No Digital Data Available
		Unmapped



The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 6/9/2021 at 4:13 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

# **APPENDIX E**

## **Hydrologic Data/Climate Change Adjustment**

---

**Hydrologic Data**

StreamStats flows data (workspace ID: MA20210504144936011000) will be used to evaluate the culvert which are listed as follows:

10 Yr = 224 cfs

25 Yr. = 302 cfs

50 Yr = 366 cfs

100 Yr = 435 cfs

**Climate Change Adjustment**



To adjust for climate change, BETA incorporated an adjustment of the StreamStats peak flow data using current (NOAA Atlas 14) rainfall data compared to the outdated TP-40 data.



**Accommodate Climate Change/Resiliency  
Adjust Streamstats/FEMA FIS Flow Data  
By Ratio of TP 40 to NOAA Atlas 14 Rainfall Data**



	1	2	3	4	5	
Storm Event (Yr)	Rainfall TP-40 (in)	$\Delta$	Flow Data (Streamstats) (cfs)	$\Delta$	Rainfall Atlas-14 (in)	Adjusted Flow (cfs)
2	3.25		103		3.4	114
		0.9		68		
5	4.15		171		4.38	194
		0.54		53		
10	4.69		224		5.2	271
		0.85		78		
25	5.54		302		6.32	384
		0.61		64		
50	6.15		366		7.15	472
		0.65		69		
100	6.80	3.55	435	332	8.05	552

$$\text{Adjusted Flow} = 3 + ((5-1)/2) \times 4$$











NOAA Atlas 14, Volume 10, Version 3  
Location name: Plainville, Massachusetts, USA\*  
Latitude: 42.0193°, Longitude: -71.3159°  
Elevation: 199.23 ft\*\*  
\* source: ESRI Maps  
\*\* source: USGS



### POINT PRECIPITATION FREQUENCY ESTIMATES

Sanja Perica, Sandra Pavlovic, Michael St. Laurent, Carl Trypaluk, Dale Unruh, Orlan Wilhite

NOAA, National Weather Service, Silver Spring, Maryland

[PF\\_tabular](#) | [PF\\_graphical](#) | [Maps\\_&\\_aerials](#)

### PF tabular

PDS-based point precipitation frequency estimates with 90% confidence intervals (in inches) <sup>1</sup>										
Duration	Average recurrence interval (years)									
	1	2	5	10	25	50	100	200	500	1000
5-min	0.314 (0.249-0.393)	0.386 (0.306-0.483)	0.503 (0.397-0.632)	0.600 (0.471-0.758)	0.734 (0.556-0.970)	0.834 (0.619-1.13)	0.940 (0.677-1.32)	1.06 (0.719-1.52)	1.24 (0.808-1.84)	1.40 (0.884-2.10)
10-min	0.445 (0.353-0.557)	0.547 (0.433-0.684)	0.713 (0.563-0.896)	0.850 (0.667-1.07)	1.04 (0.788-1.38)	1.18 (0.876-1.60)	1.33 (0.959-1.87)	1.51 (1.02-2.15)	1.76 (1.14-2.61)	1.98 (1.25-2.98)
15-min	0.524 (0.415-0.655)	0.643 (0.509-0.805)	0.838 (0.661-1.05)	1.00 (0.784-1.26)	1.22 (0.927-1.62)	1.39 (1.03-1.88)	1.57 (1.13-2.20)	1.77 (1.20-2.53)	2.07 (1.35-3.07)	2.33 (1.47-3.51)
30-min	0.723 (0.574-0.905)	0.891 (0.706-1.12)	1.17 (0.920-1.46)	1.39 (1.09-1.76)	1.71 (1.29-2.26)	1.94 (1.44-2.62)	2.19 (1.58-3.08)	2.48 (1.68-3.54)	2.91 (1.89-4.30)	3.26 (2.07-4.92)
60-min	0.923 (0.732-1.16)	1.14 (0.902-1.43)	1.49 (1.18-1.87)	1.79 (1.40-2.26)	2.19 (1.66-2.90)	2.49 (1.85-3.37)	2.81 (2.03-3.95)	3.19 (2.15-4.55)	3.74 (2.42-5.53)	4.20 (2.66-6.33)
2-hr	1.18 (0.942-1.46)	1.47 (1.18-1.83)	1.96 (1.56-2.44)	2.36 (1.86-2.95)	2.91 (2.22-3.82)	3.31 (2.48-4.46)	3.75 (2.73-5.27)	4.28 (2.91-6.07)	5.09 (3.32-7.46)	5.78 (3.67-8.62)
3-hr	1.37 (1.10-1.69)	1.71 (1.37-2.12)	2.27 (1.82-2.82)	2.74 (2.17-3.42)	3.38 (2.60-4.43)	3.86 (2.90-5.17)	4.37 (3.20-6.11)	5.00 (3.41-7.04)	5.95 (3.89-8.67)	6.77 (4.32-10.1)
6-hr	1.78 (1.44-2.18)	2.21 (1.79-2.71)	2.90 (2.34-3.57)	3.48 (2.78-4.30)	4.27 (3.30-5.54)	4.86 (3.68-6.45)	5.49 (4.04-7.60)	6.26 (4.29-8.74)	7.43 (4.89-10.7)	8.43 (5.40-12.4)
12-hr	2.31 (1.89-2.81)	2.81 (2.29-3.42)	3.63 (2.95-4.43)	4.31 (3.48-5.29)	5.24 (4.08-6.73)	5.94 (4.52-7.79)	6.69 (4.94-9.12)	7.57 (5.22-10.5)	8.89 (5.88-12.7)	10.0 (6.44-14.6)
24-hr	2.80 (2.30-3.37)	3.40 (2.79-4.10)	4.38 (3.59-5.30)	5.20 (4.23-6.32)	6.32 (4.96-8.05)	7.15 (5.49-9.31)	8.05 (5.99-10.9)	9.12 (6.33-12.5)	10.7 (7.12-15.2)	12.1 (7.82-17.4)
2-day	3.16 (2.32-4.77)	3.89 (2.99-5.65)	5.09 (4.00-7.10)	6.09 (4.80-7.73)	7.45 (5.80-9.43)	8.47 (6.56-11.0)	9.57 (7.40-12.0)	10.9 (7.82-14.8)	13.0 (8.88-18.3)	14.8 (10.82-21.2)

## **APPENDIX F**

# **Order of Magnitude Construction Costs**

---





JOB  
CALCULATED BY  
CHECKED BY  
DESCRIPTION

Plainville	No.	7624
TMW	DATE	6/25/2021
	DATE	
Cost Analysis	SHEET NO.	

# West Bacon Street over Whiting Pond Bypass

## Rehabilitation:

### Roof Slab Replacement

Slab Length over Bridge = 45.50 sf  
 Slab Width = 17.00 sf  
 Slab Thickness = 1.00 sf  
 Volume of Slab = 773.50 cf  
 = 28.65 cy  
 Say = 29.00  
 Assumed Cost for Concrete Slab = \$1,500.00 Per CY

Roof Slab = \$43,500

Assume 100lbs Steel / CY = 2900.00 LBS  
 Steel Reinforcing Unit Cost (Item 910.) = \$3.00 Per LB

Reinforcing Cost = \$8,700

### Masonry Repairs (Replace Stones, Repoint Joints, Fill Voids)

Approximate Area of Abutment Faces= 409.50 sf  
 Approximate Area of Pier Faces= 409.50 sf  
 Approximate Area of Wingwall Faces= 100.00  
 Approximate Depth of Repairs = 1.00 ft  
 Total Area = 34.04 cy  
 Repair Area in CY (67% due to fair condition) = 22.69 cy  
 Stone Masonry Wall in Cement Mortar (Item 685.) = \$900.00 Per CY

Masonry Repairs = \$20,422

Bridge Railing = \$150.00 Per LF  
 Railing Length = 109.00 LF

Bridge Rail = \$16,350

Roadway Work = 30.00% of culvert cost

Roadway Work = \$26,692

LS Cost of Water Diversion = \$10,000.00 LS

Water Diversion = \$10,000

Contingency & Misc. Items = 30.00% of construction cost

Contingency & Misc. Items = \$37,699

Mobilization/Demobilization = 10.00% of total construction cost

Mobilization/Demobilization = \$16,336

Cost of Repairs = \$179,699

Call = \$180,000

25% Engineering Cost = \$45,000

TOTAL COST = \$225,000