

**Picture 1**



**Stored Materials Blocking a Unit Ventilator**

**Pitcher 2**



**Fresh Air Intakes Located Below Grade**

**Picture 3**



**Exhaust Vents Located In Closet Ceiling**

**Picture 4**




**Exhaust Fan in Copy Room**

**Picture 5**



**Unit Exhaust Ventilator**

**Picture 6**



**Water Damage Due To Window Leaks**

**Picture 7**



**Water Damage Plaster through Air Conditioning Installation**

**Picture 8**



**Example of Damaged Plaster in Rear Area of Former Altar**

**Picture 9**



**Sump Pump in Nurse's Office Closet**

**Picture 10**



**Vent in Closet in Nurse's Office**

**Picture 11**



**Plants against Exterior Wall, West Building**

**Picture 12**



**Plants against Exterior Wall and Windows Systems, West Building**

**Picture 13**



**Plants Located At the Top of a Stairwell in the West Building**

**Picture 14**



**Unit Ventilator Installed Over Wall To Wall Carpeting**

**Picture 15**



**Hole in Downspout**

**Picture 16**



**Example of Water-Damage on Ceiling of the Copier Room**

**Picture 17**



**Water-Damage Around Skylight Outside Of Copier Room**

**Picture 18**



**Capped Drain in Copier Room**

**Picture 19**



**Example of Water-Damaged Sink Cabinet**

**Picture 20**



**Entrance to Crawlspace beneath the North Building in the Boiler Room**

**Picture 21**



**Hole in the Floor Around Heating Pipe Inside Of Unit Ventilator**

**Picture 22**



**Water Damaged Ceilings in the Top Floor of the South Building**

**Picture 23A**



**Plants Obstructing Unit Ventilator Fresh Air Intake**

**Picture 23B**



**Plants Obstructing Unit Ventilator Fresh Air Intake**

**Picture 24**



**Ivy Growth of the Exterior Wall of the South Building**

**Picture 25**



**Open Electrical Conduit in Unit Ventilator**

**Picture 26**



**Space in Wall of Room 25 and Crawlspace**

**Picture 27**



**Parapet That Forms the Library Roof**

**Picture 28**



**North Parapet Wall That Forms the Library Roof with Three Scuppers**

**Picture 29**



**South Parapet Wall That Forms the Library Roof with Two Scuppers**

**Picture 30**



**The Parapet Scupper That Empties Water onto the Lower Roof above Room 115, Note Patching In Roof Membrane**

**Picture 31**



**Library Balcony, View from Ground Level**

**Picture 32**



**Roof Of The Library Balcony, Note Staining Pattern On The Roof Membrane Indicating The Water Is Being Directed Toward The Building Exterior Wall**

**Pictures 33**



**Example of Copper Flashing On the West Building Roof**

**Picture 34**



**Roof Membrane On The East Building Attached To The Next Year Wall Of The North Building By Mechanical Fasteners, Note The Sealant Compound Installed Between The Seem Of The Metal Fasteners And Exterior Brick Wall**

**Picture 35**



**Exterior Brick Wall of the East Building, West Facing Exterior Wall**

**Picture 36**



**Photocopiers in the Copier Room**

**Picture 37**



**Filter Media in Metal Frame Installed Inside Unit Ventilators**

**Picture 38**



**Pet Bedding on Table and Wall To Wall Carpeting**

**Picture 39**



**Structure That Forms the Copier Room/Gymnasium Equipment Storage Room**

**Picture 40**



**Damaged Soffit of Copier Room/Gymnasium Equipment Storage Room where Birds were Observed Roosting**