

JANE PERLOY APPOINTED SECRETARY OF PUBLIC SAFETY

Governor Cellucci has appointed former high-ranking New York City police officer Jane Perlov as Secretary of Public Safety. Secretary Perlov officially took up her duties on January 18, 1999.

The BBRS welcomes Secretary Perlov and looks forward to working with her as we enter the new millennium.

JOSEPH LALLI APPOINTED ACTING COMMISSIONER OF PUBLIC SAFETY

Joseph Lalli has been appointed acting Commissioner of Public Safety by Governor Cellucci. Commissioner Lalli



was formerly Deputy Commissioner the of Department and also General Counsel to the Board of Buildina Regulations and Standards. Commissioner Lalli brings a wealth of experience and a unique perspective to the office of Commissioner. As a

practicing attorney, Mr. Lalli is a Town counsel and, as such, has first hand insight into development, zoning and public safety issues faced by municipalities. As General Counsel to the BBRS, Commissioner Lalli also has an excellent working knowledge of the State Building Code.

THE USE OF "WEDGES" ON DOORS EQUIPPED WITH AUTOMATIC CLOSING DEVICES

It is unfortunately all too common to see doors which are equipped with automatic closing devices wedged open with wooden wedges, rubber wedges, bricks, trash containers and the like. The doors are normally wedged open for purposes of facilitating movement of people in a building. Is this practice advisable?

Ordinarily, doors are not designed to close automatically. However, in some instances, a building's design or the building code may dictate that they do. It may appear cumbersome to have series of doors in the closed position since they may impede movement through a building. So why is it so important that the doors are not "held" or "wedged" open?

In addition to allowing occupants of a building to move from one space to another, open doors also provide an opportunity for smoke and other products of combustion to move freely throughout a building during a fire. These products of combustion can be highly toxic and can, very quickly, disorient, incapacitate and/or kill. The vast majority of fire fatalities result from inhalation of products of combustion.

The Massachusetts State Building Code, has historically required smoke enclosures and fire rated enclosures to provide passive resistance to the spread of fire and products of combustion. Containment of fire provides the valuable time necessary for occupants of a building to exit safely. However, fire or smoke resistive partitions are only as good as their weakest link. The Massachusetts State Building Code requires all penetrations or openings through fire separation walls



or smoke containment walls (including pipes, conduits and larger penetrations required for door openings), to maintain the fire or smoke resistive properties of the wall. Pipes and conduits must be firestopped: door openings must be provided with fire resistance rated doors. The fire or smoke partitions constitute a major component of a building's fire and life safety systems.

In order to maintain the fire resistive or smoke resistive properties of a wall, doors must be assured of being in the closed position in the event of a fire. The Massachusetts State Building Code therefore requires that such doors be equipped with self-closing devices (780 CMR 716.5 and 1015.4.1). These self-closing devices are intended to operate automatically and are not permitted to rely on the actions of an occupant, in particular, an occupant whose behavior in an emergency situation may not be predictable. Doors which are wedged open, have the potential for allowing rapid smoke spread throughout a building which can cause occupants who are remote from the fire to be quickly overcome by smoke.

For occupant convenience, the building code permits fire or smoke doors to be held in an open position, but only by appropriate use of APPROVED "hold open" devices. The Massachusetts State Building Code carefully regulates the use of such "hold open" devices and mandates that they release automatically upon activation of an automatic fire detector, a fire alarm or sprinkler system or loss of power to the device itself or loss of power to the building. Maintaining doors in an open position by the use of wooden (or other) wedges violates this fundamental life safety concept and represents a clear potential for disaster in a fire

CODEWORD - FIRE SEPARATION ASSEMBLY

A fire separation assembly is an assembly of materials, which is designed and constructed to resist the spread of fire for a specified period of time (ordinarily in hours or fractions of hours).

The components of the assembly need not necessarily be non-combustible - wood studs can be part of a fire rated assembly. (note, however, the construction type of the building will dictate whether the use of combustibles is permitted)

In order to assure that different fire separation assemblies are compared "apples for apples",

assemblies are constructed and tested using a standardized test methodology so that tests can be accurately replicated for each assembly, there allowing different assemblies to be compared under identical test conditions.

The standard for fire testing of assemblies referenced by the State Building Code is ASTM E119 $^{\left(1\right)}$

The test method requires that a material test assembly is subjected to a "controlled" fire - The temperature is required to follow a time-temperature curve, which is the same for all tests.

Time	Temperature			
	Fahrenheit	Centigrade		
5 minutes	1000	538		
10 minutes	1300	704		
30 minutes	1550	843		
1 hour	1700	927		
2 hours	1850	1010		
4 hours	2000	1093		
8 hours or over	2300	1260		

Time Temperature Curve (from ASTM E 119)

Thermocouples attached to the assembly at location specified in ASTM E119 record temperatures as the test proceeds. The test ends when the thermocouples reach a pre-defined temperature, specified in ASTM E119, or if burn through of the test sample occurs. The period between the start and end of the test is recorded in HOURS and the assembly is rated accordingly.

Assemblies, which have been independently tested for various hourly ratings, are listed in the UL Fire resistance directory and the US Gypsum GA 500.

(1) American Society for Testing and Materials ASTM E119 "Standard Test Methods for Fire Tests of Building Construction and Materials".

BBRS MEMBER PROFILE CHIEF WILLIAM V. DOLAN



This issue of *Codeword* profiles Chief William (Bill) V. Dolan of the North Andover Fire Department who is appointed to the Board of Buildir Regulations and Standards . the "Head of a Local Fire Department". Bill has been a member of the North Andover Fire Department since 1976 and rose to the rank of chief in 1982. Appointed to the BBRS in 1993 by Governor Weld, Bill also serves on the Fire Prevention Fire Protection Advisory Committee (FPFP) and the State Building Code Appeals Board.

Bill earned a Bachelor of Science degree in Fire Science Administration from Salem State College and is a Graduate of the National Fire Academy Executive Fire Officer Program. He presently serves on the board of directors of the Merrimac Valley Trauma Intervention Program and is a part time faculty member of the North Shore Community College, where he teaches an associates degree course in Fire Science.

Bill is an advocate of built-in fire protection" for all occupancies including residential fire protection systems - indeed, in 1992, he installed a residential sprinkler system in his own home.

Bill and his wife Colleen are the proud parents of son, Kyle and daughter, Kaitlyn. In his spare time, Bill enjoys hunting, fishing, walking, reading and skiing and is actively involved in local community projects and committees.

CONSOLIDATING CONCRETE

Consolidation (also often termed vibrating) of concrete is the act of removing excess air from concrete during placement, by means of manual and/or mechanical means. Air is inadvertently entrained into the concrete mix during batching and mixing and unless removed will adversely affect the strength and durability of the hardened concrete. Proper consolidation will densify the concrete and result in a strong durable product.

It is just as important to avoid over-consolidation of concrete as in doing so the larger aggregate portions will tend to separate from the smaller aggregates and cement paste resulting in a poorly graded product which will adversely effect the strength an durability of the hardened concrete.

Concrete mixes may be designed for increased frost resistance by the addition of controlled amounts of air into the mix. This is termed "air entrainment" and is achieved by means of special additives added to the concrete mix at the batching plant. For information of the proper methods of consolidating concrete refer to ACI (American Concrete Institute) 309R "Consolidation of Concrete"

DID YOU KNOW?

Concrete continues to gain strength during its lifetime. The strength of concrete is typically denoted by its cylinder strength in compression and is obtained by testing a cylinder of concrete to destruction in a special compression machine. The test result of importance is typically the 28-day strength. This is determined by testing a sample made from the concrete mix after curing under laboratory conditions for 28 days. Test results are reported in pounds per square inch (psi).

Laboratories who perform testing services are required to be licensed by the BBRS. There are currently 26 laboratories that are licensed to perform this service in Massachusetts. For a list visit the BBRS web Page at www.state.ma.us/bbrs and click on "BBRS Programs" then follow the prompts.

ATTORNEY GENERAL DISAPPROVES HEAT DETECTOR BY-LAW

On January 29, 1999 the Attorney General disapproved a by-law voted by the Town of Salisbury which sought to mandate heat detectors be installed in all new, one-andtwo family dwellings, in utility rooms, attached garages, attics and laundry rooms.

In disapproving this by-law, the Attorney General stated in part that;

"...Today, any town seeking fire safety regulations more restrictive than those currently imposed under the State Building Code must request that the State Board of Building Regulations and Standards adopt such a regulation. The Board will grant such a request only upon a finding, after conducting a public hearing, that more restrictive standards are reasonably necessary because of special conditions prevailing within such city or town and that such standards conform with accepted national and local engineering and fire prevention practices, with public safety and with the general purposes of a statewide building code.".....

DISCIPLINARY ACTIONS AGAINST RECEIPTERED (HOME IMPROVEMENT CONTRACTORS) The following Home Improvement Contractors were requested to appear before the Director of the HIC Program at publ hearings held pursuant to, MCI. 142A and 780 CMR RG. The designee for the Director of the Home Improveme. Contractors Registration Program issued the following administrative penalties.

NAME & ADDRESS	RE SPONISIBLE	RECHSTICATION	ADMINISTRATIME
	PE RSON	NUMBER	IPENALTY
13&J Sidling & Window, Inc.	Jossephi II undviigisenii	10/8117/5	Registarzitikom revolkad znul 99,000 panality
3381 Washington Sti.	- 		(Defenullicel)
Jamaica Alain, MA 02130			
Anexitas Cansitrucitian	Rinchannel Antarsitious	110121100	Submit new contract to BBRS and rainburse
17 Thayer Stinaeti			\$3000 ito Guerzmity Fund."
Hiingham, MA 02043			
Diymiriita Homme Imperovennianites	Domailel Ottico	1012531	Reimburse \$65110 to Guerantiy Fund
721 W. Roxbury Pkwy			Continaction submitted new continact and its was
W. Rosslaury, IMA (0121312			elphenowed."
Scoitit Gaunnand	Sacoitii Gzenumionel	116231	(Defaulted)
1110 Turnipilke Stanzett			Kagirsiiratiion newolkad & 914,000 penalliy
N. Andowar, MA 01845			
Sitery Broithers, Inc.	Dewiel Siteigerwelle	1029654	(Defiaulticel)
4:20 Dawis Rozel			Registiration nevoked and \$4,000 penellisy
Breditionneli, IMA 01730			
J & S Constitucition	Johna Szepuildo	11155575	((Defaudized))
18 Galdomiith Avenue			Registration nevoked and \$7,500 panality
Micellonel, MA 021515			
Giity Honne Builders	Marilk Grananuma	114:52:6	((Detizultical))
654 WaxIhiingtion Sit.			Kagiisiüratiion navokad and \$41000 panallity
Brainiuree, MA 02484			
A teo Z. Constanuction	(Charles Williams	111327/2	((Defaulitæl))
912, Groups Silverati			Regisitration navoked & 96,000 penality,
Willinnünigjitoini, IMIA Oti887			
Cunado & Sons Constituct, Inc.	Altineel Cunicialia	103/2177	Swapanalan until Guarantiy Fund Paid in Full."
12 Pallmar Sturaeti			
Mictidhiurani, IMIA (011834141			
Cantitury Blag Starvices	Pottar Honnem	1113421	((Defiautiicel))
1/22/3 Commandial Sii,			Regisiurziistom mwokeel emel \$4,000 pomellity
15., Weymaauidh, MA 02189	<u></u>		
Conde Constitucition	Miicherell Correlei	MME772	((Destautlized))
3412 (Brozel Siluracit			Ravocatilion of nagisturatilion and \$12,000 panality
Filiuchilaungi, IMIA (01141:210	,		
Misiunoproliitizm Deccoursitions	Thronners Recy	108943	(Destautivel)
22. Howard Stureet			Rogiisiuraliiion navakeel and \$3,000 panaliiy
Melinoxe, MA 02376			
Etwangyy Teechi, line.	Domellel Tallaoit	114215	(Defizultied)
14:05 mieilin Sturecti			Rogiosiaratizion nevelkeel and \$6,000 penuality
Whomaesitar, MVA ONGOl3			
R.A. Carllo Rooffing Co.	Roberii Carlo	106052.	Suspension until Guarantity Fund Patel in Full.
65 Dunisitar Road			Sulamiti new continacti ko BBRS for approval and
Badilionel, IMVA			\$35000 painality,"
KRS, Inc.	Kannraith Serchis	111000015	((Defizientfued))
PO Box 18			Registivation neveleal and \$5,000 panality
Miclinetace, WT 05050			

Hearing Datic Tuccelay, August 25, 1999

	-		ę	
ŗ.				1
	۶.			
Ľ		-		

- Comitimucal fironn Payre 4-

J.M. O'Briten & Som 23 Underwood Ave; Frannlingham, MA	John (MBriven)	1112995	Regisiurzition nevoked and ondered to reindurse Guaranty Fund in full. Possible future action againsit another registration held by Mr. (N3rian.*
Man zii Work Constructition 88-94 Whezitland Sii,	Harlærii Aguiiar	1141986	(Dofaulitad)) Ragisiuratiion revoked and \$6,000 panality
Somarville, MA 02145			n nagisiurziuran inamakaar zinzi gradowo jacarziinay i
Catitallii & Sonis	Avaniilhxonayy Canitaddii	1,071,371,59	(Defaulted)
4 Bezer Hill Rosel			Regilistaratidiom navalkadi & \$110,000 pamahity
Groveland, MA 01834			
	Hearing Date	: Tucsday, Ocitober	· 2.1/, 1998
NAME & ADDRESS	RESPONSIBLE	REGISTRATION	ADMINISTRATIME
	PIERSON	NUMBER	PENALTY
F & D Unlinnitized Constanucidion	Thromaers Firelel II	1115/280	(Defauliiæd)
139 Vanauna Awaanuc			Revocatition of registiration, \$7,000 penality, and
Lowell, IMA 01854			mainallourse illue Guerranii,y Fund in full.
Lynn Guitter & Kooffing Co.	John Shanahan	111 <i>710)</i> 87/	Surgeanded until Guerrantisy

		··· ··································	
Lynin Curicitar & Koofiling Co. 479 Broadway Lynn, MA Ok904	John Shenaham	1117/0/857	Surgerinded unitil Guerranity paid in full. *
Mounti Warnon Milles Company	Domalel Wasitwaitar,	120148	(Defaulizel)
577 Mounti Warthon Staraet	Jr.		Revocativon of negistrativon, \$4,000 penality, and
Donchastar, MA 02125			mainnlaurese tilhe Quarcantity Flumel in flull.
KOA Consiinuciiion	Kristiin Asmussan	1111335	(Defizultied)
39 Thrampson Stinzeti			Revocatition of registratiion, \$7,000 panality, and
Mannavel, MIA ON1254			reanaburese iches Guzarzanity Frund in fiull.
Brannen Roofing Compeny	Petitriick Breannem	11136115	(Defeulticel)
1112 Kimileell Storaet			Revocation of registration, \$7,000 penality, and
IMeilekani, IMIA 021148			neimlburge idhe Guerennity Fund in full.
AddCom, linc.	Dennis Bleine	111 <i>873</i> 9	(Defaultized))
5 Flinnwood Awanwe			Revocatilion oli registiratition, \$7,000 penaltiy, and
Szeikanni, NIH 03079			neitalburse tilhe Guerentity Fund in full,
Antidhomy's Pool Destign	Antithony Sevencesc	119154	(Defaultical)
1414) Boweloin Sitnact			Reverzition of registration, \$8,000 penality, and
IMiellelani, iMVA (0211418)			mainalaurese idhe Gwarzinity Fund in fiull.
Nonelic General Continentiers	Jachini Luréwigszani	1117/91519	Sulbmilit maw comitract and additional work andars
3381 Wershingitan Sitmatt			to BBRS,
Jannalica: li ⁿ latin, IMA 02130			
WIII-Co Homae Inaproventientes	Dewiel Willksitite	121595	Ravacetilian of negistizetilan,
440 Pleasanti Stinast			\$2,000 prinality, and imay neapply after one year.
Brockitan, MA 02301			

Hozmina Date Fridaw	Jennuer v 29, 1999	

NAME & ADDRESS	RESPONSIBLE PERSON	IREGISTIRATION INUMBER	ADMINISTRATIME PENALTY
T.W. Woods Competny 62 Bridle Süreet Billerice, MA 01821	Thiotaniars Włoczeks	111211977	Suspension of registeralision and \$6,000 panality,
Unificed Constinuction 145 Chrostinut, Stinest Williningiton, MA ONSET/	Joseph J. Pernella, Jr.	11151/26	Swepension of registration for six months and relimburse the Guaranty Fund \$4,000.
G.E.C. Continenciting, Inc. 23 Spring Sibreet Lexingicen, IMA 02173	(Akatan Carocesbyy	1113627/	([Defaultical)) Registination newoked, \$8,000 panality and music neimburae the Guaranity Fund in full.

Contilinueel om Page 6-

-Continued from Page 5-

Kelley Brothers Home	Robert Kelley	104190	(Defaulted)
Improvement			Registration revoked, \$10,000 penalty, reimburse
117 Rock Street	C. C. S. P. Ana S. C.		the Guaranty Fund in full.
Norwood, MA 02062			
Centerville Homes, Inc.	Richard Haydon	112738	(Defaulted)
4 Center Place, 1550 Rte. 28			Registration revoked, and \$4,000 penalty.
Centerville, MA 02362			
Paul Joseph Contractors	Paul R. Joseph	110687	(Defaulted)
10 Arrowhead Road			Registration revoked, \$7,000 penalty and must
N. Eastham, MA 02651			reimburse Guaranty Fund in full.
J. Martin Vierling	J. Martin Vierling	113141	(Defaulted)
175 Circuit Street			Registration revoked, and \$7,000 penalty.
Norwell, MA 02061		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
H & S Home Improvements	Henry Simons	109376	Suspension of registration,
216 Levin Road	2.19.19.19.10.2.7		\$5,000 penalty, and reimburse Guaranty Fund in
Rockland, MA 02370			full.
Bonitto Construction	Douglas Bonitto	111734	(Defaulted)
105 Ward Street	890. 火光和 HK 前首相		Registration revoked, \$6,000 penalty and must
Hingham, MA 02043	THE REPORT OF MILLION		reimburse the Guaranty Fund in full.
38 Dartmouth Terrace	A. Carl Rispettoso	116729	(Defaulted)
W. Brockton, MA 02301			Registration revoked, \$5,000 penalty and must
			reimburse the Guaranty Fund in full.
Pro-Builders & Remodeling, Inc.	Reginald Newcomb,	111245	(Defaulted) Revocation of both registrations, and
and Reggie's Exteriors	Jr.	&	\$12,000 penalty.
445 Liberty Street		125593	
Rockland, MA 02370		a the second of	
Professional Weatherproofing	Henry L. Holmes	116741	(Defaulted) Revocation of both registrations, and
and Henry L. Holmes & Son, Inc.		&	\$6,000 penalty.
10 Valley Street		125235	
Duxbury, MA 02332			
Briggs Construction, Inc.	Donald Briggs	107509	(Defaulted)
7 Highland Circle			Registration revoked, and \$10,000 penalty.
Foxboro, MA 02035			
1170 Forest Street	George Ryan	118430	(Defaulted)
Marshfield, MA 02050	이 영상 정말 승규님의		Registration revoked, \$4,000 penalty and must
			reimburse the Guaranty Fund in full.
D.B. Property Upgrade	Donald Bruce	106019	(Defaulted)
199 Spring Street	Sale - Carlos		Registration revoked, \$3,000 penalty and must
Walpole, MA 02081	344.77.2.2.2.3.1.3.1.3.1.3.1.3.1.3.1.3.1.3.1.3		reimburse the Guaranty Fund in full.
Colonial Home Improvement	Peter Van Wart	110224	(Defaulted)
581 Quarry Street			Registration revoked, \$6,000 penalty and must
Quincy, MA 02169			reimburse the Guaranty Fund in full.
Nickerson Home Improve., Inc.	Mark Nickerson	120424	(Defaulted) Registration revoked, and \$12,000
PO Box 2476			penalty.
286 S. Orleans Rd.	The states have a set		
Orleans, MA 02653			

*Any future complaints will result in another hearing seeking revocation of registration.

"LONG SPAN" HEADERS OVER GARAGE DOOR OPENINGS IN BEARING WALLS.

Table 3606.2.6 of the Massachusetts State Building Code specifies the size requirements for headers in wood frame bearing walls in one and two family dwellings.

Size of	LEADERG	IN BEARING	and the second se	Linden in Malle
Header (1)	Supporting Roof Only	One Story Above	2 Stories Above	Headers in Walls not Supporting Floor or Roof
2-2X4	4	+	4 (1)	4
2-2X6	6	4	Ŧ	
2-2X8	В	6	H A	10
2-2X10	10	8	6	12
2-2X12	12	10	8	16

Table 3606.2.6

(1) Nominal 4-inch thick members may be substituted for double members

(2) Allowable Spans based on # 2 grade lumber with 10-foot tributary floor and roof loads

The table provides "prescriptive" solutions. If longer span headers are required, the use of this table is not permitted.

Many instances have been observed by building officials where 16 or 18-foot headers have been used in bearing walls. Typically, much stronger materials or much larger members are required to satisfy strength, deflection & support criteria and may require an engineered solution.

CONTINUING EDUCATION REQUIREMENTS FOR LICENSED CONSTRUCTION SUPERVISORS MOVES FORWARD

At its March 9, 1999 meeting the BBRS gave the green light for staff to explore continuing education requirements for Licensed Construction Supervisors. The proposal to required continuing education was made as a code change proposal at the May 1998 Public Hearing. The proposal would require a CSL holder to complete 12 hours of continuing education in every twoperiod. The BBRS feels that the entire year Commonwealth will benefit by ensuring that builders are well informed on changes and updates in the State Building Code. Architects, Building Officials, Electricians and other professions and trades already require professional development through continuing education in order to remain licensed or registered. This requirement is expected to be adopted sometime in the first part of the new millennium - WATCH THIS SPACE.

ATTENTION LICENSED CONSTRUCTION SUPERVISORS

Your initial license is valid for 3 years and is renewable every two years thereafter, expiring on the licensee's birthday. You will receive a renewal notice in the mail prior to the date of expiration - PROVIDING THAT YOU HAVE INFORMED THE BBRS IN WRITING OF ANY AND ALL CHANGES OF ADDRESS. You have one year from the date of expiration to renew your license. If you do not renew within this period you are required to take the Construction Supervisor License Examination - there are NO exceptions to this policy. If you do not receive a license renewal before the expiration of the license please contact the BBRS to ensure that we have your current address on file. Please note - it is YOUR responsibility to inform the BBRS of a change in address.

CONSTRUCTION SUPERVISOR LICENSE EXAMINATION DATES

Registration and examination dates for the Construction Supervisor License Examination are;

Registration Deadline	Examination Date
May 14, 1999	June 12, 1999

If you need information or an application and candidate information package call the BBRS at; (617)- 727-7532 Extension 696

BBRS APPROVES EMERGENCY CODE CHANGE

At its regular meeting of March 9, 1999 the BBRS voted to amend the building code by emergency action to avoid a conflict with the State Electrical Code 527 CMR Section 12.

The building code section amended is 780 CMR 3603.6.1 (exception 2) which requires a lighting control switch at the top and bottom of each interior stairway in a one and two family dwelling. The electrical code does not require the switch on the floor level served by the stair if the area is not occupied (such as a cellar or basement space) i.e. not a finished area. Exception 2 has been amended to defer to the switching requirements of the Massachusetts Electrical Code.

FORMAT CHANGE - CONSTRUCTION SUPERVISOR LICENSE EXAMINATION

Beginning with the first test administration of 2000, the CSL examination will contain a series of questions which will test the candidates ability to read and comprehend a set of building plans. Candidates will be provided a set of plans at the examination and will be required to answer questions related to the plans. All tests will be designed such that candidates are required to pass this portion of the examination in order to qualify for a passing grade.

ATTENTION BUILDING OFFICIALS

For the past two years or so the BBRS has been issuing Construction Supervisor Licenses (initial issue and renewals) with picture identifications. These licenses are also laminated. Every license should now contain a picture. Please ensure that you verify the license holder and view the license to ensure the license has not expired. Do not rely on a license number you may have on file in your office.

Editor in Chief:
Supervising Editor:
Graphic Design & Layout:
Subscriptions Accountant:

Thomas L. Rogers Brian Gore, P.E. Brian Gore, P.E. Anne Marie Rose

Codeword

Board of Building Regulations and Standards One Ashburton Place, Room 1301 Boston, MA. 02108



Attention Building Officials



AS A PUBLIC SERVICE, CODEWORD IS PROVIDED FREE OF CHARGE TO ALL MUNICIPAL BUILDING DEPARTMENTS OF THE COMMONWEALTH