



- Management Plan in school office
- Annual and contractor notice current
- Training records current

## Periodic Surveillance

Location: \_\_\_\_\_ School, 222 Main St.

Date: \_\_\_\_\_

Performed by \_\_\_\_\_ (signature of person performing surveillance)

Location of ACM	Description of ACM	Amount (LF/SF)	Change in Condition (Y/N)	Comments
<b>1936 Building</b>				
Hallways	12x12 dark tan floor tiles	1500 SF	Y	Minor cracking and distributed spot damage "B" hallway
Hallways	Mastic-dark tan 12x12 tiles	1500SF	N	Not visible-assumed intact under tiles
Rest rooms	12x12 light tan floor tiles	260 SF	N	Good condition
Rest rooms	Mastic-light tan 12x12 tiles	260 SF	N	Not visible-assumed intact under tiles
Hallways and rest rooms 1 <sup>st</sup> & 2 <sup>nd</sup> floor	Plaster ceiling	2500 SF	N	Contact damage near East stairwell-present during last 6 month surveillance
<b>1959 Addition</b>				
Hallways outside gym G1	Pipe elbows	12 each	Y	Contact damage on 3 elbows
Gymnasium	Roof drain insulation			
Dishwashing off Kitchen	Pipe elbows			
Custodian rm 409	Pipe elbows Pipe insulation			
	Tan 12x12 floor tiles			
	Blue 12x12 floor tiles			
Hallways & classrooms	White/blue specked 12x12 floor tiles			
Room 405	Pipe elbows			Contact damage from storage
Storage room G0	Pipe elbows			