

Carver Cotton Gin Dam Removal Photograph Summary

List of Photographs

Photo 1: Downstream face of dam looking upstream (pre-construction)	1
Photo 2: Downstream face of dam looking at rubble fill exposed on right (pre-construction)	1
Photo 3: Crest of dam looking at the right abutment (pre-construction)	2
Photo 4: Looking upstream at mill building piers on river left and Route 106 Bridge(pre-construction)	2
Photo 5: Looking Downstream from Route 106 bridge (pre-construction).....	3
Photo 6: Piers of mill building on river right (pre-construction).....	3
Photo 7: Piers and pier foundations of mill building(pre-construction).....	4
Photo 8: Looking downstream at open gate and right dam abutment (pre-construction).....	4
Photo 9: Looking downstream at Dam right abutment with emergency overflow spillway (pre-construction)	5
Photo 10: Looking upstream at open gate and right dam abutment (pre-construction).....	5
Photo 11: Stabilized Construction Entrance (mid-construction)	6
Photo 12: Looking downstream through route 106 bridge culvert (mid-construction).....	6
Photo 13: Scour countermeasure construction upstream of Route 106 (mid-construction)	7
Photo 14: Partially removed dam with exposed material (mid-construction)	7
Photo 15: Looking upstream at channel excavation (mid-construction).....	8
Photo 16: Looking upstream at channel excavation (mid-construction).....	8
Photo 17: Looking downstream from route 106 bridge (mid-construction).....	9
Photo 18: Looking downstream from route 106 bridge (mid-construction).....	9
Photo 19: Looking downstream at route 106 bridge (post-construction).....	10
Photo 20: Mill building pier foundation protection (mid-construction).....	10
Photo 21: Mill building piers (mid-construction)	11
Photo 22: Looking upstream at constructed channel and removed dam (post-construction)	11
Photo 23: Looking downstream at river right stabilized abutment (mid-construction).....	12
Photo 24: Looking downstream from route 106 bridge (post-construction)	12
Photo 25: Looking downstream at river channel through removed dam (mid-construction)	13
Photo 26: River right stabilized abutment, loamed, and seeded with loam (post-construction)	13
Photo 27: River left retaining wall stabilized, loamed, and seeded (post-construction)	14
Photo 28: River left pipe outfalls and slope loamed and seeded (post-construction)	14

Photo 1: Downstream face of dam looking upstream (pre-construction)
(Gomez and Sullivan, 3/18/16)



Photo 2: Downstream face of dam looking at rubble fill exposed on right (pre-construction)
(Gomez and Sullivan, 3/18/16)



Photo 3: Crest of dam looking at the right abutment (pre-construction)
(Gomez and Sullivan, 3/18/16)



Photo 4: Looking upstream at mill building piers on river left and Route 106 Bridge (pre-construction)
(Gomez and Sullivan, 3/18/16)



Photo 5: Looking Downstream from Route 106 bridge (pre-construction)
(Gomez and Sullivan, 4/14/15)



Photo 6: Piers of mill building on river right (pre-construction)
(Gomez and Sullivan, 11/16/16)



Photo 7: Piers and pier foundations of mill building(pre-construction)
(Gomez and Sullivan, 11/16/16)



Photo 8: Looking downstream at open gate and right dam abutment (pre-construction)
(Gomez and Sullivan, 11/16/16)



Photo 9: Looking downstream at Dam right abutment with emergency overflow spillway (pre-construction)
(Gomez and Sullivan, 11/16/16)



Photo 10: Looking upstream at open gate and right dam abutment (pre-construction)
(Gomez and Sullivan, 10/5/17)



Photo 11: Stabilized Construction Entrance (mid-construction)
(Gomez and Sullivan, 10/6/17)



Photo 12: Looking downstream through route 106 bridge culvert (mid-construction)
(Gomez and Sullivan, 10/24/17)



Photo 13: Scour countermeasure construction upstream of Route 106 (mid-construction)
(Gomez and Sullivan, 10/17/17)



Photo 14: Partially removed dam with exposed material (mid-construction)
(Gomez and Sullivan, 10/24/17)



Photo 15: Looking upstream at channel excavation (mid-construction)
(Gomez and Sullivan, 10/24/17)



Photo 16: Looking upstream at channel excavation (mid-construction)
(Gomez and Sullivan, 10/24/17)



Photo 17: Looking downstream from route 106 bridge (mid-construction)
(Gomez and Sullivan, 10/24/17)



Photo 18: Looking downstream from route 106 bridge (mid-construction)
(Gomez and Sullivan, 10/24/17)



Photo 19: Looking downstream at route 106 bridge (post-construction)
(Gomez and Sullivan, 11/27/17)



Photo 20: Mill building pier foundation protection (mid-construction)
(Gomez and Sullivan, 9/22/17)



Photo 21: Mill building piers (mid-construction)
(Gomez and Sullivan, 10/20/17)



Photo 22: Looking upstream at constructed channel and removed dam (post-construction)
(Gomez and Sullivan, 12/13/17)



Photo 23: Looking downstream at river right stabilized abutment (mid-construction)
(Gomez and Sullivan, 12/8/17)



Photo 24: Looking downstream from route 106 bridge (post-construction)
(Gomez and Sullivan, 12/13/17)



Photo 25: Looking downstream at river channel through removed dam (mid-construction)
(Gomez and Sullivan, 12/8/17)



Photo 26: River right stabilized abutment, loamed, and seeded with loam (post-construction)
(Gomez and Sullivan, 12/13/17)



Photo 27: River left retaining wall stabilized, loamed, and seeded (post-construction)
(Gomez and Sullivan, 12/13/17)



Photo 28: River left pipe outfalls and slope loamed and seeded (post-construction)
(Gomez and Sullivan, 12/13/17)

