

DEVAL L. PATRICK GOVERNOR

TIMOTHY P. MURRAY LIEUTENANT GOVERNOR

JUDYANN BIGBY, MD SECRETARY

JOHN AUERBACH COMMISSIONER

The Commonwealth of Massachusetts

Executive Office of Health and Human Services

Department of Public Health Bureau of Environmental Health Community Sanitation Program 5 Randolph Street

Canton, MA 02021

Telephone: 781-828-7910 Facsimile: 781-828-7703

marian.robertson@state.ma.us

October 22, 2011

Lisa Jackson, Superintendent South Middlesex Correctional Center 135 Western Ave. P.O. Box 788 Framingham, MA 01701

Re: Facility Inspection

Dear Superintendent Jackson:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, and Department of Public Health Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the South Middlesex Correctional Center on October 11 and 12, 2012 accompanied by Michael Sacino, EHSO, Tony Montonari, Industrial Instructor, Eva Plumnoff, CPO A/B, Paul Halfmann, Assistant Director of the Community Sanitation Program and Amy Riordan, Environmental Health Inspector of the Community Sanitation Program. Violations noted are listed below (* indicates conditions documented on previous inspection reports).

3RD FLOOR

Bathroom 3-1		
105 CMR 451.123*	Maintenance: Missing light shields	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, 1 toilet not working	
105 CMR 451.123*	Maintenance: Toilet 1, not easily cleanable	
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower stall # 3	
105 CMR 451.123	Maintenance: All shower walls paint peeling	
105 CMR 451.123	Maintenance: Radiator cover damaged	
105 CMR 451.123	Maintenance: Light shield missing	
105 CMR 451.123	Maintenance: Ceiling damaged	
105 CMR 451.123	Maintenance: Ceiling vent dusty	
105 CMR 451.123	Maintenance: Shower wall dividers damaged in between shower stall # 1 and 4	
Bathroom 3-2		
105 CMR 451.123*	Maintenance: Paint peeling in showers	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, sink # 2 leaking	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, 1 toilet not working	

105 CMR 451.130 105 CMR 451.126	Plumbing: Plumbing not maintained in good repair, no cold water at sink # 1 Hot Water: Hot water temperature recorded at 102°F	
Bathroom 3-3 105 CMR 451.123*	Shower # 2 occupied at time of inspection Maintenance: Paint peeling in showers	
105 CMR 451.350	Structural Maintenance: Tile damaged near sink # 2	
Electrical Closet #1 & 2		
	No Violations Noted	
Rooms	Room # 327 not in used	
105 CMR 451.350	Structural Maintenance: Wall damaged around electrical wires in # 309	
105 CMR 451.350	Structural Maintenance: Ceiling damaged in # 317, 319, 321, 322, 325, 327, 328, 331, 332, 333, 334 and 335	
105 CMR 451.350	Structural Maintenance: Wall damaged in # 337	
105 CMR 451.350	Structural Maintenance: Baseboard damaged in # 330	
105 CMR 451.353	Interior Maintenance: Window sill paint damaged in #319	
105 CMR 451.353	Interior Maintenance: Wall paint damaged in #320, 321, 322 and 330	
105 CMR 451.353	Interior Maintenance: Light shield missing in # 321, 322, 327 and 337	
105 CMR 451.353	Interior Maintenance: Radiator cover screen not secure in # 321, 322, 331, 334 and 337	
105 CMR 451.101	Blankets: Blanket damaged in cell # 322	
105 CMR 451.320	Cell Size: Inadequate floor space in cell # 336	
105 CMR 451.350*	Structural Maintenance: Ceiling damaged in #327	
Porch		
	Not in Use	
Closet 3-A, 3-B & 3-D		
	No Violations Noted	
Closet 3-C		
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, sink leaking	
105 CMR 451.353	Interior Maintenance: Drain cover not in drain	
TOP CHILL ID 115 35	meener manee. Drain cover not in aran	
Closet 3-E		
105 CMR 451.353	Interior Maintenance: Slop sink drain cover damaged	
3 rd Floor Offices		
	No Violations Noted	
2 nd FLOOR		
Bathroom 2-4		
105 CMR 451.123	Maintenance: Ceiling damaged	
105 CMR 451.123	Maintenance: Drain covers not secure in all showers	
105 CMR 451.123	Maintenance: Wall paint damaged in shower # 2 and 3	
105 CMR 451.123	Maintenance: Wall vent dusty	
105 CMR 451.123	Maintenance: Wall damaged in toilet stall # 4	
Bathroom 2-3		
105 CMR 451.123	Maintenance: Wall paint damaged in shower # 3	
105 CMR 451.123	Maintenance: Drain cover not secure in shower # 1	
105 CMR 451.123	Maintenance: Wall vent dusty	
105 CMR 451.123	Maintenance: Radiator cover screen not secure	

Water Fountain near Bathroom 2-3

105 CMR 451.353 Interior Maintenance: Water fountain not working

Bathroom 2-2

105 CMR 451.123 Maintenance: Wall tiles missing in shower # 1

Janitor Closet

105 CMR 451.353 Interior Maintenance: Wet mop left in bucket

Bathroom 2-1

105 CMR 451.123* Maintenance: Floor damaged in shower

105 CMR 451.123 Maintenance: Floor paint damaged in shower # 2

105 CMR 451.123 Maintenance: Ceiling paint peeling 105 CMR 451.123 Maintenance: Ceiling vent dusty

105 CMR 451.123 Maintenance: Wall damaged near soap dispenser 105 CMR 451.123 Maintenance: Possible mold growth near windows

Library

No Violations Noted

Closet 2-C, 2-D, 2-F, 2-G, 2-H

No Violations Noted

Closet 2-A

105 CMR 451.353 Interior Maintenance: Wet mop left in bucket

Closet 2-E

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, slop sink faucet loose

Phone Area

105 CMR 451.350 Structural Maintenance: Ceiling damaged

Rooms

105 CMR 451.353 Interior Maintenance: Window shade damaged in # 201 and 207

105 CMR 451.353 Interior Maintenance: Wall paint damaged in # 203, 207, 209, 213, 223, 227, 228, 235

and 254

105 CMR 451.350 Structural Maintenance: Baseboard damaged in # 204

105 CMR 451.350 Structural Maintenance: Wall damaged near electrical wires in # 208

105 CMR 451.350 Structural Maintenance: Wall damaged in # 213, 232 and 252

105 CMR 451.331 Radiators and Heating Pipes: Pipes not properly insulated in # 229

105 CMR 451.353 Interior Maintenance: Radiator cover screen not secure in # 236, 237, 242, 245, 247

and 248

Porch

Not in Use

1st FLOOR

Administration Area

Director of Security Office

FC 4-204.112(A) Design and Construction, Functionality: No functioning thermometer in refrigerator

Shift Commanders Office

FC 4-204.112(A) Design and Construction, Functionality: No functioning thermometer in refrigerator

Break Area

No Violations Noted

Janitor's Closet

No Violations Noted

Deputy's Office

No Violations Noted

Women's Bathroom

No Violations Noted

Men's Bathroom

No Violations Noted

Visiting Area

Male Bathroom

No Violations Noted

Female Bathroom

105 CMR 451.123

Maintenance: Light shield missing

Vending Machine Area

FC 4-601.11(C)* 105 CMR 451.353 Cleaning of Equipment and Utensils, Objective: Vending machine drawer dirty

Interior Maintenance: Water fountain clogged up

Remaining Facility

Holding Cell

No Violations Noted

Meeting Room

No Violations Noted

HSU/Nurses Office

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 105°F

105 CMR 451.344

Illumination in Habitable Areas: One light fixture not functioning properly

105 CMR 480.500 Procedures; Records; Record-Keeping Log: Not maintaining a current record-keeping

log

Records Room

FC 4-204.112(A)

Design and Construction, Functionality: No functioning thermometer in one

refrigerator

Dental Office

No Violations Noted

Medical Waste Storage

105 CMR 451.350*

Structural Maintenance: Baseboard damaged

Kitchenette

No Violations Noted

Laundry			
105 CMR 451.353	Interior Maintenance: Debris behind machines		
105 CMR 451.350			
103 CMR 431.330	Structural Maintenance: Unused ventilation pipe causing hole in wall		
Staff Locker Room	·		
105 CMR 451.350	Structural Maintenance: Ceiling damaged above showers		
105 CMR 451.130	Plumbing: No backflow preventer on thread faucets		
105 CMR 451.353			
103 CMR 431.333	Interior Maintenance: Wall vent dusty		
Toxic Caustic Room			
105 CMR 451.353	Interior Maintenance: Light shield missing		
105 CMR 451.350	Structural Maintenance: Baseboard damaged		
	e e e e e e e e e e e e e e e e e e e		
105 CMR 451.353	Interior Maintenance: Light shield loose		
TV Room			
105 CMR 451.350	Structural Maintenance: Wall damaged in several areas		
	8 · · · · · · · · · · · · · · · · ·		
Recreational Room			
105 CMR 451.353	Interior Maintenance: 2 light bulbs missing		
105 CMR 451.350	Structural Maintenance: Baseboard damaged		
Chaplain's Office			
Chaptain's Office			
	No Violations Noted		
·			
Hair Salon	•		
105 CMR 451.353	Interior Maintenance: Radiator cover screen not secure		
105 CMR 451.353	Interior Maintenance: Unlabeled chemical bottle		
105 CMK 451.555	interior Maintenance. Omabered chemical bottle		
Closet 1-B, 1-D, 1-E			
	No Violations Noted		
Closet 1-C			
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet loose		
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking		
Classroom			
	No Violations Noted		
	NO A folgrious laoren		
<i>a</i>			
Computer Room			
105 CMR 451.353	Interior Maintenance: Light shield missing		
105 CMR 451.353	Interior Maintenance: Radiator cover screen not secure		
and a market to had ow	moving framitodiano, addiano, corol belocit not bootie		
TT (: T) D			
Horticulture Room			
	No Violations Noted		
BASEMENT			
Property ECA 204 112(A)			
FC 4-204.112(A)	Design and Construction, Functionality: No functioning thermometer in refrigerator		
-			
Records Storage			
	No Violations Noted		
	A 10 A SOURCE TARROLL		
777 7			
Warehouse			
	No Violations Noted		

/*/ T	~ .	- 7
1001	1 200	,
Tool	$\cup \iota \iota$	ι

No Violations Noted

Gym

105 CMR 451.353

Interior Maintenance: Bench cover damaged

Mechanical Room

105 CMR 451.331*

Radiators and Heating Pipes: Pipes not properly insulated

105 CMR 451.353*

Interior Maintenance: Standing water on floor

Fan Storage Room

No Violations Noted

Recreational Room

No Violations Noted

Hallway near Recreation Room

105 CMR 451.353

Interior Maintenance: Ceiling tiles missing

Dining Area

FC 6-201.16(A)*

Design, Construction, and Installation; Cleanability: Ceiling covering not easily

cleanable, access panel above toaster is peeling paint

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, pipe leaking by

door #5

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good

repair, milk dispenser leaking

Main Kitchen

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, pipe paint peeling

in baker's area

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, ceiling paint

damaged in baker's area

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, window broken in

baker's area

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good

repair, ice machine door broken

FC 6-201.16(A)*

Design, Construction, and Installation; Cleanability: Wall covering not easily

cleanable, wall damaged on corner of baker's area wall

FC 5-202.12(A)

Plumbing System, Design: Handwashing sinks water temperature recorded at 104°F

FC 4-501.114(A)

Maintenance and Operation; Equipment: Chlorine Sanitizer solution tested less than

recommended concentration

FC 6-501.11*

Maintenance and Operation; Repairing: Facility not in good repair, food prep sink

faucet leaking

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, wall damaged

under food prep sink

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, ceiling tiles

missing

FC 4-903.11(A)(2)

Protection of Clean Items, Storing: Single-service items not protected from

contamination, utensils not stored with handles up near service line

Dishwasher Area

FC 6-201.16(A)

Design, Construction, and Installation; Cleanability: Wall not easily cleanable, wall

damage near doorway to toxic caustic area

105 CMR 451.350*

Structural Maintenance: Door frame damaged into toxic caustic area

Toxic Caustic Room

FC 6-202.15(A)(2)* Design, Construction, and Installation; Functionality: Outer door not weather and

vermin tight

Dry Goods

FC 6-202.11(A)* Design, Construction, and Installation; Functionality: Light bulbs not shatter-resistant

or protected by light shields

FC 6-501.111(B)* Maintenance and Operations; Pest Control: Rodent droppings observed

FC 4-501.11(B) Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, gaskets damaged on refrigerator # 5

FC 6-404.11 Location and Placement; Distressed Merchandise: Dented/Damaged cans not properly

segregated

Utensils Cabinet

FC 4-502.11(A) Maintenance and Operation, Utensils: Utensils not maintained in a state of good

repair, rubber spatula damaged

FC 4-601.11(A) Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, one ladle

dirty

Walk-in Freezer

FC 4-501.11(A) Maintenance and Operation, Equipment: Equipment not maintained in a state of good

repair, freezer unit not functioning properly, ice built-up on boxes and items stored in

freezer

Loading Dock Area

FC 6-202.15(A)(2)* Design, Construction, and Installation; Functionality: Outer door not weather and

vermin tight

Kitchen Bathroom

FC 5-205.15(B) Plumbing System, Operations and Maintenance: Plumbing system not maintained in

good repair, slop sink faucet leaking

Maintenance Storage Room

No Violations Noted

Property Storage Room

No Violations Noted

Chiller Room

No Violations Noted

Telephone Room

No Violations Noted

Office Supply Room

105 CMR 451.360 Protective Measures: Rodent droppings observed

FAMILY RE-UNIFICATION HOUSE

Basement

105 CMR 451.353

Interior Maintenance: Missing drain cover on floor drain

2nd Floor

Bathroom

105 CMR 451.353*

Interior Maintenance: Light not functioning properly

EXTERIOR

No Violations Noted

GARAGE

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 93°F

HODDER HOUSE

2nd Floor

Room 2-2

105 CMR 451.353

Interior Maintenance: Wall paint damaged

Male Bathroom

105 CMR 451.126

Hot Water: Hot water temperature recorded at 64°F

Observations and Recommendations

> The inmate population was 160 at the time of inspection

> Base on the number of beds in the room, if they were to be filled, the room would not meet 105 CMR 450.320 square footage

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please indicate next to each entry on the inspection report a plan of correction. Said plan of correction must be submitted within ten working days of receiving this report and should detail the specific steps that will be taken and the date of expected compliance. The plan of correction should be submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Community Sanitation Regulations" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X – Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,

Marian Robertson

Environmental Health Inspector, CSP, BEH

cc: Suzanne K. Condon, Associate Commissioner, Director, BEH

Steven Hughes, Director, CSP, BEH

JudyAnn Bigby, MD, Secretary, Executive Office of Health and Human Services

Luis S. Spencer, Commissioner, DOC

Jason Patterson, EHSO

Framingham Board of Health

Clerk, Massachusetts House of Representatives

Clerk, Massachusetts Senate

Mary Elizabeth Heffernan, EOPS