
Massachusetts Coastal Infrastructure Inventory and Assessment Project Coastal Hazards Commission

South Coastal

dcr 🚱



Fall River



July 6, 2009

Prepared for:

Massachusetts Department of **Conservation and Recreation** Hingham, Massachusetts

Presented by:

Bourne Consulting Engineering Franklin, Massachusetts



Bourne Consulting Engineering Waterfront Engineers

South Coastal

TABLE OF CONTENTS

Section I - Coastal Hazards Infrastructure and Assessment Program

INTRODUCTION

PURPOSE

DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES
DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS

Section II - Fall River

Part A - Community Findings

- COMMUNITY DESCRIPTION
- STRUCTURE INVENTORY
- SUMMARY OF FINDINGS
- Part B Structure Assessment Reports
- Part C Structure Photographs
- Part D Structure Documents
 - CITY DOCUMENT LIST
 - o Document Table
 - MA DCR DOCUMENT LIST
 - o Document Table
 - MA DEP CH 91 DOCUMENT LIST
 - o Document Table
 - o Copies of License Documents
 - USACE PERMIT DOCUMENT LIST
 - o Document Table
 - o Copies of Permit Documents

Section I

Coastal Hazards Infrastructure and Assessment Program

INTRODUCTION

PURPOSE

DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES

DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS



Massachusetts Coastal Infrastructure Inventory and Assessment Project Coastal Hazards Commission

Section I - Coastal Hazards Infrastructure and Assessment Program

INTRODUCTION

The Project and Client

The Commonwealth of Massachusetts has initiated a Coastal Hazards Commission (CHC) to identify the vulnerability of the state to coastal hazards. As one of five working groups working under the CHC, the 20-Yr Infrastructure Plan was to establish a prioritization for the repair of coastal structures. The focus areas of the Working Group include:

- Publicly owned infrastructure
- Infrastructure for which State is responsible
- Inventory of public hazards infrastructure
- Evaluation on conditions
- Development for a prioritization of work
- Estimation of capital and maintenance costs

The 20-Yr Infrastructure Working Group is led by Representative Frank Hynes with CZM as the lead State Agency overseeing the management of the project. The Massachusetts coastline has been broken up into 4 major regions consisting of the North Shore, Boston, South Coast, and the Cape and Islands. The South Shore (the Towns of Hull, Cohasset, Seekonk, Hingham, Plymouth, Kingston, Scituate and Duxbury) was previously evaluated by Bourne Consulting Engineering as a demonstration project in 2006.

Consultant Team

The consultant team that performed the demonstration project was led by Bourne Consulting Engineering (BCE) of Franklin, MA who was responsible for overall project management, specified areas of field assessments, and research. Assisting BCE was Applied Coastal Research and Engineering Inc. of Mashpee, MA, Childs Engineering Corporation, of Medfield, MA., and Waterfront Engineer LLC of Stratham, NH.

PURPOSE

Study Purpose

CZM seeks to identify the capacity of Massachusetts coastal structures to resist major coastal storms and prevent storm damage. In working toward this goal, CZM has initiated a program to perform an assessment of Commonwealth owned and/or maintained coastal structures. The first phase of this program was the performance of a demonstration project for coastal structures located on the South Shore. The demonstration project identified existing structures, their general conditions, ability to provide coastal protection and the probable cost for repairs. The information collected and developed has been incorporated into the MassGIS system to allow use for developing a 20 Year Coastal Infrastructure Plan.

The demonstration project served as a basis for the current statewide inventory assessment of all Commonwealth coastal structures and the needs for their maintenance and/or repair.

Goals of Study

The goals of the Massachusetts Coastal Infrastructure Inventory and Assessment Project include:

- To identify all the coastal structures the state either owns or has responsibility to maintain for the 4 regions included within the study
- Of the structures identified, determine the structure location and characteristics, the structure condition relative to providing coastal protection and the structure importance in relation to what it is protecting.
- To the degree possible, identify the structure elevation and the FIRM mapping flood elevation and category.
- To the degree possible, identify structure owner and available documents from local, state and federal agencies.
- To establish an estimated cost to rehabilitate the coastal structures to provide the level of project established in the structure's original design.
- Provide the information in a format compatible for incorporation into the MassGIS system

Limit of Study

Due to the time constraints and the amount of effort necessary to collect, process and compile the information, the following are identified as limitations of the information presented:

- All property ownership was taken as presumed. No legal investigation of ownership was
 performed during the project. Property ownership is based on town assessor maps. Where
 structures were located outshore of assessor map defined property lines, it was assumed to be
 Town land unless other information indicated otherwise. Where structures were located outshore
 of Mean Low Water, property is assumed to be State owned.
- The structure ownership was based on assessor maps and research at the local, state and federal levels. Where there was indication of public work on a structure on Town land or on private property, the structure was presumed to be Town owned. Where the structure was on state property, the structure was presumed to be state owned. Where ownership of the structure was not clear but was located on private property, the structure ownership was defined as unknown.
- The study included town and state owned structures as it was assumed that most town owned structures received state funding at some level for construction and/or maintenance.
 - o Structures that were determined to be private were not included.
 - O Undocumented structures considered to be on private land, but having the potential to have been publicly built and/or maintained, were identified as having an "unknown ownership".
- The prioritizing of structures was based primarily on risk to general infrastructure and density of housing. Infrastructure included was buildings. The study did not consider all infrastructure issues including:
 - o No consideration on utility impacts water, electrical, sewer, gas
 - o No consideration of roadway and bridge protection
 - o Evacuation routes were not considered within the investigation
 - Location of Emergency Shelters were not included in priority assessments
- Research was performed at the local, state and federal levels. The local research was limited to location and documenting available coastal structure contract drawings. Research at DCR was restricted to available historic construction plans for coastal structures at the MA-DCR Waterways office in Hingham, MA, and MA-DCR Division of Urban Parks and Recreation in

I-2

BCE

Boston, MA. No investigation of state archives was performed. Research at MA DEP Chapter 91 and USACE was limited to recorded permits and licenses found in their files. No investigation was performed at the Registry of Deeds.

DEVELOPMENT OF MassGIS DATABASE ATTRIBUTES

The specific attributes that would be incorporated into the MassGIS system were developed based on the scope of work and the goals to be achieved. The following was established to standardize the data collection and presentation and to allow total flexibility for sorting by attributes in the final GIS database. The attributes identified below were input into a MS Access database which was used to manage the data from all eight communities within a single file.

Database Attributes

• Attribute Descriptions/Definitions

Structure Number: A unique structure number was given to each coastal structure. The number was based on existing numbering systems that include the State Department of Environmental Protection community number followed by the local community assessor's parcel numbering system. The last three digits of the number represent the structure within the parcel. Where structures extend over several parcels, the structure is referenced to a parcel that is approximately in the center of the structure. Where Town assessor's references include letters, those are also included within the structure number. Some communities have block numbering within their numbering system and these are included. Communities without block numbering still have the block numbering included but these are illustrated as all zeros for that specific segment.

Structures that are on Town property, which would otherwise not have a parcel number, are referenced to a parcel that is in the immediate vicinity of the coastal structure.

On this basis, the following is the general numbering convention:

CCC-MMM-BBB-PPP-SSS

		CCC WWW-DDD-111-555
Where:	CCC	DEP Community Number
	MMM	Community Map Number
	BBB	Block Number (000 if no block numbering system)
	PPP	Community Parcel Number
	SSS	Structure Number

<u>Property Ownership</u>: All property ownership was on a "presumed" basis as no legal verification of ownership was performed. The ownership of the property was classified under four basic areas which were private ownership (Private), Town ownership (Local), Commonwealth of Massachusetts ownership (State), federal government ownership (Federal) or unknown. Property ownership was based on Town assessor's maps. Where the location was located above Mean Low Water, and not within a defined parcel, the property ownership was presumed to be the Town unless documentation was found to indicate otherwise. Where a structure was located offshore of Mean Low Water, the property ownership was presumed to be federal.

Structure Ownership: The ownership of all structures is presumed as no verification of ownership was performed. Ownership of the structure was determined by research into historic state and federal

I-3

BCE

permits and the entity indicated on the permits as the applicant. Where no other information was found, the following was utilized:

- Structures located on private land but appearing to be significant structures were identified as owned by the Town or as "Unknown". Unknown was used were there was a question of local or private ownership.
- Structures on Town property were assumed to be owned by the Town
- Structures that were located off-shore were presumed to be federally owned
- Structures that were identified as being privately owned were eliminated from the database

<u>Basis of Ownership</u>: The basis of structure ownership was provided to give rationale to the structure ownership and identified the research resource that identified the ownership or the methodology otherwise used. The responses utilized were limited to the following:

- DPW DPW Employee Interview
- DCR Contract Drawings
- DEP Ch 91 License
- USACE Permits
- Property Ownership
- Offshore Structure

<u>Structure Owner's Name:</u> Ownerships names reflect the presumed owner of publicly owned structures. As this was for public structures only, the ownership was restricted to the community name, the state agency or the federal agency.

Earliest Structure Record: The year of the oldest document located for the structure. The information is determined from the document research performed on the structure from local, state and federal agencies. If no documents could be found than this entry is denoted as 'Unknown'. Where documentation of the structure could be found, the date from the oldest document was utilized.

<u>Primary Structure</u>: Many of the coastal structures consisted of combined structures which were rated separately. It was typically found that one structure was significantly more predominant (Ex. Bulkhead/Seawall) and was therefore identified as the Primary Structure while a smaller structure might exist in front (ex. Revetment) of it. The type, height and material of each structure are identified separately. The condition of each structure was based on the Primary Structure. Where there was no secondary structure, the fields were left blank.

<u>Structure Type:</u> The structure type was categorized into five basic coastal structure categories which were Bulkhead/Seawall, Revetment, Coastal Beach, Coastal Dune, and Jetty/Groin.

<u>Structure Material:</u> The identification of the coastal structure's material of construction was performed and represents the primary material. Stone structures consisted of both mortared and non-mortared conditions.

Structure Height: Each type of structure was categorized by its visible height in feet which was broken into four specific ranges which are:

< 5 feet 5 to 10 feet 10 to 15 feet >15 feet

Structure Condition: A preliminary assessment of the condition for each structure was performed by the field teams. This was by visual observation only and no detailed investigation was performed. The condition assessments were based on a predefined five level rating system that ranged from Rating A for Excellent Condition to Rating F for Critical Condition. A detailed listing of the conditions and their definitions can be seen in Exhibit A.

I-4

BCE

<u>Priority Rating:</u> In order to account for the need for protection at any one site, a five level priority rating system was established. This allowed for consideration of public infrastructure protection, density of residential housing for development of structure overall importance for coastal protection. The ratings range from Level 1 for no infrastructure or residence protection to Level 5 for critical inshore infrastructure protection and/or high density residential. The detailed listing and definitions for the priority categories can be seen in Exhibit B.

Structure Repair / Reconstruction Cost: A preliminary estimation of construction costs to maintain or repair structures was made based on the preliminary field assessment of the structures. A Repair Cost Matrix was developed based on structure type, condition, height and material and can be seen in Exhibit C. Once each structure's type, height, and material classifications were determined, the cost per foot for the structure was determine from the Repair Cost Matrix and multiplied by the length of the structure to obtain the estimated repair/restoration cost. The cost matrix repair costs include a 20 percent construction cost contingency as well as 10 percent costs for engineering and permitting.

<u>Structure Length:</u> The length of each structure is provided and utilized in the development of the repair/reconstruction costs. The lengths are given to the nearest foot and taken as the linear distance along the structure, as determined by the GPS location, which takes into account structure angles and curvature.

Structure Elevation: The elevation of structures was determined in feet from existing information where available. The datum used is NAVD 88 and elevations are to the nearest foot. From a previous study much of the south shore coastal structures had elevations defined based on LIDAR mapping data. Where available structure documentation with elevations was found, in areas with no LIDAR data, the information was included within the structure information. Where there was no LIDAR information or existing documentation, the item has been left blank.

LIDAR (Light Detection and Ranging) is technology that is currently being used for high-resolution topographic mapping by mounting a LIDAR sensor, integrated with Global Positioning System (GPS) and inertial measurement unit (IMU) technology, to the bottom of aircraft and measuring the pulse return rate to determine surface elevations.

<u>FEMA Zone and Elevation:</u> For each structure the FEMA Flood Insurance Rate Maps (FIRM) were researched for their Flood Zone designation and their Base Flood Elevation from the most recent FIRM maps for the specific Town. The elevations are provided in feet on the same datum as the FIRM maps (NGVD) with no adjustments or conversions.

Structure Comments: The engineering team provided a brief description and comment on the structure at the time of the field assessments which is provided in support of the condition rating that was given for the structure.

<u>Pictures:</u> At the time of the field assessments, digital photographs were taken to provide a general overview of the structure. The number of pictures was limited to a maximum of six. The first photograph for each structure is shown on the Structure Assessment Form. The list of all photographs is provided on the form.

Town Documents: Town documents represent the structure information that could be found in the Town's DPW/Engineering Department records. Where particular records could be found, a table of document information was developed and included within the database with limited descriptions.

BCE

I -5 South Coastal

<u>MA - DCR Documents:</u> MA-DCR documents represent the structure information that could be found within DCR - Waterways office in Hingham Where particular records could be found, a table of document information was developed and included within the database with limited descriptions.

MA - DEP Chp. 91 Licenses: MA-DEP Chapter 91 license documents represent the structure information that could be found within MA-DEP Chp 91 records in Boston. Where particular records could be found, they were scanned as pdf files and attached to the structure through the GIS database information. In addition, a table of license document information was developed and included within the database with limited descriptions

<u>USACE Permits:</u> USACE Permits represent the structure information that could be found within the Army Corp of Engineers regulatory office in Concord, MA. Where particular records could be found, they were scanned as pdf files and attached to the structure through the GIS database information. In addition, a table of license document information was developed and included within the database with limited descriptions.

DEVELOPMENT OF REPAIR / RECONSTRUCTION COSTS

A matrix to be used within the database has been developed to assess likely rehabilitation/repair costs to restore the coastal structures to their original design condition. No attempt was made to assess the level of exposure and associated level of protection that might be required to meet current design standards for these structures. These costs are only an estimation to bring these structures back to their original design intent based on 2006 construction costs.

The development of the cost matrix is based on the following:

<u>Structure Condition Ratings</u> – The condition of the coastal structures was determined in the field by the survey crew which was led by an engineer with waterfront structure assessment and design experience. The definitions of the rating criteria utilized for the assessments are presented elsewhere.

The cost implications for each rating condition are as follows:

- A Rating Structures not requiring any maintenance, repair or rehabilitation cost and would not be expected to experience damage if subject to a major coastal storm event
- B Rating Structures requiring limited or no repair and would be expected to
 experience only minor damage if subject to a major coastal storm event. The
 value of these maintenance costs is assumed to be 10 percent of the
 construction cost.
- C Rating Structures requiring moderate to significant level of repair or reconstruction and would be expected to experience significant damage if subject to a major coastal storm event. The structure is presumed to be effective under a major storm event. The value of the repair costs is assumed to be 50 percent of the construction cost.
- D Rating Structures requiring significant level of rehabilitation or total reconstruction and would be expected to experience significant damage or possibly fail if subject to a major coastal storm event. The value of the repair costs is assumed to be 100 percent of the construction cost.

I -6

BCE

• F Rating Structures requiring complete reconstruction and would expect to provide little or no protection from a major coastal storm event. The value of the repair costs is assumed to be 100 percent of the construction cost plus a cost for removal/disposal of the original structure.

<u>Height of Structure</u> – Height of a structure is a major factor in the structure cost and therefore was identified as a significant factor is assessing rehabilitation/repair construction costs. The structures were broken down into four major categories which were:

< 5'	Structures that were less than five feet in height
5'-10'	Structures five to 10 feet in height
10'-15'	Structures over 10 feet to 15 feet in height
> 15'	Structures greater than 15 feet in height – assumed 20 feet typical

<u>Length of Structure</u> – Length is based on field GPS location with measurements rounded to the nearest foot.

<u>Bulkhead / Seawall Structures</u> – These structures are assumed to be constructed out of concrete, steel, stone or wood with each having its own criteria for establishing costs. For each structure type the following was assumed:

- Concrete Seawalls These walls were assumed to be gravity structures with the volume
 of concrete used based on the bottom width being one-half of the structure height. Costs
 of construction were based on a per cubic yard estimate that varied from \$350 to \$630
 per cubic yard depending on the structure height. Values for excavation and demolition
 of existing structure were also included.
- Stone Seawalls These walls were treated the same as concrete seawalls and assumed to be gravity structures with the volume of the structure based on the bottom width being one-half of the structure height. Costs of construction were based on a per cubic yard estimate that varied from \$350 to \$630 per cubic yard depending on the structure height. Values for excavation and demolition of existing structure were also included.
- Steel Bulkheads Steel bulkheads were presumed to be constructed with steel sheet piling. Tie back systems were presumed for structures 10 feet or greater in height. Shorter walls were assumed to have a cantilever design. The total depth of sheeting was presumed to be two times the exposed height. The cost for construction varied from \$40 per square foot to \$60 per square foot plus the cost of excavation and demolition.
- Timber Bulkheads Timber bulkheads were presumed to be constructed with timber piles at eight foot on center, horizontal wales and vertical four inch sheathing. The unit costs for installed materials used were \$1,500 per pile and \$7.50 per bfm.

Revetment Structures – Revetment structures were presumed to be constructed of dry placed (no concrete) stone with a two on one slope and a horizontal toe and crown equal to the thickness layer established for each height condition. The total thickness of the revetment layers varied from six to ten feet with the cost of armor and under-layer stone assumed to be \$50 per ton and the crushed stone base to be \$15 per ton.

BCE

I-7 South Coastal

<u>Groins and Jetties</u> – Groins and jetties were assumed to be the same materials and construction as the revetment structures but would have two sides and therefore double the quantities.

<u>Coastal Beaches</u> – Costs for restoration of Coastal beaches presumed the placement of beach renourishment sands at a 1-on-20 slope over the existing beach conditions. The cost for deposition of sand assumed relatively close source of material and utilized \$20 per cubic yard for the material installed.

<u>Coastal Dunes</u> – Restoration of coastal dunes assumed a cross section of renourished sand with a one-on-four slope on one side of a 25 foot width at the defined dune height. The cost for deposition of sand assumed relatively close source of material and utilized \$20 per cubic yard for the material installed.

<u>Contingency</u> – A contingency of 20 percent was added to all costs to reflect the unknowns associated with this level of rehabilitation/repair estimating.

<u>Engineering and Regulatory Approvals</u> – A ten percent increase to the cost matrix prices was assessed to represent the engineering design and regulatory approval requirements for the restoration of these structures.



South Coastal

I -8

EXHIBIT A

Structure Condition Table – 5 Level Rating System

Co	liminary ondition sessment	Definition Based Upon Perceived Immediacy of Action and Potential to Cause Damage if Not Corrected	Level of Action Required
A	Excellent	Like new condition. Structure expected to withstand major coastal storm without damage. Stable landform (beach, dune or bank). Adequate system exists to provide protection from major coastal storm	None
В	Good	Structure observed to exhibit very minor problems, superficial in nature. Minor erosion to landform is present. Structure / landform adequate to provide protection from a major coastal storm with no damage. Actions taken to prevent / limit future deterioration and extend life of structure	Minor
C	Fair	Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure.	Moderate
		Moderate wind or wave damage to landform exists. Landform may not be sufficient to fully protect shoreline during a major coastal storm. Actions taken to provide additional material for full protection and extended life	
D	Poor	Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure has strong risk of significant damage and possible failure during a major coastal storm Structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major coastal storm.	Major
		Landform eroded, stability threatened. Landform not adequate to provide protection during major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.	
		Conditions of structure/landform may warrant emergency stabilization as failure may result in potential loss of property and/or life. Landform eroded, loss of integrity	
F	Critical	Structure exhibits critical levels of deterioration, section loss, cracking, spalling, undermining, and/or scour. Structure provides little or no protection from a major coastal storm. Actions taken to totally reconstruct structure to regain full capacity.	Immediate
		Landform stability is severely compromised, rate of erosion/material loss may be increasing, and landform does not provide adequate protection from a major coastal storm. Actions taken to recreate landform to adequate limits for full protection from a major coastal storm.	



I -9

EXHIBIT B Priority Rating System - 5 Level Rating System

Pric	eliminary ority Level sessment	Level Based Upon Perceived Immediacy of Action and Presence of Potential Risk to Inshore Structures if Not Corrected	Level of Action Required		
I	None	No Inshore Structures or Residential Dwelling Units Present	Long Term Planning Considerations		
п	Low Priority	Inshore Structures Present with Limited potential for Significant Infrastructure Damage	Future Project Consideration		
Ш	Moderate Priority	Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)	Consider for Active Project Improvement Listing		
IV	High Priority	High Value Inshore Structures with Potential for Infrastructure Damage and/or Moderate Density Residential Dwellings (1-10 dwellings impacted / 100 feet of shoreline)	Consider for Next Project Construction Listing		
V	Immediate / Highest Priority	Critical Inshore Structures Present with Potential for Infrastructure Damage and/or High Density Residential Dwellings Conditions of structure may warrant emergency stabilization as failure may result in potential loss of property and/or life. (>10 dwellings impacted / 100 feet of shoreline)	Consider For Immediate Action Due to Public Safety and Welfare Issues		



I-10

CZM SOUTH SHORE COASTAL INFRASTRUCTURE INVENTORY AND ASSESMENT PROJECT

EXHIBIT C

REPAIR / REHABILITATION COSTING DATA

September 14, 2006

Cost per linear foot of structure

STRUCTURE TYPE	STRUCTURE MATERIALS	STRUCTURE HEIGHT	A	B	RUCTURE CONDITION R	ATING D	F
BULKHEAD/ SEAWALL	CONCRETE	Under 5 Feet	\$0	\$84	\$425	\$850	\$983
	1	5 To 10 Feet	\$0	\$152	\$759	\$1,518	\$1,782
	II.	10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,970
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$4,752
	STEEL	Under 5 Feet	\$0	\$54	\$273	\$546	* \$680
		5 To 10 Feet	\$0	\$165	\$825	\$1,650	\$1,848
	A CONTRACTOR OF THE PARTY OF TH	10 To 15 Feet	\$0	\$251	\$1,254	\$2,508	\$2,772
		Over 15 Feet	\$0	\$343	\$1,716	\$3,432	\$3,795
	STONE	Under 5 Feet	\$0	\$84	\$425	\$850	\$983
		5 To 10 Feet	\$0	\$152	\$759	\$1,518	\$1,782
		10 To 15 Fest	\$0	\$251	\$1,254	\$2,508	\$2,970
	\	Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$4,752
	WOOD	Under 5 Feet	\$0	\$86	\$431	\$862	\$994
		5 To 10 Feet	\$0	\$127	\$632	\$1,265	\$1,463
		10 To 15 Feet	\$0	\$161	\$804	\$1,608	\$1,872
GERMANA EN TORRESTANTA (Over 15 Feet	\$0	\$202	\$1,008	\$2,017	\$2,380
	SAND	Under 5 Feet	\$0	\$26	\$132	\$264	\$264
COASTAL BEACH	N.	5 To 10 Feet	\$0	\$127	\$634	\$1,267	\$1,267
		10 To 15 Feet	\$0	\$224	\$1,122	\$2,244	\$2,244
		Over 15 Feet	\$0	\$396	\$1,980	\$3,960	\$3,960
	SAND	Under 5 Feet	\$0	\$18	\$93	\$188	\$186
OASTAL DUNE		5 To 10 Feet	\$0	\$48	\$238	\$476	\$476
	data in the contract of	10 To 15 Feet	\$0	\$79	\$395	\$790	\$790
Market of Market Land		Over 15 Feet	\$0	\$132	\$660	\$1,320	\$1,320
EVETMENT	STONE	Under 5 Feet	\$0	\$66	\$333	\$664	\$730
	1	5 To 10 Feet	\$0	\$120	\$601	\$1,201	\$1,300
		10 To 15 Feet	\$0	\$157	\$781	\$1,564	\$1,696
		Over 15 Feet	\$0	\$247	\$1,234	\$2,468	\$2,666
ROIN	STONE	Under 5 Feet	\$0	\$132	\$664	\$1,328	\$1,460
	THE PROPERTY	5 To 10 Feet	\$0	\$240	\$1,201	\$2,402	\$2,600
		10 To 15 Feet	\$0	\$314	\$1,564	\$3,128	\$3,392
		Over 15 Feet	\$0	\$494	\$2,468	\$4,937	\$5,333

NOTE: Repair / Rehabilitation Costs include 10% for engineering and regulatory approvals and 20 % construction contingency.

I-11



Section II

Fall River



Section II - Community Findings - City of Fall River

COMMUNITY DESCRIPTION

The City of Fall River consists of a land area of 8.11 square miles out of a total area of 11.98 square miles and had a population of 18,234 in the 2000 census. The City is located on the south coast of Massachusetts and its location can be seen on this report's cover. The estimated length of shoreline is 5.0 miles that are directly exposed to open ocean with the remaining shoreline forming a semi-protected bay with the neighboring Town of Somerset. The City is protected from major coastal storms by both natural and man-made shoreline structures that require maintenance to insure the long term protection of its coastline. The man-made and publicly owned structures that protect the City were investigated for their ability to provide adequate protection from major coastal storms. Structures have been identified as publicly owned, including coastal dunes and beaches, based on evidence of investment of public funds made to create/enhance/maintain these structures. The assessment did not include floating or pile supported structures as they are assumed not to provide any significant coastal protection from major storm events.

STRUCTURE INVENTORY

Within the City of Fall River, there were 17 structures which had public or unknown ownership which provide significant coastal protection. The location of the structures can be seen in Sheets 1 through Sheet 3 in Section II-B of this report. The structures were categorized by their type and by their structural condition based on a preliminary field assessment. The distribution of structures by type and condition can be seen in the following table:

STRUCTURE TYPE AND QUANTITY - Town of Fall River

	Total		Si	tructure Condi	tion Rating		
Primary Structure (1)	Structures	Α	В	С	D	F	Total Length
Bulkhead / Seawall	11	1	4	5	1		5455
Revetment	6			6			4920
Breakwater							
Groin / Jetty							
Coastal Dune							
Coastal Beach	•						
	17	1	4	11	1		10375

Within the above table, the total length of each type of structure is also provided. The structures are listed by the type which is providing the primary coastal protection. Many sites have multiple structure types at the same location (i.e. revetment in front of seawall). These secondary structures, although not identified within these tables, are included in the development of repair/rehabilitation costs.

The development of repair costs has been included by structure type and by condition. In the City of Fall River's case there are a total of 16 structures which would require approximately \$5.1 million to bring all the coastal structures to "A" Rating. Most critical will be the structures in the "D" and "F" classifications as those are assumed to undergo some level of damage or failure during the next major coastal storm event. To reconstruct these structures, identified in the preliminary survey as being in poor condition, an estimated \$301,000 would be required to upgrade the City's coastal protection.

BCE

STRUCTURE REPAIR / RECONSTRUCTION COST - Tow	n of Fall River
--	-----------------

	Total		 St	TUC	ture Condit	on i	Rating	*****		
Primary Structure (1)	Structures	Α	В		С		D	F	Total Co	st
Bulkhead / Seawall	11	\$-	\$ 377,982	\$	1,463,616	5	300.960		\$ 2,142	2,558
Revetment	6		•	\$	2,954,952	-	• • •		\$ 2,954	1,952
Breakwater					_,				\$	-
Groin / Jetty									\$	-
Coastal Dune									\$	_
Coastal Beach									\$	_
	17	\$-	\$ 377,982	\$	4,418,568	\$	300,960 \$		\$ 5,097	7.510

Based on the limited research within the scope of this project research, the presumed ownership of the structures was established on an initial basis and would be subject to more intense review in future tasks. Structures identified as being owned privately were excluded from further consideration. Although ownership of the land on which the structure was located was a factor, the structure ownership was treated as a separate issue from land ownership. For the City of Fall River, the breakdown of structures by assumed ownership is as follows:

STRUCTURE OWNERSHIP / REPAIR COST - Town of Fall River

	Total		St	ruc	ture Condit	ion	Rating		
Primary Structure (1)	Structures	Α	 В		С		D	F	Total Cost
Town Owned	8		\$ 126,753	\$	2,707,452	\$	300,960		\$ 3,135,165
Commonwealth of Massachusetts	9	\$-	\$ 251,229	\$	1,711,116		,		\$ 1,962,345
Federal Government Owned									\$ -
Unknown Ownership									\$ -
	17	\$ -	\$ 377,982	\$	4,418,568	\$	300.960 \$		\$ 5.097.510

The identification of presumed ownership was not based on the investigation of legal documents but relied on property ownership and from construction and regulatory documents that were found. A more detailed investigation of legal documents and agreements would be required where structure ownership is disputed. A more detailed identification of structure type, length, condition and location can be found in Section II-B which contains Structure Assessment Reports for each individual structure found.

SUMMARY

The enclosed reports and associated documents reflects the City of Fall River's coastal structure information that will eventually be input into a state-wide GIS database and will be accessible through MassGIS. This data, when compiled state-wide, will be critical in the development of both short term and long term planning for maintaining and improving Massachusetts coastal protection.

This database will also provide relatively quick access to identify available documentation for these structures as well as the ability to be updated as coastal structure improvements are made.

BCE

Section II - Fall River

Part B

Structure Assessment Reports



River/dwg/Fall River2.dwg

Coast/Fall

File: X:\27652-\27667\South

File: X:\27652-\27667\South Coast\Fall River\dwq\Fall River\dwq



Structure Assessment Form

Town: Fall River

Structure ID: 024-00C-014-002-100

Property Owner:			Location:			Date:		
Local		<u></u> .	Bicentennial Park					
Presumed Structure	e Owner:		Based On Co	mment:				
Local		<u> </u>						
Owner Name: Fall River			Earliest Struc	ture Record:	Estimated	Reconstruction/Repair Cost:		
I dii Nyei	0000000		1977			\$270,270.00		
	levation:	FIRM Map Zone:	FIRM Map Eleva		HS.			
450		V17	1	21	#J_			
Feet Feet N	IAVD 88		Feet NG	VD				
Primary Type:		Material:	Primary Height:					
Revetment	Stone		5 to 10 Feet		*			
Secondary Type:	Seconda	ry Material:	Secondary Heigh	nt:				
Structure Summary								
have been mortarte	ed with concrete.	A boat ramp is in	the middle of the	structure. There is	There is moderate erosion s some section loss in are	as.		
Rating	30.14111011		Priority		II Low Priority			
Level of Action	Moderate			Rating Action	Future Project Consideration			
Description	deterioration, se undermining, ar to withstand ma moderate dama structure to processal storm a structure. Mode landform exists. to fully protect s storm. Actions t	nd but may exhibitection loss, cracking loss, cracking cracking coastal storm was a coastal storm was a coastal storm was a coastal storm was a coastal storm and for extending life and form may not horeline during a maken to provide accordection and extending and exte	ng, spalling, ure adequate with little to to reinforce from major fe of ot damage to to be sufficient major coastal Idition	Description	Inshore Structures Protential for Significa	resent with Limited nt Infrastructure Damage		
Structure Image 024-00C-014-002-1		Stru USA DEF		ugust 18, 1 Prop	·	00C-014-002-100-COE1A 00C-014-002-100-LIC1A		

Structure Assessment Form

Town: Fall River
Structure ID: 024-00C-014-002-200

Property Owner:		Location:	Date:
Local		Bicentennial Park	7/5/2007
Presumed Structure	e Owner:	Based On Comment:	,
Local			
Owner Name:		! Earliest Structure Record:	Estimated Reconstruction/Repair Cost:
Fall River		Unkown	\$97,152.00
Length: Top E	levation: FIRM Map Zone:	ETDM Mon Elouption	
640 F	V17	FIRM Map Elevation:	
1	IAVD 88	Feet NGVD	
Primary Type:	Primary Material:	Primary Height:	
Bulkhead/ Seawall		5 to 10 Feet	
Secondary Type:	Secondary Material:	Secondary Height:	
Structure Summary	/:		
The stone block bu	ilkhead has a concrete walkway acrosome sign of stone rotation and mo	oss the top of it and a park behind it	t. The stones are approximately 3 feet by 2 feet by
1.5 leet. There is	some sign or stone rotation and mo	vernent.	
Condition	В	Priority	II
Rating	Good	Rating	Low Priority
Level of Action	Minor	Action	Future Project Consideration
Description	Structure observed to exhibit very problems, superficial in nature. Mi to landform is present. Structure adequate to provide protection fro coastal storm with no damage. At to prevent / limit future deterioration life of structure.	nor erosion / landform m a major ctions taken	Inshore Structures Present with Limited potential for Significant Infrastructure Damage
Structure Image		ucture Documents:	

Structure Assessment Form

Structure ID: 024-00C-022-013-100

Property Owner: Local Presumed Structure C Local		Location				
Presumed Structure C		IRoute 797	Taunton River	Date:		
	Presumed Structure Owner:				7/5/2007	
ocai	owner:	Based On	Comment:			
Owner Name: Fall River						
			ucture Record:	Estimated F	Reconstruction/Repair Cost:	
		2002			\$600,600.00	
ength: Top Eleva	ation: FIRM Map 2	Zone: FIRM Map Ele	vation:			
1000		V17	21			
Feet Feet NAV	D 88	Feet	NGVD	The same of the same of the	E	
rimary Type:	Primary Material:	Primary Heigh	it:		at the	
evetment	Stone	5 to 10 Feet				
econdary Type:	Secondary Material:	Secondary He	ight:		7	
				The second second		
tructure Summary :						
	ones vary in size but most	are 200 to 300 pound	ds. The stones line the	e edge of a small plot of la	nd.	
Condition C			Priority	III		
Cating Fa	air		Rating	Moderate Priority		
evel of Action M	loderate		Action		tive Project Improvement	
	tructure is sound but may		D ' ' -	Listing		
ui to m st co st la to	deterioration, section loss, cracking undermining, and/or scour. Structure to withstand major coastal storm with moderate damage. Actions taken to structure to provide full protection is coastal storm and for extending life structure. Moderate wind or wave landform exists. Landform may not to fully protect shoreline during a mistorm. Actions taken to provide admaterial for full protection and external storms.		Description	Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)		
ructure Images:	-PHO1A.JPG	Structure Docum	August 2002 Prop		OC-022-013-100-DCR1A	
24-00C-022-013-100- 24-00C-022-013-100-	· · · · · · · · · · · · · · · · · · ·	DEP	November 0 Plan	Accompanying 024-00	C-022-013-100-LIC1A	

Structure Assessment Form

Town: Fall River

Structure ID: 024-00C-022-013-200

Property Owner:				Location:			Date:			
Local				Route 79/Taunton River						7/5/2007
Presumed Structur	e Owner:			Based On Co	omment:					
Local										
Owner Name:			·	Earliest Stru	cture Record:		Es	timated Rec	onstruction/	Repair Cost:
Fall River				2002						\$29,601.00
	levation:	FIRM Map Zor		M Map Eleva						
195		1	/17		21					
	88 dvan			Feet No	GVD					
Primary Type:		Primary Material:	1	nary Height:	*** <u>*</u>		The Tribut			
Bulkhead/ Seawall	1	Stone	J 5 to	o 10 Feet				200		
Secondary Type:	- S	econdary Material:	Sec	ondary Heig	ht:			A SHEET		
i	1		1							
Structure Summar		a cast in place top ar								
Level of Action Description	problems to landfo adequate coastal s	e observed to exhibit so, superficial in nature so, superficial in nature or is present. Structe to provide protection with no damage at / limit future deterion ucture.	e. Minor e ture / land n from a n e. Actions	rosion Iform najor staken	Action Descript	ion	Long Term Pl No Inshore St Units Present	tructures or		Dwelling
Structure Image 224-00C-022-013-2			Structur MA-DCR	e Docume	nts:	Propo	sed River	1024-00C-	022-013-200	D-DCR2A
			DEP		lovember 6		Accompanying		022-013-20	
		r		- a.·		1. m. c	·	1924.000	J. 010-20	LIVEN

Structure Assessment Form

Town: Fall River

Structure ID: 024-00I-001-001-100

Property Owner:		Location:		Date:			
Local		Ferry Street			7/5/2007		
Presumed Structure	e Owner:	Based On Com	ment:	ı			
Local							
Owner Name:		Fordiget Structure	no Decemb	Estimate d Barrest			
Fall River		Earliest Structu Unkown	re Record:	Estimated Reconstruc	\$300,960.00		
.1		Į.			4550,560.00		
The second secon	levation: FIRM Map Zone			THE RESIDENCE TO			
120	V1	:	1	The state of the s			
	IAVD 88	Feet NGVI	D		2.5		
Primary Type: Bulkhead/ Seawall	Primary Material:	Primary Height:			Å		
	•	10 to 15 Feet		Too !	*		
Secondary Type:	Secondary Material:	Secondary Height:					
1	1						
Structure Summary			- 44	ere is erosion at the top. The bulkhe			
missing. The bulkt Condition Rating	nead is adjacent to the private ma D Poor	arina.	Priority	ving outwards. There are some ston I None	es unit are		
Level of Action	Major		Rating		ons		
Description	The state of the s						
Structure Image	00-PHO1A.JPG	ructure Document	s:				
024-001-001-001-10							
024-001-001-001-10	10-PHO1C.JPG						

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-001-100

Key: community-map-block-parcel-structure

Property Owner:		Locatio	n:	Date:	
State		Heritage	State Park	7/5/2007	
Presumed Structu	ire Owner:	Based Or	n Comment:		
State			- Commence		
		J.			
Owner Name: MA-DCR		Earliest 9	Structure Record:	<u> </u>	stimated Reconstruction/Repair Cost:
IN DCR		1961		**************************************	\$485,760.00
ength: Top	Elevation: FIRM Map Zo	ne: FIRM Map E	levation:		
640		/17	21		
Feet Feet	NAVD 88	Fee	t NGVD		Local Car
Primary Type:	Primary Material:	Primary Heig	aht:		
Bulkhead/ Seawa		5 to 10 Feet			THE TREE
Secondary Type:	Secondary Material:	" Secondary H	leiaht:		The Property of Paris
-: /, · / F-31	Total y Hotel Idi	Secondary I	31101	是世队富	
Structure Summa	n/ •				
evel of Action Description	Moderate Structure is sound but may expected deterioration, section loss, craundermining, and/or scour. Stowithstand major coastal stomoderate damage. Actions tastructure to provide full protect coastal storm and for extending structure. Moderate wind or vlandform exists. Landform matofully protect shoreline during storm. Actions taken to provide material for full protection and	acking, spalling, ructure adequate orm with little to ken to reinforce tion from major ng life of vave damage to y not be sufficient g a major coastal le addition	Action Description	on Inshore Struc	ct Consideration ctures Present with Limited Significant Infrastructure Damage
ructure Imag		Structure Docu		(F.112)	
-1-0014-013-001-		MA-DCR	June 1981	Fall River Heritage	024-00N-013-001-100-DCR1A
4 00N 042 004	100-PHO 18.JPG	MA-DCR	July 27, 198	Fall River Heritage	024-00N-013-001-100-DCR1B
4-00N-013-001-	ř	MA DOD		tradition of the state of	
4-00N-013-001-		MA-DCR	June 15, 198	Fall River Heritage	024-00N-013-001-100-DCR1C
4-00N-013-001-	j	MA-DCR	April 02 198	Fall River Heritage	024-00N-013-001-100-DCR1D
4-00N-013-001-		MA-DCR MA-DCR	April 02 198 June 17 198	Fall River Heritage Plan Accompanying	024-00N-013-001-100-DCR1D 024-00N-013-001-100-DCR1E
4-00N-013-001-	[[MA-DCR MA-DCR MA-DCR	April 02 198 June 17 198	Fall River Heritage	024-00N-013-001-100-DCR1D
4-00 N -013-001-	[[MA-DCR MA-DCR	April 02 198 June 17 198	Fall River Heritage Plan Accompanying	024-00N-013-001-100-DCR1D 024-00N-013-001-100-DCR1E

August 25, 1 Fall River Heritage

March 8, 200 Pedestrian Bridge

MA-DCR

MA-DCR

024-00N-013-001-100-DCR1I

024-00N-013-001-100-DCR1J

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-001-100

Key: community-map-block-parcel-structure

DEP

April 16, 199 Fall River Carousel

024-00N-013-001-100-LIC1A

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-001-200

Key: community-map-block-parcel-structure

Property Owner:		Location	n:		Date:		
State		Heritage	State Park		7/5/2007		
Presumed Structur	re Owner:	Based On	Comment:		•		
State	1, 2/2000						
Owner Name:		j Farliect S	tructure Record:	Eat	timestad Decemberation /December Control		
MA-DCR		1981	uucture Record:	ES	timated Reconstruction/Repair Cost: \$168,168.00		
Length: Top E	elevation: FIRM Map	Zone: FIRM Map El	evation:				
4	NAVD 88						
			NGVD	1			
Primary Type: Revetment	Primary Material: Stone	Primary Heig 5 to 10 Feet	2 page 17 miles				
	,	,					
Secondary Type:	Secondary Material:	Secondary H	eignt:				
ı Structure Summar	- i	- 1					
Level of Action Description	Moderate Structure is sound but may deterioration, section loss, undermining, and/or scour. to withstand major coastal moderate damage. Actions structure to provide full protocoastal storm and for extenstructure. Moderate wind olandform exists. Landform to fully protect shoreline du storm. Actions taken to promaterial for full protection a	cracking, spalling, Structure adequate storm with little to taken to reinforce section from major ding life of may not be sufficient ring a major coastal vide addition	Action Description	Inshore Struct	t Consideration tures Present with Limited ignificant Infrastructure Damage		
Structure Image	25:	Structure Docur	ments:				
tructure Image 24-00N-013-001-2		Structure Docur		ıll River Heritage	1024-00N-013-001-200-DCR2A		
			June 1981 Fa	all River Heritage	024-00N-013-001-200-DCR2A 024-00N-013-001-200-DCR2B		
		MA-DCR	June 1981 Fa				
		MA-DCR MA-DCR	June 1981 Fa July 27, 198 Fa June 15, 198 Fa	III River Heritage	024-00N-013-001-200-DCR2B		
		MA-DCR MA-DCR	June 1981 Fa July 27, 198 Fa June 15, 198 Fa April 2, 1986 Fa	III River Heritage	024-00N-013-001-200-DCR2B 024-00N-013-001-200-DCR2C		
		MA-DCR MA-DCR MA-DCR MA-DCR	June 1981 Fa July 27, 198 Fa June 15, 198 Fa April 2, 1986 Fa June 17, 198 Ph	all River Heritage all River Heritage all River Heritage	024-00N-013-001-200-DCR2B 024-00N-013-001-200-DCR2C 024-00N-013-001-200-DCR2D		
		MA-DCR MA-DCR MA-DCR MA-DCR MA-DCR	June 1981 Fa July 27, 198 Fa June 15, 198 Fa April 2, 1986 Fa June 17, 198 Pi January 30, Fa	all River Heritage all River Heritage all River Heritage an Accompanying	024-00N-013-001-200-DCR2B 024-00N-013-001-200-DCR2C 024-00N-013-001-200-DCR2D 024-00N-013-001-200-DCR2E		

August 25, 1

Fall River Heritage

March 8, 200 Pedestrian Bridge

MA-DCR

MA-DCR

024-00N-013-001-200-DCR2I

024-00N-013-001-200-DCR2J

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-001-200

Key: community-map-block-parcel-structure

DEP

April 16, 199 Fall River Carousel

024-00N-013-001-200-LIC2A

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-002-100

Key: community-map-block-parcel-structure

Property Owner:		Location	า:		Date:		
State		Heritage :	State Park		7/5/2007		
Presumed Structur	re Owner:	Based On	Comment:		*		
State							
Owner Name:		Earliest St	tructure Record:	Es	stimated Reconstruction/Repair Cost:		
MA-DCR		1981			\$303,600.00		
ength: Top E	Elevation: FIRM Maj	Zone: FIRM Map Ele	evation:				
400		V17	21				
Feet Feet I	NAVD 88	Feet	NGVD				
Primary Type:	Primary Material:	Primary Heigi	ht:				
Bulkhead/ Seawal	Stone	5 to 10 Feet			engle-se-		
econdary Type:	Secondary Materia	l: Secondary He	eight:	rating the state of the			
			·	ेन, हो			
Structure Summar	y:			A			
Condition Rating Level of Action Description	Fair Moderate Structure is sound but madeterioration, section loss undermining, and/or scouto withstand major coasta moderate damage. Action structure to provide full picoastal storm and for extestructure. Moderate wind landform exists. Landform to fully protect shoreline ostorm. Actions taken to pimaterial for full protection	o, cracking, spalling, or. Structure adequate all storm with little to us taken to reinforce cotection from major ending life of or wave damage to may not be sufficient during a major coastal rovide addition	Priority Rating Action Description	nshore Struc			
024-00N-013-002-100-PHO1A.JPG MA-I MA-I		Structure Docum MA-DCR MA-DCR MA-DCR MA-DCR	June 1981 July 27 1981 June 15, 198 June 15, 198 June 15, 198 June 15, 198 June 1981 Jun	Fall River Heritage Fall River Heritage Fall River Heritage Fall River Heritage	024-00N-013-002-100-DCR1A 024-00N-013-002-100-DCR1B 024-00N-013-002-100-DCR1C 024-00N-013-002-100-DCR1D		
		MA-DCR	June 17, 198	Plan Accompanying	024-00N-013-002-100-DCR1E		
		MA-DCR	January 30 1	all River Heritage	024-00N-013-002-100-DCR1F		
		MA-DCR	February 4,	Steampship Cove -	024-00N-013-002-100-DCR1G		

July 1988

August 25, 1

March 8, 200

Fall River Heritage

Fall River Heritage

Pedestrian Bridge

MA-DCR

MA-DCR

MA-DCR

024-00N-013-002-100-DCR1H

024-00N-013-002-100-DCR1I

024-00N-013-002-100-DCR1J

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-002-100

Key: community-map-block-parcel-structure

DEP

April 16, 199 Fall River Carousel

024-00N-013-002-100-LIC1A

Structure Assessment Form

Town: Fall River
Structure ID: 024-00N-013-003-100

Key: community-map-block-parcel-structure

Property Owner:			Locatio	n:		Date:
State			Heritage State Park			7/5/2007
Presumed Structur	e Owner	:	Based On	Comment:	1	
State						
Owner Name:			Earliest Si	tructure Record:	Fe	stimated Reconstruction/Repair Cost:
MA-DCR			1981			\$62,997.00
	levation:		FIRM Map El	levation:	. Th. 4	
415		V17		21	S. III	
Feet Feet N	88 DVA		Feet	: NGVD		
Primary Type:		Primary Material:	Primary Heig	and the second		
Bulkhead/ Seawall		Stone	5 to 10 Feet			
Secondary Type:	_	Secondary Material:	Secondary Ho	eight:	The second	
					All Street Lines	
Structure Summary						
boardwalk, park ar	nd a buik	s stones that average 3 fee ding.	et by 2 teet in s	ize. There is mir	ior stone settling and b	owing out. Above the wall is a
Condition	В			Priority	II	
Rating	Good			Rating	Low Priority	
Level of Action Description	Minor	re observed to exhibit very		Action		ct Consideration ctures Present with Limited
	to land adequa coastal to preve	ns, superficial in nature. M form is present. Structure te to provide protection fro storm with no damage. A ent / limit future deterioration tructure.	/ landform m a major ctions taken		potential for C	Significant Infrastructure Damage
tructure Image	es:	Stru	acture Docum	ments:		
24-00N-013-003-1			DCR	June 1981	Fall River Heritage	024-00N-013-003-100-DCR1A
		MA-	DCR	July 27, 198	Fall River Heritage	024-00N-013-003-100-DCR1B
			DCR	June 15, 198	Fall River Heritage	024-00N-013-003-100-DCR1C
		<u>-</u>	DCR	April 2, 1986	Fall River Heritage	024-00N-013-003-100-DCR1D
		<u>-</u>	DCR	June 17, 198	Plan Accompanying	024-00N-013-003-100-DCR1E
		<u> </u>	DCR	January 30,	Fall River Heritage	024-00N-013-003-100-DCR1F
			DCR	February 4,	Steamship Cove -	024-00N-013-003-100-DCR1G
		<u> </u>	DCR	July 1988	Fall River Heritage	024-00N-013-003-100-DCR1H
		<u>'</u>	DCR	August 25, 1	Fall River Heritage	024-00N-013-003-100-DCR1I
		1,40,7-		progust 20, 1	to an invite inclinate	#UZ4-UUIY-U 13-UU3-1UU-DUKT

March 8, 200 Pedestrian Bridge

MA-DCR

024-00N-013-003-100-DCR1J

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-003-100

DEP	April 30, 198	Plan Accompanying	024-00N-013-003-100-LIC1A
DEP	June 17, 198	Plan Accompanying	024-00N-013-003-100-LIC1B
DEP	April 16, 199	Fall River Carousel	024-00N-013-003-100-LIC1C

Structure Assessment Form

Town: Fall River Structure ID: 024-00N-013-005-100

Key: community-map-block-parcel-structure

Property Owner:				Locatio	n:				Date:
State				Heritage State Park					7/5/2007
Presumed Structur	re Owner:			Based Or	Comment:				
State									
Owner Name:				Farliact C	tructure Record:		-	ation at a d D-	and the state of t
MA-DCR			1981	ducture Record:			sumated Ke	construction/Repair Cost: \$192,192.00	
	levation:	FIRM	Map Zone:	FIRM Map El	Japanes	0.0000000000000000000000000000000000000			
]	320 V17				19				
Feet Feet I	NAVD 88			Feet	NGVD				calt
Primary Type:		Primary Mate	erial:	Primary Heig	Sec. and All and a second		STORY.		
Revetment		Stone		5 to 10 Feet					4
Secondary Type:	_ S	econdary Ma	terial:	Secondary H	eight:			NEW STATE	
					_	<u> </u>	47		
Structure Summan						_			zed section loss and
Condition Rating Level of Action Description	deteriora undermir to withsta moderate structure coastal s structure landform to fully pr storm. Ac	e is sound buttion, section ing, and/or sand major core damage. At to provide fittorm and for . Moderate exists. Landrotect shorelictions taken	at may exhibit loss, crackin scour. Structu astal storm ctions taken to all protection extending life wind or wave form may not ine during a not to provide ad ction and exte	g, spalling, ure adequate vith little to to reinforce from major e of damage to t be sufficient najor coastal dition	Priority Rating Action Descript	on li F	floderate Pri consider for isting nshore Structure	Active Projectures with per Damage and Dwellings (ect Improvement potential for nd/or Limited 11 dwelling impacted /
Structure Image	25.		Stru	cture Docur	mante:				
024-00N-013-005-1		A.JPG	MA-I		June 1981	Fall River	Heritage	024-00N	-013-005-100-DCR1A
							5.5 000 100-DOINIA		
			MA-C	DCR	July 27, 198	IFall River	Heritage	1024-00N	-013-005-100-DCR1B
			MA-0 MA-0		July 27, 198 June 15, 198	Fall River			-013-005-100-DCR1B -013-005-100-DCR1C
				DCR	June 15, 198	Fall River	Heritage	024-00N	-013-005-100-DCR1C
			MA-I	OCR OCR	June 15, 198 April 2, 1986	Fall River	Heritage Heritage	024-00N 024-00N	-013-005-100-DCR1C -013-005-100-DCR1D
			MA-C	OCR OCR	June 15, 198 April 2, 1986 June 17, 198	Fall River Fall River Plan Acco	Heritage Heritage mpanying	024-00N 024-00N 024-00N	-013-005-100-DCR1C -013-005-100-DCR1D -013-005-100-DCR1E
			MA-E	OCR OCR OCR	June 15, 198 April 2, 1986	Fall River	Heritage Heritage mpanying Heritage	024-00N 024-00N 024-00N 024-00N	-013-005-100-DCR1C -013-005-100-DCR1D

August 25, 1

March 8, 200

Fall River Heritage

Pedestrian Bridge

MA-DCR

MA-DCR

024-00N-013-005-100-DCR1H

024-00N-013-005-100-DCR1I

024-00N-013-005-100-DCR1J

Structure Assessment Form

Town: Fall River
Structure ID: 024-00N-013-005-100

MA-DCR	July 2000	Walkway	024-00N-013-005-100-DCR1K
MA-DCR	August 2002	Proposed River	024-00N-013-005-100-DCR1L
DEP	April 30, 198	Plan Accompanying	024-00N-013-005-100-LIC1A
DEP	June 17, 198	Plan Accompanying	024-00N-013-005-100-LIC1B
DEP	April 16, 199	Fall River Carousel	024-00N-013-005-100-LIC1C

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-020-100

Key: community-map-block-parcel-structure

Property Owner:		Locatio	n:		Date:
State		State Pie	<u> </u>		7/5/2007
Presumed Structur	re Owner:	Based Or	Comment:		3
State					
Owner Name:) Farliest S	tructure Record:	Ee.	timated Reconstruction/Repair Cost:
MA-DCR	<u> </u>	1949	a acture Record.		\$0.00
1125	NAVD 88 Primary Material:	17	19 t NGVD ght: t		
Structure Summar	у:				
and parking behin Condition Rating Level of Action Description	A Excellent None Like new condition. Structure withstand major coastal storm Stable landform (beach, dune Adequate system exists to pro from major coastal storm.	expected to without damage. or bank).	Priority Rating Action Descripti	II Low Priority Future Project on Inshore Struct	er fender piles in front and storage t Consideration tures Present with Limited ignificant Infrastructure Damage
Structure Image	es:	Structure Docu	ments:		
024-00N-013-020-		MA-DCR	April 1949	State Pier Fall river -	024-00N-013-020-100-DCR1A
024-00N-013-020-	100-PHO1B.JPG	MA-DCR	September 1	State Pier Fall River -	024-00N-013-020-100-DCR1B
024-00N-013-020-1	100-PHO1C.JPG	WA-DCR	June 1955	Hurricane Repair	024-00N-013-020-100-DCR1C
	Ţ	MA-DCR	October 196	Proposed Harbor	024-00N-013-020-100-DCR1D
	j	MA-DCR	May 1976	Proposed Pier	024-00N-013-020-100-DCR1E
	ſ	MA-DCR	June 17, 198	Plan Accompanying	024-00N-013-020-100-DCR1F
	Ī	MA-DCR	February 4,	Steamship Cove -	024-00N-013-020-100-DCR1G
	<u>'</u>	MA-DCR	September 2	Northwest Berth	024-00N-013-020-100-DCR1H
	Į	MA-DCR	July 2005	Fall River State Pier	024-00N-013-020-100-DCR1I

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-020-100

Key: community-map-block-parcel-structure

Prepared By: Bourne Consulting Engineering

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-020-200

Key: community-map-block-parcel-structure

Property Owner:		Location	:		Date:
State		Battleship	Cove		7/5/200
resumed Structu	re Owner:	Based On	Comment:		- •
State					
hunor Name		j Farlins C		-	
Owner Name: MA-DCR		1981	ructure Record:	- –	stimated Reconstruction/Repair Cost: \$303,072.00
				ji.	, , , , , , , , , , , , , , , , , , ,
	Elevation: FIRM Map 2	2.11112	evation:		
400		V17	19	•	
Feet Feet	NAVD 88	Feet	NGVD		The state of the s
rimary Type:	Primary Material:	Primary Heigh	nt:	District of the last of the la	
Bulkhead/ Seawa	II Stone	Under 5 Feet		The state of the s	
Secondary Type:	Secondary Material:	Secondary He	eight:		
Revetment	Stone	Under 5 Feet		18	
tructure Summa	ry:				
Rating Level of Action Description	Fair Moderate Structure is sound but may deterioration, section loss, undermining, and/or scour. to withstand major coastal moderate damage. Actions structure to provide full prot coastal storm and for extenstructure. Moderate wind olandform exists. Landform to fully protect shoreline du storm. Actions taken to promaterial for full protection a	cracking, spalling, Structure adequate storm with little to taken to reinforce tection from major ding life of or wave damage to may not be sufficient ring a major coastal vide addition	Rating Action Descripti	Listing Inshore Structure	Active Project Improvement ctures with potential for e Damage and/or Limited Dwellings (<1 dwelling impacted /
t ructure Imag	es:	Structure Docum	nents:		
	jes: 200-PHO2A.JPG	Structure Docum	nents: June 1981	Fall River Heritage	024-00N-013-020-200-DCR2A
				Fall River Heritage	024-00N-013-020-200-DCR2A 024-00N-013-020-200-DCR2B
		MA-DCR	June 1981 July 27, 198		
		MA-DCR	June 1981 July 27, 198	Fall River Heritage	024-00N-013-020-200-DCR2B
		MA-DCR MA-DCR	June 1981 July 27, 198 June 15, 198 April 2, 1986	Fall River Heritage Fall River Heritage	024-00N-013-020-200-DCR2B 024-00N-013-020-200-DCR2C
		MA-DCR MA-DCR MA-DCR MA-DCR	June 1981 July 27, 198 June 15, 198 April 2, 1986	Fall River Heritage Fall River Heritage Fall River Heritage	024-00N-013-020-200-DCR2B 024-00N-013-020-200-DCR2C 024-00N-013-020-200-DCR2D
		MA-DCR MA-DCR MA-DCR MA-DCR MA-DCR	June 1981 July 27, 198 June 15, 198 April 2, 1986 June 17, 198	Fall River Heritage Fall River Heritage Fall River Heritage Plan Accompanying	024-00N-013-020-200-DCR2B 024-00N-013-020-200-DCR2C 024-00N-013-020-200-DCR2D 024-00N-013-020-200-DCR2E

August 25, 1

March 8, 200

Fall River Heritage

Pedestrian Bridge

MA-DCR

MA-DCR

024-00N-013-020-200-DCR2I

024-00N-013-020-200-DCR2J

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-020-200

Key: community-map-block-parcel-structure

MA-DCR

September 2 Northwest Berth

024-00N-013-020-200-DCR2K

Structure Assessment Form

Town:

Town: Fall River

Structure ID: 024-00N-013-021-100

Key: community-map-block-parcel-structure

Property Owner:		Location	n:		Date:
State		Battleship	Cove		7/5/2007
Presumed Structur	re Owner:	Based On	Comment:		P
State					
Owner Name: MA-DCR		Earliest S	tructure Record:	<u>Es</u>	stimated Reconstruction/Repair Cost:
I'M DEK		11361		<u> </u>	\$258,324.00
Length: Top E	Elevation: FIRM Map	Zone: FIRM Map El	levation:	5	
190		V17	19		
Feet Feet M	NAVD 88	Feet	NGVD	1 1	
Primary Type:	Primary Material:	Primary Heig	ht:		
Bulkhead/ Seawall	a speciment of the contract of	5 to 10 Feet			
Secondary Type:	Secondary Materia	Secondary H	eiaht:	THE REAL PROPERTY.	
Revetment	Stone	5 to 10 Feet			
Structure Summary	v :	-		CHEST STATE	
The 5 feet high co	ncrete retaining wall has du	mped riprap in front of	it. The stones a	re approximately 2 feet	by 2 feet by 4 feet in size. There
is moderate under	mining of the seawall from	6 inches to 12 inches.	There is no visib	e cracks or spalling on	the wall.
G. Inc.	0				
Condition	C Fair		Priority	III	-26.
Rating Level of Action	Moderate		Rating	Moderate Pri	•
Description	Structure is sound but ma	v exhibit minor	Action	Listing	Active Project Improvement
	deterioration, section loss undermining, and/or scou to withstand major coasta moderate damage. Action structure to provide full pro- coastal storm and for exte structure. Moderate wind landform exists. Landform to fully protect shoreline d storm. Actions taken to pri material for full protection	, cracking, spalling, r. Structure adequate I storm with little to is taken to reinforce otection from major ending life of or wave damage to may not be sufficient uring a major coastal ovide addition	Descript	Infrastructure	etures with potential for Damage and/or Limited Ewellings (<1 dwelling impacted / noreline)
tructure Image 24-00N-013-021-1 24-00N-013-021-1	100-PHO1A.JPG	Structure Docur MA-DCR MA-DCR MA-DCR	June 1981 July 27, 198	Fall River Heritage Fall River Heritage	024-00N-013-021-100-DCR1A 024-00N-013-021-100-DCR1B
			june 15, 198	Fall River Heritage	024-00N-013-021-100-DCR1C
		MA-DCR	April 2, 1986	Fall River Heritage	024-00N-013-021-100-DCR1D
		MA-DCR	June 17, 198	Plan Accompanying	024-00N-013-021-100-DCR1E
		MA-DCR	January 30,	Fall River Heritage	024-00N-013-021-100-DCR1F
		MA-DCR	February 4,	Steamship Cove -	024-00N-013-021-100-DCR1G
		MA-DCR	July 1988	Fall River Heritage	024-00N-013-021-100-DCR1H

August 25, 1 Fall River Heritage

March 8, 200 Pedestrian Bridge

MA-DCR

MA-DCR

024-00N-013-021-100-DCR1I

024-00N-013-021-100-DCR1J

Structure Assessment Form

Town: Fall River

Structure ID: 024-00N-013-021-100

Key: community-map-block-parcel-structure

Prepared By: Bourne Consulting Engineering

Structure Assessment Form

Town: Fall River
Structure ID: 024-000-023-001-100

Key: community-map-block-parcel-structure

Property Owner:		Locatio	n:			Date:	
Local		Route 79)				7/5/2007
Presumed Structur	re Owner:	Based Or	Comment:			,	
Local						<u> </u>	
Owner Name:		; Earliest S	tructure Record:		Fo	stimated Reconstru	ction/Renair Cost
Fall River		2000			Ţ		\$462,462.00
Length: Top E	Elevation: FIRM Map 2	Zone: FIRM Map El	levation:				
770		V17	19				
Feet Feet I	NAVD 88	Feet	NGVD		Mer-	made with	
Primary Type:	Primary Material:	Primary Heig	ıht:		M bel-labely to a		
Revetment	Stone	5 to 10 Feet					
Secondary Type:	Secondary Material:	Secondary H	eight:				5
Structure Summar	v :						
Condition Rating Level of Action Description	C Fair Moderate Structure is sound but may deterioration, section loss, oundermining, and/or scour. to withstand major coastal s moderate damage. Actions structure to provide full prot coastal storm and for extenstructure. Moderate wind olandform exists. Landform in to fully protect shoreline dur storm. Actions taken to provimaterial for full protection and	cracking, spalling, Structure adequate storm with little to taken to reinforce ection from major ding life of r wave damage to nay not be sufficient ing a major coastal vide addition	Priority Rating Action Descript	ion	High Value In for Infrastruct Density Resid	Next Project Const shore Structures w ure Damage and/o lential Dwellings (* 0 feet of shoreline)	rith Potential r Moderate 1-10 dwellings
Structure Image	2 5:	Structure Docur	mentc:				
)24-00O-023-001-1		MA-DCR	July 2000	Walky	vay	024-00O-023-00	1-100-DCR1A
		MA-DCR	August 2002		sed River	024-000-023-00	
		DEP	November 2	Plan A	Accompanying	024-00O-023-00	

Structure Assessment Form

Town: Fall River
Structure ID: 024-000-024-002-100

Key: community-map-block-parcel-structure

State		Locati	ion:		Date:
i e		Heritag	ge State Park		7/5/200
Presumed Structu	ire Owner:	Based (On Comment:		1
State	<u>, , , , , , , , , , , , , , , , , , , </u>				<u> </u>
Owner Name:		Earliest	Structure Record:	E	stimated Reconstruction/Repair Cost:
MA-DCR		1981		ī [\$188,232.00
Length: Top	Elevation: FIRM I	Map Zone: FIRM Map	Elevation:		
1240		V17	19	, dhe	
Feet Feet	NAVD 88	Fe	eet NGVD	P. Later	
Primary Type:	Primary Materi	al: Primary He	eight:		Maria Company
Bulkhead/ Seawa	II Stone	5 to 10 Fe	et		
Secondary Type:	Secondary Mate	erial: Secondary	Height:		
Structure Summa					
The stone block s it. There is minor	eawall has stones that av	rerage 3 feet by 2 feet in tation. The toe is not vis	n size. There is a was sible to determine it	alkway above the wall	and a small park and road behind
Condition	В		Priority	Ш	
Rating	Good		Rating	Moderate Pri	•
Level of Action	Minor Structure observed to	1.91.91	Action	Consider for Listing	Active Project Improvement
Description	problems, superficial in to landform is present. adequate to provide pr coastal storm with no	n nature. Minor erosion Structure / landform	<i>Descript</i> i	Infrastructure	ctures with potential for e Damage and/or Limited Owellings (<1 dwelling impacted / horeline)
	life of structure.				
tructure Imag	life of structure.	Structure Doc	uments:		
_	life of structure.	Structure Doc MA-DCR	uments:	Fall River Heritage	024-000-024-002-100-DCR1A
24-000-024-002-	life of structure.			Fall River Heritage	024-000-024-002-100-DCR1A 024-000-024-002-100-DCR1B
24-000-024-002-	Jes:	MA-DCR	June 1981		
24-000-024-002-	Jes:	MA-DCR MA-DCR	June 1981 July 27, 198	Fall River Heritage	024-000-024-002-100-DCR1B
24-000-024-002-	Jes:	MA-DCR MA-DCR MA-DCR	June 1981 July 27, 198 June 15, 198	Fall River Heritage Fall River Heritage	024-00O-024-002-100-DCR1B 024-00O-024-002-100-DCR1C
24-000-024-002-	Jes:	MA-DCR MA-DCR MA-DCR MA-DCR	June 1981 July 27, 198 June 15, 198 April 2, 1986	Fall River Heritage Fall River Heritage Fall River Heritage	024-000-024-002-100-DCR1B 024-000-024-002-100-DCR1C 024-000-024-002-100-DCR1D
24-000-024-002-	Jes:	MA-DCR MA-DCR MA-DCR MA-DCR MA-DCR	June 1981 July 27, 198 June 15, 198 April 2, 1986 June 17, 198	Fall River Heritage Fall River Heritage Fall River Heritage Plan Accompanying	024-000-024-002-100-DCR1B 024-000-024-002-100-DCR1C 024-000-024-002-100-DCR1D 024-000-024-002-100-DCR1E
24-000-024-002-	Jes:	MA-DCR MA-DCR MA-DCR MA-DCR MA-DCR MA-DCR MA-DCR	June 1981 July 27, 198 June 15, 198 April 2, 1986 June 17, 198 January 30,	Fall River Heritage Fall River Heritage Fall River Heritage Plan Accompanying Fall River Heritage	024-000-024-002-100-DCR1B 024-000-024-002-100-DCR1C 024-000-024-002-100-DCR1D 024-000-024-002-100-DCR1E 024-000-024-002-100-DCR1F

March 8, 200 Pedestrian Bridge

MA-DCR

024-00O-024-002-100-DCR1J

Structure Assessment Form

Town: Fall River
Structure ID: 024-000-024-002-100

Key: community-map-block-parcel-structure

MA-DCR	July 2000	Walkway	024-000-024-002-100-DCR1K
MA-DCR	August 2002	Proposed River	024-000-024-002-100-DCR1L
DEP	April 30, 198	Plan Accompanying	024-000-024-002-100-LIC1A
DEP	April 16, 199	Fall River Carousel	024-000-024-002-100-LIC1B

Structure Assessment Form

Town: Fall River
Structure ID: 024-00S-022-011-100

Key: community-map-block-parcel-structure

Property Owner:		Location:			Date:
Local		Remington A	venue		7/5/2007
Presumed Structur	re Owner:	Based On Cor	nment:		
Local					
Owner Name:		, Earliest Struct	ture Record:	Estimated R	econstruction/Repair Cost:
Fall River		Unkown			\$112,860.00
	levation: FIRM Map Zone:	FIRM Map Elevat			
90 Foot Foot 8	V17	1	21		SIM
		Feet NG	VD		
Primary Type: Bulkhead/ Seawal	Primary Material: Stone	Primary Height: 10 to 15 Feet			
	15	•			
Secondary Type:	Secondary Material:	Secondary Heigh	<u>t:</u>		
Structure Summar		į.			10.3
	Il with stones that are approximately	y 4 feet by 2 feet b	y 2 feet in size. Th	e ends of the wall have con	ne unraveled. There is a
Condition	С		Priority	1	
Rating	Fair		Rating	None	
Level of Action	Moderate		Action	Long Term Planning Co	onsiderations
Description	Structure is sound but may exhibit deterioration, section loss, cracking undermining, and/or scour. Structure to withstand major coastal storm with moderate damage. Actions taken to structure to provide full protection is coastal storm and for extending life structure. Moderate wind or wave landform exists. Landform may not to fully protect shoreline during a not storm. Actions taken to provide admaterial for full protection and extending for store the store of the sto	g, spalling, ure adequate vith little to to reinforce from major e of damage to t be sufficient najor coastal dition	Description	No Inshore Structures of Units Present	n residential Dwelling
Structure Image 024-00S-022-011-1		cture Documen	its:		

Section II - Fall River

Part C

Structure Photographs



SOURCE: BCE - FIELD PHOTOGRAPHS LOCATION: Bourne Consulting Engineering DATE OF RESEARCH: JULY 2007


OWN: FALL RIVER

Structure Condtion Photo at Time of Survey Structure Condilon Photo at Time of Survey Structure Condtion Photo at Time of Survey Structure Condtlan Photo at Time of Survey Structure Condition Photo at Time of Survey Structure Condition Photo at Time of Survey Structure Condtion Photo at Time of Survey Structure Condtion Photo at Time of Survey Structure Condition Photo at Time of Survey Structure Condtion Photo at Time of Survey Structure Condition Photo at Time of Survey Structure Condition Photo at Time of Survey Structure Condtion Photo at Time of Survey Structure Condilon Photo at Time of Survey Structure Location Sheets DIGITAL IMAGE THIB August 2007 Date Fall River Fali River Fall River Fall River Fall River Fall River Fall River Fell River Fall River Consulting
Engineering
Engineering
Engineering
Engineering
Bourne
Consulting
Engineering
Enginee Entity Contract/ Drawing Number 024-00C-014-002-100-PHO1A.jpg 024-00C-014-002-200-PHO2B.Jpg 024-00C-022-013-100-PHO1A.jpg 024-00C-022-013-100-PHO1B.Jpg 024-00C-022-013-200-PHO2A.jpg 024-00N-013-001-100 024-00N-013-001-100-PHO1A.Jpg 024-00C-022-013-300-PHO3A.Jpg 024-001-001-001-100-PHO1B.Jpg 024-00N-013-001-100-PHO1B.Jpg 024-00N-013-001-200-PHO1A.Jpg 024-00N-013-002-100-PHO1A.jpg 024-00N-013-003-100-PHO1A.Jpg 024-00N-013-005-100-PHO1A.jpg 024-00N-013-020-100-PHO1A.Jpg 024-00N-013-020-100-PHO1B.jpg 024-00N-013-020-100-PHO1C.Jpg 024-00N-013-020-200-PHO2A.Jpg 024-001-001-001-100-PHO1A.jpg 024-00I-001-001-100-PHO1C.Jpg 024-00N-013-021-100-PHO1A.jpg 024-00N-013-021-100-PHO1B.jpg 024-00O-023-001-100-PHO1A.Jpg 024-000-024-002-100 024-000-024-002-100-PHO1A.jpg Document No 024-00C-014-002-100 024-00C-022-013-100 024-00C-014-002-200 324-00C-022-013-300 024-00C-022-013-100 024-00C-022-013-200 024-001-001-001-100 024-001-001-001-100 024-001-001-001-100 024-00N-013-001-100 024-00N-013-001-200 024-00N-013-002-100 024-00N-013-003-100 024-00N-013-005-100 024-00N-013-020-100 024-00N-013-020-100 024-00N-013-020-100 024-00N-013-021-100 024-00N-013-021-100 024-000-023-001-100 024-00N-013-020-200 BCE Structure No

TOWN: FALL RIVER SOURCE: BCE - FIELD PHOTOGRAPHS LOCATION: Bourne Consulting Engineering DATE OF RESEARCH: JULY 2007

Structure Condition Photo at Time of Survey	Structura Condition Photo at Time of Survey
Structure Location	Structure Location
+	-
DIGITAL IMAGE	DIGITAL IMAGE
August 2007	August 2007
Fall River	Fall River
Bourne Consulting Engineering	Bourne Consulting F Engineering
gdf	
24-000-024-002-100 024-000-024-002-100-PHO1B	024-00S-024-011-100 024-00S-024-011-100-PHO1A.jpg
024-000-024-002-100	024-00\$-024-011-100

Massachusetts Coastal Infrastructure and Assessment



024-00C-014-002-100-PHO1A



024-00C-014-002-200-PHO2A




024-00C-022-013-100-PHO1A



024-00C-022-013-100-PHO1B



024-00C-022-013-200-PHO2A




024-00C-022-013-300-PHO3A



024-00I-001-001-100-PHO1A




024-00I-001-001-100-PHO1B



024-00I-001-001-100-PHO1C


Massachusetts Coastal Infrastructure and Assessment



024-00N-013-001-100-PHO1A



024-00N-013-001-100-PHO1B



024-00N-013-001-200-PHO2A



024-00N-013-002-100-PHO1A



024-00N-013-003-100-PHO1A



024-00N-013-005-100-PHO1A



024-00N-013-020-100-PHO1A




024-00N-013-020-100-PHO1B




024-00N-013-020-100-PHO1C


Massachusetts Coastal Infrastructure and Assessment









024-00N-013-021-100-PHO1A



024-00N-013-021-100-PHO1B




024-000-023-001-100-PHO1A



024-00O-024-002-100-PHO1A



024-00O-024-002-100-PHO1B



024-00S-022-011-100-PHO1A

Section II - Fall River

Part D

Structure Documents

TOWN DOCUMENT LIST

MA DCR - DOCUMENT LIST

MA DEP - Ch 91 DOCUMENT LIST

• Copies of License Documents

USACE – PERMIT DOCUMENT LIST

• Copies of Permit Documents



CITY: FALL RIVER
SOURCE: City of Fall River
LOCATION: CITY
DATE OF RESEARCH: JUNE 2007
BCE Structure No

ПO	
Description	
Location	
Sheets	
Title SI	
Date	
Municipality	
Entity	
Contract Drawing Number	
Document No	
Structure No	

Structure Condition Photo at Time of Survey Studiure Condition Photo at Time of Survey Studiure Condition Photo at Time of Survey Studiure Condition Photo at Time of Survey Strudiure Condition Photo at Time of Survey Structure Condtion Photo at Time of Survey Structure Condtion Photo at Time of Survey Structure Condition Photo at Time of Survey Structure Condtion Photo at Time of Survey Structure Conditon Photo at Time of Survey Structure Condtion Photo at Time of Survey Structure Condition Photo at Time of Survey Structure Condition Photo at Time of Survey Structure Condition Photo at Time of Survey eritage State Park to Bicentennial Park Heritage State Park to Bicentennial Park Heritage State Park to Bicentennial Park Noumd 195 Bridge - Battleship Cove Around 185 Bridge - Battleship Cove Around 195 Bridge - Battleship Cove vround 195 Bridge - Battleship Cove 4 4 14 S 28 ιo 20 ĸ 28 2 ιO 2 2 987 Fail River Heritage State Park - Phase 2A
987 Steamehip Cove - Fail River, MA
Fail River Heritage State Park Phase II - Fail
River, MA
99 River, MA
98 River, MA
109 R Waterways Proposed River Access Walkway - Fall River, MA - Prepared for DPW of MA - Division of Proposed River Access Walkway - Fall River, MA Prepared for DPW of MA - Division of Waterwaye Proposed River Access Walkway - Fall River, MA - Prepared for DPW of MA - Division of Waterways

June 1981 Fell River Henitage Stale Park - Fell River

July 27, 1981 Fell River Henitage Stale Park - Fell River

June 15, 1982 Fell River Henitage Stale Park - Fell River

April 02 1989 Fall River Henitage Stale Park - Fall River

April 02 1989 Fall River Henitage Stale Park - Phase I

Plan Accompanying Patition of the

Masschuselt Department of Terviormental

June 17 1988 Management - To Construct and Maintain

Weiserfront Improvements Along the Taunton Fall River June 1981 State Park
Fall River June 1981 Fall River Heritage State Park - Fall River, MA
Fall River July 27, 1981 Fall River Heritage State Park - Fall River, MA
Fall River July 27, 1989 Fall River Heritage State Park - Fall River, MA
Fall River April 2, 1989 Fall River Heritage State Park - Fall River MA
Fall River April 2, 1989 Fall River Heritage State Park - Fhase In Manage April 2, 1989 Fall River Heritage State Park - Phase In Manage April 2, 1989 Fall River Heritage State Park - Phase In Massachusetta Department of Environmental Massachusetta Department of Environmental 97 Fell River Heritage State Perk - Phese 2A
Stanshib Cove - Fell River, MA
Fell River Heritage State Park Phese II - Fall
River, MA
Fall River Heritage State Park Phese II - Fall
Fall River Heritage State Park Phese II - Fall Fall River Heritage Park - Phase 2A Steampship Cove - Fall River, MA Fall River Heritage State Park - Phase 11 - Fall Management - To Construct and Maintain Waterfront Improvements Along the Taunton Massachusetts Department of Environmental Management - To Construct and Maintain Weterfront Improvements Along the Taunton Management - To Construct and Maintain Waterfrort Improvements Along the Taunton Massachusetts Department of Environmental June 1981 Fall River Heritage State Park - Fall River July 27 1981 Fall River Heritage State Park - Fall River June 15, 1982 Fall River Heritage State Park - Fall River April 2, 1986 Fall River Heritage State Park - Phase I Plan Accompanying Petition of the 333-87 MA-DCR Fall River January 30, 1887 Fall River Heritage Park - Phase 2A 8019 MA-DCR Fall River February 4, 1987 | Steamship Cove - Fall River, MA January 30, 1987 F February 4, 1987 Jenuary 30, 1987 F February 4, 1987 S August 25, 1989 August 25, 1989 March 8, 2000 January 30 1987 February 4, 1987 June 17, 1986 June 17, 1986 August 2002 August 2002 August 2002 July 1988 July 1988 July 1988 Date Fall River Fall River Fall River Fall River
 40-81
 MA-DCR
 Fall River

 991-80
 MA-DCR
 Fall River

 48-81A
 MA-DCR
 Fall River

 157-84
 MA-DCR
 Fall River
 Municipality Fall River MA-DCR MA-DCR MA-DCR 4 40-81 MA-DCR 3 991-80 MA-DCR C 48-81A MA-DCR 157-84 MA-DCR 024-00N-013-001-200 024-00N-013-001-200-DCR2F 333-87 MA-DCR 024-00N-013-001-200-DCR2G 8019 MA-DCR Entlty 024-00N-013-001-200 024-00N-013-001-200-DCR2A 40-61 024-00N-013-001-200-DCR2B 691-90 024-00N-013-001-200-DCR2B 691-90 024-00N-013-001-200-DCR2D 167-94 024-00N-013-001-200-DCR2D 167-94 333-87 024-00N-013-001-100-DCR1A 40-81 024-00N-013-001-100-DCR1B 991-80 024-00N-013-001-100-DCR1C 48-81A 024-00N-013-001-100-DCR1D 157-84 442-88 074-00 074-00 322-87 03-1601 322-87 024-00N-013-003-100-DCR1E 03-1601 03-1601 442-88 074-00 024-00N-013-002-100-DCR1E 03-1601 322-87 442-88 3481 3481 3481 024-00N-013-001-100-DCR1E 024-00N-013-001-200-DCR2E 024-00N-013-001-100-DCR1H 024-00N-013-001-100-DCR1J 024-00N-013-002-100 024-00N-013-002-100-DCR1A 024-00N-013-002-100 024-00N-013-002-100-DCR1B 024-00N-013-002-100 024-00N-013-002-100-DCR1D 024-00N-013-002-100 024-00N-013-002-100-DCR1D 024-00N-013-003-100 024-00N-013-003-100-DCR1A 024-00N-013-003-100 024-00N-013-003-100-DCR1B 024-00N-013-003-100 024-00N-013-003-100-DCR1C 024-00N-013-003-100 024-00N-013-003-100-DCR1C 024-00N-013-003-100 024-00N-013-003-100-DCR1C 024-00N-013-003-100 024-00N-013-003-100-DCR1F 024-00N-013-003-100 024-00N-013-003-100-DCR1G 024-00C-022-013-100-DCR1A 024-00C-022-013-300-DCR3A 024-00N-013-002-100-DCR1F 024-00N-013-002-100-DCR1G 024-00N-013-002-100-DCR1J 024-00N-013-001-100-DCR1I 024-00N-013-001-200-DCR2H 024-00N-013-001-200-DCR2I 024-00N-013-001-200-DCR2J 024-00N-013-002-100-DCR1H 024-00N-013-002-100-DCR1I 024-00C-022-013-200-DCR2A Document No 024-00N-013-001-100 [
024-00N-013-001-100 [
024-00N-013-001-100 [
024-00N-013-001-100 [024-00N-013-001-100 024-00N-013-001-200 024-00N-013-002-100 024-00N-013-003-100 024-00C-022-013-100 024-00C-022-013-200 024-00C-022-013-300 024-00N-013-001-100 024-00N-013-001-100 024-00N-013-001-100 024-00N-013-001-200 024-00N-013-001-200 024-00N-013-001-200 024-00N-013-002-100 024-00N-013-002-100 024-00N-013-002-100 BCE Structure No

TOWN: FALL RIVER SOURCE: MA-DCR LOCATION: MA-DCR BOSTON and HINGHAM, MA DATE OF RESEARCH: JULY 2007

												Revetment	Revelment	Riprap	Retaining Walls	Riprap	Stone Walls and Riprap	Concrete Retaining Wall			Steel Sheet Bulkhead	Existing Conditions										Bulkhead
							Around 195 Bridge - Battleship Cove					Davol Street	Heritage State Park to Bicentennial Park	State Pier	Mill Street and Water Street	State Pler	Davol Street	State pier	Around 195 Bridge - Battleship Cove		Bettleship Cove	Water Street			Around 195 Bridge - Battleship Cove		i					Battleship Cove
2	, e	┸		4 4	14	48	2	ŀ	2 2	58	u	, 6	2	6	23	-	-		9	2	6		14	4 a	LO .		2	7	56	s	_	9
Fall River Heritage State Park Phase II - Fall	River, MA Fall River Heritage State Park Phase II - Fall		State Park	Fall River Heritage State Park - Fall River, MA	Fall River Heritage State Park - Fall River, MA	Fall River Heritage State Park - Phase I	Plan Accompanying Petition of the Massachusetts Department of Environmental Management - To Construct and Maintain Welenfront Improvements Along the Taurdon River	Fall River Heritage Park - Phase 2A	Steamship COVe - Fall KIVer, MA Fall River Heritage State Park Phase II - Fall	River, MA Fall River Heritage State Park Phase II - Fall	River Pedestrian Bridge and Seawall Repeirs Heritage	State park Walkway Improvements - Davol Street - Teunton River	Proposed River Access Walkway, Fall River, MA- Prepared for DPW of MA - Division of Waterways	State Pier Fall river - Chapter 865 Acts of 1945, Chapter 308 Acts of 1947 - Wharf and Footings	State Pier Feil River - Chapter 665 Acts of 1945, Chapter 208 Acts of 1947, Chapter 758 Acts of 1951 - Bullding Approaches/Utititiles	Humicane Repair Proposed Riprap Shore Protection - State Pier - Fall River - Prepared for DPW of MA - Division of Waterways	Proposed Harbor Improvements, Berthing Area and Mooring Facilities City Pler - Teunton River	Proposed Pler Improvements - Miscellaneous Repairs - State Pier - Fall River	Plan Accompanying Petition of the Massechusetts Department of Environmental Management - To Construct and Maintain Waterfront Improvements Along the Taunton Ryver	_	Northwest Berth Expansion Fall River State Pier - Prepared for DPW of MA - Division of Waterways	Fall River State Pier Survey	Fall River Heritage State Park - Fall River	Fall River Heritage State Park - Fall River, MA	Plan Accompanying Petition of the Massachusetts Department of Environmental Management - To Construct and Maintain Waterfrort Improvements Along the Taunton Ryver	Fall River Heritage State Park - Phase 2A	Steamship Cove - Fall River, MA	Fall River Heritage State Park Phase II - Fall River	Fall River Heritage State Park Phase II - Fall River, MA	Pedestrian Bridge and Seawall Repairs - Heritage State Park		Northwest Berth Expansion Fall River State Pier -
fulv 1888	August 25, 1080	Mark a 2000	March 8, 2000	June 1981	June 15, 1982	April 2, 1986	June 17, 1986	January 30, 1987	Luly 1888	Aurust 25 1889	Marrie 9 2000	July 2000	August 2002	April 1949	September 1952	June 1855	October 1988	May 1976	June 17, 1986	February 4, 1987	September 2005	July 2005	July 27, 1981	June 15, 1982	June 17, 1886	January 30, 1987	February 4, 1987	July 1989	August 25, 1989	March 8, 2000		September 2004
Tall River	Toylo Ilo		Fall River	Fall River	Fall River	Fall River	Fall River	Fall River	Fall River	Fall River	Toli Divor	Fall River	Fall River	Fall River	Fall River	Fall River	Fall River	Fall River	Fall River	Fall River	Felf River	Fall River	Fall River	Fall River	Fall River	Fall River	Fall Rivor	Fall River	Fall River	Fall River		Fall River
MA-DCR	MADOR	100	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	000	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR	MA-DCR		MA-DCR
322.87	442.88	2 2		40-81				333-87	322-87	442-88	00,720	3416	3481	1083	1114	1528	2645	2854	03-1601	8019	3518	3536	\top	\vdash		333-87	8019	322-87	442-88	074-00		3518
024-00N-013-003-100-DCB1H	024-00N-013-003-100-DCB11	1 700 000 000 000 000	024-00N-013-003-100-DCR1J	024-00N-013-005-100-DCR1A	024-00N-013-005-100-DCR1C	024-00N-013-005-100-DCR1D	024-00N-013-005-100-DCR1E	024-00N-013-005-100-DCR1F		024-00N-013-005-100-DCB1	034 00N 043 00E 400 DCB41	024-00N-013-005-100-DCR1K	024-00N-013-005-100-DCR1L	024-00N-013-020-100-DCR1A	024-00N-013-020-100-DCR1B	024-00N-013-020-100-DCR1C	024-00N-013-020-100-DCR1D	024-00N-013-020-100-DCR1E	024-00N-013-020-100-DCR1F	024-00N-013-020-100-DCR1G	024-00N-013-020-100-DCR1H	024-00N-013-020-100-DCR11	024-00N-013-020-200-DCR2B	024-00N-013-020-200 024-00N-013-020-200-DCR2C		024-00N-013-020-200-DCR2F	024-00N-013-020-200-DCR2G	024-00N-013-020-200 024-00N-013-020-200-DCR2H	024-00N-013-020-200-DCR2i	024-00N-013-020-200-DCR2J		024-00N-013-020-200-DCR2K
024-00N-013-003-100	024-001-013-003-100	021 -000 -100 -100	024-00N-013-003-100	024-00N-013-005-100	024-00N-013-005-100	024-00N-013-005-100	024-00N-013-005-100	024-00N-013-005-100			234 DON 042 DDE 400	024-00N-013-005-100	024-00N-013-005-100	024-00N-013-020-100	024-00N-013-020-100	024-00N-013-020-100	024-00N-013-020-100	024-00N-013-020-100	024-00N-013-020-100	024-00N-013-020-100	024-00N-013-020-100	024-00N-013-020-100	024-00N-013-020-200 024-00N-013-020-200	024-00N-013-020-200	024-00N-013-020-200	024-00N-013-020-200	024-00N-013-020-200	024-00N-013-020-200	024-00N-013-020-200	024-00N-013-020-200		024-00N-013-020-200


SOURCE: MA-DCR LOCATION: MA-DCR BOSTON and HINGHAM, MA DATE OF RESEARCH: JULY 2007


TOWN: FALL RIVER

Revelment tevetment Revetment Revetment Heritage State Park to Bicentennial Park Heritage State Park to Bicentennial Park Around 195 Bridge - Battleship Cove Around 195 Bridge - Battleship Cove Davol Street Davo! Street 9 9 4 7 26 56 3 N цŋ co 8 ю River
Pedestrian Bridge and Seawall Repairs - Heritage
State park Proposed River Access Walkway, Fall River, MA -Prepared for DPW of MA - Division of Waterways River
Pedestrian Bridge and Seawall Repairs Heritage
State Park
Walkway Improvements - Davol Street, Taunton Proposed River Access walkway - Fall River, MA . Prepared for DPW of MA - Division of Waterways Valkway Improvements - Davol Street - Taunton Fall River Heritage State Park - Fell River, MA Plan Accompanying Petition of the Massachusetta Department of Environmental Management - To Construct and Maintein Waterfront Improvements Along the Taurtion Fail River Heritage State park - Phase 2A Steamship Cove - Fall River, MA Fall River Heritage State Park Phase II - Fall River Fall River Hentage State Park Phase II - Fall all River Herltage State Park Phase II - Fall January 30, 1987 February 4, 1987 Fall River April 2, 1986 August 25, 1989 March 8, 2000 August 25, 1989 March B, 2000 June 17, 1986 July 1988 August 2002 August 2002 July 2000 July 2000 Fall River MA-DCR 333-87 024-000-024-002-100 024-000-024-002-100-DCR1A 40-81 024-000-024-002-100-DCR1B 981-80 024-000-024-002-100-DCR1B 981-80 024-000-024-002-100 024-000-024-002-100-DCR1C 488-91 024-000-024-002-100 024-000-024-002-100-DCR1D 157-84 333-87 03-1601 157-84 03-1601 322-87 442-88 074-00 322-87 442-88 074-00 3416 3416 3481 3481 024-00N-013-021-100 | 024-00N-013-021-100-DCR1D | 024-000-024-002-100-DCR1E 024-00N-013-021-100-DCR1E 024-00N-013-021-100 024-00N-013-021-100-DCR1f 024-00N-013-021-100 024-00N-013-021-100-DCR1G 024-00N-013-021-100 024-00N-013-021-100-DCR1H 024-00O-024-002-100-DCR1F 024-00O-024-002-100-DCR1G 024-00N-013-021-100-DCR11 024-00N-013-021-100-DCR1J 024-000-023-001-100-DCR1A 024-000-023-001-100-DCR1B 024-000-024-002-100-DCR1H 624-000-024-002-100-DCR1I 024-000-024-002-100 024-000-024-002-100-DCR1J 024-000-024-002-100 024-000-024-002-100-DCR1K 024-000-024-002-100-DCR1L 024-000-024-002-100 024-000-024-002-100 024-000-024-002-100 024-00N-013-021-100 024-00N-013-021-100 024-00N-013-021-100 024-000-023-001-100 024-000-023-001-100 024-000-024-002-100 024-000-024-002-100 024-000-024-002-100


TOWN: FALL RIVER SOUNCE: DED LOCATION: BOSTON, MA DATE OF RESEARCH: JULY 2007

BCE Structure No	Document No	Contract/ Drawing	Entity	Municipality	Date	Trile	Sheets	Location	Description
024-00C-014-002-100	024-00C-014-002-100-LIC1A	9411	DEP	Fall River	November 6, 2002	Plan Accompanying Petition of City of Fall River to Construct Timber Walkway, Pler, and Concrete Walkway, Pler, and Concrete Makway, Buikhead. And Revetment Repairs.	7	Taunion River	Bulkhead and Revetment
024-00C-022-013-100	024-00C-022-013-100-LIC1A	9411	DEP	Fall River	November 6, 2002	Plan Accompanying Petition of: City of Fall River to Construct Timber Walkway, Pler, and Concrete Walkway	7	Taunton River	Bulkhead and Revetment
024-00C-022-013-200	024-00C-022-013-200 024-00C-022-013-200-LIC2A	9411	DEP	Fall River	Navember 6 2002	Plan Accompanying Petitioni of City of Fall River to Construct Timber Walkway Pier and Concrete Walkway, Bulkhead, Revelment Repairs	7	Taunton River	Bulkhead and Revelment
024-00C-022-013-200	024-00C-022-013-200 024-00C-022-013-300-LIC3A	9411	DEP	Fall River	November 6, 2002	Plan Accompanying Petitioni of City of Fall River to Construct Timber Walkway Pler and Concrete Walkway, Bulkhead, Revetment Repairs	7	Taunton River	Bulkhead and Revetment
024-00N-013-001-100	024-00N-013-001-100 024-00N-013-001-100-LIC1A	2641	DEP	Fall River	April 16, 1991	Fall River Carousel and Herligge Park Existing Conditions and Existing Waterways Licenses, City of Fall River (Bristol County), Massachusetts	12	Davol Street and Central Street	Extension of Existing Boardwalk and Dock Facilities - Repair and Reconstruction of Existing Seawall and Riprap
024-00N-013-001-200	024-00N-013-001-200 024-00N-013-001-200-LIC2A	2641	DEP	Fall River	April 16, 1991	Fair River Carousel and Heritage Park Existing Conditions and Existing Waterways Licenses, City of Fall River (Bristol County), Massachusetts	12	Davol Street and Central Street	Extension of Existing Boardwalk and Dock Facilities; Repair and Reconstruction of Existing Seawall and Riprap
024-00N-013-002-100	024-00N-013-002-100-LIC1A	2641	DEP	Fall River	April 16, 1991	Fall River Carousel and Herligge Park Existing Conditions and Existing Waterways Licenses, City of Fell River (Bristol County), Massachusetts	12	Davol Street and Central Street	Extension of Existing Boardwalk and Dock Facilities; Repair and Reconstruction of Existing Seawall and Riprap
024-00N-013-003-100	024-00N-013-003-100 024-00N-013-003-100-LIC1A	845	DEP	Fall River	April 30, 1982	Plan Accompanying Petition of Massachusetts Department of Environmental Management to Construct and Maintain Waterfront Improvements at Fall River Hartage State Park in the Taurion River, City of Fall River, Massachusetts	10	Frontage Road	Meintain Existing Seawall and Boardwalk
024-00N-013-003-100	024-00N-013-003-100 024-00N-013-003-100-LIC1B	1831	DEP	Fall River	June 17, 1986	Plan Accompanying Petition of the Massachusetts DEM to Construct and Mainiain Walerfront Improvements Along the Taunton River, Fall River, County of Bristol, MA	2	Davol Street	Maintain Existing Seawall and Boartwalk
024-00N-013-003-100	024-00N-013-003-100 024-00N-013-003-100-LIC1C	2641	DEP	Fall River	April 16, 1991	Fall River Carousel and Herliage Park - Existing Conditions and Existing Waterways Licenses, City of Fall River (Bristol County), Massachusetts	12	Davol Street and Central Street	Extension of Existing Boardwalk and Dock Facilities; Repair and Reconstruction of Existing Seawall and Riprep
024-00N-013-005-100	024-00N-013-005-100-LIC1A	845	DEP	Fall River	April 30, 1982	Plan Accompanying Petition of Massachusetts DEM to Construct and Maintain Waterfrort Improvements at Fall River Horlage State Park in the Tauriton River, City of Fall River, County of Bristol, Massachusetts	10	Fronlage Road	Maintain Existing Seewall and Boartwalk
024-00N-013-005-100	024-00N-013-005-100 024-00N-013-005-100-LIC1B	1831	DEP	Fall River	June 17, 1986	Plan Accompanying Petition of the Massachusetts DEM to Construct and Maintain Waterfront Improvements Along the Taunton River, Fall River, County of Bristol, Massachusetts	S.	Davol Street	Maintain Existing Seawall and Boardwalk
024-00N-013-005-100	024-00N-013-005-100-LIC1C	2641	DEP	Fall River	April 16, 1991	Fall River Carousel and Heritage Park Existing Conditions and Existing Waterways Licenses, City of Fall River (Bristol County), Messachusetts	12	Davol Street and Central Street	Extension of Existing Boardwalk and Dock Facilities; Repair and Reconstruction of Existing Seawall and Riprap
024-000-023-001-100	024-000-023-001-100 024-000-023-001-100-LIC1A	9411	DEP	Fall River	November 6 2002	Plan Accompanying Petition of City of Fall River to Construct Timbe Walkway, Pler, and Concrete Walkway, Bulkhead and Revetment Repairs, Raling, Walkway Lighting and Fending - Taumon River, Fall River, Massachusettis	7	Taunton River	Bulkhead and Revetment
024-000-024-002-100	024-000-024-002-100 024-000-024-002-100-LIC1A	845	DEP	Fall River	April 30, 1982	Plan Accompanying Petition of Massachusetts DEM to Construct and Maintain Waterfront Improvements at Fall River Heritage State Park in the Taurton River, Clip of Fall River, County of Bristol, Massachusetts	10	Frontage Road	Maintain Existing Seawall and Boardwalk
024-000-024-002-100	024-00C-024-002-100 024-00C-024-002-100-LIC1B	2641	DEP	Fall River	April 16, 1991	Fall River Carousel and Heritage Park Existing Conditions and Existing Waterways Licenses, City of Fall River (Bristol County), Massachusetts	12	Davol Street and Central Street	Extension of Existing Boardwalk and Dock Facilities; Repair and Reconstruction of Existing Seewall and Riprap







LICENSE PLAN NO. 94//
Approved by Department of Environmental Production
Date: NOV 0 & 2000



0' 50' 100'


SUFET 7 OF 5






SHEET 5 OF 7


CONCRETE WALKWAY SECTION E-E



CONCRETE WALKWAY SECTION F-F



PRECAST CONCRETE CATCH BASIN




TYPICAL STEEL HANDRAIL DETAIL


SCALE: 1"=5"






CIET - AF -









Approved by Department of Environmental Protection


NIV 0 6 2000



0' 50' 100'


CHEET 7 OF 5






SHEET 5 OF 7


CONCRETE WALKWAY SECTION E-E



CONCRETE WALKWAY SECTION F-F



PRECAST CONCRETE CATCH BASIN




TYPICAL STEEL HANDRAIL DETAIL


SCALE: 1=5'






-







NOV 0 6 2002


STE SYONAL ENG


LICENSE PLAN NO. 94//
Approved by Department of Environmental Production
Date: NIIV C 4 2000 0 6 2002 V17, EL. 18 部 調 NEW CONCRETE WALKWAY-EXISTING GUARDRAIL BONEA OPAIENT AUTHORITY T CENTER V17, EL, 21 FALL RIVER REDEVELOPHE 1 GOVERNMENT OF FALL RIVER, U RESET RAVELLED STONE, TYP. 3 -7.6 STREET WALKWAY AND PIER STREET 200 REVENDENT REPAIRS AS LINESTED BY THE ENGINEER LIST SE, STA, 2+65 TO 10+80 LIMIT OF WORK DAVOL -FEMA PLOOD DESIGNATION 100 ABOVE MLW. (TYP) DEPT. OF PUBLIC WORKS BASELINE BASELINE STONE REVENUENT (TYP) -NEW TIMBER WALKWAY DAVOL ---30'x30' PIER HEAD x -61 -- 12"W TIMBER PIER , -6.2 **Цантіка** (түр.) TAUNTON RIVER 140,4 TYPE,) DAVAD BL MINE SETT8 V17, EL. 21 SADNAL REE SHEET STAURANT PLONES -

50'

100


CHIEFT 7 OF 5






SHEET 5 OF 7


CONCRETE WALKWAY SECTION E-E



CONCRETE WALKWAY SECTION F-F



PRECAST CONCRETE CATCH BASIN




TYPICAL STEEL HANDRAIL DETAIL


SCALE: 1"=5"




0' 5' 0' 10'


CUTET C AF -









LICENSE PLAN NO. 94//
Approved by Department of Environmental Production
Date: NIIV 0 & 2000



0' 50' 100'


CULLY 2 VE -






SHEET 5 OF 7


CONCRETE WALKWAY SECTION E-E



CONCRETE WALKWAY SECTION F-F



PRECAST CONCRETE CATCH BASIN





TYPICAL STEEL HANDRAIL DETAIL
SCALE: 17=5'




0' 5' 0' 10


CUTET C AF -









Approved by Department of Environmental Production
Date: NIIV 0.6. 2000




0' 50' 100'


CULLT 2 VE 4









CONCRETE WALKWAY SECTION E-E



CONCRETE WALKWAY SECTION F-F



PRECAST CONCRETE CATCH BASIN





TYPICAL STEEL HANDRAIL DETAIL


SCALE: 1"=5"




























PLAN AND SECTION OF FLOAT EXTENSION NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL FLOAT SECTION Prepared Ric HMM Associates Inc. Concord MA

LICENSE PLAN NO. 264

Actioned by Casel and of Environmental Propagation APR 1 6 1991




024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL SECTION AT BOARDWALK EXTENSION

NOT. TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL BOARDWALK SECTION LICENSE PLAN NO. 264/

Account by Gerrie and of Embournested Property

Date ADD 4 A 1001

024-00N-013-002-100 024-00N-013-001-10C 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL RIPRAP REVETMENT RECONSTRUCTION NOT TO SCALE

NOTES:

- 1. TYPICAL STONE SIZING MAY VARY ACCORDING TO CONTRACTOR'S SPECIFICATIONS.
- EXISTING DUMPED STONE RIPRAP MATERIAL WILL BE RE-USED TO GREATEST EXTENT PRACTICAL.
- PLAN IS FOR PERMITTING PURPOSES ONLY.




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL RIPRAP REVETMENT

LICENSE PLAN NO. 2641

Approved by Department of Environmental Protection

APR 16 1991





FALL RIVER CAROUSEL AND HERITAGE PARK JIB CRANE DETAIL


Presented By HUM Approinted Inc Concord MA

LICENSE PLAN NO. 2641

Approved by Depretuent of Environmental Ambadian

Detr ADD 4 C 1001

024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



CROSS SECTION

NOT TO SCALE





FALL RIVER CAROUSEL
AND HERITAGE PARK
TYP. CAROUSEL BLDG. CROSS SECTION


LICENSE PLAN NO. 2641


Accuracy by Cophilicant of Environmental Protection


PAAL D F UUR 250

















PLAN AND SECTION OF FLOAT EXTENSION NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL FLOAT SECTION

Prepared By: HMM Associates Inc. Concord MA


LICENSE PLAN NO. 264

Actioned by Decisional of Environmental Protection

APR 1 6 1991



024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL SECTION AT BOARDWALK EXTENSION

NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL BOARDWALK SECTION LICENSE PLAN NO. 2641

Accessed by Descharat of Bustonnessal Proceedings

Date ADD 4 & 1001

024-00N-013-002-100 024-00N-013-001-10C 024-00N-013-001-200 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL RIPRAP REVETMENT RECONSTRUCTION NOT TO SCALE

NOTES:


- 1. TYPICAL STONE SIZING MAY VARY ACCORDING TO CONTRACTOR'S SPECIFICATIONS.
- 2. EXISTING DUMPED STONE RIPRAP MATERIAL WILL BE RE-USED TO GREATEST EXTENT PRACTICAL.
- 3. PLAN IS FOR PERMITTING PURPOSES ONLY.



FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL RIPRAP REVETMENT

LICENSE PLAN NO. 2641

Approved by Department of Environmental Protection
Deter APR 1 6 1991








FALL RIVER CAROUSEL AND HERITAGE PARK

LICENSE PLAN NO. 2641

Appreciate the Commission of Environmental Projection

ADD & R 1001

024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



CROSS SECTION NOT TO SCALE





FALL RIVER CAROUSEL
AND HERITAGE PARK
TYP. CAROUSEL BLDG. CROSS SECTION

LICENSE PLAN NO. 2641


Accorded by Coopen.and of Environmental Protection


PAR ANN A C 1001








(












PLAN AND SECTION OF FLOAT EXTENSION NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL FLOAT SECTION


LICENSE PLAN NO. 264

Actioned by Case Front of Environmental Protection Date: APR 16 1991

Prepared By: HMM Associates Inc. Concord MA




024-00N-013-002-100 024-00N-013-003-10 0 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL SECTION AT BOARDWALK EXTENSION

NOT. TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL BOARDWALK SECTION

LICENSE PLAN NO. 2641

Accessed by Description of Environmental Properties

Date ADD 4 A 1001

024-00N-013-002-100 024-00N-013-001-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL RIPRAP REVETMENT RECONSTRUCTION NOT TO SCALE

NOTES:


- 1. TYPICAL STONE SIZING MAY VARY ACCORDING TO CONTRACTOR'S SPECIFICATIONS.
- 2. EXISTING DUMPED STONE RIPRAP MATERIAL WILL BE RE-USED TO GREATEST EXTENT PRACTICAL.
- 3. PLAN IS FOR PERMITTING PURPOSES ONLY.



FALL RIVER CAROUSEL
AND HERITAGE PARK
TYPICAL RIPRAP REVETMENT

LICENSE PLAN NO. 2641

Approved by Department of Environmental Protection
Date: APR 1 6 1991








FALL RIVER CAROUSEL AND HERITAGE PARK CRANE DETAIL

LICENSE PLAN NO. 2641

According Copyright of Endocumental Projection

ADD & & 1001

024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



CROSS SECTION NOT TO SCALE





FALL RIVER CAROUSEL
AND HERITAGE PARK
TYP. CAROUSEL BLDG. CROSS SECTION


LICENSE PLAN NO. 2641


स्ट्राव्यक्री by Coopilerad of Environmental Protection

PARE DE MARKE









PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT


TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.

82ω-029 SHEET 3 OF 10

UCENSE PLAN NO.845

APRIL 30, 1982.

> ALL WOOD TO BE PRESSURE TREATED WITH PRESERVATIVE




PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.

UCENSE PLAN NO. 845

April 30,1982.




PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY-OF FALL RIVER, COUNTY OF BRISTOL, MASS.

BZW-029 SHEET 5 OF 10

LICENSE PLAN NO. 845

Approved by Department of Environmental Quality Engineering APRIL 30, 1982.





ENVIRONMENTAL MANAGEMENT
TO CONSTRUCT AND MAINTAIN WATERFRONT
IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK
IN THE TAUNTON RIVER, CITY OF FALL RIVER,
COUNTY OF BRISTOL, MASS.

UCENSE PLAN NO: 845

Convey by Department of Environmental Quality Engineer

April 30, 1982






ELEVATION OF FLOAT & RAMP

BELOW SCALE 1/8"=1-0

1012345678

SCALE IN FEET



SCALE IN FEET BZW-DZ9

PLAN ACCOMPANYING PETITION OF


MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER. COUNTY OF BRISTOL, MASS.


LICENSE PLAN NO. 845

APRIL 30,1982


OF




> ALL WOOD TO BE PRESSURE TREATED WITH PRESERVATIVE



TYPICAL BRIDGE SECTION





82w-029


SHEET 10 OF 10


PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT


TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.

LICENSE PLAN NO.845

Approved by Department of Environmental Quality Engineering April 30,1982








I.ALL EXISTING CONDITIONS SHOWN IS PROMDED FROM SURVEY DATA AND SOUNDINGS COMPILED BY A.L. ALMY AND ASSOC. UNDER D.E.M. CONTRACT NO.48-81A


2.EXISTING STRUCTURES LICENSED UNDER D.E.Q.E. WATERWAY # 82-845



024-00N-013-003 024-00N-013-005



ALL WOOD TO BE PRESSURE TREATED WITH PRESERVATIVE



2"x I2" DECK

POLYSTYRENE
FLOAT

O I 2 3 4 SCALE IN FEET

12'-0"

TYPICAL SECTION

FLOAT PLAN



86W-117

20"±


WATER


SHEET 4 OF 5


PLAN ACCOMPANYING PETITION OF THE MASS. DEPT. OF ENVIRONMENTAL MANAGEMENT TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS ALONG THE TAUNTON RIVER.


LICENSE PLAN NO. 1831

Approved by Department of Environmental Quality Engineering












FOCUS PLAN A Prepared By: HMM Associates. Inc. Concord. MA


Approved by Dec Planes of Environmental Properties

DAR 16 1991









PLAN AND SECTION OF FLOAT EXTENSION NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL FLOAT SECTION Prepared By: HMM Associates Inc. Concord MA


LICENSE PLAN NO. 264

Acquired by Cases and of Englanments Protection


APR 1 6 1991



024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL SECTION AT BOARDWALK EXTENSION NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL BOARDWALK SECTION LICENSE PLAN NO. 2641

Account by Desilvest of Soviennessel Proceedings

Date ADD 4 & 1001

024-00N-013-002-100 024-00N-013-001-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-60N-013-005-100



TYPICAL RIPRAP REVETMENT RECONSTRUCTION NOT TO SCALE


NOTES:


- 1. TYPICAL STONE SIZING MAY VARY ACCORDING TO CONTRACTOR'S SPECIFICATIONS.
- 2. EXISTING DUMPED STONE RIPRAP MATERIAL WILL BE RE-USED TO GREATEST EXTENT PRACTICAL.
- 3. PLAN IS FOR PERMITTING PURPOSES ONLY.



FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL RIPRAP REVETMENT LICENSE PLAN NO. 2641

Approved by Department of Environmental Protection
Descr APR 1 6 1991





FALL RIVER CAROUSEL AND HERITAGE PARK JIB CRANE DETAIL


Drengrad Rie HMM Associates Inc. Concord, MA

LICENSE PLAN NO. 2641

Approved by Copyrilating of Englacemental Ambarana

Der ADD 4 & 1001

024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



CAROUSEL BUILDING CROSS SECTION

NOT TO SCALE





FALL RIVER CAROUSEL
AND HERITAGE PARK
TYP. CAROUSEL BLDG. CROSS SECTION

LICENSE PLAN NO. 2641


स्ट्रमानको हेर् प्रेटक्शितको से हिल्लाकाकाको शिक्ताकी

PAR ANN A C INNE







024-000-024-002-100 024-00N-013-003-100 024-00N-013-005-100



12 x 12 TIMBER EDGE OVER 4 x 10 x 10 SPACER BLOCK



SECTION A-A



ALL WOOD TO BE PRESSURE TREATED WITH PRESERVATIVE.

PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.


82w-029 SHEET 3 OF 10

UCENSE PLAN NO.845

APRIL 30, 1982

024-000-024-002-100 024-00N-013-003-100 024-00N-013-003-100

> ALL WOOD TO BE PRESSURE TREATED WITH PRESERVATIVE



PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT


TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.


UCENSE PLAN NO. 845


Department of Environmental Quality Bases

APRIL 30,1982

024-000-024-002-100 024-00N-013-005-100 024-00N-013-005-100








PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY-OF FALL RIVER, COUNTY OF BRISTOL, MASS.

82W-029 SHEET 5 OF 10

UCENSE PLAN NO. 845


Approved by Department of Environmental Quality Engineers
APRIL 30,1982.




MASSACHUSETTS DEPARTMENT OF
ENVIRONMENTAL MANAGEMENT
TO CONSTRUCT AND MAINTAIN WATERFRONT
IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK
IN THE TAUNTON RIVER, CITY OF FALL RIVER,
COUNTY OF BRISTOL, MASS.

UCENSE PLAN NO: 845

April 30, 1982




024-000-024-002-100 024-00N-013-003-100, 024-00N-013-005-100



ELEVATION OF FLOAT & RAMP

12" BELOW M.L.W. SCALE 1/8"=1"-0" 1 0 1 2 3 4 5 6 7 8 SCALE IN FEET



0 1 2 3 4 5 SCALE IN FEET 82W-029


SHEET 8 OF 10

PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.


LICENSE PLAN NO.845

Expressed by Department of Marine States Service 39,1982





024-000-024-002-100 024-00N-013-003-100 024-00N-013-005-100

> ALL WOOD TO BE PRESSURE TREATED WITH PRESERVATIVE



TYPICAL BRIDGE SECTION





82w-029


SHEET 10 OF 10


PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT STRUCT AND MAINTAIN WATERFRONT


TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.

LICENSE PLAN NO.845

Approved by Department of Environmental Quality Engineerin
April 30,1982









I.ALL EXISTING CONDITIONS SHOWN IS PROMDED FROM SURVEY DATA AND SOUNDINGS COMPILED BY A.L. ALMY AND ASSOC. UNDER D.E.M. CONTRACT NO. 48-81A

2. EXISTING STRUCTURES LICENSED UNDER D.E.Q.E. WATERWAY # 82-845



OCATION MAP : SCALE | "= 3000"

024-00N-013-00



FLOAT PLAN ALL WOOD TO BE PRESSURE TREATED WITH PRESERVATIVE 2 3 4 SCALE IN FEET 12'-0" 2"x 12" DECK 617/86 (2) 2"x 8"EDGE 20"± WATER LEVEL 12" x 8' - 0"x 6-0"

TYPICAL SECTION




86W-117


SHEET 4 OF 5


PLAN ACCOMPANYING PETITION OF THE MAS.S. DEPT. OF ENVIRONMENTAL MANAGEMENT TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS ALONG THE TAUNTON RIVER.


LICENSE PLAN NO. 1831


Approved by Department of Environmental Quality Engineering













FALL RIVER CAROUSEL AND HERITAGE PARK FOCUS PLAN A


Prepared Bv. HMM Associates, Inc. Concord. MA


LICENSE PLAN NO. 2641

ADDRESS OF THE STATE OF THE PROPERTY PARTY OF THE PARTY OF T










PLAN AND SECTION OF FLOAT EXTENSION NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPIÇAL FLOAT SECTION

LICENSE PLAN NO. 264


Actioned by Case 1 and of Environmental Protection

Date: APR 1 6 1991


Prepared By: HMM Associates Inc. Concord MA



024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL SECTION AT BOARDWALK EXTENSION NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL BOARDWALK SECTION LICENSE PLAN NO. 2641

Account by General and all Environmental Properties

Date ADD 1 A 1001

024-00N-013-002-100 024-00N-013-001-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL RIPRAP REVETMENT RECONSTRUCTION NOT TO SCALE


NOTES:

- 1. TYPICAL STONE SIZING MAY VARY ACCORDING TO CONTRACTOR'S SPECIFICATIONS.
- 2. EXISTING DUMPED STONE RIPRAP MATERIAL WILL BE RE-USED TO GREATEST EXTENT PRACTICAL.
- PLAN IS FOR PERMITTING PURPOSES ONLY.



FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL RIPRAP REVETMENT LICENSE PLAN NO. 2641

Approved by Department of Environmental Protection
Date: APR 1 6 1991





FALL RIVER CAROUSEL AND HERITAGE PARK JIB CRANE DETAIL


Dranged Ris HMM Approintes Inc Concord. MA

LICENSE PLAN NO. 2641


Approved by Deposituated of Environmental Ambodium

Debr // በበበ 4 ይ 1001

024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



CAROUSEL BUILDING CROSS SECTION NOT TO SCALE





FALL RIVER CAROUSEL
AND HERITAGE PARK
TYP. CAROUSEL BLDG. CROSS SECTION

LICENSE PLAN NO. 2641

Accuracy by Cophiland of Environmental Projection

PARE DE MORTE






LICENSE PLAN NO. 94//
Approved by Department of Environmental Production
Date: NIIV 0 (2000) 6 2002 | V17, EL. 19 部 調 NEW CONCRETE WALKWAY TO WEET CURB TO BE REMOVED AND BOOKEAD FALL BUSEN OF PALL BUSEN TO SERVEN TO SOVERHAMENT OF SOVERHAMENT OF STATE RIVER, MA. RESET RAVELLED STONE, TYP. ... Part of the second seco F -7,6 STREET WALKWAY AND PIER STREET DAVOL OTY OF FALL RIVER DEPT. OF PUBLIC WORKS NEW WALKWAY -- BASELINE MONE REVENIENT (TYP). NEW TIMBER WALKWAY DAVOL --- 30'x30' PIER HEAD -62 -- 12'W TIMBER PIER **ПОНТІМО (тур.)** TAUNTON RIVER 140'£ THE TOTAL DAYED BINE No. 29201 POSTE P V17, EL. 21 BEE SHEET BAURANT 影


•

5,03


100

CHIEFT 7 AF







SHEET 5 OF 7




CONCRETE WALKWAY SECTION E-E



CONCRETE WALKWAY SECTION_F-F



PRECAST CONCRETE CATCH BASIN




TYPICAL STEEL HANDRAIL DETAIL


SCALE: 17=5'




0' 5'


CHELL C VE -








024-000-024-002-100 024-00N-013-003-100 024-00N-013-005-100



12 x 12 TIMBER EDGE OVER 4x10x10 SPACER BLOCK



SCALE IN FEET

WITH PRESERVATIVE.

PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.


SHEET 3 OF 10 82w-029

UCENSE PLAN NO.845

Approved by Department of Environmental Quality Engineer APRIL 30, 1982

024-000-024-002-100 024-00N-013-003-100 024-00N-013-003-100

> ALL WOOD TO BE PRESSURE TREATED WITH PRESERVATIVE




PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.

LICENSE PLAN NO. 845

APRIL 30,1982.

024-000-024-002-100 024-00N-013-005-100 024-00N-013-005-100



SCALE IN FEET


PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.

BZW-029 SHEET 5 OF 10

UCENSE PLAN NO. 845

Approved by Department of Environmental Quality Engineering APRIL 30,1982.




PLAN ACCOMPANYING PETITION OF
MASSACHUSETTS DEPARTMENT OF
ENVIRONMENTAL MANAGEMENT
TO CONSTRUCT AND MAINTAIN WATERFRONT

IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.


UCENSE PLAN NO: 845

Approved by Department of Environmental Quality Engineer

APRIL 30, 1982




024-000-024-002-100 024-00N-013-003-100, 024-00N-013-005-100



ELEVATION OF FLOAT & RAMP

I2" BELOW M.L.W.

1 0 1 2 3 4 5 6 7 8 SCALE IN FEET




PLAN ACCOMPANYING PETITION OF MASSACHUSETTS DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

TO CONSTRUCT AND MAINTAIN WATERFRONT IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK IN THE TAUNTON RIVER, CITY OF FALL RIVER, COUNTY OF BRISTOL, MASS.


LICENSE PLAN NO.845

April 39,1982





024-000-024-002-100 024-00N-013-003-100 024-00N-013-005-100

> ALL WOOD TO BE PRESSURE TREATED WITH PRESERVATIVE



TYPICAL BRIDGE SECTION






82w-029


SHEET 10 OF 10


PLAN ACCOMPANYING PETITION OF
MASSACHUSETTS DEPARTMENT OF
ENVIRONMENTAL MANAGEMENT
TO CONSTRUCT AND MAINTAIN WATERFRONT
IMPROVEMENTS AT FALL RIVER HERITAGE STATE PARK
IN THE TAUNTON RIVER, CITY OF FALL RIVER,
COUNTY OF BRISTOL, MASS.

LICENSE PLAN NO.845

Approved by Department of Environmental Quality Engineering April 30,1982










FOCUS PLAN A Prepared By: HMM Associates. Inc. Concord. MA


Approved by Dec Planes of Environmental Proposition-

APR 16 1991










PLAN AND SECTION OF FLOAT EXTENSION NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL FLOAT SECTION Prepared By: HMM Associates Inc. Concord MA

LICENSE PLAN NO. 264

Acquired by Castell and of Environmental Probabilist APR 16 1991




024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL SECTION AT BOARDWALK EXTENSION

NOT TO SCALE




FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL BOARDWALK SECTION LICENSE PLAN NO. 2641

Accessed by Great and all Embournessed Proposition

Date ADD 4 & 1001

024-00N-013-002-100 024-00N-013-001-100 024-00N-013-001-100 024-00N-013-001-200 024-000-024-002-100 024-00N-013-005-100



TYPICAL RIPRAP REVETMENT RECONSTRUCTION NOT TO SCALE


NOTES:


- 1. TYPICAL STONE SIZING MAY VARY ACCORDING TO CONTRACTOR'S SPECIFICATIONS.
- 2. EXISTING DUMPED STONE RIPRAP MATERIAL WILL BE RE-USED TO GREATEST EXTENT PRACTICAL.
- PLAN IS FOR PERMITTING PURPOSES ONLY.



FALL RIVER CAROUSEL AND HERITAGE PARK TYPICAL RIPRAP REVETMENT LICENSE PLAN NO. 2641

Approved by Department of Environmental Protection
Date: APR 1 6 1991





FALL RIVER CAROUSEL AND HERITAGE PARK JIB CRANE DETAIL


Dranged By HMM Associates Inc. Concord. MA

LICENSE PLAN NO. 2641

Approved by Cophilippia of Endocumental Projection

Detr ADD 4 & 1001

024-00N-013-002-100 024-00N-013-003-100 024-00N-013-001-100 024-00N-013-001-300 024-000-024-002-100 024-00N-013-005-100



CROSS SECTION NOT TO SCALE



FALL RIVER CAROUSEL
AND HERITAGE PARK
TYP. CAROUSEL BLDG. CROSS SECTION

LICENSE PLAN NO. 2641

Accessed by Department of Environmental Protection

PARE DE MAR SE

TOWN: FALL RIVER SOURCE: US ACOE LOCATION: CONCORD, MA DATE OF RESEARCH: AUGUST 2007 BCE Str 024-00C-(

		19000000					ŀ			
E Structure No	Document No	Drawing Number	Entity	Municipality	Date	Title	Sheets	Location	Description	
C-014-002-100 024-00C-014-002-100-COE1A 77-634	H002-100-COE1A	77-634	USACE	Fall River	August 18, 1977	Proposed Public Boat Launching Ramp in the 1977 Taunton River at the City of Fall River - Bristol County, MA	- ag	Remington Avenue and Brownell Street	Boat Ramp	

