



NOTE:

AT STIFFENER LOCATIONS, MODIFY THE PLATE ATTACHMENT TO THE FLANGES AS SHOWN IN THE TYPICAL STIFFENER ATTACHMENTS ON SHEET X.

CLIP DETAIL

NOT TO SCALE

NOTES:

1. Height of clip shall be $5 \times t_w$
2. Width of clip shall be $2 \times t_w$
3. Terminate weld $\frac{1}{4}$ " from edge of flange or connection plate, whichever is encountered first.

