



Massachusetts Polling Place Accessibility Study

Massachusetts Office on Disability

August, 2004

**Mitt Romney, Governor
Kerry Healey, Lieutenant Governor**

Myra Berloff, Director

**One Ashburton Place, Room 1305
Boston, MA 02108**

617- 727- 7440 V/TTY

800- 322- 2020 V/TTY

617- 727- 0965 FAX

Web: <http://www.mass.gov/mod>

This project was funded by a grant from the Office of the Secretary of the Commonwealth.

Table of Contents:

Executive Summary.....	2
Summary Status of Polling Locations Throughout the State.....	4
Key.....	4
Abington – Chelsea.....	5
Cheshire – Hamilton.....	6
Hampden – Medfield.....	7
Medford – Peru.....	8
Petersham – Swampscott.....	9
Swansea – Winthrop.....	10
Woburn – Yarmouth.....	11
Statewide Totals.....	11
Summary Status of Polling Locations By County.....	12
Key.....	12
Barnstable County.....	13
Berkshire County.....	14
Bristol County.....	15
Dukes County.....	16
Essex County.....	17
Franklin County.....	18
Hampden County.....	19
Hampshire County.....	20
Middlesex County.....	21
Nantucket County.....	22
Norfolk County.....	23
Plymouth County.....	24
Suffolk County.....	25
Worcester County.....	26
Statewide Totals.....	27
Summary of Non-Compliant Features Found at Polling Locations.....	28
Key.....	28
Abington – Chelsea.....	30
Cheshire – Hadley.....	31
Halifax – Medford.....	32
Medway – Phillipston.....	33
Pittsfield – Tisbury.....	34
Tolland – Yarmouth.....	35
Statewide Totals.....	35
Listing of Municipalities with All Polling Locations Accessible.....	36
Massachusetts Polling Place Accessibility Survey Results.....	37
Key.....	38
A.....	40
B.....	64
Boston.....	83
B continued.....	146

Table of Contents Continued

C.....	164
D.....	190
E.....	206
F.....	220
G.....	237
H.....	253
I.....	285
K.....	286
L.....	287
M.....	316
N.....	352
O.....	385
P.....	391
Q.....	415
R.....	418
S.....	434
Springfield.....	462
S continued.....	469
T.....	481
U.....	495
W.....	497
Worcester.....	551
W continued.....	557
Y.....	559



Massachusetts Office on Disability

One Ashburton Place, Room 1305
Boston, MA 02108

Mitt Romney, Governor
Kerry Healey, Lieutenant Governor
Myra Berloff, Director

[617] 727-7440 V/TTY
[800] 322-2020 V/TTY
[617] 727-0965 FAX
Web: <http://www.mass.gov/mod>
Myra.Berloff@modi.state.ma.us

Massachusetts Office on Disability August, 2004

In response to the Help America Vote Act (HAVA), the Secretary of the Commonwealth (SOC) reaffirmed his commitment to ensure that all of the 1488 polling locations throughout the state are accessible for people with disabilities by the September Primary. The Commonwealth has had polling accessibility requirements for over 15 years under the Code of Massachusetts Regulations (CMR) 950 Section 51.00 titled "Polling Place Accessibility for Elderly and Handicapped Voters". The most recent revision, effective August 28, 2003, is more stringent, in all aspects, than the requirements under HAVA.

Using 950 CMR Section 51.00 as its guide, the Massachusetts Office on Disability (MOD) conducted site surveys of all of the 1488 polling locations throughout the state, as directed by the SOC. The actual physical surveying of the locations took a total of 8 months and was performed by four Access Specialists from MOD. Each survey was conducted by an Access Specialist along with the City/Town Clerk or their designated representative.

Each municipality was mailed a copy of the survey results listing each polling location and any non-conforming features found at that location. Information gathered from the site surveys was then entered into a specially designed database.

The survey found that:

- **67 (19.10%)** of the 351 municipalities have all of their polling locations accessible.
- **587 (39.45%)** of the 1,488 polling locations comply with 950 CMR Section 51.00.
- **893 (60.01%)** of the 1,488 polling locations have at least 1 non-conforming feature¹.

Of the 893 locations that had non-conforming features:

- **471 (52.74%)** of the locations have a non-conforming feature at the designated accessible parking spaces provided in the parking lot. For example, no access aisle is provided or no sign is provided at the head of the space.
- **274 (30.68%)** of the locations have non-conforming features that involve the entrance. For example, no level landing is provided on the exterior of the entrance door.
- **262 (29.34%)** of the locations have a non-conforming feature with the ramp provided. For example, no handrails are provided or the running slope of the ramp is too steep.
- **221 (24.75%)** of the locations have changes in level greater than ½ inch along the accessible route.
- **132 (14.78%)** of the locations have curb cuts that do not provide the proper running slope.
- **123 (13.77%)** of the locations have non-conforming features that involve the exterior accessible route from the accessible parking to the designated accessible entrance. For example, a running slope of a walkway that exceeds 5%.
- **66 (7.39%)** of the locations have a non-conforming feature at the designated reserved on-street parking. For example, no sign, indicating the space is reserved for individuals with a disability, is provided.
- **45 (5.04%)** of the locations do not provide directional signage indicating the location of the accessible entrance.
- **33 (3.70%)** of the locations have a non-conforming feature with the sample ballots provided. For example, the height of the sample ballot is too high.
- **32 (3.61%)** of the locations have a non-conforming feature that involve an interior door. For example, a clear opening of the door measuring less than 32 inches.
- **23 (2.58%)** of the locations have the designated accessible entrance locked during polling.
- **19 (2.13%)** of the locations do not provide lighting that is sufficient, along the accessible route from the accessible parking to the accessible entrance.
- **15 (1.68%)** of the locations have non-conforming features that involve the interior accessible route from the accessible entrance to the voting area. For example, a path of travel measuring less than 36 inches wide.
- **5 (0.56%)** of the locations do not provide a lower shelf.

¹ There were 8 (0.54%) polling locations that could not be surveyed.

A Key to Understanding the “**Status of Polling Locations Throughout the State**” Report:

“Municipality”: The city/town the polling location is located.

“Total Number of Polling Locations”: This column indicates the total number of polling locations within the municipality.

“Compliant Polling Locations”: This column indicates the number of polling locations within the municipality that comply with 950 CMR 51.00. The polling location survey has been completed.

“Polling Locations with Non-Compliant Features”: This column indicates the number of polling locations within the municipality where there is at least one non-conforming feature that does not comply with 950 CMR 51.00. The polling location survey has been completed.

“Outstanding Polling Locations”: This column indicates the number of polling locations within the municipality that have not been surveyed. This could be caused by a building under renovation or another instance in which prevented the surveyors from conducting the survey.

Status of Polling Locations Throughout the State

Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Outstanding Polling Locations
Abington	1	0	1	0
Acton	3	1	2	0
Acushnet	2	0	2	0
Adams	1	0	1	0
Agawam	7	7	0	0
Alford	1	0	1	0
Amesbury	1	0	1	0
Amherst	9	1	8	0
Andover	2	1	1	0
Aquinnah	1	0	1	0
Arlington	13	5	8	0
Ashburnham	1	0	1	0
Ashby	1	1	0	0
Ashfield	1	0	1	0
Ashland	1	1	0	0
Athol	3	1	2	0
ATTLEBOROUGH	6	2	4	0
Auburn	1	1	0	0
Avon	1	0	1	0
Ayer	1	1	0	0
Barnstable	11	0	11	0
Barre	2	0	2	0
Becket	1	0	1	0
Bedford	1	0	1	0
Belchertown	1	1	0	0
Bellingham	4	3	0	1
Belmont	8	5	3	0
Berkley	1	1	0	0
Berlin	1	1	0	0
Bernardston	1	0	1	0
BEVERLY	9	3	6	0
Billerica	6	1	5	0
Blackstone	2	1	1	0
Blandford	1	0	1	0
Bolton	1	0	1	0
BOSTON	178	22	151	5
Bourne	4	0	4	0
Boxborough	1	0	1	0
Boxford	1	0	1	0
Boylston	1	1	0	0
Braintree	12	0	12	0
Brewster	1	0	1	0
Bridgewater	1	0	1	0
Brimfield	1	0	1	0
BROCKTON	25	18	7	0
Brookfield	1	0	1	0
Brookline	15	10	5	0
Buckland	1	0	1	0
Burlington	1	1	0	0
CAMBRIDGE	30	15	15	0
Canton	4	2	2	0
Carlisle	1	0	1	0
Carver	1	0	1	0
Charlemont	1	0	1	0
Charlton	1	1	0	0
Chatham	1	1	0	0
Chelmsford	5	5	0	0
CHELSEA	8	7	1	0

Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Outstanding Polling Locations
Cheshire	1	0	1	0
Chester	1	0	1	0
Chesterfield	1	0	1	0
CHICOPEE	14	6	8	0
Chilmark	1	0	1	0
Clarksburg	1	0	1	0
Clinton	1	0	1	0
Cohasset	1	0	1	0
Colrain	1	0	1	0
Concord	4	0	4	0
Conway	1	0	1	0
Cummington	1	0	1	0
Dalton	1	1	0	0
Danvers	8	6	2	0
Dartmouth	8	8	0	0
Dedham	5	4	1	0
Deerfield	1	0	1	0
Dennis	5	0	5	0
Dighton	1	0	1	0
Douglas	1	1	0	0
Dover	1	0	1	0
Dracut	4	0	4	0
Dudley	1	0	1	0
Dunstable	1	0	1	0
Duxbury	1	0	1	0
East Bridgewater	1	0	1	0
East Brookfield	1	0	1	0
East Longmeadow	4	0	4	0
Eastham	1	0	1	0
Easthampton	2	2	0	0
Easton	3	3	0	0
Edgartown	1	0	1	0
Egremont	1	1	0	0
Erving	1	0	1	0
Essex	1	1	0	0
EVERETT	12	2	10	0
Fairhaven	5	0	5	0
FALL RIVER	26	10	14	2
Falmouth	9	2	7	0
FITCHBURG	6	3	3	0
Florida	1	1	0	0
Foxborough	1	1	0	0
Framingham	10	5	5	0
Franklin	1	1	0	0
Freetown	2	1	1	0
GARDNER	5	0	5	0
Georgetown	1	1	0	0
Gill	1	0	1	0
GLOUCESTER	10	6	4	0
Goshen	1	1	0	0
Gosnold	1	0	1	0
Grafton	1	1	0	0
Granby	1	0	1	0
Granville	1	0	1	0
Great Barrington	2	0	2	0
Greenfield	1	0	1	0
Groton	2	0	2	0
Groveland	1	0	1	0
Hadley	1	0	1	0
Halifax	1	0	1	0
Hamilton	1	0	1	0

Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Outstanding Polling Locations
Hampden	1	0	1	0
Hancock	1	1	0	0
Hanover	1	0	1	0
Hanson	1	0	1	0
Hardwick	1	0	1	0
Harvard	1	1	0	0
Harwich	1	1	0	0
Hatfield	1	0	1	0
HAVERHILL	19	7	12	0
Hawley	1	0	1	0
Heath	1	0	1	0
Hingham	2	1	1	0
Hinsdale	1	0	1	0
Holbrook	2	0	2	0
Holden	4	3	1	0
Holland	1	0	1	0
Holliston	1	1	0	0
HOLYOKE	12	3	9	0
Hopedale	1	0	1	0
Hopkinton	1	1	0	0
Hubbardston	1	0	1	0
Hudson	7	4	3	0
Hull	1	0	1	0
Huntington	1	0	1	0
Ipswich	1	0	1	0
Kingston	2	0	2	0
Lakeville	1	0	1	0
Lancaster	1	0	1	0
Lanesborough	1	1	0	0
LAWRENCE	21	14	7	0
Lee	1	1	0	0
Leicester	1	1	0	0
Lenox	1	1	0	0
LEOMINSTER	7	7	0	0
Leverett	1	0	1	0
Lexington	9	8	1	0
Leyden	1	0	1	0
Lincoln	1	0	1	0
Littleton	1	0	1	0
Longmeadow	1	0	1	0
LOWELL	21	15	6	0
Ludlow	6	0	6	0
Lunenburg	1	0	1	0
LYNN	16	1	15	0
Lynnfield	2	0	2	0
MALDEN	12	8	4	0
Manchester-by-the Sea	1	0	1	0
Mansfield	1	0	1	0
Marblehead	3	2	1	0
Marion	1	0	1	0
MARLBOROUGH	7	6	1	0
Marshfield	1	0	1	0
Mashpee	1	0	1	0
Mattapoisett	1	0	1	0
Maynard	4	3	1	0
Medfield	1	0	1	0

Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Outstanding Polling Locations
MEDFORD	16	4	12	0
Medway	1	1	0	0
MELROSE	9	8	1	0
Mendon	1	1	0	0
Merrimac	1	1	0	0
Methuen	4	3	1	0
Middleborough	3	1	2	0
Middlefield	1	1	0	0
Middleton	1	0	1	0
Milford	5	4	1	0
Millbury	1	0	1	0
Millis	1	0	1	0
Millville	1	0	1	0
Milton	9	5	4	0
Monroe	1	0	1	0
Monson	1	0	1	0
Montague	5	0	5	0
Monterey	1	1	0	0
Montgomery	1	0	1	0
Mount Washington	1	0	1	0
Nahant	1	0	1	0
Nantucket	1	0	1	0
Natick	7	5	2	0
Needham	7	7	0	0
New Ashford	1	0	1	0
NEW BEDFORD	29	16	13	0
New Braintree	1	0	1	0
New Marlborough	1	1	0	0
New Salem	1	0	1	0
Newbury	2	0	2	0
NEWBURYPORT	5	2	3	0
NEWTON	25	13	12	0
Norfolk	1	0	1	0
NORTH ADAMS	5	0	5	0
North Andover	4	0	4	0
North Attleboroug	4	2	2	0
North Brookfield	1	0	1	0
North Reading	3	1	2	0
NORTHAMPTON	8	2	6	0
Northborough	4	3	1	0
Northbridge	3	2	1	0
Northfield	1	1	0	0
Norton	2	2	0	0
Norwell	3	0	3	0
Norwood	6	4	2	0
Oak Bluffs	1	0	1	0
Oakham	1	0	1	0
Orange	1	0	1	0
Orleans	1	0	1	0
Otis	1	0	1	0
Oxford	3	3	0	0
Palmer	3	1	2	0
Paxton	1	1	0	0
PEABODY	12	0	12	0
Pelham	1	0	1	0
Pembroke	4	0	4	0
Pepperell	1	1	0	0
Peru	1	1	0	0

Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Outstanding Polling Locations
Petersham	1	0	1	0
Phillipston	1	0	1	0
PITTSFIELD	13	9	4	0
Plainfield	1	0	1	0
Plainville	1	1	0	0
Plymouth	13	1	12	0
Plympton	1	0	1	0
Princeton	1	0	1	0
Provincetown	1	0	1	0
QUINCY	24	16	8	0
Randolph	6	0	6	0
Raynham	2	1	1	0
Reading	1	1	0	0
Rehoboth	3	1	2	0
REVERE	16	15	1	0
Richmond	1	0	1	0
Rochester	1	0	1	0
Rockland	2	0	2	0
Rockport	3	2	1	0
Rowe	1	0	1	0
Rowley	1	0	1	0
Royalston	2	0	2	0
Russell	1	0	1	0
Rutland	2	1	1	0
SALEM	13	9	4	0
Salisbury	1	1	0	0
Sandisfield	1	0	1	0
Sandwich	4	0	4	0
Saugus	8	0	8	0
Savoy	1	0	1	0
Scituate	1	0	1	0
Seekonk	4	1	3	0
Sharon	1	1	0	0
Sheffield	1	1	0	0
Shelburne	1	0	1	0
Sherbom	1	1	0	0
Shirley	1	1	0	0
Shrewsbury	8	3	5	0
Shutesbury	1	0	1	0
Somerset	5	1	4	0
SOMERVILLE	20	19	1	0
South Hadley	5	1	4	0
Southampton	1	0	1	0
Southborough	3	3	0	0
Southbridge	5	2	3	0
Southwick	1	0	1	0
Spencer	1	1	0	0
SPRINGFIELD	47	28	19	0
Sterling	1	1	0	0
Stockbridge	1	0	1	0
Stoneham	1	0	1	0
Stoughton	7	0	7	0
Stow	1	0	1	0
Sturbridge	1	0	1	0
Sudbury	2	0	2	0
Sunderland	1	0	1	0
Sutton	3	1	2	0
Swampscott	3	1	2	0

Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Outstanding Polling Locations
Swansea	4	2	2	0
TAUNTON	15	1	14	0
Templeton	1	0	1	0
Tewksbury	5	3	2	0
Tisbury	1	0	1	0
Tolland	1	0	1	0
Topsfield	1	0	1	0
Townsend	1	1	0	0
Truro	1	0	1	0
Tyngsborough	4	3	1	0
Tyringham	1	1	0	0
Upton	1	0	1	0
Uxbridge	1	1	0	0
Wakefield	5	1	4	0
Wales	1	1	0	0
Walpole	3	2	1	0
WALTHAM	15	10	5	0
Ware	1	0	1	0
Wareham	6	3	3	0
Warren	2	1	1	0
Warwick	1	0	1	0
Washington	1	0	1	0
Watertown	8	2	6	0
Wayland	2	0	2	0
Webster	1	1	0	0
Wellesley	7	7	0	0
Wellfleet	1	0	1	0
Wendell	1	0	1	0
Wenham	1	0	1	0
West Boylston	1	0	1	0
West Bridgewater	1	0	1	0
West Brookfield	1	0	1	0
West Newbury	1	0	1	0
West Springfield	7	3	4	0
West Stockbridge	1	0	1	0
West Tisbury	1	0	1	0
Westborough	3	2	1	0
WESTFIELD	11	1	10	0
Westford	5	0	5	0
Westhampton	1	0	1	0
Westminster	1	1	0	0
Weston	3	2	1	0
Westport	5	2	3	0
Westwood	4	3	1	0
Weymouth	12	0	12	0
Whately	1	0	1	0
Whitman	1	0	1	0
Wilbraham	4	0	4	0
Williamsburg	1	0	1	0
Williamstown	1	1	0	0
Wilmington	3	1	2	0
Winchendon	1	0	1	0
Winchester	4	0	4	0
Windsor	1	0	1	0
Winthrop	3	2	1	0

Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Outstanding Polling Locations
WOBURN	9	1	8	0
WORCESTER	43	26	17	0
Worthington	1	0	1	0
Wrentham	1	0	1	0
Yarmouth	5	0	5	0
Total	1,488	587	893	8
% of all polling locations		39.45%	60.01%	0.54%

A Key to Understanding the “Status of Polling Locations By County”
Report:

“County”: The county the municipality is located.

“Municipality”: The city/town the polling location is located.

“Total Number of Polling Locations”: This column indicates the total number of polling locations within the municipality.

“Compliant Polling Locations”: This column indicates the number of polling locations within the municipality that comply with 950 CMR 51.00. The polling location survey has been completed.

“Polling Locations with Non-Compliant Features”: This column indicates the number of polling locations within the municipality where there is at least one non-conforming feature that does not comply with 950 CMR 51.00. The polling location survey has been completed.

“Outstanding Polling Locations”: This column indicates the number of polling locations within the municipality that have not been surveyed. This could be caused by a building under renovation or another instance in which prevented the surveyors from conducting the survey.

Status of Polling Locations by County

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Barnstable	Barnstable	11	0	11	0
	Bourne	4	0	4	0
	Brewster	1	0	1	0
	Chatham	1	1	0	0
	Dennis	5	0	5	0
	Eastham	1	0	1	0
	Falmouth	9	2	7	0
	Harwich	1	1	0	0
	Mashpee	1	0	1	0
	Orleans	1	0	1	0
	Provincetown	1	0	1	0
	Sandwich	4	0	4	0
	Truro	1	0	1	0
	Wellfleet	1	0	1	0
	Yarmouth	5	0	5	0
Total		47	4	43	0
% of polling locations within the County			9%	91%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Berkshire	Adams	1	0	1	0
	Alford	1	0	1	0
	Becket	1	0	1	0
	Cheshire	1	0	1	0
	Clarksburg	1	0	1	0
	Dalton	1	1	0	0
	Egremont	1	1	0	0
	Florida	1	1	0	0
	Great Barrington	2	0	2	0
	Hancock	1	1	0	0
	Hinsdale	1	0	1	0
	Lanesborough	1	1	0	0
	Lee	1	1	0	0
	Lenox	1	1	0	0
	Monterey	1	1	0	0
	Mount Washington	1	0	1	0
	New Ashford	1	0	1	0
	New Marlborough	1	1	0	0
	NORTH ADAMS	5	0	5	0
	Otis	1	0	1	0
	Peru	1	1	0	0
	PITTSFIELD	13	9	4	0
	Richmond	1	0	1	0
	Sandisfield	1	0	1	0
	Savoy	1	0	1	0
	Sheffield	1	1	0	0
	Stockbridge	1	0	1	0
	Tyringham	1	1	0	0
	Washington	1	0	1	0
	West Stockbridge	1	0	1	0
	Williamstown	1	1	0	0
	Windsor	1	0	1	0
Total		49	22	27	0
% of polling locations within the County			45%	55%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Bristol	Acushnet	2	0	2	0
	ATTLEBOROUGH	6	2	4	0
	Berkley	1	1	0	0
	Dartmouth	8	8	0	0
	Dighton	1	0	1	0
	Easton	3	3	0	0
	Fairhaven	5	0	5	0
	FALL RIVER	26	10	14	2
	Freetown	2	1	1	0
	Mansfield	1	0	1	0
	NEW BEDFORD	29	16	13	0
	North Attleborough	4	2	2	0
	Norton	2	2	0	0
	Raynham	2	1	1	0
	Rehoboth	3	1	2	0
	Seekonk	4	1	3	0
	Somerset	5	1	4	0
	Swansea	4	2	2	0
	TAUNTON	15	1	14	0
	Westport	5	2	3	0
	Westwood	4	3	1	0
Total		132	57	73	2
% of polling locations within the County			43%	55%	2%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Dukes	Aquinnah	1	0	1	0
	Chilmark	1	0	1	0
	Edgartown	1	0	1	0
	Gosnold	1	0	1	0
	Oak Bluffs	1	0	1	0
	Tisbury	1	0	1	0
	West Tisbury	1	0	1	0
Total		7	0	7	0
% of polling locations within the County			0%	100%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Essex	Amesbury	1	0	1	0
	Andover	2	1	1	0
	BEVERLY	9	3	6	0
	Boxford	1	0	1	0
	Danvers	8	6	2	0
	Essex	1	1	0	0
	Georgetown	1	1	0	0
	GLOUCESTER	10	6	4	0
	Groveland	1	0	1	0
	Hamilton	1	0	1	0
	HAVERHILL	19	7	12	0
	Ipswich	1	0	1	0
	LAWRENCE	21	14	7	0
	LYNN	16	1	15	0
	Lynnfield	2	0	2	0
	Manchester-by-the-Sea	1	0	1	0
	Marblehead	3	2	1	0
	Merrimac	1	1	0	0
	Methuen	4	3	1	0
	Middleton	1	0	1	0
	Nahant	1	0	1	0
	Newbury	2	0	2	0
	NEWBURYPORT	5	2	3	0
	North Andover	4	0	4	0
	PEABODY	12	0	12	0
	Rockport	3	2	1	0
	Rowley	1	0	1	0
	SALEM	13	9	4	0
	Salisbury	1	1	0	0
	Saugus	8	0	8	0
	Swampscott	3	1	2	0
	Topsfield	1	0	1	0
	Wenham	1	0	1	0
	West Newbury	1	0	1	0
Total		159	61	98	0
% of polling locations within the County			38%	62%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Franklin	Ashfield	1	0	1	0
	Bernardston	1	0	1	0
	Buckland	1	0	1	0
	Charlemont	1	0	1	0
	Colrain	1	0	1	0
	Conway	1	0	1	0
	Deerfield	1	0	1	0
	Erving	1	0	1	0
	Gill	1	0	1	0
	Greenfield	1	0	1	0
	Hawley	1	0	1	0
	Heath	1	0	1	0
	Leverett	1	0	1	0
	Leyden	1	0	1	0
	Monroe	1	0	1	0
	Montague	5	0	5	0
	New Salem	1	0	1	0
	Northfield	1	1	0	0
	Orange	1	0	1	0
	Rowe	1	0	1	0
	Shelburne	1	0	1	0
	Sunderland	1	0	1	0
	Warwick	1	0	1	0
	Wendell	1	0	1	0
	Whately	1	0	1	0
Total		29	1	28	0
% of polling locations within the County			3%	97%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Hampden	Agawam	7	7	0	0
	Blandford	1	0	1	0
	Brimfield	1	0	1	0
	Chester	1	0	1	0
	CHICOPEE	14	6	8	0
	East Longmeadow	4	0	4	0
	Granville	1	0	1	0
	Hampden	1	0	1	0
	Holland	1	0	1	0
	HOLYOKE	12	3	9	0
	Ludlow	6	0	6	0
	Monson	1	0	1	0
	Montgomery	1	0	1	0
	Palmer	3	1	2	0
	Russell	1	0	1	0
	Southwick	1	0	1	0
	SPRINGFIELD	47	28	19	0
	Tolland	1	0	1	0
	Wales	1	1	0	0
	West Springfield	7	3	4	0
	WESTFIELD	11	1	10	0
	Wilbraham	4	0	4	0
Total		127	50	77	0
% of polling locations within the County			39%	61%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Hampshire	Amherst	9	1	8	0
	Belchertown	1	1	0	0
	Chesterfield	1	0	1	0
	Cummington	1	0	1	0
	Easthampton	2	2	0	0
	Goshen	1	1	0	0
	Granby	1	0	1	0
	Hadley	1	0	1	0
	Hatfield	1	0	1	0
	Huntington	1	0	1	0
	Longmeadow	1	0	1	0
	NORTHAMPTON	8	2	6	0
	Pelham	1	0	1	0
	Plainfield	1	0	1	0
	South Hadley	5	1	4	0
	Southampton	1	0	1	0
	Ware	1	0	1	0
	Westhampton	1	0	1	0
	Williamsburg	1	0	1	0
	Worthington	1	0	1	0
Total		40	8	32	0
% of polling locations within the County			20%	80%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Middlesex	Acton	3	1	2	0
	Arlington	13	5	8	0
	Ashby	1	1	0	0
	Ashland	1	1	0	0
	Ayer	1	1	0	0
	Bedford	1	0	1	0
	Belmont	8	5	3	0
	Billerica	6	1	5	0
	Boxborough	1	0	1	0
	Burlington	1	1	0	0
	CAMBRIDGE	30	15	15	0
	Carlisle	1	0	1	0
	Chelmsford	5	5	0	0
	Concord	4	0	4	0
	Dracut	4	0	4	0
	Dunstable	1	0	1	0
	EVERETT	12	2	10	0
	Framingham	10	5	5	0
	Groton	2	0	2	0
	Holliston	1	1	0	0
	Hopkinton	1	1	0	0
	Hudson	7	4	3	0
	Lexington	9	8	1	0
	Lincoln	1	0	1	0
	Littleton	1	0	1	0
	LOWELL	21	15	6	0
	MALDEN	12	8	4	0
	MARLBOROUGH	7	6	1	0
	Maynard	4	3	1	0
	MEDFORD	16	4	12	0
	MELROSE	9	8	1	0
	Natick	7	5	2	0
	NEWTON	25	13	12	0
	North Reading	3	1	2	0
	Pepperell	1	1	0	0
	Reading	1	1	0	0
	Sherborn	1	1	0	0
	Shirley	1	1	0	0
	SOMERVILLE	20	19	1	0
	Stoneham	1	0	1	0
	Stow	1	0	1	0
	Sudbury	2	0	2	0
	Tewksbury	5	3	2	0
	Townsend	1	1	0	0
	Tyngsborough	4	3	1	0
	Wakefield	5	1	4	0
	WALTHAM	15	10	5	0
	Watertown	8	2	6	0
	Wayland	2	0	2	0
	Westford	5	0	5	0
	Weston	3	2	1	0
	Wilmington	3	1	2	0
	Winchester	4	0	4	0
	WOBURN	9	1	8	0
Total		321	167	154	0
% of polling locations within the County			52%	48%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Nantucket	Nantucket	1	0	1	0
Total		1	0	1	0
% of polling locations within the County			0%	100%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Norfolk	Avon	1	0	1	0
	Bellingham	4	3	0	1
	Braintree	12	0	12	0
	Brookline	15	10	5	0
	Canton	4	2	2	0
	Cohasset	1	0	1	0
	Dedham	5	4	1	0
	Dover	1	0	1	0
	Foxborough	1	1	0	0
	Franklin	1	1	0	0
	Holbrook	2	0	2	0
	Medfield	1	0	1	0
	Medway	1	1	0	0
	Millis	1	0	1	0
	Milton	9	5	4	0
	Needham	7	7	0	0
	Norfolk	1	0	1	0
	Norwood	6	4	2	0
	Plainville	1	1	0	0
	QUINCY	24	16	8	0
	Randolph	6	0	6	0
	Sharon	1	1	0	0
	Stoughton	7	0	7	0
	Walpole	3	2	1	0
	Wellesley	7	7	0	0
	Weymouth	12	0	12	0
	Wrentham	1	0	1	0
Total		135	65	69	1
% of polling locations within the County			48%	51%	1%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Plymouth	Abington	1	0	1	0
	Bridgewater	1	0	1	0
	BROCKTON	25	18	7	0
	Carver	1	0	1	0
	Duxbury	1	0	1	0
	East Bridgewater	1	0	1	0
	Halifax	1	0	1	0
	Hanover	1	0	1	0
	Hanson	1	0	1	0
	Hingham	2	1	1	0
	Hull	1	0	1	0
	Kingston	2	0	2	0
	Lakeville	1	0	1	0
	Marion	1	0	1	0
	Marshfield	1	0	1	0
	Mattapoisett	1	0	1	0
	Middleborough	3	1	2	0
	Middlefield	1	1	0	0
	Norwell	3	0	3	0
	Pembroke	4	0	4	0
	Plymouth	13	1	12	0
	Plympton	1	0	1	0
	Rochester	1	0	1	0
	Rockland	2	0	2	0
	Scituate	1	0	1	0
	Wareham	6	3	3	0
	West Bridgewater	1	0	1	0
	Whitman	1	0	1	0
Total		79	25	54	0
% of polling locations within the County			32%	68%	0%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Suffolk	BOSTON	178	22	151	5
	CHELSEA	8	7	1	0
	REVERE	16	15	1	0
	Winthrop	3	2	1	0
Total		205	46	154	5
% of polling locations within the County			22%	75%	2%

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Worcester	Ashburnham	1	0	1	0
	Athol	3	1	2	0
	Auburn	1	1	0	0
	Barre	2	0	2	0
	Berlin	1	1	0	0
	Blackstone	2	1	1	0
	Bolton	1	0	1	0
	Boylston	1	1	0	0
	Brookfield	1	0	1	0
	Charlton	1	1	0	0
	Clinton	1	0	1	0
	Douglas	1	1	0	0
	Dudley	1	0	1	0
	East Brookfield	1	0	1	0
	FITCHBURG	6	3	3	0
	GARDNER	5	0	5	0
	Grafton	1	1	0	0
	Hardwick	1	0	1	0
	Harvard	1	1	0	0
	Holden	4	3	1	0
	Hopedale	1	0	1	0
	Hubbardston	1	0	1	0
	Lancaster	1	0	1	0
	Leicester	1	1	0	0
	LEOMINSTER	7	7	0	0
	Lunenburg	1	0	1	0
	Mendon	1	1	0	0
	Milford	5	4	1	0
	Millbury	1	0	1	0
	Millville	1	0	1	0
	New Braintree	1	0	1	0
	North Brookfield	1	0	1	0
	Northborough	4	3	1	0
	Northbridge	3	2	1	0
	Oakham	1	0	1	0
	Oxford	3	3	0	0
	Paxton	1	1	0	0
	Petersham	1	0	1	0
	Phillipston	1	0	1	0
	Princeton	1	0	1	0
	Royalston	2	0	2	0
	Rutland	2	1	1	0
	Shrewsbury	8	3	5	0
	Shutesbury	1	0	1	0
	Southborough	3	3	0	0
	Southbridge	5	2	3	0
	Spencer	1	1	0	0
	Sterling	1	1	0	0
	Sturbridge	1	0	1	0
	Sutton	3	1	2	0
	Templeton	1	0	1	0
	Upton	1	0	1	0
	Uxbridge	1	1	0	0
	Warren	2	1	1	0
	Webster	1	1	0	0
	West Boylston	1	0	1	0
	West Brookfield	1	0	1	0

County	Municipality	Total Number of Polling Locations	Compliant Polling Locations	Polling Locations with Non-Compliant Features	Polling Locations that are Still Outstanding
Worcester	Westborough	3	2	1	0
Continued	Westminster	1	1	0	0
	Winchendon	1	0	1	0
	WORCESTER	43	26	17	0
Total		156	81	75	0
% of polling locations within the County			52%	48%	0%
Statewide Total		1,488	587	893	8
% of all polling locations			39.45%	60.01%	0.54%

A Key to Understanding the “**A Summary of Non-Compliant Features Found at Polling Locations**” Report:

Municipality: The city/town the polling location is located.

of Loc.: This stands for “Total Number of Polling **Locations**”. This number indicates the total number of polling locations within the municipality.

Acc. Shelf: The number in this column indicates the number of polling locations within that municipality that have a non-compliant feature(s) regarding lowered voting shelves provided.

CILAR: This stands for “**Changes In Level Along and Accessible Route**”. The number in this column indicates the number of polling locations within the municipality with issues regarding changes in level exceeding ½ inch along the accessible route to the designated accessible entrance.

Curb Cuts: The number in this column indicates the number of polling locations within the municipality that have issues regarding curb cuts. For example, curb cuts with running slopes exceeding 1:12 (8.33%).

Dir. Sign: This stands for “**Directional Signage**”. The number in this column indicates the number of polling locations within the municipality that do not provided adequate signage to direct people to the designated accessible entrance, if the main entrance is not accessible.

Lkd Ent: This stands for “**Locked Entrance**”. The number in this column indicates the number of polling locations within the municipality where the designated accessible entrance for polling was locked.

Entrance: The number in this column indicates the number of polling locations within the municipality that have at least one non-compliant feature at the designated accessible entrance used for polling. Non-compliant features include: a threshold exceeding ½ inch, no level landing on the interior or exterior of the door, incorrect door hardware, and/or clear opening.

Ext. A/R: This stands for “**Exterior Accessible Route**”. The number in this column indicates the number of polling locations within the municipality with issues dealing with the accessible route to the designated accessible entrance used for polling. Non-compliant features include: longer paths of travel, ground surfaces and/or paths of travel that reduce to less than 36 inches or running slopes exceeding 5%.

Int. A/R: This stands for “**Interior Accessible Route**”. The number in this column indicates the number of polling locations within the municipality with issues dealing with the accessible route to the polling location once inside the building. Such as a path of travel that is reduced to less than 36 inches.

- Int. Doors:** This stands for “**Interior Doors**”: The number in this column indicates the number of polling locations within the municipality with issues regarding doors encountered along the accessible route to the polling location once inside the building. Non-compliant features include: a threshold exceeding ½ inch, no level landing provided on both sides of the door, clear opening and/or incorrect door hardware.
- Ltng:** This stands for “**Lighting**”. The number in this column indicates the number of polling locations within the municipality that do not provide adequate lighting along the accessible route to the accessible entrance of the polling location.
- On-Str. Prk:** This stands for “**On Street Parking**”. The number in this column indicates the number of polling locations within the municipality that provide on-street parking only, but none are reserved for persons with disabilities.
- Prk Lot:** This stands for “**Parking Lot**”. The number in this column indicates the number of polling locations within the municipality that provide a parking lot but have non-complying features found at the parking spaces. Non-compliant features include: incorrect parking or access aisle widths, improper or missing signage, improper number or missing designated accessible parking spaces, and/or access aisles abutting sidewalks without curb cuts.
- Ramps:** The number in this column indicates the number of polling locations within the municipality that have a ramp but have non-complying features found at the ramp. Non-compliant features include: steep running slopes, narrow widths, improper handrails, and/or missing handrails.
- Ballot:** This stands for “**Sample Ballot**”. The number in this column indicates the number of polling locations within the municipality that either do not provide a sample ballot, or the sample ballot is located at a height exceeding 48 inches above the floor.

A Summary of Non-Compliant Features Found at Polling Locations

Municipality	# of Loc.	Acc. Shelf	CILAAR	Curb Cuts	Dir. Sign.	Lkd. Ent.	Entrance	Ext. A/R	Int. A/R	Int. Doors	Ltng	On-Str. Prk.	Prk. Lot	Ramps	Ballot
Abington	1	0	1	1	0	0	0	0	0	0	0	0	1	0	0
Acton	3	0	0	0	0	0	0	0	0	0	0	0	2	1	0
Acushnet	2	0	0	0	0	0	0	0	0	0	0	0	2	0	0
Adams	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0
Agawam	7	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Alford	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Amesbury	1	0	1	0	0	0	0	0	0	0	0	0	1	0	0
Amherst	9	0	5	2	0	0	2	0	0	0	0	0	4	1	0
Andover	2	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Aquinnah	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Arlington	13	0	3	1	1	0	2	0	0	0	0	0	4	3	0
Ashburnham	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Ashby	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Ashfield	1	0	1	0	0	0	0	0	0	0	0	0	1	0	0
Ashland	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Athol	3	0	1	0	0	0	2	0	0	1	0	0	2	0	0
ATTLEBOROUGH	6	0	0	0	0	0	1	0	0	0	0	0	3	1	0
Auburn	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Avon	1	0	0	0	0	0	1	0	0	0	0	0	1	1	0
Ayer	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Barnstable	11	0	5	1	0	0	2	3	0	0	0	0	7	3	0
Barre	2	0	1	0	0	0	0	0	0	0	0	0	2	2	0
Becket	1	0	1	0	0	0	0	0	0	0	0	0	0	1	0
Bedford	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Belchertown	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Bellingham	4	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Belmont	8	0	0	0	0	0	0	1	0	0	0	0	3	0	0
Berkley	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Berlin	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Bernardston	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
BEVERLY	9	0	1	2	2	0	0	0	0	0	0	0	3	0	0
Billerica	6	0	4	4	0	0	0	0	0	0	1	0	4	1	0
Blackstone	2	0	1	1	0	0	0	0	0	0	0	0	1	0	0
Blandford	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Bolton	1	0	1	0	0	0	0	1	0	0	0	0	1	0	0
BOSTON	178	2	26	28	19	18	66	25	8	13	5	59	56	42	31
Bourne	4	0	0	2	0	0	1	0	0	0	0	0	1	1	0
Boxborough	1	0	1	0	0	0	1	1	0	0	0	0	1	0	0
Boxford	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0
Boylston	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Braintree	12	0	3	3	0	0	1	2	0	0	0	0	4	8	0
Brewster	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Bridgewater	1	0	1	0	0	0	0	0	0	0	0	0	1	0	0
Brimfield	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0
BROCKTON	25	0	2	0	0	0	1	0	0	0	0	0	2	4	0
Brookfield	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Brookline	15	0	2	3	0	0	2	0	0	0	0	0	1	1	0
Buckland	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Burlington	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CAMBRIDGE	30	0	2	1	0	1	6	5	0	2	0	0	4	1	0
Canton	4	0	0	0	0	0	0	0	0	0	0	0	2	0	0
Carlisle	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Carver	1	0	1	0	0	0	1	0	0	0	0	0	0	0	0
Charlemont	1	0	1	1	0	0	0	0	0	0	0	0	1	0	0
Charlton	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Chatham	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Chelmsford	5	0	0	0	0	0	0	0	0	0	0	0	0	0	0
CHELSEA	8	0	0	0	0	0	1	0	0	0	0	0	0	0	0

Municipality	# of Loc.	Acc. Shelf	CILAA	Curb Cuts	Dir. Sign.	Lkd. Ent.	Entrance	Ext. A/R	Int. A/R	Int. Doors	Ltng	On-Str. Prk.	Prk. Lot	Ramps	Ballot
Cheshire	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Chester	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Chesterfield	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
CHICOPEE	14	0	3	3	1	0	3	2	0	0	0	0	0	0	0
Chilmark	1	0	0	0	0	0	1	0	0	0	0	0	1	0	0
Clarksburg	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0
Clinton	1	0	0	0	0	0	0	0	0	1	0	0	0	0	0
Cohasset	1	0	1	0	0	0	0	0	0	1	0	0	1	1	0
Colrain	1	0	1	0	0	0	0	1	0	1	0	0	1	0	0
Concord	4	0	0	1	0	0	0	1	0	0	0	0	3	1	0
Conway	1	0	0	0	0	0	1	1	0	0	0	1	0	0	0
Cummington	1	1	1	0	0	0	0	0	0	0	0	0	1	0	0
Dalton	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Danvers	8	0	1	1	0	0	0	0	0	0	0	0	0	1	0
Dartmouth	8	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Dedham	5	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Deerfield	1	0	1	0	0	0	0	0	0	0	0	0	0	1	0
Dennis	5	0	1	0	1	0	2	1	0	0	0	0	5	3	0
Dighton	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Douglas	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Dover	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Dracut	4	0	0	0	0	0	2	0	0	0	0	0	4	1	0
Dudley	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Dunstable	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Duxbury	1	0	0	0	0	0	1	0	0	0	0	0	1	1	0
East Bridgewater	1	0	0	1	0	0	0	0	0	0	0	0	1	0	0
East Brookfield	1	0	0	1	0	0	1	1	0	0	0	0	1	1	0
East Longmeadow	4	0	1	0	0	0	0	0	0	0	0	0	4	0	0
Eastham	1	0	1	0	0	0	0	1	0	0	0	0	1	0	0
Easthampton	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Easton	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Edgartown	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Egremont	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Erving	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Essex	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
EVERETT	12	0	3	2	0	0	2	0	0	0	0	0	10	2	0
Fairhaven	5	0	1	1	0	0	1	0	0	0	0	0	4	3	0
FALL RIVER	26	0	2	0	0	0	7	2	0	0	0	0	6	3	0
Falmouth	9	0	4	0	0	0	1	1	0	0	0	0	7	2	0
FITCHBURG	6	0	0	0	0	0	1	0	0	0	0	0	1	2	0
Florida	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Foxborough	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Framingham	10	0	5	0	0	0	1	0	0	0	0	0	1	2	0
Franklin	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Freetown	2	0	0	0	0	0	0	0	0	0	0	0	1	0	0
GARDNER	5	0	1	1	0	0	1	2	0	0	0	0	3	2	0
Georgetown	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Gill	1	0	1	0	0	0	1	0	1	0	0	0	1	0	0
GLOUCESTER	10	0	0	2	0	0	4	0	1	0	0	0	0	1	0
Goshen	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Gosnold	1	0	1	0	1	0	1	1	0	0	0	0	1	1	0
Grafton	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Granby	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Granville	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0
Great Barrington	2	0	1	0	0	0	1	0	0	0	0	0	0	1	0
Greenfield	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Groton	2	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Groveland	1	0	1	1	0	0	0	1	0	0	0	0	1	0	0
Hadley	1	0	0	0	0	0	0	1	0	0	0	0	1	0	0

Municipality	# of Loc.	Acc. Shelf	CILAA	Curb Cuts	Dir. Sign.	Lkd. Ent.	Entrance	Ext. A/R	Int. A/R	Int. Doors	Ltng	On-Str. Prk.	Prk. Lot	Ramps	Ballot
Halifax	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Hamilton	1	0	0	0	0	0	1	0	0	0	0	0	1	0	0
Hampden	1	0	1	0	0	0	0	0	0	0	0	0	0	1	0
Hancock	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hanover	1	0	0	1	0	0	0	0	0	1	0	0	1	0	0
Hanson	1	0	0	1	0	0	0	0	0	0	0	0	1	0	0
Hardwick	1	0	0	1	0	0	0	0	0	0	0	0	0	1	0
Harvard	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Harwich	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hatfield	1	0	1	0	0	0	0	0	0	0	0	0	1	0	0
HAVERHILL	19	0	6	3	0	0	7	2	0	0	1	0	0	4	0
Hawley	1	0	1	0	0	0	1	0	0	0	0	0	1	1	0
Heath	1	0	1	1	0	0	0	1	0	0	0	0	1	0	0
Hingham	2	0	0	1	0	0	0	0	0	0	0	0	0	0	0
Hinsdale	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0
Holbrook	2	0	1	1	0	0	1	1	0	0	0	0	1	0	0
Holden	4	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Holland	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0
Holliston	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
HOLYOKE	12	0	0	0	5	1	3	2	0	0	1	1	3	2	0
Hopedale	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Hopkinton	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hubbardston	1	0	1	0	0	0	0	1	0	0	0	0	0	1	0
Hudson	7	0	0	0	0	0	1	1	0	0	0	0	2	1	0
Hull	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Huntington	1	0	1	0	0	0	0	0	0	0	0	0	0	1	0
Ipswich	1	0	0	1	0	0	1	0	0	0	0	0	0	0	0
Kingston	2	0	0	2	0	0	1	1	0	0	0	0	1	0	0
Lakeville	1	0	1	0	0	0	0	0	0	1	0	0	1	0	0
Lancaster	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Lanesborough	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
LAWRENCE	21	0	0	0	0	0	1	3	0	0	0	0	1	3	0
Lee	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Leicester	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Lenox	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
LEOMINSTER	7	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Leverett	1	0	1	0	0	0	1	1	0	0	0	0	1	0	0
Lexington	9	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Leyden	1	0	0	0	0	0	1	1	0	0	0	0	1	0	0
Lincoln	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Littleton	1	0	1	0	1	0	0	0	0	0	0	0	1	0	0
Longmeadow	1	0	0	0	0	0	1	1	0	0	0	0	0	0	0
LOWELL	21	0	1	1	1	0	3	0	0	0	0	0	1	3	0
Ludlow	6	0	0	2	0	0	1	0	0	0	0	0	5	0	0
Lunenburg	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0
LYNN	16	0	7	1	1	1	5	1	0	0	2	1	12	7	0
Lynnfield	2	0	0	1	1	0	2	0	0	0	0	0	2	1	0
MALDEN	12	0	0	0	0	0	2	0	0	0	0	0	2	0	0
Manchester-by-the-Sea	1	0	0	0	0	0	0	1	0	1	0	0	1	0	0
Mansfield	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Marblehead	3	0	0	0	0	0	1	0	0	0	0	0	0	0	0
Marion	1	0	0	0	0	0	0	0	1	0	0	0	1	0	0
MARLBOROUGH	7	0	0	0	0	0	1	0	0	0	0	0	0	0	0
Marshfield	1	0	0	1	0	0	0	1	0	0	0	0	0	0	0
Mashpee	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0
Mattapoisett	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Maynard	4	0	0	1	0	0	0	0	0	0	0	0	0	1	0
Medfield	1	0	1	0	0	0	1	0	0	0	0	0	1	0	0
MEDFORD	16	0	0	2	0	0	2	0	0	0	0	0	8	3	0

Municipality	# of Loc.	Acc. Shelf	CILAA	Curb Cuts	Dir. Sign.	Lkd. Ent.	Entrance	Ext. A/R	Int. A/R	Int. Doors	Ltng	On-Str. Prk.	Prk. Lot	Ramps	Ballot
Medway	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
MELROSE	9	0	0	0	0	0	0	1	1	0	0	1	0	0	0
Mendon	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Merrimac	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Methuen	4	0	0	1	0	0	0	0	0	0	0	0	1	0	0
Middleborough	3	0	1	0	0	0	0	0	0	0	0	0	2	1	0
Middlefield	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Middleton	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Milford	5	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Millbury	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Millis	1	0	1	0	0	0	0	0	0	0	0	0	1	0	0
Millville	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Milton	9	0	1	0	0	0	0	0	0	0	0	0	2	1	0
Monroe	1	0	0	0	0	0	0	1	0	0	0	0	1	0	0
Monson	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Montague	5	0	1	0	0	0	3	1	0	0	0	0	4	3	0
Monterey	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Montgomery	1	0	1	0	0	0	0	1	0	0	0	0	1	0	0
Mount Washington	1	0	1	0	1	0	0	1	0	0	0	0	0	0	0
Nahant	1	0	1	0	1	0	1	0	0	0	1	0	0	1	0
Nantucket	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Natick	7	0	0	1	0	0	0	0	0	0	0	0	1	0	0
Needham	7	0	0	0	0	0	0	0	0	0	0	0	0	0	0
New Ashford	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0
NEW BEDFORD	29	0	1	0	0	0	9	3	1	0	1	1	1	4	0
New Braintree	1	0	0	1	0	0	0	0	0	0	0	0	1	0	0
New Marlborough	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
New Salem	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Newbury	2	0	0	0	0	0	0	2	0	0	0	0	1	2	0
NEWBURYPORT	5	0	1	0	0	0	2	0	0	0	0	0	2	1	0
NEWTON	25	0	1	2	0	0	3	1	0	0	0	0	3	5	0
Norfolk	1	0	1	0	0	0	1	1	0	0	0	0	1	1	0
NORTH ADAMS	5	0	0	0	0	0	3	0	0	0	0	0	0	4	0
North Andover	4	0	0	0	1	0	2	1	0	0	1	0	3	1	0
North Attleborough	4	0	0	0	0	0	1	0	0	0	0	0	1	0	0
North Brookfield	1	0	0	0	0	0	1	0	0	0	0	0	1	0	0
North Reading	3	0	2	0	0	0	0	0	0	0	0	0	0	1	0
NORTHAMPTON	8	0	3	2	0	0	0	1	0	0	0	0	6	1	0
Northborough	4	0	0	0	0	0	1	0	0	0	0	0	0	0	0
Northbridge	3	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Northfield	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Norton	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Norwell	3	0	0	3	0	0	0	0	0	0	0	0	0	0	0
Norwood	6	0	0	0	0	0	1	0	0	0	0	0	1	1	0
Oak Bluffs	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Oakham	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Orange	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Orleans	1	0	0	0	0	0	0	0	0	1	0	0	1	1	0
Otis	1	0	0	0	1	0	0	0	0	0	0	0	0	0	0
Oxford	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Palmer	3	0	1	0	1	0	0	0	0	0	0	0	1	1	0
Paxton	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
PEABODY	12	0	9	2	1	0	7	2	0	1	0	0	10	5	0
Pelham	1	0	0	1	0	0	0	0	0	0	0	0	1	0	0
Pembroke	4	0	1	0	0	0	0	0	0	0	0	0	3	0	0
Pepperell	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Peru	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Petersham	1	0	0	0	0	0	1	0	0	0	0	0	1	0	0
Phillipston	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0


Municipality	# of Loc.	Acc. Shelf	CILAAR	Curb Cuts	Dir. Sign.	Lkd. Ent.	Entrance	Ext. A/R	Int. A/R	Int. Doors	Ltng	On-Str. Prk.	Prk. Lot	Ramps	Ballot
PITTSFIELD	13	0	1	0	0	0	2	0	0	0	0	0	2	0	0
Plainfield	1	0	0	0	0	0	1	0	0	0	0	0	1	0	0
Plainville	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Plymouth	13	0	4	3	0	0	2	1	0	0	0	0	12	2	0
Plympton	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Princeton	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0
Provincetown	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
QUINCY	24	0	1	0	0	0	3	2	0	0	0	0	1	2	0
Randolph	6	0	3	1	0	1	2	1	0	0	0	0	5	1	0
Raynham	2	0	0	0	0	0	1	0	0	0	0	0	1	0	0
Reading	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Rehoboth	3	0	0	0	0	0	0	0	0	0	0	0	2	0	0
REVERE	16	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Richmond	1	0	0	0	0	1	1	0	0	0	0	0	0	1	0
Rochester	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Rockland	2	0	1	1	0	0	1	1	0	0	0	0	1	1	0
Rockport	3	0	0	0	0	0	1	0	0	0	0	0	0	1	0
Rowe	1	0	1	0	0	0	0	0	0	0	0	0	1	1	0
Rowley	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Royalston	2	2	1	0	0	0	2	0	0	0	0	0	1	2	0
Russell	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0
Rutland	2	0	0	0	0	0	0	0	0	0	0	0	1	0	0
SALEM	13	0	0	0	0	0	1	0	0	0	0	0	1	2	0
Salisbury	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sandisfield	1	0	0	0	0	0	1	0	0	0	0	0	0	1	0
Sandwich	4	0	3	1	0	0	1	1	0	0	0	0	4	1	0
Saugus	8	0	1	1	0	0	1	1	0	0	0	0	7	2	0
Savoy	1	0	1	0	0	0	0	0	0	0	0	0	0	1	0
Scituate	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Seekonk	4	0	0	0	0	0	0	1	0	0	0	0	2	0	0
Sharon	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sheffield	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Shelburne	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Sherborn	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Shirley	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Shrewsbury	8	0	0	0	0	0	0	1	0	0	0	0	2	3	0
Shutesbury	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Somerset	5	0	1	0	1	0	2	0	0	1	0	0	1	0	0
SOMERVILLE	20	0	0	0	0	0	1	0	0	0	0	0	0	1	0
South Hadley	5	0	0	0	0	0	1	1	0	0	0	0	4	0	0
Southampton	1	0	0	0	0	0	0	1	0	0	0	0	1	1	0
Southborough	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Southbridge	5	0	1	0	0	0	2	2	0	0	1	0	2	1	0
Southwick	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Spencer	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SPRINGFIELD	47	0	2	2	0	0	10	2	0	0	2	0	3	8	0
Sterling	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Stockbridge	1	0	0	0	1	0	0	0	0	0	0	0	0	1	0
Stoneham	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Stoughton	7	0	1	1	0	0	0	1	0	0	0	0	7	2	0
Stow	1	0	0	0	0	0	0	0	0	1	0	0	1	1	0
Sturbridge	1	0	1	0	0	0	0	0	0	0	0	0	1	0	0
Sudbury	2	0	0	0	0	0	0	0	0	0	0	0	1	0	2
Sunderland	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Sutton	3	0	1	0	0	0	1	1	0	0	0	0	1	0	0
Swampscott	3	0	2	1	0	0	0	1	0	0	0	0	0	2	0
Swansea	4	0	0	0	0	0	0	1	0	0	0	0	0	1	0
TAUNTON	15	0	3	5	0	0	2	1	0	0	0	1	8	4	0
Templeton	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Tewksbury	5	0	1	0	0	0	1	0	0	0	0	0	0	1	0
Tisbury	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0

Municipality	# of Loc.	Acc. Shelf	CILAAR	Curb Cuts	Dir. Sign.	Lkd. Ent.	Entrance	Ext. A/R	Int. A/R	Int. Doors	Ltng	On-Str. Prk.	Prk. Lot	Ramps	Ballot
Tolland	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Topsfield	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0
Townsend	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Truro	1	0	0	1	0	0	0	0	0	0	0	0	1	0	0
Tyngsborough	4	0	1	0	0	0	0	0	0	0	0	0	0	0	0
Tyringham	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Upton	1	0	0	0	0	0	1	0	0	0	0	0	0	1	0
Uxbridge	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Wakefield	5	0	0	0	0	0	1	0	0	0	0	0	4	0	0
Wales	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Walpole	3	0	0	0	0	0	0	0	0	0	0	0	1	0	0
WALTHAM	15	0	1	0	0	0	0	0	0	0	1	0	2	1	0
Ware	1	0	1	1	0	0	1	0	0	0	0	0	0	0	0
Wareham	6	0	2	1	0	0	0	1	0	0	0	0	3	2	0
Warren	2	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Warwick	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0
Washington	1	0	0	0	0	0	1	0	0	1	0	0	1	0	0
Watertown	8	0	2	0	0	0	0	0	0	0	0	1	5	1	0
Wayland	2	0	2	0	1	0	1	1	0	0	0	0	1	0	0
Webster	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Wellesley	7	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Wellfleet	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Wendell	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Wenham	1	0	0	0	0	0	1	0	1	0	1	0	1	0	0
West Boylston	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
West Bridgewater	1	0	0	0	0	0	1	0	0	0	0	0	1	0	0
West Brookfield	1	0	1	0	0	0	0	0	0	0	0	0	1	0	0
West Newbury	1	0	0	1	0	0	0	0	0	0	0	0	1	0	0
West Springfield	7	0	0	0	0	0	1	2	0	0	0	0	2	1	0
West Stockbridge	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0
West Tisbury	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Westborough	3	0	0	1	0	0	0	0	0	0	0	0	1	0	0
WESTFIELD	11	0	7	2	0	0	4	1	1	1	0	0	9	3	0
Westford	5	0	2	1	0	0	0	0	0	0	0	0	4	2	0
Westhampton	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Westminster	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Weston	3	0	0	0	0	0	1	0	0	0	0	0	0	1	0
Westport	5	0	0	0	0	0	2	0	0	0	0	0	0	1	0
Westwood	4	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Weymouth	12	0	9	3	0	0	1	2	0	0	0	0	4	4	0
Whately	1	0	0	0	0	0	1	0	0	1	0	0	1	1	0
Whitman	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Wilbraham	4	0	0	2	0	0	0	0	0	0	0	0	4	1	0
Williamsburg	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Williamstown	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Wilmington	3	0	0	0	0	0	1	0	0	0	0	0	1	0	0
Winchendon	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Winchester	4	0	2	1	2	0	1	1	0	0	0	0	2	2	0
Windsor	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0
Winthrop	3	0	0	0	0	0	0	0	0	0	0	0	1	0	0
WOBURN	9	0	6	0	0	0	1	0	0	1	0	0	2	1	0
WORCESTER	43	0	4	1	0	0	9	4	0	2	1	0	2	2	0
Worthington	1	0	0	0	0	0	0	0	0	0	0	0	1	1	0
Wrentham	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0
Yarmouth	5	0	0	2	0	0	2	0	0	0	0	0	5	2	0
Total	1,488	5	221	132	45	23	274	123	15	32	19	66	471	262	33
% of all polling locations		0.34%	14.85%	8.87%	3.02%	1.55%	18.41%	8.27%	1.01%	2.15%	1.28%	4.44%	31.65%	17.61%	2.22%
% of non-conforming polling locations		0.56%	24.75%	14.78%	5.04%	2.58%	30.68%	13.77%	1.68%	3.58%	2.13%	7.39%	52.74%	29.34%	3.70%

Municipalities with All Polling Locations Accessible

Municipality	Total # of Polling Locations
Agawam	7
Ashby	1
Ashland	1
Auburn	1
Ayer	1
Belchertown	1
Bellingham	4
Berkley	1
Berlin	1
Boylston	1
Burlington	1
Charlton	1
Chatham	1
Chelmsford	5
Dalton	1
Dartmouth	8
Douglas	1
Easthampton	2
Easton	3
Egremont	1
Essex	1
Florida	1
Foxborough	1
Franklin	1
Georgetown	1
Goshen	1
Grafton	1
Hancock	1
Harvard	1
Harwich	1
Holliston	1
Hopkinton	1
Lanesborough	1
Lee	1
Leicester	1
Lenox	1
LEOMINSTER	7
Medway	1
Mendon	1
Merrimac	1
Middlefield	1
Monterey	1
Needham	7
New Marlborough	1
Northfield	1
Norton	2
Oxford	3
Paxton	1
Pepperell	1
Peru	1
Plainville	1
Reading	1
Salisbury	1
Sharon	1
Sheffield	1
Sherbom	1
Shirley	1
Southborough	3
Spencer	1
Sterling	1
Townsend	1
Tyringham	1
Uxbridge	1
Wales	1
Webster	1
Wellesley	7
Westminster	1
Williamstown	1

67 (19.10%) municipalities have all of their polling locations accessible.



Massachusetts Polling Place Accessibility Survey Results

This document was produced by the Massachusetts Office on Disability, funded by a grant from the Office of the Secretary of the Commonwealth.



A Key to Understanding the “Survey Results” Report:

- Municipality:** The city/town the polling location is located.
- Polling Location:** The name of the location where polling is held.
- Ward:** The ward the polling location is within the municipality.
- Precinct(s):** The precinct the polling location is within the ward within the municipality.

Location Complies: The information provided for the column explains that there is at least one non-conforming feature that does not comply with 950 CMR 51.00.

You will see one of three answers beside each of the “*Violation Notes*”, either *Yes*, *No* or *N/A*. These answers are an overall explanation for each polling location **NOT** for each “*Violation Notes*” entered.

Yes: This polling location survey has been completed. This polling location complies with 950 CMR 51.00.

No: This polling location survey has been completed. This polling location has features that do not comply with 950 CMR 51.00.

N/A: This polling location has not been surveyed. This could be caused by a building under renovation or another instance in which the surveyors could not survey the building.

- Violation Category:** There are 17 categories that could be next to the corresponding “*Violation Notes*” field.
- None:* If this is stated in this field, then the polling location complies with 950 CMR 51.00.
- Accessible Shelf:* If this is stated in this field, then the polling location has a non-conforming feature regarding the required lowered shelf. Non-compliant features include: no lowered shelf provided, incorrect knee space, and/or incorrect width.
- Changes in Level Along an Accessible Route:* If this is stated in this field, then the polling location has a change in level measuring greater than ½ inch along the path of travel to the accessible entrance.
- **Comments:** If this is stated in this field, then the polling location has features that although they are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible; or the polling locations has an outstanding item in terms of the survey and is used as a note.
- Curb Cuts:* If this is stated in this field, then the polling location has a curb cut(s) that does not comply with 950 CMR 51.00. For example, curb cuts with running slopes exceeding 1:12 (8.33%).

Directional Signage: If this is stated in this field, then the polling location does not provide adequate signage or is missing signage to direct people the designated accessible entrance.

Entrance Locked: If this is stated in this field, then the designated accessible entrance at this polling location is locked, or not useable without assistance. For example, requiring someone to knock on the door to get assistance.

Entrances (Other than Locked): If this is stated in this field, then the polling location has an entrance that is non-compliant with 950 CMR 51.00. . Non-compliant features include: a threshold exceeding ½ inch, no level landing on the interior or exterior of the door, incorrect door hardware, and/or clear opening.

Exterior Accessible Route: If this is stated in this field, then the accessible route to the accessible entrance for the polling location, does not comply with 950 CMR 51.00. Non-compliant features include: longer paths of travel, ground surfaces and/or paths of travel that reduce to less than 36 inches.

Interior Accessible Route: If this is stated in this field, then the accessible route once inside the polling location does not comply with 950 CMR 51.00, such as a path of travel that is reduced to less than 36 inches.

Interior Doors: If this is stated in this field, then there is an interior door(s) along the accessible route to the polling location that do not comply with 950 CMR 51.00. Non-compliant features include: a threshold exceeding ½ inch, no level landing provided on both sides of the door, clear opening and/or incorrect door hardware.

Lighting: If this is stated in this field, then the polling location does not provide adequate lighting or does not provide any lighting along the accessible route to the polling location.

On-Street Parking: If this is stated in this field, then the polling location does not have a parking lot and there are no on-street parking spaces reserved for individuals with disabilities.

Parking Spaces in Lot: If this is stated in this field, then the polling location does provide a parking lot, however the parking spaces do not comply with 950 CMR 51.00. Non-compliant features include: incorrect parking or access aisle widths, improper or missing signage, improper number or missing designated accessible parking spaces, and/or access aisles abutting sidewalks without a curb cuts.

Ramps: If this is stated in this field, then the polling location has a ramp(s) that does not comply with 950 CMR 51.00. Non-compliant features include: steep running slopes, narrow widths, improper handrails, and/or missing handrails.

Sample Ballot: If this is stated in this field, then the polling location either does not provide a sample ballot, or a sample ballot is located at a height exceeding 48 inches above the floor.

Voting Equipment: If this is stated in this field, then the polling location has voting equipment that provides levers that are located at a height exceeding 48 inches without a “reacher”.

Violations Notes: This field indicates the specific details to the “**Violation Category**” adjacent to it.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Abington	High School @ 201 Gliniewicz Way	00	01, 02, 03 & 04	No	Changes in Level Along Accessible Route	There is a change in level, at the designated accessible parking, measuring 1 to 1 1/2 inches.
					Curb Cuts	The curb cut, located at the right side access aisle, has a center running slope measuring 9.5%.
					Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. There is one sign missing from the head of a parking space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Acton	Nagog Woods Clubhouse @ 100 Nonset Path	00	01	Yes	None	
	Conant School @ 80 Taylor Road		02 & 06	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) One space is missing a sign at the head of the space. B) Both spaces share an 8 foot access aisle, thus either could be considered a van-accessible space. There currently is no space with the "van-accessible" sign at the head of the space.
	Blanchard Auditorium @ 12 Charter Road		03, 04 & 05		Parking Spaces in Lot Ramps	The parking lot provides a designated accessible parking space that is configured as a van-accessible space. However, the space does not provide a "van-accessible" sign at the head of the space. The ramp leading to the Auditorium, (probably intended as a walkway), has a running slope measuring 6.7%. However, there are no handrails provided on either side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Acushnet	Council on Aging @ 59 1/2 South Main Street	00	01	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
	Community Center @ 232 Middle Road		02 & 03		Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. However, there are no access aisles provided adjacent to the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Adams	Saint Thomas Parish Center @ 2 Columbia Street	00	01, 02, 03, 04 & 05	No	Entrances (Other than Locked)	The designated accessible entrance used for polling: a) There is a set of double doors at the entrance. Each door, opened individually, provides a clear opening measuring 28 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Agawam	Robinson School	00	01	Yes	None	
	Granger School		02		None	
	High School		03		None	
	Middle School		04		None	
	Phelps School		05		None	
	James Clark School		06 & 08		None	
	Junior High School		07		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Alford	Town Hall @ 5 Alford Center Road	00	01	No	Ramps	The ramp provided: A) The ramp is only 43 inches wide, measured between handrails. B) Handrails are located on one side of the ramp, however, the handrails are not round or oval. The handrails are a 2x2 configuration.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Amesbury	Town Hall	00	01, 02, 03, 04, 05 & 06	No	Changes in Level Along Accessible Route	There is a 3/4 inch change in level at the bottom of the ramp.
					Parking Spaces in Lot	The designated accessible parking space provided near the designated accessible entrance is configured as a van accessible parking space. The space does not have a "van-accessible" sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Amherst	North Congregational Church @ 1199 North Pleasant Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level measuring 3/4 of an inch at the base of the ramp.
					Parking Spaces in Lot	There is one designated accessible parking space provided. However, the space does not provide an access aisle adjacent to the space. NOTE: The entire parking lot is not striped.
					Ramps	The ramp provided: A) The running slope of the ramp measures 9.6% at the top. B) The ramp measures 46 inches wide, measured between the handrails. C) The ramp does not provide lower handrails. D) The upper handrails are not round or oval, they are a 2x4 configuration.
	North Fire Station @ East Pleasant Street		02		Entrances (Other than Locked)	The designated accessible entrance door does not provide door hardware that can be operated with a closed fist. Currently there is a door knob provided.
	Immanuel Lutheran @ 867 North Pleasant Street		03		Parking Spaces in Lot	There is a designated accessible parking space that is configured as a van accessible space. However, the space is missing a "van-accessible" sign.
	Bangs Community Center @ 70 Boltwood Walk		04 & 05		**Comments	**The walkway, leading to the designated accessible entrance, has a cross slope measuring 12.2%.
					Parking Spaces in Lot	There is a designated accessible parking space that is configured as a van accessible space. However, the space is missing a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Amherst	Fort River School @ 70 South East Street	00	06	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut located across from the parking, measuring 3/4 to 1 inch.
					Curb Cuts	The curb cut, located across from the parking, has a center running slope measuring 10.3%.
	Crocker Farm School @ 280 West Street		07	Yes	None	
	Munson Memorial Library @ South East Street		08	No	Changes in Level Along Accessible Route	There are changes in level, along the cobblestone leading to the entrance, measuring 3/4 to 1-1/2 inches.
					Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. Each door opened by itself only provides 28 inches of clear width.
					NOTE: There is an automatic door opener that will open both doors.	
	Wildwood School @ 71 Strong Street		09		Changes in Level Along Accessible Route	There are changes in level, from the sidewalk at the parking to the entrance, measuring 3/4 to 1 inch.
					Curb Cuts	The curb cut, located across from the parking, has a center running slope exceeding 8.33%.
					Parking Spaces in Lot	There is a designated accessible parking space that is configured as a van accessible space. However, the space is missing a "van-accessible" sign.
	Hampden Dining Commons @ SW Residential Area Umass		10		Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 1 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Andover	Senior Center	00	01, 07 & 08	No	Parking Spaces in Lot	The designated "van-accessible" space does not provide the "van-accessible" sign.
	High School		02, 03, 04, 05 & 06	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Aquinnah	Town Hall @ 65 State Road	00	01	No	Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. There are no access aisles provided adjacent to any of the spaces.
					Ramps	The ramp does not provide any handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Arlington	Thompson School @ 70 North Union Street	00	01 & 05	No	Changes in Level Along Accessible Route	1) The walkway leading from the parking lot to the designated accessible entrance has changes in level greater than 1/2 inch.
						2) At the entrance, there is a 3/4 inch change in level, just outside the door.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
	Hardy School @ 52 Lake Street		02 & 04	Yes	None	NOTE: During the survey, we were told by Jack Jones that temporary spaces are set up during the time of polling.
	Edith Fox Library/Community Center @ 175 Mass Ave		03	No	Changes in Level Along Accessible Route	There is a 6" step at the entrance to the polling location.
						NOTE: During the survey, Jake Jones stated that a temporary ramp is installed along the sidewalk. Upon inspection of the location, we found that with the temporary ramp installed, the path of travel would be reduced to less than 36 inches. As we looked around the building we found an entrance door that was level with the sidewalk. The entrance door currently has a buzzer to gain access into the location, no hardware on the exterior of the door, and signage would need to be provided to that entrance. For polling purposes, the above items would need to be addressed for that entrance to work.
	Gibbs Junior High School @ 41 Foster Street		06 & 07		Directional Signage	There is no directional signage indicating the location of the designated accessible entrance.
					Entrances (Other than Locked)	The door located closest to the basketball court has a threshold measuring 2 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Arlington	Gibbs Junior High School @ 41 Foster Street	00	06 & 07	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: a) The spaces only provide a 4 foot access aisle. B) There is no "van accessible" parking space provided. NOTE: During the survey, Jack Jones stated that temporary designated on-street accessible parking space is provided during polling. However, the location indicated is not near a curb cut to access the sidewalk.
	Town Hall		08 & 10		**Comments	** The path of travel to the entrance where the parking lot is provided, has grates with openings measuring 2 inches by 2 inches.
					Changes in Level Along Accessible Route	There are two entrances to the Town Hall, both have changes in level: 1) The side entrance area there is a change in level near the door measuring 3/4 - 1 inch. 2) The front entrance walkway has changes in level measuring 1 inch caused by the "heaving" bricks.
					Parking Spaces in Lot	There are 3 designated accessible parking spaces provided in the parking lot. A) One space is blocked by a dumpster. B) One space does not have an access aisle beside it. C) One space, located next to the access aisle that is 8 feet wide, is missing the "van-accessible" sign.
	Chestnut Manor @ 54 Medford Street		09		Ramps	The ramp provided has a running slope in the middle measuring 12.5%.
	Bishop School @ 25 Columbia Road		11	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Arlington	Brackett School @ 66 Eastern Avenue	00	12	Yes	None	
	Stratton School @ 180 Mountain Avenue		13 & 15		None	
	Highland Fire Station @ 1007 Mass Ave		14 & 17	No	Entrances (Other than Locked)	The fire door, which remains open during polling, does not provide a level area on the exterior of the door. NOTE: The other door used for polling has a 6 1/2 inch step.
	Dallin School @ 185 Florence Avenue		16 & 18		Curb Cuts	The designated on-street accessible parking space that will be provided for polling is not located near a curb cut.
					Ramps	The ramp provided: A) In the middle of the ramp there is a running slope measuring 9.2%. B) The ramp measures 39 inches wide, from handrail to handrail.
	Pierce Elementary School @ Park Avenue Extension		19 & 21		Parking Spaces in Lot	The designated accessible parking space provided: A) The space does not have a "van-accessible" sign. B) The curb cut provided for the parking space is at the head of the parking space, not the access aisle.
					Ramps	The ramp provided: A) The running slope of the top of the first run up the ramp measures 9.2%. B) The running slope of the middle of the second run up the ramp measures 10.3%. **C) The ramp is a curved ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Arlington	Park Avenue Congregational Church @ 50 Paul Revere Road	00	20	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Ashburnham	J.R. Briggs Elementary School @ 96 Williams Road	00	01	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not provide a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Ashby	Ashby Elementary School @ 911 Main Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Ashfield	Town Hall @ 412 Main Street	00	01	No	**Comments	** The running slope of the ramp could not be measured at the time of the survey. There was about 3-4 feet of snow on the entire run. The handrails and width were okay.
					Changes in Level Along Accessible Route	1) There are changes in level, along the walkway leading to the lower entrance (this entrance requires the use of a lift to gain access to the voting area), measuring 3/4 to 1 inch. 2) The path of travel to the ramp, which brings you to the area of voting, is over dirt and gravel. The dirt and gravel create changes in level measuring 1/2 to 1 inch.
					Parking Spaces in Lot	There is one designated accessible parking space provided. A) There is no van accessible space provided. B) There is no sign at the head of the accessible space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Ashland	High School Small Gymnasium @ 87 West Union Street	00	01, 02, 03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Athol	Congregational Church @ 1225 Chestnut Street	00	01	Yes	None	
	CCD Center, Our Lady Immaculate Church @ 925 Main Street		02	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 2 inches.
					Entrances (Other than Locked)	The designated accessible entrance does not provided a 5-foot level landing on the exterior of the door. The slope of the landing measures 3.0%.
					Parking Spaces in Lot	The 2 designated accessible parking spaces provided in the lot: A) One space does not provide an access aisle adjacent to the space. B) There is no van accessible parking space provided. C) The spaces do not have signs at the head of them.
	Liberty Hall @ 584 Main Street		03		Entrances (Other than Locked)	The designated accessible entrance does not provided a 5-foot level landing on the exterior of the door. The slope of the landing measures 6.2%.
					Interior Doors	There is a set of double door on the interior of the building. Each door, opened individually, provides only 28 inches of clear opening.
					Parking Spaces in Lot	There is no van accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
ATTLEBOROUGH	Knights of Columbus #5876 @ 304 Highland Avenue	01	A & B	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 3.3% to 3.6%.
	Good News Chapel @ 235 West Street	02			Parking Spaces in Lot	The designated accessible parking spaces provided: A) The parking space that is configured as van accessible is missing the "van-accessible" sign. B) The standard accessible space does not provide an access aisle. C) The signs at the head of the spaces measure 2 feet to the top of the sign.
	Saint John's @ Corner of North Main and Peck Streets	03			Parking Spaces in Lot	There are no signs at the head of the designated accessible parking spaces provided.
	Faith Alliance Church @ 833 Pleasant Street	04		Yes	None	
	LaSalette Shrine @ 947 Park Street	05		No	Parking Spaces in Lot	There are no signs provided at the head of the designated accessible parking spaces.
					Ramps	The ramp provided: A) The running slope of the ramp exceeds 8.33%. B) The handrails are not round or oval, they are flat.
	Elk's Lodge #1014 @ 887 South Main Street	06		Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Auburn	High School @ 99 Auburn Street	00	01, 02, 03, 04 & 05	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Avon	Buckley Center @ 65 East Main Street	00	01	No	Entrances (Other than Locked)	The designated accessible entrance used for polling has a threshold measuring 3/4 to 1 inch.
					Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) The three spaces only provide access aisles that are 4 1/2 feet wide. B) No van accessible space is provided. C) There is a sign missing from one of the three parking spaces.
					Ramps	The ramp provided: A) The upper handrails are provided at a height measuring 32 inches. B) The lower handrails are provided at a height measuring 16 inches. C) The handrails are not round or oval. The handrails are flat.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Ayer	Page-Hilltop School @ Washington Street	00	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Barnstable	West Barnstable Elementary School @ 2463 Main Street	00	01	No	Changes in Level Along Accessible Route	There are changes in level, along the walkway leading to the ramp, measuring 3/4 to 1 1/2 inches.
					Entrances (Other than Locked)	The designated accessible entrance is a set of double doors with a vestibule. A) The exterior doors, when opened individually, provide a clear opening measuring 29 1/2 inches. B) The interior doors, when opened individually, provide a clear opening measuring 29 1/2 inches.
					Exterior Accessible Route	The walkway, leading to the ramp, has a running slope measuring 15.4%.
	Saint Georges Greek Church @ 1130 Falmouth Road		02		Parking Spaces in Lot	There are 9 designated accessible parking spaces provided. A) There are 8 spaces that do not provide an access aisle adjacent to the spaces. B) There are 6 spaces that do not provide signs at the heads of the spaces. C) The space that is configured as a van accessible space does not provide a "van-accessible" sign. D) All designated accessible spaces that abut a sidewalk. 8 of the spaces do not provide a curb cut to access the sidewalk.
	Hyannis West Elementary School @ 549 West Main Street		03		Changes in Level Along Accessible Route	There are changes in level, along the walkway leading to the entrance, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	There are 4 designated accessible parking spaces provided. A) There is no van accessible space provided. B) The access aisles, for each of the spaces, measure 4 feet wide. C) There are 2 spaces that do not provide signs at the head of the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Barnstable	Hyannis West Elementary School @ 549 West Main Street	00	03	No	Ramps	The first ramp run up, leading to the entrance, does not provide handrails on the right side.
	Centerville Elementary @ 658 Bay Lane		04		Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) The left side parking space does not provide a sign at the head of the space. B) The space configured as van accessible does not provide the "van-accessible" sign.
					Ramps	The ramp has a running slope measuring 9.5% at the top.
	Osterville Elementary @ 350 Bumps River Road		05		Changes in Level Along Accessible Route	1) There is a change in level, where the walkway meets the cement near the entrance and along the walkway, measuring 1 to 2 1/2 inches.
					Exterior Accessible Route	The walkway, at the parking leading to the entrance, has a running slope measuring 9.5% at the bottom and 9.4% at the top.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) The access aisle measures 3 feet wide.
	Marstons Mills East Elementary @ 760 Osterville/West Barnstable Road		06 & 10		Parking Spaces in Lot	There are 4 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) The access aisles, for the 4 spaces, abut a sidewalk. There are no curb cuts provided. Where the access aisles abut the sidewalk there is a slope to access the sidewalk, however, the running slopes measure 27.6%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Barnstable	Freedom Hall @ 976 Main Street	00	07	No	Entrances (Other than Locked)	The designated accessible entrance: A) The hardware on the door is not operable with a closed fist. Currently a thumb latch is provided. B) The entrance door is a set of double doors. Opened individually, each door provides 29 1/2 inches of clear opening. NOTE: There is an automatic door opener at this location that opens both doors when activated.
	Kennedy Skating Rink @ 141 Bassett Lane		08		Changes in Level Along Accessible Route	There is a change in level, at the entrance landing, measuring 3/4 to 1 inch.
	Town Hall @ 367 Main Street		09 & 13		Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) The 3 spaces do not provide access aisles adjacent to the spaces.
	West Barnstable Community Center @ 2377 Meetinghouse Way		11		Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 1 to 2 inches.
					Exterior Accessible Route	The walkway, leading from the parking to the entrance, has running slopes measuring 5.8% to 6.2%.
					Ramps	The ramp does not provide handrails that are round or oval. The current configuration is 2x4.
	Marstons Mills Elementary @ 2095 Main Street		12		Curb Cuts	The curb cut, located closest to the entrance, has a center running slope measuring 10.0%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Barnstable	Marstons Mills Elementary @ 2095 Main Street	00	12	No	Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) There is no van accessible space provided. B) The access aisle, shared for the 2 spaces, measures 4 feet wide.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Barre	Town Hall @ 2 Exchange Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level, along the accessible route from both of the parking spaces, measuring 3/4 to 1 1/2 inches.
					Parking Spaces in Lot	The designated accessible parking spaces: A) The left most space provides a 3 foot access aisle. B) The spaces do not have signs at the head of the spaces. C) The access aisles abut a sidewalk. Curb cuts are not provided.
					Ramps	The ramp has running slopes measuring 9.9% at the bottom, 9.6% in the middle and 10.0% at the top.
	Post 404 @ 450 South Barre Road		02		Parking Spaces in Lot	There are 6 designated accessible parking spaces provided. 5 spaces do not provide signs.
					Ramps	The ramp has a running slope measuring 9.3% at the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Becket	Town Hall @ 557 Main Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the end of the ramp, measuring 1 1/4 inches.
					Ramps	The ramp provided: A) The running slope, at the bottom of the ramp, measures 9.4%. B) There are no handrails on either side of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Bedford	John Glenn Middle School	00	01, 02, 03 & 04	No	Parking Spaces in Lot	The access aisles provided at the designated accessible parking spaces abut a sidewalk. There are no curb cuts provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Belchertown	High School @ 142 Springfield Road	00	A, B, C & D	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Bellingham	Stall Brook School @ 324 Hartford Avenue	00	01	Yes	None	
	Clara Macy School @ Monique Drive		02		None	
	Public Library @ 100 Blackstone Street		03		None	
	Assumption Parish Hall @ 370 Pulaski Blvd		04 & 05	N/A	**Comments	This voting location will be closed prior to the November elections. The Town Clerk will inform of the new location.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Belmont	Memorial Library (Formerly Wellington School)	00	01	Yes	None	
	Town Hall @ 455 Concord Avenue		02	No	Exterior Accessible Route	The walkway leading from the parking to the entrance has the running slope of a ramp. The slopes measure 7.2% - 8.3%.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot do not provide access aisles adjacent to the spaces.
	All Saints' Church Hall @ 17 Clark Street		03	Yes	None	
	Butler School Gymnasium @ 90 White Street		04	No	Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. The 2 spaces share an access aisle that measures 44 inches wide.
	United Methodist Church @ 421 Common Street		05		Parking Spaces in Lot	The designated accessible parking spaces do not provide access aisles adjacent to the spaces.
	Senior Center @ 23 Oakley Road		06	Yes	None	
	Fire Station @ 85 Fairview Avenue		07		None	
	Winn Brook Elementary School @ 97 Waterhouse Road		08		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Berkley	Community School @ 59 South Main Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Berlin	Town Offices @ 23 Linden Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Bernardston	Town Hall @ 38 Church Street	00	01	No	Parking Spaces in Lot	There are temporary parking spaces provided during polling as "on-street" style spaces. However, where the spaces would be located, there are no curb cuts to get onto the sidewalk.
					Ramps	<p>The ramp provided:</p> <p>A) The bottom run of the ramp is 44 inches wide, measured between the handrails.</p> <p>B) The handrails for the ramp are not round or oval. The handrails are a 2x4 configuration.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BEVERLY	Ayers-Ryal Side School	01	01 & 02	No	Curb Cuts	The curb cut located at the accessible parking has a center running slope measuring 9.4%.
					Parking Spaces in Lot	There are 2 missing signs for the accessible parking spaces.
	Public Library	02			Directional Signage	Signage is not present to indicate where the accessible entrance is.
	McKeown School	03		Yes	**Comments	** The curb cut located at the accessible parking spaces has a running slope measuring 12.2% on the left side flare.
	Cove School	04	01	No	Parking Spaces in Lot	1) At the accessible parking spaces, 2 signs are missing. However the "Van-Accessible" sign is present. 2) The curb cut located at the accessible parking protrudes into the access aisle more than ½ inch.
	Senior Center		02	Yes	None	
	Second Congregational Church	05	01	No	Directional Signage	Signage needs to be provided to indicate where the accessible entrance is.
					Parking Spaces in Lot	No Van accessible sign provided at the accessible parking.
	North Beverly School		02	Yes	None	
	St. Johns Episcopal Church	06	01	No	Changes in Level Along Accessible Route	At the exit of the polling location, where everyone leaves the location, there is a walkway with a 6-inch step.
	Centerville School		02		Curb Cuts	The curb cut in front of the school: a) The center running slope measures 9.5%. **b) There is no flat level landing at the top of the curb cut.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Billerica	Parker School @ River Street	00	01	Yes	None	
	Hajjar School @ Roger Street		02 & 08	No	Changes in Level Along Accessible Route	The accessible route to the designated accessible entrance has changes in level measuring greater than 1/2 inch.
					Curb Cuts	The curb cut provided located near the designated accessible entrance has a center running slope exceeding 1:12 (8.33%).
					Parking Spaces in Lot	The designated accessible parking spaces: A) The space configured as a van accessible space is missing the "van-accessible" sign. B) There is no curb cut provided where the access aisle abuts the sidewalk.
	Ditson School @ Cook Street		03 & 09		Parking Spaces in Lot	The designated accessible parking spaces that is configured as a van accessible space does not provide a "van-accessible" sign.
	Vining School @ 121 Lexington Road		04 & 07		Changes in Level Along Accessible Route	There is a patch of asphalt missing near the designated accessible entrance creating a change in level measuring greater than 1/2 inch.
					Curb Cuts	The curb cut near the designated accessible parking spaces has a center running slope measuring 18.7% (2.25:12).
	Kennedy School @ 20 Kimbrough Road		05 & 10		Changes in Level Along Accessible Route	The accessible route to the designated accessible entrance has changes in level measuring greater than 1/2 inch.
					Curb Cuts	The curb cut located near the designated accessible entrance for polling has a center running slope exceeding 1:12 (8.33%).

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Billerica	Kennedy School @ 20 Kimbrough Road	00	05 & 10	No	Parking Spaces in Lot	The designated accessible parking space configured as a van accessible space: A) The space is missing the "van-accessible" sign and the regular HP sign at the head of the space.
					Ramps	The portable ramp is missing the wheel guards on both sides of the ramp.
	Dutile School @ Biagotti Way		06 & 11		Changes in Level Along Accessible Route	The accessible route to the designated accessible entrance has changes in level measuring greater than 1/2 inch.
					Curb Cuts	The curb cut at the designated accessible parking spaces has a center running slope measuring 14.5% (1.75:12).
					Lighting	The path of travel from the designated accessible parking to the designated accessible entrance does not provide adequate lighting.
					Parking Spaces in Lot	The designated accessible parking space configured as a van accessible parking space does not provide a "van-accessible" sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Blackstone	Municipal Center @ 15 Saint Paul Street	00	01 & 03	No	Changes in Level Along Accessible Route	There is a change in level, where the sidewalk and the curb cut meet near the entrance, measuring 2 inches.
					Curb Cuts	The curb cut, located near the ramp, has a center running slope measuring 12.0%.
					Parking Spaces in Lot	The designated accessible parking spaces do not provide any signs at the heads of the spaces.
	Saint Theresa's Church (Formerly Fire Station #2)		02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Blandford	Blandford Elementary School @ Russell Stage Road	00	01	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot do not provide signs at the head of the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Bolton	Town Hall @ 663 Main Street	00	01	No	Changes in Level Along Accessible Route	There are changes in level along the accessible route, from the lower parking lot to the lower entrance, that measures between 3/4 to 1 inch.
					Exterior Accessible Route	The walkway, leading from the lower parking lot to the lower entrance, has running slopes that measures 8.1%, closest to the parking. After about 10 feet the walkway has slopes of less than 5%.
					Parking Spaces in Lot	The designated accessible parking spaces provided: A) The space in the lower lot, does not provide an access aisle. B) There is no van accessible parking space provided in either the upper or lower lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Robert & Theresa Parks Community Building @ 2 New Whitney Street	??	??	N/A	**Comments	NOTE: The ramp survey was conducted by MOD, however this location was not surveyed by any team
					Ramps	<p>The ramp provided:</p> <p>a) The running slope of the ramp measures 10.0 % at the top.</p> <p>**b) The cross slope of the ramp measures 9.3% at the bottom and 6.5% in the middle.</p> <p>**c) The top landing has a slope measuring 3.4%.</p> <p>**d) The left side handrails do not extend at the top of the ramp.</p> <p>**e) The right side handrails do not extend at the bottom of the ramp.</p>
	Adams School @ 165 Webster Street	01	01	No	Changes in Level Along Accessible Route	There are sections of asphalt missing creating changes in level exceeding ½ inch.
					Entrances (Other than Locked)	The hardware on the entrance doors are doorknobs.
					Interior Accessible Route	The path of travel to the registration table is reduced to 32 inches because of a magazine rack.
					Interior Doors	<p>There is a set of double doors located on the interior of the building. Each of the doors provide less than 32 inches of clear width when open.</p> <p>NOTE: At the time of the survey these doors were not staffed.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Adams School @ 165 Webster Street	01	01	No	Parking Spaces in Lot	There is a parking lot provided at the polling location with no designated accessible parking spaces provided. NOTE: During the resurvey of this location on July 22, 2004 it was discussed that this is a teacher's parking lot. It was suggested by MOD that during the time of polling, a "Van-Accessible" parking space be provided near the designated accessible entrance door.
					Ramps	The ramp, located on the interior of the school: A) The ramp measures less than 48 inches wide. B) No handrails are provided on either side of the ramp. NOTE: The slope of the ramp could not be measured. The school was closed and access into the school was not possible.
	Donald McKay School @ 122 Cottage Street		02		Parking Spaces in Lot	There is a parking lot provided at the school. This parking lot provides over 100 parking spaces. There are no designated accessible parking spaces provided.
	BHA Heritage Apartments @ 209 Sumner Street		03		On-Street Parking	There is no on-street designated accessible parking space provided.
	Paris Street Community Center @ 112 Paris Street		04 & 05	Yes	None	
	Little Folks Day Care Center @ 65-67 Trenton Street		06 & 08		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	O'Donnell School @ 33 Trenton Street	01	07	No	Changes in Level Along Accessible Route	1) There are changes in level, located where you enter the playground, measuring 3/4 of an inch. 2) There is a change in level, on the interior of the designated accessible entrance, measuring 3/4-1 inch.
					Curb Cuts	The curb cut, located at the intersection of Lexington and Marion, near #74, has a center running slope measuring 11.3%.
					Entrances (Other than Locked)	The designated accessible entrance for polling: 1) The entrance does not provide hardware provided on the door. NOTE: At the time of the survey, the door was propped open 3 inches with a piece of wood. 2) The threshold, on the interior of the entrance door, measures 1 inch.
	Fire Station @ 360 Saratoga Street		09 & 10		On-Street Parking	There are no designated on-street accessible parking spaces provided along Lexington Street. Note: During the re-survey of the location, it was suggested by MOD that an on-street accessible parking space be provided at the intersection of Lexington and Marion, near #74. However the curb cut has non-compliant features.
					Entrances (Other than Locked)	The door hardware provided on the designated accessible entrance for polling is not useable with a closed fist.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Savio Prep High School Gym @ 94 Horace Street	01	11	No	Exterior Accessible Route	There is a running slope at the base of the ramp, where the playground meets the ramp, measuring 11.7%.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot. NOTE: During the re-survey, it was explained that the recess lot is used for parking during voting. Boston explained that a temporary accessible parking space will be provided near the ramp.
					Ramps	The ramp provided: a) The running slope of the ramp measures 9.2%, one block down from the top. **b) The handrails do not extend at the top of the ramp. **c) The handrails are not continuous. **d) The cross slope of the ramp measures 3.0% at the top.
	Orient Heights Branch Library @ 18 Barings Ave		12		Changes in Level Along Accessible Route	There is a change in level at the base of the curb cut, located at the intersection of Barnes Avenue and Baywater Street where the designated accessible parking space is provided, measuring 1-inch.
					Curb Cuts	The curb cut, located at the intersection of Barnes Avenue and Baywater Street where the designated accessible parking space is provided, has a center running slope measuring 10.9%.
					Entrances (Other than Locked)	The entrance used for polling does not provide a 60-inch level landing in front of the door on the outside. It provides only 54 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Curtis Guild School @ 5 Ashley Street	01	13	No	Entrances (Other than Locked)	The door for the designated accessible entrance used for polling does not have any hardware on the door. NOTE: At the time of the survey the door was propped open.
					Sample Ballot	The sample ballot is posted at a height of 66 ½ inches off the ground measured to the bottom of the ballot.
	Orient Heights Housing Project Community Building @ Faywood Avenue		14		**Comments	The ramp provided: **a) The landing provided at the area where the ramp changes direction, has a slope measuring 4.8%. **b) The landing provided on the second portion of the ramp, heading towards the entrance, has a slope measuring 4.0%. **c) The handrails do not extend at the bottom of the ramp.
					Changes in Level Along Accessible Route	1) There are changes in level in the sidewalk, leading to the ramp, measuring greater than ½ inch. 2) There are changes in level at the top and bottom of the ramp, measuring greater than 1/2 inch.
					Curb Cuts	There are no curb cuts to access the sidewalk that would lead to the ramp. However, there is a driveway that could be used to access the sidewalk but the running slope measures 18.5%.
					Entrances (Other than Locked)	The entrance has a threshold on the exterior of the door measuring 1-inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Orient Heights Housing Project Community Building @ Faywood Avenue	01	14	No	On-Street Parking	There is no designated on-street accessible parking space provided. NOTE: During the resurvey, MOD suggested that a temporary on-street space be provided near the driveway, since no curb cut are located near the entrance. However, the driveway has non-conforming features.
	Harbor Point @ 1 North Point Drive		15	Yes	None	
	Community Room @ 114 Old Rutherford Ave	02	01	No	Exterior Accessible Route	The path of travel to the polling entrance has running slopes measuring 10.5% and 11.0% at the driveway and 13.1% at the next rise.
					On-Street Parking	There are no designated accessible on-street parking spaces provided.
	Kent School @ 50 Bunker Hill Street		02 & 04		Entrances (Other than Locked)	The designated accessible entrance to the polling location does not provide hardware on the doors. These doors are fire doors. NOTE: These doors were propped open during the survey.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Charlestown Library @ 179 Main Street	02	03	No	**Comments	<p>**1) The cross slopes along Green Street measure 8.7% to 9.0%.</p> <p>**2) The running slope from Main Street to Green Street, leading to the entrance, measures 9.5%.</p> <p>**3) Even though at the time of the survey the elevator was working, the note attached to the elevator states "Elevator has a habit of breaking down in severe rain storms - we're sorry for the inconvenience."</p>
					Curb Cuts	The curb cut located at the corner of Green Street and Main Street has a center running slope measuring 9.0% and 11.0%.
					On-Street Parking	There are no designated accessible on-street parking spaces provided.
	Edwards School @ 28 Walker Street		05 & 06		Entrances (Other than Locked)	<p>The designated accessible polling entrance:</p> <p>a) The threshold at the door measures 1 ½ inches.</p> <p>b) The landing at the exterior of the door has a slope measuring 5.4%.</p> <p>c) The designated accessible polling entrance has a set of double doors.</p> <p>The doors:</p> <p>i) Each door only provides 29 inches of clear width.</p> <p>ii) The doors do not provide have any hardware on the exterior.</p> <p>NOTE: At the time of the survey, the doors were propped open.</p>
					Exterior Accessible Route	The sidewalk along Eden Street narrows reducing the path of travel from the required 36 inches to 29 inches because of trees.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Edwards School @ 28 Walker Street	02	05 & 06	No	Lighting	The approach to the polling entrance does not provide any lighting.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
	Golden Age Senior Center @ 382 Main Street		07		Changes in Level Along Accessible Route	The gate, at the entrance, has changes in level measuring 1 ½ inches.
					Curb Cuts	The curb cut located at the intersection of Main and Middlesex Street has a center running slope measuring 11.0%.
					Directional Signage	There is no directional signage indicating where the accessible entrance is located.
					Entrances (Other than Locked)	The landing, on the exterior of the designated accessible entrance to the polling site, measures 54 inches out from the door.
					Exterior Accessible Route	1) The crosswalk provided in front of the polling site does not provide a curb cut to access the sidewalk. 2) The designated accessible entrance is located through a laundry room. The driveway and sidewalk that leads to this entrance has a cross slope measuring 14.0%.
					Interior Accessible Route	The accessible route inside the polling location is reduced from the required 36 inches to 29 inches because of furniture.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Golden Age Senior Center @ 382 Main Street	02	07	No	On-Street Parking	There are no temporary designated accessible on-street parking spaces provided.
						NOTE: The day of the survey was also street cleaning day. We were cautioned to not leave car in front of polling location.
	Christopher Columbus Elderly Housing @ 145 Commercial Street	03	01		Sample Ballot	The sample ballot is posted at a height of 65 inches measured to the bottom of the ballot.
					On-Street Parking	There are no designated accessible on-street parking spaces provided.
	Nazzaro Building (Formerly ABCD Program Community Room)		02 & 03		Curb Cuts	The driveway, used to access the sidewalk to get to the entrance, has a center running slope measuring 10.9%.
					Entrances (Other than Locked)	The designated accessible entrance used for polling: A) The landing on the exterior of the entrance door is not level. The slope measures 4.7%. B) The hardware on the exterior of the door is not operable with a closed fist. The hardware is a handle, but it is too small to use. C) The door is extremely sticky. It requires an extreme amount of pulling force to open the door.
	Knights of Columbus @ 41 North Margin Street		04		On-Street Parking	There is no designated on-street parking space provided.
					Curb Cuts	The curb cut located at the corner of Salem and North Margin Street: a) Has a center running slope measures 23.6%. **b) There is pooling of water at the base of the curb cut.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Knights of Columbus @ 41 North Margin Street	03	04	No	Entrances (Other than Locked)	The double doors at the designated accessible entrance for the polling location: a) Each door provides only 26 inches of clear opening. b) The door hardware is not accessible.
					Interior Doors	There is a set of double doors on the interior of the entrance. a) Each door provides only 28 inches off clear opening. b) The vestibule measures 6 feet 3 inches between the doors.
					Parking Spaces in Lot	There are no designated accessible parking spaces located in the parking lot.
	Amy Lowell House @ 65 Martha Road		05		Ramps	The ramp provided has a running slope measuring 8.4% to 9.8%.
					Curb Cuts	The curb cut located at the front of the building near the entrance has center running slope measuring 20.8%.
					On-Street Parking	There are no temporary designated accessible on-street parking spaces provided. NOTE: Even though there is no on-street parking provided, a space should be temporarily designated for accessible on-street parking near the fire lane at the front of the building.
	City Hall @ 1 City Hall Plaza		06		On-Street Parking	There are no designated accessible on-street parking spaces provided at either the main entrance or the dock square entrance.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	City Hall @ 1 City Hall Plaza	03	06	No	Ramps	There are 3 ramps provided that could be used depending on which entrance is used. 1) Main Entrance: A) The ramp leading to the main entrance has an upper handrail, on the left side of the ramp near the bottom that is disconnected from the wall. 2) Dock Square Ramp: A) The running slope of the ramp measures 11.2% at the bottom and 10.2% at the top. B) There is only an upper handrail provided on the right side of the ramp. There are no other handrails provided. 3) The interior ramp, that would lead to the voting area: A) The running slope measures 8.9% in the middle and 9.4% at the top. B) No handrails are provided on either side of the ramp.
	YMCA of Boston @ 40 Berkeley Street		07		Curb Cuts	There are two curb cuts located at the corner of Gray and Berkeley Street. a) One curb cut has a center running slope measuring 18.2%. b) One curb cut has a center running slope measuring 10.0% to 13.1%.
					On-Street Parking	There are no designated accessible on-street parking spaces provided.
	Josiah Quincy School @ 885 Washington Street		08		Curb Cuts	The curb cut located near the designated accessible entrance to the polling location has a center running slope measuring 11.8% and 13.3%.
					Entrances (Other than Locked)	The entrance doors at the designated accessible entrance to the polling location has a threshold measuring 1 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Josiah Quincy School @ 885 Washington Street	03	08	No	On-Street Parking	There are no designated accessible on-street parking spaces provided.
					Ramps	The ramp provided: a) Has a running slope measuring 9.3%. b) The ramp does not provide any handrails.
	McKinley School @ 90 Warren Avenue	04	01 & 03		Changes in Level Along Accessible Route	1) There are changes in level measuring greater than ½ inch along the accessible route to the polling location. 2) The designated accessible entrance for polling has a change in level that requires the use of a portable ramp. At the time of the survey, the ramp was not in place. NOTE: The surveyor was told that when someone needs the ramp, it is installed and then uninstalled.
					Interior Doors	There are accessibility issues with the interior doors.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
	Tent City Community Room @ 130 Dartmouth Street		02		Exterior Accessible Route	There is a change in level measuring greater than ½ inch at the entrance.
					On-Street Parking	There are no designated on-street accessible parking spaces provided. NOTE: There are no parking spaces of any kind provided at this location.
	Douglas Apartments @ 755 Tremont Street		04		Changes in Level Along Accessible Route	There are changes in level measuring greater than ½ inch at the entrance.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Douglas Apartments @ 755 Tremont Street	04	04	No	Entrances (Other than Locked)	The threshold at the designated accessible entrance for polling measures greater than ½ inch.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
	YMCA @ 316 Huntington Avenue		05 & 08		Directional Signage	The designated accessible entrance used for polling could not be located. There were no signs indicating where the accessible entrance was located.
					Ramps	The ramp provided: a) The running slope of the ramp measures 9.8% at the top. **b) The landing located at the bottom of the ramp measures 2.8% and 5.4%. **c) The handrails do not extend at the bottom of the ramp. **d) The clear space, measured between the handrail and the wall, measures 1 ¾ inches.
	Morville House @ 100 Norway Street		06 & 07	Yes	None	
	Old Boston Trade School @ 550 Parker Street		09		None	
	Simmons College @ 300 Fenway		10	No	On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Franklin Institute @ 465 Tremont Street	05	01		Changes in Level Along Accessible Route	1) There are changes in level, located at the driveway used to access the sidewalk, measuring 3/4-1 inch within the cobblestones. 2) There are change in level, along the walkway leading to the entrance measuring 3/4 to 1 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Franklin Institute @ 465 Tremont Street	05	01	No	Curb Cuts	The driveway, which is the only way to access the sidewalk to get to the designated accessible entrance, has a center running slope measuring 20.7% at the bottom and 9.5% at the top.
					Exterior Accessible Route	The walkway, leading to the designated accessible entrance, has a running slope measuring 13.5%.
					On-Street Parking	There is no designated accessible on-street parking spaces provided.
	Boston Arts Academy @ 174 Ipswich Street		02		On-Street Parking	NOTE: During the re-survey, MOD suggested that the spaces be provided near door #4, near the driveway. However, the driveway has non-conforming features.
						There are no designated on-street accessible parking spaces provided.
	State House Hearing Room B1 (Basement)		03	Yes	None	
	West End Library @ 151 Cambridge Street		04	No	On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Hill House Community Center @ 177 Mount Vernon Street		05 & 11		On-Street Parking	There is no designated accessible on-street parking space provided.
						NOTE: During the re-survey, MOD suggested that make the first spot the designated accessible space. This would be the closest to the curb cut on River Street.
	Fisher Jr. College @ 116 Beacon Street		06		Directional Signage	There were no directional signs indicating where the accessible entrance was located.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Fisher Jr. College @ 116 Beacon Street	05	06	No	Entrances (Other than Locked)	1) The designated accessible entrance does not provide a 5 foot level landing on the exterior of the door. A) The slope of the landing measures 9.7%. B) There is no landing present because the ramp run extends to the door.
					Interior Doors	The door, located in the vestibule after the entrance door, does not provide door hardware that is operable with a closed fist. The door hardware on the interior and exterior of the door are door knobs.
					On-Street Parking	There are no designated on-street accessible parking spaces provided. NOTE: During the re-survey, Boston suggested that a space will be provided near the entrance.
					Ramps	There are 2 ramps provided at this location. 1) The ramp provided on the interior of the building: a) The running slope of the ramp measures 9.0% at the bottom and 12.1% at the top. B) The lower handrail is missing from the right side of the ramp. **c) The handrails do not extend at the top of the ramp. **d) The wall hung handrail provides a clear space, measured between the handrail and the wall, measuring 2 ¼ inches.
	Copley Square Library on Boylston Street		07, 08 & 09		Curb Cuts	2) The ramp, located on the exterior of the building at the entrance. A) The top of the ramp has a running slope measuring 9.7%. The curb cut, located near the designated accessible on-street parking spaces at Boylston and Exeter, has a center running slope measuring 12.3% to 13.2%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Boston University - Myles Standish Hall @ 30 Bay State Road	05	10	No	Directional Signage	There are no signs indicating where the designated accessible entrance is located.
					Entrances (Other than Locked)	The hardware on the designated accessible entrance doors are doorknobs.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Condon School @ 200 D Street	06	01, 02 & 03	On-Street Parking	There are no designated on-street accessible parking spaces provided.	
	Gate of Heaven CYO Hall @ East Fourth Street		04 & 06	Curb Cuts	The curb cut, located at 1st Street and East 4th Street, where the designated accessible on-street parking will be provided, has a center running slope measuring 9.8%.	
	Entrance Locked	At the time of the survey (12:10pm) the doors were locked.				
	Entrances (Other than Locked)	The designated accessible entrance used for polling: 1) There is no door hardware provided on the exterior of the door. 2) The entrance does not provide a 5 foot level landing on the exterior of the door. The landing measures 26 inches. The slope after the level portion measures 12.5%. 3) The entrance doors are a set of double doors. Each door opened individually provides only 26 inches of clear opening.				
	Interior Accessible Route	The accessible route on the interior of the building is reduced to less than 36 inches in some locations.				
		NOTE: During the re-survey the accessible route throughout the building was at least 36 inches. A 36 inch path of travel throughout the polling location will be maintained during polling.				

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Gate of Heaven CYO Hall @ East Fourth Street	06	04 & 06	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot do not have any access aisles. NOTE: During the re-survey it was noticed that the parking lot is a long distance from the entrance used. Boston has suggested that an on-street parking space be located 1st Street and East 4th Street. However, the curb cut has non-conforming features.
	South Boston Library @ 646 East Broadway		05	Yes	None	
	Saint Bridgid's Church @ 845 East Broadway		07, 08 & 09	No	Directional Signage	There are no signs indicating where the designated accessible entrance for polling is located. NOTE: During the re-survey, the directional signage has not been posted.
					Entrances (Other than Locked)	The designated accessible entrance used for polling: A) There is no 5 foot level landing provided on the exterior of the door. The landing is sloped at the door. B) There is no 5 foot level landing on the interior of the door. The landing has a slope measuring 21.3%. C) The entrance is a set of double doors. Each door opened individually provides only 27 inches of clear opening.
					Exterior Accessible Route	The walkway, leading to the designated accessible entrance, has a running slope measuring 8.1% at the top, 11.5% in the middle and 4.5% at the top.
					On-Street Parking	There is no designated accessible on-street parking provided. NOTE: There are no curb cuts located near the area where an on-street parking space could be provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Saint Bridgid's Church @ 845 East Broadway	06	07, 08 & 09	No	Ramps	There is an interior ramp: A) The running slope of the ramp measures 9.8% at the bottom, 10.3% in the middle and 10.5% at the top. B) The ramp measures 40 inches wide, measured between the handrails. C) There are no lower handrails provided on either side of the ramp. D) The upper handrail, on the left side of the ramp, does not extend the entire run of the ramp. E) The upper handrails provided are not round or oval.
		07	01 & 02		**Comments	During the re-survey, Boston suggested that a temporary accessible parking space be created near the designated accessible entrance. This would put the parking closer to the entrance. However, the curb cut located at the on-street accessible parking space would still need to be addressed.
	L Street Bath House @ 1663 Columbia Road				Curb Cuts	The curb cut, located at the designated accessible on-street parking space, has a center running slope measuring 10.2%.
					Entrances (Other than Locked)	The designated accessible entrance for polling: A) The threshold at the entrance doors measures 2 ½ inches. B) There is no 5 foot level landing provided on the exterior of the doors. The slope of the landing measures 4.2%.
					Exterior Accessible Route	The walkway, leading to the designated accessible entrance used for polling, has running slopes that are ramp slopes. The slopes measure 5.6% to 6.3%.
	Foley Building @ 199 H Street		03	Yes	None	
	Gavin School @ 215 Dorchester Street		04	No	Entrance Locked	The designated accessible entrance for polling was locked.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Gavin School @ 215 Dorchester Street	07	04	No	Entrances (Other than Locked)	The designated accessible entrance used for polling: A) The hardware on the door could not be used with a closed fist. B) There is no 5 foot level landing provided on the exterior of the entrance door. The landing measures 48 inches.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot. NOTE: During the re-survey, Boston suggested that an accessible parking space will be provided at the base of the ramp, near the entrance.
					Ramps	The ramp, provided at the designated accessible entrance: A) The running slope measures 9.9% to 11.6%. B) There are no handrails provided on the right side of the ramp.
	West Ninth Elderly Community Room @ 185 West Ninth Street		05		On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Mary Ellen McCormack Task Force Office @ 345 Old Colony Avenue		06 & 07		On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Bellflower Apartments @ 24 Bellflower Street		08 & 09		On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Fire Station Engine 21 @ 641 Columbia Road		10		Changes in Level Along Accessible Route	There is a changes in level measuring 2 ½ inches on the exterior of the entrance door..

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Fire Station Engine 21 @ 641 Columbia Road	07	10	No	Entrances (Other than Locked)	The designated accessible entrance used for polling: A) The hardware on the doors at the designated accessible entrance are doorknobs. B) There is no 5 foot level landing provided on the exterior of the door. The landing measures 54 inches and has a slope measuring 5.4%. C) The door provides a clear width measuring 29-30 inches.
					On-Street Parking	There are no designated on-street accessible parking spaces provided. NOTE: During the re-survey, Boston suggested locating the on-street accessible parking space to be near the fire doors.
					Entrances (Other than Locked)	The interior threshold of the designated accessible entrance measures 1 inch. NOTE: During the re-survey, Boston suggested moving the entrance for everyone to the door to the left. The door on the left is only 10 feet away from the door mentioned above.
	Cathedral Housing Project @ 1472 Washington Street	08	01		Exterior Accessible Route	The accessible route, from the parking to the ramp, has running slopes measuring 10.2% and 11.9%.
					Ramps	The ramp provided: a) The running slope of the ramp measures 9.9% at the top of the second run up. B) The handrails on the right side of the ramp do not extend the entire run of the ramp. **c) The landing at the bottom of the ramp has a slope measuring 4.6%. **d) The handrails do not extend at the top of the ramp. **e) The handrails are not continuous.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Blackstone School @ 380 Shawmut Avenue	08	02	No	Changes in Level Along Accessible Route	There are change in level along the ramp that is closest to the school and the street, measuring between 1-2 inches.
					Curb Cuts	There are no curb cuts provided near the metered parking, where the designated accessible on-street parking space would be provided as suggested by Boston. However, the driveways, that would be used to access the sidewalk, have running slopes measuring 15.6% and 19.2%.
					Entrances (Other than Locked)	The designated accessible entrance used for polling: A) There is no door hardware provided on the exterior of the entrance door. B) The entrance door provides 30 inches of clear opening.
					On-Street Parking	There are no designated accessible on-street parking provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Blackstone School @ 380 Shawmut Avenue	08	02	No	Ramps	<p>There are 3 ramps that could be used to access the designated accessible entrance:</p> <p>1) The ramp provided closest to the playground provides the lower handrails at a height of 16 inches.</p> <p>2) The ramp, located closest to the school and the street:</p> <p>A) The first portion down:</p> <p>I) The running slope measures 14.8% at the top.</p> <p>II) This portion measures 44 inches wide, measured between the handrails.</p> <p>III) This portion does not provide handrails on the right side.</p> <p>IV) The bottom handrails, provided on the left side of this portion, measures 16 inches high.</p> <p>B) The 2nd run down:</p> <p>I) The running slope measures 10.4% in the middle and 10.2% at the bottom.</p> <p>II) The bottom handrails, provided on both sides, measures 16 inches high.</p> <p>3) The ramp, that leads to the designated accessible entrance door: (This ramp would need to be used regardless of whether ramp 1 or 2 was used.)</p> <p>A) The running slope measures 10.3% at the bottom.</p> <p>B) The bottom handrails, provided on both sides, measure 16 inches high.</p>
	Orchard Gardens Elementary School @ 906 Albany Street		03 & 04		Ramps	The ramp, located on the interior of the school, has running slopes measuring 10.8% at the top of the 1st run down and 9.4% at the top of the 2nd run down.
	Mason School @ 150 Norfolk Avenue		05	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Boston Patrolman Association @ 9 11 Shetland Street	08	06	No	Ramps	The ramp provided: a) The running slope measures 9.1% at the bottom and 9.9% at the top. b) There is a change in level at the to of the ramp measuring ½ inch and is not beveled. **c) The clear space, measured between the handrail and the wall, measures between 2 inches and 2 ½ inches.
	Vine Street Community Center @ 339 Dudley Street		07		Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
	ETC Building @ 80 West Dedham Street	09	01		Entrances (Other than Locked)	The door for the designated accessible entrance does not provided accessible hardware. A doorknob is provided.
	Fire Station @ 700 Tremont Street		02	Yes	None	
	Elderly Housing @ 155 North Hampton Street		03	N/A	**Comments	** No survey form received for this location.
	Madison Park Complex - Haynes House Community Room @ 735 Shawmut Avenue		04	No	On-Street Parking	There are no designated on-street accessible parking spaces provided.
					Ramps	The running slope of the ramp measures 9.2% at the top.
					Sample Ballot	The sample ballot was not posted.
	Marcus Garvey Gardens		05	N/A	**Comments	** No survey form received for this location.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Tobin Municipal Building @ 1481 Tremont Street	10	01, 02, 03 & 05	No	Ramps	The ramp provided: a) The running slope of the ramp measures 10.2% at the bottom, 9.0% in the middle, and 8.7% at the top. **b) The clear space, measured between the handrail and the wall, measures 1 ¾ inches.
	Mission Park		04		Entrances (Other than Locked)	The door for the designated accessible entrance for polling does not provide accessible hardware on the door.
	Kennedy School @ 7 Bolster Street		06 & 07	N/A	**Comments	** No survey form received for this location
	Back of the Hill Apartments @ 100 South Huntington Avenue		08	No	Parking Spaces in Lot	There are two designated accessible parking spaces provided in the parking lot, however: a) There is no access aisle provided for the 2 spaces. b) The 2 spaces do not have signs at the head of the spaces. NOTE: The driveway is used as the access aisle.
					Ramps	The ramp provided: a) The running slope of the ramp measures 11.1%. b) Handrails are provided only on the right side of the ramp. c) The upper handrail is located at a height of 30 ½ inches and the lower handrails are located at a height of 16 ½ inches. **d) The lower handrail is not continuous.
	James M. Curley School @ 493 Center Street		09		Entrances (Other than Locked)	The landing on the exterior of the entrance measures 43 inches out.
					Parking Spaces in Lot	The parking lot, that provides about 25 parking spaces, does not provide any designated accessible parking spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	James M. Curley School @ 493 Center Street	10	09	No	Ramps	1) The ramp (exterior) provided at the entrance: a) The running slope measures 10.5%. b) No handrails are provided. 2) There is an interior ramp along the path of travel to the polling area: a) There is only the upper handrails provided on each side of the ramp. b) The left handrail does not run the entire length of the ramp.
	Roxbury Community College Student Lounge @ 1234 Columbus Avenue	11	01		Sample Ballot	The sample ballot is located at a height of 55 inches measured to the bottom of the ballot.
	Shelburne Center @ 2730 Washington Street		02		Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
	Ellis School @ 302 Walnut Avenue		03		Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot do not have signs at the head of the spaces.
	Elderly Housing @ 125 Armory Street		04		**Comments	** There is an interior ramp at this location. However the ramp was not inspected during the survey.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot do not provide access aisles adjacent to the spaces.
	Elderly Housing @ 1990 Columbus Avenue		05		Sample Ballot	The sample ballot is located at a height of 54 inches measured to the bottom of the ballot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Brookside Family Life Center @ 3297 Washington Street	11	06	Yes	None	
	Boston English High School @ 144 McBride Street		07 & 08	No	Entrances (Other than Locked)	The designated accessible entrance for polling does not provide any hardware on the exterior of the door. NOTE: At the time of the survey the door was propped open with a brick.
	Agassiz School @ 13 Carolina Avenue		09 & 10		Entrances (Other than Locked)	The door that is designated the accessible entrance for polling has a doorknob.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
					Sample Ballot	The sample ballot is located at a height of 52 inches measured to the bottom of the ballot.
	Roxbury Boys Club @ 1145 Warren Street	12	01		On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Boston Latin Academy @ 35 Townsend Street		02		Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot do not provide signs at the head of the spaces.
					Sample Ballot	The sample ballot is located at a height of 53 inches measured to the bottom of the ballot.
	Lewis School @ 131 Walnut Avenue		03		Entrances (Other than Locked)	The designated accessible entrance for polling: a) The doorway only provides a 29 inch clear opening. b) There is no hardware on the exterior of the door. NOTE: At the time of the survey the door was propped open.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Lewis School @ 131 Walnut Avenue	12	03	No	Interior Doors	The interior door leading to the gymnasium provides only 29 inches of clear opening.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Sara Baker House @ 33 Perrin Street		04		Entrance Locked	The designated accessible entrance for polling is locked.
					Parking Spaces in Lot	The designated accessible parking spaces do not have signage at the front of the spaces.
					Sample Ballot	The sample ballot is located at a height of 55 inches measured to the bottom of the ballot.
	Housing for the Elderly @ 280 Martin Luther King Boulevard		05	Yes	None	
	Early Learning Center @ 263 Blue Hill Avenue		06	No	On-Street Parking	There are no designated on-street accessible parking spaces provided.
					Sample Ballot	The sample ballot is located at a height of 56 inches measured to the bottom of the ballot.
	Elderly Housing @ 125 Elm Hill Avenue		07		**Comments	** There is an interior ramp at this location. However the ramp was not inspected during the survey.
					Exterior Accessible Route	At the time of the survey, a fire hose was blocking the accessible route to the polling entrance.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Ellis School @ 302 Walnut Avenue	12	08 & 09	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot do not have signs at the head of the spaces.
	Cardinal Medeiros Manor @ 11 Woodcliff Street	13	01 & 02		Curb Cuts	The curb cut, located near the ramp, has a center running slope measuring 10.2%.
					On-Street Parking	There are no designated accessible on-street parking spaces provided. NOTE: During the re-survey, it looked like the sign was missing.
					Ramps	The ramp provided: a) The running slope of the ramp measures 9.1% at the top. b) The ramp narrows to 41 inches wide at the top area. **c) The clear space, measured between the handrail and the wall, measures 2 inches near the top of the ramp. **d) The lower handrails are not continuous.
	Harbor Point @ 1 North Point Drive		03	Yes	None	
	Boston Pilot Middle School @ 270 Columbia Road		04	No	Curb Cuts	The curb cut, located across from the flag pole, near the designated accessible entrance used for polling, has a center running slope measuring 10.9% and 11.4%.
					Entrances (Other than Locked)	The designated accessible entrance door used for polling does not provide hardware on the exterior of the door.
	Municipal Building @ 500 Columbia Road		05		Curb Cuts	The curb cut, located at the designated accessible on-street parking, has a center running slope measuring 9.6%.
					Entrances (Other than Locked)	The entrance has a 1-inch threshold.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Municipal Building @ 500 Columbia Road	13	05	No	Ramps	<p>The ramp provided:</p> <p>a) The running slope of the ramp measures 11.1% at the bottom of the ramp (3rd block up).</p> <p>b) Only the upper handrails are provided.</p> <p>c) The right handrail ends about 12 feet from the bottom of the ramp.</p> <p>d) The left handrail ends about 8 feet from the bottom of the ramp.</p> <p>**e) The landing provided at the top of the ramp has a slope measuring 2.5%.</p> <p>**f) The landing provided at the bottom of the ramp has a slope that measures 3.1%.</p>
	Annapolis Apartments @ 8 Annapolis Street		06		Exterior Accessible Route	<p>The walkway, leading from the designated accessible parking space to the entrance, has a running slope at the top that equals a ramp. The slope at the top measures 6.3%.</p>
					Parking Spaces in Lot	<p>The designated accessible parking space:</p> <p>A) There is no sign provided at the head of the space.</p> <p>**b) The slope of the access aisle measures 5.7%.</p> <p>NOTE: During the re-survey, Boston suggested a different route for people to the entrance, which included a different parking space.</p>
	Catherine Clark Apartments @ 915 Dorchester Avenue		07 & 08	Yes	Sample Ballot	<p>The sample ballot is located at a height of 59 ½ inches to the bottom.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Edward Everett School @ 71 Pleasant Street	13	09	No	Entrances (Other than Locked)	The designated accessible entrance door leads to a lift that is independently operable. A) There is a 1-inch threshold on the exterior of the door. B) There is no level landing provided on the exterior of the entrance door. The slope of the landing measures 7.9%.
					Parking Spaces in Lot	The parking lot: a) There are 27 parking spaces provided with only 1 designated accessible parking space. B) The access aisle measures 4 feet wide.
						NOTE: During the re-survey, Boston suggested that 2 designated accessible parking spaces will be provided that will share an eight-foot access aisle.
	Saint William School @ 100 Savin Avenue		10		**Comments	This Location has been moved. Need to clarify where it was relocated.
	Boston Pilot Middle School @ 270 Columbia Road	14	01 & 03		Curb Cuts	The curb cut, located across from the flag pole, near the designated accessible entrance used for polling, has a center running slope measuring 10.9% and 11.4%.
					Entrances (Other than Locked)	The designated accessible entrance door used for polling does not provide hardware on the exterior of the door.
	Sarah Greenwood School @ 186 Glenway Street		02		Directional Signage	There is no directional signage indicating where the designated accessible entrance is located.
					Entrances (Other than Locked)	The designated accessible entrance for polling provides a 1 ½ inch threshold.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	John P. Holland School Community Center @ 85 Onley Street	14	04	No	Entrances (Other than Locked)	There is a ¾ inch threshold at the entrance.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
	Pauline Agassisz Shaw School @ 429 Norfolk Street		05, 12 & 13		Changes in Level Along Accessible Route	There is a 1-inch change in level at the bottom of the ramp.
					Entrance Locked	The designated accessible entrance for polling was locked.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
	Boston Middle School Academy (Formerly the William Endicott School) @ 2 Mclelan Street		06		Sample Ballot	The sample ballot was located at a height of 53 inches measured to the bottom of the ballot.
					Entrances (Other than Locked)	There is a ¾ inch threshold at the entrance.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Boston Middle School Academy (Formerly the William Endicott School) @ 2 Mclelan Street	14	06	No	Ramps	The ramp provided: a) The upper handrails are located at a height of 31 inches and the lower handrails are located at a height of 16 inches. b) There is a change in level measuring 2 inches at the top of the ramp . **c) The landing provided at the top of the ramp has a slope measuring 7.7%. **d) There is pooling of water in the middle landing area.
					Sample Ballot	The sample ballot is located at a height of 51 inches above the floor measured to the bottom of the ballot.
					Entrances (Other than Locked)	The door for the designated accessible entrance for polling does not provided any hardware on the exterior of the door. NOTE: At the time of the survey, the door was propped open.
	Joseph Lee School @ 43 Talbot Avenue		07		Interior Doors	The interior set of double doors do not provide the proper hardware. There are doorknobs provided.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: a) There are about 57 parking spaces provided. There is only 1 designated accessible parking space provided. b) There is no access aisle provided.
	Solomon Lewenberg School @ 20 Outlook Road		08 & 14		**Comments	**There was an interior ramp, but the ramp was not surveyed.
					Entrances (Other than Locked)	There is no door hardware provided on the exterior of the designated accessible entrance door. NOTE: At the time of the survey, one door was propped open.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Solomon Lewenberg School @ 20 Outlook Road	14	08 & 14	No	Exterior Accessible Route	The parking lot is located on the opposite side of the school in relation to the accessible entrance. The only way to get from the parking lot to the entrance is to use the street. There is no direct route of travel from the parking lot to the accessible entrance.
					Parking Spaces in Lot	The designated accessible parking spaces provided: a) There are 27 parking spaces provided. There is only one designated accessible parking space. b) There is no sign provided at the designated accessible parking space.
					Curb Cuts	The curb cut located at the head of the access aisle for the designated accessible parking space has a center running slope exceeding 8.33%.
	Boys and Girls Club @ 15 Talbot Avenue		09		Interior Accessible Route	There is a metal detector located inside the entrance. The accessible route is reduced to 29 inches because of it.
					Parking Spaces in Lot	The designated accessible parking space provided in the parking lot does not have a sign at the head of the space.
					On-Street Parking	There are no designated accessible on-street parking spaces provided.
	Tenants Association Apartments @ 92 Ames Street		10		Ramps	The running slope of the ramp measures 9.0% at the bottom.
					Sample Ballot	The sample ballot is located at a height measuring 50 ½ inches to the bottom of the ballot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Mattapan Police Station @ 1165 Blue Hill Avenue	14	11	No	**Comments	<p>**The ramp to the left of the entrance, when facing the entrance:</p> <p>**a) The clear space, measured between the wall and the handrail, measures 4 ¼ inches.</p> <p>**b) The handrails do not extend at the top and bottom of the ramp.</p> <p>**c) This ramp is designed as a curved ramp.</p> <p>**The ramp to the right of the entrance, when facing the entrance:</p> <p>**a) The handrails do not extend at the top and bottom of the ramp.</p> <p>**b) This ramp is designed as a curved ramp.</p> <p>**c) The clear space, measured between the wall and the handrail, measures 4 ½ inches.</p>
					Changes in Level Along Accessible Route	The ramp to the right of the entrance, when facing the entrance has a 1-inch change in level at the top.
					On-Street Parking	There is no designated on-street accessible parking space provided.
					Sample Ballot	The sample ballot is located at a height measuring 53 inches to the bottom of the ballot.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
					Entrance Locked	<p>The designated accessible entrance is the "fire engine door". At the time of the survey it was closed.</p> <p>NOTE: At the time of the survey, the polling staff stated that someone needing assistance would have to bang on the "fire engine door" and they would raise it. The door was not staffed at the time of the survey.</p>
	Early Learning Center @ 370 Columbia Road	15	01			
	Fire Station @ 7 Parish Street		02 & 03			

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Fire Station @ 7 Parish Street	15	02 & 03	No	Exterior Accessible Route	There are large patches of asphalt along the accessible route to the polling entrance that have changes in level measuring greater than ½ inch.
					On-Street Parking	There are no designated on-street accessible parking spaces provided. NOTE: During the re-survey, Boston suggested that the on-street parking be provided near the pole close to the employee parking lot.
					Sample Ballot	The sample ballot is located at a height measuring 59 ½ inches to the bottom of the ballot.
	Pasciucco Apartments @ 330 Bowdoin Street		04		Entrances (Other than Locked)	The designated accessible entrance: A) The threshold at the designated accessible entrance for polling measures 1 ½ inches. B) There is no 5 foot level landing provided on the interior of the entrance door. The landing measures 3 feet before the slope of the ramp begins.
					Ramps	There is a ramp located on the interior of the entrance door. There are no lower handrails provided.
					Sample Ballot	The sample ballot is located at a height measuring 53 inches to the bottom of the ballot.
	John Marshall School @ 35 Westville Street		05		Entrances (Other than Locked)	The exterior doors entering the polling location have thresholds measuring between ¾ to 1 inch.
					Exterior Accessible Route	There are no curb cuts provided on the side of the street facing the accessible entrance. NOTE: During the re-survey, Boston suggested installing a curb cut and adding an accessible on-street parking space where work is being conducted on the sidewalk.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	John Marshall School @ 35 Westville Street	15	05	No	On-Street Parking	There are no designated on-street accessible parking spaces provided. NOTE: There is a small parking lot provided for teachers and staff without any designated accessible parking spaces.
	Saint William School @ 100 Savin Avenue		06	N/A	**Comments	This Location has been moved. Need to clarify where it was relocated.
	Viet Aid Community Center @ 42 Charles Street		07 & 08	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot do not have signs at the head of the spaces.
	Dorchester House @ 1353 Dorchester Avenue		09		Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: a) The spaces do not have signs at the head of the spaces. b) There is no curb cut provided where the access aisle meets the sidewalk.
	Patrick O'Hearn School @ 1669 Dorchester Avenue	16	01 & 04		Curb Cuts	The curb cut, located near the gateway to access the walkway leading to the designated accessible entrance, has a center running slope measuring 9.8% at the bottom.
					Entrance Locked	The designated accessible entrance for polling was locked. NOTE: Someone would need to enter the building through the inaccessible main entrance and get assistance through the back door.
					Exterior Accessible Route	The top of the walkway, that leads to the designated accessible entrance, has a running slope measuring 13.3%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Patrick O'Hearn School @ 1669 Dorchester Avenue	16	01 & 04	No	On-Street Parking	There are no designated on-street accessible parking spaces provided. NOTE: During the re-survey, Boston suggested locating a designated accessible on-street parking space near the curb cut that leads to the walkway that leads to the entrance. However, the curb cut and the walkway have non-conforming features.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
	National Guard Armory @ 70 Victory Road		02		Ramps	At the time of the survey (11:25am) there was a portable ramp at the entrance to the polling location to traverse one step. The portable ramp: a) The running slope of the ramp measures 5 ½ inches high with 36 inches of run (15%). b) The portable ramp does not have handrails or wheel guards. c) There is a ½ inch lip at the bottom of the ramp that is not beveled.
	Saint Mark's School Hall		03 & 06		Directional Signage	There are no signs indicating where the accessible entrance is located.
					Entrance Locked	At the time of the survey (2:55pm) the designated accessible entrance was locked.
					Entrances (Other than Locked)	The designated accessible entrance for polling has a 1-inch threshold at the door.
					Interior Doors	The interior door has a clear opening measuring 27 inches.
					Parking Spaces in Lot	The designated accessible parking space provided in the parking lot does not provided a sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Richard J. Murphy School @ 1 Worrell Street	16	05	No	Changes in Level Along Accessible Route	1) The designated accessible entrance has a change in level at the bricks near the door measuring 1 1/2 to 2 inches.
						2) The left side curb cut, located at the designated accessible on-street parking, has a change in level at the base measuring 1-2 inches.
						3) The right side curb cut, located at the designated accessible on-street parking, has a change in level at the base measuring 1 to 1 1/2 inches.
	Saint Ann's School @ 237 Neponset Avenue		07 & 10		Entrances (Other than Locked)	There is no 5 foot level landing provided on the exterior of the entrance door. The slope of the landing measures 13.8%.
					Changes in Level Along Accessible Route	1) There are changes in level, along the accessible route from the street to the designated accessible entrance measuring 3/4 to 1 inch.
						2) There is a change in level, located at the entrance, measuring 3/4 to 1 inch.
					Entrances (Other than Locked)	The designated accessible entrance for polling: 1) The entrance has a 1 1/8 inch threshold. 2) There is no 5 foot level landing on the exterior of the entrance door. The slope of the landing measures 17.1%.
					Exterior Accessible Route	At the time of the survey (10:40am) the path of travel to the polling location had deep areas of wet, matted leaves.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
						NOTE: During the re-survey, Boston suggested putting a designated accessible on-street parking space near the driveway to the school.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Saint Ann's School @ 237 Neponset Avenue	16	07 & 10	No	Sample Ballot	The sample ballot is located at a height measuring 54 inches to the bottom of the ballot.
	Dorchester Branch Library @ 690 Adams Street				Curb Cuts	The curb cut, located at Oaktent Street, on the same side of the street as the library, has a center running slope measuring 13.6%.
					On-Street Parking	There are no designated on-street accessible parking spaces provided. NOTE: At the time of the survey (10:20am) there was a sign in a cement bucket inside the school lobby. NOTE: During the re-survey, Boston suggested the on-street accessible parking space be located near the curb cut at Oaktent Street. However, the curb cut has non-compliant features.
					Ramps	The ramp: A) Does not provide handrails on both sides. B) There is only the upper handrail provided on one side. C) The handrail on the left side of the ramp does not extend the entire run.
	Thomas J. Kenny School @ 19 Oakten Avenue		09		Entrances (Other than Locked)	The designated accessible entrance for polling has a threshold measuring 3/4 to 1 inch.
					Exterior Accessible Route	1) At the time of the survey (9:50am) the path of travel to the polling location had deep areas of wet, matted leaves. 2) The path of travel, from the parking lot (teacher's?) to the designated accessible entrance is to traverse a slope of a driveway. The slope of the driveway through the gate exceeds 5%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Thomas J. Kenny School @ 19 Oakten Avenue	16	09	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot. NOTE: During the re-survey, Boston suggested creating an accessible parking spaces) near the designated accessible door. The spaces would be on the other side of the gate, in the recess area.
	Florian Hall @ 55 Hallet Street		11 & 12		Ramps	The ramp provided: a) The running slope of the ramp measures 8.8%. b) Handrails are provided only on one side of the ramp. c) The handrail provided only provides the top handrail located at a height of 32 inches. **d) There are no landings provided at the top and bottom of the ramp. **e) The handrail provided does not extend at the top and bottom of the ramp. **f) The clear space, measured between the wall and the handrail, measures between 2 ¼ - 3 inches.
					Sample Ballot	The sample ballot measures 56 inches to the bottom of the ballot.
	Holmes School @ 40 School Street	17	01		Curb Cuts	The curb cut located near the entrance to the elevator has a center running slope measuring 14.4%.
					Entrances (Other than Locked)	The accessible entrance requires the use of an elevator. When we tried to use the elevator (at 8:12am) the elevator was not working. NOTE: It was explained by the maintenance person that the elevator does not stay on when activated as a security related measure. It was not apparent if the elevator could have remained on for the entire day or if it was only on for single use.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Holmes School @ 40 School Street	17	01	No	Sample Ballot	The sample ballot was located at a height of 51 inches measured to the bottom of the ballot.
	John Marshall School @ 35 Westville Street		02		Entrances (Other than Locked)	The exterior doors entering the polling location have thresholds measuring between ¾ to 1 inch.
					Exterior Accessible Route	There are no curb cuts provided on the side of the street facing the accessible entrance.
					NOTE: During the re-survey, Boston suggested installing a curb cut and adding an accessible on-street parking space where work is being conducted on the sidewalk.	
	Lucy Stone School @ 22 Regina Road	03	On-Street Parking		There are no designated on-street accessible parking spaces provided.	
					NOTE: There is a small parking lot provided for teachers and staff without any designated accessible parking spaces.	
			Changes in Level Along Accessible Route		The path of travel to the accessible entrance has cracks in the sidewalk exceeding ½ inch.	
			Curb Cuts		The curb cut located near the accessible entrance has a center running slope measuring 11.8%.	
			Exterior Accessible Route		1) The path of travel required to access the accessible entrance is not the same for all persons entering the polling location. A person who requires accessible features is required to circle the building, which is a distance exceeding 500 feet.	
					2) The path of travel is also blocked by a thick covering of leaves.	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Lucy Stone School @ 22 Regina Road	17	03	No	Parking Spaces in Lot	The parking lot does not provide any designated accessible parking spaces. NOTE: There is on-street parking provided a little closer to the accessible entrance, but there are no designated temporary accessible parking spaces provided.
	Woodrow Wilson School @ 18 Croftland Avenue		04 & 11		Entrances (Other than Locked)	The door located at the accessible entrance does not provide the proper hardware. Currently there is a door knob provided.
					Interior Accessible Route	The accessible route to Precinct 11 is narrowed at an archway which reduces the path of travel to 34 inches.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot do not have signs at the head of the spaces.
	Codman Square Branch Library @ 690 Washington Street		05, 06 & 08		Sample Ballot	Precinct 4 has the sample ballot located at a height of 51 inches to the bottom.
					Accessible Shelf	Precinct 5 and 6 do not provided the lowered marking shelf.
					Curb Cuts	When facing the building, the curb cut located to the left of the building has a center running slope measuring 12.5%.
					Entrances (Other than Locked)	The door located at the accessible entrance does not provide the proper hardware. Currently there is a thumb latch that is required to be operated in order to open the door.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Codman Square Branch Library @ 690 Washington Street	17	05, 06 & 08	No	Sample Ballot	Precinct 6 has the sample ballot located at a height of 54 inches to the bottom.
					Entrance Locked	To enter the door one is required to knock on the door and await assistance. The door does not provide hardware on the outside of the door and cannot be accessed independently.
						NOTE: During the survey (9:53am) the polling staff explained that someone requiring access to the rear door must enter the other entrance and notify someone inside that assistance is need at the rear door.
	Berea SDA Academy @ 800 Morton Street		07 & 10		Entrances (Other than Locked)	The designated accessible entrance has a landing on the exterior of the door has a slope measuring 33.6%.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
					Sample Ballot	The sample ballots for both precincts (7 and 10) are: a) Located at the top of a flight of stairs. b) Located at a height exceeding 48 inches to the bottom.
	Codman Square Apartments @ 784 Washington Street		09		**Comments	** NOTE: It was indicated that a ramp was at this location. The slopes of the "ramp" did not exceed 5%, therefore the "ramp" is actually a walkway.
					Changes in Level Along Accessible Route	There is a change in level where the sidewalk meets the walkway that measures greater than ½ inch.
					Parking Spaces in Lot	The designated accessible parking space does not provide an access aisle.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Charles H. Taylor School @ 1060 Morton Street	17	12	No	Entrances (Other than Locked)	The entrance to the polling location: a) There is a 1 inch threshold at the door. b) The entrance door only provides 30 ½ inches clear width.
					Exterior Accessible Route	The path of travel is not similar for all persons entering the polling location. If someone walks to the location and cannot traverse stairs, one would have to enter the driveway entrance and access the polling location by traveling in front of the building. There are only stairs (3 sets) provided along the sidewalk.
					Parking Spaces in Lot	There are no accessible parking spaces provided in the parking lot.
	Lower Mills Library @ 27 Richmond Street		13 & 14		Changes in Level Along Accessible Route	There are cracks in the sidewalks creating changes in level exceeding ½ inch.
					Entrances (Other than Locked)	The entrance door has a threshold measuring between ¾ - 1 inch.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Groveland Senior Center @ 15 Dr. Mary Moore Realty Drive	18	01 & 04		Changes in Level Along Accessible Route	NOTE: There is a parking lot located across the street (where the CVS is) with one accessible parking space provided. However, there is no way to access the polling location without traversing to either end of the block. There is gravel in the path of travel to the designated accessible entrance creating changes in level measuring greater than 1/2 inch.
					Directional Signage	There are no signs indicating where the designated accessible entrance for polling is located.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Groveland Senior Center @ 15 Dr. Mary Moore Realty Drive	18	01 & 04	No	On-Street Parking	There are no designated on-street accessible parking spaces provided.
					Ramps	The running slope of the ramp measures 8.9% on the second portion, leading to the entrance.
					Directional Signage	There are no signs indicating the location of the designated accessible entrance.
	The Church of Christ @ 1505 Blue Hill Avenue		02		Entrances (Other than Locked)	There is doorknob hardware on the doors at the designated accessible entrance.
					Exterior Accessible Route	The path of travel on the inside of the polling location is reduced to less than 36 inches in some locations.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
					Sample Ballot	The sample ballot is not located at a height of 48 inches above the floor.
	Mattahunt School @ 100 Hebron Street		03		Changes in Level Along Accessible Route	There is a 1-inch change in level at the designated accessible entrance.
					Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
					Entrances (Other than Locked)	The door to the designated accessible entrance for polling provides only 30 inches of clear opening.
					Interior Accessible Route	The accessible route of travel inside the polling location is reduced to less than 36 inches in some locations.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Mattahunt School @ 100 Hebron Street	18	03	No	Interior Doors	The interior door: a) The clear opening is less than 32 inches. b) The threshold measures over ½ inch.
					Parking Spaces in Lot	The parking lot has between 60-70 parking spaces provided. However, only 2 designated accessible parking spaces are provided.
					Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
	Hassan Apartments @ 705 River Street		05		Entrance Locked	The designated accessible entrance for polling is locked.
					Sample Ballot	A sample ballot was located at a height measuring greater than 48 inches above the floor to the bottom of the ballot.
					Changes in Level Along Accessible Route	The approach to the designated accessible entrance has changes in level measuring greater than ½ inch.
	James J. Chittick School @ 154 Ruskindale Road		06 & 21		Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
					Entrances (Other than Locked)	The designated accessible entrance for polling: a) The landing on the exterior of the door measures less than 60 inches. b) The entrance doors provide 28 inches of clear opening.
					Parking Spaces in Lot	The recess yard is used for parking on election day. There are no designated accessible parking spaces provided in the parking lot.
	John D. Philbrick School @ 40 Philbrick Street		07		Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	John D. Philbrick School @ 40 Philbrick Street	18	07	No	Entrances (Other than Locked)	The entrance has a threshold (on the interior) measuring greater than ½ inch.
					Exterior Accessible Route	The path of travel to the polling place are missing curb cuts.
					Lighting	The path of travel to the polling place is not reasonably lit.
					Parking Spaces in Lot	The recess area is used for parking during elections. There are no designated accessible parking spaces provided in the parking lot.
	Elihu Greenwood School @ 612 Metropolitan Avenue		08, 14 & 15		Changes in Level Along Accessible Route	The approach to the designated accessible entrance has changes in level measuring greater than ½ inch.
					Directional Signage	There are no signs indicating the location of the designated accessible entrance.
					Entrance Locked	The designated accessible entrance is locked.
						NOTE: At the time of the survey, the polling staff explained that someone who needed assistance would need to enter the main entrance and notify someone from the polling staff. However, the main entrance doors provide only 19 inches of clear opening and has a threshold greater than ½ inch.
					Parking Spaces in Lot	There is one designated accessible parking space provided in the parking lot. a) The space does not have an access aisle beside it. b) The space has a sign located at a height of 3 ½ feet to the top of the sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Elihu Greenwood School @ 612 Metropolitan Avenue	18	08, 14 & 15	No	Ramps	The ramp provided: a) The running slope of the ramp measures 14% at the bottom. b) There are no handrails provided. **c) The landing on the bottom of the ramp measures 4.2%. **d) There is no level landing provided at the top of the ramp.
					**Comments	** The ramp provided: **a) The landing at the bottom of the ramp measures 3.4%. **b) The handrails provided are not continuous. **c) The clear space, measured between the wall and the handrail, measures between 1 - 2 ¼ inches.
	George H. Conley School @ 430 Poplar Street		09 & 22		Parking Spaces in Lot	The recess lot is used for parking during elections. There are no designated accessible parking spaces provided in the parking lot.
					Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
	Phineas Bates School		10 & 11		Entrances (Other than Locked)	The door hardware for the designated accessible entrance for polling has doorknobs.
					Exterior Accessible Route	There are no curb cuts provided to enter the school grounds.
					Interior Doors	The interior doorway provides 30 inches of clear opening.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Henry Grew School @ 40 Gordon Avenue		12		Interior Accessible Route	The path of travel from the registration table to the accessible polling booth is reduced to 25 between the polling booths.
					Interior Doors	The interior door provides only 28 inches of clear opening.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Henry Grew School @ 40 Gordon Avenue	18	12	No	Ramps	The ramp provided: a) The running slope of the ramp measures 15.5%. b) The ramp does not provide any handrails.
					**Comments	**The handrails provided on the ramp: **a) The clear space, measured between the wall and the handrail, measures between 6 ½ - 6 ¾ inches. **b) The handrails are not continuous.
					Interior Doors	The interior door hardware is a thumb latch style. It requires the use of a thumb to depress then open the door.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Police Academy @ 85 Williams Avenue		16		Changes in Level Along Accessible Route	The driveway, which is used to access the sidewalk, has a 1-inch change in level.
					Entrance Locked	The designated accessible entrance for polling is locked.
					Exterior Accessible Route	The path of travel to the polling location does not provide any curb cuts to access the sidewalk.
					Parking Spaces in Lot	There is a sign indicating a designated accessible parking space is provided at the side of the building. However the space: a) There is no sign at the head of the space. b) The space does not provide an access aisle. **c) The space is not level.
	Roosevelt School @ 95 Needham Road		17		On-Street Parking	There are no designated on-street accessible parking spaces provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	William E. Channing School @ 35 Sunnyside Street	18	19	No	Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
					Interior Accessible Route	The path of travel inside the building is reduced to less than 36 inches because of furniture.
					Lighting	The route of travel to the entrance is not lit.
					Parking Spaces in Lot	The recess lot is used for parking during elections. There are no designated accessible spaces provided in the parking lot.
	Archives and Records Building @ 30 Millstone Road		20		Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
					Entrance Locked	The designated accessible entrance for polling was locked.
					Entrances (Other than Locked)	The designated accessible entrance for polling provides a doorway that only provides 27 inches of clear opening.
					On-Street Parking	There are no designated on-street parking spaces provided.
					Ramps	The ramp provided: a) The running slope of the ramp measures 9.0% at the bottom and 8.7% at the top. b) The handrails that are provided are only the upper handrails and are not round or oval. c) The width of the ramp measures 36 inches. **d) The landing at the bottom of the ramp has a slope measuring 6.6%. **e) The handrails do not extend at the bottom of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Georgetown Complex @ 221 Crown Point Drive	18	23	No	Ramps	The ramp provided: a) The running slope of the ramp measures 11.8% at the bottom, 9.0% in the middle and 9.9% at the top. b) There are no handrails provided. **c) There is no level landing provided at the top of the ramp.
					Entrances (Other than Locked)	The landing on the exterior of the entrance measures 43 inches out.
					Parking Spaces in Lot	The parking lot, that provides about 25 parking spaces, does not provide any designated accessible parking spaces.
	Mary E. Curley School (Location located at James Michael Curley School) @ 493 Center Street	19	01 & 03		Ramps	The ramp (exterior) provided at the entrance: a) The running slope measures 10.5%. b) No handrails are provided. 2) The interior ramp along the path of travel to the polling area: a) There is only the upper handrails provided on each side of the ramp. b) The left handrail does not run the entire length of the ramp.
					Directional Signage	There was one sign posted directing people to an accessible entrance. However, it did not direct people to the doors someone would need to access.
						NOTE: The sign indicated the main entrance was the accessible entrance. When we surveyed the facility we enter the main entrance which leads you to a set of stairs accessing the polling location.
	Joseph P. Manning School @ 130 Louders Lane		02			

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Joseph P. Manning School @ 130 Louders Lane	19	02	No	Entrance Locked	The designated accessible entrance requires someone knock to get assistance. NOTE: During the survey (11:40am) the polling staff explained that someone requiring access to the rear door must enter the other entrance and notify someone inside that assistance is need at the rear door.
					Entrances (Other than Locked)	The designated accessible entrance: a) The door at the accessible entrance provides 26 inches of clear opening. b) There is no hardware on the exterior of the door
					Exterior Accessible Route	The path of travel to the designated accessible entrance is not similar for all persons entering the polling area. To access the accessible entrance, one must circle the building. The distance exceeds 500 feet.
					Lighting	The path of travel to the designated accessible entrance does not provide any lighting to that area of the school.
	Nate Smith Elderly Housing @ 155 Lamartine Street		04		On-Street Parking	There are no designated on-street accessible parking spaces provided. NOTE: There is a parking lot provided for residents only, as explained by the Management of the Building (12:00pm). There was one accessible space located in that lot, however there is no access aisle provided for the space.
					Sample Ballot	The sample ballot was located at a height of 51 inches measured to the bottom of the ballot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Jamaica Plain Development, Community Building @ 29 Pond Street	19	05	No	Changes in Level Along Accessible Route	The ramp on the furthest side as you enter from the street has a change in level at the bottom of the ramp measuring $\frac{3}{4}$ of an inch.
					Ramps	There are two ramps provided at this location. The ramp on the closest side as you enter from the street is missing handrails on the left side (when facing the ramp).
					Sample Ballot	The sample ballot that was posted was at a height measuring 53 inches to the bottom.
	Bodwitch School Building @ 82 Green Street		06		Curb Cuts	The curb cut located near the accessible entrance has a center running slope measuring 10.2%.
					On-Street Parking	There is no on-street designated accessible parking space provided.
					Curb Cuts	The curb cut located near the entrance to the polling location has a center running slope measuring 9.4%.
	Woodbourne Apartments @ 6 Southbourne Road		07 & 12		Entrances (Other than Locked)	The landing on the exterior of the entrance door to the polling location has a slope measuring 5.5%.
					Parking Spaces in Lot	The designated accessible parking space provided in the parking lot provides a sign located at a height of 2 feet 2 inches to the bottom of the sign and 3 feet 8 inches to the top of the sign.
					**Comments	**The ramp provided: **b) The handrails provided are not continuous. **c) The landing at the top of the ramp has a slope measuring 4.4%.
	Curtis Hall @ 20 Spring Street		08 & 09			

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Curtis Hall @ 20 Spring Street	19	08 & 09	No	Changes in Level Along Accessible Route	There are changes in level on the 1st and 2nd portion of the ramp that are greater than ½ inch.
					Parking Spaces in Lot	The 2 designated accessible parking spaces provided have one sign identifying both spaces with the sign located at a height of 1 foot 7 inches to the bottom and 3 feet 1 inch to the top.
	Washington Irving School @ 114 Cummings Highway		10		**Comments	** There was no directional signage indicating where the polling location was once inside the building.
					Curb Cuts	The curb cut located closest to the accessible entrance has a center running slope measuring 11.0%.
					Entrance Locked	The designated accessible entrance was locked. Someone needing to access that entrance is required to knock for assistance.
					Entrances (Other than Locked)	There is no hardware provided on the exterior of the door.
					Interior Doors	Doors required to be used to access the polling area: a) The hardware on the doors were door knobs. b) The doors labeled "Girls Lunch Room Doors", are double doors and one remained open (2:10pm). The clear width through the open door measures 29 inches.
					Lighting	The accessible entrance does not have any lights in its vicinity.
					Parking Spaces in Lot	There are no accessible parking spaces provided in the parking lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Washington Irving School @ 114 Cummings Highway	19	10	No	Ramps	The ramp provided: a) The running slope of the ramp measures 9.4% at the bottom. **b) There is no level landing provided at the top of the ramp. The landing measures 3 feet and has a slope measuring 8.3%. **c) The handrails do not extend at the bottom of the ramp. **d) The handrails provided are not continuous.
					Sample Ballot	The sample ballot was located at a height of 51 inches to the bottom.
	Joseph Calci Training Center @ 25 Colgate Road		11		Entrances (Other than Locked)	The entrance to the polling location is a set of double doors. The clear opening measured between the door that could be opened measures 29 inches. NOTE: This door was not staffed. (2:25pm)
					Parking Spaces in Lot	The accessible parking spaces provided in the parking lot do not provide any signs at the head of the spaces.
	Roslindale Branch Library @ 4238 Washington Street		13		**Comments	** There needs to be better signage once one has entered the library at the accessible entrance to the voting area entrance. One entrance is accessible but another is blocked by the voting equipment.
					On-Street Parking	There is no on-street designated accessible parking space provided.
	Saint Nectarios Greek Church	20	01, 02 & 04		Ramps	The ramp provided: a) The running slope of the ramp measures 10.0% at the bottom and 9.6% at the top. **b) The cross slope of the ramp measures 3.1% at the top. **c) The handrails are not continuous.
					On-Street Parking	There is no designated on-street accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Saint Nectarios Greek Church	20	01, 02 & 04	No	Sample Ballot	The sample ballot was located at a height of 58 inches measured to the bottom of the ballot.
	Beethoven School @ 5125 Washington Street		03 & 15		Entrances (Other than Locked)	The doors at the designated accessible entrance for polling are double doors. Each door only provides a clear opening measuring 30 inches.
					Ramps	The running slope of the ramp measures 9.6% at the top.
	Elderly Housing Recreation Room @ 23 Spring Street		05		Parking Spaces in Lot	There is no curb cut provided at the head of the access aisle for the designated accessible parking space in the parking lot.
	Holy Name Church Hall @ 535 West Roxbury Parkway		06, 07, 19 & 20		**Comments	** NOTE: The ramp has not been measured for slope.
					Entrances (Other than Locked)	The designated accessible entrance: a) There is a 1-inch threshold at the entrance. b) The entrance is a set of double doors. The clear width measures 27 inches for both doors individually. NOTE: At the time of the survey this entrance was not staffed.
					Parking Spaces in Lot	The parking lot provides 3 designated accessible parking spaces. However, the spaces do not have any access aisles.
					Ramps	The ramp does not provide the proper handrail configuration.
	Area E Police Station @ 1708 Centre Street		08		Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Area E Police Station @ 1708 Centre Street	20	08	No	Sample Ballot	The sample ballots are located at a height of 52 inches measured to the bottom of the ballot. NOTE: By the time the survey was completed, the officials had lowered one of the ballots.
	Mozart School @ 236 Beech Street		09		**Comments	The ramp at this location has not been measured for slope.
					Entrances (Other than Locked)	The door that is designated the accessible entrance for polling does not provide any exterior door hardware.
	Saint George Orthodox Church @ 55 Emmonsdale Road		10 & 14	Yes	None	
	Roche Community Room @ 1716 Centre Street		11	No	Entrances (Other than Locked)	The landing provided on the exterior of the entrance used for polling is not level. The slope measures 8.0%.
	Robert G. Shaw School @ 20 Mount Vernon		12 & 13		Directional Signage	There are no signs indicating where the accessible entrance for polling is.
					Entrance Locked	The designated accessible entrance door was locked.
					Entrances (Other than Locked)	The designated accessible entrance provides door hardware that are doorknobs.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
					Sample Ballot	The sample ballot is located at a height of 53 ¼ inches measured to the bottom of the ballot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Joyce Kilmer School @ 35 Baker Street	20	16	No	Entrances (Other than Locked)	The door to the designated accessible entrance used for polling does not have accessible hardware.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
	West Roxbury Branch Library @ 1961 Centre Street		17 & 18	Yes	None	
	Boston Arts Academy @ 174 Ipswich Street	21	01	No	On-Street Parking	There are no designated on-street accessible parking spaces provided.
	Boston University, Room 144 @ 111 Cummington Street		02	Yes	None	
	Jackson Mann School @ 500 Cambridge Street		03, 04, 05, 06 & 07	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the 1st run up of the ramp, measuring 3/4 of an inch.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
						NOTE: During the re-survey, Boston suggested having a designated space provided near the ramp, near the bus area. However, there is a change in level along the bricks near the proposed area for the parking.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Jackson Mann School @ 500 Cambridge Street	21	03, 04, 05, 06 & 07	No	Ramps	<p>1) The ramp located on the bottom portion:</p> <p>a) The running slope of the ramp measures: 2nd panel up: 9.0%; 5th panel up: 9.1%; 6th panel up: 9.1%.</p> <p>**b) The clear space, measured between the wall and the handrail, measures 2 inches.</p> <p>2) The ramp located on the upper portion:</p> <p>a) The running slope of the ramp measures: 2nd panel up: 10.2%; 3rd panel up: 9.8%; 4th panel up: 9.3%; 6th panel up: 8.9%.</p> <p>**b) The landing at the top has a slope measuring 4.2%.</p> <p>**c) The landing at the bottom has a slope measuring 4.3%.</p> <p>**d) The clear space, measured between the wall and the handrail, measures between 1 ¾ - 2 inches.</p> <p>**e) The handrails do not extend at the bottom of this ramp.</p>
	William Howard Taft School @ 20 Warren Street		08 & 09		Entrance Locked	The designated accessible entrance door was locked.
					Exterior Accessible Route	The path of travel to the polling place is longer to the designated accessible entrance than it is to the main entrance.
					Parking Spaces in Lot	<p>There are no designated accessible parking spaces provided in the parking lot.</p> <p>NOTE: During the re-survey, Boston suggested creating a van accessible parking space near the designated accessible entrance door.</p>
	Washington Street Elderly Development @ 91-95 Washington Street		10 & 11	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Patricia White Apartments @ 20 Washington Street	21	12	No	Curb Cuts	The curb cut, provided at the designated accessible on-street parking space, has a center running slope measuring 12.5%.
					Ramps	<p>The ramp provided:</p> <p>a) The running slope of the ramp measures 10.8% at the 2nd panel from the top.</p> <p>**b) The cross slope of the ramp measures 4.2% at the top.</p> <p>**c) The landing at the top of the ramp has a slope measuring 6.3%.</p> <p>**d) The landing in the middle of the ramp has a slope measuring 2.6% and 2.5%.</p> <p>**e) The landing at the bottom of the ramp has slopes measuring 5.5%.</p> <p>**f) The first portion of the ramp, heading towards the entrance, measures longer than 30 feet before the landing.</p> <p>**g) The handrails that are wall hung have a clear space, measured between the wall and the handrail, measuring 2 ½ inches.</p> <p>**h) The handrails are not continuous.</p>
	Jewish Community Housing for the Elderly @ 30 Wallingford Road		13	Yes	None	
	Alexander Hamilton School @ 198 Strathmore Road and Chestnut Hill Avenue		14, 15 & 16	No	Accessible Shelf	Precinct 14 does not have a lowered marking shelf.
					Entrance Locked	At the time of the survey the doors were locked and could not be opened.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Alexander Hamilton School @ 198 Strathmore Road and Chestnut Hill Avenue	21	14, 15 & 16	No	Entrances (Other than Locked)	<p>The designated accessible entrance for polling:</p> <p>a) The threshold at the entrance measures greater than ½ inch.</p> <p>b) The entrance doors are double doors. Each door provides only 28 inches of clear opening.</p> <p>c) The entrance does not have hardware on the exterior of the door.</p> <p>NOTE: At the time of the survey, the doors were not staffed.</p>
					Parking Spaces in Lot	<p>The designated accessible parking space provided in the parking lot:</p> <p>a) There is no sign at the head of the space.</p> <p>B) The space does not provided an access aisle.</p> <p>NOTE: During the re-survey, Boston suggested moving the accessible parking space to the "reserved" spaces near the beginning of the driveway. The spaces are an on-street style.</p>
					Ramps	<p>The ramp provided:</p> <p>a) The running slope of the ramp measures 10.1% at the top, 9.9% in the middle, and 11.7 at the bottom.</p> <p>b) There are no handrails provided.</p>
					Sample Ballot	<p>The sample ballot is located at a height measuring 57 inches to the bottom of the ballot.</p>
	Allston Branch Library @ 300 North Harvard Street	22	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	Thomas Gardner School @ 30 Athol Street	22	02 & 05	No	Entrance Locked	The designated accessible entrance for polling was locked. NOTE: During the re-survey, MOD noted that there is a buzzer system to enter the building. This entrance can not be independently operated during polling.
					Parking Spaces in Lot	The designated accessible parking space provided is designated as a "van-accessible" space. However, the access aisle adjacent to the space measures 4 1/2 feet wide.
					Ramps	There are 2 interior ramps to get to the polling locations: a) The bottom portion of the 1st ramp, where the cement meets the wood, has a running slope measuring 10.2%. b) The bottom portion of the 2nd ramp, where the cement meets the wood, has a running slope measuring 13.5%. **c) The clear space, measured between the wall and the handrail, provided on the 1st portion of the ramp measures 1 3/4 inches.
	Academy Hill Library @ 40 Academy Hill Road		03		Ramps	The ramp has a running slope measuring 10.1% measured after the middle landing.
	Brighton Branch YMCA @ 615 Washington Street		04, 07 & 13	Yes	None	
	William Howard Taft School @ 20 Warren Street		06	No	Entrance Locked	The designated accessible entrance door was locked.
					Exterior Accessible Route	The path of travel to the polling place is longer to the designated accessible entrance than it is to the main entrance.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BOSTON	William Howard Taft School @ 20 Warren Street	22	06	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot. NOTE: During the re-survey, Boston suggested creating a van accessible parking space near the designated accessible entrance door.
	Thomas A. Edison School @ 60 Glenmont Road		08 & 09		Parking Spaces in Lot	There are no designated accessible parking space provided in the parking lot. NOTE: During the re-survey, Boston suggested placing a van-accessible parking space near the ramp leading to the entrance.
	James A. Garfield School @ 95 Beechcroft Street		10 & 11		Interior Doors	There are 2 sets of double doors that need to be used to enter the polling locations. For each set of doors, when one door is opened individually, the clear width measures 28 inches. NOTE: During the re-survey, Boston explained that both sets of doors will remain open during the hours of polling.
					On-Street Parking	There are no designated on-street accessible parking spaces provided. NOTE: During the re-survey, Boston suggested placing an accessible parking space for voting in the driveway to the right of the entrance, however the driveway has changes in level along the accessible route to the entrance. Another suggestion was to place on-street parking near the entrance, however there is no curb cut provided near that location.
	Vocational Adjustment Center @ 221 North Beacon Street		12	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Bourne	Community Center @ 239 Main Street (Formerly @ Town Hall)	00	01	No	Curb Cuts	1) The curb cut, located to the left of the accessible parking spaces, has a center running slope measuring 9.1%.
						2) The curb cut, located to the right of the accessible parking spaces, has a center running slope measuring 10.4%.
	Hoxie Elementary School @ 30 Williston Road		02		Ramps	The handrails, provided on the ramp, are not round or oval. They are a 2x4 configuration.
	Middle School @ 77 Waterhouse Road		03 & 04		Curb Cuts	The curb cut, located near the entrance, has a center running slope measuring 11.3%.
	Saint John's Parish Center @ 841 Shore Road		05 & 06		Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope measures 5.5%.
					Parking Spaces in Lot	There is no van accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Boxborough	Town Hall @ 29 Middle Road	00	01	No	Changes in Level Along Accessible Route	There is a change in level measuring 3/4 to 1 inch along the walkway.
					Entrances (Other than Locked)	The landing on the exterior of the door at the designated accessible entrance: A) The landing measures only 4 feet out from the door. B) The landing, from 4 feet to 5 feet from the door, measures 4.4%.
					Exterior Accessible Route	The walkway, in front of the designated accessible parking, has a running slope measuring 7.6%. This slope is considered to be a slope of a ramp.
					Parking Spaces in Lot	There is no van-accessible parking space provided in the parking lot. Currently there are 2 spaces sharing 1 5-foot access aisle.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Boxford	Spofford School @ 31 Spofford Road	00	01, 02 & 03	No	Changes in Level Along Accessible Route	There is a change in level at the curb cut that is in the path of travel to the designated accessible entrance that measures more than 1/2 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Boylston	Municipal Office Building @ 221 Main Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Braintree	John Hancock @ Pond Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the top of the curb cut leading to the entrance, measuring 1 to 2 inches.
	Town Hall @ 1 JFK Memorial Drive		02		Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 1 to 1 1/2 inches.
					Ramps	The ramp provided: A) The running slope, of the 1st run up, measures 9.0% at the top and 9.2% at the bottom. B) The running slope, of the 2nd run up, measures 10.2% at the bottom and 8.9% at the very bottom.
	Hollis School @ 482 Washington Street		03		Parking Spaces in Lot	The designated accessible parking spaces provided: A) There is one designated accessible parking space that does not provide an access aisle adjacent to it. B) The signs provided, are located at a height measuring 3 feet to the top of the sign. C) There is no van accessible parking space provided.
	Mary Flaherty School @ Lakeside Drive		04		Exterior Accessible Route	The running slope to access the sidewalk, located beside the parking, has a running slope measuring 10.9% to 11.2%.
	Saint Thomas More Church @ Elm Street		05		Parking Spaces in Lot	There is no van accessible parking space provided in the parking lot.
					Ramps	There are 2 ramps provided: A) The ramp near the designated accessible entrance used for polling does not provide handrails that are round or oval. The handrails provided are a 2x4 configuration. B) The ramp provided near the main entrance: I) The ramp is not 48 inches wide, measured between the handrails. II) The running slope of the ramp exceeds 1:12 (8.33%).

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Braintree	Ross School @ 20 Hayward Street	00	06	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
					Ramps	The ramp provided: A) The running slope of the ramp measures 10.5%. B) There are no handrails provided on either side of the ramp.
	Thayer Public Library @ Quincy Avenue		07		Ramps	The built up ramp, to access the sidewalk near the main entrance: A) The running slope measures 11.2%. B) There are no handrails provided on either side.
	East Jr. High School @ 305 River Street		08		Ramps	The handrails, provided on the right side of the ramp, do not extend the entire run of the ramp. The handrails stop about 1/2 way down.
	Morrison School @ 15 Mayflower Road		09		Curb Cuts	The curb cut, located near the entrance, has a center running slope measuring 13.0%.
					Parking Spaces in Lot	The designated accessible parking space provided: A) There is no van accessible space provided. B) There is no sign at the head of the space.
					Ramps	The ramp has a running slope measuring 9.4% at the bottom.
	Liberty School @ 49 Proctor Road		10		Curb Cuts	The curb cut, located where the temporary on-street accessible parking spaces are provided, has a center running slope measuring 18.0%.
	South Jr. High School @ 232 Peach Street		11		Curb Cuts	The curb cut, located where the on-street accessible parking spaces are provided, has a center running slope measuring 10.5%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Braintree	South Jr. High School @ 232 Peach Street	00	11	No	Ramps	The ramp provided: A) The running slope of the ramp measures 11.2%. B) The ramp measures 46 inches wide, measured between the handrails.
	Highlands School @ 144 Wildwood Avenue		12		Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 4 1/2 feet.
					Exterior Accessible Route	The path of travel, from the 2 designated accessible parking spaces provided, requires the use of curb cuts with steep center running slopes and narrow sidewalks. NOTE: During the survey, it was discussed that temporary parking spaces be provided near the front entrance.
					Ramps	The running slope of the ramp measures 9.0% at the top and the bottom.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Brewster	Town Offices @ 2198 Main Street	00	01, 02 & 03	No	Parking Spaces in Lot	There is no van accessible parking space provided near the entrance used for polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Bridgewater	Bridgewater- Raynham High School @ 166 Mount Prospect Street	00	01, 02, 03, 04, 05, 06 & 07	No	Changes in Level Along Accessible Route	There are changes in level, along the accessible route from the parking to the entrance, measuring 3/4 to 1 1/2 inches.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not provide a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Brimfield	Town Hall @ 21 Main Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level, along the sidewalk leading to the entrance, measuring 3/4 to 1 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BROCKTON	Housing Authority @ Hawley Street	01	A	No	Changes in Level Along Accessible Route	There is a change in level, at the bottom of the ramp, measuring more than 1/2 inch.
	West Junior High School @ 271 West Street		B	Yes	None	
	Hancock School @ 125 Pearl Street		C & D	No	Parking Spaces in Lot	There is no van accessible parking space provided.
	Senior Center @ 10 Father Kenney Way	02	A	Yes	None	
	Manning Towers @ 45 Goddard Road		B		None	
	School Department @ Maple Avenue		C		None	
	War Memorial Building @ 156 West Elm Street		D	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5 foot level landing on the exterior of the door. Currently, only 46 inches is provided.
					Ramps	The ramp provided: A) The ramp measures 33 1/2 inches wide, measured between the handrails. B) There is no upper handrail provided on the left side of the ramp.
	South Junior High School @ 105 Keith Avenue Extension	03	A	Yes	None	
	Huntington School @ 1121 Warren Avenue		B		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BROCKTON	John F. Kennedy School @ 900 Ash Street	03	C	Yes	None	
	West Side Library @ 540 Forest Avenue		D	No	Ramps	The ramp provides handrails on both sides of the ramp. However, the right side handrails do not extend the entire run of the ramp. The handrails end 10 inches before the top of the ramp.
	Goddard School @ 20 Union Street	04	A	Yes	None	
	Gilmore School @ 150 Clinton Street		B	No	Ramps	The ramp provided: A) The running slope at the bottom of the ramp measures 9.3%. B) The ramp does not provide any handrails.
	Davis School @ 380 Plain Street		C	Yes	None	
	Campello High Rise Apartments @ 1380 Main Street		D		None	
	East Side Library @ 54 Kingman Street	05	A		None	
	East Junior High School @ Centre Street		B		None	
	Downey School @ 55 Electric Avenue		C		None	
	Caffrey Towers @ 755 Crescent Street		D		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
BROCKTON	Brookfield School @ 135 Jon Drive	06	A, C & D	Yes	None	
	Ashfield School @ 225 Coe Road		B		None	
	North Junior High School @ Oak Street	07	A	No	Changes in Level Along Accessible Route	There is a change in level, located at the base of the curb cut near the main entrance, measuring 1 inch.
	Belair Street High Rise @ 105 Belair Street		B	Yes	None	
	Sullivan Towers @ 140 Colonel Bell Drive		C	No	Parking Spaces in Lot	The designated accessible parking spaces do not have access aisles adjacent to the spaces.
	Raymond School @ 125 Oak Street		D	Yes	Ramps	The ramp does not provide lower handrails on either side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Brookfield	Town Hall @ 6 Central Street	00	01	No	Parking Spaces in Lot	The designated accessible parking spaces provided: A) The spaces do not provide any access aisles adjacent to them. B) The spaces do not have signs at the head of them.
					Ramps	The ramp is 46 inches wide, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Brookline	Wheelock College	00	01	Yes	None	
	Coolidge Corner Library		02	No	**Comments	** The path of travel from the sidewalk to the ramp has cross slopes measuring between 2.6% to 2.8%.
					Changes in Level Along Accessible Route	There are changes in level along the ramp that exceed ½ inch.
					Curb Cuts	1) The curb cut near the main entrance: a) Has a 10.2% center running slope. **b) The landing at the top of the curb cut has a slope measuring 4.2%.
						2) The curb cut provided at the entrance to the polling location: a) Has a running slope measuring 14.6%. **b) The left flare has a running slope measuring 9.2%.
					Entrances (Other than Locked)	The landing in front of the polling entrance door has a slope measuring 4.4%.
	Theresa Morse Apartments		03	Yes	None	
	Lynch Recreation Center		04	No	Changes in Level Along Accessible Route	1) There is a manhole cover in the path of travel to the polling place. The cover has openings that measure 1 ½ inches and creates a change in level measuring 1 inch. 2) There is a 2-inch change in level at the entrance.
					Parking Spaces in Lot	There are no access aisles provided for the designated accessible parking spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Brookline	19 Kennard Road	00	05	No	Curb Cuts	The curb cut located near the designated on-street accessible parking spaces has a center running slope measuring 8.9%.
	115 Greenough Street		06	Yes	None	
	61 Park Street		07	No	Curb Cuts	The curb cut located near the designated on-street accessible parking spaces has a center running slope measuring 13.4%.
	Devotion School		08	Yes	None	
	Senior Center		09		None	
	Fire Station on Washington Street		10		None	
	Driscoll School		11		None	
	Runkle School		12 & 13	No	Entrances (Other than Locked)	The landing provided at the entrance has a slope measuring 3.9%.
	Heath School		14	Yes	None	
	Fire Station on Hammond Street		15		None	
	Putterham Library		16		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Buckland	Town Hall @ 1 William Street	00	01	No	Parking Spaces in Lot	The designated accessible parking space provided in the lot does not provide a painted striped access aisle adjacent to the space.
					Ramps	NOTE: None of the parking spaces are striped. The ramp leading to the designated accessible entrance has running slopes measuring 10.0% at the very bottom of the 1st run up, 9.0 in the middle of the 1st run up, and 9.5% at the very top of the first run up.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Burlington	Burlington High School @ 123 Cambridge Street	00	01, 02, 03, 04, 05 & 06	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
CAMBRIDGE	East End House @ 105 Spring Street	01	01	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5 foot level landing on the exterior of the door. Currently it measures 4 feet 5 inches by 5 feet 2 inches.
	Truman Apartments @ 25 Eighth Street		02	Yes	None	
	Miller River Apartments @ 15 Lambert Street		03	No	Exterior Accessible Route	The accessible route from the designated accessible on-street parking spaces to the designated accessible entrance is not the "same or similar for all persons entering the polling location. It requires someone to travel 250 feet in either direction to get to a curb cut to access the sidewalk, then traverse 250 feet to get to the entrance.
	Pisani Center @ 131 @ 131 Washington Street	02	01		**Comments	There is a grate, located near the designated accessible parking spaces that has an openings measuring 2 inches by 2 inches.
					Changes in Level Along Accessible Route	There is a change in level measuring 2 inches in the sidewalk leading from the designated accessible parking to the designated accessible entrance.
					Parking Spaces in Lot	The sign for the designated accessible parking space is located about 20 feet away from the space.
	MIT; Kresge Auditorium @ 70 Massachusetts Avenue		02 & 03	Yes	None	
	King Open School @ 850 Cambridge Street	03	01		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
CAMBRIDGE	DPW Headquarters @ 147 Hampshire Street	03	02	Yes	None	
	Salvation Army Headquarters @ 402 Massachusetts Avenue		03	No	Exterior Accessible Route	There are no curb cuts provided near the designated accessible on-street parking. A driveway, with a running slope measuring between 9 - 10%, is the means of access to the designated accessible entrance.
					Interior Doors	There is a set of double doors located along the accessible route to the polling location. The clear opening of a single door measures 27 inches.
						NOTE: During the survey, Joseph explained that the double doors were left open during times of polling.
	Putnam Gardens Community Room	04	01		Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) No van accessible space is provided. B) No signs are provided at the head of the spaces. C) The access aisle abuts a sidewalk and does not provide a curb cut.
	City Hall Basement @ 795 Massachusetts Avenue		02	Yes	None	
	2 Mount Auburn Street @ Putnam Gardens Lobby		03	No	Entrances (Other than Locked)	There is a 1 inch threshold at the designated accessible entrance used for polling.
	LBJ Apartments @ 150 Erie Street	05	01		Exterior Accessible Route	There are no curb cuts provided near the designated accessible on-street parking. A driveway, with a running slope measuring between 9 - 10%, is the means of access to the designated accessible entrance.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
CAMBRIDGE	River Street Fire House @ 176 River Street	05	02	No	Changes in Level Along Accessible Route	There is a change in level measuring 2 inches along the accessible route to the designated accessible entrance.
					Entrance Locked	Someone using the designated accessible entrance for polling is required to "bang" in the door to alert someone to assist.
					Entrances (Other than Locked)	The designated accessible entrance used for polling: A) There is a threshold measuring 1 inch. B) The hardware on the door is a door knob. C) The clear opening measures 30 inches.
	Morse School @ 40 Granite Street		03	Yes	None	
	Conference Room @ 51 Inman Street	06	01		None	
	Vernon Hall Nursing Home @ 8 Dana Street		02		None	
	Youville Hospital @ 1575 Cambridge Street		03	No	Parking Spaces in Lot	There is no van accessible parking space provided.
	Baldwin School @ 28 Sacramento Street	07	01 & 02	Yes	None	
	Gund HL, Harv Design School @ 48 Quincy Street		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
CAMBRIDGE	Graham & Parks School @ 44 Linnaean Street	08	01	No	Interior Doors	There is a set of double doors along the accessible route to the polling location. The clear opening of one of these doors measures 28 inches. NOTE: During the survey, Joseph explained that both doors are left open during polling.
			02	Yes	None	
	Quincy House, Harvard University @ 58 Plympton Street		03	No	Entrances (Other than Locked)	The designated accessible entrance used for polling does not provide proper door hardware.
	Lexington Avenue Fire House @ 167 Lexington Avenue	09	01		Entrances (Other than Locked)	The door hardware on the designated accessible entrance is a door knob.
					Exterior Accessible Route	The path of travel to the designated accessible entrance has changes in level measuring from 1 inch to 3 inches.
	Tobin School @ 197 Vassal Avenue		02		Curb Cuts	The curb cut, located near the designated accessible entrance, has a center running slope measuring 14.2%.
					Entrances (Other than Locked)	The designated accessible entrance used for polling: A) There is a 1 1/2 inch threshold at the door. B) There is no level area provided on the exterior of the door. The slope measures 6.2%.
					Ramps	The ramp provided: A) The running slope measures 10.6%. B) There are handrails provided on 1 side of the ramp, however these handrails are a 2X5 configuration.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
CAMBRIDGE	Haggerty School @ 110 Cushing Street	09	03	No	Exterior Accessible Route	The accessible route from the designated accessible on-street parking spaces to the designated accessible entrance is not the "same or similar for all persons entering the polling location. It requires someone to travel 300 feet in either direction to get to a curb cut to access the sidewalk, then traverse 300 feet to get to the entrance.
	Russell Apartments @ 2050 Massachusetts Avenue	10	01	Yes	None	
	Graham & Parks School @ 44 Linnaean Street		02	No	Interior Doors	There is a set of double doors along the accessible route to the polling location. The clear opening of one of these doors measures 28 inches. NOTE: During the survey, Joseph explained that both doors are left open during polling.
	Cadbury Commons @ 66 Sherman Street		03	Yes	None	
	Jefferson Park Community @ 1 Jackson Place	11	01		None	
	Gately Shelter @ Haskell Street		02	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) There are no access aisles provided for the spaces. B) No van accessible spaces are provided.
	Burns Apartments @ 50 Churchill Avenue		03	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Canton	Public Library @ 796 Washington Street	00	01 & 06	Yes	None	
	Dean S. Luce Elementary School @ 45 Independence Street		02		None	
	Blue Hills Regional School @ 800 Randolph Street		03	No	Parking Spaces in Lot	There are about 100 parking spaces in the parking lot. Currently, there are no HP spaces provided.
	John F. Kennedy Elementary School @ 100 Dedham Street		04 & 05		Parking Spaces in Lot	NOTE: There are 2 HP spaces located in the driveway as "on-street" style parking, but do not provide any signs. The recess area is used during elections as a parking area. During polling there are no designated accessible parking spaces provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
--------------	------------------	------	-------------	----------------------	--------------------	-----------------

Carlisle	Town Hall @ 66 Westford Street	00	01	No	Parking Spaces in Lot	The designated accessible parking space configured as a van accessible space is missing the "van-accessible" sign.
----------	-----------------------------------	----	----	----	-----------------------	---

NOTE: During the survey, Charlene explained that the sign
would be ordered and installed prior to the next election.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Carver	Carver High School @ 60 South Meadow Road	00	01, 02 & 03	No	Changes in Level Along Accessible Route	There are changes in level, along the sidewalk leading to the entrance, measuring 3/4 to 1 inch.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 3.7%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Charlemont	Hawlemont Regional School @ 10 School Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut at the rear entrance, measuring 3/4 to 1 inch.
					Curb Cuts	<p>1) The curb cut, provided at the rear entrance, has running slopes measuring 13.4% and 15.5% (to the left of the ballard), and 13.2% (to the right of the ballard).</p> <p>2) The curb cut, provided at the main entrance, near the "on-street" style accessible spaces, has a center running slope measuring 10.0%.</p>
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot provided at the rear entrance. However, there are 2 designated "on-street" style accessible spaces provided near the front entrance.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Charlton	Elementary School @ 9 Burlingame Road	00	01, 02 & 03	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Chatham	Depot Road School @ 147 Depot Road	00	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Chelmsford	Town Office Building Gymnasium @ 50 Billerica Road	00	01 & 09	Yes	None	
	Harrington School @ 120 Richardson Road		02 & 03		None	
	Westlands School @ 170 Dalton Road		04 & 06		None	
	Byam School @ 25 Maple Road		05		None	
	McCarthy Middle School @ 250 North Road		07 & 08		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
CHELSEA	Early Learning Center	01	01 & 02	Yes	None	
	St. Rose Elementary		03 & 04		None	
	Knights of Columbus	02	01 & 03		None	
	Williams School		02 & 04		None	
	Irish Club	03	01 & 02		None	
	St. Luke's Church		03 & 04	No	Entrances (Other than Locked)	Doorknobs are on all of the doors to enter the polling area. NOTE: During the survey it was explained that the doors remain open, and a police officer is present during polling.
	Clark School	04	01 & 04	Yes	None	
	Public Safety Building		02 & 03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Cheshire	Community/Senior Center @ 119 School Street	00	01	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) There are no access aisles provided adjacent to the spaces. B) There is no van accessible space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Chester	Town Hall @ 15 Middlefield Road	00	01	No	Ramps	The ramp, at the designated accessible entrance used for polling, narrows to only providing 45 inches of space measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Chesterfield	Davenport Office Building @ 422 Main Road	00	01	No	Parking Spaces in Lot	The designated accessible parking spaces provided do not provide painted access aisles. NOTE: At the time of the survey, the parking lot was not striped.
					Ramps	The running slope of the ramp measures 9.6% at the bottom of the 3rd run up and 9.0% at the bottom of the 2nd run up.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
CHICOPEE	Bellamy School	01	A & B	Yes	None	
	Patrick E. Bowe School	02	A, B & CS	No	Changes in Level Along Accessible Route	The curb cut along the accessible route to the polling location has a change in level measuring 1-inch.
					Curb Cuts	The curb cut located closest to the designated accessible entrance for polling has a center running slope measuring 19.7%.
	Knights of Columbus @ 460 Granby Road		CN & D	Yes	None	
		03	AE		None	
	Stefanik School		AW, B & C	No	Changes in Level Along Accessible Route	1) The sidewalk leading to the polling entrance has changes in level measuring 1 ½ inches.
						2) The curb cut located along the accessible route to the entrance to the polling location has a change in level measuring 1-inch.
					Curb Cuts	1) The curb cut located closest to the accessible entrance for polling has a center running slope measuring 28.0%.
	State Armory Building	04	A & C		Exterior Accessible Route	The path of travel is not "the same or substantially similar" for all persons entering the polling location.
	First Baptist Church @ 50 Broadway		B		Exterior Accessible Route	The path of travel is not "the same or substantially similar" for all persons entering the polling location.
		05	A		Exterior Accessible Route	The path of travel is not "the same or substantially similar" for all persons entering the polling location.
	A-Hepa Hall		B		Entrances (Other than Locked)	The designated accessible entrance for polling has doorknobs on the exterior of the doors.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
CHICOPEE	Selser Elementary School	06	AN	Yes	None	
	Sheridan Circle Community Building		AS & BW	No	Entrances (Other than Locked)	The entrance to the polling location does not provide accessible hardware on the exterior of the door.
	Litwin School		BE		Changes in Level Along Accessible Route	There is a curb cut located along the accessible route to the polling location has changes in level measuring greater than ½ inch.
					Curb Cuts	There is a curb cut located along the accessible route to the polling location has a center running slope measures 15.9%.
	Nativity Church Hall	07	A & B	Yes	None	
	Valley View	08	A		None	
	Anna Barry School		B	No	Directional Signage	There are no signs indicating the location of the accessible entrance for polling.
					Entrances (Other than Locked)	The doors for the designated accessible entrance for polling provide only 29 inches of clear opening.
	Knights of Columbus @ 1599 Memorial Drive	09	A & B	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Chilmark	Community Center @ 520 South Road	00	01	No	Entrances (Other than Locked)	The designated accessible entrance door is a set of double doors. Opened individually, each door provides 21 inches of clear opening.
					Parking Spaces in Lot	There is no access aisle provided adjacent to the designated accessible parking space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Clarksburg	Town Hall	00	01	No	Entrances (Other than Locked)	The designated accessible entrance for polling does not have a level landing on the exterior of the door.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Clinton	Town Hall @ 242 Church Street	00	01, 02, 03 & 04	No	Interior Doors	The auditorium door has a threshold measuring 1 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Cohasset	Town Hall Auditorium @ 41 Highland Avenue	00	01 & 02	No	Changes in Level Along Accessible Route	There is a change in level at the base of the ramp that measures 3/4 to 1 inch.
					Interior Doors	There is a set of double doors to access the auditorium. Each door only provides 29 inches of clear opening. NOTE: If both doors were left open during polling, the clear space would exceed 32 inches.
					Parking Spaces in Lot	There are 3 parking spaces provided. A) The right most space, when facing the building, does not provide an access aisle. B) There is no "van-accessible" parking space provided. NOTE: When the "Van-accessible" parking space is provided, there needs to be a "van-accessible" sign added.
					Ramps	The ramp provided: A) The second run up the ramp has running slopes measuring 9.0% at the top and 9.9% in the middle. B) The second run up the ramp measures 43 inches wide, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Colrain	Town Hall @ 55 Main Road	00	01	No	Changes in Level Along Accessible Route	There is a change in level, where the pavement meets the cement at the bottom of the driveway leading to the accessible entrance, measuring 3/4 of an inch along the entire lip.
					Exterior Accessible Route	<p>The path of travel from the parking to the designated accessible entrance requires someone to use a driveway to the lower area. The running slopes down the driveway measured 7.5% at the top, 8.7% in the middle, 9.2% after the stairs, and 7.4% at the bottom.</p> <p>This area was mentioned to be a ramp, however, vehicles can travel this lane to this entrance. If this was to be considered a ramp, the slope exceeds 8.33%, and there is only one handrail provided on one side, and is not continuous. (The handrail stops at the stairs the continues after the stairs.)</p>
					Interior Doors	<p>There is a set of interior double doors to access the polling location. Each door, when opened individually, provides only 28 1/2 inches of clear opening.</p> <p>NOTE: During the survey, it was stated that the doors would remain propped open during the elections.</p>
					Parking Spaces in Lot	<p>There are 2 designated accessible parking spaces provided at the upper portion of the lot:</p> <p>A) The space that is located away from the main entrance provides only a 4 foot access aisle.</p> <p>B) The space, that is configured as an "on-street" style within the lot, does not provide an access aisle adjacent to the space.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Concord	Concord Health Center @ @ Route 2	00	01	No	Curb Cuts	The curb cut, located across from the parking spaces, leading to the ramp, has a center running slope measuring 12.4%.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided near the polling entrance. NOTE: During the survey, Anita discussed that temporary spaces will be provided at the entrance.
					Ramps	1) The exterior ramp provided has handrails on both sides of the ramp. However, the right side handrails do not extend to the bottom of the ramp. 2) The interior ramp has running slope measuring 9.2% at the bottom and 10.2% in the middle.
	Harvey Wheeler Community Center @ Church Street (Formally The Willard Elementary School)		02 & 03		Exterior Accessible Route	There is a walkway located at the entrance. The running slopes measure between 7.4% to 7.8%. These slopes are ramp slopes.
	Riply School Administration Building Gymnasium @ 120 Meriam Road		04		Parking Spaces in Lot	The designated accessible parking spaces provided in the lot do not provide access aisle adjacent to the spaces.
	Hunt Gymnasium @ 90 Stow Street		05		Parking Spaces in Lot	The designated accessible parking space provided is configured as a van-accessible space. However, the space does not provide a "van-accessible" sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Conway	Town Hall @ 32 Main Street	00	01	No	Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. Opened individually, each door provides 28 inches of clear opening.
					Exterior Accessible Route	The walkway, leading to the entrance: A) The running slope measures 6.5% at the top and 5.5% in the middle. **B) There is pooling of water at the base of the walkway, covering most of the walkway.
					On-Street Parking	There is no parking lot provided for this site. There are no designated "on-street" parking spaces reserved for people with disabilities.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Cummington	Town Hall @ 33 Main Street	00	01	No	Accessible Shelf	There is no lowered marking shelf provided. NOTE: During the survey, Judy explained that a table will be used and privacy guards would be installed.
					Changes in Level Along Accessible Route	The ramp, located at the front entrance has a change in level measuring 3/4 - 1 inch at the base.
					Parking Spaces in Lot	1) The designated accessible parking spaces do not have painted access aisles beside the spaces. 2) The left most designated accessible parking space abuts a sidewalk without a curb cut. NOTE: At the time of the survey, the parking lot was not striped.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dalton	Community House @ 400 Main Street	00	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Danvers	Town Hall @ One Sylvan Street	00	01	Yes	None	
	Highlands School @ 190 Hobart Street		02		None	
	Riverside School @ 95 Liberty Street		03		None	
	Saint John's Prep Auditorium @ Summer Street		04	No	Ramps	The ramp has a running slope measuring 9.9%.
	Willis Thorpe School @ Avon Road		05	Yes	None	
	Ivan Smith School @ 15 Lobao Drive		06		None	
	Great Oak School @ 76 Pickering Street		07	No	Changes in Level Along Accessible Route	There is a change in level, along the walkway leading to the ramp, measuring 2 inches.
	Engine 2 Fire Station @ Old Maple Street		08	Yes	Curb Cuts	There is a curb cut, near the walkway that leads to the ramp, with a center running slope measuring 12.8%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dartmouth	Fire Engine House #3 @ 140 Cross Road	00	01 & 03	Yes	None	
	Smith Mills Church Hall @ 11 Anderson Way		02 & 04		None	
	Old Town Hall @ 247 Russells Mills Road		05		None	
	Town Office Building @ 400 Slocum Road		06		None	
	Senior Citizens Building @ 628 Dartmouth Street		07		None	
	Southworth Library @ 732 Dartmouth Street		08		None	
	Pananaram Engine House #1 @ 10 Bridge Street		09		None	
	Russells Mills Engine House @ 1100 Russells Mills Road		10		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dedham	Town Hall @ 26 Bryant Street	00	01	Yes	None	
	Riverdale School @ 143 Needham Street		02		None	
	Avery School @ 123 High Street		03	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) Do not provide access aisles B) Do not provide signs at the head of the spaces.
	Oakdale School @ 147 Cedar Street		04 & 06	Yes	None	
	Greenlodge School @ 191 Greenlodge Street		05 & 07		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Deerfield	Town Offices @ 8 Conway Street	00	01	No	Changes in Level Along Accessible Route	1) There is a change in level, after the first landing down the ramp, measuring 1/2 to 3/4 of an inch. 2) There is a change in level, at the base of the ramp, measuring 1 inch.
					Ramps	The ramp measures 38 1/2 inches wide at the top and 44 inches wide for the remaining, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dennis	Charlton Hall @ 1006 Old Bass River Road	00	01	No	Directional Signage	There is no signage provided to indicate the location of the designated accessible entrance used for polling.
					Parking Spaces in Lot	There are 10 parking spaces provided near the polling entrance. A) There are no access aisles provided adjacent to the designated accessible parking spaces. B) There is no van accessible parking space provided.
	Senior Center @ 1045 Route 134		02		Parking Spaces in Lot	There are 7 designated accessible parking spaces provided near the entrance used for polling. A) There are only 2 signs provided at the heads of the spaces. B) There are only 2 access aisles provided adjacent to the spaces.
	V.I.C. Hall @ 187 Depot Street		03		Changes in Level Along Accessible Route	There are changes in level, along the accessible route to the designated accessible entrance used for polling, measuring greater than 1/2 inch.
					Entrances (Other than Locked)	The designated accessible entrance used for polling does not provide hardware on the door that is operable with a closed fist.
					Exterior Accessible Route	The accessible route, from the parking to the designated accessible entrance used for polling is not paved.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot near the entrance used for polling. NOTE: The entire lot is no paved or striped.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dennis	V.I.C. Hall @ 187 Depot Street	00	03	No	Ramps	The ramp provided: A) The running slope of the ramp measures: I) The first section: 11.0% - 12.5%. II) The second section: 8.9% - 10.0%. III) The third section: 9.3% - 9.7%. B) The ramp is 45 inches wide, measured between the handrails.
	West Dennis Graded School @ 67 School Street		04		Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) The space that is configured as van accessible is missing the "van-accessible" sign. B) The signs, located at the head of the designated spaces, measure 51 inches to the top of the sign.
					Ramps	There are 2 ramps provided. One at the main entrance and one at the rear entrance. Both entrances are used during polling: 1) The ramp at the main entrance: A) There are no handrails provided on either side of the ramp. B) The running slope of the ramp measures 8.9% to 9.3%. 2) The ramp at the rear entrance does not provide handrails on both sides of the ramp.
	Nathaniel Wixon School @ 901 Route 134		05		Entrances (Other than Locked)	The designated accessible entrance, used for polling, does not provide a level area on the exterior of the door.
					Parking Spaces in Lot	There is no van accessible parking space provided near the designated accessible entrance used for polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dennis	Nathaniel Wixon School @ 901 Route 134	00	05	No	Ramps	<p>There are 2 ramps at the designated accessible entrance used for polling:</p> <p>1) The first ramp:</p> <p>A) The ramp has running slopes measuring 5.8% to 10.6%. B) There are no handrails provided on either side of the ramp.</p> <p>2) The second ramp does not provided handrails on either side.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dighton	Elementary School @ 1250 Somerset Avenue	00	01	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not have a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Douglas	Municipal Center Gym @ 29 Depot Street	00	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dover	Town House @ 5 Springdale Avenue	00	01	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dracut	Senior Center (Council on Aging)	00	01 & 06A	No	Entrances (Other than Locked)	There is not a 5-foot level landing provided at the exterior of the entrance door. Currently only 4-feet 2- inches is provided.
					Parking Spaces in Lot	The designated accessible parking spaces: a) There are no access aisles provided at these spaces. b) The tops of the signs are located at a height of 3 feet off the ground.
	Lakeview Junior High School		02, 05, 06 & 09		**Comments	Note: During the survey it was explained that temporary spaces and access aisles are provided at the time of polling. **The curb cut provided in front of the accessible parking, directly in front of the doors to the polling location: **a) Provides only a 3-foot 4-inch landing at the top of the curb cut. **b) The left flare running slope of the curb cut measures 11.0%.
					Parking Spaces in Lot	The designated accessible parking spaces does not have one designated with a sign indicating it is "van accessible".
	Christ Church United		03 & 08		Parking Spaces in Lot	Designated accessible parking: a) There are no access aisles provided for the accessible parking spaces. b) The signs for the designated accessible parking spaces do not measure between 5-8 feet to the top of the signs.
					Ramps	Note: During the survey it was explained that temporary spaces and access aisles are provided during polling. The ramp located within the church: a) The handrails are a 2X4 configuration. b) The running slope of the ramp measures 10.5% at the top and 11.5% at the bottom.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dracut	Campbell School	00	04 & 07	No	Entrances (Other than Locked)	At the entrance leading into the polling location, there is a landing provided. The sloped area leading to the landing has a running slope measuring 10.3% at the bottom and 8.0% at the top.
					Parking Spaces in Lot	<p>The designated accessible parking spaces:</p> <p>a) There are no signs provided for the accessible parking spaces.</p> <p>b) The accessible parking spaces abut a sidewalk. No curb cut is provided.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dudley	Saint Andrew Bobola Church @ 54 West Main Street	00	01, 02, 03 & 04	No	Parking Spaces in Lot	There are signs missing at the heads of the designated accessible parking spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Dunstable	Dunstable Library @ 588 Main Street	00	01	No	Parking Spaces in Lot	The designated accessible parking spaces do not provide a van accessible space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Duxbury	Middle School @ 130 Saint George Street	00	01, 02, 03, 04, 05 & 06	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope measures 15.6%.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the rear lot.
					Ramps	The interior ramp provided: A) The running slope measures 9.4% at the top and 9.0% in the middle. B) The ramp does not provide handrails on the right side of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
East Bridgewater	Middle School @ 435 Central Street	00	01, 02, 03 & 04	No	Curb Cuts	The curb cut, located to the rear of the accessible parking spaces provided for precinct 4, has a center running slope measuring 9.0%.
					Parking Spaces in Lot	<p>The designated accessible parking spaces provided for Precinct 4:</p> <p>A) There are no access aisles adjacent to the 4 accessible parking spaces provided.</p> <p>B) The parking spaces abut a sidewalk. There are no curb cuts to access the sidewalk.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
East Brookfield	Senior Center @ 110 Pleasant Street	00	01	No	Curb Cuts	The curb cut, provided to the rear of the parking, has a center running slope measuring 9.6%.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. Currently, the threshold has a metal sloped covering, extending into the level landing and the slope exceeds 2%.
					Exterior Accessible Route	The walkway leading to the ramp, has a running slope at the bottom measuring 8.6%.
					Parking Spaces in Lot	The designated accessible parking space that is configured as a van accessible space, provides a 7-foot access aisle.
					Ramps	<p>The ramp provided:</p> <p>A) The running slope at the top measures 9.0%.</p> <p>B) The ramp is 41 inches wide, measured between the handrails.</p> <p>C) The ramp provides handrails on the right side only.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
East Longmeadow	Birchland Park School @ 50 Hanward Hill	00	01	No	Parking Spaces in Lot	The designated accessible parking space that is properly configured as a van accessible space is missing the "van-accessible" sign.
	Pleasant View Building @ 328 North Main Street		02		Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) There are only 3 signs provided for the 5 accessible parking spaces. B) The parking space that is configured as van accessible is missing the "van-accessible" sign.
	High School @ 180 Maple Street		03		Parking Spaces in Lot	The 1 designated accessible parking space does not provide an access aisle adjacent to the space that would accommodate a van. Currently the space has an access aisle on either side, one measuring 2 1/2 feet and one measuring 3 feet.
	Meadowbrook School @ 607 Parker Street		04		Changes in Level Along Accessible Route	There are changes in level, along the accessible route from the service road to the sidewalk leading to the entrance, measuring 3/4 - 1-1/2 inches.
					Parking Spaces in Lot	The designated accessible parking space that is properly configured as a van accessible space is missing the "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Eastham	Town Hall @ 2500 State Highway	00	01	No	Changes in Level Along Accessible Route	There are changes in level, along the accessible route to the entrance, measuring greater than 1/2 inch. This is caused by the heaving bricks.
					Exterior Accessible Route	At the top of the ramp, where the bricks have heaved, the running slope exceeds 5%.
					Parking Spaces in Lot	There is no van accessible parking space provided. The access aisle shared for the 2 spaces measures 6 feet wide.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Easthampton	White Brook Middle School	00	01, 02 & 05	Yes	None	
	Easthampton High School		03 & 04		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Easton	Junior High School @ Columbus Avenue	00	01, 02 & 04	Yes	None	
	Knights of Columbus Hall @ 375 Foundry Street		03 & 05		None	
	Baptist Church @ 197 Bay Road		05		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Edgartown	Town Hall @ 70 Main Street	00	01	No	Parking Spaces in Lot	There is no access aisle provided adjacent to the designated accessible parking space.

NOTE: During the survey, it was discussed that a temporary access aisle be provided adjacent to the space during polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Egremont	North Egremont Fire Station @ 175 Egremont Plain Road	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Erving	Town Hall @ 12 East Main Street	00	01	No	Ramps	The ramp does not provide lower handrails on the left side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Essex	Memorial Fire Station @ 24 Martin Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
EVERETT	Armory @ 90 Chelsea Street	01	01 & 02	No	Parking Spaces in Lot	The designated accessible parking space is not striped.
	Sumner Whittier School		03	Yes	None	
	Parlin School @ 587 Broadway	02	01, 02 & 03	No	Parking Spaces in Lot	The designated accessible parking spaces: A) The space does not provide an access aisle. B) There are no signs at the head of the space. NOTE: During the survey, John Hanlon stated that during polling temporary signs and spaces are created.
	Kaverian School		1 & 3 (Moving in November)		Parking Spaces in Lot	There is no "van-accessible" sign provided at the designated accessible parking space. NOTE: The space is properly configured, it is just missing the sign.
	Whittier Drive Elderly Complex	03	01 (Currently This Building is Under Renovations, Will Be Used When Renovations Complete)	Yes	**Comments	The interior of the building could not be surveyed as it is under renovation. The exterior of the building was surveyed for compliance.
	Pope John 23rd High School @ Lafayette Street		01 (Temporary - Will be Moved to Whittier Drive Complex when Renovations are Complete)	No	Changes in Level Along Accessible Route	The side entrance walkway has changes in level measuring greater than 1/2 inch.
					Curb Cuts	The curb cut located in front of the entrance that is closest to the designated accessible parking has a center running slope measuring 11.1%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
EVERETT	Pope John 23rd High School @ Lafayette Street	03	01 (Temporary - Will be Moved to Whittier Drive Complex when Renovations are Complete)	No	Entrances (Other than Locked)	There are 2 entrances that can be used for polling: A) The entrance closest to the designated accessible parking spaces has a landing on the exterior of the door with a slope measuring 7.7%. B) The entrance on the side of the building: I) The distance to the entrance is not the "same or similar" for all persons entering the polling location. The side entrance is located down a long walkway. II) The landing on the exterior of the door has a slope measuring 6.6%.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) The designated accessible parking spaces do not provide signs at the head of each space. B) There is no curb cut provided in front of the accessible parking space.
	Recreation Center Building @ 47 Elm Street		02 & 03		Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) The parking spaces are not striped. B) There are no signs at the head of the spaces.
					Ramps	There is a walkway provided to the entrance. The running slope measures 6.0% at the bottom.
	Lafayette School @ 117 Edith Street	04	01 & 03		Parking Spaces in Lot	The designated accessible parking space that is configured as van-accessible is missing the "van-accessible" sign.
	Glendale Towers @ 381 Ferry Street		02		Changes in Level Along Accessible Route	The curb cut in front of the access aisle for the designated accessible parking space allows access to the loading dock area. To get to the main entrance there is a curbing with a change in level measuring 3 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
EVERETT	Glendale Towers @ 381 Ferry Street	04	02	No	Curb Cuts	The curb cut, located in front of the main entrance has a running slope measuring 11.6% at the bottom and 12.2% at the top.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van-accessible is missing the "van-accessible sign".
	Madeline English School @ 117 Edith Street (formally the Lewis School)	05	01		Parking Spaces in Lot	The designated accessible parking space that is configured as van-accessible does not provide the "van-accessible" sign
	City Hall		02 & 03		**Comments	There is a grate at the head of the access aisle for the designated accessible parking space that has openings measuring 2 inches by 2 inches.
					Entrances (Other than Locked)	The designated accessible entrance: A) The level landing on the exterior of the door has a slope measuring 3.1%. **B) The door is very heavy to open. The pressure of the door exceeds 12lbs.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van-accessible does not provide the "van-accessible" sign.
	Madeline English School @ 117 Edith Street (formally the Lewis School)	06	01		Parking Spaces in Lot	The designated accessible parking space that is configured as van-accessible does not provide the "van-accessible" sign
	Adams School @ 78 Tilestone Street		02 & 03		Changes in Level Along Accessible Route	There is a change in level measuring greater than 1/2 inch at the top of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
EVERETT	Adams School @ 78 Tilestone Street	06	02 & 03	No	Parking Spaces in Lot	The designated accessible parking spaces provided: A) The spaces are not striped. B) There are no signs at the head of the spaces.
					Ramps	The ramp provided has a running slope at the bottom of the first run measuring 11.2%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Fairhaven	Town Hall @ 40 Center Street	00	01	No	Ramps	The ramp, at the top of the 3rd run up, has a running slope measuring 9.4%.
					Curb Cuts	The curb cut, located near the entrance, across from the parking, has a center running slope measuring 11.7%.
					Parking Spaces in Lot	There is no van accessible parking space provided in the lot. NOTE: During the survey, it was noted that the accessible spaces and the entire lot was used by teachers, even during elections.
	Oxford School @ 347 Main Street				Ramps	The interior ramp has a running slope, at the top of the 1st run up, measuring 9.3%.
					Changes in Level Along Accessible Route	1) There is a change in level, where the entrance cement meets the driveway, measuring 3/4 to 1 inch. 2) There is a change in level, at the base of the ramp, measuring 1 inch.
					Entrances (Other than Locked)	There is a threshold, at the entrance, measuring 3/4 of an inch.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
					Ramps	The ramp provided: A) There are no handrails on the left side of the ramp. B) The right side handrails are a 2x4 configuration. C) The right side handrails do not extend the entire run of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Fairhaven	Hastings Middle School @ 30 School Street	00	04	No	Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) The middle space does not have an access aisle adjacent to the space. B) There are 2 spaces that do not have a sign at the head of them. C) The space that is configured as van accessible does not provide a "van-accessible" sign.
	Leroy Wood School @ 60 Sconticut Neck Road		05 & 06		Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not provide a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
FALL RIVER	Old Henry Lord School @ 615 Tucker Street	01	A	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 3 inches.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. Currently, only 2-1/2 feet are provided.
					Ramps	The ramp provided: A) The ramp measures 43 inches wide, measured between the handrails. B) The handrails provided are not round or oval.
	Edward Doolan Apartments @ Corner of Laurel and Mitchell Drive	02	B	Yes	None	
	Saint Williams Church (Msgr. Considine Center) @ Stafford Road		C & D	No	Entrances (Other than Locked)	1) The entrance does not provide a 5-foot level landing on the exterior of the door.
						2) The entrance has 2 steps up to the landing. No ramp is provided.
Kosior-Globe Fire Station @ Fenner Street	02	A	Yes	None		
Saint Stanislaus School @ 37 Rockland Street		B	N/A	**Comments	This location is not going to be used in November.	
Candias-Niagara Fire Station @ Corner of Plymouth Avenue and Warren Street		C	Yes	None		

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
FALL RIVER	Mitchell Apartments @ 2100 South Main Street	03	A	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) There are no signs provided at the head of each of the parking spaces. B) There are 4 access aisles that abut a sidewalk. No curb cuts are provided.
	Hector Belisle School @ 40 Clarkson Street		B		Entrances (Other than Locked)	The designated accessible entrance: A) The hardware on the door is not operable with a closed fist. Currently the door hardware is a door knob. B) The door only provides 30 1/2 inches of clear opening.
	Osborn Street School @ 160 Osborn Street		C		Entrances (Other than Locked)	The entrance has 11 steps. No vertical access is provided.
	Frank Oliveria Apartments @ 170 William Street	04	A		Parking Spaces in Lot	There is a designated accessible parking space that is configured as a van-accessible space. However, there is no "van-accessible" sign provided.
	James O'Brien Apartment @ Morgan and Second Streets		B	Yes	None	
	Riverview Towers @ 301 Milliken Blvd.		C	No	Parking Spaces in Lot	The designated accessible parking spaces, provided in the lot, do not provide an access aisle adjacent to any of the spaces.
	Candias-Niagara Fire Station @ Corner of Plymouth Avenue and Warren Street	05	A	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
FALL RIVER	Chor Bishop EID Apartment @ Quequechan Street	05	B	No	Parking Spaces in Lot	The designated accessible parking spaces do not provide any access aisles adjacent to the spaces.
	Small School @ North Quarry Street		C		Entrances (Other than Locked)	The designated accessible entrance: A) The doors provide a clear opening measuring 27 inches. B) The door hardware on the door is not operable with a closed fist. Currently a door knob is provided.
	Francis Barresi Heights @ 1863 Pleasant Street	06	A	Yes	None	
	George Cottell Hieghts @ 1685 Pleasant Street		B	No	Parking Spaces in Lot	There is a designated accessible parking space that is configured as a van accessible space, however no "van-accessible" sign is provided.
	Edmund Talbot Middle School @ 124 Melrose Street		C		Entrances (Other than Locked)	The designated accessible entrance door provides a clear opening measuring 27 inches.
					Exterior Accessible Route	There is a curb cut missing along the accessible route from the parking to the designated accessible entrance.
	Municipal Veterans Memorial @ 72 Bank Street	07	A & B		Changes in Level Along Accessible Route	There is a change in level at the base of the ramp measuring 2 - 6 inches.
					Entrances (Other than Locked)	The designated accessible entrance: A) There is no door hardware on the door. B) The door provides only 27 inches of clear opening.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
FALL RIVER	Municipal Veterans Memorial @ 72 Bank Street	07	A & B	No	Ramps	The ramp provided: A) The running slope of the ramp measures 12.0% at the bottom, 14.0% in the middle and 16.0% at the top. B) There is only one handrail provided. The handrail is in the middle of the ramp, making the ramp less than 48 inches wide. C) The handrail provided is only the upper handrail and is not round or oval.
	Union United Methodist Church @ 600 Highland Avenue		C	Yes	None	
	Raymond Holmes Apartments @ Fulton and Essex Streets		D	N/A	**Comments	At the time of the survey, the building was still under renovations.
	Oak Village @ 1177 Locust Street	08	A & D	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot does not provide an access aisle adjacent to the space.
	Cardinal Medeiros Towers @ 1197 Robeson Street		B	Yes	None	
	Spencer Borden School @ Chestnut Street		C		None	
	Tansey School @ 711 Ray Street	09	A	No	Exterior Accessible Route	The approach to the designated accessible entrance requires traversing 2 steps. There is no vertical access provided.
					Ramps	The ramp provided at the designated accessible entrance does not provide handrails on one side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
FALL RIVER	The Highlands @ 1800 Highland Avenue	09	B	Yes	None	
	Calvary Temple Assembly of God @ 4321 North Main Street		C		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Falmouth	Town Hall @ 59 Town Hall Square	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the designated accessible entrance, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) There is no van accessible space provided. B) The access aisle, provided adjacent to the parking space, measures 4 feet wide.
	Gus Canty Community Center @ 790 East Main Street		02		Changes in Level Along Accessible Route	There is a change in level, where the access aisle meets the sidewalk for one of the parking spaces, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) There is no van accessible space provided. B) The access aisles, provided adjacent to the parking spaces, measure 4 feet wide. C) There are no signs provided at the head of the spaces.
					Ramps	The upper handrails, provided on the ramp, are not round or oval. The upper handrails are a 2x4 configuration.
					Teaticket Elementary School @ 45 Maravista Avenue	03
Exterior Accessible Route	The walkway, leading to the designated accessible entrance, has an incline with a running slope measuring 10.4%.					

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Falmouth	Teaticket Elementary School @ 45 Maravista Avenue	00	03	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) There is no van accessible space provided. B) The access aisle, provided adjacent to the parking space, measures 4 feet wide. C) There are no signs provided at the head of the spaces.
	East Falmouth Elementary School @ 33 Davisville Road		04		Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut across from the parking, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	There is no access aisle adjacent to the designated accessible parking space provided.
	North Falmouth Elementary School @ 62 Old Main Road		05	Yes	None	
	Morse Pond School @ 323 Jones Road		06	No	Parking Spaces in Lot	There are no signs at the head of the designated accessible parking spaces.
	East Falmouth Fire Station @ 505 East Falmouth Highway		07	Yes	None	
	Navigator @ 55 Ashumet Road (Formerly @ High School)		08	No	Parking Spaces in Lot	The 2 designated accessible parking spaces do not provide access aisles adjacent to them.
	Knights of Columbus @ 279 Brick Kiln Road		09		Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 4 feet.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Falmouth	Knights of Columbus @ 279 Brick Kiln Road	00	09	No	Parking Spaces in Lot	There is no access aisle provided adjacent to the designated accessible parking space.
					Ramps	<p>The ramp provided:</p> <p>A) The ramp is 41 inches wide, measured between the handrails.</p> <p>B) The handrails provided are not round or oval. The handrails are a 2x4 configuration.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
FITCHBURG	Knights of Columbus Hall @ 165 Electric Avenue	01	A & B	No	Entrances (Other than Locked)	The designated accessible entrance used for polling does not provide a level area on the exterior of the door. Currently the ramp extends to the door.
					Ramps	The ramp: A) The ramp provides handrails on one side. B) The handrails that are provided are not round or oval. C) The ramp does not measure 48 inches wide.
	Saint Joseph's Church Hall @ 46 Woodland Street	02			Parking Spaces in Lot	The designated accessible parking spaces provided in the lot do not provide access aisles adjacent to the spaces.
	Memorial Middle School @ 615 Rollstone Street	03		Yes	None	
	Senior Citizens Center @ 14 Wallace Avenue	04			None	
	Civic Center @ 1000 John Fitch Highway	05		No	Ramps	The handrails for the ramp: A) The handrails are not round or oval. Currently they are a 2X4 configuration. B) The handrails to not extend for the entire run of the ramp.
	Saint Bernard's Activity Center @ Summer Street	06		Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
--------------	------------------	------	-------------	----------------------	--------------------	-----------------

Florida

Town Hall

00

01

Yes

None

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Foxborough	Ahern Middle School @ 111 Mechanic Street	00	01, 02, 03, 04 & 05	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Framingham	Hemenway School @ 729 Water Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level measuring 5 inches where the walkway, that leads to the designated accessible entrance, ends.
	Potter Road School @ 492 Potter Road		02	Yes	None	
	George King School @ 454 Water Street		03 & 05	No	Changes in Level Along Accessible Route	There is a change in level measuring 1 1/2 inches at the base of the ramp.
					Ramps	The ramp provided is missing an upper handrail on the left side.
	Brophy School @ 575 Pleasant Street		04 & 07	Yes	None	
	Juniper Hill School @ 29 Upper Jocyn Avenue		06 & 09		None	
	McCarthy School @ 8 Flagg Drive		08 & 13	No	Changes in Level Along Accessible Route	The curb cut located at the front of the school: A) There is a change in level measuring 3/4 of an inch at the base of the curb cut. B) There is a change in level measuring 1 1/4 inches at the top of the curb cut.
					Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. Currently only 2 of the spaces have a sign at the head of the space.
	Keefe Technical School @ 750 Winter Street		10 & 11		Changes in Level Along Accessible Route	The curb cut located on the side of the building near the gymnasium has a change in level measuring 3/4 of an inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Framingham	Keefe Technical School @ 750 Winter Street	00	10 & 11	No	Entrances (Other than Locked)	The designated entrance for polling is through door 12. Door 12: A) There is only a 3 foot level area on the exterior of the door. B) On the inside of the door, there are 3 steps.
					Ramps	The ramp leading to door 12 has a slope measuring between 7.7% and 8.3% but does not provide handrails on either side.
	Memorial Building @ 150 Concord Street		12 & 14	Yes	None	
	Saint Tarcisius Parish Center @ 562 Waverly Road		15 & 18	No	Changes in Level Along Accessible Route	There is no curb cut provide near the entrance to gain access to the sidewalk.
	Woodrow Wilson School @ 169 Leland Street		16 & 17	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Franklin	High School @ Oak Street	00	01, 02, 03, 04, 05, 06, 07 & 08	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Freetown	Elementary School @ 43 Bullock Road	00	01 & 02	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	Multi-Purpose Senior Center @ 227 Chace Road		03	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
GARDNER	Elk's Home @ 31 Park Street	01	A, B & C	No	Exterior Accessible Route	1) The walkway, leading to the ramp, has running slopes measuring 6.0% in the middle and 8.6% at the bottom.
					Ramps	2) There are "on-street" styles designated accessible parking spaces provided during polling. However, no curb cuts are provided near the location of the spaces.
						The handrails on the ramp: A) The left side upper handrail is a 2x4 configuration. B) The right side handrails, both upper and lower, are a 2x4 configuration.
	Fred E. Perry Auditorium @ 95 Pleasant Street	02	A & B		Entrances (Other than Locked)	The designated accessible entrance has a strip of loose gravel creating changes in level measuring 3/4 to 1 1/2 inches.
						NOTE: This entire area is under renovation. The intent is that the entrance area will be fully accessible and repaved by November.
					Parking Spaces in Lot	There is one designated accessible parking space located near the designated accessible entrance. Currently, the space does not provide an access aisle adjacent to it.
		03	A			NOTE: This entire area is under renovation. The intent is that the parking area will be fully accessible.
					Entrances (Other than Locked)	The designated accessible entrance has a strip of loose gravel creating changes in level measuring 3/4 to 1 1/2 inches.
						NOTE: This entire area is under renovation. The intent is that the entrance area will be fully accessible and repaved by November.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
GARDNER	Fred E. Perry Auditorium @ 95 Pleasant Street	03	A	No	Parking Spaces in Lot	There is one designated accessible parking space located near the designated accessible entrance. Currently, the space does not provide an access aisle adjacent to it. NOTE: This entire area is under renovation. The intent is that the parking area will be fully accessible.
	High Rise (Lounge Area) @ 116 Church Street		B		Parking Spaces in Lot	There are 5 designated accessible parking spaces provided. There are no access aisles provided adjacent to the spaces.
	Sacred Heart Church Hall @ 166 Cross Street	04	A & B		Changes in Level Along Accessible Route	There are changes in level, along the entire walkway that leads to the entrance, measuring 3/4 to 1 inch.
					Curb Cuts	The curb cut, located near the parking, has a center running slope measuring 19.3%.
					Exterior Accessible Route	The walkway, leading to the entrance, has a running slope at the top measuring 7.1%.
	Knights of Columbus @ 110 South Main Street	05			Parking Spaces in Lot	There is one designated accessible parking space provided. There is no access aisle provided adjacent to the space.
					Ramps	The ramp does not provide handrails on the right side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Georgetown	Penn Brook School	00	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Gill	Garage/Public Service Building @ 196 Main Road	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the lip at the landing, measuring between 1 to 2 inches.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5- foot level landing on the exterior of the door. The landing measures 28 inches.
					Interior Accessible Route	If vehicles are present in the bay, such as the ambulance or fire trucks, the path of travel from the entrance to the voting area, is reduced to less than 36 inches.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
						Note: During the survey, it was discussed that temporary spaces would be provided during polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
GLOUCESTER	East Gloucester Elementary School @ 8 Davis Street Extension	01	01	Yes	**Comments	** There is a built up curb ramp at the sidewalk that leads to the entrance. This curb ramp has a running slope of 6.4%, however the cross slope exceeds 2%. The curb ramp is also "domed" making it very difficult for someone using a wheelchair to gain access onto the sidewalk.
	Veterans Memorial School @ 11 Webster Street		02	No	Entrances (Other than Locked)	The threshold at the door exceeds 1/2 inch.
	Our Lady's Youth Center @ 140 Prospect Street	02	01	Yes	None	
	McPherson Park Building @ 31 Prospect Street		02		**Comments	** There is a built up curb ramp at the sidewalk that leads to the entrance. This curb ramp has a running slope not exceeding 8.33%, however the cross slope exceeds 2%. The curb ramp is also "domed" making it very difficult for someone using a wheelchair to gain access onto the sidewalk.
	Veterans Center @ 12 Emerson Avenue	03	01		None	
	First Baptist Church @ 38 Gloucester Avenue		02		None	
	Beeman Memorial School @ 138 Cherry Street	04	01	No	Curb Cuts	There is a built up curb ramp at the sidewalk that leads to the entrance. A) The running slope measures 24.0%. **B) The cross slope exceeds 2%. **C) The curb ramp is also "domed" making it very difficult for someone using a wheelchair to gain access onto the sidewalk.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
GLOUCESTER	Beeman Memorial School @ 138 Cherry Street	04	01	No	Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. Each door, when opened singularly, provides only 26 inches of clear opening. NOTE: During the survey, Robert explained that the doors would remain open during the times of polling.
					Entrances (Other than Locked)	The door at the designated accessible entrance provides only 30 inches of clear opening.
	Saint Paul Lutheran Church @ 1123 Washington Street		02		Interior Accessible Route	To get to the voting booths requires traversing 4 steps down.
					None	
	Magnolia Library Center @ 1 Lexington Avenue	05	01	Yes		
	West Parish Elementary School @ 10 Concord Street		02	No	Curb Cuts	There is a built up curb ramp at the sidewalk that leads to the entrance. A) The running slope exceeds 8.33%. **B) The cross slope exceeds 2%. **C) The curb ramp is also "domed" making it very difficult for someone using a wheelchair to gain access onto the sidewalk.
					Entrances (Other than Locked)	The entrance used for polling: A) The entrance has 2 steps, one to get to the landing and another to get to the door. B) The entrance door has a clear opening measuring 28 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
GLOUCESTER	West Parish Elementary School @ 10 Concord Street	05	02	No	Ramps	There is a built up ramp that leads to the designated accessible entrance used for polling. A) The running slope exceeds 8.33%. B) The width is less than 48 inches wide. C) The ramp does not have any handrails. **D) This ramp is "domed" making it very difficult for someone using a wheelchair to use.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Goshen	Town Hall @ 42 Main Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Gosnold	Town Hall @ 28 Tower Hill Road	00	01	No	Changes in Level Along Accessible Route	1) There is a change in level, at the base of the ramp, measuring 1 inch. 2) There is a change in level, where the landing meets the entrance door, measuring 5 1/2 inches.
					Directional Signage	There is no direction sign present to indicate the location of the designated accessible entrance.
					Entrances (Other than Locked)	The designated accessible entrance: A) There is no hardware provided on the exterior of the door. B) The entrance has an interior threshold measuring 1 1/2 inches.
					Exterior Accessible Route	1) The path of travel, for someone who cannot traverse stairs to access the ramp at the rear of the building, is not paved. The path of travel is over grass that is hilly and not hard packed. 2) The path of travel is not the same for all persons entering the building. If someone can traverse stairs, the access to the main entrance is relatively short. For someone not able to traverse stairs, the distance is greater. Someone would need to travel to where the school is (where the retaining wall stops) and gain access to the grass and traverse to the rear of the building where the ramp is.
					Parking Spaces in Lot	There are no on-street designated accessible parking spaces provided.
					Ramps	The ramp: A) There are no lower handrails provided. B) The upper handrails are not round or oval. The handrails are a 2x4 configuration.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Grafton	Municipal Center Gym @ 30 Providence Road	00	01, 02, 03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Granby	East Meadow School @ 393 East State Street	00	01	No	Parking Spaces in Lot	There is no access aisle provided adjacent to the designated accessible parking space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Granville	Town Hall @ 707 Main Road	00	01	No	**Comments Entrances (Other than Locked)	** At the time of the survey, the parking lot had just been repaved. The lot had not been restriped. It was discussed that the spaces were to be striped by the end of March. The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 4.8%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Great Barrington	Searles Middle School	00	A, C & D	No	Changes in Level Along Accessible Route	There is a change in level measuring 3/4 - 2 inches along the accessible route from the parking to the ramp.
					Ramps	The ramp does not provide a lower handrail on either side.
	Housatonic Community Center		B		Entrances (Other than Locked)	There is no level landing on the exterior of the entrance door.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Greenfield	High School @ 1 Lenox Avenue	00	01, 02, 03, 04, 05, 06, 07, 08 & 09	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Groton	Senior Center @ 163 West Main Street	00	01	No	Ramps	The ramp: A) The handrails are not round or oval. The handrails are a 1X3, flat configuration. B) The upper handrail, on both sides, is located at a height measuring 30 1/2 inches.
	GDR High School Gymnasium @ 703 Chicopee Row		02 & 03		Parking Spaces in Lot	There is no van accessible parking space provided in the parking lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Groveland	Town Hall @ 183 Main Street	00	01	No	Changes in Level Along Accessible Route	There are changes in level along the sidewalk, leading to the designated accessible entrance, that measure 3/4 - 1 inch.
					Curb Cuts	The curb cut, located near the designated accessible parking, has a running slope measuring greater than 8.33%.
					Exterior Accessible Route	The path of travel for someone who is disabled is a greater distance than that of the general public.
					Parking Spaces in Lot	There is no van accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hadley	Hopkins Academy @ 131 Russell Street	00	01	No	Exterior Accessible Route	The walkway, leading to the entrance, has a running slope measuring 7.0% at the bottom and 5.9% at the top.
					Parking Spaces in Lot	There is no van accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Halifax	Elementary School @ 464 Plymouth Street	00	01 & 02	No	Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. There is one sign missing from the head of one space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hamilton	Winthrop School @ 325 Bay Road	00	01, 02 & 03	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 4.2%.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
						NOTE: During the survey, it was discussed that temporary spaces are provided during polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hampden	Town House @ 625 Main Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level at the top of the ramp measuring 1 - 1 1/4 inches.
					Ramps	The ramp provided: A) The ramp has a running slope measuring 11.6% at the top and 10.0% at the bottom. B) The ramp measures 41 inches wide, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hancock	Hancock School @ 3080 Hancock Road	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hanover	High School	00	01, 02, 03 & 04	No	Curb Cuts	The curb cut located in front of the accessible parking space: **a) There is pooling of water at the bottom. b) Running slope measures 11.8%.
					Interior Doors	Doors (at gymnasium and entrance and corridor doors) to access the polling area only provide a clear width of 28-30 inches. NOTE: During the survey it was explained that the double doors remain open during time of polling.
					Parking Spaces in Lot	Parking located at the entrance used for polling only has one designated accessible parking space. NOTE: During the survey it was explained that there are temporary spaces created at time of polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hanson	Maquan School @ School Street	00	01, 02 & 03	No	Curb Cuts	The curb cut, located at the entrance, has a center running slope measuring 9.1%.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hardwick	Elementary School @ 531 Lower Road	00	01	No	Curb Cuts	The curb cut, located at the designated accessible entrance, has a center running slope measuring 11.4%.
					Ramps	The interior ramp does not provide lower handrails on either side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Harvard	Bromfield School @ 14 Massachusetts Avenue	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Harwich	Community Center @ 100 Oak Street	00	01, 02, 03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hatfield	Town Hall @ 59 Main Street	00	01	No	Changes in Level Along Accessible Route	<p>1) There is a change in level, at the base of the ramp, measuring 3/4 to 1 inch.</p> <p>2) There is a change in level, in the middle of the ramp, where the patchwork has degraded, measuring 3/4 of an inch.</p> <p>3) There is a grate, at the base of the ramp, with openings measuring 2 inches by 2 inches.</p>
					Parking Spaces in Lot	There are 3 designated accessible parking spaces provided in the lot. There is no access aisle provided adjacent to one of the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
HAVERHILL	Consentino School @ 685 Washington Street	01	01	No	Changes in Level Along Accessible Route	There are changes in level along the accessible route to the designated accessible entrance that measure greater than 1/2 inch.
					Entrances (Other than Locked)	The designated accessible entrance: A) The entrance has 1 step that measures 9 inches. B) The door hardware is not operable with a closed fist.
					Lighting	The path of travel from the designated accessible parking spaces to the designated accessible entrance does not provide enough lighting.
	Washington Square Elderly Housing @ 25 Washington Square		02		Ramps	The portable ramp that is provided at the entrance: A) The slope well exceeds a 1:12 (8.33%) running slope. B) The ramp does not provide handrails or a wheel guard.
					Entrances (Other than Locked)	The door hardware on the designated accessible entrance is not operable with a closed fist. The current configuration is a door knob.
	High School @ 137 Monument Street		03	Yes	None	
	First Church of Christ @ 10 Church Street	02	01	No	Changes in Level Along Accessible Route	There are changes in level along the accessible route to the designated accessible entrance that measure greater than 1/2 inch.
					Entrances (Other than Locked)	There is no door hardware on the exterior of the designated accessible entrance.
					Exterior Accessible Route	The path of travel to the voting area is not "the same or substantially similar for all persons entering the polling place".
	Hunking School @ Winchester Street		02		Entrances (Other than Locked)	The designated accessible entrance has a threshold that exceeds 1/2 inch. The threshold measures 1 1/4 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
HAVERHILL	Moody School @ 59 Margin Street	02	03	No	Changes in Level Along Accessible Route	There are changes in level along the accessible route to the designated accessible entrance that measure greater than 1/2 inch.
					Curb Cuts	The curb cut located at the head of the access aisle provided at the designated accessible parking spaces, has a running slope measuring 13.0%.
					Entrances (Other than Locked)	The designated accessible entrance: A) The threshold measures greater than 1/2 inch. The threshold measures 1 - 1 1/2 inches. B) The door hardware is not operable with a closed fist.
					Ramps	The ramp, located on the interior of the building, has a running slope that measures 9.6%.
	Citizen Center @ 10 Welcome Street	03	01		Changes in Level Along Accessible Route	There are changes in level along the accessible route to the designated accessible entrance that measure greater than 1/2 inch.
	Haverill Public Library @ Summer Street		02		Ramps	The ramp only provides one handrail on each side.
	Universalist Unitarian Church @ Ashland Street		03		Entrances (Other than Locked)	The door hardware at the designated accessible entrance is not operable with a closed fist. NOTE: During the survey, it was explained that the doors would remain open during polling hours.
	Nettle School @ 150 Boardman Street	04	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
HAVERHILL	Second Baptist Church @ 314 Amesbury Line Road	04	02	Yes	None	
	Kennedy Circle Community Room @ Kennedy Circle		03	No	Exterior Accessible Route	The designated accessible entrance is located at the rear entrance. The path of travel is not the "same or substantially similar for all persons entering the polling place".
	Julian Steele Elderly Housing @ Washington Street	05	01		Curb Cuts	The curb cut along the accessible route has a running slope measuring 18%.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot flat level area on the exterior of the door. Currently there is only 4 feet 3 inches provided.
					Ramps	The ramp provided is only 41 1/2 inches wide, measured between the handrails.
	First Presbyterian Church @ 346 Broadway		02		Changes in Level Along Accessible Route	There are changes in level along the accessible route to the designated accessible entrance that measure greater than 1/2 inch.
	High School @ 137 Monument Street		03	Yes	None	
	Saint James School @ 415 Primrose Street	06	01		None	
	J.G. Whittier School @ Winchester Street		02		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
HAVERHILL	Pentucket Lake School @ 252 Concord Street	06	03	No	Curb Cuts	The curb cut along the accessible route has a center running slope measuring 9.9%.
	Elderly Housing Community Room @ Greystone Avenue	07	01		Changes in Level Along Accessible Route	There are changes in level along the accessible route to the designated accessible entrance that measure between 3/4 to 1 inch.
	Hunking School @ Winchester Street		02		Entrances (Other than Locked)	The designated accessible entrance has a threshold that exceeds 1/2 inch. The threshold measures 1 1/4 inches.
	Bradford Elementary School @ 116 Montvale Street		03	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hawley	Town Office @ 8 Pudding Hollow Road	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the bottom of the ramp where the asphalt meets the driveway, measuring 3/4 to 1 inch in multiple areas.
					Entrances (Other than Locked)	The designated accessible entrance door has a threshold measuring 3/4 to 1 inch.
					Parking Spaces in Lot	The designated accessible parking space provided: A) There is no access aisle adjacent to the space. B) The sign, at the head of the space, measures 2 1/2 feet to the top.
					Ramps	The ramp is 42 inches wide, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Heath	Elementary School (Formerly @ Community Hall: 1 West Main Street. Community Hall is under renovation and no location has been determined for the November Election)	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut at the accessible parking, measuring 3/4 to 1 inch.
					Curb Cuts	1) The curb cut, located at the head of the access aisle for the designated accessible parking spaces: A) The center running slope measures 9.0%. **B) The left flare running slope measures 23.2%.
					Exterior Accessible Route	The designated accessible parking spaces are located about 300 feet away from the entrance. They are not the closest spaces provided to access that entrance. NOTE: During the survey, it was discussed that temporary spaces be provided closer to the voting entrance. There is a curb cut located there, however the running slope measures 10.2%.
					Parking Spaces in Lot	The designated accessible parking space configured as van accessible is missing the "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hingham	High School @ 17 Union Street	00	01, 02, 03 & 05	Yes	None	
	Middle School @ 1103 Main Street		04 & 06	No	Curb Cuts	The curb cut, located near the 2 on-street style designated accessible parking spaces provided to the left of the main entrance, has a center running slope measuring 9.0%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hinsdale	Town Hall	00	01	No	Exterior Accessible Route	The accessible route to the designated accessible entrance used for polling has a walkway that has running slopes measuring 9.0% at the bottom, 6.4% in the middle, and 5.6% at the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Holbrook	Junior/Senior High School @ 245 South Franklin Street	00	01, 03 & 04	No	Changes in Level Along Accessible Route	There are changes in level, along the accessible route from the parking to the ramp, measuring 3/4 to 1 1/4 inches.
					Curb Cuts	The curb cut, located at the base of the ramp, has a center running slope measuring 18.8%.
					Exterior Accessible Route	The walkway, leading to the base of the ramp, has a running slope measuring 12.0%.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	Kennedy School @ 337 Plymouth Street		02		Entrances (Other than Locked)	There are 2 entrances that are used for this polling location. A) The right side entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 13.2%. B) The left side entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 16.3%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Holden	Senior Center @ 1130 Main Street	00	01 & 02	Yes	None	
	Rice School (This precinct was formerly at the Senior Center)		03		None	
	Mountview School Gymnasium @ 270 Shrewsbury Street		04	No	Ramps	The ramp provided: A) The running slope of the ramp measured 9.6% at the bottom and 10.0% at the top. B) The ramp does not provide a lower handrail on either side.
	Municipal Light Department @ 1 Holden Street		05	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Holland	Town Hall @ 27 Sturbridge Road	00	01	No	Curb Cuts	The curb cut, located at the accessible parking space, has a center running slope measuring 12.1%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Holliston	High School @ 370 Hollis Street	00	01, 02, 03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
HOLYOKE	Kelly School	01	A	No	Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
					Exterior Accessible Route	The path of travel to the polling location is not "the same or substantially similar" for all persons using the polling location. The accessible route is 400 feet longer than the standard route.
					Ramps	The interior ramp, leading to the polling location: a) The running slope measures 9.8% at the bottom, 10.4% in the middle, and 10.6% at the top. **b) The handrails are loose and need maintenance.
	Prospect Heights		B		Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
					Parking Spaces in Lot	The access aisles for the designated accessible parking spaces meet the sidewalk without any curb cuts.
	Morgan School Gymnasium	02	A		Exterior Accessible Route	The accessible route to the polling entrance: a) There is a walkway, leading from the parking lot, with a running slope measuring 10.4%. b) The walkway near the entrance, has a running slope measuring 11.4%.
					On-Street Parking	There are no designated on-street accessible parking spaces provided.
					Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
	Elmwood Engine House	03	A		Entrances (Other than Locked)	The designated accessible entrance for polling: a) The door provides 27 ½ inches of clear opening. b) The hardware on the door is a doorknob.
					Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
	Joseph Metcalf School		B			

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
HOLYOKE	Joseph Metcalf School	03	B	No	Entrance Locked	The designated accessible entrance requires a button to be pushed to enter the building.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: a) The "van-accessible" space is missing a "van-accessible" sign at the head of the space. b) The "van-accessible" space has an access aisle that measures 4 feet wide. c) The 3 designated accessible parking spaces only have one sign at the head of one of the parking spaces.
	Gas and Electric Plant @ 91 Walnut Street	04	A	Yes	None	
	Saint Paul's Parish House		B		None	
	McMahon School Gymnasium	05	A	No	Entrances (Other than Locked)	The designated accessible entrance for polling: a) The doors provide 27 inches of clear opening. b) The hardware on the door is a thumb latch.
					Lighting	The accessible route to the designated accessible entrance for polling does not provide enough lighting.
	Maurice A. Donahue School		B	Yes	None	
	Rodphey Sholom Synagogue	06	A & B	No	Directional Signage	There is no signage indicating the location of the accessible entrance for polling.
					Entrances (Other than Locked)	The designated accessible entrance for polling: a) The landing on the exterior of the door measures 48 inches. b) The hardware on the door is a doorknob.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
HOLYOKE	Rodphey Sholom Synagogue	06	A & B	No	Ramps	<p>The ramp:</p> <p>a) The right side of the ramp does not provided ant handrails.</p> <p>b) The left side of the ramp provides only one flat handrail.</p> <p>c) The width of the ramp measures less than 48 inches wide.</p>
	E.N. White School Gymnasium	07			Parking Spaces in Lot	One designated accessible parking space provided in the parking lot is missing a sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hopedale	George A. Draper Gymnasium @ 13 Dutcher Street	00	01	No	Ramps	The ramp does not provide handrails that are round or oval. Currently they are flat.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hopkinton	Middle School @ 88 Hayden Road	00	01, 02, 03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hubbardston	Center School @ Main Street	00	01	No	Changes in Level Along Accessible Route	1) Where the designated temporary accessible parking spaces would be provided, there is no curb cut provided to access the sidewalk. 2) There is a change in level, at the grate at the ramp, measuring 3/4 to 1 inch. 3) There is a change in level, in the middle of the ramp, measuring 3/4 to 1 inch.
					Exterior Accessible Route	The walkway, that leads to the ramp, has a running slope measuring 7.9% in the middle and 7.2% at the top.
					Ramps	The ramp is 46 inches wide, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hudson	Hudson High School @ 69 Brigham Street	00	01	No	Parking Spaces in Lot	The designated accessible parking space that is configured as a "van-accessible" space is missing the "van accessible" sign.
	Glen Road Community Center @ 4 Glen Road		02	Yes	None	
	JFK Middle School @ 201 Manning Street		03		None	
	Joseph L. Mulready School @ 306 Cox Street		04		None	
	Forest Avenue School @ 138 Forest Avenue		05		None	
	Town Hall @ 78 Main Street		06	No	Exterior Accessible Route	There is a walkway leading to the ramp. The walkway has a running slope measuring 6.2%.
					Parking Spaces in Lot	There is no van accessible parking space provided.
	Hudson Senior Center @ 29 Church Street		07		Entrances (Other than Locked)	The designated accessible entrance does not provide a level area on the exterior of the door.
					Ramps	The ramp provided has a running slope measuring 11.4% at the bottom and 10.9% at the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Hull	Memorial Middle School @ 81 Central Avenue	00	01, 02 & 03	No	Ramps	The ramp, leading to the Auditorium, has a running slope measuring 8.7% at the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Huntington	Stanton Hall @ Russell Road	00	01	No	Changes in Level Along Accessible Route	There is a change in level near the designated accessible entrance used for polling that measures between 3/4 to 1 inch.
					Ramps	The ramp has a running slope measuring 12.4% at the bottom of the first run up (from street).

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Ipswich	YMCA @ 110 County Road	00	01, 02, 03 & 04	No	Curb Cuts	There is a curb cut, near the entrance, that has a center running slope measuring 9.5%.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 4.5%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Kingston	Elementary School	00	01, 02 & 03	No	Curb Cuts	Curb cut at walkway leading to main entrance has a center running slope measuring 10.2%.
					Entrances (Other than Locked)	The doorway used for the polling entrance does not have a level area outside of the door. The slope of this area measures 5.2%.
					Exterior Accessible Route	The walkway leading to the entrance: a) The running slopes measure 6.2% and 8.9%. **b) The cross slopes measure 4.0%.
	Pembroke Street Fire Station		04		Curb Cuts	The curb cut at the front door used to enter the building for polling has a center running slope measuring 10.4%.
					Parking Spaces in Lot	The accessible parking spaces: a) Are not striped. b) Do not provide access aisles. c) Provide only 1 sign for the 2 possible spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Lakeville	Ted Williams Camp @ 28 Precinct Street	00	01, 02 & 03	No	Changes in Level Along Accessible Route	There is a change in level, where the sidewalk meets the parking space, measuring 3/4 to 1 inch. NOTE: At this location, there is a severe pooling of water.
					Interior Doors	The door to Precinct 3 does not provide a 5 foot level landing on the interior side. The slope measures 13.7%.
					Parking Spaces in Lot	There are 4 designated accessible parking spaces provided. A) The space that is configured as van accessible is missing the "van-accessible" sign. B) 3 spaces do not provide an access aisle.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Lancaster	Town Hall @ 695 Main Street	00	01 & 02	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot, do not provide access aisles adjacent to the spaces.
					Ramps	The handrails, provided on the ramp, are not round or oval.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
--------------	------------------	------	-------------	----------------------	--------------------	-----------------

Lanesborough

Town Hall

00

01

Yes

None

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LAWRENCE	Prospect Hill Community Center @ 112 East Haverhill Street	A	01 & 02	Yes	None	
	Rollins School @ 451 Howard Street		03	No	Ramps	The ramp does not provide handrails on the right side.
	Storrow School @ 40 Pleasant Street		04	Yes	None	
	M.I. Residential Community @ 189 Maple Street	B	01	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) No van accessible parking space is provided. B) The standard accessible parking space does not provide a 5 foot access aisle adjacent to the space. C) There are no curb cuts provided where the spaces (or access aisles) abut the sidewalk. NOTE: If the access aisles abut the sidewalk, then curb cuts would need to be provided at each instance.
	Lawlor School @ 44 Lexington Street		02	Yes	None	
	Leahy School @ 100 Erving Avenue		03		None	
	Valebrook Apartments @ Union and Summer Streets		04		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LAWRENCE	LHA Multi-Service Center @ Essex and Winter Streets	C	01	No	Ramps	The ramp provided: A) The ramp measures 44 inches wide, measured between the handrails. B) The ramp does not provide lower handrails. C) The upper handrail, provided on the right side, does not run the entire length of the ramp.
	Plains Community Center @ 245 Hampshire Street		02		Entrances (Other than Locked)	The designated accessible entrance does not provide any hardware on the exterior of the door.
	Brien Building @ 355 Park Street		03	Yes	None	
	Arlington School @ 150 Arlington Street		04		None	
	Bruce School @ 135 Butler Street	D	01 & 03		None	
	Engine 8 Firehouse @ 329 Ames Street		02		None	
	Essex Towers @ 18 Franklin Street		04		None	
	Diamond Spring Gardens @ One Beacon Avenue	E	01		None	
	Frost School @ 33 Hamlet Street		02	No	Exterior Accessible Route	The path of travel is not the "same or substantially similar for all persons entering the polling place." Currently, due to the lack of curb cuts, someone would need to travel 600 feet further to gain access to the ramp to gain access to the designated accessible entrance.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LAWRENCE	South Congregational Church @ 198 South Broadway	E	03	No	Exterior Accessible Route	The walkway, leading to the designated accessible entrance, has slopes exceeding 5%. The running slopes measure 10.3% at the bottom and 12.4% at the top.
	Elderly Housing @ 339A Salem Street		04		Exterior Accessible Route	The path of travel is not the "same or substantially similar for all persons entering the polling place." Currently, someone needing to use the accessible entrance needs to travel an additional 300 feet than the general public.
	South Lawrence East School @ 165 Crawford Street	F	01 & 02	Yes	None	
	Branch Library @ 135 Parker Street		03		None	
	Knights of Columbus Hall @ One Market Square		04	No	Ramps	The ramp provided: A) The ramp does not provide handrails on the left side. B) The ramp does not provide a lower handrail on the right side. C) The ramp, if handrails were to be added, would not measure 48 inches wide, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Lee	Senior Center (Airoldi Building) @ 45 Railroad Street	00	01, 02, 03, 04, 05, & 06	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Leicester	Town Hall @ 3 Washburn Square	00	01, 02, 03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
--------------	------------------	------	-------------	----------------------	--------------------	-----------------

Lenox	Town Hall	00	01	Yes	None	
-------	-----------	----	----	-----	------	--

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LEOMINSTER	Sky View Middle School @ 500 Kennedy Way	01	A, B & C	Yes	None	
	Southeast Elementary School @ 95 Viscoloid Avenue	02			None	
	Fraternal Order Eagles Hall @ 456 Litchfield Street	03			None	
	Senior Citizen Drop-In Center @ 5 Pond Street	04	A		None	
	Veteran's Quarters @ 100 West Street		B & C		None	
	City Hall Auditorium @ 25 West Street	05	A & B		None	
	First Baptist Church @ 23 West Street		C		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Leverett	Town Hall @ 9 Montague Road	00	01	No	Changes in Level Along Accessible Route	There is a change in level, where the walkway meets the gravel driveway, measuring 1 - 1-1/2 inches.
					Entrances (Other than Locked)	The designated accessible entrance door has hardware that is not operable with a closed fist. The style is a thumb latch. NOTE: The door is operated with an automatic door opener that remains on during polling.
					Exterior Accessible Route	The 5th cement block, of the walkway leading to the entrance, has a running slope measuring 9.1%.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Lexington	Harrington School @ 146 Maple Street	00	01	Yes	None	
	Bowman School @ 9 Philip Road		02		None	
	Clarke Middle School @ Stedman Road		03	No	Ramps	There is a walkway that leads to the gymnasium doors. This walkway is actually the slope of a ramp. A) The running slope measures 9.3% at the top, 8.1% in the middle and 7.2% near the bottom. B) No handrails are provided.
	Bridge School @ 55 Middleby Road		04	Yes	None	
	Fiske School @ 34A Colony Road		05		None	
	WM. Diamond Middle School @ 99 Hancock Street		06		None	
	Joesph Estabrook School @ 117 Grove Street		07		None	
	Central Fire Station @ 43 Bedford Street		08		None	
	Maria Hastings School @ 2618 Massachusetts Avenue		09		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Leyden	Town Hall @ 16 West Leyden Road	00	01	No	Entrances (Other than Locked)	The designated accessible entrance used for polling: A) The threshold measures 1 to 1 1/2 inches. B) There is no 5-foot level landing provided on the exterior of the door. The slope measures 10.4%. C) The entrance door does not provide hardware that is operable with a closed fist. A door knob is provided.
					Exterior Accessible Route	The walkway, leading from the parking to the designated accessible entrance used for polling, has running slopes measuring 8.6% at the top and 9.5% at the bottom.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
--------------	------------------	------	-------------	----------------------	--------------------	-----------------

Lincoln

Smith School

00

01, 02 & 03

No

Parking Spaces in Lot

There are no signs provided at the head of the accessible parking spaces.

NOTE: During the survey it was discussed that the Town is planning to install them prior to school opening in September.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Littleton	Littleton Middle School @ Russell Street	00	01, 02 & 03	No	**Comments	There is a grate near the designated accessible entrance that has openings measuring 2 inches by 2 inches.
					Changes in Level Along Accessible Route	There are changes in level along the accessible route to the designated accessible entrance used for polling measuring between 3/4 to 1 1/2 inches.
					Directional Signage	There are no signs directing people to the designated accessible entrance used for polling.
					Parking Spaces in Lot	The designated accessible parking space that is configured as a van accessible space does not provided the "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Longmeadow	Community House @ 735 Longmeadow Street	00	A, B, C, D & E	No	Entrances (Other than Locked)	The designated accessible entrance has door hardware that is not operable with a closed fist. The hardware is currently a thumb latch. NOTE: During the survey, it was explained that the latching system was disabled during polling. There is also an automatic door opener provided that is operational during the times of voting.
					Exterior Accessible Route	The walkway, leading from the designated accessible parking to the designated accessible entrance, has running slopes measuring 6.4% to 7.8%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LOWELL	Firehouse @ High Street	01	01	Yes	None	
	Reilly School @ 115 Douglas Road		02 & 03	No	Ramps	The ramp provided: A) The running slope of the ramp measures 10.9% at the top and 10.1% in the middle. B) The ramp measures 36 inches wide, measured between the handrails. C) The handrails are not round or oval, they are flat.
	Masonic Center @ 79 Dutton Street (Formerly Smith Baker Center [prec. 1 & 2] and City Magnet School [prec. 3])	02	01, 02 & 03		Entrances (Other than Locked)	The designated accessible entrance: A) The entrance does not provide a 5-foot level area on the exterior of the door. Currently there is only 3-feet provided. B) The hardware on the door is not operable with a closed fist. Currently there is a door knob provided.
					Ramps	The portable ramp does not provide either wheel guards or handrails.
	Bailey School @ 175 Campbell Drive	03	01 & 02	Yes	None	
	Morey School @ 114 Pine Street		03	No	Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. Opened individually, each door provides only 26 inches of clear opening.
		04	01		Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. Opened individually, each door provides only 26 inches of clear opening.
	VFW @ 190 Plain Street		02	Yes	None	
	Rodgers School @ 43 Highland Street		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LOWELL	McAvinnue School @ 117 Mammoth Road	05	01	Yes	None	
	Polish American Veteran's Hall @ 190 Plain Street		02	No	Directional Signage	There are no signs directing people to the designated accessible entrance location.
					Entrances (Other than Locked)	The designated accessible entrance: A) The entrance does not provide a level landing on the exterior of the door. The slope measures 6.2%. B) The entrance does not provide any door hardware on the exterior.
					Ramps	The ramp provided: A) The ramp measures 39 inches wide, measured between the handrails. B) The ramp does not provide lower handrails.
	Greenhalge School @ 149 Ennell Street		03		Parking Spaces in Lot	There is a designated accessible parking space provided that is properly configured as a van accessible space. However, there is no "van-accessible" sign provided.
	McAvinnue School @ 117 Mammoth Road	06	01	Yes	None	
	Dr. An Wang School @ West Meadow Road		02		None	
	Lodge of the Elks @ Old Ferry Road		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LOWELL	Council on Aging @ 276 Broadway Street (Formerly Bartlett School [prec. 1] and Murkland School [prec. 2 & 3])	07	01, 02 & 03	Yes	None	
	Firehouse @ Pine Street	08	01		None	
	James Daley School @ 150 Fleming Street		02 & 03		None	
	Polish American Veteran's Hall @ 190 Plain Street	09	01	No	Directional Signage	There are no signs directing people to the designated accessible entrance location.
					Entrances (Other than Locked)	The designated accessible entrance: A) The entrance does not provide a level landing on the exterior of the door. The slope measures 6.2%. B) The entrance does not provide any door hardware on the exterior.
					Ramps	The ramp provided: A) The ramp measures 39 inches wide, measured between the handrails. B) The ramp does not provide lower handrails.
	Robinson School @ 110 June Street		02 & 03		Changes in Level Along Accessible Route	There is a change in level, near the curb cut provided at the parking, measuring 1 inch.
					Curb Cuts	The curb cut, provided at the head of the access aisle at the designated accessible parking, is a T-cut configuration. A) The left side center running slope measures 12.0%. B) The right side center running slope measures 11.9%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LOWELL	VFW @ 190 Plain Street	10	01	Yes	None	
	Firehouse @ Lawrence Street		02		None	
	Saint Anthony's Parish Hall @ 920 Central Street		03		None	
	Shaughnessy School @ 1170 Gorham Street	11	01		None	
	J.G. Pyne School @ Boylston Street		02 & 03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Ludlow	Chapin Elementary School @ Chapin Street	00	01	No	Parking Spaces in Lot	The designated accessible parking spaces provided: A) The space that is configured as a van accessible space does not provide a "van-accessible" sign. B) The access aisle, shared for the 2 spaces abuts a sidewalk. No curb cut is provided.
	Christ the King Social Center @ Center Street		02		Parking Spaces in Lot	The designated accessible parking spaces provided: A) There are 2 spaces provided. Only 1 space has a sign at the head. B) The space that is configured as a van accessible space does not have a "van-accessible" sign.
	High School @ Chapin Street		03		Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 6.6%.
	East Street School @ East Street		04		Curb Cuts	The curb cut, located at the parking, has a center running slope measuring 10.1%.
					Parking Spaces in Lot	The 2 designated accessible parking spaces provided: A) There is no van accessible parking space provided. B) The 2 spaces share a 4-foot access aisle.
	First Church in Ludlow @ Church and Center Street		05		Parking Spaces in Lot	The 2 designated accessible parking spaces provided do not have an access aisle adjacent to them.
	Veteran's Park Elementary @ Chapin Street		06		Curb Cuts	The curb cut, located near the ramp, has a center running slope measuring 9.1%.
					Parking Spaces in Lot	The 2 designated accessible parking spaces provided do not have an access aisle adjacent to them.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Lunenburg	Passios Elementary School @ 1025 Massachusetts Avenue	00	A, B, C & D	No	Entrances (Other than Locked)	The designated accessible entrance door provides only a 28 inch clear opening.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LYNN	Shoemaker School @ Clearview Avenue	01	01	No	Changes in Level Along Accessible Route	There is some missing asphalt, near the designated accessible entrance creating a change in level measuring 3/4 to 1 inch.
					Parking Spaces in Lot	There is a small parking lot located near the designated accessible entrance. There are no designated accessible parking spaces provided.
	Briarcliff Lodge @ 112 Kernwood Drive	02	03	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.	
	Sission School @ 56 Conomo Avenue			Lighting	There is no lighting provided along the path of travel from the accessible parking to the designated accessible entrance.	
				Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.	
				Ramps	The ramp, at the designated accessible entrance, measures only 46 inches wide, measured between the handrails.	
	St. Pius Lower Church Hall @ 215 Maple Street	04	Changes in Level Along Accessible Route	There is a 1 inch lip located at the designated accessible entrance.		
			Entrances (Other than Locked)	The designated accessible entrance door only provides 26 inches of clear opening.		
			Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) One space is missing an access aisle. B) There is no van-accessible space provided. C) The spaces do not have signs at the head of the spaces.		
		02	01, 02 & 03		Changes in Level Along Accessible Route	There is a 1 inch lip located at the designated accessible entrance.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LYNN	St. Pius Lower Church Hall @ 215 Maple Street	02	01, 02 & 03	No	Entrances (Other than Locked)	The designated accessible entrance door only provides 26 inches of clear opening.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) One space is missing an access aisle. B) There is no van-accessible space provided. C) The spaces do not have signs at the head of the spaces.
	Quaker Meadow Clubhouse @ 65 Memorial Park Avenue		04		Entrances (Other than Locked)	The designated accessible entrance does not provide a level area on the exterior of the door. The slope measures 6.8%.
					Parking Spaces in Lot	The designated accessible parking space provided in the lot does not provide a sign at the head of the space.
	Holy Family Civic Center @ 21 Bessom Street	03	01, 02 & 03		Changes in Level Along Accessible Route	There is a change in level measuring 3/4 to 1 inch at the designated accessible entrance.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) There are no signs at the head of the spaces. B) The space that is configured as a van-accessible space does not provide the "van-accessible" sign.
					Ramps	The ramp, leading to the designated accessible entrance has a slope measuring: A) For the left panel: 9.4% at the bottom and 10.5% at the top. B) For the right panel: 9.7% in the middle. C) No handrails are provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LYNN	Congregation Ahabat Sholom @ 151 Ocean Street	03	04	No	Changes in Level Along Accessible Route	There is a change in level measuring 3/4 to 1 1/4 inches at the base of the ramp.
					Ramps	The ramp provided: A) The ramp has running slopes measuring 12.8% at the bottom and 12.0% at the top. B) The ramp only provides an upper handrail on each side, however, the handrails provided are not round or oval.
	Ford School @ 49 Hollingsworth Street	04	01		Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
					Ramps	The ramp has running slopes, on the 2nd run up the ramp, measuring 10.3% at the top and 9.4% at the bottom.
	McGee House @ 37 Green Street		02		Ramps	The ramp provided has running slopes measuring 9.9% on the first run down and 9.6% on the second run down.
	Harrington School @ 21 Dexter Street		03 & 04		**Comments	There is an elevator located inside that needs to be used in order to get to the polling location. We need to get the dimensions of the elevator measured from door to wall and wall to wall.
					Changes in Level Along Accessible Route	There is a 3/4 inch lip located along the ramp.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a level area on the exterior of the door. The slope measures 5.2%.
					Lighting	There is no lighting provided from the parking to the designated accessible entrance.
					On-Street Parking	There is no indication of any temporary spaces being provided on street during elections.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LYNN	Harrington School @ 21 Dexter Street	04	03 & 04	No	Ramps	The ramp provided: A) The running slopes of the ramp measures 11.1% at the bottom, 12.8% in the middle and 11.9% at the top. B) Handrails are only provided on the left side of the ramp. **C) There is a drain cover with openings measuring 2 inches by 2 inches.
	Salvation Army @ 1 Franklin Street	05	01, 02 & 03		Entrances (Other than Locked)	The designated accessible entrance uses two doors, one for entering and one for exiting the polling location. The door the right: a) has a 1 -1 1/4 inch threshold and b) does not provide a level area on the exterior of the door. The door to the left: a) has a 2 - 2 1/2 inch threshold and b) does not provide a level area on the exterior of the door.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
	Community Hall @ 10 Church Street		04	Yes	None	
	Drewicz Elementary School @ 34 Hood Street	06	01, 02 & 04	No	Changes in Level Along Accessible Route	There is a change in level measuring 3/4 inch at the base of the ramp.
					Directional Signage	There are no signs indicating the location of the designated accessible entrance used for polling.
					Entrance Locked	The designated accessible entrance requires someone to meet the person who is disabled at the door. The disabled individual is then escorted to an elevator and brought down to the polling location. The disabled individual is not allowed to do this on their own. The process is reversed when the disabled person leaves the polling location.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LYNN	Drewicz Elementary School @ 34 Hood Street	06	01, 02 & 04	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
					Ramps	The ramp has running slopes measuring 9.5% at the bottom of the first run up the ramp and 9.3% at the top of the first run up the ramp.
	Marian Gardens Association @ Sheppard Street		03		Changes in Level Along Accessible Route	There is a change in level at the designated accessible entrance that measures between 1 and 2 inches.
					Curb Cuts	The curb cut provided at the access aisle on the left side of one of the designated accessible parking spaces provides a curb cut to access the sidewalk. However the center running slope measures 10.2%.
					Exterior Accessible Route	The path of travel along the sidewalk in front of the designated accessible parking spaces is reduced to less than 36 inches because of bushes that have encroached the sidewalk.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) The space configured as a van-accessible space does not provided a "van-accessible" sign at the head of the space. B) One space does not provide a sign at the head of the space. C) The access aisle for the right side parking space does not provide a curb cut where the sidewalk and the access aisle abut.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
LYNN	Classical High School @ 235 O'Callaghan Way	07	01 & 04	No	Entrances (Other than Locked)	The designated accessible entrance used for polling does not provided any hardware on the exterior of the door. NOTE: IT was explained during the survey that this entrance is used for everyone entering the polling location. Someone monitors the doors at all times during the polling hours.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) There are no spaces provided close to the entrance used for polling. B) There is no van-accessible parking space provided. C) There are no signs at the head of the spaces.
	Breed Jr. High School @ 90 O'Callaghan Way		02 & 03		Parking Spaces in Lot	There are no designated accessible parking spaces located near the designated accessible entrance used for polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Lynnfield	Town Hall @ 55 Summer Street	00	01 & 04	No	Curb Cuts	The curb cut at the designated accessible entrance used for polling has a center running slope measuring 10.6%.
					Entrances (Other than Locked)	The designated accessible entrance used for polling has a threshold measuring 3/4 of an inch.
					Parking Spaces in Lot	The designated accessible parking provided in the parking lot: A) The signs at the head of the parking spaces measure 4 feet 2 inches to the top. B) The space that is configured as a van accessible space is missing the "van-accessible" sign.
					Ramps	The ramp, directly inside the designated accessible entrance for polling, has a running slope measuring 9.8% at the top and 9.2% at the bottom.
	South Fire Station @ Summer and Salem Street		02 & 03		Directional Signage	There is no sign directing people to the designated accessible entrance used for polling.
					Entrances (Other than Locked)	The designated accessible entrance used for polling does not provide a level area on the exterior of the door.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
						NOTE: During the survey, Pam stated that temporary spaces are provided at the time of polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
MALDEN	Ferryway School @ 150 Cross Street	01	01 & 02	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	Community Room @ 89 Pearl Street	02	01	Yes	None	
	Irish American @ 177 West Street		02	No	Entrances (Other than Locked)	The designated accessible entrance: A) The entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 4.2%. B) The entrance door provides only 27 inches of clear opening.
	Beebe School @ 403 Pleasant Street	03	01 & 02		Parking Spaces in Lot	The designated accessible parking provided in the lot: A) The parking space that is configured as a van accessible space is missing the "van-accessible" sign. B) One of the parking spaces does not provide a sign at the head of the space.
	Holmes School (Formerly Oak Grove Community Center)	04	01	Yes	None	
	Government Center @ 200 Pleasant Street		02		None	
	Salemwood School @ 529 Salem Street	05	01		None	
	Forestdale School @ 74 Sylvan Street		02		None	
	Maplewood School @ 30 Laurel Street	06	01		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
MALDEN	Community Room @ 630 Salem Street	06	02	Yes	None	
	Ferryway School @ 150 Cross Street	07	01	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	Suffolk Mannor @ 312 Bryant Street		02		Entrances (Other than Locked)	The designated accessible entrance door does not provide 32 inches of clear opening. Currently, it provides only 30 inches.
	Linden School @ 29 Wescott Street	08	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Manchester-by-the-Sea	Memorial School @ 55 Lincoln Street	00	01	No	Exterior Accessible Route	The 3 designated accessible parking spaces provided in the parking lot are located near the main entrance. The spots are a long distance from the designated accessible entrance used for polling. NOTE: During the survey, it was discussed that temporary parking spaces be provided closer to the designated accessible entrance used for polling.
					Interior Doors	There is a set of double doors on the interior of the building. Opened individually, each door provides only 28 inches of clear opening.
					Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. There are no access aisles provided adjacent to any of the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Mansfield	High School Gymnasium @ 250 East Street	00	01, 02, 03, 04, 05 & 06	No	Parking Spaces in Lot	The designated accessible parking spaces: A) There are no signs provided at the heads of the designated accessible parking spaces. B) The space that is configured as van-accessible does not provide a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Marblehead	Old Town House @ 1 Market Square	00	01	Yes	None	
	Star of the Sea Community Center @ 80 Atlantic Avenue		02, 03 & 04	No	Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. When a single door is open, the clear opening measures less than 32 inches. NOTE: During the survey, Tom explained that during polling the double doors will remain open.
	Marblehead Community Center @ 10 Humphrey Street		05, 06 & 07	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Marion	The Music Hall @ 164 Front Street	00	01	No	Interior Accessible Route	There is a lift, on the inside of the building, that is not able to be operated independently. During the course of the survey, Debra explained that there is a police officer who would notify the people upstairs and the lift would be lowered, then raised when the person is on the lift. The lift requires keys to operate.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) There are no access aisles provided adjacent to the spaces. NOTE: The entire lot is not striped. During the survey, it was discussed that temporary spaces are provided during polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
MARLBOROUGH	Francis Kane School	01	01 & 02	Yes	None	
		02				
	Raymond Richer School	03	01		None	
	Heritage Banquet Hall		02		None	
	Boys and Girls Club	04	01 & 02	No	Entrances (Other than Locked)	The designated accessible entrance: a) The landing outside of entrance door has a slope measuring 9.0%. b) The threshold measures ¾ of an inch.
	Senior Center	05	01	Yes	None	
	Heritage Banquet Hall		02		None	
	Middle School	06	01 & 02		None	
	Hildreth School	07			None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Marshfield	Furnace Brook Elementary School	00	01, 02, 03, 04, 05, 06 & 07	No	Curb Cuts	1) The curb cut leading to the Gym Entrance, closest to the drop-off area has a center running slope measuring 12.7%. 2) The curb cut located at the head of the 8-foot access aisle at the designated accessible parking has a center running slope measuring 9.2%.
					Exterior Accessible Route	** The cross slopes of the sidewalk leading from the designated accessible parking to the Gym Entrance has slopes exceeding 2%. Some areas measure 6-8%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Mashpee	Quashnet School @ 150 Old Barnstable Road	00	01, 02, 03, 04 & 05	No	Exterior Accessible Route	The walkway, leading to the designated accessible entrance, at the curved portion, has a running slope measuring 6.6%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Mattapoisett	Knights of Columbus @ 57 Fairhaven Road	00	01 & 02	No	Parking Spaces in Lot Ramps	There are 2 designated accessible parking spaces provided. A) There is no van accessible space provided. B) No access aisles are provided adjacent to the spaces. The handrails provided on the ramp: A) The right side handrail is not round or oval. B) The right side of the ramp does not provide a lower handrail.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Maynard	Memorial Gymnasium @ 121 Washington Street	00	01	Yes	None	
	Town Hall @ 195 Main Street		02		None	
	High School Gymnasium @ 1 Tiger Drive		03	No	Curb Cuts	The curb cut, at the walkway that leads to the gymnasium has a center running slope measuring 12.0%.
					Ramps	The ramp provided: A) The ramp has a running slope measuring 16.0% and 9.1%. B) The ramp does not measure 48 inches wide. This is because there is a railing in the middle of the ramp. C) The ramp does not provide handrails on the left or right side.
	Housing Authority Recreation Room @ 15 Powder Mill Circle		04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Medfield	Ralph Wheelock School @ 17 Elm Street	00	01, 02, 03 & 04	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut located near the parking, measuring greater than 1/2 inch.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing does not measure 5-feet.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
MEDFORD	Community Family @ 121 Washington Street	01	01	Yes	None	
	Firefighters Club @ 340 Salem Street		02	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot. NOTE: During the survey, Edward explained that temporary "on-street" parking spaces are provided.
	Saint Francis Parish Center @ Fellsway and Fulton Street	02	01		Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot. NOTE: During the survey, Edward explained that there are temporary spaces provided in the lot near the entrance for polling.
	Ames Street Fire Station @ 2 Ames Street		02	Yes	None	
	Lawrence Memorial Hospital @ 170 Governors Avenue	03	01	No	Parking Spaces in Lot	The designated accessible parking space configured as van-accessible does not provide the "van-accessible" sign.
	Temple Shalom @ 475 Winthrop Street		02		Parking Spaces in Lot Ramps	There are no designated accessible parking spaces provided in the parking lot. However, there are 2 "on-street" style spaces provided near the entrance along the driveway.. The ramp provided at the main entrance has running slopes measuring 9.6% in the middle and 9.2% at the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
MEDFORD	Zion Fellowship Church @ 320 Boston Avenue	04	01	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot. NOTE: During the survey, Edward explained that there are temporary spaces provided during polling.
					Ramps	The ramp provided at the designated accessible entrance for polling is missing the left side handrails.
	Wellesley Methodist Church @ 100 Winthrop Street		02		Entrances (Other than Locked)	The hardware on the designated accessible entrance is a door knob.
					Ramps	The ramp provided: A) The ramp does not provide any handrails on the right side of the ramp. B) The ramp only provides an upper handrail on the left side of the ramp, however the upper handrail is a 2X4 configuration. C) The running slope of the ramp measures 10.3% at the middle of the first run and 11.7% at the middle of the top run.
	Kennedy School @ Yale Street	05	01	Yes	None	
	Fire Station @ Medford Street		02	No	Entrances (Other than Locked)	The landing on the exterior of the entrance door has a slope measuring 3.3%.
	Fire Station @ 28 Harvard Avenue	06	01		Curb Cuts	The curb cut located at the entrance has a center running slope measuring 18.9%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
MEDFORD	Walking Court @ Auburn Street and North Street	06	02	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) The access aisles measure only 5 feet wide. There is no 8 foot access aisle provided for a "van-accessible" space. B) There are no signs provided at the head of the spaces.
	Mystic Valley Towers @ North Building	07	01		Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot. NOTE: During the survey, Edward explained that temporary "on-street" style spaces are set up near the entrance during polling.
	Saint James Parish Center @ 122 Fourth Street		02	Yes	None	
	Senior Center @ 101 Riverside Avenue	08	01	No	Curb Cuts	The curb cut provided in front of the access aisle at the designated accessible parking space has a center running slope measuring 9.2%.
	VFW @ 114 Mystic Avenue		02		Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) Some of the parking spaces were missing the access aisles. B) The space that does provide an access aisle, the access aisle measures 4 feet wide.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
--------------	------------------	------	-------------	----------------------	--------------------	-----------------

Medway	High School @ 45 Holliston Street	00	01, 02, 03 & 04	Yes	None	
--------	--------------------------------------	----	-----------------	-----	------	--

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
MELROSE	Roosevelt School	01	01	Yes	None	
	Steele House School		02		None	
	Horace Mann School	02	01 & 02		None	
	Beebe School	03			None	
	City Hall	04	01		None	
	Winthrop School		02		None	
	Lincoln School	05	01 & 02		None	
	City Hall	06	01		None	
	Winthrop School		02		None	
	Ripley School	07	01	No	Exterior Accessible Route	The path of travel is not "substantially similar" for all persons entering the polling place.
					Interior Accessible Route	The path of travel inside the school to the polling area is much longer than the path of travel for the general public.
					On-Street Parking	No designated on-street accessible parking space is provided.
	Hoover School		02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Mendon	Miscoe Hill Elementary School @ 148 North Avenue	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Merrimac	Sweetsir School @ 104 Church Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Methuen	Timony Grammer School @ 45 Pleasant View Street	00	01, 02, 06 & 10	Yes	None	
	Tenney Grammer School @ 75 Pleasant Street		03, 07, 09 & 12		None	
	Park Garden Apartment Community Room @ 10 Burnham Road		04 & 05	No	Curb Cuts	The curb cut along the accessible route to the designated accessible entrance has a center running slope measuring 10.4%. (2 1/2:24)
					Parking Spaces in Lot	There are no designated accessible parking spaces provided. NOTE: During the survey, Christine stated that temporary spaces are provided closest to the polling entrance during polling.
	Marsh School @ 311 Pelham Street		08 & 11	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Middleborough	Senior Multi Service Center @ 558 Plymouth Street	00	01 & 05	No	Changes in Level Along Accessible Route	There is a change in level, in the walkway at the driveway, measuring 1 to 1 1/4 inches.
					Parking Spaces in Lot	There is no van accessible parking space provided.
	High School @ 71 East Grove Street		02, 04 & 06		Parking Spaces in Lot	None of the designated accessible parking spaces provide signs at the head of the spaces.
					Ramps	There are no handrails provided on the ramp.
	South Middleborough Fire Station @ 566 Wareham Street		03	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Middlefield	Town Hall @ 188 Skyline Trail	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Middleton	Fuller Meadow School @ 143 South Main Street	00	01 & 02	No	Parking Spaces in Lot	There are 2 designated accessible parking spaces provided in the lot, both sharing an 8 foot access aisle. One of the spaces needs to have a "van-accessible" sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Milford	Middle School East @ 45 Main Street	00	01	Yes	None	
	Italian American War Veterans @ 11 Hayward Field		02		None	
	Memorial School @ 12-14 Walnut Street		03	No	Parking Spaces in Lot	The designated accessible parking spaces do not provide signage at the head of the spaces.
	Brookside Elementary @ 110 Congress Street		04 & 05	Yes	None	
	Woodland Elementary @ North Vine Street		05 & 06		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Millbury	Raymond Shaw School @ Elmwood Street	00	01, 02, 03 & 04	No	Parking Spaces in Lot	There is 1 designated accessible parking space provided. A) There is no access aisle provided adjacent to the space. B) There is no sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Millis	Veterans' Memorial Building @ 900 Main Street	00	01, 02 & 03	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut located at the parking, measuring greater than 1/2 inch.
					Parking Spaces in Lot	There is no van accessible parking space provided in the lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Millville	Municipal Center @ 8 Central Street	00	01	No	Parking Spaces in Lot Ramps	The designated accessible parking spaces provided in the lot do not have signage at the head of the spaces. The ramp provided: A) The running slope measures 9.2% at the bottom and 9.4% at the top. B) The ramp does not provide lower handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Milton	Parkway Methodist Church (Temporarily moved from Tucker School)	00	01	Yes	None	
	Saint Mary's School @ 250 Brook Road		02		None	
	Glover School @ 255 Canton Avenue		03	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) There is no van accessible space provided. B) There are no signs at the head of the spaces.
	Milton Senior Center @ 10 Walnut Street		04 & 11		Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) There is no van accessible space provided. B) There are no signs at the head of the spaces.
	Fuller Village @ 1399 Blue Hill Avenue		05	Yes	None	
	Cunningham School @ 44 Edge Hill Road		06	No	Changes in Level Along Accessible Route	There is a change in level measuring 3/4 of an inch near the designated accessible entrance.
	Cunningham Park Center @ 75 Edge Hill Road		07 & 10	Yes	None	
	Collicot School @ 80 Edge Hill Road		08		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Milton	Winter Valley @ 600 Canton Avenue (Temporary Site: Will be moving to another location in August	00	09	No	Ramps	The ramp only provides handrails on one side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Monroe	Town Hall @ 3-C School Street	00	01	No	Exterior Accessible Route	The walkway, leading to the designated accessible entrance, has a running slope measuring 5.7% to 6.0%.
					Parking Spaces in Lot	There is no access aisle provided adjacent to the designated accessible parking space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Monson	Town Office Building @ 110 Main Street	00	A, B & C	No	Parking Spaces in Lot	The designated accessible parking space that is designated the van-accessible space, does not provide an eight-foot access aisle adjacent to the space. Currently, the access aisle is a triangle, and narrows to 1-1/2 feet at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Montague	Center Library @ 15 Center Street	00	01	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
					Ramps	The ramp has running slopes that measure 9.8% near the top of the 2nd run up, and 9.9% at the top of the 3rd run up.
	Highland School Apartment @ 446 Millers Falls Road		02		Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level area on the exterior of the door. Currently, only 3-feet are provided then there is a slope measuring 5%.
					Parking Spaces in Lot	The designated accessible parking space provided in the lot, does not provide an access aisle adjacent to it.
	Hillcrest Elementary @ 30 Griswold Street		03 + 04		Parking Spaces in Lot	The designated accessible parking space provided in the parking lot: A) The space does not provide an access aisle adjacent to it. B) There is no "van-accessible" sign at the head of the space.
					Entrances (Other than Locked)	The level area on the exterior of the designated accessible entrance measures only 4-feet.
	Senior Center @ 62 Fifth Street		05		Exterior Accessible Route	The walkway, leading to the ramp, has a running slope measuring 8.33%.
					Ramps	The ramp provided: A) The ramp has a running slope measuring 9.2% on the top run. B) The ramp measures 42 inches wide, between the handrails, on the top run.
	Masonic Lodge @ 20 Masonic Avenue		06		Changes in Level Along Accessible Route	1) There is a change in level measuring 3/4 to 1 inch at the base of the ramp.
						2) There is a change in level measuring 3/4 to 1 inch at the entrance.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Montague	Masonic Lodge @ 20 Masonic Avenue	00	06	No	Entrances (Other than Locked)	The designated accessible entrance: A) There is no level area on the exterior of the door. B) There is no door hardware on the exterior of the door.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
					Ramps	The ramp provided: A) The running slope measures 9.0% at the middle of the 1st run up, and 11.0% at the top of the 1st run up. B) The ramp measures 45 inches wide, measured between the handrails. C) The handrails are a 2X4 configuration, not round or oval.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Monterey	Monterey Fire House @ 411 Main Road	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Montgomery	Town Hall @ 161 Main Road	00	01	No	Changes in Level Along Accessible Route	There are changes in level, along the sidewalk at the side of the building, measuring from 1/2 to 3/4 of an inch.
					Exterior Accessible Route	The driveway, from the parking to the walkway that leads to the entrance, has a running slope measuring 10.4%.
					Parking Spaces in Lot	1) There is no access aisle adjacent to the designated accessible parking space provided. 2) The sign at the head of the accessible space measures 54 inches to the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Mount Washington	Town Hall @ 118 East Street	00	01	No	Changes in Level Along Accessible Route	1) There is a change in level, where the walkway, leading to the ramp begins, measuring 3 inches. 2) There is a change in level, at the ramp, measuring 4 inches.
					Directional Signage	There is no directional signage indicating the location of the designated accessible entrance.
					Exterior Accessible Route	The path of travel to the designated accessible entrance from the parking, is not paved. Currently, to access the ramp, the path of travel is over grass.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Nahant	Town Hall	00	01	No	Changes in Level Along Accessible Route	The first ramp leading to the designated accessible entrance for polling has changes in levels at the top measuring between 1 to 3 inches.
					Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
					Entrances (Other than Locked)	The designated accessible entrance does not provided hardware on the exterior of the door. NOTE: During the survey, it was explained that the doors remain propped open during elections.
					Lighting	There are no lights provided in the parking lot.
					Ramps	The first ramp leading to the designated accessible entrance for polling: a) The width of the ramp measures 38 inches between the handrails. b) The running slopes of the ramp measure 9.2% on the first portion and 9.6% on the second portion.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Nantucket	High School @ 10 Surfside Road	00	01	No	Parking Spaces in Lot	The designated van-accessible parking space has an access aisle that is less than 8-feet wide for the entire length. The access aisle narrows at the head of the space, creating a triangle.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Natick	Kennedy Middle School @ 163 Mill Street	00	01 & 03	No	Curb Cuts	The curb cut, located to the right of the main entrance, has a center running slope measuring 9.5%.
	Cole Recreational Building @ 179 Boden Lane		02		Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not provide a "van-accessible" sign.
	Wilson Middle School @ 22 Rutledge Road		04 & 05	Yes	None	
	Lilja School @ 41 Bacon Street		06 & 07		None	
	High School @ 15 West Street		08		None	
	Morse Institute Library @ 14 East Central Street		09		None	
	Memorial School @ 107 Eliot Street		10		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Needham	Hillside School @ 28 Glen Gary Road	00	A & B	Yes	None	
	Newman School @ 1155 Central Avenue		C		None	
	High Rock School @ 77 Ferndale Road		D		None	
	Pollard Middle School @ 200 Harris Avenue		E		None	
	South Palmer Community Room @ 83 Pickering Street		F		None	
	Broadmeadow School @ 120 Broad Meadow Road		G & H		None	
	WM. Mitchell School @ 187 Brookline Street		I & J		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
New Ashford	Town Hall @ 188 Mallery Road	00	01	No	Ramps	The ramp does not provide lower handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEW BEDFORD	Normandin Jr. High School @ Orleans Street	01	A & B	Yes	None	
	Campbell School @ Phillip Road and Morton Avenue		C & D	No	Entrances (Other than Locked)	The designated accessible entrances used for polling has an 8 inch step. No ramp or vertical access is provided.
					Exterior Accessible Route	The walkway, leading to the designated accessible entrance for polling, has a running slope measuring 7.8%.
	Mariners Health Center (Formerly Our Lady Fatima Parish @ 4254 Acushnet Avenue)		E & F	Yes	None	
	VFW Poirier Post @ 281 Appleton Street		G	No	Entrances (Other than Locked)	The hardware on the designated accessible entrance door is not operable with a closed fist. The hardware is a thumb latch.
					Lighting	There is no lighting provided along the accessible route from the parking to the designated accessible entrance used for polling.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) There are no access aisles provided adjacent to the standard designated accessible spaces. B) There are no signs provided at the heads of the standard designated accessible parking spaces.
					Ramps	The ramp does not provide handrails on either side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEW BEDFORD	Snhor Da Pedra Club @ 81 Tinkham Street	02	A & B	No	Ramps	The ramp provided at the designated accessible entrance used for polling: A) The running slope measures 9.5% at the bottom, 9.4% in the middle and 9.3% at the top. B) The left side of the ramp does not provided handrails. C) The handrails that are provided, are not round or oval. The handrails are a flat configuration.
	Saint Andrew's Parish House @ 169 Belleville Road				Entrances (Other than Locked)	The designated accessible entrance has a 6-inch step. There is no vertical access provided.
			C & G		On-Street Parking	There is no curb cut provided where the on-street designated accessible parking spaces is located.
	Wilk's Branch Library @ 1911 Acushnet Avenue				Entrances (Other than Locked)	The designated accessible entrance does not provide a level landing on the exterior of the door. The slope of the landing measures 9.1%.
		03	D & E		Ramps	The ramp provided: A) The running slope of the ramp measures 9.1% at the top. B) The ramp does not provided lower handrails.
	Taber Mill Community Room @ 217 Dean Street				None	
	Braz/Bean Community Center @ 360 Coggeshall Street		A	No	Entrances (Other than Locked)	The designated accessible entrance does not provided a 5-foot level landing on the exterior of the door. The slope of the landing measures 9.4%.
					Interior Accessible Route	The accessible route on the interior requires the use of an elevator. The elevator is not operable independently. It requires the assistance of others.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEW BEDFORD	Braz/Bean Community Center @ 360 Coggeshall Street	03	A	No	Ramps	The ramp: A) The running slope measures 9.4% at the top. B) The ramp does not provide handrails on either side.
	Holy Name of Sacred Heart @ Mt. Vernon Street		B & C		Entrances (Other than Locked)	The hardware on the designated accessible entrance door is not operable with a closed fist. The hardware is a thumb latch.
	Hillside Court @ 525 Coggeshall Street		D	Yes	None	
	High School @ 230 Hathaway Blvd		E		None	
	Bayberry Community Center @ 155 Oakdale Street		F		None	
	Water Department @ 1105 Shawmut Avenue		G	No	Entrances (Other than Locked)	The hardware on the designated accessible entrance door is not operable with a closed fist. The hardware is a door knob.
	Boa Vista @ 134 South Second Street	04	A	Yes	None	
	Carney Academy @ 247 Elm Street		B	No	Exterior Accessible Route	The walkway, leading to the designated accessible entrance, has a running slope measuring 9.8% at the bottom and 10.6% in the middle.
	New Bedford Hotel Apartments @ 725 Pleasant Street		C	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEW BEDFORD	Parker Street School @ 705 County Street	04	D & E	Yes	None	
	Caroline Street Community Center @ 26 Caroline Street		F		None	
	Boys and Girls Club @ 166 Jenney Street		G		None	
	Kennedy Youth Center @ 377 County Street	05	A & B	No	Changes in Level Along Accessible Route	There is a 6-inch curb to access the designated accessible entrance door. There is no vertical access provided.
	Moose Home @ 119 Rockdale Avenue		C	Yes	None	
	Hathaway School Gym @ Corner of Union and Tremont Street		D & F		None	
	Buttonwood Warming House @ Buttonwood Park		E & G	No	Entrances (Other than Locked)	The hardware on the designated accessible entrance door is not operable with a closed fist. The hardware is a door knob.
	Hazelwood Community Center @ Hazelwood Park	06	A & B	Yes	None	
	Tripp Towers @ 12 Ruth Street		C		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEW BEDFORD	Howland Green Library @ 3 Rodney French Blvd	06	D	No	Exterior Accessible Route	The path of travel, from the designated accessible parking to the designated accessible entrance, is reduced to less than 36 inches. There is a sign in the sidewalk that reduces the path of travel.
	Saint Martin's Parish House @ 138 Rivet Street		E		Entrances (Other than Locked)	The designated accessible entrance: A) The entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 23 inches wide. B) There is a 6 inch step at the rear of the landing to the entrance. C) There is no hardware provided on the exterior of the entrance door.
	Ashley Park Community Center @ Rivet and Bolton Street		F	Yes	None	
	Moose Home @ 119 Rockdale Avenue		G		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
New Braintree	Town Hall @ 20 Memorial Drive	00	01	No	Curb Cuts	1) The curb cut, located near the van accessible parking space, has a center running slope measuring 9.9%. 2) The curb cut, located near the 4 other accessible parking spaces, has a center running slope measuring 10.8%.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not provide a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
--------------	------------------	------	-------------	----------------------	--------------------	-----------------

New Marlborough

Town Hall

00

01

Yes

None

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
New Salem	Town Hall @ 15 South Main Street	00	01	No	Parking Spaces in Lot	The designated accessible parking space provided in the lot does not have an access aisle adjacent to the space. NOTE: The entire parking lot does not have any striping.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Newbury	Town Hall @ 25 High Road	00	01	No	Exterior Accessible Route	The walkway leading to the base of the ramp has a running slope measuring 8.3% and 8.2%.
					Parking Spaces in Lot	The designated accessible parking space provided in the parking lot: A) The space is not configured for a "van-accessible" space. The space only has a 5 foot access aisle. B) The space does not have a sign at the head of the space.
					Ramps	The ramp only provides the upper handrails, however the handrails are a 2X4 configuration and are not round or oval.
	Byfield Town Hall @ 7 Central Street		02		Exterior Accessible Route	The walkway leading to the base of the ramp has a running slope measuring 8.2%.
					Ramps	The ramp only provides the upper handrails, however, the handrails are a 2X4 configuration and are not round or oval.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEWBURYPORT	United Methodist Church @ Purchase Street	01	01	No	Entrances (Other than Locked)	The door to the designated accessible entrance used for polling has door hardware that is a door knob.
					Ramps	The ramp does not provide a lower handrail on the right side of the ramp.
	Parker River Wildlife OFC @ 261 Northern Blvd		P		Entrances (Other than Locked)	The designated accessible entrance used for polling: A) The clear opening provided at the door measures only 28 1/2 inches. B) The hardware on the door is a door knob. NOTE: During the survey, John explained that to get over the 6 inch step at the door, a portable ramp is installed.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
					Changes in Level Along Accessible Route	There is a change in level measuring 1 inch at the landing near the entrance door.
	Brown School @ Lime and Milk Street	02	01		Parking Spaces in Lot	The designated accessible parking space provided in the lot does not provide the access aisle the whole length of the space. The access aisle tapers to a point from the middle to the end.
	Hope Community Church	03		Yes	None	
		04			None	
		05			None	
		06			None	
	Bresnahan School @ 333 High Street					

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEWTON	Lincoln Eliot School @ 191 Pearl Street	01	01	Yes	None	
	Fire Station 1 @ 241 Church Street		02		None	
	Bigelow Middle School @ 42 Vernon Street		03		None	
	Pellegrini Playground @ 11 Hawthorn Street		04		None	
	Horace Mann School @ 687 Watertown Street	02	01	No	Entrances (Other than Locked)	The designated accessible entrance used for polling: A) The exterior of the door does not provide a 5-foot level landing. Currently there is a 4-foot landing provided. B) The hardware on the door is not operable with a closed fist.
	Cabot School @ 229 Cabot Street		02		Ramps	The ramp provided: A) The ramp measures 45 inches wide. B) The ramp does not provide a lower handrail on the left side.
	North High School @ 360 Lowell Avenue		03		Exterior Accessible Route	The path of travel is not "the same or substantially similar for all persons entering the polling place." Currently, someone needing to use the accessible entrance is required to travel 300 feet to the entrance.
					Ramps	The ramp provided only measures 44 inches wide, measured between the handrails.
	Community Senior Center @ 492 Waltham Street	03	01 & 03		Entrances (Other than Locked)	The designated accessible entrance provides a 5 foot landing on the exterior of the door. However, the landing has a slope measuring 3%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEWTON	Peirce School @ 170 Temple Street	03	02	No	Curb Cuts	The curb cut located near the designated accessible entrance has a center running slope measuring 12.0%.
					Ramps	The ramp does not provide lower handrails.
	Franklin School @ 125 Derby Street		04	Yes	None	
	Burr School @ 171 Pine Street	04	01 & 04		None	
	Hamilton Community Center @ 545 Grove Street		02		None	
	Williams School @ 141 Grove Street		03		None	
	Emerson Community Center @ 51 Pettee Street	05	01	No	Changes in Level Along Accessible Route	The curb cut, located along the accessible route from the parking to the designated accessible entrance, has a change in level at the base measuring 1-1/4 inches.
					Ramps	The ramp provided: A) The running slope for the ramp measures 10.2% at the top, 10.0% in the middle and 9.8% at the bottom. B) The ramp does not provide lower handrails.
	Hyde Community Center @ 90 Lincoln Street		02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEWTON	Zervas School @ 30 Beethovan Avenue	05	03 & 04	No	Ramps	The ramp provided: A) The running slope measures 9.8% at the top and 9.4% in the middle. B) The ramp measures 42 inches wide, measured between the handrails. C) The ramp does not provide a lowered handrail on the right side.
	Bowen School @ 280 Cypress Street	06	01	Yes	None	
	Weeks House @ 7 Hereward Road		02	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) There is a space that is configured as a van-accessible parking space, however, there is no "van-accessible" sign provided. B) The spaces do not have any signs at the head of each designated accessible space.
	Hyde Community Center @ 90 Lincoln Street		03	Yes	None	
	Mason Rice School @ 149 Pleasant Street		04	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) There are no access aisles provided adjacent to the spaces. B) Each designated accessible parking space does not have a sign in front. Currently there is only one sign for all of the spaces.
	Church of the Redeemer @ 379 Hammond Street	07	01		Entrances (Other than Locked)	The designated accessible entrance: A) The threshold measures 1-1/2 inches. B) The door hardware is not operable with a closed fist. Currently, the configuration is a door knob. C) The entrance only provides a 24 inch clear opening.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NEWTON	Bigelow Middle School @ 42 Vernon Street	07	02	Yes	None	
	Ward School @ 10 Dolphin Road		03 & 04		None	
	Oak Hill Middle School @ 130 Wheeler Road	08	01		None	
	Memorial-Spaulding School @ 250 Brookline Street		02	No	Curb Cuts	The curb cut, located near the ramp, has a center running slope measuring 9.8% at the top and 9.6% at the bottom.
	Countryside School @ 191 Dedham Street		03		Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) The parking spaces do not provide any access aisles adjacent to the spaces. B) One of the parking spaces is missing a sign at the head of the space.
	Shuman Community Center @ 675 Saw Mill Brook Parkway		04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Norfolk	H. Olive Day Auditorium @ 232 Main Street	00	01, 02, 03 & 04	No	Changes in Level Along Accessible Route	There is a change in level, at the top of the ramp used for entering, measuring 3/4 of an inch.
					Entrances (Other than Locked)	The threshold, for the entering door, measures 1 inch.
					Exterior Accessible Route	There is no curb cut provided to access the sidewalk that leads to the entrance.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
					Ramps	There are 2 ramps located at the designated accessible entrances. One for entering and one for exiting the polling area. A) The ramp used for entering: I) The running slope measures 9.0% at the top. II) There are no handrails provided on either side of the ramp. B) The ramp used for exiting does not provide handrails on either side of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NORTH ADAMS	Conte Middle School	01	01	No	Ramps	The ramp does not provide a lower handrail on the right side.
	Notre Dame Parish Center	02	02		Entrances (Other than Locked)	The designated accessible entrance for polling: a) The hardware on the door is a doorknob. b) The clear opening for the doors measure 27 inches.
					Ramps	The ramp provides only the lower handrail on one side.
	Ashland Park Apartments	03	03		Ramps	The ramp provides handrails on one side of the ramp, and only the top handrails.
	Greylock School	04	04		Entrances (Other than Locked)	The designated accessible entrance used for polling: a) The hardware on the door is a thumb latch. b) The doorway provides 27 inches of clear opening.
					Ramps	The ramp does not provide a bottom handrail on both sides.
	Saint Anthony's Parish Center	05	05		Entrances (Other than Locked)	The designated accessible entrance for polling: a) The door hardware is not accessible. b) The doorway does not provide a clear opening measuring 32 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
North Andover	North Andover Middle School @ 495 Main Street	00	01 & 02	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot: A) One space is missing a sign at the front of the space. B) The space configured as a van accessible space is missing the "van-accessible" sign.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a level area on the exterior of the door.
	Atkinson School @ 111 Philips Brook Road		03 & 04		Exterior Accessible Route	The walkway leading to the designated accessible entrance has a running slope measuring between 5.6% and 6.5%.
					Lighting	There is not sufficient lighting provided at this location.
					Parking Spaces in Lot	The designated accessible parking spaces do not have signs at the head of the spaces.
	Franklin School @ 2 Cypress Terrace		05 & 06		Directional Signage	There is no signage provided to indicate the location of the designated accessible entrance.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a level area on the exterior of the door.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
					Ramps	The ramp provided on the interior of the school: A) The handrail, provided on the right side of the ramp, as one goes up the ramp, is not continuous. **B) The ramp extends more than 30 feet without providing a level area.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
North Attleborough	Town Hall @ 43 South Washington Street	00	01	No	Parking Spaces in Lot	There are no access aisles adjacent to the designated accessible parking spaces provided.
	AMVET Blvd. School Auditorium @ 70 AMVET Blvd.		02	Yes	None	
	First United Methodist Church @ 20 Hoppin Hill Avenue		03 & 09		None	
	Middle School @ 564 Landry Avenue		04, 05, 06, 07 & 08	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing has a slope measuring between 6.1% and 7.3%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
North Brookfield	Senior Center @ 29 Forest Street	00	01	No	Entrances (Other than Locked)	The designated accessible entrance does not have a 5-foot level landing on the exterior of the door. The slope measures 5.7%.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
North Reading	High School @ 191 Park Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level at the top of the ramp, near the designated accessible entrance, measuring 1 /14 inches.
					Ramps	The ramp provided only provides one handrail.
	Town Hall Murphy Center @ 235 North Street		02		Changes in Level Along Accessible Route	There is a change in level, near the designated accessible entrance, that measures over 1/2 inch.
	Saint Theresa's Church @ 63 Winter Street		03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NORTHAMPTON	Jackson Street School @ 120 Jackson Street	01	A & B	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut located to the left of the driveway when leaving the "Bus" driveway, measuring 3/4 to 1 inch.
					Curb Cuts	1) The curb cut, located on the left of the driveway, when leaving the "Bus" driveway, has a center running slope measuring 17.8%.
						2) The curb cut, located on the left, as you enter, has a center running slope measuring 14.0%.
	Smith Vocational School @ 80 Locust Street	02			Parking Spaces in Lot	The designated accessible parking space configured as van accessible is missing the "van-accessible" sign.
					Parking Spaces in Lot	The designated accessible parking spaces provided: A) The space that is configured as van accessible is missing the "van-accessible" sign. B) There is a built up curb cut protruding into the access aisle.
	Walter Salvo House @ 81 Conz Street	03			Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut located to the right of the main entrance, measuring 3/4 of an inch.
					Curb Cuts	The curb cut, located to the right of the main entrance, has a center running slope measuring 13.3%.
	McDonald House @ 49 Old South Street	04			Parking Spaces in Lot	There is no van accessible parking space provided.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) The space configured as van accessible is missing the "van-accessible" sign. B) There is no sign provided at the head of one of the two spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
NORTHAMPTON	Florence Civic Center @ 90 Park Street	05	A	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided near the designated accessible entrance.
					Ramps	The ramp has a running slope measuring 11.3% at the top of the 1st run up.
	Smith Vocational School @ 80 Locust Street		B		Parking Spaces in Lot	The designated accessible parking spaces provided: A) The space that is configured as van accessible is missing the "van-accessible" sign. B) There is a built up curb cut protruding into the access aisle.
	Ryan Road School @ 498 Ryan Road	06	A & B	Yes	None	
	J. F. Kennedy Middle School @ 100 Bridge Street	07	A		None	
	Leeds School @ 20 Florence Street		B	No	Changes in Level Along Accessible Route	There are changes in level, along the walkway, leading to the entrance, measuring 3/4 to 1 inch.
					Exterior Accessible Route	The walkway, leading to the entrance, has a slope measuring 18.4%.
					Parking Spaces in Lot	There is no van accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Northborough	Proctor School @ 26 Jefferson Road	00	01	Yes	None	
	Lincoln Street School @ 76 Lincoln Street		02	No	Entrances (Other than Locked)	The designated accessible entrance door only provides a 27 inch clear opening.
	Peaslee School @ 31 Maple Street		03	Yes	None	
	Marion Zeh School @ 33 Howard Street		04		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Northbridge	Middle School @ 171 Linwood Avenue	00	01	Yes	None	
	American Legion Post @ 118 Church Avenue		02	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) The van accessible space that is correctly configured, does not provide a "van-accessible" sign. B) There are 2 designated accessible parking spaces that do not provide an access aisle adjacent to the space.
	Balmer School @ 21 Crescent Street		03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Northfield	Town Hall @ 69 Main Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Norton	High School @ 66 West Main Street	00	01 & 02	Yes	None	
	Henri Yelle Elementary School @ 64 West Main Street		03, 04 & 05		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Norwell	Cole School District @ 81 High Street	00	01	No	Curb Cuts	The curb cut, located across from the van accessible parking space, close to the entrance, has a center running slope measuring 9.6%.
	Goldman School District @ 328 Main Street		02		Curb Cuts	The curb cut, located across from the designated accessible parking spaces, has a center running slope measuring 10.0%.
	Vinal School District @ 102 Old Oaken Bucket Road		03		Curb Cuts	The curb cut, located across from the parking, on the entrance side, has a center running slope measuring 11.2%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Norwood	Oldham School @ 165 Prospect Street	00	01 & 02	No	Ramps	The ramp provided has a center running slope measuring 9.1%.
	Civic Center @ 165 Nahatan Street		03 & 05	Yes	None	
	Cleveland School @ 33 George Willett Parkway		04		None	
	Balch School @ 1168 Washington Street		06 & 07		None	
	Callahan School @ 90 Garfield Avenue		08	No	Entrances (Other than Locked)	The designated accessible entrance has hardware that is a doorknob.
					Parking Spaces in Lot	The designated accessible parking spaces in the lot: A) No van accessible parking space is provided. B) One of the designated spaces is missing a sign at the head of the space.
	Prescott School @ 66 Richland Road		09	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Oak Bluffs	Oak Bluffs School @ Tradewinds Road	00	01	No	Parking Spaces in Lot	There is one designated accessible parking space provided. A) The space is not a van accessible space. The access aisle measures 4 1/2 feet wide. B) The access aisle abuts a sidewalk. There is no curb cut provided.
					Ramps	The ramp provided: A) The running slope of the ramp measures 10.4%. B) There are no handrails provided on either side of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Oakham	Town Hall Voting Room @ 2 Coldbrook Road	00	01	No	Parking Spaces in Lot	The designated accessible parking space provided: A) There is no van accessible parking space provided. The access aisle is a triangle, measuring 4 feet narrowing to 3 feet in width. B) There is no sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Orange	Armory @ 135 East Main Street	00	01 & 02	No	Parking Spaces in Lot	There is no van accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Orleans	American Legion Hall @ Main Street	00	01 & 02	No	Interior Doors	The door, for precinct 2, provides only 30 inches of clear opening.
					Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) There is no sign at the head of the left most designated accessible parking space.
					Ramps	The ramp provided: A) The running slope of the ramp measures 9.4% at the top and bottom. B) The handrails are not round or oval. The handrails are a 2x4 configuration.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Otis	Town Hall	00	01	No	Directional Signage	There is no directional signage provided indicating the location of the designated accessible entrance for polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Oxford	Alfred Chaffee School @ 9 Clover Street	00	01 & 04	Yes	None	
	Middle School @ 497 Main Street		02		None	
	Town Hall @ 325 Main Street		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Palmer	Palmer Town Building @ 417 Main Street	00	01	No	Directional Signage	There are no signs indicating the location of the designated accessible entrance for polling.
					Ramps	The ramp: a) The ramp measures less than 48 inches wide. b) The running slope at the top of the ramp measures 9.2%. c) The ramp has handrails on the right side only. However, the right side handrails are broken and in disrepair.
	Converse Middle School		02 & 03	Yes	None	
	SS Peter and Paul Parish Center		04	No	Changes in Level Along Accessible Route	There is a 1-inch change in level along the walkway leading to the entrance.
					Parking Spaces in Lot	The designated accessible parking space provided does not provide a sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Paxton	Center School @ 19 West Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
PEABODY	Saint Ann's Church @ 140 Lynn Street	01	01 & 03	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. Currently, only 52 inches is provided.
					Ramps	1) The ramp provide on the exterior of the building: A) Handrails are not provided on both sides of the ramp. B) The ramp measures 46 inches wide, measured between the handrails. 2) The ramp provided on the interior of the building: A) The ramp measures 43 inches wide, measured between the handrails. B) The running slope of the ramp measures 8.8%.
	Rockdale Park Community Hall @ 15 Rockdale Park	02			Changes in Level Along Accessible Route	There are changes in level, along the path of travel from the designated accessible parking to the designated accessible entrance, measuring greater than 1/2 inch.
					Entrances (Other than Locked)	The designated accessible entrance: A) The hardware on the door is not operable with a closed fist. B) There is no 5-foot landing provide on the exterior of the entrance door. Currently, on 56 inches is provided.
					Exterior Accessible Route	The path of travel is not the "same or substantially similar for all persons entering the polling place". The designated accessible entrance is located at the rear of the building, while the main entrance is at the front.
	Welch School @ 50 Swampscott Avenue	02	01 & 02		Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
					Changes in Level Along Accessible Route	There is a change in level, where the sidewalk meets the concrete pad in front of the entrance, measuring 2 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
PEABODY	Welch School @ 50 Swampscott Avenue	02	01 & 02	No	Curb Cuts	The curb cut, located along the path of travel from the designated accessible parking to the designated accessible entrance, has a center running slope measuring 14.2%.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. The space that is configured as a van accessible parking space is missing the two signs that are required at the head of the space.
	South Memorial School @ 16 Maple Street Extension		03		Changes in Level Along Accessible Route	There is a change in level, at the transition from the parking area to the ramp, measuring 1 inch.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. Currently, there is only 4 feet 6 inches.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
	Our Lady of Fatima Church @ 50 Walsh Avenue	03	01 & 02		Ramps	The ramp provided: A) The running slope of the ramp measures 9.1% to 9.8%. B) The right side of the ramp only provides a lower handrail.
					Parking Spaces in Lot	The designated accessible parking spaces do not have signs at the head of the spaces.
					Changes in Level Along Accessible Route	There are changes in level along the accessible path of travel from the parking to the entrance that measure greater than 1/2 inch.
	Wilson Terrace Community Hall @ 15A Wilson Terrace		03		Entrances (Other than Locked)	The designated accessible entrance does not provide door hardware that is operable with a closed fist.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
PEABODY	Wilson Terrace Community Hall @ 15A Wilson Terrace	03	03	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
		04	01 & 02		Changes in Level Along Accessible Route	There is a change in level, where the ramp meets the street, measuring 2 inches.
					Entrances (Other than Locked)	The designated accessible entrance door provides on 27 inches of clear opening.
					Parking Spaces in Lot	The designated accessible parking spaces do not provide signs at the head of the spaces.
	High School @ 485 Lowell Street		03		Ramps	The ramp does not provide any handrails.
					Changes in Level Along Accessible Route	There are changes in level, along the accessible path of travel from the parking to the entrance, measuring more than 1/2 inch.
					Exterior Accessible Route	The walkway, from the parking exceeds 5%.
	Kiley School @ 21 Johnson Street	05	01 & 02		Changes in Level Along Accessible Route	1) There are changes in level, along the accessible path of travel from the parking to the entrance, measuring more than 1/2 inch.
						2) There are changes in level along the ramp that measure greater than 1/2 inch due to disrepair.
					Directional Signage	There is no directional signage provided to indicated where the designated accessible entrance is located.
					Entrances (Other than Locked)	The designated accessible entrance: A) There is no 5-foot level landing provided on the exterior of the doors. B) The entrance is a set of double doors. Opened individually, each door provides 28 inches of clear opening.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
PEABODY	Kiley School @ 21 Johnson Street	05	01 & 02	No	Interior Doors	There is a set of double doors on the interior of the building. Opened individually, there is only 28 inches of clear opening provided.
						NOTE: During the survey, it was stated that the doors would remain open during polling.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) The spaces do not provide signs at the head of the spaces. B) No access aisles are provided adjacent to the spaces.
	McCarthy School @ 76 Lake Street	06	01		Ramps	The ramp has running slopes that measure 11.2%.
					Parking Spaces in Lot	The access aisles, for the standard designated accessible parking spaces, measure 3 feet 8 inches wide.
					Changes in Level Along Accessible Route	There are changes in level, along the accessible path of travel from the parking to the entrance, measuring more than 1/2 inch.
	West Memorial School @ 15 Bow Street				Entrances (Other than Locked)	The designated accessible entrance door does not provide 32 inches of clear opening.
					Parking Spaces in Lot	The designated accessible parking spaces do not provide signs at the head of the spaces.
					Ramps	The ramp provided at the entrance: A) The running slope measures 13.6%. B) The ramp does not measure 48 inches wide. C) The ramp does not provide any handrails.
	Burke School @ 127 Birch Street		02 & 03		Changes in Level Along Accessible Route	There are changes in level, along the accessible path of travel from the parking to the entrance, measuring more than 1/2 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
PEABODY	Burke School @ 127 Birch Street	06	02 & 03	No	Curb Cuts	There is a built up curb ramp that has a center running slope measuring 11.5% to 12.4%.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Pelham	Community Center @ 2 South Valley Road (Formerly @ the Elementary School)	00	01	No	Curb Cuts	The curb cut, at the head of the access aisle, has a center running slope measuring 9.3%.
					Parking Spaces in Lot	The designated accessible parking space, that is configured as a van accessible space, does not have a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Pembroke	Town Hall @ 100 Center Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the beginning of the entrance walkway, measuring 1 to 1 1/2 inches.
	Hobomock Elementary School @ 95 Learning Lane		02 & 04		Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the sign at the head of the space as well as the "van-accessible" sign.
	Bryantville Elementary School @ Gurney Lane		03		Parking Spaces in Lot	There are no designated accessible parking spaces located near the designated accessible entrance. NOTE: During the survey, it was discussed that temporary spaces be provided near the curb cut at the entrance.
	North Pembroke Elementary School @ 74 Pilgrim Road		05		Parking Spaces in Lot	There is no van accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Pepperell	Varnum Brook Elementary School @ 10 Hollis Street	00	01, 02 & 03	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Peru	Community Center @ 3 East Main Road	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Petersham	Town Hall @ 3 South Main Street	00	01	No	Entrances (Other than Locked)	The designated accessible entrance does not have door hardware that is operable with a closed fist. Currently a door knob is provided.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. Neither of the spaces provides an access aisle adjacent to the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Phillipston	Town Hall @ 50 on the Common	00	01	No	Ramps	The ramp provided: A) The running slope of the ramp measures 9.0% - 10.0% at the bottom. B) The handrails are not round or oval. Currently, they are a 2x4 configuration.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
PITTSFIELD	Reid Middle School @ 950 North Street	01	A & B	No	Parking Spaces in Lot	The designated "van-accessible" parking space provided in the parking lot is missing the "van-accessible" sign.
	Morningside School @ 100 Burbank Street	02	A	Yes	None	
	Somerset Fire Station @ 9 Somerset Avenue		B		None	
	Providence Court @ 379 East Street	03	A		None	
	All Souls Church @ 51 Pembroke Avenue		B		None	
	Herberg Middle School @ 501 Pomeroy Avenue	04	A		None	
	Williams School @ 50 Bushey Road		B		None	
	Saint Teresa Parish Center @ 290 South Street	05	A		None	
	Fire Station @ 311 West Housatonic Street		B	No	Changes in Level Along Accessible Route	There is a 4 inch change in level along the path of travel to the designated accessible entrance used for polling.
					Entrances (Other than Locked)	The hardware on the door for the designated accessible entrance is a doorknob.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
PITTSFIELD	Columbus Arms Housing @ 65 Columbus Avenue	06	A	Yes	None	
	Conte Community School @ 200 West Union Street		B	No	Parking Spaces in Lot	The parking lot provided can accommodate around 101-150 cars. The parking lot does not provide any striping for parking spaces. The designated accessible parking spaces are not striped. There needs to be 5 designated accessible parking spaces, with one "van-accessible" space. NOTE: There is a designated on-street accessible parking space provided.
	Pecks Road Fire Station @ 54 Pecks Road	07	A		Entrances (Other than Locked)	The hardware on the designated accessible entrance used for polling is a doorknob.
	Capeless Elementary School @ 86 Brooks Avenue		B	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Plainfield	Town Hall @ 344 Main Street	00	01	No	Entrances (Other than Locked)	There are 2 entrances used during polling. The kitchen entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 4.0%.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the small parking lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Plainville	Beatrice Wood School @ 200 South Street	00	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Plymouth	Hedge Elementary School @ 258 Standish Avenue	00	01	No	Parking Spaces in Lot	There is one designated accessible parking space provided. A) No access aisle is provided adjacent to the space. B) The sign is located at the head of the space, however it is blocked and unviewable because of an overgrown bush.
					Ramps	The lower handrails on the ramp are not round or oval. The handrails are a 2x4 configuration.
	Cold Spring Elementary School @ 25 Alden Street		02		Changes in Level Along Accessible Route	1) There are changes in level, along the walkway leading to the entrance, measuring greater than 1/2 inch. 2) There is a change in level, at the entrance, measuring 2 inches.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing has a slope measuring 6.6%.
					Exterior Accessible Route	The walkway, leading to the accessible entrance, narrows to less than 36 inches. The walkway narrows to 24 inches in some locations.
					Parking Spaces in Lot	There is one designated accessible parking space provided. There is no access aisle adjacent to the space.
	Town Hall @ 11 Lincoln Street		03		Parking Spaces in Lot	There are 2 designated accessible parking spaces provided, 2 in the right side lot and 2 in the left side lot. 1) The right side lot: A) There is no van accessible parking space provided. The access aisle measures 6 feet wide. 2) The left side lot: A) There is no van accessible parking space provided. The access aisle measures 6 feet wide. B) The left side space, does not have a sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Plymouth	Town Hall @ 11 Lincoln Street	00	03	No	Ramps	There are 2 ramps leading to the designated accessible entrance. A) The right side ramp, when facing the entrance, has a running slope measuring 9.4% at the top. B) The left side ramp, when facing the entrance, has a running slope measuring 10.4% in the middle.
	North High School @ 41 Obery Street		04		Changes in Level Along Accessible Route	1) There is a change in level, near the entrance doors, measuring 1 to 2 inches. 2) There is a change in level, at the curb cut near the parking, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	There are 4 designated accessible parking spaces provided. A) There are no access aisles provided adjacent to any of the 4 spaces. B) There is no curb cut to access the sidewalk that the spaces abut.
	Intermediate School @ 117 Long Pond Road		05		Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) There is no access aisle provided adjacent to one space. B) The space that is configured as van accessible is missing the "van-accessible" sign.
	Manomet Elementary School @ 70 Manomet Point Road		06		Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	Indian Brook School @ 1181 State Road		07 & 14		Curb Cuts	1) The built up curb ramp, in the access aisle of the left side parking space, has a center running slope measuring 11.6% at the bottom and 9.3% at the top. 1) The built up curb ramp, in the access aisle of the right side parking space, has a center running slope measuring 9.8% at the bottom.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Plymouth	Indian Brook School @ 1181 State Road	00	07 & 14	No	Parking Spaces in Lot	The designated accessible parking spaces provided: A) There is no van accessible parking space provided. B) The curb cuts, one for each space, are built up curb ramps that project into the access aisles.
	Cedarville Fire Station @ 2209 State Road		08	Yes	None	
	South Elementary School @ 178 Bourne Road		09	No	Parking Spaces in Lot	There are 5 designated accessible parking spaces provided. A) The space configured as van accessible is missing the "van-accessible" sign. B) There are no signs at the head of 4 of the 5 spaces.
	Federal Furnace School @ 860 Federal Furnace Road		10		Curb Cuts	The built up curb ramp, that projects into the left side parking access aisle, has a center running slope measuring 9.9%.
					Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) There is no van accessible space provided. B) There are no signs at the head of 2 of the 3 spaces. C) There are 2 built up curb ramps that project into the access aisles for the 3 spaces.
	Municipal Airport @ 246 South Meadow Road		11		Entrances (Other than Locked)	The designated accessible entrance does not have door hardware that is operable with a closed fist. The door hardware provided is a door knob.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) The space that is configured as van accessible is missing the "van-accessible" sign. B) There is no sign at the head of one of the two spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Plymouth	South High School @ 490 Long Pond Road	00	12	No	Changes in Level Along Accessible Route	1) There is a change in level, at the base of the curb cut near the gym entrance, measuring 3/4 to 1 inch. 2) There is a change in level, at the curb cut near the main entrance, measuring 2 to 3 inches.
					Parking Spaces in Lot	1) There are 3 designated accessible parking spaces provided at the Gym Entrance. A) There is no van accessible parking space provided. B) There is no sign at the head of one of the spaces. 2) There are 3 designated accessible parking spaces provided at the Main Entrance. A) There is no sign at the head of 2 of the spaces.
	West Elementary School @ 170 Plympton Road		13		Changes in Level Along Accessible Route	There is a change in level, at the top of the built up curb ramp, measuring 3/4 to 1 inch.
					Curb Cuts	There is a built up curb cut to access the sidewalk from the driveway. The center running slope measures 13.7% at the bottom and 10.5% at the top.
					Parking Spaces in Lot	There is no access aisle adjacent to the designated accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Plympton	Town House @ 5 Palmer Road	00	01	No	Parking Spaces in Lot	There is one designated accessible parking space provided. There are two 4-foot access aisles on each side of the space. NOTE: To be a van-accessible parking space, the adjacent access aisle needs to be 8 feet wide, located to one side of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Princeton	Town Hall Annex @ 4 Town Hall Drive	00	01	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a level area on the exterior of the door.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Provincetown	Town Hall @ 260 Commercial Street	00	01	No	Parking Spaces in Lot	<p>There are 2 designated accessible parking spaces provided near the entrance. The spaces measure 10 feet wide, sharing a 4 foot access aisle. This configuration is not van accessible.</p> <p>NOTE: During the survey, it was discussed that restriping the spaces, so there are 2 8-foot wide spaces sharing an 8-foot wide access aisle would correct the issue.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
QUINCY	Merrymount School @ 4 Agawam Road	01	01	Yes	None	
	Snug Harbor School @ 330 Palmer Street		02	No	Entrances (Other than Locked)	The designated accessible entrance does not have door hardware that is operable with a closed fist. Currently there is a door knob.
	Thomas Crane Library @ 40 Washington Street		03	Yes	None	
	Adams Shore Library @ Sea Street		04	No	Changes in Level Along Accessible Route	There are three changes in level measuring 3/4 of an inch along the walkway leading to the designated accessible entrance.
	Saint Thomas Aquinas Hall @ Darrow Street		05		Ramps	The handrails for the ramp run only 9 feet of the 12 foot ramp.
	Fore River Club House @ 16 Nevada Road	02	01	Yes	None	
	Senior Citizens Housing @ 1000 Southern Artery		02		None	
	Martensen Street Housing @ 95 Martensen Street		03		None	
	Saint John' Church @ 44 School Street		04 & 05		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
QUINCY	Covenant Congregational Church @ 315 Whitwell Street	03	01	Yes	None	
	First Baptist Church @ 81 Prospect Avenue		02	No	Entrances (Other than Locked)	<p>The designated accessible entrance:</p> <p>A) The door hardware is not operable with a closed fist. Currently a door knob is provided.</p> <p>B) The door provides 27 inches of clear opening.</p> <p>C) There is no 5-foot level area provided on the exterior of the door.</p> <p>D) The entrance has an 8 inch step.</p> <p>NOTE: During the visit, it was stated that there was a portable ramp that is used during polling. I was unable to see the portable ramp at the time of the site survey.</p>
	Montclair School @ 8 Belmont Street		03		Entrances (Other than Locked)	<p>The designated accessible entrance:</p> <p>A) The threshold measures 4 inches.</p> <p>B) The door provides a clear opening of 28 inches.</p>
	Wollaston School @ 205 Beale Street		04 & 05		Exterior Accessible Route	The accessible route to the designated accessible entrance is along a walkway. There is no curb cut provided to gain access to the walkway. Currently the only way on to the walkway is by using the driveway.
	Lincoln Hancock School @ Water Street	04	01 & 04	Yes	None	
	Quincy Lodge of Elks @ 254R Quarry Street		02 & 03	No	Parking Spaces in Lot	There is a designated accessible parking space that is configured as a van accessible space. However, there is no "van-accessible" sign provided.
					Ramps	The ramp does not provide a round or oval top handrail. Currently it is a flat configuration.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
QUINCY	Morrisette Post- Legion @ 81 Liberty Street	04	05	Yes	None	
	Charles Bernazzani School @ 701 Furnace Brook Parkway	05	01		None	
	Quincy Methodist Church @ 40 Beale Street		02 & 03		None	
	Beechwood Knoll School @ 225 Fenno Street		04 & 05		None	
	North Quincy High School @ 318 Hancock Street	06	01	No	Exterior Accessible Route	The path of travel is not the "same or substantially similar for all persons entering the polling place". The curb cut to access the entrance is 400 feet away.
	Sacred Heart School @ Glover Avenue		02	Yes	None	
	Beechwood Center @ 440 East Squantum Street		03		None	
	Atlantic Middle School @ 86 Hollis Avenue		04		None	
	Squantum School @ 50 Huckins Avenue		05		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Randolph	Senior Center @ Fencourt Avenue	00	01	No	Entrance Locked	There are 2 entrances used for polling. The rear entrance does not provide hardware on the exterior of the door.
					Parking Spaces in Lot	There are 2 entrances used for this polling location. A) There are 3 designated accessible parking spaces provided for the front entrance. There is no van accessible parking space provided. B) There are no designated accessible parking spaces provided in the rear.
						NOTE: During the survey, it was discussed that temporary accessible parking spaces are provided in the rear during polling.
	High School @ Memorial Parkway		02 & 03		Ramps	The ramp, to the front entrance, has a running slope measuring 9.6% in the middle.
					Changes in Level Along Accessible Route	There are changes in level, at the base of the 3 curb cuts provided at the parking, measuring 3/4 to 1 inch.
					Curb Cuts	1) The curb cut, located to the left most of the parking spaces, has a center running slope measuring 11.4%. 2) The curb cut, located in the middle of the parking spaces, has a center running slope measuring 11.9%.
	Tower Hill School @ Adams Street		04		Parking Spaces in Lot	There are 6 designated accessible parking spaces provided. A) There are no access aisles provided for 5 of the spaces. B) The space that is configured as van accessible is missing the "van-accessible" sign. C) There are no signs at the head of 3 of the spaces.
					Entrances (Other than Locked)	The designated accessible entrance used for polling does not provide accessible hardware on the exterior of the door.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Randolph	Tower Hill School @ Adams Street	00	04	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.
						NOTE: During the survey, it was discussed that temporary accessible parking spaces would be provided.
	Lyons School @ Vesey Road		05 & 06		Entrances (Other than Locked)	The designated accessible entrance does not have a 5-foot level landing on the exterior of the door. The slope of the landing measures 4.5%.
					Exterior Accessible Route	The walkway, leading to the designated accessible entrance, has a running slope measuring 8.4% at the bottom.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) There is no van accessible parking space. B) The access aisles, adjacent to the spaces, measure 3 1/2 feet wide. C) There are no signs located at the head of each space.
	Donovan School @ Reed Street		07		Changes in Level Along Accessible Route	There is a change in level, at the end of the walkway leading to the entrance, measuring 2 inches.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) There is no sign at the head of one of the spaces.
	Devine School @ Old Street		08		Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 3/4 to 1 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Raynham	Merrill School @ 687 Pleasant Street	00	01 & 03	No	Entrances (Other than Locked)	The entrance, to precinct 3, does not provide hardware on the exterior of the door.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	Senior Center @ 2215 King Philip Street		02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Reading	Hawkes Field House @ 62 Oakland Road	00	01, 02, 03, 04, 05, 06, 07 & 08	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Rehoboth	Town Hall	00	01	No	Parking Spaces in Lot	The "van-accessible" sign is missing from the designated Van space.
	Palmer River School		02	Yes	**Comments	**There is no level area at the bottom of the ramp leading to the entrance.
	South Fire Station		03	No	Parking Spaces in Lot	The "van-accessible" sign is missing from the designated Van space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
REVERE	YMCA @ 1 Donnelly Square	01	01	Yes	None	
	Alfred Liston Towers @ 45 Dolphin Avenue		02	No	Ramps	The ramp provided has handrails. A) The handrails provided are a 2X8 configuration. B) There are no bottom handrails provided on either side of the ramp.
	Youth Center @ 150 Beach Street		03	Yes	None	
	Garfield Magnet School @ 144 Garfield Avenue	02	01		None	
	Carl Hyman Towers @ 50 Walnut Avenue		02 & 03A		None	
	Abraham School @ Malden Street	03	01 & 02		None	
	Saint Anthony's Church @ 250 Revere Street (Formally at Paul Revere School)		03		None	
	Legion Building @ 249 Broadway	04	01		None	
	Central Fire Station @ 400 Broadway		02		None	
	Lighthouse Nursing Care @ 204 Proctor Avenue		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
REVERE	Point of Pines Fire Station @ 140 Lynnway	05	01	Yes	None	
	Jack Satter House @ 420 Boulevard		01A & 02		None	
	Freeman Fire Station @ 2 Freeman Street		02A		None	
	Revere High School @ 101 School Street		03		None	
	Whelan School @ 107 Newhall Street	06	01 & 02		None	
	ITAM Post #17 @ 61 Lucia Street		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Richmond	Town Hall	00	01	No	Entrance Locked	The designated accessible entrance used for polling is locked.
					Entrances (Other than Locked)	The designated accessible entrance used for polling: a) The hardware on the door is a doorknob. b) To enter, one is required to use the buzzer and wait for assistance.
					Ramps	The ramp provided has openings measuring 1 inch wide by 3 inches long. These openings are along the entire length of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Rochester	Senior Center @ 67 Dexter's Lane	00	01	No	Parking Spaces in Lot	There are 4 designated accessible parking spaces provided. A) There are no access aisles provided adjacent to 2 of the spaces. B) There are no signs provided at the head of the 4 spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Rockland	High School @ 52 MacKinlay Way	00	01, 02, 03 & 04	No	Changes in Level Along Accessible Route	There are changes in level, along the walkway to the entrance, measuring 3/4 to 1 1/2 inches.
					Curb Cuts	The curb cut, located at the sidewalk to access the entrance, has a center running slope measuring 15.3%.
					Entrances (Other than Locked)	There is a set of 2 double doors at the designated accessible entrance. Opened individually, each door provides 27 inches of clear opening.
	R. Stewart Esten School @ 733 Summer Street		05 & 06		Exterior Accessible Route	The walkway, leading to the entrance, has a running slope measuring 7.5% at the bottom, 9.7% in the middle and 6.5% at the top.
					Parking Spaces in Lot	The designated accessible parking spaces provided: A) There is no van accessible parking space provided. B) There is no sign provided at the head of one of the spaces.
					Ramps	The ramp has a running slope measuring 9.2% at the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Rockport	Pigeon Cove Circle @ Breakwater Avenue	00	01	No	Entrances (Other than Locked)	The designated accessible entrance does not have a level landing provided on the exterior of the door. Currently the ramp slopes right to the door.
					Ramps	The ramp provides handrails only on one side of the ramp.
	Saint Mary's Church @ Broadway		02	Yes	None	
	School Complex @ Jerden's Lane		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Rowe	Town Hall @ 321 Zoar Road	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	There is no access aisle provided adjacent to the designated accessible parking space.
					Ramps	<p>The ramp provided:</p> <p>A) The running slope of the ramp measures 9.0% at the top, 9.2% in the middle and 9.0% at the bottom.</p> <p>B) The right side handrail, when one is going up the ramp, does not extend the entire length of the ramp.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Rowley	Saint Mary's Church Hall @ 206 Main Street	00	01	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the parking lot are not striped. NOTE: None of the parking spaces in the lot are striped.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Royalston	Town Hall @ The Common	00	01	No	Accessible Shelf	There is no lowered shelf provided.
					Changes in Level Along Accessible Route	There are change in level, along the accessible route across the driveway, measuring 3/4 - 1-1/2 inches.
					Entrances (Other than Locked)	The designated accessible entrance: A) The hardware on the door is not operable with a closed fist. There is a door knob provided. B) The threshold of the door measures 1 inch.
	Whitney Hall @ School Street		02		Ramps	The running slope of the ramp measures 10.9% in the middle and 11.0 at the top.
					Accessible Shelf	There is no lowered shelf provided.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. Only 4-feet are provided.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
						NOTE: During the survey, it was explained that temporary spaces are provided during polling.
					Ramps	The ramp is only 38 inches wide, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Russell	Town Hall @ 65 Main Street	00	01	No	Exterior Accessible Route	There is a strip of marble, where the landing for the entrance and walkway meet, with a running slope measuring 16.2%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Rutland	Naquag Elementary School @ 285 Main Street	00	01	Yes	None	
	Public Library @ 280 Main Street		02	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not provide a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SALEM	Bentley School @ Memorial Drive	01	01	No	Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) There is only one sign for all 3 spaces. B) The sign is at a height of 4 feet 6 inches to the top.
	Recreation Room @ 27 Charter Street		02	Yes	None	
	Bentley School @ Memorial Drive	02	01	No	Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) There is only one sign for all 3 spaces. B) The sign is at a height of 4 feet 6 inches to the top.
	Recreation Room @ 12 Pope Street		02	Yes	None	
	Council on Aging @ 5 Broad Street	03	01	No	Ramps	The lower handrail, on the ramp, does not run the entire length of the ramp.
	Saint Ann's School @ 9 Cleveland Street		02	Yes	None	
	Endicott School @ 112 Boston Street	04	01		None	
	Princeton Crossing @ 12 Heritage Drive		02		None	
	Temple Shalom @ 287 Lafayette Street	05	01	No	Ramps	The portable ramp provided has a running slope estimated around 11 - 12%. (28 inches of rise: 240 inches of run).
	Community Room @ Pioneer Terrace		02	Yes	None	
	Bates School @ Liberty Hill Avenue	06	01		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SALEM	Recreation Department @ Mack Park	06	02	Yes	None	
	Fire Station @ 64 Loring Avenue	07	01		None	
	Salem State Gymnasium @ Harrison Road		02	No	Entrances (Other than Locked)	The gymnasium doors do not provide accessible door hardware on the exterior. NOTE: During the survey, it was explained that the doors remain open during polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Salisbury	Hilton Senior Center @ 39 - 41 Lafayette Road	00	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sandisfield	Town Hall @ 3 Silverbrook Road	00	01	No	Entrances (Other than Locked)	The designated accessible entrance (at the rear of the building): A) The entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 36 inches. B) The hardware on the exterior of the entrance door is not operable with a closed fist. The door hardware is a Thumb latch.
					Ramps	The ramp provided: A) The ramp, as estimated in the photograph, measures 36 inches wide, measured between the handrails. B) The right side of the ramp does not provide handrails. C) The upper handrails, provided on the left side of the ramp, are not round or oval. The upper handrail provided is flat. D) The slope of the ramp, as estimated in the photograph provided, exceeds a 1:12 (8.33%) slope.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sandwich	Henry Wing School @ Route 130 and Beale Avenue	00	01 & 02	No	Changes in Level Along Accessible Route	There is a change in level, along the exterior ramp, measuring 3/4 to 1 1/2 inches.
					Curb Cuts	The curb cut, located at the head of the access aisle at the parking, has a center running slope measuring 12.6%.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	High School @ Quaker Meetinghouse Road	03			Ramps	1) The exterior ramp provided: A) The running slope of the ramp measures 10.3% in the middle and 9.0% at the top. B) There are no handrails provided on the right side of the ramp. 2) The interior ramp provided: A) The running slope of the ramp measures 9.6% at the bottom and 10.8% at the top.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 5.7%.
					Exterior Accessible Route	The walkway, leading to the entrance doors, has running slopes measuring 6.9% at the bottom and 8.4% at the top.
	Oak Ridge School @ Quaker Meetinghouse Road		04 & 05		Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) There are no access aisles provided adjacent to the 3 spaces.
					Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut near the parking, measuring 3/4 to 1 1/2 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sandwich	Oak Ridge School @ Quaker Meetinghouse Road	00	04 & 05	No	Parking Spaces in Lot	There is no access aisle provided adjacent to the designated accessible parking space.
					Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut near the parking, measuring 1 to 1 1/2 inches.
	Forestdale School @ Route 130		06 & 07		Parking Spaces in Lot	There is no access aisle provided adjacent to the designated accessible parking space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Saugus	American Legion Hall @ Taylor Street	00	01	No	Changes in Level Along Accessible Route	There are changes in level measuring 3/4 to 1 inch near the designated accessible parking spaces and the ramp.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) The spaces are missing the adjacent access aisles. B) There is no van accessible parking space provided.
					Ramps	The ramp provided has a running slope measuring 9.0% at the top of the first run up.
	Veteran's School @ Hurd Avenue		02 & 06		Parking Spaces in Lot	The designated accessible parking space configured as a van-accessible space only provides a 7 foot 5 inch access aisle.
	Hammersmith Nursing Home @ Chestnut Street		03		Curb Cuts	The curb cut, located across from the designated accessible parking spaces, has a center running slope measuring 11.7% at the bottom and 11.2% at the top.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) The spaces do not provide any access aisles adjacent to the spaces. B) No van-accessible parking space is provided.
	Belmonte Middle School @ Dow Street		04 & 08		Parking Spaces in Lot	The designated accessible parking spaces do not have an access aisle adjacent to the spaces.
	Lynnhurst School @ Elm Street		05		Parking Spaces in Lot	The designated accessible parking space that is indicated to be "van-accessible" does not provide an adjacent access aisle.
	Knights of Columbus @ 1 K of C Drive		07		Ramps	The running slope of the ramp exceeds 8.33%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Saugus	Oaklandvale School @ Main Street	00	09	No	Entrances (Other than Locked)	The designated accessible entrance has a threshold that measures 1 /14 inches.
					Parking Spaces in Lot	During times of elections a recess lot is used. Currently, there are no designated accessible parking space provided. NOTE: During the survey, Jean explained that temporary spaces are provided.
	Italian American Club @ 1 Beachview Avenue		10		Exterior Accessible Route	The walkway leading to the designated accessible entrance has running slopes measuring 9.7% in the middle and 5.7% at the top.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) The spaces do not provide access aisles. B) There is no van accessible parking space provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Savoy	Senior Center @ 720 Main Road	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 2-3 inches.
					Ramps	The ramp does not provide lower handrails on either side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Scituate	High School Gymnasium @ 606 Chief Justice Cushing Highway	00	01, 02, 03, 04, 05 & 06	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Seekonk	North School @ North Street	00	01	No	Parking Spaces in Lot	The designated accessible parking space that is identified as "van-accessible" does not provide an 8-foot access aisle. The access aisle measures 2 feet wide.
	Library @ Newman Avenue		02		Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) There are no access aisles provided adjacent to the spaces. B) The spaces abut a sidewalk. There are no curb cuts to access the sidewalk.
	Town Hall @ 100 Peck Street		03		Exterior Accessible Route	The walkway, leading to the designated accessible entrance, has a running slope measuring 9.4% at the bottom, 8.7% in the middle and 8.3% at the top.
	George R. Martin School @ Cole Street		04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sharon	High School @ 180 Pond Street	00	01, 02, 03, 04 & 05	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sheffield	Town Hall	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Shelburne	Memorial Hall @ 51 Bridge Street	00	01	No	Ramps	The ramp provided: A) The running slope of the ramp measures 10.1% at the bottom and 8.8% at the top. B) The handrails provided are not round or oval. The handrails are flat.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sherbom	Town Hall @ 19 Washington Street	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Shirley	Town Offices @ 7 Keady Way	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Shrewsbury	Municipal Office Building @ 100 Maple Avenue	00	01	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not provide a "van-accessible" sign.
	Frohsinn Clubb @ 25 North Quinsig Avenue		02		Ramps	The ramp provided: A) The ramp does not provide handrails on the right side. B) The handrails on the left side are not round or oval.
	Coolidge School @ May Street		03	Yes	None	
	Scandinavian Club @ 438 Lake Street		04	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not provide a "van-accessible" sign.
					Ramps	The ramp does not provide handrails that are round or oval. Currently they are a flat design.
	Sewer/Water Garage @ 209 South Street		05 & 08		Ramps	The portable ramp does not provide either 2 inch wheel guards on both sides or handrail on both sides.
	Senior Center @ 98 Maple Avenue		06	Yes	None	
	Spring Street School @ 121 Spring Street		07	No	Exterior Accessible Route	The walkway leading to the designated accessible entrance has running slopes measuring 7.3% and 8.3%.
	Liberty Assembly of God @ 495 Hartford Turnpike		09	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Shutesbury	Elementary School (Alternate Location [based on possible turnout] [Will not be used for November Election])	00	01	N/A	Changes in Level Along Accessible Route	There is a change in level, at the top of the curb cut located near the entrance, measuring 3/4 - 1 inch.
					Curb Cuts	1) The curb cut located near the designated accessible parking spaces, has a center running slope measuring 10.8%. 2) The curb cut located near the designated accessible entrance has a center running slope measuring 11.1%.
	Town Hall @ 1 Cooleyville Road			No	Parking Spaces in Lot	There is a designated accessible parking space configured as a van accessible space, however, there is no "van accessible" sign provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Somerset	Water Treatment Plant @ 3249 County Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 2 inches.
	Chace Street School @ Chace Street		02	Yes	None	
	Public Library @ 1464 County Street		03	No	Parking Spaces in Lot	There are no signs at the heads of each of the designated accessible parking spaces.
	Junior High School @ Brayton Avenue		04	Directional Signage	There are no signs indicating where the designated accessible entrance is located.	
				Entrances (Other than Locked)	The designated accessible entrance door provides only 28 inches of clear opening.	
				Interior Doors	There is an interior door that does not provide 32 inches of clear opening.	
	Wilbur School @ Brayton Point Road		05	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 47 inches.	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SOMERVILLE	East Somerville School @ Glen Street	01	01	Yes	None	
	East Somerville Library @ 115 Broadway		02		None	
	Reilly-Brickley Fire Station @ 266 Broadway		03		None	
	Police Department @ 220 Washington Street	02	01		None	
	Lincoln Park School @ 290 Washington Street		02		None	
	Lowell Street Fire Station @ 651 Somerville Avenue		03		None	
	Somerville High School @ Highland Avenue	03	01		None	
	Cummings School @ Prescott Street		02		None	
	The Dante Club @ Craigie Street		03	No	Entrances (Other than Locked) Ramps	The designated accessible entrance does not provide a level area on the exterior of the door. The ramp runs directly up to the door. The ramp does not provide handrails on either side.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SOMERVILLE	Mystic Activity Center @ 530 Mystic Avenue	04	01	Yes	None	
	Reilly-Brickley Fire Station @ 266 Broadway		02		None	
	Winter Hill School @ Sycamore Street		03		None	
	Public Works Garage @ Behind Trum Field	05	01		None	
	Brown School @ Josephine Avenue		02		None	
	Engine 7 Fire Station @ 265 Highland Avenue		03		None	
	G.F. Dilboy Post @ 371 Summer Street	06	01		None	
	Ciampa Manor @ 27 College Avenue		02		None	
	Methodist Church @ Chapel Street		03		None	
	Powder House School @ 1060 Broadway	07	01		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SOMERVILLE	Teele Square Fire Station @ 6 Newbury Street	07	02	Yes	None	
	Conwell School @ One Capen Court		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
South Hadley	Town Hall @ 116 Main Street	00	A	Yes	None	
	Main Library @ 27 Bardwell Street		B	No	Entrances (Other than Locked)	The designated accessible entrance: A) The entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 6.0%. B) The entrance door does not provide hardware that is operable with a closed fist. A door knob is provided.
					Exterior Accessible Route	The walkway, leading to the entrance, has a running slope measuring 5.8% to 6.2%.
					Parking Spaces in Lot	There are no access aisles provided for the designated accessible parking spaces.
	Council on Aging @ 45 Dayton Street		C		Parking Spaces in Lot	There are no access aisles provided adjacent to the 3 designated accessible parking spaces.
	Michael Smith Middle School @ Mosier Street		D		Parking Spaces in Lot	The designated accessible parking spaces provided: A) There is no van accessible parking space provided. B) There are no signs at the head of the parking spaces. C) There is no curb cut provided at the head of the access aisle of the left most parking space.
	Mosier School @ 101 Mosier Street		E		Parking Spaces in Lot	There are no signs at the heads of the designated accessible parking spaces provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Southampton	Town Hall @ 8 East Street	00	01	No	Exterior Accessible Route	The walkway, from the accessible parking spaces to the ramp, has running slopes measuring 6.9% at the asphalt and 14.9% at the 1st cement block.
					Parking Spaces in Lot	The designated accessible parking spaces provided: A) The space that is configured as van accessible is missing a "van-accessible" sign. B) The signs, located at the head of each space, measure 3 feet 4 inches to the top.
					Ramps	The ramp provided: A) The running slope of the 1st run up, measures 10.9% at the top and 12.1% at the bottom. B) The running slope of the 2nd run up, measures 9.3% at the bottom. C) There is only an upper handrail provided on the left side of the 1st run up. The upper handrail is not round or oval, it is flat. D) There is only an upper handrail provided on the right side of the 2nd run up. The upper handrail is not round or oval, it is flat.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Southborough	Central Fire Station @ 21 Main Street	00	01	Yes	None	
	Trottier Middle School @ 49 Parkville Road		02		None	
	Mary Finn School @ 60 Richards Road		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Southbridge	High School	00	01	No	Exterior Accessible Route	The path of travel to the side door, which is used by everyone during polling, has a five-inch step.
						NOTE: The main entrance is accessible, but it is not used for polling.
	West School		02	Yes	None	
	Charlton Street School		03	No	Entrances (Other than Locked)	There is no level area on the exterior of the entrance door.
					Parking Spaces in Lot	There is no accessible parking provided on site.
						NOTE: During the survey it was explained that temporary accessible parking spaces will be provided the day of polling.
	Eastford Road School		04		Changes in Level Along Accessible Route	The path of travel to the designated accessible entrance has changes in level greater than ½ inch.
					Entrances (Other than Locked)	The designated accessible entrance does not have a level landing on the exterior of the door.
					Exterior Accessible Route	The distance to the designated accessible entrance is not "the same or substantially similar for all persons entering the location".
					Lighting	The path of travel to the designated accessible entrance is not reasonably lit.
	Wells Jr. High School		05	Yes	Parking Spaces in Lot	There are no accessible parking spaces provided.
					Ramps	The ramp provided has a running slope exceeding 1:12.
					None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Southwick	Town Hall @ 454 College Highway	00	01, 02 & 03	No	Parking Spaces in Lot	<p>1) There are 4 designated accessible parking spaces provided near the entrance for Precinct 1 & 2.</p> <p>A) The space that is configured as van accessible is missing the "van-accessible" sign.</p> <p>B) There are signs missing from the head of some of the parking spaces.</p> <p>2) There are 3 designated accessible spaces provided near the entrance for precinct 3.</p> <p>A) There is no van accessible parking space provided.</p> <p>B) There are no signs at the head of the spaces.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Spencer	Town Hall @ 157 Main Street	00	01, 02, 03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SPRINGFIELD	Riverview Administration Building @ 82 Division Street	01	A & B	No	Curb Cuts	The curb cut, located along the accessible route to the accessible entrance, has a center running slope measuring 11.2% to 13.8%.
					Parking Spaces in Lot	There are no signs provided at the head of the designated accessible parking spaces.
	New North Citizen Council @ 2382 Main Street		C	Yes	None	
	Bay State Police @ 414 Chestnut Street		D & E		None	
	Hobby Club @ 309 Chestnut Street		F	No	Parking Spaces in Lot	There is no access aisle provided for the standard designated accessible parking space.
	Fire Department Headquarters @ Spring and Worthington Streets		G	Yes	None	
	The Good Life Center @ 1600 East Columbus Avenue		H	No	Parking Spaces in Lot	There are no van accessible parking spaces provided.
	Kendall Commons @ 190 Kendall Street	02	A	Yes	None	
	OLH Church Basement @ 474 Armory Street		B & C		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SPRINGFIELD	Saint James Manor @ 754 Saint James Avenue	02	D	Yes	None	
	Van Sickle School @ 1170 Carew Street		E & H		None	
	Safety Complex @ 1212 Carew Street		F		None	
	Bowles School @ 24 Bowles Park		G		None	
	Maple Commons @ 60 School Street	03	A	No	Ramps	The handrails, provided for the ramp, are not round or oval. The handrails are flat.
	Gentile Apartments Common Room @ 85 William Street		B & C	Yes	None	
	Brookings Middle School @ 367 Hancock Street		D & E	No	Changes in Level Along Accessible Route	There is a change in level, at the designated accessible entrance, measuring 5 inches.
					Entrances (Other than Locked)	The designated accessible entrance: A) The entrance does not provide a 5-foot level landing on the exterior of the door. B) The door does not provide hardware on the exterior. C) The door provides only a 28 inch clear opening.
	Holy Name Social Center @ 323 Dickinson Street		F & G		Ramps	There are no handrails provided on either side of the ramp.
	Wesleyan Church @ 98 White Street		H	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SPRINGFIELD	Rebecca Johnson School @ 55 Catharine Street	04	A & B	Yes	None	
	Urban League Of Springfield (Formerly at Mason Square Library @ 765 State Street)		C		None	
	Highland House @ 250 Oak Grove Avenue		D		None	
	Mason Square Fire Station @ 33 Eastern Avenue		E		None	
	AIC Health Science Comp @ State and Homer Streets		F & H		None	
	Independence House @ 1475 Roosevelt Avenue		G		None	
	Kasparian Complex @ 60 Alton Street	05	A & B		None	
	Mary Lynch School @ 315 North Branch Parkway		C	No	Entrances (Other than Locked)	<p>The designated accessible entrance:</p> <p>A) The entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 18 inches, then there is a slope measuring 3%.</p> <p>B) The door provides only 28 inches of clear opening.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SPRINGFIELD	Sixteen Acres Library @ 1187 Parker Street	05	D & G	Yes	None	
	Pine Point Library @ 204 Boston Road		E		None	
	Duggan Middle School @ 1015 Wilbraham Road		F	No	Entrances (Other than Locked)	The designated accessible entrance door provides only 28 inches of clear opening.
	Church in the Acres @ 1383 Wilbraham Road		H	Yes	None	
	Forest Park Middle School @ 46 Oakland Street	06	A & B	No	Exterior Accessible Route	There is no curb cut provided at the on-street designated accessible parking spaces to access the sidewalk.
					Ramps	The ramp provided: A) There are no lower handrails provided. B) The upper handrails provided are not round or oval. The handrails are flat.
	Forest Park Manor @ 25 Barney Lane		C	Yes	None	
	Alice Beal School @ 285 Tiffany Street		D & F	No	Entrances (Other than Locked)	The designated accessible entrance door provides only 28 inches of clear opening.
					Ramps	The ramp has a running slope measuring 11.3% at the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SPRINGFIELD	Goodwill Shoppes @ 473 Sumner Avenue	06	E	Yes	None	
	Goodwill Industries @ 285 Dorset Street		G & H	No	Entrances (Other than Locked)	The designated accessible entrance: A) The entrance door has a 1 inch threshold. B) The hardware on the door is not operable with a closed fist. The door hardware is a door knob.
	Mary Dryden School @ 190 Surrey Road	07	A		Changes in Level Along Accessible Route	There is a change in level, at the designated accessible entrance, measuring 8 inches.
					Exterior Accessible Route	There is no curb cut provided to access the sidewalk where the on-street accessible parking spaces are located.
					Lighting	The path of travel, from the on-street accessible parking spaces to the designated accessible entrance, is not "reasonably lit". There is no lighting provided.
	Frederick Harris School @ 58 Hartford Terrace		B & C		Entrances (Other than Locked)	The designated accessible entrance does not have a 5-foot level landing on the exterior of the door. The slope of the landing measures 3.8%.
					Lighting	The path of travel, from the on-street accessible parking spaces to the designated accessible entrance, is not "reasonably lit". There is no lighting provided.
	Talmadge School @ 1395 Allen Street		D	Yes	None	
	Brunton School @ 1801 Parker Street		E & G		None	
	Kiley Middle School @ 80 Cooley Street		F	No	Ramps	There are no handrails provided on the right side of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SPRINGFIELD	Glickman School @ 120 Ashland Avenue	07	H	No	Entrances (Other than Locked)	The designated accessible entrance has three doors. A) The middle door, which would be accessible, remains locked. B) The 2 outside doors, do not provide hardware that is operable with a closed fist. The hardware is a thumb latch. NOTE: During the survey, Bruce mentioned that if the middle door remains unlocked during polling, the entrance would be accessible.
	Saint Mary's Church @ 840 Page Blvd	08	A	Yes	None	
	Mary Lynch School @ 315 North Branch Parkway		B	No	Entrances (Other than Locked)	The designated accessible entrance: A) The entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 18 inches, then there is a slope measuring 3%. B) The door provides only 28 inches of clear opening.
	Central High School @ 1840 Roosevelt Avenue		C	Yes	None	
	John F. Kennedy School @ 1385 Berkshire Avenue		D	No	Entrances (Other than Locked)	The designated accessible entrance door provides only 28 inches of clear opening.
	Indian Orchard Country Club @ 117 Main Street		E		Curb Cuts	The curb cut, located near the designated accessible entrance, has a center running slope measuring 9.8%.
	Odessa Street Fire Station @ 15 Odessa Street		F	Yes	Ramps None	There are no handrails provided on either side of the ramp.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
SPRINGFIELD	Warner Street School @ 493 Parker Street	08	G	No	Entrances (Other than Locked)	The designated accessible entrance does not provided a 5-foot level landing on the exterior of the door. The slope of the landing measures 6.0%.
	Robinson Gardens @ 51 Robert Dyer Circle		H		Entrances (Other than Locked)	The designated accessible entrance has two doors in a series, one a screen door, the other a standard door. The standard door has hardware that is not operable with a closed fist. The hardware is a door knob.
					Ramps	<p>The ramp provided:</p> <p>A) The running slope of the middle ramp measures 12.8% at the bottom, 13.0% in the middle.</p> <p>B) The running slope of the side ramp measures 9.6% at the top.</p> <p>C) The handrails on the middle ramp do not extend the entire run of the ramp.</p> <p>D) The side ramp does not provide an upper and lower handrail on both sides.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sterling	Houghton Elementary School @ 32 Boutelle Road (Formerly Chocksett School)	00	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Stockbridge	Town Hall	00	01	No	Directional Signage	There are no signs directing people to the designated accessible entrance used for polling.
					Ramps	<p>The ramp:</p> <p>a) The running slope measures 8.6% at the bottom and 14.2% at the top.</p> <p>**b) The handrails do not extend at the top and bottom of the ramp.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Stoneham	Town Hall @ 35 Central Street	00	01, 02, 03, 04, 05, 06 & 07	No	Parking Spaces in Lot	The designated accessible parking spaces provided: A) The space designated "van-accessible" provides a 5-foot access aisle. B) The signs at the head of the spaces measures 4 feet 5 inches to the top of the sign. C) The access aisles abut a sidewalk without providing a curb cut.
					Ramps	The ramp provided has a running slope measuring 11.8% and 12.6% at the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Stoughton	Joseph Dawe Elementary School @ 131 Pine Street	00	01	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	E. A. Jones Elementary School @ 137 Walnut Street		02		Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	South Elementary School @ 171 Ash Street		03		Exterior Accessible Route	The walkway, leading to the designated accessible entrance used for polling, has running slopes measuring 6.1% at the bottom and 8.3% in the middle.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	Gibbons Elementary School @ 235 Morton Street	04 & 05		Ramps	The interior ramp: A) The running slope of the ramp measures 18.7% at the top and 18.9% at the bottom. B) The ramp measures 34 inches wide, measured between the handrails. C) The handrails provided: I) The handrails are located only on one side of the ramp. II) Only the upper handrail is provided.	
				Curb Cuts	The curb cut, located across from the designated accessible parking space, leading to the ramp, has a center running slope measuring 12.6%.	
				Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.	
				Ramps	The handrails, for the ramp, are provided only on one side of the ramp.	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Stoughton	Hansen Elementary School @ 1800 Central Street	00	06	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the ramp, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	West Elementary School @ 1322 Central Street		07		Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	O'Donnell Middle School @ 211 Cushing Street		08		Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Stow	Center School @ 403 Great Road	00	01	No	Interior Doors	The is a set of double doors at the gymnasium entrance. When only one door is open, there is only 29 inches of clear space. NOTE: During the survey, Linda explained that the two doors were left open during the time of polling.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided in the lot: A) The 2 spaces do not provide an access aisle beside them. B) Only one space has a sign at the head of the space.
					Ramps	The ramp provided at the designated accessible entrance door: A) The running slope measures 9.6% - 10.0%. B) There are no handrails provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sturbridge	Burgess Elementary School @ Off Cedar Street	00	01 & 02	No	Changes in Level Along Accessible Route	1) There is a change in level, at the head of the access aisle, measuring 1 inch. 2) There is a change in level, along the walkway to the entrance, measuring 3/4 of an inch.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided: A) There is no sign provided at the head of the left space. B) The space that is configured as van accessible does not provide a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sudbury	Fairbanks Community Center	00	01, 02 & 05	No	Parking Spaces in Lot	<p>The designated accessible parking:</p> <p>a) There are 4 spaces measuring 13 feet wide but do not provide access aisles.</p> <p>b) There are 2 spaces that share an access aisle, but the access aisle abuts a sidewalk without a curb cut provided at the head of the access aisle.</p> <p>c) The 4 spaces have 2 signs for the spaces.</p> <p>d) The 2 spaces with signs only have one sign.</p> <p>e) There is no "van-accessible" space provided.</p>
					Sample Ballot	A sample ballot is not posted within at least one machine, not higher than 48 inches.
	Town Hall		03 & 04		Sample Ballot	A sample ballot is not posted within at least one machine, not higher than 48 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sunderland	Elementary School @ 1 Swamp Field Road	00	01	No	Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) All 3 spaces have an 8 foot access aisle adjacent to them. One of the 3 spaces needs to have a "van-accessible" sign. B) The left side access aisle abuts a sidewalk. There is no curb cut provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Sutton	Early Learning Center @ 409 Boston Road	00	01	Yes	None	
	Manchaug Library @ 6 Main Street		02	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 5.6%.
					Exterior Accessible Route	The path of travel, from the parking to the designated accessible entrance, is not paved.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot.
	Community Room @ 5 Church Street		03		Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut near the parking, measuring 1 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Swampscott	Clarke School @ Corner of Paradise Road and Norfolk Avenue	00	01 & 02	No	Changes in Level Along Accessible Route	The accessible route requires using a driveway to access the polling location. Where the driveway meets the street there are changes in level measuring 1 to 1 1/2 inches.
					Exterior Accessible Route	To access the ramp, located in the rear of the building, there is a gate that must be passed through for someone needing access to the designated accessible entrance.
						NOTE: During the survey, Linda explained that there is a Police Officer who will open the gate for people needing access.
	First Church @ 40 Monument Avenue		03 & 04	Yes	Ramps	The ramp provided: A) The ramp has a running slope measuring 11.5% in the middle and 9.3% at the top. B) The ramp is missing handrails on the right side. C) The handrails provided on the left side of the ramp are a 2X4 configuration.
					None	
	Swampscott High School @ 207 Forest Avenue		05 & 06	No	Changes in Level Along Accessible Route	There are changes in level along the accessible route to the designated accessible entrance measuring 3/4 to 1 inch.
					Curb Cuts	The curb cut located to the right of the on-street accessible parking spaces has a center running slope measuring 13.5%.
					Ramps	The ramp provided on the interior of the school: A) The running slope at the bottom of the ramp measures 9.7%. B) The ramp measures 45 inches wide, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Swansea	Brown School @ Gardner Neck Road	00	01	No	Exterior Accessible Route	The walkway, leading to the designated accessible entrance landing, has a running slope measuring 8.3%.
	Bluffs Facility @ 458 Ocean Grove Avenue		02	Yes	None	
	Saint Dominic Hall @ 1277 Gar Highway		03 & 05	No	Ramps	The ramp does not provide handrails that are round or oval. The handrails are a 2x4 configuration.
	Fire Station 4 @ 1680 Gar Highway		04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
TAUNTON	Assembly of God Church @ 159 Winthrop Street	01	A	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 5.5%.
					Ramps	Handrails are not provided on both sides of the ramp.
	Westville Congregational Parish High School @ Corner of Winthrop and North Walker Street		B	Yes	None	
	Fitzsimmons Arms Community Hall @ 30 Olney Street	02	A	No	Curb Cuts	The curb cut, to access the sidewalk leading to the entrance, has a center running slope measuring 9.7%.
					Entrances (Other than Locked)	The designated accessible entrance: A) There is no level landing provided on the exterior of the door. The slope of the landing measures 7.6%. B) The hardware on the door is not operable with a closed fist. A thumb latch is provided.
						NOTE: During the survey, it was discussed that the thumb latch is disabled during polling.
					Parking Spaces in Lot	There are 4 designated accessible parking spaces provided. A) The right-most space does not provide a 5-foot access aisle adjacent to it. The access aisle measures less than 5 feet. B) The designated accessible parking space configured as van accessible is missing the "van-accessible" sign.
	Maxham School @ 141 Oak Street		B		On-Street Parking	There are no designated "on-street" accessible parking spaces provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
TAUNTON	Maxham School @ 141 Oak Street	02	B	No	Ramps	The ramp provided on the interior of the school: A) The running slope measures 16.2% at the top and 16.0 % at the bottom. B) The ramp is only 38 inches wide, measured between the handrails. C) The upper handrails are located lower than 34-38 inches.
	Saint Anthony Parish Center @ 122-126 School Street	03	A		Changes in Level Along Accessible Route	1) There is a change in level, at the base of the curb cut, located at the left most access aisle of the designated accessible parking, measuring 3/4 to 1 inch. 2) There is a change in level, at the base of the curb cut, located at middle access aisle of the designated accessible parking, measuring 3/4 to 1 inch. 3) There is a change in level, at the base of the curb cut, located at the right most access aisle of the designated accessible parking, measuring 3/4 to 1 inch. 4) There is a change in level, at the top of the 2nd run up the ramp, measuring 3/4 of an inch.
					Curb Cuts	1) The curb cut, located at the left most access aisle at the designated accessible parking, has a center running slope measuring 12.3%. 2) The curb cut, located at the middle access aisle at the designated accessible parking, has a center running slope measuring 11.5%.
					Parking Spaces in Lot	There are 6 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) Only 4 of the 6 spaces have signs at the heads of the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
TAUNTON	Saint Anthony Parish Center @ 122-126 School Street	03	A	No	Ramps	The ramp has a running slope measuring 9.0% at the bottom of the 1st run up and 9.4% at the bottom of the 2nd run up.
	Elizabeth Pole School @ 110 County Street		B		Changes in Level Along Accessible Route	There is a change in level, at the rear of the access aisle for the designated accessible parking, measuring 1 to 2 inches.
	Joseph Martin School @ 131 Caswell Street	04	A		Parking Spaces in Lot	There is no van accessible parking space provided in the lot.
	East Taunton Elementary School @ 58 Stevens Street		B		Exterior Accessible Route	The path of travel, from the designated accessible parking to the designated accessible entrance for polling is up a sloped incline. The running slope measures 7.6%.
	Hopewell School @ 16 Monroe Street	05	A		Ramps	The running slope of the ramp measures 10.1% at the top.
	Saint Anthony Parish Center @ 122-126 School Street		B		Changes in Level Along Accessible Route	<p>1) There is a change in level, at the base of the curb cut, located at the left most access aisle of the designated accessible parking, measuring 3/4 to 1 inch.</p> <p>2) There is a change in level, at the base of the curb cut, located at middle access aisle of the designated accessible parking, measuring 3/4 to 1 inch.</p> <p>3) There is a change in level, at the base of the curb cut, located at the right most access aisle of the designated accessible parking, measuring 3/4 to 1 inch.</p> <p>4) There is a change in level, at the top of the 2nd run up the ramp, measuring 3/4 of an inch.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
TAUNTON	Saint Anthony Parish Center @ 122-126 School Street	05	B	No	Curb Cuts	1) The curb cut, located at the left most access aisle at the designated accessible parking, has a center running slope measuring 12.3%. 2) The curb cut, located at the middle access aisle at the designated accessible parking, has a center running slope measuring 11.5%.
					Parking Spaces in Lot	There are 6 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) Only 4 of the 6 spaces have signs at the heads of the spaces.
					Ramps	The ramp has a running slope measuring 9.0% at the bottom of the 1st run up and 9.4% at the bottom of the 2nd run up.
	Craig C Sherman Center - DPW @ 90 Ingell Street	06	A	Parking Spaces in Lot	There are 4 designated accessible parking spaces provided. The 2 standard parking spaces only provide a 3 foot access aisle.	
	Leddy School @ 36 Second Street			B	Curb Cuts	The curb cut, located at the entrance, has a center running slope measuring 12.2%.
			Parking Spaces in Lot	The parking lot used for the polling location is located across the street at the Funeral Home. There are 3 designated accessible parking spaces provided. A) The 2 standard accessible parking spaces do not have an access aisle adjacent to them. B) None of the parking spaces have signs at the heads of the spaces.		
					NOTE: At the time of the survey, it was discussed that 2 temporary on-street spaces be provided, one on each side of the curb cut near the entrance.	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
TAUNTON	Mulcahy School @ 28 Clifford Street	07	A	No	Parking Spaces in Lot	The designated accessible parking space that is identified as "van-accessible" only provides a 7-foot wide space with a 7-foot wide access aisle.
	Bennett School @ 45 North Walker Street		B		Curb Cuts	The curb cut, located at the entrance, has a center running slope measuring 10.4%.
	Chamberlain School @ 480 Norton Avenue	08	A		Changes in Level Along Accessible Route	There are changes in level, at the base of some of the curb cuts along the accessible route, measuring 3/4 to 1 inch.
					Curb Cuts	1) The curb cuts, located in front of the access aisles at the designated accessible parking spaces, have level entry, the slope to the left and right. The running slopes of the inclines measure up to 10%.
						2) The curb cut, located at the walkway leading to the entrance, closest to the entrance, has a center running slope measuring 9.6%.
					Parking Spaces in Lot	There is no van accessible parking space located within the lot.
	North Taunton Baptist Church @ 1940 Bay Street		B		Parking Spaces in Lot	There are 2 designated accessible parking spaces provided in the lot. A) There are no access aisle provided adjacent to the spaces. B) There are no signs at the heads of either spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Templeton	Narragansett Middle School @ 464 Baldwinville Road	00	A & B	No	**Comments	During the survey, I was shown multiple entrances, depending on the room that was used for polling. ALL of the entrances and areas are accessible under the polling requirements. The only concern was that there would need to be temporary accessible parking provided if the area chosen does not have any.
					Parking Spaces in Lot	The designated accessible parking does not provide a van accessible space. NOTE: During the survey, it was discussed that temporary accessible spaces will be provided during polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Tewksbury	DPW Building @ 999 Whipple Road	00	01 & 1A	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a level landing on the exterior of the door.
					Ramps	The ramp provided has a running slope measuring 13.5%.
	Teen Center @ 286 Livingston Street		02		Changes in Level Along Accessible Route	There is a change in level at the bottom of the curb cut that measures greater than 1/2 inch.
	Senior Center @ 175 Chandler Street		03 & 3A	Yes	None	
	Library @ 300 Chandler Street		04 & 4A		None	
	South Fire Station @ 2342 Main Street		2A		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Tisbury	American Legion Hall @ 47 Martin Road	00	01	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible does not have a "van-accessible" sign.
					Ramps	The ramp has running slopes measuring 10.5% on the 1st run up, where the cement meets the wood and 10.2% at the top of the 2nd run up.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Tolland	Town Hall @ 241 West Granville Road	00	01	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the parking lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Topsfield	Saint Rose Church Hall @ 12 Park Street	00	01	No	Changes in Level Along Accessible Route	There is a change in level, near the walk, that measures greater than 1/2 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Townsend	Memorial Hall @ 272 Main Street	00	01, 02 & 03	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Truro	Central School @ 317 Route 6	00	01	No	Curb Cuts	The curb cut, located at the entrance, has a center running slope measuring 10.0%.
					Parking Spaces in Lot	There are 4 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) The access aisles provided measure 4 feet wide.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Tyngsborough	Early Childhood Center @ 135 Coburn Road	00	01	Yes	None	
	Multi-Service Center @ 180 Lakeview Avenue		02	No	**Comments	<p>**There are 2 ramps provided at this location.</p> <p>**A) Both ramps have pooling of water at the base of the ramps, which in cold weather, turn to ice.</p> <p>**B) The ramps do not provide a level area at the base of the ramps.</p>
					Changes in Level Along Accessible Route	The path of travel from the designated accessible parking spaces to the designated accessible entrance has changes in level measuring greater than 1/2 inch.
	Library/Town Hall @ 25 Bryants Lane		03	Yes	None	
	Tyngsborough Elementary School @ 205 Westford Road		04		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Tyringham	Town Hall @ 116 Main Road	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Upton	Town Hall @ One Main Street	00	01	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 60 inch level area on the interior of the door.
					Ramps	The ramp does not provide lower handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Uxbridge	High School @ Capron Street	00	01, 02, 03 & 04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wakefield	Masonic Lodge @ 372 Salem Street	00	01 & 07	No	Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. Opened individually, each door provides only 30 inches of clear width.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot. NOTE: During the survey, it was discussed that temporary spaces would be provided during polling.
	Crystal Community Club @ 71 Preston Street		02	N/A	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot. NOTE: During the survey, it was discussed that temporary spaces would be provided during polling.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot. NOTE: During the survey, it was discussed that temporary spaces would be provided during polling.
	Franklin School @ 100 Nahant Street		03	No	Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot. NOTE: During the survey, it was discussed that temporary spaces would be provided during polling.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot. NOTE: During the survey, it was discussed that temporary spaces would be provided during polling.
	Most Blessed Sacrement Church @ 1155 Main Street		04		Parking Spaces in Lot	There are no designated accessible parking spaces provided in the lot. NOTE: During the survey, it was discussed that temporary spaces would be provided during polling.
	West Side Social Club @ Harrington Court		05 & 06	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wales	Elementary School (Formerly @ Senior Center and will return at a later undetermined date)	00	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Walpole	Old Post Road School (New Location)	00	01 & 02	No	Parking Spaces in Lot	There is no van-accessible parking space provided in the parking lot..
	Walpole High School @ 275 Common Street		03, 04 & 05 (formerly included 01 and 02)	Yes	None	
	Fisher School @ 65 Gould Street		06, 07 & 08		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WALTHAM	Park and Recreation Building @ 314 Totten Pond Road	01	01	Yes	None	
	Waltham High School @ 617 Lexington Street		02		None	
		02	01		None	
	Lake Street Police Substation @ Corner of Lake Street and Indian Road		02		None	
	Macarthur School @ Corner of Lake Street and Lincoln Street	03	01	No	Lighting	There is not adequate lighting at the designated accessible entrance.
	Northeast School @ Putney Lane (Formally the "Old" Northeast School located across the street)		02	Yes	None	
	Fitzgerald School @ 140 Beal Road	04	01 & 02		None	
	Bright School Basement @ Corner of Grove Street and Bright Street	05	01		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WALTHAM	Police Substation @ 11 Carter Street	05	02	Yes	None	
	Charles A. Lawless Apartments @ 110 Pond Street	06	01		None	
	Clark Government Center @ Corner of School Street and Lexington Street		02	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot are not striped.
	Banks School @ Corner of South Street and Russell Street	07	01 & 02	Yes	None	
	Whalen Housing @ 84 Orange Street	08	01	No	Ramps	The ramp: A) The ramp only provides an upper handrail. B) The upper handrails provided on the ramp are a 2X4 configuration.
	Whittemore School Basement @ 30 Parmenter Road		02		Changes in Level Along Accessible Route	There is a 3 foot 3 inch change in level along the path of travel to the designated accessible entrance.
	Arthur J. Clark Housing @ 48 Pine Street	09	01		Parking Spaces in Lot	The designated accessible parking spaces provided in the lot are missing the signs at the head of the spaces.
	Cutter Street Polling Place @ Corner of Cutter Street and Newton Street		02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Ware	Town Hall @ 126 Main Street	00	A, B & C	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut at the designated accessible parking, measuring 1 inch.
					Curb Cuts	The curb cut, located at the designated accessible parking, has a center running slope measuring 12.6%.
					Entrances (Other than Locked)	<p>The designated accessible entrance:</p> <p>A) The door hardware is not operable with a closed fist. The present hardware is a thumb latch.</p> <p>B) The entrance is a set of double doors. Each door opened individually provides only 30 inches of clear width.</p> <p>NOTE: There is an automatic door opener that opens both doors at once. During the survey, it was explained that the automatic doors are "on" during the hours of polling.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wareham	Town Hall	00	01	No	Parking Spaces in Lot	The designated accessible parking spaces: a) 2 of the spaces do not provide an access aisle. b) None of the spaces are designated "van-accessible".
	Hammond Elementary School				Changes in Level Along Accessible Route	There is a change in level at the bottom of the curb cut, which is located near the on-street designated accessible parking space, that measures between ¾ - 1 inch.
					Exterior Accessible Route	The accessible route on the sidewalk, leading from the on-street designated accessible parking space to the entrance, narrows to 30 inches at the light pole.
					Ramps	The ramp provided has running slopes measuring 16.8% at the bottom, 10.0% in the middle, and 10.3% at the top.
	Minot Forest Elementary School		03	Yes	None	
	Redman Hall		04		None	
	Deacas Elementary School		05		Parking Spaces in Lot	** There are built up curb ramps that protrude into the access aisles for the designated accessible parking spaces.
	Elks Hall		06	No	Changes in Level Along Accessible Route	The curb cut provided at the end of the sidewalk closest to the ramp has changes in level in the curb cut measuring between ¾ - 1 inch.
					Curb Cuts	The curb cut provided at the end of the sidewalk closest to the ramp has a running slope measuring 16.3%.
					Parking Spaces in Lot	The designated accessible parking spaces: a) There is no "van-accessible" sign at the van space. b) The 5-foot access aisle abuts a sidewalk without a curb cut provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wareham	Elks Hall	00	06	No	Ramps	The ramp: a) The running slope at the top of the ramp measures 9.1%. b) The ramp does not provide 48 inches between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Warren	Shepard Municipal Building @ 48 High Street	00	A	Yes	None	
	Senior Center @ 2252 Main Street		B	No	Ramps	The ramp has a running slope measuring 10.1%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Warwick	Town Hall @ 12 Athol Road	00	01	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The slope measures 3.2% to 4.0%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Washington	Town Hall @ 8 Summit Hill Road	00	01	No	Entrances (Other than Locked)	<p>NOTE: There are 2 entrances for this building. During the survey, I was told that the main entrance is the entrance used for polling. I surveyed the rear entrance as well and included the findings.</p> <p>1) The designated accessible entrance used for polling at the main entrance:</p> <p>A) There is a 6-inch step at the doorway. There is no vertical access provided.</p> <p>B) The hardware, provided on the exterior of the door, is not operable with a closed fist. The hardware is a door knob.</p> <p>C) The threshold for the door measures 1 inch.</p> <p>D) The clear opening measures 27 inches.</p> <p>2) The entrance to the rear of the building:</p> <p>A) The hardware, provided on the exterior of the door, is not operable with a closed fist. The hardware is a door knob.</p>
					Interior Doors	There is a doorway, along the path of travel from the main entrance to the polling location, that provides a clear opening measuring 27 inches.
					Parking Spaces in Lot	<p>There are no designated accessible parking spaces provided in the lot.</p> <p>NOTE: During the survey, it was discussed that temporary spaces are provided during polling.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Watertown	Saint Stephen's Parish Hall @ 38 Elton Avenue	00	01 & 03 (formally precinct 2 as well, but will be moved for Nov. Elections)	No	Changes in Level Along Accessible Route	There is a change in level at the base of the ramp measuring 3/4 to 1 inch.
					On-Street Parking	There are temporary on-street designated accessible parking spaces provided. However, where the spaces are provided there are no curb cuts located near them to access the sidewalk.
					Ramps	The ramp provided: A) The running slope of the ramp measures 10.2% in the middle and 9.5% at the top. B) There are no handrails provided on the left side of the ramp.
	Hosema School @ Concord Road	02 (Will be used for Nov. Elections)	04 & 05	Yes	None	
	Phillip School @ 30 Common Street				None	
	Hiberian Hall @ 151 Watertown Street	06	07	No	Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. There is 1 space that is configured as a van-accessible space, however, the "van-accessible" sign is missing from the head of the space.
	Lowell School @ 175 Orchard Street				Changes in Level Along Accessible Route	There is a change in level along the sidewalk leading to door #10 that measures 1-2 inches.
						Parking Spaces in Lot

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Watertown	Middle School @ 68 Waverley Avenue	00	08 & 09	No	Parking Spaces in Lot	There are 2 designated accessible parking spaces provided in the lot. There is one space that is configured as a van-accessible space, however, there is no "van-accessible" sign at the head of the space.
	Browne/Atrium School @ 552 Main Street		10		Parking Spaces in Lot	There is no van accessible parking space provided in the parking lot.
	Cunniff School @ 241 Warren Street		11 & 12		Parking Spaces in Lot	There is no van-accessible parking space provided in the parking lot.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wayland	Town Hall	00	01 & 04	No	Changes in Level Along Accessible Route	The walkway leading to the entrance has cracks in the sidewalk that create changes in level measuring greater than ½ inch.
					Directional Signage	Since the Main entrance is not accessible, there needs to be signage directing people to the polling entrance.
					Entrances (Other than Locked)	1) The interior door used as the "enter" door for polling has a threshold that is not beveled and measures about 2 inches. 2) The interior door used as the "exit" door for polling: a) Has a 2 inch threshold and is not beveled. b) The doors provided only a 27-½ inch clear opening. **c) Since the doors "stick" together, the pound pressure to open the door exceeds 5 pounds.
	Middle School		02 & 03		Parking Spaces in Lot	The designated accessible parking spaces are missing the signs at the front of the spaces.
					Changes in Level Along Accessible Route	There are some locations on the walkway where there is deterioration thus creating changes in level greater than ½ inch.
					Curb Cuts	** The curb cut provided to allow access onto the sidewalk from where the parallel parking is provided: **a) The right side flare has a running slope measuring 16.5%. **b) The landing at the top of the curb cut has a slope measuring 7.2%.
					Exterior Accessible Route	The walkway leading to the entrance used for polling has running slopes measure 6.4% and 5.3%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Webster	Town Hall @ 340 Main Street	00	01, 02, 03, 04 & 05	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wellesley	Bates School @ 116 Elmwood Road	00	A	Yes	None	
	Sprague School @ 401 School Street		B		None	
	Upham School @ 35 Wynnewood Road		C		None	
	Schofield School @ 27 Cedar Street		D		None	
	Fiske School @ 45 Hastings Street		E		None	
	Senior High School @ 50 Rice Street		F		None	
	Hunnewell School @ 28 Cameron Street		G		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
--------------	------------------	------	-------------	-------------------	--------------------	-----------------

Wellfleet

Public Library @
55 West Main Street

00

01

No

Parking Spaces in Lot

There are 2 designated accessible parking spaces provided in the lot. There is no van accessible parking space provided. The access aisles adjacent to the right most space, has a 2 foot access aisle on the left side and a 6 foot access aisle on the right side.

NOTE: To properly configure a van accessible space, the access aisle adjacent to the space should measure 8-feet.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wendell	Town Hall @ Center Street	00	01	No	Parking Spaces in Lot	The designated accessible parking provided in lot: A) The accessible parking spaces do not have an access aisle adjacent to the spaces. B) The right side parking space does not have a sign at the head of it.
					Ramps	The ramp has a running slope measuring 9.7%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wenham	Bessie Burke School @ 1 School Street	00	01	No	Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. Opened individually, each door provides only 28 inches of clear opening.
					Interior Accessible Route	There is a set of double doors on the interior of the building. Opened individually, each door provides only 28 inches of clear opening.
					Lighting	The path of travel from the parking lot to the designated accessible entrance does not provide adequate light.
					Parking Spaces in Lot	The designated accessible space that is configured as van accessible does not provide a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
West Boylston	Mixer Municipal Offices @ 120 Prescott Street	00	01 & 02	No	Parking Spaces in Lot	The designated accessible parking spaces provided: A) There is no van accessible parking space provided. B) The spaces do not provide an access aisle adjacent to the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
West Bridgewater	Spring Street School @ 2 Spring Street	00	01 & 02	No	Entrances (Other than Locked)	The designated accessible entrance does not provided a 5-foot level landing on the exterior of the door. The landing has a slope measuring 8.3%.
					Parking Spaces in Lot	There are 4 designated accessible parking spaces provided. A) The space that is configured as van accessible is missing the "van-accessible" sign. B) Three of the spaces do not provide a sign at the head of the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
West Brookfield	Senior Center @ Front Street (Will be moving to the new Senior Center in July that is still under construction)	00	01	No	Changes in Level Along Accessible Route	There is a change in level, along the path of travel leading to the accessible entrance, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	There are no access aisles adjacent to the 3 designated accessible parking spaces provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
West Newbury	Town Hall	00	01	No	Curb Cuts	1) The curb cut closest to the entrance (brick) has a running slope measuring 10.2%. 2) The curb cut located to the left of the entrance: a) The running slope of the center slope measures 10.5%. **b) The landing at the top has a slope measuring 6.3%.
					Parking Spaces in Lot	The designated accessible parking spaces do not have a space identified as a "van accessible" parking space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
West Springfield	Senior Center @ 128 Park Street	00	01 & 02	No	Ramps	The ramp has lower handrails that are located at a height of 16 inches.
	Grove Village Community Room		03		Entrances (Other than Locked)	The designated accessible entrance door has hardware that is a thumb latch.
					Exterior Accessible Route	The walkway leading to the designated accessible entrance has a running slope measuring 17.9%.
	Mittineague School		04	Yes	None	
	New Tatham School		05	No	Parking Spaces in Lot	The "van-accessible" parking space has an access aisle that measures 7 feet 4 inches wide.
	Mittineague Congregational Church		06	Yes	None	
	Fausey School		07	No	Exterior Accessible Route	The accessible route to the designated accessible entrance requires using the driveway. The running slope measures between 9.4% and 12.6%.
					Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: a) There is only one designated accessible parking space provided for a lot containing 25-50 spaces. b) The designated accessible space is not "van-accessible". c) The space does not provide a sign at the head of the space.
	Senior High School		08	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
West Stockbridge	Town Hall	00	01	No	Entrances (Other than Locked)	The designated accessible entrance doors: a) The clear opening measures 28 inches. b) The door hardware is a thumb latch and requires the use of a thumb.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
West Tisbury	Public Safety Building @ 454 State Road	00	01	No	Parking Spaces in Lot	There are 3 designated accessible parking spaces provided: A) There are no signs provided at the head of each of the spaces. B) The access aisles abut a sidewalk. There are no curb cuts provided to access the sidewalk.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Westborough	Gibbons Middle School @ 20 Fisher Street	00	01 & 03	No	Curb Cuts	The curb cut, located near the designated accessible entrance, has a center running slope measuring 12.3% at the bottom and 12.6% in the middle.
					Parking Spaces in Lot	The designated accessible parking space that is configured as a van accessible space does not have a "van-accessible" sign.
	Hastings School @ 11 East Main Street		02	Yes	None	
	Mill Pond School @ 6 Old Hickory Path		04 & 05		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WESTFIELD	Road School @ 330 Southamptn Road	01	A	Yes	None	
	High School @ 177 Montgomery Road		B	No	Changes in Level Along Accessible Route	There is a change in level, at the curb cut located near the designated accessible parking space, measuring 3/4 of an inch.
					Curb Cuts	The curb cut, located near the designated accessible parking space, has a center running slope measuring 10.5%.
	Fort Meadow School @ 35 White Street	02	A		Changes in Level Along Accessible Route	1) There are changes in level, along the walkway that leads to the ramp, measuring 3/4 to 1 inch. 2) There are changes in level along the entire ramp measuring between 3/4 to 1 inch.
					Parking Spaces in Lot	There is no van accessible parking space provided.
					Ramps	The ramp has a running slope measuring 10.0% on the top of the 2nd run.
	Kennedy Apartment Complex @ Kasper Drive		B		Changes in Level Along Accessible Route	1) There are changes in level, along the walkway leading to the entrance, measuring 3/4 to 1 inch. 2) There is a change in level, at the landing to the entrance, that exceeds 1/2 inch.
					Curb Cuts	The curb cut, located at the designated accessible parking space, has a center running slope measuring 19.4%.
					Parking Spaces in Lot	The designated accessible parking space configured as van accessible is missing the "van-accessible" sign.
	Franklin Avenue School @ 22 Franklin Avenue	03	A		Changes in Level Along Accessible Route	There is a change in level at the base of the curb cut, located along the route from the driveway to the entrance, measuring 3/4 of an inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WESTFIELD	Franklin Avenue School @ 22 Franklin Avenue	03	A	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 3 1/2 feet to 2 1/2 feet.
					Parking Spaces in Lot	There are no designated accessible parking spaces provided near the designated accessible entrance used for polling.
					Ramps	The ramp at the entrance door does not provide handrails.
	Westfield Vocational Technical High School @ 33 Smith Avenue		B		Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 1 foot out. NOTE: At the time of the survey, the Asst.. Town Clerk did not know if the temporary ramp used added the 4 feet of landing.
					Parking Spaces in Lot	There is no sign at the head of one of the two designated accessible parking spaces.
					Interior Doors	There is a set of double doors on the interior of the building. Opened individually, each door does not provide a 32 inch clear opening. NOTE: During the survey, the Asst.. Town Clerk explained that the doors remained open during polling.
	Juniper Park Lab School @ 715 Western Avenue	04	A		Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible: A) There are no signs at the head of the space. B) There is a built up curb ramp protruding into the access aisle.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WESTFIELD	Highland School @ 34 Western Avenue	04	B	No	Changes in Level Along Accessible Route	1) There are a changes in level, along the sidewalk in front of the parking leading to the designated accessible entrance, measuring greater than 1/2 inch.
						2) There is a change in level, at the designated accessible entrance, measuring 2 inches.
					Interior Accessible Route	The path of travel is not the "same or similar for all persons entering the polling place". The path of travel to the polling area from the "accessible" entrance is much longer than the path of travel from the "inaccessible" entrance.
	Munger Hill School @ 33 Mallard Lane	05	A & B		Parking Spaces in Lot	There are no designated accessible parking spaces provided.
						NOTE: During the survey, the Asst.. Town Clerk stated that temporary spaces are provided during polling.
					Ramps	The ramp, provided in front of the designated accessible entrance, does not have handrails.
					Changes in Level Along Accessible Route	1) There are changes in level, along the sidewalk from the parking, measuring 3/4 to 1 inch.
						2) There is a change in level, at the entrance used for Precinct 5A, measuring 5 inches.
					Entrances (Other than Locked)	The designated accessible entrance door, for Precinct 5A, does not provide a 32 inch clear opening. The clear opening measures 30 inches.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) The access aisles, provided adjacent to the parking spaces, measure 3 1/2 feet wide. C) There are no curb cuts provided where the access aisles abut the sidewalk.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WESTFIELD	Blessed Sacrament Center @ 113 Holyoke Road	06	A	No	Exterior Accessible Route	The walkway, leading to the entrance landing, has a running slope measuring 10.2% at the bottom and 12.9% at the top,
					Parking Spaces in Lot	There are no signs at the head of the designated accessible parking spaces provided.
	Paper Mill School @ 148 Paper Mill Road		B		Changes in Level Along Accessible Route	1) There are changes in level, along the sidewalk leading from the parking to the entrance, measuring 3/4 to 1 inch. 2) There is a change in level, at the entrance landing, measuring 5 1/2 inches.
					Entrances (Other than Locked)	The designated accessible entrance door, for Precinct 5A, does not provide a 32 inch clear opening. The clear opening measures 30 inches.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided. A) There is no van accessible parking space provided. B) The access aisles, provided adjacent to the parking spaces, measure 3 1/2 feet wide. C) There are no curb cuts provided where the access aisles abut the sidewalk.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Westford	Abbot School @ 25 Depot Street	00	01 & 03	No	Parking Spaces in Lot	The designated accessible parking spaces provided in the lot: A) The spaces do not provide any access aisles. B) There is no van accessible space provided. NOTE: During the survey, Kaari explained that there are 4 temporary spaces provided near the polling entrance during polling.
					Ramps	The ramp provided has a running slope measuring 1.87:12 (15.6%).
	Blanchard Middle School @ 14 West Street		02		Changes in Level Along Accessible Route	There are changes in level measuring greater than 1/2 inch due to frost heaves leading from the designated accessible parking to the entrance.
					Curb Cuts	The curb cut located near the designated accessible parking spaces: A) The center running slope measures 1.38:24 (11%). **B) The left side running slope measures 10.2%. **C) The right side running slope measures 10.6%. **D) The area at the top of the curb cut has a slope measuring 3.4%.
	Robinson School @ 56 Concord Road		04		Parking Spaces in Lot	The access aisles for the designated accessible parking spaces abut a sidewalk. There are no curb cuts provided to access the sidewalk.
					Ramps	The ramp provided: A) The ramp does not provide the required handrails. **B) The cross slope of the ramp measured 3.5%. **C) The area at the end of the ramp has a slope measuring 4.7%.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Westford	Stony Brook School @ 9 Farmers Way	00	05	No	Parking Spaces in Lot	The designated accessible parking space that is configured as a van-accessible space is missing the "van-accessible" sign.
	Miller School @ 1 Mitchell Way		06		Changes in Level Along Accessible Route	There is a 3/4 inch change in level near the curb cuts at the designated accessible parking spaces.
					Parking Spaces in Lot	<p>The designated accessible parking spaces provided:</p> <p>A) The space that is configured as a van accessible space is missing the "van-accessible" sign.</p> <p>B) Some of the designated accessible parking spaces have access aisles that abut a sidewalk and do not provide a access aisle to access it.</p>

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Westhampton	Town Hall @ One South Road	00	01	No	Parking Spaces in Lot	There is one designated accessible parking space provided. The space measures 12 feet wide but no access aisle is provided.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Westminster	Meetinghouse School @ 8 South Street	00	01 & 02	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Weston	United Methodist Church @ 377 North Avenue	00	01	No	Entrances (Other than Locked)	The designated accessible entrance does not provided accessible door hardware. The current hardware is a door knob.
					Ramps	1) The permanent ramp: A) Handrails are only provided on the left side. B) The handrails on the left are not round or oval. Currently they are a flat configuration.
						2) The portable ramp: A) The running slope of the ramp measures about 16.0% - 18.0%. B) The portable ramp does not provide wheel guards or handrails.
	Saint Peter's Church @ 320 Boston Post Road		02	Yes	None	
	Greek Orthodox Church @ 57 Brown Street		03 & 04		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Westport	Legion Hall @ 489 Sanford Road	00	A	No	Entrances (Other than Locked)	The designated accessible entrance does not provide door hardware that is operable with a closed fist. The hardware provided is a door knob.
	Town Hall Annex @ 856 Main Road		B	Yes	None	
	Alice A. Macomber School @ 154 Gifford Road		C	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 49 inches.
	Briggs Road Fire Station @ 85 Briggs Road		D		Ramps	The handrails, provided on the ramp, are not round or oval. The handrails are flat.
	High School @ 19 Main Road		E	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Westwood	Senior Center @ 210 Nahatan Street	00	01	No	Parking Spaces in Lot	There are 5 designated accessible parking spaces provided in the lot. There are signs missing from the head of 2 of the spaces.
	Sheehan School @ 549 Pond Street		02	Yes	None	
	Paul Hanlon School @ 790 Gay Street		03		None	
	Downey School @ 250 Downey Street		04		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Weymouth	Wessagusset School @ 75 Pilgrim Road	00	01 & 02	No	Curb Cuts	The curb cut, located near the designated accessible entrance used for polling, has a center running slope measuring 9.2%.
	McCulloch School @ 182 Green Street		03		Parking Spaces in Lot	There are 4 designated accessible parking spaces provided in the lot: A) The space that is configured as van accessible does not provide a "van-accessible" sign. B) There is a sign missing from the head of one of the spaces. C) There are 2 access aisles that abut a sidewalk. There are no curb cuts provided.
	High School @ 1051 Commercial Street		04		Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut to access the sidewalk from the on-street parking, measuring 3/4 to 1 inch.
	Tufts Library @ 46 Broad Street		05		Changes in Level Along Accessible Route	There are changes in level, along the walkway leading to the entrance, measuring 3/4 to 1 inch.
					Exterior Accessible Route	The walkway, leading to the entrance, has a running slope measuring 9.1% in the middle, and 7.0% at the bottom.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided in the parking lot. A) There is no van accessible parking space provided. The width of the spaces measure 11 feet with a 4 foot access aisle adjacent to the spaces. A van accessible parking space needs an 8 foot access aisle. B) There is one sign provided for the 2 spaces.
	Abigail Adams Inter. @ 89 Middle Street		06 & 07		Changes in Level Along Accessible Route	There are changes in level, along the walkway leading to the entrance, measuring 3/4 to 1 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Weymouth	Abigail Adams Inter. @ 89 Middle Street	00	06 & 07	No	Parking Spaces in Lot	There are 2 designated accessible parking spaces provided in the parking lot. A) There is no van accessible space provided. B) There is one sign missing from the head of one of the spaces.
	Pingree School @ 1250 Commercial Street		08 & 11		Curb Cuts	The curb cut, located near the on street parking, has a center running slope measuring 11.1%.
	Murphy School @ 471 Front Street		09		Changes in Level Along Accessible Route	There are changes in level, along the accessible route from the parking to the ramp, measuring 3/4 to 1 1/4 inches.
					Curb Cuts	The curb cut, located at the on-street parking space, has a center running slope measuring 12.9%.
					Ramps	The ramp provided: A) The running slope of the ramp measures 10.0% at the top. B) The ramp is only 42 inches wide, measured between the handrails.
	William Seach School @ 770 Middle Street		10		Changes in Level Along Accessible Route	There are changes in level, along the accessible route from the parking to the entrance, measuring 3/4 to 1 inch.
					Parking Spaces in Lot	The designated accessible parking space configured as van accessible is missing the "van-accessible" sign.
	Nash School @ 1003 Front Street		12 & 13		Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut near the on-street parking, measuring 1 to 1 1/4 inches.
					Ramps	The ramp is only 41 inches wide, measured between the handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Weymouth	Ralph Talbot School @ 277 Ralph Talbot Street	00	14 & 15	No	Changes in Level Along Accessible Route	There is a change in level, at the base of the curb cut near the on-street parking, measuring 3/4 to 1 inch.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing measures 3 feet.
					Ramps	The ramp is only 42 inches wide, measured between the handrails.
	Alice Fulton School @ 245 Pond Street		16 & 17		Changes in Level Along Accessible Route	There are changes in level, along the accessible route from the parking to the entrance, measuring 3/4 to 1 inch.
					Exterior Accessible Route	The walkway/driveway, leading to the entrance, has a running slope measuring 7.1% in the middle.
					Ramps	There is a built up ramp to access the landing to the entrance. A) The running slope measures 10.3%. B) There are no handrails provided on either side. C) The ramp does not measure 48 inches wide.
	Union Street School @ 400 Union Street		18		Changes in Level Along Accessible Route	There are changes in level, along the walkway leading to the entrance, measuring 3/4 to 1 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Whately	Town Hall @ 218 Chestnut Plain Road	00	01	No	Entrances (Other than Locked)	The designated accessible entrance: A) The entrance doors does not provide hardware that is operable with a closed fist. A thumb latch is provided. B) The entrance threshold measures 3/4 to 1 inch. C) The entrance doors are a set of double doors. Opened individually, each door provides only 28 inches of clear opening.
					Interior Doors	There is a set of interior doors: A) Opened individually, each door provides 23 inches of clear opening. B) The hardware on the interior door is not operable with a closed fist. A door knob is provided.
					Parking Spaces in Lot	The designated accessible parking space configured as van accessible is missing the "van-accessible" sign.
					Ramps	The ramp provided: A) The running slope of the ramp measures 13.0% in the middle, and 13.3% at the top. B) There are no lower handrails provided. C) The upper handrails provided are not round or oval.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Whitman	Town Hall @ 54 South Avenue	00	01, 02, 03 & 04	No	**Comments	**At the time of the survey, the parking lot had just been repaved. The Clerk explained the layout of the lot and described the parking that would be striped. The features that were explained would be compliant with the polling regulations.
					Ramps	The running slope of the ramp measures 9.6% and 9.9% at the top of the 1st run down.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wilbraham	Community Center @ 88 Stony Hill Road	00	A	No	Parking Spaces in Lot	The designated accessible parking spaces do not have an access aisle adjacent to them.
	Stony Hill School @ 675 Stony Hill Road		B		Parking Spaces in Lot	The designated accessible parking spaces: A) Both spaces do not provide a sign at the head of the spaces. B) The space that is configured as van accessible does not provide a "van-accessible" sign.
	Memorial School @ 310 Main Street		C		Curb Cuts	There is a built up curb ramp provided across for the parking. The center running slope measures 12.0%.
					Parking Spaces in Lot	There is no van accessible parking space provided.
					Ramps	The ramp provided at the entrance door: A) The running slope measures 13.2%. B) The ramp measures 36 inches wide. C) The ramp does not provide any handrails.
	Soule Road School @ 300 Soule Road		D		Curb Cuts	The curb cut, provided at the entrance across from the parking, has a center running slope measuring 14.0%.
					Parking Spaces in Lot	The designated accessible parking space that is properly configured as van accessible does not provide a "van-accessible" sign.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Williamsburg	Anne T. Dunphy School @ 1 Petticoat Hill Road	00	01	No	Parking Spaces in Lot	There are 3 designated accessible parking spaces provided. A) There are no access aisles provided adjacent to any of the spaces. B) There are no signs at the head of any of the spaces.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Williamstown	Elementary School @ 115 Church Street	00	01, 02 & 03	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wilmington	West Intermediate School @ 22 Carter Lane	00	01 & 02	Yes	None	
	Wildwood School @ 182 Wildwood Street		03 & 04	No	Parking Spaces in Lot	The designated accessible parking space provided is configured as a van accessible space. However, the "van-accessible" sign is missing.
	Town Hall @ 121 Glen Road		05 & 06		Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. Currently, with one door open, the clear space provided measures less than 32 inches. NOTE: During the survey, Kathleen explained that during polling, both doors remain open.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Winchendon	Toy Town Elementary School @ 175 Grove Street	00	01, 02 & 03	No	Parking Spaces in Lot	There is 1 designated accessible parking space provided. A) There is no van accessible space provided. B) The access aisle, for the space, measures 3 feet wide. C) There is no sign at the head of the space. NOTE: During the survey, it was discussed that portable signs would be used during polling.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Winchester	Muraco School @ 33 Bates Road	00	01 & 02	No	Directional Signage	There are no signs directing people to the location of the designated accessible entrance.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided in the lot that do not provide a sign at the head of the spaces.
	McCall Middle School @ 458 Main Street		03 & 04		Ramps	The ramp provided at the location, the 3rd block up from the bottom, has a running slope measuring 9.2%.
	Vinson-Owen School @ 75 Johnson Road		05 & 06		Changes in Level Along Accessible Route	There are several changes in level along the walkway leading to doorway #34 measuring between 3/4 to 1 1/2 inches.
					Curb Cuts	There is an asphalt curb cut at the rear of the access aisle at the designated accessible parking space. The center running slope measures 12.2%.
					Directional Signage	There are no signs directing people to the designated accessible entrance used for polling.
					Entrances (Other than Locked)	The designated accessible entrance has hardware that is a doorknob.
					Exterior Accessible Route	The walkway leading to door #34, part of the accessible route to the designated accessible entrance used for polling, has a running slope measuring 10.0% at the bottom, 13.6% in the middle, and 7.7% at the top.
					Parking Spaces in Lot	The designated accessible parking space that is configured as a van accessible space does not provided a "van-accessible" sign.
	Lynch School @ 10 Brantwood Road		07 & 08		Changes in Level Along Accessible Route	The curb cut located near the designated accessible parking spaces has changes in level at the base measuring 1/2 to 3/4 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Winchester	Lynch School @ 10 Brantwood Road	00	07 & 08	No	Ramps	The ramp provided has a running slope measuring 9.2% at the bottom.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Windsor	Town Hall	00	01	No	Ramps	The ramp is missing the lower handrails.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Winthrop	Middle School	00	01, 02 & 05	Yes	None	
	High School		03 & 06	No	Parking Spaces in Lot	The designated accessible parking space provided in the lot: a) No access aisle is provided. b) There is no sign at the head of the space.
	Housing Complex on Golden Drive		04	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WOBURN	Joyce Jr High @ 50 Locust Street	01	01	No	Changes in Level Along Accessible Route	There are changes in level along the accessible route measuring greater than 1/2 inch.
					Parking Spaces in Lot	The designated accessible parking spaces do not have a sign at the head of the spaces.
	Clapp School @ Arlington Road and Hudson Street		02	Yes	None	
	Shamrock School @ 50 Green Street	02	01 & 02	No	Parking Spaces in Lot	The designated accessible parking space that is configured as a van accessible space does not provide a "van accessible" sign.
	Hurld School Cafeteria and Gymnasium @ Bedford Road	03			Changes in Level Along Accessible Route	There are changes in level along the sidewalk, leading to the main entrance, measuring greater than 1/2 inch.
					Interior Doors	There is a set of double doors along the interior path of travel to the voting area. The clear width, when one side is open, measures 27 inches.
	Wyman School @ Main Street and Eaton Avenue	04	01		Changes in Level Along Accessible Route	There are changes in level along the accessible route to the designated accessible entrance that measures greater than 1/2 inch.
	Senior High School @ 88 Montvale Avenue		02		Changes in Level Along Accessible Route	There is a change in level, at the end of the walkway leading to the parking, that measures 3/4 - 1 inch.
	Goodyear School @ Orange Street	05	01 & 02		Ramps	The ramp provides handrails on both sides of the ramp. However, the bottom rail is missing for a portion of one side.
	Altavesta School @ 990 Main Street	06			Changes in Level Along Accessible Route	There is a change in level at the base of the ramp that measures greater than 1/2 inch.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WOBURN	Old Reeves School @ Lexington Street	07	01 & 02	No	Changes in Level Along Accessible Route	There are changes in level along the accessible route, from the parking to the door, that measures greater than 1 inch.
					Entrances (Other than Locked)	There is no level area provided on the exterior of the designated accessible entrance.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WORCESTER	Unitarian Universalist Church @ 90 Holden Street	01	01	No	Exterior Accessible Route	The walkway, leading to the main entrance, has running slopes measuring 6.2% at the bottom, 6.3% in the middle and 6.2% at the top.
	Saint Georges Church Hall @ 40 Brattle Street		02		Ramps	The ramp provided: A) The running slope measures 9.6% at the bottom, 10.0% in the middle and 9.8% at the top. B) There are no handrails provided on the left side of the ramp. C) The handrails provided on the right side of the ramp are not round or oval.
	Forest Grove School @ 495 Grove Street		03	Yes	None	
	Flagg Street School @ 115 Flagg Street		04	No	Entrances (Other than Locked)	The designated accessible entrance: A) The door has a threshold measuring 1 1/2 inches. B) There is no 5-foot level landing provided on the exterior of the door.
	Norrback School @ 44 Malden Street	02	05	Yes	None	
	Salem Covenant Church @ 215 East Mountain Street		01		None	
	Greendale Fire Station @ 438 West Boylston Street		02		None	
	Thorndyke Road School @ 30 Thorndyke Road		03		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WORCESTER	Arts Magnet School @ St. Nicholas Avenue	02	04	No	Entrances (Other than Locked)	The designated accessible entrance door only provides a 27 inch clear opening.
					Interior Doors	There is an interior door that provides a clear opening measuring 27 inches.
	Multi Purpose Building @ 180 Constitution Avenue		05	Yes	None	
	Wawecus Road School @ 20 Wawecus Road	03	01	No	Exterior Accessible Route	The walkway, leading to the entrance, has running slopes measuring 6.9% path the bottom, 10.2% in the middle and 12.0% at the top.
					Lighting	There are no lights provided within the parking lot.
	Worcester Vocational @ 26 Salisbury Street Building G		02 & 04	Yes	None	
	McGrath School @ 493 Grove Street		03	No	Changes in Level Along Accessible Route	There is a change in level, at the designated accessible entrance, measuring 1 inch.
					Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. Currently there is a 1 1/2 foot landing.
	First Assembly of God @ 30 Tyler Prentice Road		05	Yes	None	
	Mount Carmel Recreation Center @ 10 Mulberry Street	04	01 & 02		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WORCESTER	Plumley Village East @ 16 Laurel Street	04	03	Yes	None	
	Friendly House @ 36 Wall Street		04	No	Changes in Level Along Accessible Route	There are changes in level, along the walkway leading to the entrance, measuring up to 3 inches.
	Lincoln Park Tower @ 11 Lake Avenue		05	Yes	None	
	Addison Apartments @ Addison Street	05	01		None	
	East Middle School @ 420 Grafton Street		02 & 05		None	
	Lake Park Community House @ 264 Lake Avenue		03	No	Entrances (Other than Locked)	The designated accessible entrance door has hardware that is not operable with a closed fist. There is a door knob provided.
					Ramps	The ramp provided: A) The running slope of the ramp measures 10.8%. B) There is only one upper handrail provided on one side of the ramp. One side does not provide any handrails. C) The upper handrail provided is not round or oval.
	Southeast Fire Station @ 745 Grafton Street		04	Yes	None	
	Union Hill School @ 86 Dorchester Street	06	01		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WORCESTER	Senior Center @ 128 Providence Street	06	02 & 03	Yes	None	
	Quinsigamond Village N.C. @ 16 Greenwood Street		04	No	Changes in Level Along Accessible Route	There is a change in level, at the asphalt landing, measuring 2 inches.
					Entrances (Other than Locked)	The designated accessible entrance door has a 1 inch threshold.
	Greenwood Gardens @ 337 Greenwood Street		05		Entrances (Other than Locked)	The designated accessible entrance: A) There is no 5-foot level landing provided on the exterior of the entrance door. The slope measures 3.3%. B) The door provides only 29 inches of clear opening.
					Exterior Accessible Route	1) The path of travel is not the "same or a substantially similar distance for all persons entering the polling place". The curb cut, to access the sidewalk to the entrance is located 800 yards away from the parking. 2) The walkway, leading to the designated accessible entrance has running slopes measuring 7.9% at the top and 6.8% in the middle.
	Beaver Brook Community Building @ 9 Mann Street	07	01	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WORCESTER	Gates Lane School @ 1238 Main Street	07	02	No	Parking Spaces in Lot	The designated accessible parking spaces provided: A) There is no van accessible space provided. B) The spaces do not provide an access aisle adjacent to the spaces.
	Coes Pond Village @ 39 First Street		03	Yes	None	
	Sullivan Middle School @ 140 Apricot Street		04 & 5		None	
	Code Enforcement Department @ 25 Meade Street	08	01		None	
	Canterbury Community School @ 125 Canterbury Street		02		None	
	Saint Peter's Church Hall @ 929 Main Street		03	No	Entrances (Other than Locked)	The designated accessible entrance is a set of double doors. Each door opened individually provides a clear opening measuring 26 1/2 inches.
					Interior Doors	There is a set of double doors, near the entrance, when opened individually provides a clear opening of 26 1/2 inches.
	Webster Square Towers @ 1050 Main Street		04	Yes	None	
	Harry Sherry Fieldhouse @ 55 Camp Street		05		None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
WORCESTER	Temple Emanuel @ 280 May Street	09	01 & 02	No	Curb Cuts	The curb cut, located near the entrance, has a center running slope measuring 19.8%.
	Chandler Magnet School @ 525 Chandler Street		03	Yes	None	
	West Tatnuck School @ 300 Mower Street		04		None	
	Tatnuck School @ 1083 Pleasant Street		05	No	Changes in Level Along Accessible Route	There is a change in level, where the dirt pathway meets the asphalt, measuring 1 inch.
					Exterior Accessible Route	The accessible path of travel to the designated accessible entrance is a dirt pathway.
	Elm Park Towers @ 425 Pleasant Street	10	01 & 03		Entrances (Other than Locked)	The designated accessible entrance door does not provide hardware that is operable with a closed fist. There is a door knob provided.
	Elm Park Community School @ 23 North Ashland Street		02		Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The walkway slopes to the door.
	Chandler Elementary School @ 114 Chandler Street		04		Parking Spaces in Lot	The designated accessible parking spaces have access aisles that abut a sidewalk. There are no curb cuts provided.
	Murray Avenue Apartments @ 50 Murray Avenue		05	Yes	None	

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Worthington	Town Hall @ 160 Huntington Road	00	01	No	Parking Spaces in Lot	The designated accessible parking space does not provide a painted access aisle beside the space.
					Ramps	The ramp provided has running slopes measuring 10% at the top and the middle, and 9.7% at the bottom.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Wrentham	Delaney School @ Taunton Street	00	01, 02 & 03	No	Parking Spaces in Lot	The designated accessible parking space is configured as a van accessible space. However, there is no "van-accessible" sign at the head of the space.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Yarmouth	First Congregational Church @ Route 6A	00	01	No	Entrances (Other than Locked)	The designated accessible entrance does not provide a 5-foot level landing on the exterior of the door. The landing has a slope measuring 6.6%.
					Parking Spaces in Lot	There are 3 designated accessible parking spaces provided in the lot. There are no access aisles provided adjacent to any of the spaces.
					Ramps	The ramp has a running slope measuring 13.9% at the bottom.
	Senior Center @ Forest Road		02 & 04 (Formerly precincts 2 & 7)		Curb Cuts	The curb cut, located at head of the access aisle for the parking, has a center running slope measuring 16.6%.
					Entrances (Other than Locked)	1) The designated accessible entrance for Precinct 2, does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 5.2%. 2) The designated accessible entrance for Precinct 4, does not provide a 5-foot level landing on the exterior of the door. The slope of the landing measures 7.3%.
					Parking Spaces in Lot	There are 2 designated accessible parking spaces provided in the lot: A) There is no van accessible parking space provided. B) There are no signs at the head of the spaces.
	Town Hall Hearing Room @ 1146 Route 28		03		Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
					Curb Cuts	The curb cut, located to the right of the designated accessible parking spaces, has a center running slope measuring 10.3% at the top.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.

Massachusetts Polling Place Accessibility Survey Results

Municipality	Polling Location	Ward	Precinct(s)	Location Complies	Violation Category	Violation Notes
Yarmouth	Mattacheese Middle School @ Higgins Crowell Road	00	05 & 06 (Formerly precincts 4, 5 & 6)	No	Parking Spaces in Lot	The designated accessible parking space that is configured as van accessible is missing the "van-accessible" sign.
	Kings Way Meeting House @ 68 Kings Circuit		07 (New Location: Formerly at the Senior Center)		Parking Spaces in Lot	The designated accessible parking provided in the lot: A) There is no van accessible parking space provided. B) There is no curb cut provided where the access aisle abuts the sidewalk.
					Ramps	The ramp: A) The running slope of the ramp measures 12.0%. B) The handrails: I) There are no handrails provided on the right side of the ramp. II) There is no lower handrail provided on the left side of the ramp. III) The upper handrail, located on the left side of the ramp, is located at a height of 43 inches.

** indicates that although these features are not addressed in 950 CMR 51:00, they do make accessing the polling location difficult, if not impossible.

This document was prepared by the Massachusetts Office on Disability.