



MAURA T. HEALEY
GOVERNOR

KIMBERLEY DRISCOLL
LIEUTENANT GOVERNOR

TERRENCE M. REIDY
SECRETARY

The Commonwealth of Massachusetts
Executive Office of Public Safety and Security
Department of Fire Services

P.O. Box 1025 ~ State Road

Stow, Massachusetts 01775

Telephone (978) 567~3100

www.mass.gov/dfs



ANTHONY P. CAPUTO
CHAIRMAN

6/2/2023

Leo Landry Sr.
[REDACTED]
[REDACTED]

Official use Only

527 CMR 12.00, Rule 10

Board of Fire Prevention Regulations
527 CMR 12:00 Interpretation Committee
Department of Fire Services
PO Box 1025, State Road
Stow, MA 01775

Background:

Request for Interpretation Relative to 527 CMR 12.00, Rule 10.

Question # 1:

If the inspector fails to meet the required 24 hour window for inspection, After proper notification in writing, May the excavation be closed without further inspection?

Response: Yes

Question #2:

If the inspector fails to meet the required 72 hour window for inspection After proper notification in writing, may the exterior or interior installation be closed without further inspection?

Response: Yes

If you have any questions or need any additional information, please contact me.

Sincerely,

Anthony P. Caputo, Chairman
Board of Fire Prevention Regulations