

From: [REDACTED] <reply+2ff6ab505074c1d3@formstack.com>
Sent: Saturday, January 02, 2016 6:15 PM
To: RegReform (ANF)
Subject: A Clearer Code: Regulatory Reform

Formstack Submission for form A Clearer Code: Regulatory Reform

Submitted at 01/02/16 6:14 PM

Name (optional)::	Marcus Phelps
Company/Organization (if applicable) (optional)::	
Address (optional)::	[REDACTED]
Primary Phone (optional)::	
Email (optional)::	[REDACTED]
CMR Number (If known): :	521 CMR 28.12
General Regulatory Themes::	Building Codes/Accessibility Standards
Please list the Agency or Agencies affiliated with this regulation::	
Describe the regulatory issue or observation::	Frequency and cost of inspection needs to be evaluated based on the type of lift installed and the amount of use. Over the years there has been an increase in the cost for inspections that seems to be excessive for houses of worship and requiring an annual inspection seems excessive.
Suggestions for improvements to the regulation::	Set a standard schedule for inspection of all lifts in houses of worship. Have a different inspection fee schedule for new installations and re-inspection of existing lifts.

[Terms](#) | [Privacy](#)

Copyright © 2016 Formstack, LLC. All rights reserved.

This is a customer service email.

Formstack, LLC
8604 Allisonville Rd.
Suite 300
Indianapolis, IN 46250