



The Commonwealth of Massachusetts
Executive Office of Public Safety and Security
Department of Fire Services



CHARLES D. BAKER
GOVERNOR

 KARYN E. POLITO
LT. GOVERNOR

 DANIEL BENNETT
SECRETARY

P.O. Box 1025 ~ State Road

Stow, Massachusetts 01775
(978) 567~3100 Fax: (978) 567~3121
www.mass.gov/dfs

PETER J. OSTROSKY
STATE FIRE MARSHAL

To: Heads of Fire Departments

From: Peter J. Ostroskey

Date: November 1, 2018

Subject: **Hydrolevel Recalls Controllers for Slant/Fin Boilers
 Due to Fire Hazard**

Slant/Fin, a manufacturer of residential and commercial boilers, in conjunction with the U.S. Consumer Product Safety Commission (CPSC), has announced a recall of a certain boiler controller due to potential malfunction in the recalled controller that can cause the boiler to overheat, posing a fire hazard.

This recall involves the Hydrolevel HydroStat Model 3000 boiler controller which is a black rectangular control unit for residential Slant/Fin VSPH boilers. The unit has six small LED lights and the word 'Hydrostat' on the front. The controller is labeled as HydroStat on the front and HydroStat Model 3000 on the back.



Consumers with Slant/Fin model VSPH boilers should immediately contact a qualified contractor to schedule a free repair.

A copy of the press release and the safety notice are enclosed.

If you receive inquiries please immediately direct them to contact Slant Fin at 800-873-4346 from 9 a.m. to 5 p.m. ET, Monday through Friday or Hydrolevel at 800-654-0768 from 8 a.m. to 5 p.m. ET, Monday through Friday or online at www.hydrolevel.com