



MAURA T. HEALEY
GOVERNOR

KIMBERLEY DRISCOLL
LIEUTENANT GOVERNOR

TERRENCE M. REIDY
SECRETARY

The Commonwealth of Massachusetts
Executive Office of Public Safety and Security
Department of Fire Services

P.O. Box 1025 ~ State Road

Stow, Massachusetts 01775

Telephone (978) 567~3100

www.mass.gov/dfs



LARRY S. FISHER
CHAIRMAN

February 6, 2025

Official use Only

210.12, 210.8

[REDACTED]
[REDACTED]
[REDACTED]
Board of Fire Prevention Regulations
527 CMR 12:00 Interpretation Committee
Department of Fire Services
PO Box 1025, State Road
Stow, MA 01775

Request for Interpretation submitted by [REDACTED] on January 13, 2025.

Background:

Request for Interpretation Relative to 527 CMR 12.00, NEC 210.12, 210.8

Question 1: Does a replacement furnace need to be ArcFault protected?

Response: No

Question 2: Does a replacement furnace need to be GFCI protected?

Response: No

If you have any questions or need any additional information, please contact me.

Sincerely,

Larry S. Fisher

Larry S. Fisher, Chairman
Board of Fire Prevention Regulations