

MAURA T. HEALEY GOVERNOR

KIMBERLEY DRISCOLL LIEUTENANT GOVERNOR

TERRENCE M. REIDY SECRETARY

The Commonwealth of Massachusetts Executive Office of Public Safety and Security Department of Fire Services

P.O. Box 1025 ~ State Road

Stow, Massachusetts 01775 Telephone (978) 567~3100

www.mass.gov/dfs



LARRY S. FISHER CHAIRMAN

Official use Only

250.140(A)&(B)

Article

September 5, 2024



Board of Fire Prevention Regulations 527 CMR 12:00 Interpretation Committee Department of Fire Services PO Box 1025, State Road Stow, MA 01775

Code Change Proposal submitted by

on April 11, 2024

Background:

Request for Interpretation Relative to 527 CMR 12.00, NEC 250.140(A)&(B)

Question 1: When an existing one and two-family dwelling units electrical service is replaced in accordance with article 230.85, the neutral and grounding conductors are separated in the panel. Does the existing 2-wire cable that feeds the clothes dryers, cooktop, wall oven, and range also need to be replaced to comply with article 250.140(A)&(B).

Response: No Response

Note: The question may be resubmitted in the future. Different appliances could have different responses.

If you have any questions or need any additional information, please contact me.

Sincerely,

Larry S. Fisher, Chairman

Board of Fire Prevention Regulations