



MAURA T. HEALEY  
GOVERNOR

KIMBERLEY DRISCOLL  
LIEUTENANT GOVERNOR

TERRENCE M. REIDY  
SECRETARY

*The Commonwealth of Massachusetts*  
*Executive Office of Public Safety and Security*  
*Department of Fire Services*

*P.O. Box 1025 ~ State Road*

*Stow, Massachusetts 01775*

*Telephone (978) 567~3100*

*www.mass.gov/dfs*



ANTHONY P. CAPUTO  
CHAIRMAN

June 2, 2023

***Official use Only***

Article 70.11

Bill Clinton

[REDACTED]  
[REDACTED]  
[REDACTED]

[REDACTED]

Board of Fire Prevention Regulations  
527 CMR 12:00 Interpretation Committee  
Department of Fire Services  
PO Box 1025, State Road  
Stow, MA 01775

**Background:**

Request for Interpretation Relative to Article 230.82

**Question # 1:**

For Single and Two family existing homes when installing Power Source Production Source Systems (Solar) by way of a Supply Side Connection, is the intent to disallow said Supply Side Connection inside the interior service panel and install the Supply Side Connection outside ONLY, such as in a tap box or meter main to treat this as an emergency disconnect?

**Response:** No

**Question #2:**

Does the Mass Amendments 2023 230.85 allow the Supply Side Connection (Solar) to be performed INSIDE the interior service panel, and extend the tap conductors unfused back outside to the 1st overcurrent protection device?

**Response:** Question was withdrawn by requestor.

**Question #3:**

Is the intent of 2023 705.11(D) to adhere to Article 230 VI through VII to keep all taps and connections OUTSIDE of the structure, and treat the Power Source production Equipment as an Emergency Disconnect on Single and Two Family existing dwellings?

**Response:** Question was withdrawn by requestor.

If you have any questions or need any additional information, please contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "A. P. Caputo", written in a cursive style.

Anthony P. Caputo, Chairman  
Board of Fire Prevention Regulations