

CHARLES D. BAKER GOVERNOR

> KARYN E. POLITO LIEUTENANT GOVERNOR

MIKE KENNEALY SECRETARY OF HOUSING AND ECONOMIC DEVELOPMENT Commonwealth of Massachusetts Division of Professional Licensure Office of Public Safety and Inspections

1000 Washington Street, Suite 710 Boston, Massachusetts 02118 EDWARD A. PALLESCHI UNDERSECRETARY OF CONSUMER AFFAIRS AND BUSINESS REGULATION

LAYLA R. D'EMILIA COMMISSIONER, DIVISION OF PROFESSIONAL LICENSURE

## **BOARD OF BUILDING REGULATIONS AND STANDARDS**

## **DRAFT MEETING MINUTES**

A virtual meeting of the *Fire Protection Fire Prevention Committee (FPFP) of the Board of Building Regulations and Standards* was held on:

March 31, 2021 beginning @ 9:06 am and ending @ 11:30 pm.

## Roll Call.

Robert Carasitti, Chair	🛛 present 🔲 absent	Louise Vera	🛛 present 🗌 absent
Dave LeBlanc	present absent	<architect -vacant=""></architect>	present 🛛 absent
Commissioner DPL designee	🛛 present 🗌 absent	Fire Marshal designee	present absent
Jeff Putnam for the Commissioner		Jen Hoyt for the Fire Marshal	
Paul Donga	🛛 present 🗌 absent	Joseph Castronovo (9:40)	🛛 present 🗌 absent
Fredrick L. Tustin	🗌 present 🔀 absent		

## Agenda:

Review Draft Meeting Minutes from March 10, 2021 & March 17, 2021.
Both the 3/10/21 and 3/17/21 minutes were reviewed and approved 6-0-0 (JC not yet in attendance).

- 2. Review the use of fire testing standards not referenced in 780 CMR (FPFP Task #21-001). *Tabled until April 14, 2021 Meeting.*
- 3. Review of 2021 IBC Chapter 9 for the 10<sup>th</sup> Edition of 780 CMR (FPFP Task #21-002).
  - Reviewed Section 907 and fire code references.
  - Reviewed Section 901 at length and discussion on fire protection documents.
  - Jake Nunnemacher reviewed status of smoke detector testing and criteria on the national level (specifically UL updates). In short, the latest criteria as of 2022 will be for mutli-criteria devices and the need to specify photelectric may be changing.
- 4. Review for conflicts and recommendations on fire protection criteria in the following:
  - a. 2021 IBC Chapter 4 (FPFP Task #21-002.C4)

- b. 2021 IBC fire protection provisions for exterior walls in Chapters 14 & 26 (FPFP Task #21-002.C14&C26).
- c. 2021 IEBC fire protection provisions and Chapter 34 Committee review conclusions for conflicts or recommendations (FPFP Task #21-002.IEBC).

This is a placeholder until the Chapter 9 efforts are complete.

5. Discuss other matters not reasonably anticipated 48 hours in advance of meeting. *No new matters were discussed.* 

Documents used in the meeting included the following:

• 210330 RMC IBC 2021 Chapter 9 with 2018 efforts and 903