

DCR Facilities with Changes to Regulated Status in Permit Year 3

DCR reviewed factors which impact the regulated status during a detailed review of all DCR facilities in support of PCP and NSIR planning efforts. The following list explains the reasoning of each regulated status change. All DCR facilities can be viewed at:

<https://vhb.maps.arcgis.com/apps/webappviewer/index.html?id=1fffa8d7b9e144e793dcffb0445846e2>

Newly Identified Regulated Facility

Detailed review identified that this facility is owned by DCR and had not previously been included in the facility list:

- Brook Farm

Facilities Changed from Unregulated to Regulated

These facilities were previously identified as not having drainage infrastructure or development that likely resulted in a points source discharge, but the detailed review found channelized flow which is a point source per the MS4 and therefore these facilities were revised to be considered regulated:

- Cutler Park Reservation
- Paul Revere Park
- Red Wing Bay
- Whalom Lake Access
- Wilson Mountain Reservation
- Ed Burns Arena

Detailed review identified that this leased facility is owned by DCR and is regulated as part of DCR's MS4:

- Franklin Park Annex

A 2021 construction project constructed impervious surface and drainage infrastructure on previously undeveloped land at these facilities thereby revising their regulated status:

- Fresh Pond Pathway
- Watertown Greenway

Facilities Changed from Regulated to Unregulated

The facilities below include property that is only partially within the urbanized area. The detailed review found the facility area within the urbanized area does not include a point source discharge and therefore is considered unregulated:

- Otter River State Forest
- Walden Pond State Reservation

During the detailed review updates to the facility boundary indicated that this facility contains only non-discharging area and is therefore considered unregulated:

- Sudbury River Watershed