

CHARLES D. BAKER GOVERNOR

KARYN E. POLITO LIEUTENANT GOVERNOR

MIKE KENNEALY SECRETARY OF HOUSING AND ECONOMIC DEVELOPMENT Commonwealth of Massachusetts Division of Professional Licensure Office of Public Safety and Inspections

1000 Washington Street, Suite 710 Boston, Massachusetts 02118 EDWARD A. PALLESCHI UNDERSECRETARY OF CONSUMER AFFAIRS AND BUSINESS REGULATION

DIANE M. SYMONDS COMMISSIONER, DIVISION OF PROFESSIONAL LICENSURE

Agenda

Meeting of the Board of Elevator Regulations April 2, 2019 at 1:00 p.m. 1000 Washington Street Boston, MA 02118 1st Floor – Room 1C

1. Roll Call

- Stephen Sampson, Chairman 🛛 present 🔾 absent
- John O'Donoghue
- David Gaudet
- Cheryl Davis
- David Morgan
- Brian Ronan
- Eric Morse
- Vacancy

- \Box present \Box absent \Box absent
 - \Box present \Box absent
 - present absent
 - present absent
- 2. 5 High Street Monson, MA Relief from Inspector's Report

524 CMR Section 17.03 - Hoistway vent not code compliant.

- 3. 1 Charles Street Boston, MA ASME A18.1-2014
 - (a) Section 2.1.1.4 Interlock requirement.
 - (b) Section 2.1.1.3 Doors cannot be more than 1" wider than the platform.
 - (c) Section 2.1.1.3 Doors must present a smooth surface not closer than $\frac{3}{8}$ " and not more than $\frac{3}{4}$ " from the platform floor.
 - (d) Glass must be laminated safety glass as required by applicable elevator codes.

- 4. 250 Franklin Street Boston, MA Variance request for a 1' deep pit and installation of "Gillespie Elevator" shallow pit elevator safety system due to the existing conditions of a loading dock located beneath the location of the elevator. Section 3.4 – Bottom and top clearances and run bys for cars and counterweight. Section 3.4.1 – Bottom car clearance
- 5. Approval of meeting minutes from March 26, 2019
- 6. Discussion of outside hoists.
- 7. Old business (The Board may or may not discuss):
 - 55 South Street Hingham, MA Placed on hold: Deadline April 18, 2019
 - Discussion regarding the adoption of the 2016 elevator code.
- 8. Matters not reasonably anticipated 48 hours in advance of meeting.