Crow Lane Landfill
Complaint Response Report

ver. 08/09

Date: 1\15\10 Time of Complaint: 8:39 Am

Complaintant Response

Name: michael frey Time: 9:58 Am

Address 5 wilson way By Name: Peter Lidausis

Odor YES NO (circle one)

Other: _____ Initial: PL

Were odors detected during the response? Yes

Odor Intensity (1-5 scale) 1 Odor Duration: less than 1 min.

Odor Description/Type: H_2S

Location	H2S Readings During Response				Comments
In front of house	0.11	0.006	0.006	0.006	Very slight odor detected (H_2S)

Weather Conditions at time of response: 37°F

Wind: Direction (From) NNW Speed: 0-3 mph

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)