Crow Lane Landfill
Complaint Response Report

ver. 08/09

Date: 12/15/09 Time of Complaint: 4:02 pm

Complaintant Response

Name: Michael Frey Time: 4:15 pm

Address 5 Wilson Way By Name: Peter Lielausis

Odor YES NO (circle one)

Other: Initial: [illegible]

Were odors detected during the response? Yes

Odor Intensity (1-5 scale) 1-2 Odor Duration 4 25 min.

Odor Description/Type: H_2S

Location	H2S Readings During Response				Comments
Front of house	0.014	0.007	0.009		
W sided house	0.014	0.015	0.005		

Weather Conditions at time of response: 42°F

Wind: Direction (From) NA Speed: NA

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)