Crow Lane Landfill
Complaint Response Report

Date: 7/31/9 Time of Complaint: 7/30/9 @ 0300-0515

Complaintant	Response
Name: ALIDA FREY	Time 0928-1025
Address 5 WILSON WAY	By Name: MATTHEW VISCOVICH

Odor YES NO (circle one)

Other: _____ Initial: MV

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: _____

Odor Description/Type: 7/30 @ 2000, H_2S w/ HEADACHE. 7/31 @ 0315, BURNT SMELL w/ NAUSEA, HEADACHE, DRAINAGE. MR FREY WAS EXPERIENCED ELEVATED PACEMAKER RATES DURING EVENTS OF NOTICABLE H_2S. BURNT SMELL LIKENED TO LINGERING AROMA A HALF-HOUR AFTER BURNING TOAST.

Location	H2S Readings During Response				Comments
FRONT	0.001	0.003	0.003	0.003	WSW 3-8 mph
L FRONT	0.001	0.003	0.002	0.003	WSW 0-3
L REAR	0.001	0.11	0.002	0.003	EDDYING
R R	0.002	0.005	0.003	0.008	WSW 3-5
R F	0.003	0.003	0.003	0.007	WSW 5-10

Weather Conditions at time of response: MODERATE OVERCAST, BREEZY.

Wind: Direction (From) (SEE ABOVE) Speed: _____

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)

Crow Lane Landfill
Complaint Response Report

Date: 7/31/9 Time of Complaint: 7/30/9 @ 1810

Complaintant

Name: BILL WOODBURY

Address 3 CHARMINSKI DR.

Response

Time 1030-1058

By Name: MATTHEW VISCOVICH

Odor YES NO (circle one)

Other: _____ Initial: MV

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: _____

Odor Description/Type: _____

Location	H2S Readings During Response				Comments
FRONT	0.003	0.003	0.003	0.003	SSW 3-5 MPH
RF	0.003	0.003	0.003	0.003	SSE 0-5
R REAR	0.003	0.003	0.003	0.003	EDDYING.
L R	0.002	0.003	0.003	0.003	SSW 0-3
L F	0.003	0.003	0.003	0.003	

Weather Conditions at time of response: OVERCAST, BREEZY

Wind: Direction (From) (SEE ABOVE Speed: _____

Was Perimeter Landfill Survey Performed following the complaint? YES NO
(circle one)

Crow Lane Landfill
Complaint Response Report

Date: 7/31/9 Time of Complaint: _____

Complaintant | Response

Name: MARY WOLFE Time 1103 – 3/31

Address 16 ZABRISKIE DR By Name: MATTHEW YISCOVICH

Odor YES NO (circle one)

Other: _____ Initial: M

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: _____

Odor Description/Type _____

Location	H2S Readings During Response				Comments
FRONT	0.003	0.003	0.003	0.003	~~NEW~~ SE 3-5 MPH
L F	0.003	0.003	0.004	0.003	SE 0-3
L REAR	0.003	0.003	0.003	0.003	E 3-5
R R	0.003	0.003	0.003	0.003	E 0-3
R F	0.003	0.003	0.004	0.003	EDDY, 0-5
LIGHT POLE BEHIND #10	0.003	0.003	0.003	0.003	EDDY, 0-3

Weather Conditions at time of response: OVERCAST, BREEZY.

Wind: Direction (From) (SEE ABOVE) Speed: _____

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)

Crow Lane Landfill
Complaint Response Report

Date: 7/31/9 Time of Complaint: 7/30/9 @ 2043

Complaintant | Response

Name: Kim Jackson Time: 1134-1208

Address 3 Court Farm Ln. By Name: Matthew Viscovich

Odor YES NO (circle one)

Other: Initial: M

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration:

Odor Description/Type:

Location	H2S Readings During Response				Comments
Front	0.003	0.003	0.003	0.003	calm
L F	0.003	0.003	0.003	0.003	SSW 0-3
L Rear	0.003	0.003	0.003	0.003	NNE 0-3
R R	0.003	0.003	0.003	0.003	NNE 3-5
R F	0.003	0.003	0.003	0.003	NNE 0-3

Weather Conditions at time of response: Drizzle

Wind: Direction (From) (see above) Speed:

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)

Crow Lane Landfill
Complaint Response Report

Date: 7/31/9 Time of Complaint: _____

Complaintant | Response

Name: MARY WOLFE Time 1450-1528

Address 16 ZABRISKIE DR

By Name: MATTHEW VISCOVICH

Odor YES NO (circle one)

Other: _____ Initial: _____

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: _____

Odor Description/Type: _____

Location	H2S Readings During Response				Comments
FRONT	0.004	0.003	0.003	0.003	
[illegible] ROOM	0.000	0.001	0.001	0.001	
BATHROOM	0.001	0.002	0.002	0.002	
BACK STOOP	0.006	0.006	0.007	0.006	
BACK STOOP (BREATHING ZONE)	0.005	0.006	0.005	0.006	

Weather Conditions at time of response DRIZZLE, BREEZY.

Wind: Direction (From) ESE Speed: 0-3

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)

Crow Lane Landfill
Complaint Response Report

Date: 7/31/19 Time of Complaint: @ 0800

Complaintant Response

Name: Leo Rocco Time 1531-1558

Address 204 Low St By Name: Matthew Viscovich

Odor YES NO (circle one)

Other: Initial: M

Were odors detected during the response? YES

Odor Intensity (1-5 scale) 1 Odor Duration: Brief, intermittant.

Odor Description/Type: Sulphurous.

Location	H2S Readings During Response				Comments
Front L	0.005	0.13	0.009	0.005	
Rear L	0.007	0.007	0.007	0.007	
R B	0.007	0.006	0.006	0.006	
~~F~~ R	0.006	0.007	0.007	0.006	

Weather Conditions at time of response: Drizzle, Breezy.

Wind: Direction (From) SSE Speed: 0-5

Was Perimeter Landfill Survey Performed following the complaint? YES NO
(circle one)

Crow Lane Landfill
Complaint Response Report

Date: 8/3/9 Time of Complaint: @0700

Complaintant	Response
Name: JOHN ADAMS (?)	Time
Address CITY OF NEWBURYPORT	By Name: MATTHEW VISCOVICH

Odor YES NO (circle one)

Other: Initial:

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration.

Odor Description/Type:

Location	H2S Readings During Response				Comments
SEVERAL POINTS ALONG LOW ST S FROM CROW LN ALONG HALE ST, DOGTOWN DR, QUAIL RUN HOLLOW, CHARMINSKY, & WILSON WAY.	0.000				

Weather Conditions at time of response:

Wind: Direction (From) Speed:

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)

Crow Lane Landfill
Complaint Response Report

Date: 8/5/9 Time of Complaint: 1624

Complainant

Name: MARY WOLFE

Address 16 ZABRISKIE DR

Response

Time 1645-1724

By Name: MATTHEW VISCOVICH

Odor YES NO (circle one)
(ONE SMALL WHIFF)

Other: _____ Initial: MV

Were odors detected during the response? _____

Odor Intensity (1-5 scale) ≤1 Odor Duration VERY BRIEF

Odor Description/Type: H_2S

Location	H2S Readings During Response				Comments
FRONT	0.002	0.004	0.003	0.004	CALM
L FRONT	0.003	0.004	0.004	0.005	CALM
L REAR	0.004	0.004	0.005	0.004	WSW 0-3
R R	0.004	→			
R F	0.004	→			
BATHROOM	0.002	0.002	0.003	0.002	

Weather Conditions at time of response: HAZY, HOT, HUMID

Wind: Direction (From) WSW Speed: CALM – 3 MPH

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)

Crow Lane Landfill
Complaint Response Report

Date: 8-7-09 Time of Complaint: 3:00 PM

Complaintant Response

Name: Klodeski Time 5:15 PM

Address 18 wildwood dr. By Name: Austin Maynard

Odor YES (NO) (circle one)

Other: Initial: AM

Were odors detected during the response? NO

Odor Intensity (1-5 scale) — Odor Duration: complaint says 1 hour

Odor Description/Type Odor 2 hours ago, consistent w/ wind direction

Location	H2S Readings During Response				Comments
front corner of house	.003	.003			
Back corner	.003	.003			
Back middle	.003	.003			
Beach in garden	.003	.003			

Weather Conditions at time of response:

Wind: Direction (From) towards landfill, earlier, at time of complaint wind was coming this direction Speed:

Was Perimeter Landfill Survey Performed following the complaint? (YES) NO (circle one)

Crow Lane Landfill
Complaint Response Report

Date: 8-7-09 Time of Complaint: 12:35

Complaintant

Name: Mary Wolf

Address 16 Ziebinski St

Response

Time 1:15

By Name: Austin Magnant

Odor YES NO (circle one)

Other: _____ Initial: AM

Were odors detected during the response? No

Odor Intensity (1-5 scale) 0 Odor Duration _____

Odor Description/Type: odor hangs out in back of apartment (supposedly), spoke w/ neighbors working outside & mail woman who smelled nothing, near-by farm + industrial park more likely sources. No H_2S odor said by neighbors

Location	H2S Readings During Response				Comments
In house	.000	.001			
In hallway	.001	.001			
back lot Apt 16 middle	.001	.001			
Behind Apt 18	.000				
Behind Apt 14	.001	.002			
Behind Apt 10 corner light post					

Weather Conditions at time of response: Sunny, windy breezy

Wind: Direction (From) opposite from landfill Speed: _____

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)

Crow Lane Landfill
Complaint Response Report

ver. 08/09

Date: 8-7-09 Time of Complaint: 11:30 AM

Complaintant

Name:

Address
5 Wilson Way

Response

Time: 12:15 PM

By Name: Austin Magnant

Odor **YES** **NO** (circle one)

Other:

Initial: AM

Were odors detected during the response? No

Odor Intensity (1-5 scale) Odor Duration:

Odor Description/Type: this morning @ Breakfast - no odor but woman had headache man had sinus drainage, also happens nightly around 8:30-10 PM

Location	H2S Readings During Response				Comments
	high	med	low		
Front of house under oak tree	.001	.001	.002		
Back Middle of Yard	.001	.001			
Back corner	.002	.001	.002		
end of driveway	.002	.002			

Weather Conditions at time of response: Sunny

Wind: Direction (From) landfill Speed: light → breezy

Was Perimeter Landfill Survey Performed following the complaint? **YES** **NO** (circle one)