Crow Lane Landfill
Complaint Response Report

Date: 9/24/09 Time of Complaint: 9:04 Am

Complaintant Response

Name: Bill Woodbury Time: 9:13 Am

Address 3 Charmanski By Name: Peter Lielauis

Odor YES NO (circle one)

Other: _____ Initial: PL

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration NA

Odor Description/Type NA

Location	H2S Readings During Response				Comments
Back of house	0.002	0.002	0.001	0.000	No odors noticed by show

Weather Conditions at time of response 74°F, sunny

Wind: Direction (From) S Speed: 0-3 mph

Was Perimeter Landfill Survey Performed following the complaint? YES NO (circle one)