



# The Commonwealth of Massachusetts

Executive Office of Health and Human Services

Department of Public Health

Bureau of Environmental Health

Community Sanitation Program

5 Randolph Street

Canton, MA 02021

Telephone: 781 828-8046

Facsimile: 781 828-7703

Nicholas.Gale@state.ma.us

DEVAL L. PATRICK  
GOVERNOR

JOHN W. POLANOWICZ  
SECRETARY

CHERYL BARTLETT, RN  
COMMISSIONER

December 4, 2013

Joseph D. McDonald, Jr., Sheriff  
Plymouth County Correctional Facility  
26 Long Pond Road  
Plymouth, MA 02360

Re: Facility Inspection – Plymouth County Correctional Facility

Dear Sheriff McDonald:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Plymouth County Correctional Facility on November 4 and 5, 2013 accompanied by Captain Eugene Irvine, Environmental Health and Safety Officer. Violations noted during the inspection are listed below:

### HEALTH AND SAFETY VIOLATIONS

(\* indicates conditions documented on previous inspection reports)

#### Administration/Entrance Area

##### **Front Lobby**

##### *Main Area*

105 CMR 451.353\*  
105 CMR 451.353

Interior Maintenance: Ceiling vent dirty  
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

##### *Janitor's Closet*

105 CMR 451.353\*  
105 CMR 451.353\*

Interior Maintenance: Light shield missing  
Interior Maintenance: Ceiling vent dusty

##### *Male Bathroom*

105 CMR 451.123

Maintenance: Ceiling vent damaged, rusty

##### *Female Bathroom*

105 CMR 451.123\*  
105 CMR 451.123

Maintenance: Ceiling vent damaged, rusty  
Maintenance: Ceiling vent dusty

## **Main Hallway**

### *Janitor's Closet*

105 CMR 451.350

Structural Maintenance: Wall not easily cleanable, wall damaged

## **Female Locker Room**

105 CMR 451.353\*

Interior Maintenance: Ceiling vents damaged, rusty

### *Showers*

No Violations Noted

## **Male Locker Room**

105 CMR 451.123\*

Maintenance: Ceiling vents damaged, rusty

105 CMR 451.123\*

Maintenance: Ceiling vents dusty

105 CMR 451.123\*

Maintenance: Carpets damaged

105 CMR 451.350

Structural Maintenance: Ceiling leaking

105 CMR 451.123

Maintenance: No soap at handwash sink

### *Showers*

105 CMR 451.130\*

Plumbing: Plumbing not maintained in good repair, leak in shower # 1

105 CMR 451.123\*

Maintenance: Soap scum on walls in all showers

105 CMR 451.123

Maintenance: Shower tiles stained

## **Staff Gym**

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353

Interior Maintenance: Weight lifting equipment not easily cleanable, bench padding damaged

### *General Male Locker Room*

No Violations Noted

### *General Female Locker Room*

No Violations Noted

## **Administration Area – 1018**

### *Break Room*

FC 4-601.11(C)

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, Poland Spring tray dirty

FC 3-701.11(A)

Contaminated Food, Disposition: Unsafe, adulterated, or not honestly presented food not properly reconditioned or discarded, outdated milk left in refrigerator

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, toaster oven missing door

### *Male Bathroom*

105 CMR 451.123\*

Maintenance: Ceiling vent dusty

### *Female Bathroom*

105 CMR 451.123\*

Maintenance: Ceiling vent dusty

### *IPS Office*

105 CMR 451.353

Interior Maintenance: Floor dirty, appearance of mold on floor

FC 4-602.12(B)

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

FC 4-204.112(A)

Design and Construction, Functionality: No functioning thermometer in refrigerator

FC 4-601.11(A) Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, toaster oven dirty  
FC 4-601.11(C) Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, Poland Spring tray dirty

**Kitchen**

FC 6-201.11 Design, Construction and Installation: Floor not easily cleanable, floor damaged in many areas

*Staff Dining Area*

FC 4-601.11(A) Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, cereal tray dirty

FC 4-601.11(C) Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, Poland Spring tray dirty

FC 6-501.14 Maintenance and Operation; Cleaning: Ventilation Systems, ceiling vents dusty

*Staff Serving Line*

FC 6-201.11 Design, Construction and Installation: Floor not easily cleanable, floor damaged

FC 6-501.12(A) Maintenance and Operation; Cleaning: Facility not cleaned properly, ventilation hoods dirty

*Office*

No Violations Noted

*Office Bathroom*

No Violations Noted

*Dry Storage*

No Violations Noted

*Tool Closet*

FC 4-502.11(A) Maintenance and Operation, Utensils: Utensils not maintained in a state of good repair, green cooking spoon damaged

*Cooler # 2*

No Violations Noted

*Inmate Break Area*

No Violations Noted

*Inmate Bathroom*

FC 6-501.12(A) Maintenance and Operation; Cleaning: Facility not cleaned properly, ceiling vent dirty

*Janitor's Closet*

FC 6-501.12(A)\* Maintenance and Operation; Cleaning: Facility not cleaned properly, ceiling vent dirty  
FC 6-501.11 Maintenance and Operation; Repairing: Facility not in good repair, light out

*Freezer # 1*

No Violations Noted

*Cooler # 3*

No Violations Noted

*Cooler # 4*

No Violations Noted

*Cooler # 5*

FC 3-302.11(A)(4)

Preventing Food and Ingredient Contamination: Preventing cross contamination, herbs not appropriately covered

*Freezer # 6*

FC 3-302.11(A)(4)

Preventing Food and Ingredient Contamination: Preventing cross contamination, chicken not appropriately covered

**Prep Area**

FC 5-205.15(B)\*

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, leak at prep sink

FC 6-201.16(A)

Design, Construction, and Installation; Cleanability: Wall not easily cleanable, paint peeling

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, oven out-of-order

*Kettle Area*

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, light out

*Bakery Area*

FC 5-205.15(B)

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, sink leaking

FC 5-205.15(B)

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, cold water not working

**3-Bay Sink Area**

FC 5-205.15(B)

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, incorrect backflow preventer installed

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, standing water on floor

**Dishwashing Machine Area**

*Slop Sink*

FC 6-201.16(A)

Design, Construction, and Installation; Cleanability: Ceiling not easily cleanable, ceiling damaged above slop sink

FC 5-205.15(B)

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, slop sink leaking

**Medical Corridor**

105 CMR 451.350\*

Structural Maintenance: Ceiling leaking

105 CMR 451.353\*

Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

105 CMR 451.353

Interior Maintenance: Floor dirty, appearance of mold on floor

**HSU**

*Kitchen*

FC 4-204.112(A)\*

Design and Construction, Functionality: No functioning thermometer in refrigerator

FC 4-903.11(A)(2)\*

Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered

FC 4-601.11(A)

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, coffee maker dirty

<i>Room – M132</i> 105 CMR 451.126	Hot Water: Hot water temperature recorded at 86 <sup>0</sup> F
<i>Autoclave – M131</i> 105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty
<i>Pharmacy – M128</i> 105 CMR 451.126	Hot Water: Hot water temperature recorded at 71 <sup>0</sup> F
<i>Staff Bathroom</i> 105 CMR 451.126	Hot Water: Hot water temperature recorded at 71 <sup>0</sup> F
<i>Janitor's Closet – M127</i> 105 CMR 451.353* 105 CMR 451.353	Interior Maintenance: Ceiling vent dusty Interior Maintenance: Wet mop stored in sink
<i>Laboratory</i>	No Violations Noted
<i>Dentist – M124</i>	No Violations Noted
<i>Inmate Bathroom</i> 105 CMR 451.126 105 CMR 451.110(A)	Water Supply: No hot water supplied to handwash sink Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink
<i>Exam Room – M121</i> 105 CMR 451.126	Hot Water: Hot water temperature recorded at 73 <sup>0</sup> F
<i>Room – M119</i> 105 CMR 451.126	Hot Water: Hot water temperature recorded at 73 <sup>0</sup> F
<i>Handicap Bathroom</i>	No Violations Noted
<i>Cells</i>	No Violations Noted
<i>Chapel/Contact Room</i> 105 CMR 451.350* 105 CMR 451.353 105 CMR 451.353* 105 CMR 451.353*	Structural Maintenance: Wall not easily cleanable, water leak behind wall Interior Maintenance: Wall dirty Interior Maintenance: Carpet dirty Interior Maintenance: Air vent dirty
<b><u>Laundry</u></b> 105 CMR 451.353* 105 CMR 451.353 105 CMR 451.130	Interior Maintenance: Ceiling vents dusty Interior Maintenance: Floor not maintained in good repair, paint peeling Plumbing: Plumbing not maintained in good repair, drinking fountain out-of-order
<i>Janitor's Closet</i> 105 CMR 451.353*	Interior Maintenance: Light shield missing
<i>Office</i>	No Violations Noted

*Chemical Closet*

No Violations Noted

**Maintenance**

105 CMR 451.353  
FC 4-501.11(B)

Interior Maintenance: Wet mop stored on floor  
Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets dirty

*Small Tool Room*

105 CMR 451.353\*

Interior Maintenance: Light shield missing

*Bathroom*

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

*Office*

No Violations Noted

*Office Bathroom*

105 CMR 451.110(A)

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

**Inmate Bathroom – 1058**

105 CMR 451.123\*

Maintenance: Floor damaged, paint peeling

**Loading Dock**

105 CMR 451.350\*

Structural Maintenance: Garage doors not rodent and weathertight

**Gymnasium**

105 CMR 451.353\*  
105 CMR 451.350  
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty  
Structural Maintenance: Floor not easily cleanable, baseboard missing around floor  
Interior Maintenance: Ceiling ventilation missing diffusers

**Hallway**

*Janitor's Closet - 1084*

105 CMR 451.353\*  
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty  
Interior Maintenance: Floor dirty

*Staff Bathroom – 1090*

105 CMR 451.123\*

Maintenance: Ceiling vent dusty

*Janitor's Closet – 1095*

105 CMR 451.130\*  
105 CMR 451.353\*  
105 CMR 451.353\*

Plumbing: Plumbing not maintained in good repair, faucet leaking  
Interior Maintenance: Ceiling vent dusty  
Interior Maintenance: Floor not maintained in good repair, paint peeling

*Staff Bathroom – 1098*

105 CMR 451.123

Maintenance: Ceiling vent dusty

*Staff Bathroom – 1099*

No Violations Noted

*Staff Bathroom – 1107*

105 CMR 451.110(A)

Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink

*Janitor's Closet – 1108*

105 CMR 451.353\*  
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty  
Interior Maintenance: Floor dirty

*Unit Manager's Office*

No Violations Noted

*Staff Bathroom – 1102*

105 CMR 451.123

Maintenance: Ceiling damaged

*Classroom – 1110*

105 CMR 451.353  
105 CMR 451.353

Interior Maintenance: Ceiling vents dusty  
Interior Maintenance: Ceiling dirty

**Library**

105 CMR 451.353

Interior Maintenance: Ceiling vents dusty

**Human Services**

*Break Room*

FC 4-601.11(A)\*

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, toaster oven dirty

FC 4-601.11(A)\*

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, coffee maker dirty

FC 3-302.11(A)(4)

Preventing Food and Ingredient Contamination: Preventing cross contamination, food not appropriately covered

FC 4-903.11(A)(2)

Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered

*Offices*

105 CMR 451.353  
105 CMR 451.353  
105 CMR 451.353

Interior Maintenance: Floor dirty  
Interior Maintenance: Ceiling dirty  
Interior Maintenance: Ceiling vents dusty

*Staff Bathroom*

No Violations Noted

*Janitor's Closet*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

**Booking**

*Main Area*

FC 4-204.112(A)\*  
FC 4-601.11(C)\*

Design and Construction, Functionality: No functioning thermometer in refrigerator  
Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, interior of refrigerator dirty

FC 3-701.11(A)

Contaminated Food, Disposition: Unsafe, adulterated, or not honestly presented food not properly reconditioned or discarded, outdated food stored in refrigerator

*Office – R112*

105 CMR 451.350  
105 CMR 451.353

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking  
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

*Records*

No Violations Noted

*Inmate Toilet*

No Violations Noted

*Inmate Bathroom – R118*

105 CMR 451.130

105 CMR 451.123

Plumbing: Plumbing not maintained in good repair, hot water not working properly  
Maintenance: Floor dirty

*Janitor's Closet*

105 CMR 451.353\*

Interior Maintenance: Wet mop stored in bucket

*Showers*

No Violations Noted

*Staff Bathroom – R127*

105 CMR 451.123\*

105 CMR 451.123\*

105 CMR 451.123\*

Maintenance: Ceiling vent dusty  
Maintenance: Floor dirty  
Maintenance: Paper towel dispenser broken

*Kitchen Area*

FC 4-204.112(A)\*

FC 4-501.11(B)

FC 5-202.12(A)

FC 4-903.11(A)(2)

FC 4-903.11(B)(1)

Design and Construction, Functionality: No functioning thermometer in refrigerator  
Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets dirty  
Plumbing System, Design: Handwashing sinks water temperature recorded at 100<sup>0</sup>F  
Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered  
Protection of Clean Items, Storing: Cups not stored in the inverted under sink

*Officer's Landing*

105 CMR 451.353

Interior Maintenance: Carpet dirty

*Cells*

105 CMR 451.353\*

105 CMR 451.353\*

105 CMR 451.353

Interior Maintenance: Ceiling vent damaged in cell # R110 and R111  
Interior Maintenance: Ceiling dirty in cell # R110 and R111  
Interior Maintenance: Ceiling dirty in cell # R103

**Property**

FC 4-903.11(A)(2)

Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered

**Cell Blocks/Pods**

**A1**

Unable to Inspect – Under Construction

**E1**

*Main Area*

105 CMR 451.353\*

105 CMR 451.353\*

105 CMR 451.353

105 CMR 451.353

Interior Maintenance: Floor dirty  
Interior Maintenance: Staircases dirty  
Interior Maintenance: Ceiling vents dusty  
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

*Slop Sink*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dirty

*Showers*

105 CMR 451.123\* Maintenance: Ceiling vents dirty  
105 CMR 451.123 Maintenance: Shower hooks rusty  
105 CMR 451.123 Maintenance: Soap scum on walls in showers

*Recreation Area*

No Violations Noted

*Cells*

105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 109, 110, 113, 115, 116, 203, 209, and 235  
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 101, 123, 127, 210, 217, 220, 221, 223, and 229  
105 CMR 451.353\* Interior Maintenance: Ceiling vent dusty in cell # 237  
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged in cell # 238

**H1**

*Main Area*

105 CMR 451.350\* Structural Maintenance: Wall damaged, hole in wall near cell # 119  
105 CMR 451.353\* Interior Maintenance: Ceiling vents dusty  
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

*Slop Sink*

105 CMR 451.353\* Interior Maintenance: Ceiling vent dusty

*Showers*

105 CMR 451.123\* Maintenance: Shower hooks rusty  
105 CMR 451.123\* Maintenance: Ceiling vents dirty  
105 CMR 451.123\* Maintenance: Soap scum on walls in all showers  
105 CMR 451.123\* Maintenance: Curtains dirty  
105 CMR 451.123 Maintenance: Standing water outside handicap shower  
105 CMR 451.123 Maintenance: Ceiling dirty, appearance of mold outside showers

*Recreation Area*

105 CMR 451.353\* Interior Maintenance: Birds' nests in the rafters

*Cells*

105 CMR 451.353\* Interior Maintenance: Ceiling vent dusty in cell # 237 and 238  
105 CMR 451.350\* Structural Maintenance: Ceiling leaking in cell # 237  
105 CMR 451.350\* Structural Maintenance: Ceiling tiles damaged in cell # 237 and 238  
105 CMR 451.353 Interior Maintenance: Light fixture rusty in cell # 101 and 104  
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 107, 108, 110, 113, 114, 119, 124, 125, 134, 204, 213, 218, 219, 221, 228, and 234  
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 127  
105 CMR 451.350 Structural Maintenance: Wall not easily cleanable, paint peeling in cell # 230

**FNI**

*Main Area*

105 CMR 451.353 Interior Maintenance: Ceiling tiles dirty  
105 CMR 451.353 Interior Maintenance: Ceiling vents dusty  
105 CMR 451.370 Garbage Storage: Garbage stored in an unsanitary condition, trash covers missing flaps

*Slop Sink*

105 CMR 451.353  
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty  
Interior Maintenance: Wall not maintained in good repair, paint peeling

*Rec Area*

105 CMR 451.353\*

Interior Maintenance: Birds' nests in the rafters

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.123  
105 CMR 451.123

Maintenance: Ceiling vents dirty  
Maintenance: Rusty shower hooks  
Maintenance: Soap scum on walls in all showers  
Maintenance: Floors dirty  
Maintenance: Curtain missing

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.123  
105 CMR 451.123  
105 CMR 451.123  
105 CMR 451.123

Maintenance: Ceiling vents dirty  
Maintenance: Wall damaged behind faucets  
Maintenance: Ceiling tiles rusty outside showers  
Maintenance: Soap scum on walls in all showers  
Maintenance: Curtain missing in shower # 7  
Maintenance: Floor drains rusty in showers  
Maintenance: Floor damaged, paint peeling outside showers

*Cells*

105 CMR 451.353  
  
105 CMR 451.353  
105 CMR 451.353  
  
105 CMR 451.353  
105 CMR 451.140

Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 204, 206, and 207  
Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 101  
Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 102 and 106  
Interior Maintenance: Light fixture blocked in cell # 107  
Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 102, 104, 105, and 204

**FS1**

*Main Area*

105 CMR 451.353  
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty  
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

*Slop Sink*

No Violations Noted

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*

Maintenance: Ceiling dirty, appearance of mold outside showers  
Maintenance: Rusty shower hooks  
Maintenance: Ceiling vents dirty  
Maintenance: Curtains dirty

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123

Maintenance: Floor paint peeling outside of showers  
Maintenance: Ceiling dirty, appearance of mold outside showers  
Maintenance: Curtains dirty  
Maintenance: Rusty shower hooks  
Maintenance: Curtains missing

*Recreation Area*

105 CMR 451.353\*

Interior Maintenance: Birds' nests in the rafters

*Cells*

105 CMR 451.353

Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 101, 105, and 206

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 102

105 CMR 451.353

Interior Maintenance: Light fixture blocked in cell # 104, 201, 202, 205, and 206

**DNI**

*Main Area*

105 CMR 451.353

Interior Maintenance: Ceiling tiles dirty

105 CMR 451.353

Interior Maintenance: Ceiling vents dusty

105 CMR 451.370

Garbage Storage: Garbage stored in an unsanitary condition, trash covers missing flaps

*Slop Sink*

105 CMR 451.353\*

Interior Maintenance: Wet mop stored in bucket

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Toilet Area*

105 CMR 451.123

Maintenance: Floor damaged

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123\*

Maintenance: Ceiling vents dusty

105 CMR 451.123

Maintenance: Soap scum on walls in all showers

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123

Maintenance: Soap scum on walls in all showers

105 CMR 451.123

Maintenance: Floor damaged, paint peeling outside showers

105 CMR 451.123

Maintenance: Wall ventilation grilles damaged, rusty

105 CMR 451.123

Maintenance: Rusty shower hooks

*Recreation Area*

105 CMR 451.353\*

Interior Maintenance: Birds' nests in the rafters

*Cells*

105 CMR 451.353\*

Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 101

105 CMR 451.353

Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 107

105 CMR 451.350

Structural Maintenance: Wall not easily cleanable, hole in wall in cell # 208

105 CMR 451.353

Interior Maintenance: Light fixture blocked in cell # 107 and 201

105 CMR 451.353

Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 201 and 204-207

**DS1**

*Slop Sink*

105 CMR 451.353\*

Interior Maintenance: Mop stored in bucket

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123

Maintenance: Rusty shower hooks

105 CMR 451.123

Maintenance: Ceiling vents dusty

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.130\*  
105 CMR 451.123

Maintenance: Floor paint peeling  
Maintenance: Rusty shower hooks  
Maintenance: Shower drains rusty  
Plumbing: Plumbing not maintained in good repair, leak in shower # 1  
Maintenance: Ceiling dirty, appearance of mold outside showers

*Cells*

105 CMR 451.353  
  
105 CMR 451.353\*  
105 CMR 451.353\*  
105 CMR 451.353\*  
  
105 CMR 451.350\*  
105 CMR 451.353

Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 201  
Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 205  
Interior Maintenance: Ceiling vent dusty in cell # 208 and 209  
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged in cell # 208  
Structural Maintenance: Roof leaking in cell # 208  
Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 107, 202, and 205

**BS101**

105 CMR 451.353\*  
105 CMR 451.353

Interior Maintenance: Ceiling vents dusty  
Interior Maintenance: Ceiling ventilation grilles damaged, rusty

*Bunks*

No Violations Noted

*Bathroom*

105 CMR 451.130  
105 CMR 451.130  
105 CMR 451.123

Plumbing: Plumbing not maintained in good repair, toilet # 4 and 7 out-of-order  
Plumbing: Plumbing not maintained in good repair, faucet loose at sink # 5  
Maintenance: Wall damaged, paint peeling

*Showers*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.130

Maintenance: Soap scum on walls in all showers  
Maintenance: Rusty shower hooks  
Maintenance: Shower curtains dirty  
Plumbing: Plumbing not maintained in good repair, shower leaking in shower # 7

**BN101**

105 CMR 451.353\*  
105 CMR 451.350  
105 CMR 451.353  
105 CMR 451.350

Interior Maintenance: Ceiling vent dusty  
Structural Maintenance: Ceiling not easily cleanable, ceiling leaking  
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged  
Structural Maintenance: Floor not easily cleanable, floor damaged

*Bunks*

No Violations Noted

*Bathroom*

105 CMR 451.130  
105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, toilet # 6 leaking  
Plumbing: Plumbing not maintained in good repair, faucet leaking at sink # 2

*Showers*

105 CMR 451.123\*  
105 CMR 451.123\*

Maintenance: Soap scum on walls in all showers  
Maintenance: Curtains dirty

**BS201**

105 CMR 451.350\*

Structural Maintenance: Floor not easily cleanable, baseboard missing behind bed # 13 and 14

105 CMR 451.353\*

Interior Maintenance: Ceiling vents dusty

*Bunks*

No Violations Noted

*Bathroom*

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, sink # 2 out-of-order

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink

105 CMR 451.123

Maintenance: Light fixtures rusty

*Showers*

105 CMR 451.123

Maintenance: Curtains dirty

105 CMR 451.123\*

Maintenance: Soap scum on walls in all showers

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, leak at shower # 4

**BN201**

105 CMR 451.353\*

Interior Maintenance: Ceiling vents dusty

105 CMR 451.353\*

Interior Maintenance: Floor not maintained in good repair, floor tiles damaged

105 CMR 451.353

Interior Maintenance: Ceiling ventilation grilles rusty

105 CMR 451.353

Interior Maintenance: Floor not maintained in good repair, baseboard damaged

105 CMR 451.353

Interior Maintenance: Outlet cover not installed properly

*Bunks*

No Violations Noted

*Bathroom*

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, sink # 7 out-of-order

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet loose at sink # 1

*Showers*

105 CMR 451.123\*

Maintenance: Rusty metal shutoffs at shower # 1 and 2

105 CMR 451.123\*

Maintenance: Rusty shower hooks

105 CMR 451.123\*

Maintenance: Soap scum on walls in all showers

**C1***Main Area*

105 CMR 451.350\*

Structural Maintenance: Wall damaged, hole in wall near cell # 113

105 CMR 451.353\*

Interior Maintenance: Ceiling vents dusty

105 CMR 451.353

Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

105 CMR 451.353

Interior Maintenance: Chair not easily cleanable, officer's chair padding damaged

*Slop Sink*

105 CMR 451.353

Interior Maintenance: Floor not maintained in good repair, floor tiles damaged

*Showers*

105 CMR 451.123\*

Maintenance: Rusty metal doors

105 CMR 451.123\*

Maintenance: Soap scum on walls in all showers

105 CMR 451.123\*

Maintenance: Rusty shower hooks

105 CMR 451.123\*

Maintenance: Ceiling dirty, appearance of mold outside showers

105 CMR 451.123

Maintenance: Ceiling damaged, paint peeling outside showers

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 2 and 4 out-of-order

*Recreation Area*  
105 CMR 451.353

Interior Maintenance: Birds' nests

*Cells*  
105 CMR 451.140\*

Adequate Ventilation: Inadequate ventilation, wall ventilation grilles blocked in all cells

105 CMR 451.353

Interior Maintenance: Light fixture blocked in cell # 107, 109, 120, 121, 127, 131, 201, 202, 204, 209, 215, 217, 219, 221, 223, 226, and 228

*Visitor Room*  
105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Non-Contact Room*  
105 CMR 451.350\*  
105 CMR 451.353\*

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking  
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

## **G Block**

*Main Area*

No Violations Noted

**GE South**  
105 CMR 451.353  
105 CMR 451.350

Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged  
Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

*Slop Sink*

No Violations Noted

*Showers*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123

Maintenance: Soap scum on walls in all showers  
Maintenance: Wall damaged  
Maintenance: Rusty shower hooks  
Maintenance: Ceiling vent rusty

*Chemical Storage*

No Violations Noted

*Cells*  
105 CMR 451.140\*

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 102, 104, 108, and 207

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 103, 105, 202, 203, and 205

**GE North**

*Slop Sink*  
105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Showers*  
105 CMR 451.123  
105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.123  
105 CMR 451.123

Maintenance: Pipe chase door rusty  
Maintenance: Ceiling vent dusty  
Maintenance: Rusty shower hooks  
Maintenance: Soap scum on walls in all showers  
Maintenance: Floor dirty in all showers

*Recreation Deck*

No Violations Noted

*Cells*

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 113, 114, 117, 118, and 216-218

105 CMR 451.353

Interior Maintenance: Light fixture blocked in cell # 109, 111, 113, and 217

**GW North**

*Main Area*

105 CMR 451.350\*

Structural Maintenance: Wall not easily cleanable, hole in wall near cell # 109

105 CMR 451.350\*

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

105 CMR 451.353

Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

*Slop Sink*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Showers*

Unable to Inspect – In Use

*Cells*

105 CMR 451.140\*

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 109

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 117, 209, 214, and 215

105 CMR 451.353

Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 110

105 CMR 451.353

Interior Maintenance: Light fixture blocked in cell # 112-114

*GW219*

No Violations Noted

**GW South**

*Main Area*

105 CMR 451.353

Interior Maintenance: Ceiling vents dusty

*Slop Sink*

No Violations Noted

*Showers*

105 CMR 451.123\*

Maintenance: Soap scum on walls in all showers

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Cells*

105 CMR 451.140\*

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in all cells

105 CMR 451.353

Interior Maintenance: Wall not maintained in good repair, paint peeling at entrance of all cells

105 CMR 451.353

Interior Maintenance: Light fixture blocked in cell # 205

### **3<sup>rd</sup> Floor**

#### **Main Hallway**

##### *Janitor's Closet – 3022*

105 CMR 451.353\*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

Interior Maintenance: Trash in slop sink

##### *Staff Bathroom – 3021*

No Violations Noted

##### *Storage – 3020*

Unable to Inspect – No Access

##### *Janitor's Closet – 3018*

105 CMR 451.344

Illumination in Habitable Areas: Light not functioning properly, light out

##### *Janitor's Closet - 3010*

105 CMR 451.353\*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Interior Maintenance: Wet mop stored in bucket

##### *Staff Bathroom – 3009*

105 CMR 451.123

Maintenance: Ceiling vent dusty

##### *Storage – 3008*

FC 4-204.112(A)\*

FC 4-601.11(C)\*

105 CMR 451.344\*

FC 4-601.11(A)

Design and Construction, Functionality: No functioning thermometer in refrigerator

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, inside of freezer dirty

Illumination in Habitable Areas: Light fixture not functioning properly

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, coffee maker dirty

##### *Janitor's Closet – 3006*

105 CMR 451.353\*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Interior Maintenance: Debris clogging slop sink drain

##### *Staff Bathroom – 3003*

105 CMR 451.123\*

Maintenance: Ceiling vent dusty

#### **FS3**

##### *Main Area*

105 CMR 451.350\*

105 CMR 451.353

105 CMR 451.353

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

Interior Maintenance: Ceiling vents dusty

##### *Slop Sink*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

##### *Medical Room*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

##### *Toilet Area*

105 CMR 451.123

Maintenance: Wall damaged

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*

Maintenance: Soap scum on walls in all showers  
Maintenance: Ceiling vents dusty  
Maintenance: Shower hooks rusty

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.123  
105 CMR 451.130

Maintenance: Soap scum on walls in all showers  
Maintenance: Floor damaged, paint peeling outside showers  
Maintenance: Floor drains rusty  
Maintenance: Shower hooks rusty  
Maintenance: Floor dirty in all showers  
Maintenance: Curtains missing  
Plumbing: Plumbing not maintained in good repair, shower # 5 out-of-order

*Cells*

105 CMR 451.353  
  
105 CMR 451.140\*

Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 301, 302, 304, and 306  
Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 307 and 407

**FN3**

*Slop Sink*

105 CMR 451.350\*

Structural Maintenance: Ceiling damaged

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.130

Maintenance: Ceiling vent dusty  
Maintenance: Floor drains rusty  
Maintenance: Shower hooks rusty  
Maintenance: Soap scum on walls in all showers  
Plumbing: Plumbing not maintained in good repair, shower leaking in shower # 1

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123

Maintenance: Ceiling vent dusty  
Maintenance: Floor drains rusty  
Maintenance: Shower hooks rusty  
Maintenance: Soap scum on walls in all showers

*Cells*

105 CMR 451.353  
  
105 CMR 451.350  
  
105 CMR 451.353\*  
105 CMR 451.350\*  
105 CMR 451.343\*

Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 307  
Structural Maintenance: Floor not easily cleanable, floor damaged in cell # 401 and 402  
Interior Maintenance: Ceiling vent dusty in cell # 408 and 409  
Structural Maintenance: Ceiling not easily cleanable, ceiling leaking in cell # 408  
Electric Fixtures in Cell: No electrical outlet in cell # 408

**H3**

*Main Area*

105 CMR 451.353  
105 CMR 451.353

Interior Maintenance: Ceiling vents dusty  
Interior Maintenance: Ceiling tiles dirty

*Slop Sink*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

*Showers*

105 CMR 451.123\* Maintenance: Shower hooks rusty  
105 CMR 451.123\* Maintenance: Soap scum on walls in all showers  
105 CMR 451.130\* Plumbing: Plumbing not maintained in good repair, leak in shower # 3  
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, leak in shower # 4-7  
105 CMR 451.123\* Maintenance: Ceiling dirty, appearance of mold outside showers  
105 CMR 451.123 Maintenance: Ceiling vent dusty in all showers

*Cells*

105 CMR 451.353 Interior Maintenance: Ceiling dirty in cell # 324 and 412  
105 CMR 451.103 Mattresses: Mattress damaged in cell # 305  
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 301  
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 307, 328, 333, 412, 426, 432, and 434  
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 413

**DN3**

*Main Area*

105 CMR 451.353 Interior Maintenance: Ceiling vents dusty

*Slop Sink*

105 CMR 451.353\* Interior Maintenance: Ceiling vent dusty  
105 CMR 451.353 Interior Maintenance: Mop stored in slop sink

*Toilet Area*

105 CMR 451.123\* Maintenance: Floor not easily cleanable, floor tiles damaged

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123\* Maintenance: Shower hooks rusty  
105 CMR 451.123\* Maintenance: Floor drains rusty  
105 CMR 451.123 Maintenance: Soap scum on walls in all showers

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\* Maintenance: Floor not easily cleanable, paint peeling outside showers  
105 CMR 451.123\* Maintenance: Shower hooks rusty  
105 CMR 451.123\* Maintenance: Floor drains rusty  
105 CMR 451.123\* Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged outside showers

*Cells*

105 CMR 451.140\* Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in all cells  
105 CMR 451.353\* Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 306  
105 CMR 451.353\* Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 406 and 407

*Recreation Deck*

No Violations Noted

**DS3**

*Main Area*

105 CMR 451.353 Interior Maintenance: Wall dirty near recreation deck

*Slop Sink*

105 CMR 451.353 Interior Maintenance: Ceiling vent dusty

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123\* Maintenance: Shower hooks rusty  
105 CMR 451.123\* Maintenance: Soap scum on walls in all showers  
105 CMR 451.123\* Maintenance: Ceiling vents dirty  
105 CMR 451.123 Maintenance: Floor dirty in showers

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\* Maintenance: Floor not easily cleanable, paint peeling outside showers  
105 CMR 451.123\* Maintenance: Shower hooks rusty  
105 CMR 451.123\* Maintenance: Shower drains rusty  
105 CMR 451.123\* Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged outside showers  
105 CMR 451.123\* Maintenance: Ceiling dirty, appearance of mold outside showers

*Cells*

105 CMR 451.353\* Interior Maintenance: Floor not maintained in good repair, paint peeling in all cells  
105 CMR 451.353 Interior Maintenance: Bed not maintained in good repair, paint peeling in cell # 406 and 407  
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 403  
105 CMR 451.353 Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 408

*Recreation Deck*

105 CMR 451.353 Interior Maintenance: Trash on recreation deck

**E3**

105 CMR 451.353 Interior Maintenance: Wall not maintained in good repair, paint peeling  
105 CMR 451.353 Interior Maintenance: Ceiling vents dusty

*Slop Sink*

105 CMR 451.353\* Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged  
105 CMR 451.353\* Interior Maintenance: Ceiling vent dusty

*Showers*

105 CMR 451.123\* Maintenance: Soap scum on walls in all showers  
105 CMR 451.123\* Maintenance: Curtains dirty  
105 CMR 451.123\* Maintenance: Ceiling vents dirty  
105 CMR 451.123\* Maintenance: Shower hooks rusty  
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower leaking in shower # 7

*Cells*

105 CMR 451.353\* Interior Maintenance: Wall not maintained in good repair, paint peeling in all cells  
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 301, 308, 314, and 330  
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 410, 430, and 434  
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 302, 307, 321, and 428

105 CMR 451.353 Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 320  
105 CMR 451.353\* Interior Maintenance: Molding damaged in cell # 438  
105 CMR 451.353\* Interior Maintenance: Ceiling vent dusty in cell # 438

**C3**  
105 CMR 451.353 Interior Maintenance: Wall not maintained in good repair, paint peeling near phones  
105 CMR 451.353 Interior Maintenance: Ceiling vents dusty  
105 CMR 451.353 Interior Maintenance: Ceiling tiles dirty

*Slop Sink*  
105 CMR 451.353\* Interior Maintenance: Ceiling vent dusty  
105 CMR 451.353\* Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged  
105 CMR 451.344 Illumination in Habitable Areas: Light not functioning properly, light out

*Showers*  
105 CMR 451.123 Unable to Fully Inspect – In Use  
Maintenance: Ceiling dirty, appearance of mold outside showers

*Cells*  
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 305

### **Warehouse – Support Building**

*Freezer*  
No Violations Noted

*Fridge # 1*  
No Violations Noted

*Fridge # 2*  
FC 6-202.11(A) Design, Construction, and Installation; Functionality: Light bulbs not shatter-resistant or protected by light shields

*Male Bathroom*  
105 CMR 451.123\* Maintenance: Ceiling vent dusty  
105 CMR 451.123\* Maintenance: Floor not easily cleanable, damaged at entrance

*Female Bathroom*  
105 CMR 451.123\* Maintenance: Ceiling vent dusty  
105 CMR 451.123\* Maintenance: Wall not easily cleanable, hole in wall behind flusher

*Inmate Bathroom*  
No Violations Noted

*Janitor's Closet*  
105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket  
105 CMR 451.353 Interior Maintenance: Ceiling vent dusty

### **K9 Unit**

*Bathroom # 1*  
105 CMR 451.123\* Maintenance: Wall not easily cleanable, damaged behind door  
105 CMR 451.123\* Maintenance: Floor dirty

*Bathroom # 2*

105 CMR 451.123\*  
105 CMR 451.123\*

Maintenance: Wall not easily cleanable, wall damaged behind door  
Maintenance: Ceiling vent dusty

*Janitor's Closet*

105 CMR 451.353\*

Interior Maintenance: Mop stored in bucket

*Kitchen Area*

105 CMR 451.353

Interior Maintenance: Dryer not vented to the exterior

**Garage**

*Bathroom – W124*

105 CMR 451.123\*

Maintenance: Ceiling vent dusty

*Janitor's Closet – W123*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353\*

Interior Maintenance: Wet mop stored in bucket

**Print Shop**

FC 4-601.11(A)

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, coffee maker dirty

FC 4-602.12(B)

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, Refrigerator door broken

*Inmate Bathroom*

105 CMR 451.110(A)

Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink

*Staff Bathroom*

105 CMR 451.126\*

Hot Water: Hot water temperature recorded at 133°F

105 CMR 451.123\*

Maintenance: Ceiling vent dirty

*Janitor's Closet*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Janitor's Closet – W111*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink

**Observations and Recommendations**

1. The inmate population was 1256 at the time of inspection.
2. Cell block A1 was under construction at the time of inspection. No inmates were housed in this block.
3. Cell block DS3 was empty at the time of inspection. The Department conducted the inspection of this block as normal.
4. Many locations did not have a paper towel dispenser installed and paper towels were left exposed. The Department recommended that paper towels are stored in a dispenser.
5. Ceiling air vents were painted black in the staff dining room next to the kitchen. The dark color makes dirt and dust difficult to see and cleaning problematic. The Department recommended replacing these vents.
6. The warewash machine in the main kitchen took an excessive amount of time to reach appropriate sanitizing temperature. The Department recommended looking at the manufacturer's specifications for the unit to find out the acceptable amount of time to reach temperature.
7. The large tool room in the maintenance area was disorganized and posed dangerous conditions for workers. The Department recommended organizing this room.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please indicate next to each entry on the inspection report a plan of correction. Said plan of correction must be submitted within ten working days of receiving this report and should detail the specific steps that will be taken and the date of expected compliance. The plan of correction should be submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at [www.mass.gov/dph/fpp](http://www.mass.gov/dph/fpp) and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments" and "[1999 Food Code](#)".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Nicholas Gale  
Environmental Health Inspector, CSP, BEH

cc: Suzanne K. Condon, Associate Commissioner, Director, BEH  
Steven Hughes, Director, CSP, BEH  
John W. Polanowicz, Secretary, Executive Office of Health and Human Services  
Luis S. Spencer, Commissioner, DOC  
Antone Moniz, Superintendent  
Captain Eugene Irvine, EHSO  
Michelle Roberts, MA, CHO, Health Director, Plymouth Health Department  
Clerk, Massachusetts House of Representatives  
Clerk, Massachusetts Senate  
Andrea Cabral, Secretary, EOPS