



The Commonwealth of Massachusetts
 Executive Office of Health and Human Services
 Department of Public Health
 Bureau of Environmental Health
 Community Sanitation Program
 5 Randolph Street
 Canton, MA 02021
 Telephone: 781 828-8046
 Facsimile: 781 828-7703
 Nicholas.Gale@state.ma.us

DEVAL L. PATRICK
 GOVERNOR
 JOHN W. POLANOWICZ
 SECRETARY
 CHERYL BARTLETT, RN
 COMMISSIONER

March 18, 2014

Joseph D. McDonald, Jr., Sheriff
 Plymouth County Correctional Facility
 26 Long Pond Road
 Plymouth, MA 02360

Re: Facility Inspection – Plymouth County Correctional Facility

Dear Sheriff McDonald:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Plymouth County Correctional Facility on February 19 and 20, 2014 accompanied by Captain Eugene Irvine, Environmental Health and Safety Officer. Violations noted during the inspection are listed below including 604 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

Administration/Entrance Area

Front Lobby

Main Area

105 CMR 451.353*	Interior Maintenance: Ceiling vent dirty
105 CMR 451.353*	Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged
105 CMR 451.350	Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

Janitor's Closet

105 CMR 451.353*	Interior Maintenance: Light shield missing
105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty

Male Bathroom

105 CMR 451.123*	Maintenance: Ceiling vent damaged, rusted
------------------	---

Female Bathroom

105 CMR 451.123*	Maintenance: Ceiling vent damaged, rusted
105 CMR 451.123*	Maintenance: Ceiling vent dusty

105 CMR 451.123 Maintenance: Caulking damaged around toilet

Main Hallway

Janitor's Closet 1027

105 CMR 451.350* Structural Maintenance: Wall not easily cleanable, wall damaged
105 CMR 451.353 Interior Maintenance: Wet mop stored in sink
105 CMR 451.353 Interior Maintenance: Floor dirty

Female Locker Room

105 CMR 451.123* Maintenance: Ceiling vents damaged, rusted

Showers

No Violations Noted

Male Locker Room

105 CMR 451.123* Maintenance: Ceiling vents damaged, rusty
105 CMR 451.123* Maintenance: Ceiling vents dusty
105 CMR 451.123 Maintenance: Carpets dirty
105 CMR 451.123* Maintenance: Ceiling leaking

Showers

105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, leak in shower # 1
105 CMR 451.123* Maintenance: Soap scum on walls in showers # 1-3
105 CMR 451.123 Maintenance: Ceiling damaged, paint peeling

Staff Gym

105 CMR 451.353* Interior Maintenance: Ceiling vent dusty
105 CMR 451.353* Interior Maintenance: Weight lifting equipment not easily cleanable, bench padding damaged

General Male Locker Room

105 CMR 451.353* Interior Maintenance: Floor not maintained in good repair, baseboard damaged

General Female Locker Room

No Violations Noted

Administration Area – 1018

Break Room

105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged
105 CMR 451.350 Structural Maintenance: Ceiling not easily cleanable, ceiling leaking
105 CMR 451.370 Garbage Storage: Garbage stored in an unsanitary condition, trash can missing cover
FC 4-601.11(A) Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, toaster oven dirty
105 CMR 451.353 Interior Maintenance: Ceiling vent dusty

Male Bathroom 1013

105 CMR 451.123* Maintenance: Ceiling vent dusty

Female Bathroom

105 CMR 451.123* Maintenance: Ceiling vent dusty

IPS Office

105 CMR 451.353* Interior Maintenance: Floor dirty, appearance of mold on floor

FC 4-601.11(A)*	Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, toaster oven dirty
FC 4-601.11(C)*	Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, Poland Spring cooler tray dirty
105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
105 CMR 451.350	Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

Kitchen

FC 6-201.11*	Design, Construction and Installation: Floor not easily cleanable, floor damaged in many areas
--------------	--

Staff Dining Area

FC 6-201.16(A)	Design, Construction, and Installation; Cleanability: Ceiling not easily cleanable, ceiling leaking above salad bar
----------------	---

FC 6-201.16(A)	Design, Construction, and Installation; Cleanability: Ceiling covering not easily cleanable, ceiling tiles damaged
----------------	--

FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, snack tray in vending machine dirty
----------------	---

Staff Serving Line

FC 6-201.11*	Design, Construction and Installation: Floor not easily cleanable, floor damaged
--------------	--

FC 3-304.14(B)(2)	Preventing Contamination from Linens: Wet cloth not stored in sanitizer bucket
-------------------	--

Office

No Violations Noted

Office Bathroom

No Violations Noted

Dry Storage

No Violations Noted

Tool Closet

No Violations Noted

Cooler # 2

No Violations Noted

Inmate Break Area

No Violations Noted

Inmate Bathroom

FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, cold water out-of-order at handwash sink
----------------	--

FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, urinal out-of-order
----------------	---

FC 6-501.11	Maintenance and Operation; Repairing: Facility not in good repair, door does not close properly
-------------	---

Janitor's Closet

FC 6-501.12(A)*	Maintenance and Operation; Cleaning: Facility not cleaned properly, ceiling vent dirty
-----------------	--

FC 6-202.11(A)	Design, Construction, and Installation; Functionality: Light bulbs not protected by light shields
----------------	---

Freezer # 1

No Violations Noted

Cooler # 3

No Violations Noted

Cooler # 4

No Violations Noted

Cooler # 5

No Violations Noted

Freezer # 6

No Violations Noted

Prep Area

FC 5-205.15(B)*

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, leak at prep sink

FC 6-201.16(A)*

Design, Construction, and Installation; Cleanability: Wall not easily cleanable, paint peeling

Kettle Area

No Violations Noted

Bakery Area

No Violations Noted

3-Bay Sink Area

FC 6-501.12(A)*

Maintenance and Operation; Cleaning: Facility not cleaned properly, standing water on floor

FC 5-205.15(B)

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, sink faucet leaking

FC 5-205.15(B)

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, pipe under sink leaking

Dishwashing Machine Area

Slop Sink

FC 5-205.15(B)*

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, slop sink leaking

Chapel/Contact Room

105 CMR 451.350*

Structural Maintenance: Wall not easily cleanable, water leak behind wall

105 CMR 451.353*

Interior Maintenance: Wall dirty

105 CMR 451.353*

Interior Maintenance: Carpet dirty

105 CMR 451.353*

Interior Maintenance: Air vent dirty

Medical Corridor

105 CMR 451.350*

Structural Maintenance: Ceiling leaking

105 CMR 451.353*

Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

105 CMR 451.353*

Interior Maintenance: Floor dirty, appearance of mold on floor

105 CMR 451.350

Structural Maintenance: Door leading to exterior not rodent and weathertight

HSU

Kitchen

No Violations Noted

Nurse's Station – M106

No Violations Noted

Room – M132

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 86⁰F

Autoclave – M131

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Staff Bathroom – M130

105 CMR 451.126

Hot Water: Hot water temperature recorded at 76⁰F

Pharmacy – M128

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 71⁰F

Janitor's Closet – M127

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Laboratory – M126

105 CMR 451.110(A)

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

Dentist – M124

No Violations Noted

X-Ray Room – M123

No Violations Noted

Inmate Bathroom

105 CMR 451.110(A)*

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

Exam Room – M121

105 CMR 451.126

Hot Water: Hot water temperature recorded at 70⁰F

Room – M119

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 73⁰F

Handicap Bathroom

105 CMR 451.123

Maintenance: Shower head broken

105 CMR 451.123

Maintenance: Ceiling vent dusty

Cells

No Violations Noted

Laundry

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

105 CMR 451.353*

Interior Maintenance: Floor not maintained in good repair, paint peeling

105 CMR 451.353

Interior Maintenance: Ceiling not maintained in good repair, paint peeling

Janitor's Closet

No Violations Noted

Office

FC 3-501.16(B)

Limitation of Growth of Organisms, Temperature and Time Control: Refrigerator temperature recorded at 52⁰F

Chemical Closet

No Violations Noted

Maintenance

FC 4-501.11(B)*

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets dirty

FC 4-903.11(A)(2)

Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered

Small Tool Room

No Violations Noted

Bathroom

No Violations Noted

Office

No Violations Noted

Office Bathroom

No Violations Noted

Inmate Bathroom – 1058

105 CMR 451.123*

Maintenance: Floor damaged, paint peeling

Loading Dock

105 CMR 451.350*

Structural Maintenance: Garage doors not rodent and weathertight

Gymnasium

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353*

Interior Maintenance: Floor not maintained in good repair, baseboard missing

105 CMR 451.353*

Interior Maintenance: Ceiling ventilation missing diffusers

105 CMR 451.370

Garbage Storage: Garbage stored in an unsanitary condition, trash can missing cover

Hallway

Janitor's Closet - 1084

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353*

Interior Maintenance: Floor dirty

105 CMR 451.353

Interior Maintenance: Wall dirty

Staff Bathroom – 1090

105 CMR 451.123*

Maintenance: Ceiling vent dusty

Janitor's Closet – 1095

105 CMR 451.130*

Plumbing: Plumbing not maintained in good repair, faucet leaking

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353

Interior Maintenance: Floor not maintained in good repair, baseboard damaged

Staff Bathroom – 1098

105 CMR 451.123*

Maintenance: Ceiling vent dusty

105 CMR 451.123

Maintenance: Paper towel dispenser missing

Staff Bathroom – 1099

105 CMR 451.123

Maintenance: Wall vent dusty

Staff Bathroom – 1107

105 CMR 451.123

Maintenance: Paper towel dispenser missing

Janitor's Closet – 1108

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Unit Manager's Office – 1112

105 CMR 451.350

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

105 CMR 451.353

Interior Maintenance: Ceiling not maintained in good repair, tiles damaged

Staff Bathroom – 1102

105 CMR 451.123*

Maintenance: Ceiling damaged

105 CMR 451.110(A)

Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink

105 CMR 451.123

Maintenance: Paper towel dispenser missing

Classroom – 1110

Unable to Inspect – In Use

Library

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

Human Services

Break Room

FC 3-302.11(A)(4)*

Preventing Food and Ingredient Contamination: Preventing cross contamination, food not appropriately stored

FC 4-903.11(A)(2)*

Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered

Offices

105 CMR 451.350

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking in office # 1071 and 1074

Staff Bathroom - 1069

105 CMR 451.123

Maintenance: Floor dirty

105 CMR 451.123

Maintenance: Ceiling vent dusty

Janitor's Closet - 1064

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Booking

Main Area

FC 4-601.11(C)*

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, interior of refrigerator dirty

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, exterior of refrigerator rusted

Office – R112

105 CMR 451.350*

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

105 CMR 451.353*

Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

105 CMR 451.353

Interior Maintenance: Wall not maintained in good repair, wall paint peeling

105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light out
<i>Records – R106</i>	
105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
<i>Inmate Toilet – R105</i>	
	No Violations Noted
<i>Inmate Bathroom – R118</i>	
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water not working properly
<i>Janitor’s Closet – R126</i>	
105 CMR 451.353*	Interior Maintenance: Wet mop stored in bucket
<i>Showers</i>	
105 CMR 451.123	Maintenance: Light out in shower # 1
<i>Staff Bathroom – R127</i>	
105 CMR 451.123*	Maintenance: Ceiling vent dusty
<i>Kitchen Area</i>	
FC 4-204.112(A)*	Design and Construction, Functionality: No functioning thermometer in refrigerator
FC 4-501.11(B)*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets dirty
FC 5-202.12(A)*	Plumbing System, Design: Handwashing sinks water temperature recorded at 105 ⁰ F
FC 4-903.11(A)(2)*	Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered
FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, refrigerator damaged
<i>Officer’s Landing</i>	
105 CMR 451.353*	Interior Maintenance: Carpet dirty
<i>Cells</i>	
105 CMR 451.353*	Interior Maintenance: Ceiling vent damaged in cell # R110 and R111
105 CMR 451.353*	Interior Maintenance: Ceiling dirty in cell # R110 and R111
105 CMR 451.353	Interior Maintenance: Ceiling dirty in cell # R117
105 CMR 451.353*	Interior Maintenance: Ceiling dirty in cell # R103
105 CMR 451.353	Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # R108
<u>Property</u>	
FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, refrigerator door damaged
<u>Cell Blocks/Pods</u>	
A1	
<i>Main Area</i>	
105 CMR 451.353	Interior Maintenance: Ceiling vents dusty
<i>Slop Sink</i>	
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink out-of-order

Showers

105 CMR 451.130
105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 5 out-of-order
Plumbing: Plumbing not maintained in good repair, shower # 4 leaking

Bathroom

105 CMR 451.123
105 CMR 451.123
105 CMR 451.130

Maintenance: Floor dirty
Maintenance: Handwash sinks dirty
Plumbing: Plumbing not maintained in good repair, faucet loose at sink # 3 and 4

E1

Main Area

105 CMR 451.353*
105 CMR 451.353*
105 CMR 451.350
105 CMR 451.370

Interior Maintenance: Ceiling vents dusty
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged
Structural Maintenance: Ceiling not easily cleanable, ceiling leaking
Garbage Storage: Garbage stored in an unsanitary condition, trash can missing cover

Slop Sink

105 CMR 451.353*
105 CMR 451.353

Interior Maintenance: Ceiling vent dirty
Interior Maintenance: Floor dirty

Showers

105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.130
105 CMR 451.123

Maintenance: Shower hooks rusty in shower # 1-9
Maintenance: Soap scum on walls in shower # 1-9
Plumbing: Plumbing not maintained in good repair, shower leaking in shower # 7
Maintenance: Curtain missing in shower # 3, 4, and 6

Recreation Area

105 CMR 451.353

Interior Maintenance: Bird's nest in rafters

Cells

105 CMR 451.140

105 CMR 451.353
105 CMR 451.353*
105 CMR 451.353*

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 107, 112, 204, 213, 214, 220, 222, 224, and 230
Interior Maintenance: Light fixture blocked in cell # 105, 210, 219, and 236
Interior Maintenance: Ceiling vent dusty in cell # 237
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged in cell # 238

H1

Main Area

105 CMR 451.350*
105 CMR 451.353*
105 CMR 451.353*

Structural Maintenance: Wall damaged, hole in wall near cell # 119
Interior Maintenance: Ceiling vents dusty
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

Slop Sink

105 CMR 451.353*
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty
Interior Maintenance: Floor not maintained in good repair, baseboard damaged

Showers

105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123

Maintenance: Shower hooks rusty in shower # 1-9
Maintenance: Ceiling vents dirty in shower # 1-9
Maintenance: Soap scum on walls in shower # 1-9
Maintenance: Ceiling dirty, appearance of mold outside showers

Recreation Area

105 CMR 451.353*

Interior Maintenance: Bird's nest in rafters

Cells

105 CMR 451.353*

Interior Maintenance: Light fixture rusty in cell # 101 and 104

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 108 and 228

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 103, 106, 120, and 227

105 CMR 451.353

Interior Maintenance: Light fixture blocked in cell # 118

105 CMR 451.353*

Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 230

105 CMR 451.353

Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 127, 128, and 234

FN1

Main Area

105 CMR 451.353*

Interior Maintenance: Ceiling tiles dirty

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

105 CMR 451.370*

Garbage Storage: Garbage stored in an unsanitary condition, trash covers missing flaps

105 CMR 451.350

Structural Maintenance: Staircase damaged outside of slop sink closet

105 CMR 451.353

Interior Maintenance: Exit sign light out

Slop Sink

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353*

Interior Maintenance: Wall not maintained in good repair, paint peeling

Rec Area

No Violations Noted

Showers – 1st Floor

105 CMR 451.123*

Maintenance: Ceiling vents dirty in shower # 1-3

105 CMR 451.123*

Maintenance: Rusty shower hooks in shower # 1-3

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 1-3

105 CMR 451.123

Maintenance: Curtain missing in shower # 1

Showers – 2nd Floor

105 CMR 451.123*

Maintenance: Ceiling vents dirty in shower # 4-7

105 CMR 451.123*

Maintenance: Wall damaged behind faucets in shower # 4-7

105 CMR 451.123*

Maintenance: Ceiling tiles rusty outside showers

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 4-7

105 CMR 451.123*

Maintenance: Curtain missing in shower # 7

105 CMR 451.123*

Maintenance: Floor drains rusty in shower # 4-7

105 CMR 451.123*

Maintenance: Floor damaged, paint peeling outside showers

Cells

105 CMR 451.353*

Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 204, 206, and 207

105 CMR 451.353*

Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 101

105 CMR 451.353*

Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 102 and 106

105 CMR 451.353

Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 205, 206, and 207

105 CMR 451.344

Illumination in Habitable Areas: Light not functioning properly, light out in cell # 208

FS1

Main Area

105 CMR 451.353*
105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

Slop Sink

No Violations Noted

Showers – 1st Floor

105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123*

Maintenance: Ceiling dirty, appearance of mold outside showers
Maintenance: Rusty shower hooks in shower # 1-3
Maintenance: Wall vents dirty in shower # 1-3
Maintenance: Curtains dirty in shower # 1-3

Showers – 2nd Floor

105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123*

Maintenance: Floor paint peeling outside of showers
Maintenance: Ceiling dirty, appearance of mold outside showers
Maintenance: Curtains dirty in shower # 4-7
Maintenance: Rusty shower hooks in shower # 4-7

Recreation Area

105 CMR 451.353*
105 CMR 451.350

Interior Maintenance: Bird's nest in the rafters
Structural Maintenance: Door not rodent and weathertight

Cells

105 CMR 451.353*
105 CMR 451.353*
105 CMR 451.353
105 CMR 451.344
105 CMR 451.353

Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 101
Interior Maintenance: Light fixture blocked in cell # 202 and 206
Interior Maintenance: Wall dirty in cell # 207
Illumination in Habitable Areas: Light not functioning properly, light out in cell # 208
Interior Maintenance: Ceiling not maintained in good repair, tiles damaged in cell # 208

DN1

Main Area

105 CMR 451.353*
105 CMR 451.353*
105 CMR 451.370*

Interior Maintenance: Ceiling tiles dirty
Interior Maintenance: Ceiling vents dusty
Garbage Storage: Garbage stored in an unsanitary condition, trash can covers missing flaps

Slop Sink

No Violations Noted

Toilet Area

105 CMR 451.123*

Maintenance: Floor damaged

Showers – 1st Floor

105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123

Maintenance: Wall vents dusty in shower # 1-3
Maintenance: Soap scum on walls in shower # 1-3
Maintenance: Floor dirty in shower # 2

Showers – 2nd Floor

105 CMR 451.123*
105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 4-7
Maintenance: Rusty shower hooks in shower # 4-7

105 CMR 451.123*	Maintenance: Ceiling dirty, appearance of mold outside showers
<i>Recreation Area</i>	
105 CMR 451.353*	Interior Maintenance: Bird's nest in rafters
<i>Cells</i>	
105 CMR 451.353*	Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 101
105 CMR 451.353	Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 202 and 204
105 CMR 451.353	Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 208
105 CMR 451.350	Structural Maintenance: Wall not easily cleanable, hole in wall in cell # 208
105 CMR 451.353*	Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 205
105 CMR 451.353	Interior Maintenance: Ceiling vent dusty in cell # 208
105 CMR 451.353	Interior Maintenance: Light fixture blocked in cell # 102, 105, and 203
DS1	
<i>Main Area</i>	
105 CMR 451.353	Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged
105 CMR 451.353	Interior Maintenance: Ceiling vents dusty
<i>Slop Sink</i>	
105 CMR 451.353*	Interior Maintenance: Mop stored in bucket
<i>Showers – 1st Floor</i>	
105 CMR 451.123*	Maintenance: Rusty shower hooks in shower # 1-3
105 CMR 451.123*	Maintenance: Wall vents dusty in shower # 1-3
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, missing fixture in shower # 1
<i>Showers – 2nd Floor</i>	
105 CMR 451.123*	Maintenance: Floor paint peeling outside showers
105 CMR 451.123*	Maintenance: Rusty shower hooks in shower # 4-7
105 CMR 451.123*	Maintenance: Shower drains rusty in shower # 4-7
105 CMR 451.123*	Maintenance: Ceiling dirty, appearance of mold outside showers
<i>Recreation Area</i>	
105 CMR 451.353	Interior Maintenance: Bird's nest in rafters
<i>Cells</i>	
105 CMR 451.353*	Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 201
105 CMR 451.353*	Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 205
105 CMR 451.353*	Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged in cell # 208
105 CMR 451.350*	Structural Maintenance: Ceiling not easily cleanable, ceiling leaking in cell # 208
105 CMR 451.353*	Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 107, 202, and 205
105 CMR 451.353	Interior Maintenance: Light fixture blocked in cell # 101 and 102
BS101	
105 CMR 451.353*	Interior Maintenance: Ceiling vents dusty
105 CMR 451.353*	Interior Maintenance: Ceiling ventilation grilles damaged, rusted
105 CMR 451.353	Interior Maintenance: Floor not maintained in good repair, baseboard damaged under phones

105 CMR 451.353 Interior Maintenance: Trash can covers dirty

Bunks

No Violations Noted

Bathroom

105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, toilet # 7 out-of-order
105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, faucet loose at sink # 5
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, faucet loose at sink # 1

Showers

105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1-7
105 CMR 451.123* Maintenance: Rusty shower hooks in shower # 1-7
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower leaking in shower # 7

BN101

105 CMR 451.353* Interior Maintenance: Ceiling vent dusty
105 CMR 451.350* Structural Maintenance: Ceiling not easily cleanable, ceiling leaking
105 CMR 451.353* Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged
105 CMR 451.350* Structural Maintenance: Floor not easily cleanable, floor damaged

Bunks

No Violations Noted

Bathroom

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, sink # 7 out-of-order

Showers

105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1-7
105 CMR 451.123 Maintenance: Rusty shower hooks in shower # 1-7
105 CMR 451.123 Maintenance: Ceiling vent dusty

BS201

105 CMR 451.350* Structural Maintenance: Floor not easily cleanable, baseboard missing behind bed # 13 and 14
105 CMR 451.350 Structural Maintenance: Floor not easily cleanable, baseboard missing behind bed # 16 and 17
105 CMR 451.353* Interior Maintenance: Ceiling vents dusty
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged outside of bathroom
105 CMR 451.353 Interior Maintenance: Floor not maintained in good repair, baseboard damaged under phones

Bunks

No Violations Noted

Bathroom

105 CMR 451.123* Maintenance: Light fixtures rusty
105 CMR 451.123 Maintenance: Sink caulking damaged at sink # 1-7
105 CMR 451.123 Maintenance: Floor dirty

Showers

105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1-7
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower # 6 out-of-order
105 CMR 451.123 Maintenance: Rusty shower hooks in shower # 1-7

105 CMR 451.123 Maintenance: Wall damaged, paint peeling
105 CMR 451.123 Maintenance: Ceiling vent dusty outside showers

BN201

105 CMR 451.353* Interior Maintenance: Ceiling vents dusty
105 CMR 451.353* Interior Maintenance: Floor not maintained in good repair, floor tiles damaged
105 CMR 451.353* Interior Maintenance: Ceiling ventilation grilles rusty
105 CMR 451.353* Interior Maintenance: Floor not maintained in good repair, baseboard damaged
105 CMR 451.353* Interior Maintenance: Outlet cover not installed properly

Bunks

No Violations Noted

Bathroom

105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, faucet loose at sink # 1
105 CMR 451.123 Maintenance: Sink caulking damaged at sink # 4
105 CMR 451.123 Maintenance: Floor dirty
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, toilet leaking at toilet # 1-6

Showers

105 CMR 451.123* Maintenance: Rusty metal shut-offs at shower # 1 and 2
105 CMR 451.123* Maintenance: Rusty shower hooks in shower # 1-7
105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1-7
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, leak at shower # 1 and 5
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower # 6 out-of-order
105 CMR 451.123 Maintenance: Ceiling vent dusty outside showers

C1

Main Area

105 CMR 451.350* Structural Maintenance: Wall damaged, hole in wall near cell # 113
105 CMR 451.353* Interior Maintenance: Ceiling vents dusty
105 CMR 451.353* Interior Maintenance: Chair not easily cleanable, officer's chair padding damaged
105 CMR 451.353 Interior Maintenance: Trash can covers dirty

Slop Sink

105 CMR 451.353* Interior Maintenance: Floor not maintained in good repair, floor tiles damaged

Showers

105 CMR 451.123* Maintenance: Rusty metal doors
105 CMR 451.123* Maintenance: Soap scum on walls in showers
105 CMR 451.123* Maintenance: Rusty shower hooks
105 CMR 451.123* Maintenance: Ceiling dirty, appearance of mold outside showers
105 CMR 451.123* Maintenance: Ceiling damaged, paint peeling outside showers

Recreation Area

105 CMR 451.353* Interior Maintenance: Bird's nest in rafters

Cells

105 CMR 451.140* Adequate Ventilation: Inadequate ventilation, wall ventilation grilles blocked in cell # 103, 107, 110, 114, 115, 116, 126, 130, 206, 209, 212, 218, 227, and 232
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 117 and 234

Visitor Room

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Non-Contact Room

105 CMR 451.350*

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

105 CMR 451.353*

Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

G Block

Main Area

105 CMR 451.353

Interior Maintenance: Floor not maintained in good repair, paint peeling

GE South

105 CMR 451.353*

Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

105 CMR 451.350*

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

Slop Sink

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 1 and 2

105 CMR 451.123*

Maintenance: Rusty shower hooks in shower # 1 and 2

105 CMR 451.123*

Maintenance: Ceiling vent rusty

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, handicap shower out-of-order

Chemical Storage

No Violations Noted

Cells

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 103, 108, 202, and 208

GE North

105 CMR 451.370

Garbage Storage: Garbage stored in an unsanitary condition, trash can missing cover

Slop Sink

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Showers

105 CMR 451.123*

Maintenance: Pipe chase door rusty in shower # 1-3

105 CMR 451.123*

Maintenance: Ceiling vent rusty

105 CMR 451.123*

Maintenance: Rusty shower hooks in shower # 1-3

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 1-3

Recreation Deck

No Violations Noted

Cells

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 109, 115, 209, 212, and 214

105 CMR 451.353

Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 115, 116, 117, 118, 211, 213, 214, 216, 217, and 218

GW North

Main Area

105 CMR 451.350* Structural Maintenance: Wall not easily cleanable, hole in wall near cell # 109
105 CMR 451.350* Structural Maintenance: Ceiling not easily cleanable, ceiling leaking
105 CMR 451.353* Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged
105 CMR 451.353 Interior Maintenance: Floor not maintained in good repair, paint peeling
105 CMR 451.370 Garbage Storage: Garbage stored in an unsanitary condition, trash can missing cover

Slop Sink

No Violations Noted

Showers

105 CMR 451.123 Unable to Inspect – In Use
Maintenance: Ceiling dirty, appearance of mold outside showers

Cells

105 CMR 451.140* Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 214
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 113 and 116
105 CMR 451.103 Mattresses: Mattress damaged in cell # 216

GW South

Main Area

105 CMR 451.353* Interior Maintenance: Ceiling vents dusty
105 CMR 451.353 Interior Maintenance: Wall not maintained in good repair, paint peeling at entrance

Slop Sink

No Violations Noted

Showers

105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1 and 2
105 CMR 451.353* Interior Maintenance: Ceiling vent dusty

Cells

105 CMR 451.140* Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 105, 107, 204, 205, 206, and 207

3rd Floor

Main Hallway

Janitor's Closet – 3022

105 CMR 451.353* Interior Maintenance: Ceiling vent dusty
105 CMR 451.353* Interior Maintenance: Trash in slop sink

Staff Bathroom – 3021

No Violations Noted

Storage – 3020

Unable to Inspect – No Access

Janitor's Closet – 3018

105 CMR 451.353
105 CMR 451.130
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty
Plumbing: Plumbing not maintained in good repair, slop sink leaking
Interior Maintenance: Floor dirty

Janitor's Closet - 3010

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Staff Bathroom – 3009

No Violations Noted

Storage – 3008

FC 4-601.11(A)*

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, coffee maker dirty

FC 4-903.11(A)(2)

Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered

Janitor's Closet – 3006

105 CMR 451.353*
105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty
Interior Maintenance: Debris clogging slop sink drain

Staff Bathroom – 3003

No Violations Noted

FS3

Main Area

105 CMR 451.350*
105 CMR 451.353*
105 CMR 451.353*
105 CMR 451.370

Structural Maintenance: Ceiling not easily cleanable, ceiling leaking
Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged
Interior Maintenance: Ceiling vents dusty
Garbage Storage: Garbage stored in an unsanitary condition, trash can covers missing flaps

105 CMR 451.353

Interior Maintenance: Wall dirty, appearance of mold near recreation deck

Slop Sink

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Medical Room

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Toilet Area

Unable to Inspect – In Use

Showers – 1st Floor

105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 1-3
Maintenance: Wall vent dusty in shower # 1-3
Maintenance: Shower hooks rusty in shower # 1-3

Showers – 2nd Floor

105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.130*

Maintenance: Soap scum on walls in shower # 4-7
Maintenance: Floor damaged, paint peeling outside showers
Maintenance: Floor drains rusty in shower # 4-7
Maintenance: Shower hooks rusty in shower # 4-7
Plumbing: Plumbing not maintained in good repair, shower # 5 out-of-order

Cells

- 105 CMR 451.353* Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 301, 302, 304, and 306
- 105 CMR 451.353 Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 402 and 405
- 105 CMR 451.350 Structural Maintenance: Ceiling not easily cleanable, ceiling leaking outside cell # 401
- 105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles rusted

FN3

Main Area

- 105 CMR 451.353 Interior Maintenance: Ceiling vents dusty
- 105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

Slop Sink

- 105 CMR 451.350* Structural Maintenance: Ceiling damaged

Showers – 1st Floor

- 105 CMR 451.123* Maintenance: Wall vent dusty
- 105 CMR 451.123* Maintenance: Floor drains rusty in shower # 1-3
- 105 CMR 451.123* Maintenance: Shower hooks rusty in shower # 1-3
- 105 CMR 451.123 Maintenance: Soap scum on walls in shower # 1-3

Showers – 2nd Floor

- 105 CMR 451.123* Maintenance: Ceiling vent dusty
- 105 CMR 451.123* Maintenance: Floor drains rusty in shower # 4-7
- 105 CMR 451.123* Maintenance: Shower hooks rusty in shower # 4-7
- 105 CMR 451.123 Maintenance: Soap scum on walls in shower # 4-7

Cells

- 105 CMR 451.353* Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 307
- 105 CMR 451.350* Structural Maintenance: Floor not easily cleanable, floor damaged in cell # 402
- 105 CMR 451.353* Interior Maintenance: Ceiling vent dusty in cell # 408 and 409
- 105 CMR 451.350* Structural Maintenance: Ceiling not easily cleanable, ceiling leaking in cell # 408
- 105 CMR 451.343* Electric Fixtures in Cell: No electrical outlet in cell # 408

H3

Main Area

- 105 CMR 451.353* Interior Maintenance: Ceiling vents dusty
- 105 CMR 451.353* Interior Maintenance: Ceiling tiles dirty
- 105 CMR 451.353 Interior Maintenance: Floor not maintained in good repair, floor tiles damaged near recreation deck
- 105 CMR 451.353 Interior Maintenance: Staircase dirty

Slop Sink

- 105 CMR 451.353* Interior Maintenance: Ceiling vent dusty
- 105 CMR 451.353 Interior Maintenance: Floor not maintained in good repair, floor tiles damaged
- 105 CMR 451.353 Interior Maintenance: Wall not maintained in good repair, wall paint peeling

Showers

- 105 CMR 451.123* Maintenance: Shower hooks rusty in shower # 1-9
- 105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1-9

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, leak in shower # 9
105 CMR 451.123* Maintenance: Ceiling dirty, appearance of mold outside showers
105 CMR 451.123 Maintenance: Ceiling vent dusty in all showers
105 CMR 451.123 Maintenance: Curtains missing in shower # 1, 2, and 6
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower # 6 out-of-order

Cells

105 CMR 451.353* Interior Maintenance: Ceiling dirty in cell # 412
105 CMR 451.353 Interior Maintenance: Ceiling dirty in cell # 325
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 315, 413, 414, and 431
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 308, 310, 330, 408, 413, 419, and 421
105 CMR 451.353 Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 437 and 438
105 CMR 451.344 Illumination in Habitable Areas: Light not functioning properly, light out in cell # 438
105 CMR 451.353 Interior Maintenance: Floor dirty in cell # 335

DN3

Main Area

105 CMR 451.353 Interior Maintenance: Ceiling tiles dirty

Slop Sink

105 CMR 451.353* Interior Maintenance: Ceiling vent dusty
105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, slop sink leaking

Toilet Area

No Violations Noted

Showers – 1st Floor

105 CMR 451.123* Maintenance: Shower hooks rusty in shower # 1-3
105 CMR 451.123* Maintenance: Floor drains rusty in shower # 1-3
105 CMR 451.123 Maintenance: Soap scum on walls in shower # 1-3
105 CMR 451.123 Maintenance: Wall vent dusty in shower # 1-3

Showers – 2nd Floor

105 CMR 451.123* Maintenance: Shower hooks rusty in shower # 4-7
105 CMR 451.123* Maintenance: Floor drains rusty in shower # 4-7
105 CMR 451.123* Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged outside showers
105 CMR 451.123 Maintenance: Light out in shower # 5

Recreation Deck

No Violations Noted

Stairway # 309

105 CMR 451.350 Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

Cells

No Violations Noted

DS3

Main Area

105 CMR 451.353* Interior Maintenance: Wall dirty near recreation deck

Slop Sink

105 CMR 451.353 Interior Maintenance: Ceiling vent dusty
105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

Toilet Area

105 CMR 451.123 Maintenance: Floor dirty
105 CMR 451.123 Maintenance: Baseboard missing

Showers – 1st Floor

105 CMR 451.123* Maintenance: Shower hooks rusty in shower # 1-3
105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1-3
105 CMR 451.123* Maintenance: Ceiling vents dirty

Showers – 2nd Floor

105 CMR 451.123* Maintenance: Floor not easily cleanable, paint peeling outside showers
105 CMR 451.123* Maintenance: Shower hooks rusty in shower # 4-7
105 CMR 451.123* Maintenance: Shower drains rusty in shower # 4-7
105 CMR 451.123* Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged outside showers
105 CMR 451.123* Maintenance: Ceiling dirty, appearance of mold outside showers
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, leak at shower # 4, 5, and 6

Recreation Deck

No Violations Noted

Cells

105 CMR 451.353* Interior Maintenance: Floor not maintained in good repair, paint peeling in cell # 301, 302, 303, 304, 305, 306, 307, 401, and 407
105 CMR 451.353* Interior Maintenance: Bed not maintained in good repair, paint peeling in cell # 406 and 407
105 CMR 451.353* Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 403
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 302
105 CMR 451.353* Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 408

E3

105 CMR 451.353* Interior Maintenance: Wall not maintained in good repair, paint peeling
105 CMR 451.353* Interior Maintenance: Ceiling vents dusty
105 CMR 451.344 Illumination in Habitable Areas: Light not functioning properly, light out
105 CMR 451.370 Garbage Storage: Garbage stored in an unsanitary condition, trash can covers missing flaps

Slop Sink

105 CMR 451.353 Interior Maintenance: Floor not maintained in good repair, floor tiles damaged
105 CMR 451.353* Interior Maintenance: Ceiling vent dusty

Showers

105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1-9
105 CMR 451.123* Maintenance: Ceiling vents dirty in shower # 1-9

105 CMR 451.123* Maintenance: Shower hooks rusty in shower # 1-9
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower leaking in shower # 3
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower # 5 out-of-order

Stairway # 339

105 CMR 451.350 Structural Maintenance: Ceiling not easily cleanable, ceiling leaking

Cells

105 CMR 451.353* Interior Maintenance: Wall not maintained in good repair, paint peeling in cell # 301-335 and 401-436
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 303, 305, 310, 322, 412, 426, and 431
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 303 and 407
105 CMR 451.353* Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 307
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 317 and 421
105 CMR 451.353* Interior Maintenance: Molding damaged in cell # 438
105 CMR 451.353* Interior Maintenance: Ceiling vent dusty in cell # 438

C3

105 CMR 451.353* Interior Maintenance: Wall not maintained in good repair, paint peeling near phones
105 CMR 451.353* Interior Maintenance: Ceiling vents dusty
105 CMR 451.353* Interior Maintenance: Ceiling tiles dirty

Slop Sink

105 CMR 451.353* Interior Maintenance: Ceiling vent dusty
105 CMR 451.353* Interior Maintenance: Ceiling not maintained in good repair, ceiling tiles damaged

Showers

105 CMR 451.123* Maintenance: Ceiling dirty, appearance of mold outside showers
105 CMR 451.123 Maintenance: Curtain missing at shower # 1
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, leak at shower # 2, 4, and 6
105 CMR 451.123 Maintenance: Rusty shower hooks in shower # 1-9
105 CMR 451.123 Maintenance: Soap scum on walls in shower # 1-9
105 CMR 451.123 Maintenance: Rusty trap doors in shower # 7, 8, and 9

Cells

105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 421 and 436
105 CMR 451.353 Interior Maintenance: Ceiling not maintained in good repair, paint peeling in cell # 405
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 401
105 CMR 451.353 Interior Maintenance: Floor not maintained in good repair, floor damaged in cell # 301-335 and 401-436

Warehouse – Support Building

Freezer

No Violations Noted

Fridge # 1

No Violations Noted

Fridge # 2
FC 6-202.11(A)*

Design, Construction, and Installation; Functionality: Light bulbs not shatter-resistant or protected by light shields

Male Bathroom

No Violations Noted

Female Bathroom
105 CMR 451.123*
105 CMR 451.123*

Maintenance: Ceiling vent dusty
Maintenance: Wall not easily cleanable, hole in wall behind flusher

Inmate Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Work Crew Area

Bathroom

No Violations Noted

Break Area
FC 4-204.112(A)

Design and Construction, Functionality: No functioning thermometer in refrigerator

K9 Unit

Bathroom # 1

Unable to Inspect – In Use

Bathroom # 2
105 CMR 451.123*
105 CMR 451.123*

Maintenance: Wall not easily cleanable, wall damaged behind door
Maintenance: Ceiling vent dusty

Janitor's Closet
105 CMR 451.353*

Interior Maintenance: Mop stored in bucket

Kitchen Area
105 CMR 451.350

Structural Maintenance: Wall not easily cleanable, wall damaged around dryer exhaust pipe

Garage

Bathroom – W124

No Violations Noted

Janitor's Closet – W123

No Violations Noted

Print Shop
FC 4-601.11(A)*

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, coffee maker dirty

FC 6-501.11*

Maintenance and Operation; Repairing: Facility not in good repair, refrigerator door broken

Inmate Bathroom
105 CMR 451.123

Maintenance: Paper towel dispenser missing

Staff Bathroom
105 CMR 451.126*

Hot Water: Hot water temperature recorded at 133⁰F

Janitor's Closet

No Violations Noted

Janitor's Closet – W111
105 CMR 451.130*

Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink

Observations and Recommendations

1. The inmate population was 1175 at the time of inspection.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please indicate next to each entry on the inspection report a plan of correction. Said plan of correction must be submitted within ten working days of receiving this report and should detail the specific steps that will be taken and the date of expected compliance. The plan of correction should be submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X – Minimum Sanitation Standards for Food Establishments" and "[1999 Food Code](#)".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Nicholas Gale
Environmental Health Inspector, CSP, BEH

cc: Suzanne K. Condon, Associate Commissioner, Director, BEH
Steven Hughes, Director, CSP, BEH
John W. Polanowicz, Secretary, Executive Office of Health and Human Services
Luis S. Spencer, Commissioner, DOC
Antone Moniz, Superintendent
Captain Eugene Irvine, EHSO
Michelle Roberts, MA, CHO, Health Director, Plymouth Health Department
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Andrea Cabral, Secretary, EOPS