

Recent Drought Impacts on Rivers

Massachusetts Rivers Alliance Presentation to Drought Management Task Force September 3, 2020



Ipswich River, 8/28



Photo: Ipswich River Watershed Association James Brook Ayer Road, Groton 8/15

Dry streambed, one of several in the area.

Photo: Kathryn Nelson, Nashua River Watershed Association

Photo: Peter Severance, River Merrimack

Stony Brook at Wilson Lake in Chelmsford 9/1




Photo: Peter Severance, River Merrimack

Concord River, East Merrimack Street, Lowell 9/1



Beaver Brook, Beaver Street, Lowell, 9/1

Photo: Peter Severance, River Merrimack



Spicket River at Canal Street, Lawrence 9/1




Photo: Peter Severance, River Merrimack

Shawsheen River 9/1

Photo: Peter Severance, River Merrimack






Loring Street, Lawrence

Balmoral Street, Andover

Sudbury River, Saxonville MA

Graph courtesy of Marlies Henderson.

USGS 01098530 SUDBURY RIVER AT SAXONVILLE, MA




---- Provisional Data Subject to Revision ----

riangle Median daily statistic (40 years) imes Measured discharge $extcolor{black}{igoplus}$ Discharge


Silver Brook, Farmington River Watershed (8/24)

Photo: Alisa Phillips-Griggs, FRWA



Clam River, Sandisfield (Farmington River Watershed)

Photo: Alisa Phillips-Griggs, FRWA



Farmington River Watershed

Photo: Alisa Phillips-Griggs, FRWA



West Branch Farmington River, Otis

Hubbard Brook, Granville