
Streamflow and Groundwater Conditions in Massachusetts

Sept. 3, 2020

Gardner Bent
U.S. Geological Survey
New England Water Science Center




Average Streamflow Conditions – April 2020




Average Streamflow Conditions – May 2020

Hay 2020




Average Streamflow Conditions – June 2020


June 2020




Average Streamflow Conditions – July 2020




Average Streamflow Conditions – August 2020







Last updated: 2020-09-01




USGS 01108000 TAUNTON RIVER NEAR BRIDGEWATER, MA



28-day average streamflow

Last updated: 2020-09-01




USGS 01176000 QUABOAG RIVER AT WEST BRIMFIELD, MA



28-day average streamflow

Last updated: 2020-09-01




USGS 01197500 HOUSATONIC RIVER NEAR GREAT BARRINGTON, MA



Streamflow Conditions - Sept. 1, 2020

Tuesday, September 01, 2020 08:30ET



GW Conditions Late June, 2020




science for a changing world

GW Conditions Late July, 2020



science for a changing world


GW Conditions Late August, 2020








Explanation - Percentile classes								
•		0			•	•		O Real Time
New Low	<10	10-24	25-75	76-90	>90	New	Not	Continuous Periodic
	Much Below Normal	Below Normal	Normal	Above Normal	Much Above Normal	High	Ranked	Measurements


Groundwater Conditions – Aug. 31, 2020











Questions