

DEVAL L. PATRICK GOVERNOR

JOHN W. POLANOWICZ SECRETARY

EILEEN M. SULLIVAN ACTING COMMISSIONER The Commonwealth of Massachusetts Executive Office of Health and Human Services Department of Public Health Bureau of Environmental Health Community Sanitation Program 180 Beaman Street West Boylston, MA 01583 Telephone: 508-792-7880, ext. 2338 Facsimile: 508-792-7706 TTY: 508-835-9796 paul.halfmann@state.ma.us

December 31, 2014

Thomas Bowler, Sheriff Berkshire County Jail and House of Corrections 467 Cheshire Road Pittsfield, MA 01201

Re: Facility Inspection - Berkshire County Jail and House of Corrections, Pittsfield

Dear Sheriff Bowler:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Berkshire County Jail and House of Corrections on December 2, 2014 accompanied by Captain Katherine Sonsini. Violations noted during the inspection are listed below including 152 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

Front Entry

Female Bathroom	
105 CMR 451.123	Maintenance: Ceiling vent dusty
Male Bathroom	
	No Violations Noted
Kitchen	
Walk-in Freezer	
	No Violations Noted
Walk-in Cooler	
	No Violations Noted

<i>Reach-in Freezer</i> FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, condenser was leaking
Changing Room	No Violations Noted
Dry Storage	No Violations Noted
Inmate Bathroom	No Violations Noted
Storage Room	No Violations Noted
Chemical Storage	No Violations Noted
Inmate Dining	No Violations Noted
<u>Staff Dining</u> FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, refrigerator out-of-service
<u>Bakery</u>	No Violations Noted
Visitation Area	No Violations Noted
<u>Property</u>	No Violations Noted
<u>Laundry</u>	No Violations Noted
<u>Commissary</u>	No Violations Noted
Vocational Education	
Inmate Bathroom	No Violations Noted
Staff Bathroom	No Violations Noted
Classrooms	No Violations Noted
<u>Recreational Area</u>	No Violations Noted

Intake/Booking

Medical Triage 105 CMR 451.353	Interior Maintenance: Examination table bench cushion damaged
Transportation Room	No Violations Noted
Cells	No Violations Noted
HSU	
Medical Waste Storage	No Violations Noted
Dental Office	No Violations Noted
Exam Rooms	No Violations Noted
Tub Room	No Violations Noted
Staff Bathroom 105 CMR 451.126	Hot Water: Hot water temperature recorded at 106°F
<u>A Pod</u>	
Staff Bathroom	No Violations Noted
<i>Cells</i> 105 CMR 451.103	Mattresses: Mattress damaged in cell # 209
Day Room 105 CMR 451.353*	Interior Maintenance: Ceiling stained in common area
Showers 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123*	Maintenance: Floor not easily cleanable in shower # 1-7 Maintenance: Showers leaking into back chase area Maintenance: Expansion joints hold stagnant water in shower # 1, 2, and 3
Sub Dayroom Shower 105 CMR 451.123* 105 CMR 451.123*	Maintenance: Floor not easily cleanable Maintenance: Air vent dusty
Janitor Closet	No Violations Noted

<u>B Pod</u>

Staff Bathroom 105 CMR 451.123	Interior Maintenance: Air vent rusted
Cells 105 CMR 451.353* 105 CMR 451.353 105 CMR 451.353*	Interior Maintenance: Air vent blocked in cell # 105 and 205 Interior Maintenance: Air vent blocked in cell # 106 Interior Maintenance: Air vent rusted in cell # 106, 107, 109, 110, 202, 203, 204, 207, 208, 211, 212, 214, 215, and 217
Day Room	No Violations Noted
Showers	
105 CMR 451.123*	Maintenance: Floor not easily cleanable in shower # 1-7
105 CMR 451.123*	Maintenance: Black substance on shower walls # 1-7
105 CMR 451.123*	Maintenance: Showers were leaking into back chase area
Sub Dayroom Shower	
105 CMR 451.123*	Maintenance: Floor not easily cleanable
105 CMR 451.123	Maintenance: Soap scum on shower walls
105 CMR 451.123*	Maintenance: Shower were leaking into back chase area
Janitor's Closet	No Violations Noted
<u>C Pod</u>	
Staff Bathroom	
105 CMR 451.123	Maintenance: Ceiling vent dusty
105 CMR 451.126	Hot Water: Hot water temperature recorded at 106°F
Cells	
105 CMR 451.353*	Interior Maintenance: Debris in air vent in cell # 104, 105, 108, 110, 112, 213, and 214
105 CMR 451.353*	Interior Maintenance: Air vent rusted in cell # 107, 109, 110, 111, 114, 115, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 215, 216, 217, and 218
Showers	
105 CMR 451.123*	Maintenance: Floor not easily cleanable in shower # 1-7
105 CMR 451.123	Maintenance: Soap scum on shower walls # 1-7
105 CMR 451.123*	Maintenance: Showers were leaking into back chase area
105 CMR 451.123*	Maintenance: Expansion joints hold stagnant water in showers # 1, 2, and 3
Sub Dayroom Shower	
105 CMR 451.123*	Maintenance: Floor not easily cleanable
105 CMR 451.123*	Maintenance: Black substance on shower walls
Janitor's Closet	
FC 6-501.11	Maintenance and Operation; Repairing: Facility not in good repair, rusted door jamb
D Pod	
Staff Bathroom	
Siajj Duni UUni	No Violations Noted

Cells	No Violations Noted
Showers 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123*	Maintenance: Soap scum on shower walls # 1-7 Maintenance: Ceiling light rusted shower # 1-7 Maintenance: Showers were leaking into back chase area
<i>Sub Dayroom Shower</i> 105 CMR 451.123* 105 CMR 451.123*	Maintenance: Floor not easily cleanable Maintenance: Shower was leaking into back chase area
Janitor's Closet	No Violations Noted
<u>E Pod</u>	
Staff Bathroom 105 CMR 451.126	Hot Water: Hot water temperature recorded at 102°F
<i>Cells</i> 105 CMR 451.353* 105 CMR 451.353*	Interior Maintenance: Air vent rusted in cell # 101, 103, 105, 106, 107, 109, 110, 111, 112, 113, 114, 115, 117, 204, 206, 207, 208, 209, 210, 211, 214, 215, 216, and 217 Interior Maintenance: Air vent rusted in cell # 116, 202, 205, and 212
Showers 105 CMR 451.123* 105 CMR 451.123	Maintenance: Floor not easily cleanable in shower # 1-7 Maintenance: Black substance on shower walls # 1-7
Sub Dayroom Shower 105 CMR 451.123* 105 CMR 451.123	Maintenance: Floor not easily cleanable Maintenance: Soap scum on shower walls
Janitor's Closet	No Violations Noted
<u>F Pod</u>	Under Renovation-Not in Use
<u>G Pod</u>	
Staff Bathroom	No Violations Noted
Cells	No Violations Noted
Showers 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123*	Maintenance: Floor not easily cleanable in shower # 1-7 Maintenance: Black substance on shower walls # 1-7 Maintenance: Showers were leaking into back chase area on 1 st floor
<i>Sub Dayroom Shower</i> 105 CMR 451.123* 105 CMR 451.123	Maintenance: Floor not easily cleanable Maintenance: Soap scum on shower walls

Janitor's Closet

No Violations Noted

<u>H Pod – Regional Lockup</u>

Staff Bathroom	
	No Violations Noted
Cells	NT - X7' - 1 - 4' NT - 4 - J
	No Violations Noted
Showers	
105 CMR 451.123*	Maintenance: Floor not easily cleanable in showers # 1-7
105 CMR 451.123	Maintenance: Soap scum on shower walls # 1-7
Sub Dayroom Shower	
105 CMR 451.123*	Maintenance: Floor not easily cleanable
105 CMR 451.123	Maintenance: Soap scum on shower walls
Janitor's Closet	
	No Violations Noted
Warehouse	
105 CMR 451.350	Structural Maintenance: Entry door not rodent proof and weathertight
<i>Staff Bathroom</i> 105 CMR 451,126	Water Supply: No hot water supplied to handwash sink
100 Caviat +51,120	water Suppry. No not water suppried to handwash shike
Walk-in Cooler	
	No Violations Noted
Freezer	
FC 4-501.11(A)*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good
	repair, missing light bulb
FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, ice build-up on ceiling by door

Observations and Recommendations

1. The inmate population was 245 at the time of inspection.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at <u>www.mass.gov/dph/dcs</u> and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at <u>www.mass.gov/dph/fpp</u> and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely

Paul Halfmann, MPH Assistant Director, CSP, BEII

 cc: Suzanne K. Condon, Associate Commissioner, Director, BEH Steven Hughes, Director, CSP, BEH John W. Polanowicz Secretary, Executive Office of Health and Human Services Carol Higgins O'Brien, Commissioner, DOC John J. Quinn, Jr., Superintendent Captain Katherine Sonsini, EHSO Gina Armstrong, Health Director, Pittsfield Board of Health Clerk, Massachusetts House of Representatives Clerk, Massachusetts Senate Andrea Cabral, Secretary, EOPS