

CHARLES D. BAKER Governor

KARYN E. POLITO Lieutenant Governor The Commonwealth of Massachusetts Executive Office of Health and Human Services Department of Public Health Bureau of Environmental Health Community Sanitation Program 67 Forest Street, Suite # 100 Marlborough, MA 01752 Phone: 781-223-7503

MARYLOU SUDDERS Secretary

MARGRET R. COOKE Commissioner

Tel: 617-624-6000 www.mass.gov/dph

October 18, 2022

Thomas Neville, Superintendent Boston Pre-Release Center 430 Canterbury Street Roslindale, MA 02131 (electronic copy)

Re: Facility Inspection - Boston Pre-Release Center, Roslindale

Dear Superintendent Neville:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 2013 Food Code; 105 CMR 500.000 Good Manufacturing Practices for Food; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; the Department's Community Sanitation Program (CSP) conducted an inspection of the Boston Pre-Release Center on October 13, 2022 accompanied by Matthew Knarr, Environmental Health and Safety Officer. Violations noted during the inspection are listed below including 16 repeat violations:

Should you have any questions, please don't hesitate to contact me.

Shanene Purce

Shanene Pierce Environmental Health Inspector, CSP, BEH

Margret R. Cooke, Commissioner, DPH cc: Nalina Narain, Director, BEH Steven Hughes, Director, CSP, BEH Marylou Sudders, Secretary, Executive Office of Health and Human Services (electronic copy) Carol A. Mici, Commissioner, DOC (electronic copy) Terrence Reidy, Secretary, EOPSS (electronic copy) Timothy Gotovich, Director, Policy Development and Compliance Unit (electronic copy) Matthew Knarr, EHSO (electronic copy) Daniel J. Prendergast, Assistant Commissioner, ISD/Health Division, City of Boston (electronic copy) Clerk, Massachusetts House of Representatives (electronic copy) Clerk, Massachusetts Senate (electronic copy)

**HEALTH AND SAFETY VIOLATIONS** (\* indicates conditions documented on previous inspection reports)

## **FIRST FLOOR**

## Lobby

10009	No Violations Noted
Visitor's Room #A1-4	No Violations Noted
Female Visitor's Bathroom #A	<i>1-5</i> No Violations Noted
Male Visitor's Bathroom #A1-0	6 No Violations Noted

Janitor's Closet #A1-7

No violations Noted

# A Wing

Shift Commander's Office #A	<i>I-8</i> No Violations Noted
Female Staff Bathroom # A1-9	No Violations Noted
Male Staff Bathroom # A1-10	No Violations Noted
Intake Holding Area # A1-12	No Violations Noted
Property # A1-17	No Violations Noted
Holding Cell # A1-18	No Violations Noted
Weight Room # A1-19	No Violations Noted
Male Staff Locker Room #A1	29/30 No Violations Noted
Janitor's Closet # A1-31	No Violations Noted
Female Staff Locker Room # A 105 CMR 451.130	<i>1-32/33</i> Plumbing: Plumbing not maintained in good repair, hot water control not functioning properly

FC 6-501.112	floor under dry storage shelves Maintenance and Operations; Removing Dead or Trapped Birds, Insects, Rodents and other Pest: Dead mouse observed on trap under dry storage shelves
Dry Storage Room # A1-46 FC 6-501.12(A)*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, rodent droppings observed on
Prep Table	No Violations Noted
Walk-in Refrigerator	No Violations Noted
Walk-in Freezer	No Violations Noted
Bathroom	No Violations Noted
Walk-in Freezer (Outside)	No Violations Noted
<b>Food Service Area</b> The following Food Code viola	ations listed in <b>BOLD</b> were observed to be corrected on-site.
Dental Room # A1-26 105 CMR 451.353	Interior Maintenance: Upholstery damaged on patient chair
Exam Room # A1-25	No Violations Noted
Medical Lab # A1-24	No Violations Noted
Bathroom #A1-23	No Violations Noted
Health Service Unit	
Office # A1-41	No Violations Noted
Tool Crib #A1-10	No Violations Noted
<i>Maintenance</i> # <i>A1-39</i>	No Violations Noted
Storage/Warehouse #A1-38	No Violations Noted
Mechanical Room # A1-36 (Me	edical Waste Storage) No Violations Noted

<i>Office</i> # <i>A1</i> -47	
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, window does not open and close properly
Mechanical Warewashing Roor	n
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, water dripping from ceiling tiles near warewash machine
Handwash Sink	No Violations Noted
Traulsen Refrigerator	
Tradisen Kejrigeralor	No Violations Noted
Food Service Line	No Violations Noted
Traulsen Warmer	No Violations Noted
Rubbish Room (Chemical Stora	(qe) # 41-51
Rubbish Robin (Chemical Stora	No Violations Noted
Supply Room # A1-50	No Violations Noted
Ice Machine	
	No Violations Noted
Grease Hood	
	No Violations Noted
Asber Freezer	
	No Violations Noted
Inmate Dining Room # A1-52	
	No violations Noted
Staff Dining Room # A1-53	
<i></i>	No Violations Noted
<u> B Wing – P1 Unit</u>	
Day Room	
Duy 100m	No Violations Noted
Bathroom #B1-31	
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handicapped toilet out-of-order

Shower Room # B1-33 105 CMR 451.123 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123*	Maintenance: Floor paint damaged and no longer cleanable throughout sh Maintenance: Soap scum on walls in shower # 3 and 7 Maintenance: Door frame paint damaged at entrance Maintenance: Wall dirty in shower # 2 Maintenance: Wall dirty in shower # 4	hower area
Janitor's Closet # B1-34 105 CMR 451.353* 105 CMR 451.353	Interior Maintenance: Water pooling on floor Interior Maintenance: Water leaking from closet into hallway	
Laundry Room	No Violations Noted	
<i>Cells</i> 105 CMR 451.321* 105 CMR 451.360	Cell Size: Inadequate floor space, cells triple bunked Protective Measures: Rodent droppings observed on floor in cell # B106	
<u>C Wing – M1 Unit</u>	Unable to Inspect – Quarantine/Isolation Unit	
SECOND FLOOR		
<u>A Wing</u>		
<i>Office</i> # <i>A2-6</i>	No Violations Noted	
<i>Office</i> # <i>A2-7</i>	No Violations Noted	
<i>Office</i> # <i>A2-9</i>	No Violations Noted	
<i>Office</i> # <i>A2-10</i>	No Violations Noted	
Closet #A2-8	Unable to Inspect – Locked	
<i>Multi-Purpose Room # A2-2</i> 105 CMR 451.353*	Interior Maintenance: Door hinge detached from wall	
Classroom # A2-4	No Violations Noted	
Classroom #A2-5	No Violations Noted	
Staff Bathroom # A2-34	No Violations Noted	
<i>Office</i> # <i>A2-35</i>	No Violations Noted	
451-22(2)-Boston Pre-Release-Rep		Page 5 of 7

Storage # A2-36	Unable to Inspect – Locked
Barber Shop # A2-11	Unable to Inspect – Locked
Work Release Offices	No Violations Noted
Janitor's Closet # A2-12	No Violations Noted
Administration Area	
Janitor's Closet # A2-24	No Violations Noted
Female Staff Bathroom # A2-25	No Violations Noted
Male Staff Bathroom # A2-26	No Violations Noted
Kitchenette	No Violations Noted
IPS	Unable to Inspect – Locked
<u>B Wing – P2 Unit</u>	
Day Room	No Violations Noted
Bathroom # B2-31 105 CMR 451.123	Maintenance: Ceiling louver/grill cover missing in handicapped stall
Janitor's Closet # B2-32	No Violations Noted
Shower Room # B2-33 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1, 2, 4, 5, and 7 Maintenance: Floor paint damaged and no longer cleanable throughout shower area Maintenance: Wall dirty in shower # 1 and 5 Maintenance: Ceiling dirty throughout shower area, possible mold/mildew
Laundry Room # B2-34	No Violations Noted
<i>Cells</i> 105 CMR 451.321*	Cell Size: Inadequate floor space, cells triple bunked

<u>C Wing – M2 Unit</u> 105 CMR 451.350	Structural Maintenance: Window does not open and close properly in hallway near stairwell # 4
Computer Classroom	No Violations Noted
Laundry Room # C2-31	No Violations Noted
Bathroom # C2-32 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # 1 Maintenance: Floor paint damaged and no longer cleanable throughout shower area Maintenance: Wall dirty in shower # 3
Janitor's Closet # C2-34	No Violations Noted
Cells	No Violations Noted

### **Observations and Recommendations**

- 1. The inmate population was 46 at the time of inspection.
- 2. M1 Unit of C Wing was the COVID-19 quarantine/isolation area. There were 3 inmates housed in the M1 Unit.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at <u>www.mass.gov/dph/dcs</u> and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment Regulations or download a copy, please visit the Food Protection website at <a href="http://www.mass.gov/dph/fpp">www.mass.gov/dph/fpp</a> and click on "Retail food". Then under DPH Regulations and FDA Code click "Merged Food Code" or "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments".

To review the Labeling regulations please visit the Food Protection website at <u>www.mass.gov/dph/fpp</u> and click on "Food Protection Program regulations". Then under Food Processing click "105 CMR 500.000: Good Manufacturing Practices for Food".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely, Shanene Purce

Shanene Pierce Environmental Health Inspector, CSP, BEH