



The Commonwealth of Massachusetts  
 Executive Office of Health and Human Services  
 Department of Public Health  
 Bureau of Environmental Health  
 Community Sanitation Program  
 5 Randolph Street, Canton, MA 02021  
 Phone: 781-828-7700 Fax: 781-828-7703

CHARLES D. BAKER  
 Governor

KARYN E. POLITO  
 Lieutenant Governor

MARYLOU SUDDERS  
 Secretary

MONICA BHAREL, MD, MPH  
 Commissioner

Tel: 617-624-6000  
[www.mass.gov/dph](http://www.mass.gov/dph)

April 5, 2019

Thomas M. Hodgson, Sheriff  
 Bristol County Sheriff's Office  
 Bristol County Jail and House of Correction  
 400 Faunce Corner Road  
 North Dartmouth, MA 02747 (electronic copy)

Re: Facility Inspection - Bristol County Jail and House of Correction, North Dartmouth

Dear Sheriff Hodgson:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 2013 Food Code; 105 CMR 500.000 Good Manufacturing Practices for Food; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Bristol County Jail and House of Correction on March 18 and 29, 2019 accompanied by Lieutenant Andrew Mitzan, Environmental Health and Safety Officer; Michael Moreira, Fire and Safety Officer; and Amy Riordan, Community Sanitation Program. Violations noted during the inspection are listed below including 131 repeat violations:

**HEALTH AND SAFETY VIOLATIONS**

(\* indicates conditions documented on previous inspection reports)

**Entrance**

*Lobby*

No Violations Noted

*Male Bathroom*

No Violations Noted

*Female Bathroom*

No Violations Noted

*Janitor's Closet*

No Violations Noted

*Male Shower Room*

105 CMR 451.123

Maintenance: Ceiling vent dusty

*Female Shower Room*

No Violations Noted

**Inside Area**

**Rotunda**

*Janitor's Closet*

No Violations Noted

*Inmate Bathroom*

No Violations Noted

*Storage Closet*

No Violations Noted

*Barber Shop*

No Violations Noted

*Civilian Visiting Rooms*

No Violations Noted

*Non-Contact Visiting Room*

No Violations Noted

*Inmate Bathroom*

No Violations Noted

**Main Hallway**

*Medical Administration Room*

No Violations Noted

*Male Bathroom # B1-44*  
105 CMR 451.123\*

Maintenance: Partition rusted

*Female Bathroom # B1-45*

No Violations Noted

*Disciplinary Room*

No Violations Noted

*Laundry*

105 CMR 451.353

Interior Maintenance: One washing machine out-of-order

*Trash Room*

No Violations Noted

*Receiving Yard*

No Violations Noted

*Male Bathroom # B1-16*

Unable to Inspect – In Use

*Male Bathroom # B1-17*  
105 CMR 451.123

Maintenance: Ceiling vent clogged with debris

<i>Staff Bathroom # B1-9</i>	No Violations Noted
<i>Staff Bathroom # B1-10</i>	No Violations Noted
<i>Maintenance Shop</i>	No Violations Noted
<i>Old Print Shop - Offices</i>	No Violations Noted
<i>Wood Shop</i>	No Violations Noted
<i>Cart Storage Room</i>	No Violations Noted
<i>Welding Shop</i>	No Violations Noted
<b><u>Food Service</u></b>	
<b>Kitchen</b>	
<i>3-Compartment Sink</i>	No Violations Noted
<i>Handwash Sink (near 3-compartment sink)</i>	No Violations Noted
<i>Kettle Area</i> FC 4-901.11(A)	Protection of Clean Items, Drying: Clean and sanitized stainless steel trays not allowed to air dry fully, clean trays stored wet on rack
<i>Ice Machine</i>	No Violations Noted
<i>Dry Food Storage</i> FC 3-302.12	Preventing Food and Ingredient Contamination: Unlabeled flour container
<i>Dishwashing Machine Area</i> FC 5-202.13*	Plumbing System, Design: Air gap between water supply inlet (sink hose) and the flood level rim of sink (top of sink) is missing, sink sprayer was hanging below the top of sink
FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, ceiling dirty above warewash machine
FC 4-204.115	Design and Construction, Functionality: Temperature measuring device not functioning properly on warewashing machine
FC 4-901.11(A)	Protection of Clean Items, Drying: Clean and sanitized stainless steel trays not allowed to air dry fully, clean trays stored wet on rack
<i>Handwash Sink (near dishwashing machine)</i> FC 5-205.11(B)	Plumbing System, Operations and Maintenance: Handwashing sink used for an unapproved purpose, drinking pitchers stored in handwashing sink

<i>Cooler # 1</i> FC 3-305.11(A)(1)	Preventing Contamination from Premises: Food stored in an inappropriate location, uncovered bread stored in small cooler
FC 3-304.12(A)	Preventing Contamination from Utensils: Service utensils handle stored below the food and container line, scoop stored in peaches
<i>Cooler # 2</i> FC 3-302.11(A)(4)	Preventing Food and Ingredient Contamination: Preventing cross contamination, prepared food not appropriately covered on rack
<i>Freezer # 1</i>	No Violations Noted
Prep Serving Line FC 4-102.11(B)(2)	Materials for Construction and Repair; Multiuse: Unused single-service article not protected against contamination, plastic utensils stored uncovered
FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, wall cooling fan dusty
<i>Inmate Dining</i> FC 6-201.11*	Design, Construction and Installation: Floor not easily cleanable, paint damaged
<b><u>HSU</u></b>	
<i>Staff Bathroom</i> 105 CMR 451.123*	Maintenance: Ceiling vent dusty
<i>Inmate Bathroom # BLI-17</i>	No Violations Noted
<i>Office # BLI-19b</i> 105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged
<i>Large Nurse Office Space</i>	No Violations Noted
<i>Trauma Room BLI-18 # 6</i> 105 CMR 451.353*	Interior Maintenance: Ceiling tile water damaged
<i>Dental Area # 3</i>	No Violations Noted
<i>Eye Exam Room # BLI-21</i>	No Violations Noted
<i>Lab # 5</i> 105 CMR 451.353* 105 CMR 451.353* 105 CMR 451.350*	Interior Maintenance: Ceiling tiles water damaged Interior Maintenance: Ceiling tiles missing Structural Maintenance: Ceiling leaking
<i>Exam Room # 1</i>	No Violations Noted
<i>Exam Room # 2</i>	No Violations Noted

<i>Control Area</i>	No Violations Noted
<i>Nurse's Station</i>	No Violations Noted
<i>Janitor's Closet</i>	No Violations Noted
<i>Single Cells</i>	No Violations Noted
<i>Staff Bathroom # 2</i>	No Violations Noted
<i>Inmate Bathroom # BLI-10</i>	No Violations Noted
<i>Administrative Office</i>	No Violations Noted
<i>Biohazard Closet</i>	No Violations Noted
<i>Inmate Bathroom # BLI-28</i>	No Violations Noted
<i>Inmate Shower</i> 105 CMR 451.123	Maintenance: Ceiling vent dusty
<i>Ward A</i>	No Violations Noted
<i>Ward B</i> 105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty
<b><u>Dispatch/Receiving</u></b>	
<i>Property</i> 105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, ice build-up in freezer
<i>Sally Port</i> 105 CMR 451.350	Structural Maintenance: Door not rodent and weathertight
<i>Female Staff Bathroom # ALI-45</i>	No Violations Noted
<i>Male Staff Bathroom # ALI-44</i>	No Violations Noted
<i>Janitor's Closet # ALI-25</i>	No Violations Noted
<i>Intake Office</i>	No Violations Noted

*Medical Offices*

105 CMR 451.200\*

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, gaskets dirty in refrigerator in medical office # ALI-12

*Group Cells*

105 CMR 451.353\*

Interior Maintenance: Floor paint damaged in group cell # 1

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, toilet clogged in group cell # 1

*Male Cells*

105 CMR 451.353\*

Interior Maintenance: Ceiling dirty in cell # M5

105 CMR 451.353\*

Interior Maintenance: Floor paint damaged in cell # M1, M2, M3, and M4

*Female Cells*

No Violations Noted

*Inmate Bathroom # ALI - 21*

105 CMR 451.123

Maintenance: Ceiling vent dusty

**Sector D**

*Muster Room*

105 CMR 451.200\*

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, ceiling tiles water damaged

105 CMR 451.110(A)

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

*Chapel*

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles missing

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles water stained

*Classrooms*

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles water damaged in classroom A, B, and C

105 CMR 451.350

Structural Maintenance: Hole in ceiling surface in classroom D

*Classification*

No Violations Noted

*Inmate Bathroom # DI-13*

No Violations Noted

*Inmate Bathroom # DI-14*

105 CMR 451.123

Maintenance: Floor surface damaged around floor drain

*Staff Bathroom # DI-23*

No Violations Noted

*Staff Bathroom # DI-24*

No Violations Noted

*Janitor's Closet*

No Violations Noted

## Units

### **EC Unit**

#### *Main Area*

No Violations Noted

#### *Officer's Room*

No Violations Noted

#### *Storage – 2<sup>nd</sup> Floor*

No Violations Noted

#### *Janitor's Closet – 2<sup>nd</sup> Floor*

No Violations Noted

#### *Shower – 2<sup>nd</sup> Floor # F2-C10*

105 CMR 451.123\*

Maintenance: Floor dirty

105 CMR 451.123\*

Maintenance: Ceiling vent dusty

105 CMR 451.123

Maintenance: Soap scum on walls

#### *Janitor's Closet – 1<sup>st</sup> Floor*

No Violations Noted

#### *Storage – 1<sup>st</sup> Floor*

No Violations Noted

#### *Shower – 1<sup>st</sup> Floor # E1-C10*

105 CMR 451.123

Maintenance: Walls dirty

105 CMR 451.123

Maintenance: Floor dirty

105 CMR 451.123

Maintenance: Ceiling vent dusty

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower leaking

#### *Handicapped Shower*

105 CMR 451.123

Maintenance: Walls stained orange

105 CMR 451.123

Maintenance: Bench rusted

#### *Cells*

105 CMR 451.321\*

Cell Size: Inadequate floor space in all cells

### **ED Unit**

#### *Main Area*

No Violations Noted

#### *Computer Room*

No Violations Noted

#### *Showers – 2<sup>nd</sup> Floor*

No Violations Noted

#### *Janitor's Closet – 1<sup>st</sup> Floor*

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

#### *Cells*

105 CMR 451.321\*

Cell Size: Inadequate floor space in all cells

**EE Unit**

*Main Area*

No Violations Noted

*Cage Room*

No Violations Noted

*Showers – 2<sup>nd</sup> Floor*

No Violations Noted

*Janitor's Closet – 1<sup>st</sup> Floor*

No Violations Noted

*Showers – 1<sup>st</sup> Floor*

No Violations Noted

*Cells*

105 CMR 451.353

Interior Maintenance: Wall vent clogged in cell # G7 and G8

105 CMR 451.353

Interior Maintenance: Ceiling dirty in cell # M12

**EA/EB Units**

EA/EB Control

No Violations Noted

*Staff Bathroom*

No Violations Noted

*Caseworker's Office*

No Violations Noted

*Nurse's Office*

No Violations Noted

EA Unit – Female

*Main Area*

No Violations Noted

*Janitor's Closet – 1<sup>st</sup> Floor*

No Violations Noted

*Shower – 1<sup>st</sup> Floor*

No Violations Noted

*Shower – 2<sup>nd</sup> Floor*

No Violations Noted

*Cells*

105 CMR 451.321\*

Cell Size: Inadequate floor space in all cells

EB Unit – Female

*Main Area*

105 CMR 451.353\*

Interior Maintenance: Floor covering damaged



*Bathroom – 2<sup>nd</sup> Floor*  
105 CMR 451.123\*

Maintenance: Floor surface damaged

*Showers – 2<sup>nd</sup> Floor*  
105 CMR 451.130  
105 CMR 451.123

Plumbing: Plumbing not maintained in good repair, shower # E2-B12 leaking  
Maintenance: Interior door paint damaged in shower # E2-B11

*Bathroom – 1<sup>st</sup> Floor*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123

Maintenance: Wall paint damaged in stall # 1  
Maintenance: Floor covering damaged  
Maintenance: Wall paint damaged behind handwash sink on left  
Maintenance: Ceiling vent dusty

*Shower – 1<sup>st</sup> Floor*  
105 CMR 451.123\*

Maintenance: Door frame paint damaged

*Janitor's Closet – 1<sup>st</sup> Floor*

No Violations Noted

*Cells*  
105 CMR 451.321\*  
105 CMR 451.322\*

Cell Size: Inadequate floor space in all cells  
Cell Size: Inadequate floor space in dorm room attached to cell block

## **FA Unit**

*Control*

No Violations Noted

*Main Area*

No Violations Noted

*Classroom*

No Violations Noted

*Storage – 2<sup>nd</sup> Floor # FM-A23*

No Violations Noted

*Showers – 2<sup>nd</sup> Floor*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.123  
105 CMR 451.123

Maintenance: Floor surface damaged outside shower # FM-A18  
Maintenance: Ceiling vent dusty in shower # FM-A19 and FM-A21  
Maintenance: Walls dirty in shower # FM-A21  
Maintenance: Interior of door paint damaged in shower # FM-A19  
Maintenance: Shower encasing paint damaged in shower # FM-A21  
Maintenance: Ceiling paint cracking outside shower FM-A19

*Janitor's Closet # FG-A20*

No Violations Noted

*Janitor's Closet – 1<sup>st</sup> Floor # FG-A23*

105 CMR 451.353\*  
105 CMR 451.353

Interior Maintenance: Wall paint damaged  
Interior Maintenance: Wet mop stored in bucket

*Handicapped Shower*  
105 CMR 451.123

Maintenance: Ceiling vent dusty

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.123\*

Maintenance: Floor damaged outside shower # FG-A18 and FG-A21  
Maintenance: Ceiling vent dusty in shower # FG-A18 and FG-A21

*Cells*

105 CMR 451.321\*  
105 CMR 451.353\*

Cell Size: Inadequate floor space in all cells  
Interior Maintenance: Floor surface damaged in cell # G2, G3, G4, G6, G7, G12, G14, G15, G16, M1, M4, M8, M12, M13, M15, and handicapped cell  
Interior Maintenance: Ceiling paint damaged in cell # M5

105 CMR 451.353

**FB Unit**

*Control*

No Violations Noted

*Main Area*

105 CMR 451.353\*

Interior Maintenance: Floor covering damaged

*Medical Room*

No Violations Noted

*Janitor's Closet – 2<sup>nd</sup> Floor*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123  
105 CMR 451.123\*  
105 CMR 451.123

Maintenance: Walls stained orange in shower # FM-B19 and FM-B21  
Maintenance: Soap scum on walls in shower # FM-B19  
Maintenance: Soap scum on walls in shower # FM-B18

*Janitor's Closet – 1<sup>st</sup> Floor # FG-B20*

No Violations Noted

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123

Maintenance: Ceiling vent blocked in shower # FG-B18  
Maintenance: Soap scum on walls in shower # FG-B21 and FG-B22  
Maintenance: Ceiling paint damaged outside shower # FG-B21  
Maintenance: Floor surface damaged outside shower # FG-B21  
Maintenance: Door encasing paint damaged in shower # FG-B18

*Cells*

105 CMR 451.321\*  
105 CMR 451.353\*

Cell Size: Inadequate floor space in all cells  
Interior Maintenance: Floor surface damaged in cell # G1, G4, G5, G6, G7, G9, G10, G12, G13, G14, G15, G16, M1, M10, M13, M14, and M16

105 CMR 451.353  
105 CMR 451.353  
105 CMR 451.353  
105 CMR 451.353

Interior Maintenance: Floor surface damaged in cell # G8  
Interior Maintenance: Ceiling dirty in cell # M8 and M16  
Interior Maintenance: Ceiling dirty in cell # G15  
Interior Maintenance: Wall dirty in cell # M9

**Courtyard Units**

**HA Unit**

*Main Area*

105 CMR 451.141\*

Screens: Screen missing from window near entrance

*Staff Bathroom*

No Violations Noted

*Janitor's Closet – 2<sup>nd</sup> Floor*

No Violations Noted

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\*

Maintenance: Door rusted in shower # HM-A23

105 CMR 451.123

Maintenance: Door rusted in shower # HM-A26

105 CMR 451.123\*

Maintenance: Door frame rusted in shower # HM-A23

105 CMR 451.123

Maintenance: Door frame rusted in shower # HM-A26

*Janitor's Closet – 1<sup>st</sup> Floor*

No Violations Noted

*Storage – 1<sup>st</sup> Floor*

No Violations Noted

*Handicapped Shower*

105 CMR 451.123

Maintenance: Floor dirty

*Showers – 1<sup>st</sup> Floor*

105 CMR 451.123\*

Maintenance: Door rusted in shower # HG-A22 and HG-A23

*Cells*

105 CMR 451.321\*

Cell Size: Inadequate floor space in all cells

**HB Unit**

*Main Area*

105 CMR 451.141\*

Screens: Screen missing from window near entrance

*Staff Bathroom*

No Violations Noted

*Storage – 1<sup>st</sup> Floor # HG-B24*

105 CMR 451.353\*

Interior Maintenance: Floor paint damaged

*Storage – Near Shower # HG-B26*

105 CMR 451.353\*

Interior Maintenance: Floor paint damaged

*Janitor's Closet – 2<sup>nd</sup> Floor*

No Violations Noted

*Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\*

Maintenance: Mold on ceiling outside shower # HM-B26 and HM-B27

105 CMR 451.123\*

Maintenance: Floor dirty in shower # HM-B26

105 CMR 451.123\*

Maintenance: Walls dirty in shower # HM-B26 and HM-B27

105 CMR 451.123\*

Maintenance: Door frame rusted in shower # HM-B23, HM-B26, and HM-B27

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # HM-B26 and HM-B27

*Janitor's Closet – 1<sup>st</sup> Floor*

No Violations Noted

*Handicapped Shower*  
105 CMR 451.123\*

Maintenance: Wall stained

*Showers – 1<sup>st</sup> Floor*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*

Maintenance: Door rusted in shower # HG-B22 and HG-B23  
Maintenance: Door frame rusted in shower # HG-B22 and HG-B23  
Maintenance: Walls dirty in shower # HG-B22

*Cells*  
105 CMR 451.321\*  
105 CMR 451.353\*

Cell Size: Inadequate floor space in all cells  
Interior Maintenance: Exterior of door paint damaged in cell # G1, G5, G6, G7, G9, G19, M1, and M3

## **GA Unit**

*Main Area*  
105 CMR 451.141\*

Screens: Screen missing from window near entrance

*Staff Bathroom*

No Violations Noted

*Handicapped Shower*  
105 CMR 451.123

Maintenance: Ceiling vent dusty

*Storage # GG-A29*  
105 CMR 451.344\*

Illumination in Habitable Areas: Light not functioning properly, light out

*Storage # GG-A32*

No Violations Noted

*Janitor's Closet (near handicapped cell)*  
105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

*Bathroom – 2<sup>nd</sup> Floor*  
105 CMR 451.110(A)

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sinks

*Janitor's Closet – 2<sup>nd</sup> Floor*

No Violations Noted

*Showers – 2<sup>nd</sup> Floor*  
105 CMR 451.123\*  
105 CMR 451.123

Maintenance: Door frame paint damaged in shower # GM-A27 and GM-A28  
Maintenance: Door frame rusted in shower # GM-A28

*Bathroom – 1<sup>st</sup> Floor*  
105 CMR 451.123\*  
105 CMR 451.110(A)

Maintenance: Floor surface removal left unfinished  
Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sinks

*Showers – 1<sup>st</sup> Floor*  
105 CMR 451.130\*  
105 CMR 451.123\*

*Unable to Fully Inspect – Shower # GG-A28 In Use*  
Plumbing: Plumbing not maintained in good repair, shower # GG-A27 leaking  
Maintenance: Door rusted in shower # GG-A31

*Cells*  
105 CMR 451.321\*

Cell Size: Inadequate floor space in all cells

## **GB Unit**

### *Main Area*

No Violations Noted

### *Staff Bathroom*

No Violations Noted

### *Handicapped Shower*

No Violations Noted

### *Storage – 1<sup>st</sup> Floor*

No Violations Noted

### *Janitor's Closet – 1<sup>st</sup> Floor*

No Violations Noted

### *Bathroom – 2<sup>nd</sup> Floor*

No Violations Noted

### *Showers – 2<sup>nd</sup> Floor*

105 CMR 451.123\*

105 CMR 451.130

Maintenance: Floor dirty in shower # GM-B31

Plumbing: Plumbing not maintained in good repair, shower # GM-B27 and GM-B28 leaking

### *Bathroom – 1<sup>st</sup> Floor*

105 CMR 451.110(A)

105 CMR 451.130

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sinks

Plumbing: Plumbing not maintained in good repair, hot water out-of-order at sink # 2

### *Showers – 1<sup>st</sup> Floor*

No Violations Noted

### *Janitor's Closet – 2<sup>nd</sup> Floor*

No Violations Noted

### *Cells*

105 CMR 451.321\*

Cell Size: Inadequate floor space in all cells

## **GC Unit – Former Gym**

### *Main Area*

105 CMR 451.353\*

Interior Maintenance: Floor damaged in several areas

### *Bathroom*

105 CMR 451.110(A)

105 CMR 451.126

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sinks

Hot Water: Hot water temperature recorded at 96<sup>0</sup>F

### *Showers*

105 CMR 451.123\*

Maintenance: Wall tiles damaged in shower area

### *Library*

No Violations Noted

### *Janitor's Closet*

No Violations Noted

Storage Closet

No Violations Noted

Sleeping Area

105 CMR 451.322\*

Cell Size: Inadequate floor space in dorm area

**Observations and Recommendations**

1. The inmate population was 737 at the time of inspection.
2. During the inspection, the Department found many shower identification tags damaged or painted over and therefore, made them difficult or impossible to read. The Department recommended implementing a simple numbering system to all toilet and shower stalls to allow the Department and Correctional staff to better recognize where issues exist.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment Regulations or download a copy, please visit the Food Protection website at [www.mass.gov/dph/fpp](http://www.mass.gov/dph/fpp) and click on "Retail food". Then under DPH Regulations and FDA Code click "Merged Food Code" or "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments".

To review the Labeling regulations please visit the Food Protection website at [www.mass.gov/dph/fpp](http://www.mass.gov/dph/fpp) and click on "Food Protection Program regulations". Then under Food Processing click "105 CMR 500.000: Good Manufacturing Practices for Food".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Nicholas Gale  
Environmental Health Inspector, CSP, BEH

cc: Monica Bharel, MD, MPH, Commissioner, DPH  
Jana Ferguson, Director, BEH  
Steven Hughes, Director, CSP, BEH  
Marylou Sudders, Secretary, Executive Office of Health and Human Services (electronic copy)  
Carol A. Mici, Commissioner, DOC (electronic copy)  
Thomas Turco, Secretary, EOPSS (electronic copy)  
Nelson Alves, Director, Policy Development and Compliance Unit (electronic copy)  
Steven Sousa, Superintendent (electronic copy)  
Andrew Mitzan, Lieutenant, EHSO (electronic copy)  
Christopher Michaud, RS, Health Director, Dartmouth Board of Health (electronic copy)  
Clerk, Massachusetts House of Representatives  
Clerk, Massachusetts Senate