



The Commonwealth of Massachusetts

Executive Office of Health and Human Services

Department of Public Health

Bureau of Environmental Health

Community Sanitation Program

5 Randolph Street

Canton, MA 02021

Telephone: (781) 828-8046

Facsimile: (781) 828-7703

mikel.beacham@state.ma.us

DEVAL L. PATRICK
GOVERNOR

TIMOTHY P. MURRAY
LIEUTENANT GOVERNOR

JUDYANN BIGBY, MD
SECRETARY

JOHN AUERBACH
COMMISSIONER

March 25, 2011

Michael Corsini, Superintendent
Massachusetts Treatment Center
30 Administration Road
Bridgewater MA, 02324

Re: Facility Inspection

Dear Superintendent Corsini:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, and Department of Public Health Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Massachusetts Treatment Center on March 23, 2011 accompanied by Ken Costa, Environmental Health and Safety Officer. Violations noted are listed below (* *indicates conditions documented on previous inspection reports*).

Front Lobby

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Administration Area

Roll Call Room

105 CMR 451.350

Structural Maintenance: Rug dirty

Male Locker Room

105 CMR 451.353

Interior Maintenance: Strong sewer odor

Female Locker Room

105 CMR 451.353

Interior Maintenance: Strong sewer odor

Visiting Room

105 CMR 451.350*
105 CMR 451.350
105 CMR 451.350*
105 CMR 451.353
105 CMR 451.353

Structural Maintenance: Ceiling tiles damaged
Structural Maintenance: Ceiling tiles missing
Structural Maintenance: Rug damaged
Interior Maintenance: Rug dirty
Interior Maintenance: Vent dirty

Fire Safety Room

No Violations Noted

Central Laundry

105 CMR 451.211
105 CMR 451.340

Laundry: Dryer # 1 not working
Illumination: Insufficient lighting in laundry area

Archives

105 CMR 451.353

Interior Maintenance: Debris on floor

A1 Unit

Officers Trap

105 CMR 451.350
105 CMR 451.123
105 CMR 451.130

Structural Maintenance: Ceiling tiles missing
Maintenance: Counter near sink damaged
Plumbing: Plumbing not maintained in good repair, sink drains slowly

Main Area

105 CMR 451.350
105 CMR 451.350
105 CMR 451.350
105 CMR 451.350
105 CMR 451.350*

Structural Maintenance: Baseboard damaged between lower showers
Structural Maintenance: Rug damaged near refrigerator
Structural Maintenance: Dryer not working
Structural Maintenance: Dryer vent has hole
Structural Maintenance: Stair risers damaged

Cells

No Violations Noted

Showers

105 CMR 451.123

Maintenance: Shower AM-13 dirty

A2 Unit

Main Area

105 CMR 451.353
105 CMR 451.350*
105 CMR 451.350*
105 CMR 451.350*
105 CMR 451.350
105 CMR 451.350

Interior Maintenance: Rug dirty
Structural Maintenance: Rug damaged
Structural Maintenance: Treads on ramp damaged
Structural Maintenance: Stair risers damaged
Structural Maintenance: Floor in front of cell # 25 & 28 damaged
Structural Maintenance: Ceiling leak by cell # 18

Cells

105 CMR 451.350*
105 CMR 451.350

Structural Maintenance: Floor tiles damaged in many cells
Structural Maintenance: Window cracked in cell # 27

Showers

No Violations Noted

Health Service Unit

Main Area

105 CMR 451.350* Structural Maintenance: Ceiling tiles missing

Break Room

105 CMR 451.350 Structural Maintenance: Counter damaged

NP Office

No Violations Noted

Medical Records Room

105 CMR 451.350* Structural Maintenance: Ceiling tiles missing

105 CMR 451.350* Structural Maintenance: Ceiling tiles damaged

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Trauma Room

No Violations Noted

Therapy Room

105 CMR 451.353 Interior Maintenance: Rug dirty

B1 Unit

Officers Trap

No Violations Noted

Main Area

105 CMR 451.350 Structural Maintenance: Dryer not working

105 CMR 451.350* Structural Maintenance: Stair risers damaged

Cells

105 CMR 451.350* Structural Maintenance: Floor tiles damaged in many cells

Showers

105 CMR 451.123 Maintenance: Showers dirty

B2 Unit

Officers Trap

No Violations Noted

Main Area

105 CMR 451.350* Structural Maintenance: Stair risers damaged

Cells

105 CMR 451.350* Structural Maintenance: Floor tiles damaged in some cells

105 CMR 451.350 Structural Maintenance: Weather stripping damaged around window in cell # 28
105 CMR 451.350 Structural Maintenance: Ceiling leak by cell # 29

Showers
105 CMR 451.123 Maintenance: Showers dirty

Maintenance Corridor

Mechanical Room
105 CMR 451.353 Interior Maintenance: Floors dirty

Staff Bathroom
105 CMR 451.123 Maintenance: Vent dirty

Barber Shop
No Violations Noted

Food Service

Kitchen
FC 6-501.11 Repairing: Floor tiles damaged
FC 6-501.11 Repairing: Floor tiles missing
FC 6-501.11 Repairing: Ceiling light fixture is rusty
FC 6-501.11 Repairing: Ceiling vent is rusty
FC 6-501.12(A) Maintenance and Operation: Cleaning: Grease trap clogged
FC 4-501.11(A) Equipment Maintenance: Steam table not working
FC 4-903.11(B)(2) Equipment Storage: Pots and pans not inverted

Dining Area
FC 6-501.11* Repairing: Floor tiles damaged

Dry Storage
No Violations Noted

Toxic/Caustic
No Violations Noted

Inmate Bathroom
No Violations Noted

Swill Room
No Violations Noted

Staff Food Service

Dining Area
FC 6-501.11* Repairing: Severe ceiling damaged due to leak

Kitchen
No Violations Noted

Storage Area
No Violations Noted

Gym

Main Area

105 CMR 451.350*
105 CMR 451.350*

Structural Maintenance: Ceiling tiles are missing/damaged
Structural Maintenance: Ceiling leaking

Male Staff Bathroom

105 CMR 451.123
105 CMR 451.123

Maintenance: Hot water not working
Maintenance: Toilet leaks

Female Staff Bathroom

No Violations Noted

C1 Unit

Officers Trap

105 CMR 451.350

Structural Maintenance: Ceiling tiles damaged

Main Area

105 CMR 451.350*

Structural Maintenance: Stair risers damaged

Cells

105 CMR 451.350*

Structural Maintenance: Floor tiles damaged in some cells

Showers

105 CMR 451.123

Maintenance: Showers dirty

C2 Unit

Officers Trap

105 CMR 451.350

Structural Maintenance: Ceiling tiles damaged

Main Area

105 CMR 451.350*
105 CMR 451.350

Structural Maintenance: Stair risers damaged
Structural Maintenance: Floor tiles damaged in hallway

Cells

105 CMR 451.350
105 CMR 451.350
105 CMR 451.350

Structural Maintenance: Weather stripping around cell # 29 & 30 damaged
Structural Maintenance: Floor damaged in front of cell # 9
Structural Maintenance: Door window cracked on cell # 11

Showers

105 CMR 451.123
105 CMR 451.123
105 CMR 451.123

Maintenance: Shower doors rusty
Maintenance: Floor damaged in front of lower left shower
Maintenance: Showers dirty

D1 Unit

Officers Trap

105 CMR 451.350

Structural Maintenance: Ceiling tiles damaged

FC 4-602.12(B)

FC 4-501.11(A)

Cleaning of Equipment and Utensils; Frequency: Refrigerator needs replacing
Equipment Maintenance: Microwave not working

Main Area

105 CMR 451.350* Structural Maintenance: Stair risers damaged
105 CMR 451.353 Interior Maintenance: Vent dirty in cooking area
105 CMR 451.350 Structural Maintenance: Cove molding in hallway loose

Cells

105 CMR 451.350 Structural Maintenance: Floor tiles damaged in some cells

Showers

105 CMR 451.123 Maintenance: Drainage problems with lower showers
105 CMR 451.123 Maintenance: Showers dirty

D2 Unit

Officers Trap

No Violations Noted

Main Area

105 CMR 451.350* Structural Maintenance: Therapy room ceiling stained

Cells

No Violations Noted

Showers

105 CMR 451.123 Maintenance: Showers dirty

MODULAR UNITS

South 1

Medication Room

No Violations Noted

Laundry

No Violations Noted

Conference Room

105 CMR 451.350 Structural Maintenance: Table tops damaged

Backroom

No Violations Noted

Staff Bathroom

No Violations Noted

Dorms

105 CMR 451.350 Structural Maintenance: Wall damaged in back corners of many dorms

East Bathroom

105 CMR 451.123 Maintenance: Ceiling leak
105 CMR 451.123 Maintenance: Wall damaged in showers

West Bathroom

105 CMR 451.123 Maintenance: Curtain rod loose

105 CMR 451.123 Maintenance: Showers damaged

South 2

Laundry

No Violations Noted

Conference Room

105 CMR 451.350

Structural Maintenance: Table tops damaged

105 CMR 451.350

Structural Maintenance: Broken chairs at tables

105 CMR 451.350

Structural Maintenance: Ceiling leak in front dayroom, near light fixture

Backroom

No Violations Noted

Staff Bathroom

No Violations Noted

Dorms

105 CMR 451.350

Structural Maintenance: Cove molding damaged in many dorms

105 CMR 451.350

Structural Maintenance: Wall damaged in back corners of many dorms

West Bathroom

(Not in use, under construction)

East Bathroom

105 CMR 451.123*

Maintenance: Vent dirty

105 CMR 451.123

Maintenance: Wall damaged

North 1

Laundry

No Violations Noted

Conference Room

No Violations Noted

Backroom

No Violations Noted

Staff Bathroom

No Violations Noted

Dorms

105 CMR 451.350

Structural Maintenance: Door handle not working properly on dorm # 160

West Bathroom

105 CMR 451.123

Maintenance: Sink needs repair

105 CMR 451.123

Maintenance: Wall damaged in showers

East Bathroom

105 CMR 451.123

Maintenance: Wall damaged in showers

105 CMR 451.123

Maintenance: Marlite in shower area coming loose

North 2

Laundry

No Violations Noted

<i>Conference Room</i>	No Violations Noted
<i>Backroom</i>	No Violations Noted
<i>Staff Bathroom</i>	No Violations Noted
<i>Dorms</i> 105 CMR 451.350	Structural Maintenance: Desk seat broken in dorm # 255
<i>West Bathroom</i>	No Violations Noted
<i>East Bathroom</i>	No Violations Noted

ADMINISTRATION AREA

<i>Main Area</i>	No Violations Noted
<i>Male Bathroom</i>	No Violations Noted
<i>Female Bathroom</i>	No Violations Noted

Minimum Privilege Unit

<i>Cells</i> 105 CMR 451.350 105 CMR 451.350	Structural Maintenance: Window does not work properly in cell # 7 Structural Maintenance: Window broken in cell # 4
<i>Officers Trap</i> 105 CMR 451.350	Structural Maintenance: Ceiling tiles damaged
<i>Hallway</i>	No Violations Noted

Learning Area

<i>Hallway</i> 105 CMR 451.350* 105 CMR 451.350	Structural Maintenance: Ceiling tiles missing/damaged Structural Maintenance: Ceiling leaks
<i>Library</i> 105 CMR 451.350	Structural Maintenance: Ceiling damaged
<i>Staff Bathroom</i>	No Violations Noted
<i>Inmate Bathroom</i>	No Violations Noted
<i>Industry Operations</i>	

105 CMR 451.350 Structural Maintenance: Dark room ceiling damaged
Wood Shop

No Violations Noted

Print Shop

No Violations Noted

Art Room

No Violations Noted

Community Transition House

Exterior
105 CMR 451.141 Screens: Screens damaged on porch

Officers Area
105 CMR 451.350 Structural Maintenance: Rug damaged

Common Room
105 CMR 451.350 Structural Maintenance: Window cracked

First Floor Staff Bathroom

No Violations Noted

Second Floor Inmate Bathroom
105 CMR 451.123 Maintenance: Toilet leaking

Second Floor Hallway

No Violations Noted

Bedrooms
105 CMR 451.350 Structural Maintenance: Ceiling leaks in room # 6

This facility does not comply with the Department’s Regulations cited above. In accordance with 105 CMR 451.404, please indicate next to each entry on the inspection report a plan of correction. Said plan of correction must be submitted within ten working days of receiving this report and should detail the specific steps that will be taken and the date of expected compliance. The plan of correction should be submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Community Sanitation Regulations" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X – Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,

Mikel Beacham
Environmental Health Inspector, CSP, BEH

cc: Suzanne K. Condon, Associate Commissioner, Director, BEH
Steven Hughes, Director, CSP, BEH
JudyAnn Bigby, MD, Secretary, Executive Office of Health and Human Services
Luis S. Spencer, Acting Commissioner, DOC
Ken Costa, Environmental Health and Safety Officer
Bridgewater Board of Health
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Mary Elizabeth Heffernan, EOPS