



The Commonwealth of Massachusetts  
Executive Office of Health and Human Services  
Department of Public Health  
Bureau of Environmental Health  
Community Sanitation Program  
5 Randolph Street, Canton, MA 02021  
Phone: 781-828-7700 Fax: 781-828-7703

CHARLES D. BAKER  
Governor

KARYNE E. POLITO  
Lieutenant Governor

MARYLOU SUDDERS  
Secretary

MONICA BHAREL, MD, MPH  
Commissioner

Tel: 617-624-6000  
[www.mass.gov/dph](http://www.mass.gov/dph)

April 19, 2017

Steven J. O'Brien, Superintendent  
Massachusetts Treatment Center  
30 Administration Road  
Bridgewater, MA 02324

Re: Facility Inspection – Massachusetts Treatment Center, Bridgewater

Dear Superintendent O'Brien:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Massachusetts Treatment Center on March 22 and 23, 2017 accompanied by Kenneth Finn, Environmental Health and Safety/Fire Safety Officer. Violations noted during the inspection are listed below including 96 repeat violations:

**HEALTH AND SAFETY VIOLATIONS**

(\* indicates conditions documented on previous inspection reports)

**Front Lobby**

*Waiting Area*

105 CMR 451.350\*                      Structural Maintenance: Ceiling water damaged

*Mail Room*

No Violations Noted

*Male Bathroom*

105 CMR 451.123\*                      Maintenance: Ceiling vent dusty

*Female Bathroom*

105 CMR 451.123\*                      Maintenance: Ceiling vent dusty

**Administration Area**

*Utility Closet # A2-52*

No Violations Noted

*Utility Closet # A3-29*

No Violations Noted

*Main Area*

105 CMR 451.353\*  
105 CMR 451.353\*  
105 CMR 451.353\*

Interior Maintenance: Ceiling tiles damaged  
Interior Maintenance: Ceiling tiles water damaged  
Interior Maintenance: Ceiling tiles missing

*Handicapped Bathroom*

105 CMR 451.123

Maintenance: Ceiling tiles water damaged

*Male Bathroom*

No Violations Noted

*Female Bathroom*

No Violations Noted

**Control Area**

*Roll Call Room*

105 CMR 451.200

Food Storage, Preparation and Service: Food service not in compliance with  
105 CMR 590.000, food vending machine tray dirty

*Male Locker Room*

105 CMR 451.123

Maintenance: Caulking damaged around sinks

*Female Locker Room*

105 CMR 451.353  
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty  
Interior Maintenance: Ceiling tile missing

*Control Room # A2-40*

105 CMR 451.353  
105 CMR 451.353

Interior Maintenance: Ceiling tiles damaged  
Interior Maintenance: Ceiling tiles missing

*Control Room Bathroom*

No Violations Noted

*Central Tower*

105 CMR 451.353\*  
105 CMR 451.353\*  
105 CMR 451.350\*  
105 CMR 451.350\*

Interior Maintenance: Window pane cracked  
Interior Maintenance: Window latch broken  
Structural Maintenance: Four windows broken  
Structural Maintenance: Window not weathertight, plastic covering window

*Inmate Bathroom # A2-46*

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles damaged outside bathroom

*Strip Room # A2-45*

105 CMR 451.350\*

Structural Maintenance: Ceiling damaged

**Visiting Room**

No Violations Noted

*Children's Day Room*

No Violations Noted

*Conference Rooms*

105 CMR 451.353

Interior Maintenance: Ceiling tiles damaged

*Toxic/Caustic Closet*

No Violations Noted

**Fire Safety Room**

No Violations Noted

*Central Laundry*

No Violations Noted

*Archives*

No Violations Noted

**Therapy Room # A1-19**

No Violations Noted

*Utility Closet # A1-11*

No Violations Noted

**A Units**

**A Control**

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles water damaged

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles missing

105 CMR 451.130\*

Plumbing: Plumbing not maintained in good repair, sink faucet loose

*Control Bathroom*

No Violations Noted

**A1 Unit**

*Common Area*

105 CMR 451.353\*

Interior Maintenance: Ceiling surface damaged

105 CMR 451.350\*

Structural Maintenance: Window cracked near stairs

*Slop Sink # A1-1*

105 CMR 451.353\*

Interior Maintenance: Ceiling damaged

*Utility Closet # AG-2*

No Violations Noted

*Utility Closet # AM-2*

No Violations Noted

*2<sup>nd</sup> Floor Showers*

Unable to Inspect Shower # AM-13 – In Use

No Violations Noted

*1<sup>st</sup> Floor Showers*

105 CMR 451.123

Maintenance: Soap scum on curtain in shower # AG-13

*Cells*

105 CMR 451.353

Interior Maintenance: Floor surface damaged in cell # 11 and 12

## **A2 Unit**

### *Common Area*

105 CMR 451.353\*

Interior Maintenance: Floor paneling missing outside 1<sup>st</sup> floor showers

105 CMR 451.353

Interior Maintenance: Ceiling surface damaged in main area

### *Classroom # A1-8*

No Violations Noted

### *Utility Closet*

No Violations Noted

### *2<sup>nd</sup> Floor Showers*

105 CMR 451.123

Maintenance: Floor paint peeling in shower # AM-35

### *1<sup>st</sup> Floor Showers*

105 CMR 451.123\*

Maintenance: Floor cracked in shower # AG-35

105 CMR 451.123

Maintenance: Floor paint peeling in shower # AG-35

105 CMR 451.123

Maintenance: Door frame rusted in shower # AG-36

### *Cells*

105 CMR 451.350\*

Structural Maintenance: Ceiling damaged in cell # 13

105 CMR 451.350

Structural Maintenance: Ceiling damaged in cell # 11

105 CMR 451.353\*

Interior Maintenance: Floor tiles missing in cell # 4 and 6

105 CMR 451.353

Interior Maintenance: Baseboard damaged outside cell # 28

## **IPS**

No Violations Noted

### *IPS Interview*

Unable to Inspect – In Use

### *Utility Closet*

No Violations Noted

### *Bathroom # A1-40*

No Violations Noted

### *Booking*

No Violations Noted

## **Health Service Unit**

### *Biohazard Room # A1-23*

No Violations Noted

### *Male Bathroom # A1-47*

No Violations Noted

### *Medication Room # A1-35*

No Violations Noted

### *Administrative Assistant Room # A1-36*

No Violations Noted

*Dentist's Office # A1-37*

Unable to Inspect – In Use

*X-Ray Room # A1-46*

No Violations Noted

*Main Area*

No Violations Noted

*Break Room # A1-65*

No Violations Noted

*Nurse Practitioner's Office # A1-58*

No Violations Noted

*Medical Records Room # A1-60*

No Violations Noted

*Patient Bathroom # A1-69*

No Violations Noted

*Exam Room # A1-58*

105 CMR 451.126

Hot Water: Hot water temperature recorded at 100°F

*Utility Closet # A1-68*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Exam Room # A1-49*

No Violations Noted

*Officer's Area*

No Violations Noted

*Female Bathroom # A1-48*

No Violations Noted

**Chemical Closet # B1-13**

No Violations Noted

**Therapy Suite**

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles damaged

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles missing

*Offices*

No Violations Noted

*Utility Closet*

No Violations Noted

*Male Bathroom*

No Violations Noted

*Female Bathroom*

No Violations Noted

**B Units**

105 CMR 451.353\* Interior Maintenance: Ceiling tiles damaged outside B Units

**B Control**

No Violations Noted

*Control Bathroom*

105 CMR 451.123\* Maintenance: Ceiling vent dusty

**B1 Unit***Common Area*

105 CMR 451.350\* Structural Maintenance: Window cracked near washer and dryer units

*Utility Closet # B1-1*

105 CMR 451.353 Interior Maintenance: Pipe insulation damaged

*Therapy Room # B1-2 & B1-3*

105 CMR 451.350\* Structural Maintenance: Ceiling damaged in room # B1-3

*2<sup>nd</sup> Floor Showers*

No Violations Noted

*1<sup>st</sup> Floor Showers*

105 CMR 451.123 Maintenance: Floor paint damaged in shower # BG-13

*Cells*

No Violations Noted

**B2 Unit***Common Area*

No Violations Noted

*Utility Closet # B1-11*

No Violations Noted

*Utility Closet # BG-50*

No Violations Noted

*2<sup>nd</sup> Floor Showers*

Unable to Inspect – In Use

*1<sup>st</sup> Floor Showers*

No Violations Noted

*Cells*

105 CMR 451.350\* Structural Maintenance: Ceiling damaged and covered with plastic in cell # 24, 25, and 26

105 CMR 451.353 Interior Maintenance: Ceiling surface damaged in cell # 27 and 29

105 CMR 451.353 Interior Maintenance: Floor surface damaged in cell # 9

**Maintenance Corridor***Maintenance Workshop # B1-62*

No Violations Noted

*Bulk Storage # EI-59*

No Violations Noted

*Staff Bathroom # B1-76*

105 CMR 451.123

Maintenance: Caulking damaged around sinks

*Store Room # B1-75*

105 CMR 451.350\*

Structural Maintenance: Ceiling damaged

*Flammable Storage # B1-63*

Unable to Inspect – Locked

*Tool Crib Room # B1-74*

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of refrigerator damaged

105 CMR 451.200

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave dirty

*Canteen Room*

No Violations Noted

**Barber Shop**

No Violations Noted

**Food Service**

*South-Side Dining Area*

FC 6-501.11\*

FC 6-501.11\*

Maintenance and Operation; Repairing: Facility not in good repair, ceiling tiles missing  
Maintenance and Operation; Repairing: Facility not in good repair, floor surface damaged on far right of dining area

*North-Side Dining Area*

FC 6-501.11\*

Maintenance and Operation; Repairing: Facility not in good repair, ceiling tiles missing

**Kitchen**

*3-Bay Sink Area*

FC 5-205.15(B)

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, faucet leaking

*Rinse/Dishwashing Area*

FC 6-501.12(A)\*

Maintenance and Operation; Cleaning: Facility not cleaned properly, wall dirty under table, possible mold and/or mildew

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, warewash machine must be filled manually

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, soap dispensing system in warewash machine not functioning properly

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, warewash machine not meeting appropriate sanitizing temperature

*Serving Area*

No Violations Noted

*Cooler # 6/Freezer Unit*

FC 3-305.11(A)(2)\*

Preventing Contamination from Premises: Food exposed to dust, cooler fans dusty

FC 3-302.11(A)(4)	Preventing Food and Ingredient Contamination: Preventing cross contamination, cookies on trays not appropriately covered
FC 3-302.11(A)(4)	Preventing Food and Ingredient Contamination: Preventing cross contamination, cereal not appropriately covered
<i>Dry Storage</i>	
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, ceiling damaged
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, floor surface damaged
FC 4-903.11(A)(2)	Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered
<i>Recycling Area</i>	
	No Violations Noted
<i>Office</i>	
	No Violations Noted
<i>Hoods</i>	
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, floor tiles damaged and missing near kettles
<i>Utility/Toxic Closet</i>	
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, ceiling paint peeling
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, ceiling water damaged
FC 6-501.16	Maintenance and Operation; Cleaning: Wet mop stored in bucket
FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, mobile fan dusty
<i>Inmate Bathroom</i>	
	No Violations Noted
<i>Swill Room</i>	
	No Violations Noted
<b><u>Staff Food Service</u></b>	
<i>Dining Area</i>	
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, ceiling tiles missing
<b>Kitchen</b>	
<i>Prep Area</i>	
FC 3-304.12(A)	Preventing Contamination from Utensils: Service utensils handle stored below the food and container line, scoop stored in food on prep table
<i>Storage Area</i>	
FC 3-302.12	Preventing Food and Ingredient Contamination: Unlabeled food containers, prepared food not dated in refrigerator # 1
<b><u>Gym</u></b>	
<i>Main Area</i>	
105 CMR 451.353*	Interior Maintenance: Floor surface damaged throughout
105 CMR 451.353*	Interior Maintenance: Ceiling tiles missing in back corner



*Male Staff Bathroom*

105 CMR 451.123

105 CMR 451.123

Maintenance: Shower floor damaged

Maintenance: Caulking damaged around sinks

*Female Staff Bathroom*

No Violations Noted

*Inmate Bathroom*

No Violations Noted

*Utility Room*

No Violations Noted

*Office*

No Violations Noted

**C Units**

**C Control**

105 CMR 451.353\*

105 CMR 451.200

Interior Maintenance: Ceiling tiles missing

Food Storage, Preparation and Service: Food preparation not in compliance with  
105 CMR 590.000, toaster oven dirty

*Control Bathroom*

No Violations Noted

**C1 Unit**

*Common Area*

105 CMR 451.353

105 CMR 451.350

Interior Maintenance: Ceiling surface damaged

Structural Maintenance: Ceiling leaking

*Utility Closet # CG-2*

No Violations Noted

*2<sup>nd</sup> Floor Showers*

105 CMR 451.123\*

Maintenance: Floor paint damaged in shower # CM-13

*1<sup>st</sup> Floor Showers*

No Violations Noted

*Cells*

No Violations Noted

**C2 Unit**

*Common Area*

105 CMR 451.353

105 CMR 451.350

Interior Maintenance: Ceiling surface damaged

Structural Maintenance: Ceiling leaking

*Utility Closet*

105 CMR 451.350\*

Structural Maintenance: Ceiling water damaged

*2<sup>nd</sup> Floor Showers*

105 CMR 451.123\*

Maintenance: Floor paint damaged in shower # CM-36

*1<sup>st</sup> Floor Showers*

105 CMR 451.123\*

Maintenance: Floor paint damaged in shower # CG-35 and CG-36

*Cells*

105 CMR 451.353\*

105 CMR 451.353

Interior Maintenance: Door window broken in cell # 10 and 11

Interior Maintenance: Floor surface damaged outside cell # 9

**D Units**

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles missing outside of D Units

*Utility Closet # D1-12*

No Violations Noted

**D Control**

No Violations Noted

*Control Bathroom*

No Violations Noted

**D1 Unit**

*Common Area*

105 CMR 451.350\*

105 CMR 451.350\*

105 CMR 451.350

Structural Maintenance: Ceiling damaged at entrance

Structural Maintenance: Window cracked near cell # 1

Structural Maintenance: Ceiling leaking

*Utility Closet*

No Violations Noted

*Therapy Room # D1-3*

105 CMR 451.353\*

Interior Maintenance: Ceiling damaged

*2<sup>nd</sup> Floor Showers*

No Violations Noted

*1<sup>st</sup> Floor Showers*

105 CMR 451.123\*

Maintenance: Floor paint damaged in shower # DG-12 and DG-13

*Cells*

No Violations Noted

**D2 Unit**

*Common Area*

105 CMR 451.353\*

Interior Maintenance: Floor tiles missing outside of 1<sup>st</sup> floor showers

*Utility Closet # D1-10*

105 CMR 451.353

Interior Maintenance: Ceiling surface damaged

*2<sup>nd</sup> Floor Showers*

105 CMR 451.123

105 CMR 451.123

105 CMR 451.123

Unable to Inspect Shower # DM-36 Out-of-Order

Maintenance: Floor paint peeling in shower # DM-35

Maintenance: Door frame rusted in shower # DM-35

Maintenance: Mold on ceiling in shower # DM-35

*1<sup>st</sup> Floor Showers*

105 CMR 451.123\*

Maintenance: Floor paint damaged in shower # DG-35 and DG-36

105 CMR 451.123\*

Maintenance: Door frame rusted in shower DG-36

*Cells*

No Violations Noted

**Chapel**

105 CMR 451.353\*

Interior Maintenance: Ceiling tile missing

**Minimum Privilege Unit**

**Control**

105 CMR 451.353

Interior Maintenance: Ceiling tile damaged

*Control Bathroom*

No Violations Noted

**Main Area**

*Utility Closet*

No Violations Noted

*Closet # A2-25*

No Violations Noted

*Showers*

105 CMR 451.123\*

Maintenance: Floor paint damaged in shower # 1

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 1 and 2

*Cells*

No Violations Noted

**Library # 132-3**

No Violations Noted

*Library Bathroom # B2-12*

No Violations Noted

*Library Storage # B2-13*

No Violations Noted

**Learning Center**

*Hallway*

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles missing

*Male Staff Bathroom*

No Violations Noted

*Female Staff Bathroom*

105 CMR 451.123\*

Maintenance: Ceiling water damaged

*Utility Closet # B2-28*

No Violations Noted

*Toxic/Caustic Closet # B2-29*

No Violations Noted

*Bathroom # B2-34*

No Violations Noted

*Inmate Bathroom # B2-16*

No Violations Noted

**Industry Operations**

*Print Shop*

No Violations Noted

*Art Room*

No Violations Noted

**Wood Shop**

No Violations Noted

*Hallway*

105 CMR 451.350\*

Structural Maintenance: Ceiling leaking

*Assembly Room*

No Violations Noted

*Utility Closet # C2-10*

No Violations Noted

*Inmate Bathroom # C2-11*

No Violations Noted

*Staff Office # C2-16*

No Violations Noted

*Staff Office Bathroom*

No Violations Noted

**MODULAR UNITS**

**South 1**

**Staff Area**

*Staff Bathroom*

105 CMR 451.123

Maintenance: Light out

*Offices*

No Violations Noted

*Staff Break Room*

No Violations Noted

## **Common Area**

### *Day Room*

No Violations Noted

### *Medication Room*

No Violations Noted

### *Exam Room*

No Violations Noted

### *Back Rooms*

No Violations Noted

## **Dorm Hallway**

### *Dorms*

No Violations Noted

### *Utility Closet*

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, slop sink leaking

### *East Bathroom*

105 CMR 451.123\*

Maintenance: Soap scum on shower curtains in shower # 1-5

105 CMR 451.123

Maintenance: Mold on ceiling

105 CMR 451.123

Maintenance: Wall vents dusty

### *West Bathroom*

105 CMR 451.123\*

Maintenance: Soap scum on shower curtains in shower # 1-5

105 CMR 451.123\*

Maintenance: Wall vents dusty

## **South 2**

## **Staff Area**

### *Staff Bathroom*

105 CMR 451.123

Maintenance: Light out

### *Staff Break Room*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

## **Common Area**

### *Day Room*

No Violations Noted

### *Old Laundry Area*

No Violations Noted

### *Back Rooms*

No Violations Noted

## **Dorm Hallway**

105 CMR 451.353

Interior Maintenance: Floor tiles damaged

*Dorms*

No Violations Noted

*Utility Closet*

No Violations Noted

*East Bathroom*

105 CMR 451.123\*

Maintenance: Soap scum on shower curtains in shower # 1-5

105 CMR 451.123\*

Maintenance: Ceiling vents dusty

105 CMR 451.123

Maintenance: Mold on walls outside showers

*West Bathroom*

105 CMR 451.123

Maintenance: Urinal out-of-order

105 CMR 451.123

Maintenance: Wall vents dusty outside showers

**North 1**

**Staff Area**

*Staff Bathroom*

No Violations Noted

*Staff Break Room*

No Violations Noted

*Conference Room*

No Violations Noted

**Common Area**

*Day Room*

No Violations Noted

*Old Laundry Area*

No Violations Noted

*Back Rooms*

No Violations Noted

**Dorm Hallway**

*Dorms*

No Violations Noted

*Utility Closet*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

*East Bathroom*

105 CMR 451.123

Maintenance: Counter top damaged

105 CMR 451.123

Maintenance: Wall vent dusty outside showers

105 CMR 451.123

Maintenance: Shower surface damaged in shower # 1-5

*West Bathroom*

105 CMR 451.123\*

Maintenance: Wall vent rusted in shower area

105 CMR 451.123\*

Maintenance: Bottom of toilet partitions rusted

105 CMR 451.123

Maintenance: Wall vent dusty outside showers

## **North 2**

### **Staff Area**

#### *Staff Bathroom*

Unable to Inspect – In Use

#### *Staff Break Room*

No Violations Noted

#### *Conference Room*

No Violations Noted

### **Common Area**

#### *Day Room*

No Violations Noted

#### *Old Laundry Area*

No Violations Noted

#### *Back Room*

No Violations Noted

### **Dorm Hallway**

#### *Dorms*

No Violations Noted

#### *Utility Closet*

105 CMR 451.353\*

Interior Maintenance: Wall damaged

105 CMR 451.353\*

Interior Maintenance: Floor damaged

105 CMR 451.353\*

Interior Maintenance: Drain cover not secure in slop sink

#### *East Bathroom*

105 CMR 451.123

Maintenance: Wall vent dusty outside showers

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 1-5

#### *West Bathroom*

105 CMR 451.123\*

Maintenance: Unfinished wood bench in handicapped shower

105 CMR 451.123\*

Maintenance: Soap scum on shower curtains in shower # 2, 3, 4, and 5

105 CMR 451.123

Maintenance: Soap scum on shower curtains in shower # 1

105 CMR 451.123

Maintenance: Wall vent dusty outside showers

## **VEHICLE TRAP TOWER**

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, utensils left uncovered

## **REAR TOWER**

105 CMR 451.350\*

Structural Maintenance: Two windows cracked

## **COMMUNITY TRANSITION HOUSE**

### **1<sup>st</sup> Floor**

#### *Kitchen*

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, upper cabinet damaged

#### *Living Area*

No Violations Noted

#### *Bathroom/Laundry*

No Violations Noted

### **2<sup>nd</sup> Floor**

#### *Bathroom*

No Violations Noted

#### *Bedrooms*

No Violations Noted

### **Basement**

No Violations Noted

### **Observations and Recommendations**

1. The inmate population was 512 at the time of inspection.
2. At the time of inspection, the warewash machine was not reaching the appropriate temperature and was not functioning properly. The Department recommended the kitchen use paper plates and utensils until the temperature was brought into compliance.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at [www.mass.gov/dph/fpp](http://www.mass.gov/dph/fpp) and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X – Minimum Sanitation Standards for Food Establishments" and "[1999 Food Code](#)".

To review the Labeling regulations please visit the Food Protection website at [www.mass.gov/dph/fpp](http://www.mass.gov/dph/fpp) and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."



This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Nicholas Gale  
Environmental Health Inspector, CSP, BEH

cc: Jan Sullivan, Acting Director, BEH  
Steven Hughes, Director, CSP, BEH  
Timothy Miley, Director of Government Affairs  
Marylou Sudders, Secretary, Executive Office of Health and Human Services  
Thomas Turco, Commissioner, DOC  
Kenneth Finn, EHSO/FSO  
Eric J. Badger, CHO, Health Agent, Bridgewater Health Department  
Clerk, Massachusetts House of Representatives  
Clerk, Massachusetts Senate  
Daniel Bennett, Secretary, EOPSS  
Jennifer Gaffney, Director, Policy Development and Compliance Unit