



DEVAL L. PATRICK
GOVERNOR

JOHN W. POLANOWICZ
SECRETARY

CHERYL BARTLETT, RN
COMMISSIONER

The Commonwealth of Massachusetts

Executive Office of Health and Human Services

Department of Public Health

Bureau of Environmental Health

Community Sanitation Program

5 Randolph Street

Canton, MA 02021

Telephone: (781) 828-7910

Facsimile: (781) 828-7703

Marian.Robertson@state.ma.us

July 9, 2014

Peter J. Koutoujian, Sheriff
Middlesex County Sheriff's Office
400 Mystic Avenue
Medford, MA 02155

Re: Facility Inspection – Middlesex County House of Correction, Billerica

Dear Sheriff Koutoujian:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Middlesex County House of Correction on June 11, 12, and 13, 2014 accompanied by Sergeant Rudy Chaput, EHSO, Sergeant Brain Coffey, EHSO/Housekeeper, Officer Jason Reuling, EHSO/Housekeeper, and Jonathan Brown, Community Sanitation Program. Violations noted during the inspection are listed below including 571 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

CHECKPOINT BUILDING

Checkpoint

FC 4-601.11(C)*

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, gasket dirty on refrigerator unit

105 CMR 451.350*

Structural Maintenance: One window broken

FC 4-204.112(A)

Design and Construction, Functionality: No functioning thermometer in refrigerator

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

NEW BUILDING

Lobby

Water Fountain

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Administration Wing

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Kitchenette

FC 4-602.12(B)*

Cleaning of Equipment and Utensils; Frequency: Coffee maker dirty

Central Control

FC 4-602.12(B)*

FC 4-601.11(C)*

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, gaskets dirty on refrigerator unit

Bathroom

105 CMR 451.123

Maintenance: Ceiling vent dusty

Attorney Visit Hallway

Female Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Male Bathroom

No Violations Noted

MIT Room

FC 4-601.11(C)*

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, gasket dirty on refrigerator unit

Inmate Bathroom

105 CMR 451.123*

Maintenance: Ceiling vent dusty

Urinalyses Room

FC 4-204.112(A)*

FC 4-501.11(A)*

Design and Construction, Functionality: No functioning thermometer in refrigerator
Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, gaskets damaged on refrigerator unit

Entrance Hallway for Pod A & B

Nurse's Station

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, hot water faucet leaking

Janitor's Closet

No Violations Noted

Caseworker's Office

No Violations Noted

Pod A

Common Area

105 CMR 451.350

Structural Maintenance: Window broken near cell # 1-20

Storage Cage (Barber Shop)

105 CMR 451.353*

Interior Maintenance: Floor surface damaged

105 CMR 451.353

Interior Maintenance: Chair broken

105 CMR 451.353

Interior Maintenance: Hair cutting equipment not cleaned properly

Janitor's Closet

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet continuously running

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, water leaking from back flow preventer

Storage Room

105 CMR 451.353

Interior Maintenance: Floor surface damaged

Lower Level Shower Area

105 CMR 451.123*

Maintenance: Drain flies observed throughout shower area

105 CMR 451.123*

Maintenance: Ceiling vents dusty outside shower units

105 CMR 451.123

Maintenance: Floor dirty outside of shower units

105 CMR 451.123*

Maintenance: Ceiling paint peeling around light outside handicapped shower

105 CMR 451.123*

Maintenance: Ceiling paint peeling outside of shower # 1 and 2

105 CMR 451.123

Maintenance: Ceiling paint peeling outside of shower # 3, 4, and 5

105 CMR 451.123

Maintenance: Soap scum on floor in shower # 4

Lower Cells

105 CMR 451.353*

Interior Maintenance: Floor surface damaged in cell # 1-13, 1-15, and 1-23

105 CMR 451.353

Interior Maintenance: Floor surface damaged in cell # 1-04 and 1-31

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet leaking in cell # 1-08 and 1-18

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet continuously running in cell # 1-01 and 1-02

Upper Level Shower Area

105 CMR 451.123	Maintenance: Drain flies observed throughout shower area
105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1, 2, 3, 4, and 5
105 CMR 451.123*	Maintenance: Soap scum on floor in shower # 5
105 CMR 451.123	Maintenance: Wall dirty outside of shower # 1
105 CMR 451.123	Maintenance: Ceiling paint peeling outside shower # 2 and 3
105 CMR 451.123	Maintenance: Ceilings vents dusty outside of shower units
105 CMR 451.123	Maintenance: Sink dirty
105 CMR 451.123	Maintenance: Caulking damaged around sink

Upper Cells

105 CMR 451.353*	Interior Maintenance: Floor surface damaged in cell # 2-21
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking in cell # 2-02 and 2-03
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet continuously running in cell # 2-04

Pod B

Common Area

No Violations Noted

Storage Cage (Barber Shop)

105 CMR 451.353	Interior Maintenance: Hair cutting equipment not cleaned properly
-----------------	---

Janitor's Closet

No Violations Noted

Storage Room (Small)

No Violations Noted

Storage Room (Large)

No Violations Noted

Lower Level Shower Area

105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 4
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 2, 3, and 5
105 CMR 451.123	Maintenance: Floor dirty outside of shower # 3 and 5
105 CMR 451.123*	Maintenance: Soap scum on floor in shower # 4
105 CMR 451.123	Maintenance: Soap scum on floor in shower # 3 and 5
105 CMR 451.123	Maintenance: Walls dirty outside of shower # 5

Lower Cells

105 CMR 451.353*	Interior Maintenance: Floor surface damaged in cell # 1-23 and 1-25
105 CMR 451.353	Interior Maintenance: Floor surface damaged in cell # 1-19
105 CMR 451.353	Interior Maintenance: Light fixture blocked in cell # 1-13 and 1-21
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation, vent blocked in cell # 1-07, 1-09, 1-18, 1-28, and 1-29
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet continuously running in cell # 1-12

Upper Level Shower Area

105 CMR 451.123*	Unable to Inspect Shower # 1 – Occupied
105 CMR 451.123*	Maintenance: Ceiling vent dusty outside of showers
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 3 and 5
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 4

105 CMR 451.123*	Maintenance: Soap scum on floor in shower # 3
105 CMR 451.123	Maintenance: Soap scum on floor in shower # 5
105 CMR 451.123*	Maintenance: Floor dirty outside of shower # 4

Upper Cells

105 CMR 451.353*	Interior Maintenance: Floor surface damaged in cell # 2-17 and 2-30
105 CMR 451.353	Interior Maintenance: Light fixture blocked in cell # 2-18
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking in cell # 2-06 and 2-23

Entrance Hallway for Pod C & D

Nurse's Station

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Office

No Violations Noted

Pod C

Common Area

No Violations Noted

Storage Cage (Barber Shop)

105 CMR 451.353*	Interior Maintenance: Floor surface damaged
------------------	---

Janitor's Closet

105 CMR 451.353*	Interior Maintenance: Floor paint damaged
105 CMR 451.353*	Interior Maintenance: Door frame rusted

Storage Room

No Violations Noted

Counselor/Interview Office

No Violations Noted

Multi-Purpose Room

No Violations Noted

Lower Level Shower Area

105 CMR 451.123*	Maintenance: Drain flies observed throughout shower area
105 CMR 451.123*	Maintenance: Ceiling paint peeling outside of showers
105 CMR 451.123*	Maintenance: Walls dirty throughout shower area, possible mold/mildew growth
105 CMR 451.123*	Maintenance: Floors dirty throughout shower area, possible mold/mildew growth
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 4 and 5

Lower Cells

105 CMR 451.353*	Interior Maintenance: Floor surface damaged in cell # 1-13 and 1-24
105 CMR 451.353	Interior Maintenance: Floor surface damaged in cell # 1-17

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, faucet continuously running in cell # 1-08, 1-09, and 1-14
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 1-20

Upper Level Shower Area

105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1, 4, and 5
105 CMR 451.123 Maintenance: Soap scum on walls in shower # 2 and 3
105 CMR 451.123 Maintenance: Soap scum on floor in shower # 1, 2, 3, 4, and 5
105 CMR 451.123* Maintenance: Floor dirty throughout shower area, possible mold/mildew growth
105 CMR 451.123* Maintenance: Ceiling vent dirty outside of showers
105 CMR 451.123* Maintenance: Walls dirty in shower # 1, 2, 3, 4, and 5, possible mold/mildew growth
105 CMR 451.123* Maintenance: Walls dirty throughout shower area, possible mold/mildew growth

Upper Cells

105 CMR 451.353* Interior Maintenance: Floor surface damaged in cell # 2-01
105 CMR 451.353 Interior Maintenance: Floor surface damaged in cell # 2-08 and 2-21
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, faucet continuously running in cell # 2-28

Pod D

Common Area

No Violations Noted

Storage Cage (Barber Shop)

105 CMR 451.353* Interior Maintenance: Ceiling vent dusty
105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, faucet loose

Janitor's Closet

No Violations Noted

Multi-Purpose Room

No Violations Noted

Storage Room

No Violations Noted

Lower Level Shower Area

105 CMR 451.123* Maintenance: Ceiling vent dusty outside of showers
105 CMR 451.123* Maintenance: Floor dirty outside handicapped shower # 1
105 CMR 451.123 Maintenance: Soap scum on walls in shower # 2, 3, 4, and 5
105 CMR 451.123 Maintenance: Soap scum on floor in shower # 2 and 3

Lower Cells

105 CMR 451.353* Interior Maintenance: Floor surface damaged in cell # 1-06
105 CMR 451.353 Interior Maintenance: Floor surface damaged in cell # 1-32

Upper Level Shower Area

105 CMR 451.123* Maintenance: Drain flies observed throughout shower area
105 CMR 451.123 Maintenance: Ceiling vents dusty outside of showers
105 CMR 451.123 Maintenance: Ceiling paint peeling outside of showers
105 CMR 451.123 Maintenance: Soap scum on floor in shower # 4 and 5

Upper Cells

105 CMR 451.353
105 CMR 451.130

Interior Maintenance: Light fixture blocked by paper in cell # 2-17
Plumbing: Plumbing not maintained in good repair, faucet continuously running in cell # 2-27 and 2-28

Intake and Discharge

Desk Area

No Violations Noted

Shake Room # 1 & 2

No Violations Noted

Holding Cell # 1 & 2

105 CMR 451.353
105 CMR 451.353
105 CMR 451.353

Interior Maintenance: Floor paint damaged in holding cell # 2
Interior Maintenance: Bench paint damaged in holding cell # 2
Interior Maintenance: Wall paint damaged in holding cell # 2

Institutional Property

No Violations Noted

Holding Cell # 1-6

105 CMR 451.353
105 CMR 451.353

Interior Maintenance: Lower wall vent rusted in holding cell # 1 and 2
Interior Maintenance: Bench paint damaged in holding cell # 3 and 4

Old Shower Room # 1 & 2

105 CMR 451.123

Unable to Inspect Room # 2 – Under Construction
Maintenance: Ceiling vent dusty in shower room # 1

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

105 CMR 451.353*

Interior Maintenance: Floor paint damaged

Break Room

FC 4-204.112(A)*

Design and Construction, Functionality: No functioning thermometer in refrigerator

Inmate Property Room

No Violations Noted

A & B Hall Entrance

Janitor's Closet

No Violations Noted

Hall A

Teacher's Office

No Violations Noted

Hall B

No Violations Noted

Food Service Area

Staff Dining Room

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, refrigerator rusted out at bottom

FC 4-903.11(A)(2)

Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils not covered

Male Bathroom

No Violations Noted

Female Bathroom

105 CMR 451.353

Interior Maintenance: Unlabeled chemical bottle

Main Kitchen

FC 6-501.11*

Maintenance and Operation; Repairing: Facility not in good repair, several floor tiles damaged and missing throughout kitchen

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, several ceiling tiles missing near kitchen office

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, ceiling leaking

FC 6-501.114(A)*

Maintenance and Operations; Maintaining Premises: Nonfunctional equipment not repaired or removed from premises, several unused pieces of equipment throughout kitchen

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, several light shields filled with debris

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, several ceiling vents dusty throughout kitchen

Handwash Sink # 1

No Violations Noted

Freezer # 1

FC 4-601.11(C)

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, debris on floor

Ice Machine

FC 4-602.11(E)(4)(b)

Cleaning of Equipment and Utensils, Frequency: Mold growth observed on interior surfaces of ice machine

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, debris behind ice machine

Diet Food Prep Area

No Violations Noted

Warmer # 1 & 2

No Violations Noted

McCall Refrigerator # 1

FC 4-601.11(C)

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, interior surface dirty

Food Prep Area

FC 4-501.114(A)

Maintenance and Operation; Equipment: Chlorine sanitizer solution tested greater than recommended concentration

Handwash Sink # 10

No Violations Noted

Walk-in Refrigerator

FC 4-501.11(A)*

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, 1 light out

FC 4-601.11(C)*

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, floor dirty

Tray Prep Area

No Violations Noted

Janitor's Closet

No Violations Noted

Spice Cabinet

No Violations Noted

Grease Hood Area

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, debris behind ovens, stoves, and kettles

FC 6-501.14(A)

Maintenance and Operation; Cleaning: Ventilation Systems, ventilation hoods dirty

FC 6-501.11*

Maintenance and Operation; Repairing: Facility not in good repair, floor tiles damaged behind kettles and fryers

Kettles

FC 4-501.11(A)*

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, kettle # 1 lid hinge broken

Fryers

No Violations Noted

Grills and Stovetop

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, 1 light out

Ovens

FC 4-602.13

Cleaning of Equipment and Utensils, Frequency: Nonfood-contact surfaces dirty, oven handles dirty

Prep Sink # 7

FC 4-501.114(A)

Maintenance and Operation; Equipment: Chlorine sanitizer solution tested less than recommended concentration

Steam Hood Area

No Violations Noted

Handwash Sink # 4

No Violations Noted

Vegetable Prep and Sink Area

FC 5-205.15(B)*

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, column paneling not secure next to prep table

Cutting Area

FC 4-501.114(A)

Maintenance and Operation; Equipment: Chlorine sanitizer solution tested greater than recommended concentration

Ice Machine # 3

No Violations Noted

Handwash Sink # 5

No Violations Noted

Walk-in Refrigerator # 2

FC 3-305.11(A)(2)

FC 4-601.11(C)

Preventing Contamination from Premises: Food exposed to dust, fans in cooler dusty
Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, floor dirty

Back Kitchen

Pots & Pans Sink

No Violations Noted

Cooler # 1-4

Unable to Inspect – Not in Use

Dry Goods Bins

No Violations Noted

Baking Area

No Violations Noted

Handwash Sink # 3

No Violations Noted

Serve Line # 2

No Violations Noted

Mechanical Warewash Area

FC 6-501.111(B)

Maintenance and Operations; Pest Control: Flying insects observed around warewashing machine and food digester

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, light shields water stained

Mechanical Warewash Machine

FC 6-501.12(A)*

Maintenance and Operation; Cleaning: Facility not cleaned properly, wall dirty behind spray sink, possible mold/mildew growth

FC 6-501.12(A)*

Maintenance and Operation; Cleaning: Facility not cleaned properly, floor dirty under warewash machine

FC 4-501.11(A)*

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, warewash machine leaking

FC 4-501.112(A)(2)

Maintenance and Operation, Equipment: Inadequate water temperature in the mechanical warewashing machine

FC 4-501.114(A)

Maintenance and Operation; Equipment: Chlorine sanitizer solution tested less than recommended concentration from warewash machine after hooked up

Food Digester

FC 6-304.11

Ventilation; Mechanical: Area not properly ventilated, strong odors around digester

FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, walls dirty around machine
FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, floor dirty under machine

Front Kitchen Pots & Pans Sink

FC 6-501.12(A)*	Maintenance and Operation; Cleaning: Facility not cleaned properly, standing water on floor
FC 6-501.111(B)	Maintenance and Operations; Pest Control: Drain flies observed

Rack Spray Area

FC 6-501.111(B)*	Maintenance and Operations; Pest Control: Drain flies observed
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, wall paint damaged
FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, walls dirty
FC 6-501.11	Maintenance and Operation; Repairing: Facility not in good repair, wooden shelf rotted out

Inmate Bathroom

No Violations Noted

Staff Bathroom

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water knob leaks when cold water is on
-----------------	--

Kitchen Staff Break Room

FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, bottom of utensil locker dirty
----------------	--

Supply Room # 1 (Culinary Arts Supply Room)

No Violations Noted

Supply Room # 1 (Dry Storage Room)

FC 6-501.12(A)*	Maintenance and Operation; Cleaning: Facility not cleaned properly, floor dirty under shelving units
-----------------	--

Chemical Storage Cabinet

No Violations Noted

Spice Cabinet

No Violations Noted

Daily Cleaning Supply Cabinet

No Violations Noted

Culinary Arts Storage Cabinet

Unable to Inspect – Locked

Loading Dock

FC 6-501.111(B)	Maintenance and Operations; Pest Control: Flying insects observed
FC 6-202.15(A)(2)	Design, Construction, and Installation; Functionality: Outer door not weather and vermin tight

Spare Kitchen Equipment Room

No Violations Noted

Kitchen Surplus

No Violations Noted

Culinary Arts Program Kitchen

McCall Refrigerator

No Violations Noted

Proofers

No Violations Noted

Walk-in Freezer

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, ice build-up observed

Smokers

No Violations Noted

Ovens

No Violations Noted

Fryolator

No Violations Noted

Skillet

No Violations Noted

Barbecuer

No Violations Noted

Handwash Sink

No Violations Noted

3-Bay Sink

No Violations Noted

Prep Sink

No Violations Noted

Prep Tables

No Violations Noted

Walk-in Refrigerator

No Violations Noted

Health Service Unit

ISO 1 & 2

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet continuously running in ISO 1

Nurse's Pantry

FC 4-602.12(B)*

FC 4-601.11(C)

Cleaning of Equipment and Utensils; Frequency: Coffee maker dirty
Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty,
gaskets dirty on refrigerator unit

Janitor's Closet

No Violations Noted

Risk Cell # 1 & 2
105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet continuously running in cell # 2

Holding Cell # 1-4
105 CMR 451.353

Interior Maintenance: Wall paint damaged in cell # 2

Ward A

No Violations Noted

Inmate Shower Room
105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, bottom shower head leaking

Nurse's Station and Bathroom

No Violations Noted

Cleaning Utility Room

No Violations Noted

Storage Room # 1

No Violations Noted

Storage Room # 2
105 CMR 451.383(B)*

Fire Safety System: Facility not in compliance with 780 CMR Massachusetts Building Code provisions for fire safety, food stored less than 18" from ceiling

Holding

No Violations Noted

Ward B
105 CMR 451.123*
105 CMR 451.130

Maintenance: Ceiling vent dirty near showers
Plumbing: Plumbing not maintained in good repair, toilet button leaking while flushing

Treatment Room # 1

No Violations Noted

Inmate Bathroom

No Violations Noted

Treatment Room # 2

No Violations Noted

Physical Therapy

No Violations Noted

Dental Room

No Violations Noted

Pharmacy
105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

105 CMR 480.500(B)(2)	Procedures; Records; Record-Keeping Log: Log book not up to date with recent tracking receipts
<i>Medical Waste Room</i>	Unable to Inspect – Locked
<i>Lab</i>	No Violations Noted
<i>Internal Medicine Office</i>	No Violations Noted
<i>Psychiatry Office</i>	No Violations Noted
<i>Treatment Room # 3</i>	No Violations Noted
<i>Exam Room # 1</i>	No Violations Noted
<i>Exam Room # 2</i>	No Violations Noted
<i>Health Service Administrator's Office</i>	No Violations Noted
<i>Female Bathroom</i>	No Violations Noted
<i>Male Bathroom</i>	No Violations Noted
<u>OLD BUILDING</u>	
Main Level	
105 CMR 451.350	Structural Maintenance: Wall tiles damaged near entrance
<i>Lobby</i>	No Violations Noted
<i>Janitor's Closet</i>	No Violations Noted
<i>Female Bathroom</i>	
105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, toilet # 1 out-of-order
105 CMR 451.123*	Maintenance: Several glass window panels broken
105 CMR 451.123	Maintenance: Window panel missing
<i>Male Bathroom</i>	
105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound
105 CMR 451.130	Plumbing: No backflow preventer on sink

Control Area

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound

105 CMR 451.350*

Structural Maintenance: Window sills and wall near windows damaged

105 CMR 451.350*

Structural Maintenance: Several window panes broken

105 CMR 451.350*

Structural Maintenance: Ceiling damaged, white powdery substance flaking off from ceiling

Roll Call Room

No Violations Noted

Old Administration Wing

First Floor

105 CMR 451.353

Interior Maintenance: Ceiling tiles missing in hallway

Tool Crib Area

No Violations Noted

Tool Crib Bathroom

105 CMR 451.123

Maintenance: Sink rusted

Mail Room

Unable to Inspect – Locked

Chemical Area

No Violations Noted

Female Bathroom

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound

Second Floor

105 CMR 451.353

Interior Maintenance: Floor tiles missing in hallway

Break Room

No Violations Noted

Male Bathroom

105 CMR 451.123*

Maintenance: Ceiling damaged, paint peeling

105 CMR 451.123*

Maintenance: Wall vent missing

Third Floor

Male Locker Room

No Violations Noted

Male Locker Room Bathroom

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound

105 CMR 451.350

Structural Maintenance: Window broken

Female Locker Room

Unable to Inspect – Locked

Officer's Weight Room

105 CMR 451.353*

Interior Maintenance: Floor paint damaged

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound

105 CMR 451.353

Interior Maintenance: Ceiling paint peeling

Lower Report

A & B Side Cells

Unable to Inspect – No longer in use due to lack of natural lighting

TRAINING BUILDING

First Floor

Staff Meeting Room

Unable to Inspect – Under Construction

Offices and Classroom

No Violations Noted

Library

No Violations Noted

Bathroom and Storage Room

No Violations Noted

Second Floor

Main Laundry

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound

105 CMR 451.353

Interior Maintenance: Wall paint peeling

105 CMR 451.353

Interior Maintenance: Lint and debris behind washer and dryer units

Inmate Bathroom

No Violations Noted

Officer's Bathroom

No Violations Noted

Laundry Storage

No Violations Noted

Canteen

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound

105 CMR 451.350

Structural Maintenance: Window panel missing

Main Level

Old Wing Day Room

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound

Side Entry Stairs

No Violations Noted

Tier Building Dorm Room

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound

105 CMR 451.353

Interior Maintenance: Floor surface damaged

Dorm Bathroom

105 CMR 451.130	Hot Water: Shower water temperature recorded at 127 ⁰ F
105 CMR 451.123	Maintenance: Walls dirty outside of showers, possible mold/mildew
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet # 7 out-of-order
105 CMR 451.123	Maintenance: Standing water around toilet # 6
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1, 2, 3, 4, and 5

First Tier

Common Area

No Violations Noted

Control

105 CMR 451.353	Interior Maintenance: Hair cutting equipment not cleaned properly
-----------------	---

A & B Side

105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound in cell # A1-A24 and B1-B26
105 CMR 451.360	Protective Measures: Flying insects observed on hallway
105 CMR 451.353	Interior Maintenance: Standing water in bucket under hot water dispenser
105 CMR 451.350	Structural Maintenance: Center window missing in cell # B1-B24
105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # B1
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # A15
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # A20, B15, and B19
105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # B21
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # A12 and B19

Bathroom and Shower Area (11 Showers)

105 CMR 451.123*	Maintenance: Walls dirty throughout room, possible mold/mildew growth
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation
105 CMR 451.123	Maintenance: Wall paint peeling throughout room
105 CMR 451.123	Maintenance: Ceiling paint peeling throughout room
105 CMR 451.123*	Maintenance: Ceiling paint damaged in shower # 1, 2, 5, and 6
105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1, 2, 3, 4, 5, 6, 10, and 11
105 CMR 451.123*	Maintenance: Soap scum on floors in shower # 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, and 11
105 CMR 451.123	Maintenance: Walls dirty in shower # 1, 2, 3, 4, 5, and 6; possible mold/mildew growth
105 CMR 451.123	Maintenance: Bottom of shower partitions damaged in between shower # 1, 2, 3, 4, 5, and 6
105 CMR 451.123	Maintenance: Insects observed in shower # 1 and 2
105 CMR 451.123	Maintenance: Urinal dirty

C & D Side (Administrative Segregation and Segregation Unit)

105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound in cell # C1-C24 and D1-D26
105 CMR 451.350*	Structural Maintenance: Wall damaged outside of cell # D16
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # C16 and D9
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # C2, C6, C7, C9, C13, C18, C20, C24, D4, D8, D12, D13, D15, D17, and D18
105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # C20 and D14
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # C11, C12, C14, C22, C23, D4, D5, D6, D7, D8, D12, D13, D16, D18, D20, and D25

Shower Room # D23

105 CMR 451.119*

Bathing Facilities: Inadequate shower to inmate ratio, 1 shower provided for 43 inmates

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation

105 CMR 451.123*

Maintenance: Wall paint peeling

Second Tier

Common Area

No Violations Noted

Control

105 CMR 451.353

Interior Maintenance: Hair cutting equipment not cleaned properly

105 CMR 451.353

Interior Maintenance: Hair cutting equipment rusted

105 CMR 451.353

Interior Maintenance: Hair cutting equipment container dirty

E & F Side

105 CMR 451.320*

Cell Size: Inadequate floor space in all cells

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound in cell # E1-E24 and F1-F26

105 CMR 451.353*

Interior Maintenance: Wall paint damaged in cell # E2, E14, F3, F7, and F19

105 CMR 451.353

Interior Maintenance: Wall paint damaged in cell # E1 and E7

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # F14

105 CMR 451.353

Interior Maintenance: Floor paint damaged in cell # E2, E14, E15, F1, F3, F4, F11, and F15

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet continuously running in cell # E11

Bathroom and Shower Area (12 Showers)

105 CMR 451.123*

Maintenance: Walls dirty outside shower units, possible mold/mildew growth

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation

105 CMR 451.123*

Maintenance: Wall paint damaged throughout room

105 CMR 451.123*

Maintenance: Ceiling paint damaged throughout room

105 CMR 451.123

Maintenance: Flying insects observed throughout room

105 CMR 451.123

Maintenance: Drain flies observed in shower # 3

105 CMR 451.123*

Maintenance: Ceiling paint damaged in shower # 1, 2, 3, and 7

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, and 12

105 CMR 451.123*

Maintenance: Soap scum on floors in shower # 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, and 12

105 CMR 451.123*

Maintenance: Bottom of partitions damaged between shower # 4, 5, and 6

105 CMR 451.123

Maintenance: Caulking dirty in shower # 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, and 12; possible mold/mildew growth

Janitorial Cage

105 CMR 451.353

Interior Maintenance: Mops stored in bucket

G & H Side

105 CMR 451.320*

Cell Size: Inadequate floor space in all cells

105 CMR 451.350*

Structural Maintenance: Windows not weathertight and structurally sound in cell # G1-G24 and H1-H26

105 CMR 451.103

Mattresses: Mattress damaged in cell # G1, H5, H8, H9, H11, H14, and H23

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # G3, G8, and G14

105 CMR 451.353

Interior Maintenance: Floor paint damaged in cell # G5, G6, G10, G11, G15, G16, G18, G19, and G21

105 CMR 451.353

Interior Maintenance: Wall paint damaged in cell # G11 and G23

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet continuously running in cell # G17
Gym	
105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound
105 CMR 451.353*	Interior Maintenance: Floor surface damaged
105 CMR 451.353*	Interior Maintenance: Wall mounted fans dirty
105 CMR 451.350*	Structural Maintenance: Ceiling damaged
105 CMR 451.353	Interior Maintenance: Wall paint damaged
Gym Office	
105 CMR 451.350*	Structural Maintenance: Floor tiles missing
105 CMR 451.353*	Interior Maintenance: Ceiling dirty
105 CMR 451.353*	Interior Maintenance: Wall paint damaged
105 CMR 451.141	Screens: Screen missing
Staff Bathroom	
105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound
105 CMR 451.123*	Maintenance: Floor damaged and missing tiles
105 CMR 451.353*	Interior Maintenance: Light switch panel loose
105 CMR 451.353*	Interior Maintenance: Wall paint damaged
Stairway to Third Tier	
105 CMR 451.353*	Interior Maintenance: Ceiling paint peeling
Third Tier	
Common Area	
	No Violations Noted
Control	
105 CMR 451.353	Interior Maintenance: Hair cutting equipment not cleaned properly
105 CMR 451.353	Interior Maintenance: Hair cutting equipment container dirty
Offices	
	No Violations Noted
I & J Side	
105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound in cell # I1-I24 and J1-J26
105 CMR 451.350	Structural Maintenance: Center window missing in cell # I1-I24 and J1-J26
105 CMR 451.353	Interior Maintenance: Vent fan dusty at end of hallway
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # I23
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # I18 and J20
105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # I20, I22, and J17
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # J18
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, slop sink leaking
105 CMR 451.353	Interior Maintenance: Sock tied around faucet on slop sink
Bathroom and Shower Area (12 Showers)	
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation
105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1, 3, 4, 5, 6, 7, 8, 9, 10, 11, and 12
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 2
105 CMR 451.123*	Maintenance: Soap scum on floor in shower # 1, 3, 4, 5, 6, 7, 8, 9, 10, 11, and 12
105 CMR 451.123	Maintenance: Soap scum on floor in shower # 2

105 CMR 451.123	Maintenance: Caulking dirty in shower # 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, and 12; possible mold/mildew growth
105 CMR 451.123*	Maintenance: Caulking damaged around sink
105 CMR 451.123*	Maintenance: Sink leaking
105 CMR 451.123*	Maintenance: Toilet dirty
105 CMR 451.123*	Maintenance: Urinal dirty
 <i>Janitor's Closet</i>	
105 CMR 451.353*	Interior Maintenance: Floor surface damaged
105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light not working

<i>K & L Side</i>	
105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound in cell # K1-K24 and L1-L26
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # K3
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # K2
105 CMR 451.350	Structural Maintenance: Center window missing in cell # L1-L26

CWP BUILDING

First Floor

Entrance

No Violations Noted

Control

No Violations Noted

Officer's Bathroom

105 CMR 451.123	Maintenance: Light shield missing
-----------------	-----------------------------------

Caseworker's Office

Unable to Inspect – Locked

Teacher's Office

Unable to Inspect – Locked

Closet

No Violations Noted

Food Service Area

Dining Room

105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound
105 CMR 451.350*	Structural Maintenance: Window broken

Kitchen

FC 6-202.15(A)(2)*	Design, Construction, and Installation; Functionality: Windows not weathertight and structurally sound
FC 6-501.12(A)*	Maintenance and Operation; Cleaning: Facility not cleaned properly, vent fan dirty
FC 6-501.12(A)*	Maintenance and Operation; Cleaning: Facility not cleaned properly, floor dirty under 3-bay sink
FC 6-501.12(A)*	Maintenance and Operation; Cleaning: Facility not cleaned properly, floor dirty throughout kitchen

FC 6-501.12(A)*	Maintenance and Operation; Cleaning: Facility not cleaned properly, hot holding unit dirty on the outside
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, floor surface damaged throughout kitchen
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, wall paint damaged near 3-bay sink and warewash machine
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, ceiling paint peeling above 3-bay sink
FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, gaskets damaged on hot holding unit
FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, gaskets damaged on Traulsen refrigerator
FC 4-601.11(A)	Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, can opener dirty
FC 4-204-113(A)	Design and Construction, Functionality: Data plates not working on warewashing machine
FC 6-202.11(A)	Design, Construction, and Installation; Functionality: Light bulbs not shatter-resistant or protected by light shields in closet

Inmate Housing Area

Shower and Bathroom

105 CMR 451.123*	Maintenance: Vent fan dirty
105 CMR 451.123	Maintenance: Standing water in shower area
105 CMR 451.123	Maintenance: Door damaged on toilet stall # 5
105 CMR 451.126	Hot Water: Hot water temperature recorded at 135°F
105 CMR 451.123	Maintenance: Heat vents under sink rusted
105 CMR 451.126	Water Supply: No hot water supplied to handwash sink # 6

Supply Cage

No Violations Noted

Hallway

No Violations Noted

Laundry Area

105 CMR 451.353*	Interior Maintenance: Floor paint damaged
105 CMR 451.350*	Structural Maintenance: Wall not weathertight and structurally sound, old ventilation hole not covered
105 CMR 451.353	Interior Maintenance: Debris and lint behind machines

Recreational and Weight Room

105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound
105 CMR 451.353	Interior Maintenance: Light shields missing

Second Floor

Hallway

105 CMR 451.353	Interior Maintenance: Standing water in bucket from hot water dispenser
-----------------	---

Bathroom

105 CMR 451.123*	Maintenance: Vent fan dirty
105 CMR 451.123*	Maintenance: Inadequate ventilation, vent fan not functioning properly
105 CMR 451.123*	Maintenance: Floor paint damaged

<i>Plaza # 1</i>	
105 CMR 451.353	Interior Maintenance: Wall paint peeling
105 CMR 451.103	Mattresses: Mattress damaged at bed # 7
 <i>Plaza # 2</i>	
	No Violations Noted
 <i>Plaza # 3</i>	
105 CMR 451.322*	Cell Size: Inadequate floor space in dorm rooms
 <i>Room # 1</i>	
105 CMR 451.350*	Structural Maintenance: Wall damaged
 <i>Room # 2</i>	
105 CMR 451.353*	Interior Maintenance: Wall paint damaged
 <i>Room # 3</i>	
105 CMR 451.353*	Interior Maintenance: Wall paint damaged
 <i>Room # 4</i>	
	No Violations Noted
 <i>Room # 5</i>	
	No Violations Noted
 <i>Room # 6</i>	
	No Violations Noted
 <i>Room # 7</i>	
	No Violations Noted
 <i>Room # 8</i>	
	No Violations Noted
 <i>Room # 9</i>	
	No Violations Noted
 <i>Room # 10</i>	
	No Violations Noted

WORK RELEASE BUILDING

House # 1

First Floor

<i>Hallway</i>	
105 CMR 451.353*	Interior Maintenance: Wall paint damaged near phones
 <i>Control</i>	
	No Violations Noted
 <i>Office</i>	
	No Violations Noted

Bathroom

105 CMR 451.123*	Maintenance: Lights fixture not functioning properly, 2 lights out
105 CMR 451.123*	Maintenance: Vent fan dusty
105 CMR 451.123*	Maintenance: Baseboard not secure under sink
105 CMR 451.123*	Maintenance: Ceiling tiles water damaged
105 CMR 451.123*	Maintenance: Floor dirty throughout bathroom
105 CMR 451.123	Maintenance: Ceiling tiles missing

Bedrooms

No Violations Noted

Food Service Area

Dining Room

FC 4-602.12(B)*	Cleaning of Equipment and Utensils; Frequency: Interior of toaster over dirty
-----------------	---

Kitchen

FC 4-601.11(A)*	Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, can opener dirty
FC 6-501.14(A)	Maintenance and Operation; Cleaning: Ventilation Systems, ventilation hoods dirty
FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, dishwasher out-of-order
FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, gaskets damaged on True refrigerator

Second Floor

Stairway

No Violations Noted

Hallway

105 CMR 451.353	Interior Maintenance: Fan dirty in hallway
-----------------	--

Bedrooms

105 CMR 451.353*	Interior Maintenance: Wall paint damaged in bedroom # 7 and 10
105 CMR 451.353	Interior Maintenance: Wall paint damaged in bedroom # 8

Bathroom

105 CMR 451.123*	Maintenance: Caulking damaged in shower # 1 and 3
105 CMR 451.123*	Maintenance: Caulking dirty in shower # 1, possible mold/mildew growth
105 CMR 451.123*	Maintenance: Ceiling vent damaged
105 CMR 451.123	Maintenance: Floor paint damaged

Stairway to Basement

105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, 1 light out
------------------	--

Basement

Laundry Room

105 CMR 451.353*	Interior Maintenance: Ceiling paint peeling
------------------	---

Boiler Room

105 CMR 451.353*	Interior Maintenance: Wall paint peeling
------------------	--

Chemical Storage Room

105 CMR 451.350*

Structural Maintenance: Wall damaged

105 CMR 451.350*

Structural Maintenance: Floor damaged

105 CMR 451.353*

Interior Maintenance: Ceiling paint peeling

Day Room Between Houses

105 CMR 451.350*

Structural Maintenance: Ledge damaged

105 CMR 451.353

Interior Maintenance: Floor tiles damaged

House # 2

First Floor

Officer's Bathroom

No Violations Noted

Bedrooms

No Violations Noted

Second Floor

Hallway

No Violations Noted

Bathroom

105 CMR 451.350

Structural Maintenance: Window covered with wood

Bedrooms

105 CMR 451.353

Interior Maintenance: Light shield not secure in bedroom # 1

Third Floor

Bedrooms

No Violations Noted

Basement

Day Room

105 CMR 451.141

Screens: Screen damaged

105 CMR 451.141

Screens: Screen not secure

Bathroom

105 CMR 451.123*

Maintenance: Shower wall tiles damaged in shower # R1

105 CMR 451.123

Maintenance: Vent fan dusty

105 CMR 451.123

Maintenance: Light not functioning properly, 1 light out

WAREHOUSE

105 CMR 451.350

Structural Maintenance: Exterior door not weathertight

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Walk-in Freezer

FC 4-501.11(A)*

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, 1 light out

FC 4-501.11(A)*

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, metal baseboard damaged

Observations and Recommendations

1. The inmate population was 992 at the time of inspection.
2. The mechanical warewashing machine was not functioning properly at the time of inspection. The Department recommended using 3-bay sink or using paper plates until the warewash machine was adjusted to reach the proper temperature or the correct sanitizing solution concentration. The Department also recommended to the facility to implement a way of testing the hot water rinse cycle on a daily basis.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Marian Robertson

Environmental Health Inspector, CSP, BEH

cc: Suzanne K. Condon, Associate Commissioner, Director, BEH
Steven Hughes, Director, CSP, BEH
John W. Polanowicz, Secretary, Executive Office of Health and Human Services
Luis S. Spencer, Commissioner, DOC
Sean McAdam, Superintendent
Richard Vivier, Deputy Superintendent
Captain William Buckley, EHSO
Sergeant Rudy Chaput, EHSO
Richard Berube, Director, Billerica Board of Health
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Andrea Cabral, Secretary, EOPS