

**CHARLES D. BAKER** Governor

KARYN E. POLITO Lieutenant Governor

# The Commonwealth of Massachusetts Executive Office of Health and Human Services Department of Public Health **Bureau of Environmental Health Community Sanitation Program** 250 Washington Street, Boston, MA 02108-4619 Phone: 617-624-5757 Fax: 617-624-5777

TTY: 617-624-5286

**MARYLOU SUDDERS** Secretary

MONICA BHAREL, MD, MPH Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

March 12, 2015

Peter J. Koutoujian, Sheriff Middlesex County Sheriff's Office 400 Mystic Avenue Medford, MA 02155

Re: Facility Inspection - Middlesex County House of Correction, Billerica

Dear Sheriff Koutoujian:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Middlesex County House of Correction on January 26, 29, and 30, 2015 accompanied by Sergeant Rudy Chaput, EHSO, and Marian Robertson, Community Sanitation Program. Violations noted during the inspection are listed below including 176 repeat violations:

## **HEALTH AND SAFETY VIOLATIONS**

(\* indicates conditions documented on previous inspection reports)

## **CHECKPOINT BUILDING**

Checkpoint

FC 4-903.11(A)(2) Protection of Clean Items, Storing: Single-service items not protected from

contamination, utensils not covered

FC 4-602.12(B)\* Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

105 CMR 451.353 Interior Maintenance: Standing water in bucket

105 CMR 451.353 Interior Maintenance: Drain cover missing in slop sink

# **NEW BUILDING**

Lobby

Water Fountain

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

105 CMR 451.344

Illumination in Habitable Areas: Light not functioning properly, light not working

**Administration Wing** 

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Kitchenette

No Violations Noted

**Central Control** 

No Violations Noted

**Bathroom** 

No Violations Noted

**Attorney Visit Hallway** 

Female Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Male Bathroom

No Violations Noted

Visiting Control Room

No Violations Noted

Inmate Bathroom

No Violations Noted

Urinalyses Room

# Entrance Hallway for Pod A & B

Nurse's Station

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

105 CMR 451.123

Maintenance: Debris on floor

Janitor's Closet

No Violations Noted

Caseworker's Office

No Violations Noted

Pod A

Common Area

No Violations Noted

Storage Cage (Barber Shop)

105 CMR 451.353\*

Interior Maintenance: Floor surface damaged

105 CMR 451.353\*

Interior Maintenance: Chair broken

Janitor's Closet

105 CMR 451.130\*

Plumbing: Plumbing not maintained in good repair, water leaking from back flow

preventer

Storage Room

105 CMR 451.353\*

Interior Maintenance: Floor surface damaged

Lower Level Shower Area

105 CMR 451.123\*

Maintenance: Ceiling vents dusty outside shower units Maintenance: Ceiling paint peeling in shower # 1, 2, 3, and 4

105 CMR 451.123\*

105 CMR 451.123

Maintenance: Wall paint peeling in shower #3

Lower Cells

No Violations Noted

Upper Level Shower Area

105 CMR 451.123\*

Maintenance: Caulking damaged around sink

105 CMR 451.123

Maintenance: Ceiling paint peeling in shower # 3 and 5

105 CMR 451.123

Maintenance: Wall paint peeling in shower # 1, 2, 3, 4, and 5

Upper Cells

No Violations Noted

Pod B

Common Area

No Violations Noted

Storage Cage (Barber Shop)

105 CMR 451.353

Interior Maintenance: Barber chair damaged

Janitor's Closet

No Violations Noted

Storage Room (Small)

No Violations Noted

Storage Room (Large)

No Violations Noted

Lower Level Shower Area

105 CMR 451.123\* 105 CMR 451.123

Maintenance: Soap scum on walls in shower # 3 Maintenance: Ceiling paint peeling in shower # 5

Lower Cells

No Violations Noted

Upper Level Shower Area

105 CMR 451.123\* 105 CMR 451.123\* 105 CMR 451.123

Maintenance: Ceiling vent dusty outside of showers Maintenance: Floor dirty outside of shower #4 Maintenance: Floor paint peeling in shower # 1 Maintenance: Sink basin dirty

105 CMR 451.123

105 CMR 451.123

Maintenance: Shower head leaking in shower # 4

Upper Cells

FC 3-501.16(B)

Limitation of Growth of Organisms, Temperature and Time Control: Potentially

hazardous food not held at the proper cold holding temperature, milk stored outside of

FC 3-501.16(B)

Limitation of Growth of Organisms, Temperature and Time Control: Potentially

hazardous food not held at the proper cold holding temperature, milk stored on window

sill in cell # B2-11

# Entrance Hallway for Pod C & D

Nurse's Station

No Violations Noted

Female Bathroom

105 CMR 451.126

Hot Water: Hot water temperature recorded at 72°F

Male Bathroom

No Violations Noted

Office

No Violations Noted

Pod C

Common Area

No Violations Noted

Storage Cage (Barber Shop)

105 CMR 451.353\* 105 CMR 451.353

Interior Maintenance: Floor surface damaged Interior Maintenance: Barber chair damaged

Janitor's Closet 105 CMR 451.353\*

Interior Maintenance: Door frame rusted

105 CMR 451.353

Interior Maintenance: Drain cover missing from slop sink

Storage Room

No Violations Noted

Counselor/Interview Office

No Violations Noted

Multi-Purpose Room

No Violations Noted

Lower Level Shower Area

105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 Maintenance: Debris on floor in shower # 2 and 3 Maintenance: Ceiling paint peeling in shower # 1 and 3

Maintenance: Floor dirty in shower # 4

Lower Cells

No Violations Noted

Upper Level Shower Area

105 CMR 451.123 105 CMR 451.123 105 CMP 451.123 Maintenance: Drain flies observed throughout shower area Maintenance: Ceiling paint peeling in shower # 1 and 2

105 CMR 451.123 105 CMR 451.123 Maintenance: Wall paint peeling in shower # 1
Maintenance: Debris on floor outside shower # 4

Upper Cells

105 CMR 451.353\*

Interior Maintenance: Floor tiles missing outside cell # C-2 01 - C-2 11

Pod D

Common Area

No Violations Noted

Storage Cage (Barber Shop)

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet leaking

Janitor's Closet

No Violations Noted

Multi-Purpose Room

No Violations Noted

Storage Room

No Violations Noted

Lower Level Shower Area

105 CMR 451.123

Maintenance: Drain flies observed throughout shower area

Lower Cells

No Violations Noted

Upper Level Shower Area

105 CMR 451.123

Maintenance: Ceiling paint peeling in shower # 3 and 4

Upper Cells

No Violations Noted

E - Pod

**Administration Area** 

Female Staff Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Male Staff Bathroom

No Violations Noted

Nurse's Station

Unable to Inspect - Locked

Block

Janitor's Closet 105 CMR 451.353

Interior Maintenance: Debris in slop sink

Barber Shop

105 CMR 451.110(A)

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

Segregation Showers

105 CMR 451.123

Maintenance: Debris on floor in shower # 1-4

Segregation Cells

No Violations Noted

Classroom

No Violations Noted

Library

No Violations Noted

Caseworker's Office

FC 4-602.12(B) FC 4-903.11(A)(2) Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

Protection of Clean Items, Storing: Single-service items not protected from

contamination, utensils not stored with handles up

Upper Cells

No Violations Noted

**Upper Showers** 

105 CMR 451.123 Maintenance: Debris on floor in shower # 1-10 105 CMR 451.123 Maintenance: Soap scum on wall in shower # 1-10 105 CMR 451.123 Maintenance: Soap scum on floor in shower # 1-10

Dorm # 1 and 2 Landing

Administration Office

Janitor's Closet

No Violations Noted

Men's Staff Bathroom

No Violations Noted

Women's Staff Bathroom

Unable to Inspect - Locked

Dorm #1

Storage/Med Pass

No Violations Noted

Sleeping Area

No Violations Noted

Common Area

No Violations Noted

Toilet Area

No Violations Noted

Sink Area

105 CMR 451.123

Maintenance: Debris in sink

Shower Area

105 CMR 451.123

Maintenance: Soap scum on wall in shower # 1, 3, and 4

105 CMR 451.123

Maintenance: Soap scum on floor in shower # 1

105 CMR 451.123

Maintenance: Debris on floor in shower # 1

Janitor's Closet

105 CMR 451.353

Interior Maintenance: Debris in sink

Case Worker's Office

No Violations Noted

Barber Shop

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet heading missing

**Dorm # 2** 

Storage/Med Pass

Unable to Inspect - Locked

Classroom # 2

No Violations Noted

Barber Shop

No Violations Noted

Case Worker's Office

Janitor's Closet 105 CMR 451.353

Interior Maintenance: Debris in sink

Shower Area

Unable to Inspect – Used for Storage

Toilet Area

No Violations Noted

Sink Area

105 CMR 451.123

Maintenance: Debris in sink

Common Area

No Violations Noted

Sleeping Area

No Violations Noted

**Dorm #3** 

Storage/Med Pass

No Violations Noted

Sleeping Area

No Violations Noted

Common Area

No Violations Noted

Toilet Area

No Violations Noted

Sink Area

No Violations Noted

Shower Area

Maintenance: Water dripping from ceiling in shower # 1
105 CMR 451.123
Maintenance: Soap scum on wall in shower # 2, 3, 5, 6, and 7
105 CMR 451.123
Maintenance: Soap scum on floor in shower # 1, 2, 3, 5, 6, and 7
Maintenance: Debris on floor in shower # 1 and 2

Janitor's Closet

No Violations Noted

Case Worker's Office

No Violations Noted

Barber Shop

105 CMR 451.353

Interior Maintenance: Debris in sink

**Dorm #4** 

Medical Office

Classroom # 2

No Violations Noted

Barber Shop

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet heading missing

Case Worker's Office

No Violations Noted

Janitor's Closet

105 CMR 451.353

Interior Maintenance: Debris in sink

Shower Area

105 CMR 451.123

Maintenance: Drain flies observed throughout shower area

Toilet Area

No Violations Noted

Sink Area

105 CMR 451.123

Maintenance: Debris in sink

Common Area

No Violations Noted

Sleeping Area

105 CMR 451.353

Interior Maintenance: Tile damaged along back wall

Pod F

Medical Office

Unable to Inspect - Locked

Administration Area

No Violations Noted

Female Staff Bathroom

Unable to Inspect - Locked

Janitor's Closet

105 CMR 451.344

Illumination in Habitable Areas: Light not functioning properly, light not working

Male Staff Bathroom

No Violations Noted

Block

Janitor's Closet

No Violations Noted

Barber Shop

No Violations Noted

Lower Showers

Lower Cells

No Violations Noted

Assessment Office

FC 4-903.11(A)(2)

Protection of Clean Items, Storing: Single-service items not protected from

contamination, utensils not covered

Library

No Violations Noted

Case Worker's Office

No Violations Noted

Upper Cells

No Violations Noted

Upper Showers

105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 Maintenance: Soap scum on wall in shower # 8, 9, and 10 Maintenance: Soap scum on floor in shower # 8, 9, and 10 Maintenance: Debris on floor in shower # 8, 9, and 10

Common Area

No Violations Noted

**Intake and Discharge** 

Administrative Office

No Violations Noted

Desk Area

No Violations Noted

Shake Room # 1 & 2

No Violations Noted

Holding Cell # 1 & 2

No Violations Noted

Institutional Property

No Violations Noted

Holding Cell # 1-6

No Violations Noted

Old Shower Room # 1 & 2

105 CMR 451.123\*

Maintenance: Ceiling vent dusty in shower room # 1

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

Break Room

FC 4-903.11(A)(2) Protection of Clean Items, Storing: Single-service items not protected from

contamination, utensils not covered

Inmate Property Room

No Violations Noted

A & B Hall Entrance

Janitor's Closet

No Violations Noted

Hall A

Teacher's Office

No Violations Noted

Hall B

No Violations Noted

Food Service Area

Staff Dining Room

FC 4-501.11(B) Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, refrigerator handle damaged

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Administrative Office

No Violations Noted

Main Kitchen

FC 6-501.12(A)\* Maintenance and Operation; Cleaning: Facility not cleaned properly, several light shields

filled with debris

Handwash Sink # 1

No Violations Noted

Freezer # 1

No Violations Noted

Ice Machine

FC 4-602.11(E)(4)(b)\* Cleaning of Equipment and Utensils, Frequency: Mold growth observed on interior

surfaces of ice machine

Diet Food Prep Area

No Violations Noted

Warmer # 1 & 2

McCall Refrigerator # 1

FC 4-601.11(C) Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, interior

surface dirty

Food Prep Area

No Violations Noted

Handwash Sink # 10

No Violations Noted

Walk-in Refrigerator # 2

FC 4-501.11(B) Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, refrigerator gaskets damaged

FC 3-305.11(A)(2) Preventing Contamination from Premises: Food exposed to dust, fans in cooler dusty

Tray Prep Area

No Violations Noted

Janitor's Closet

No Violations Noted

Spice Cabinet

No Violations Noted

Grease Hood Area

No Violations Noted

Kettles

No Violations Noted

Fryers

No Violations Noted

Grills and Stovetop

No Violations Noted

**Ovens** 

No Violations Noted

Butcher Prep Table

FC 4-501.114(C)(2) Maintenance and Operation; Equipment: Quaternary ammonium solution less than the

manufacturers recommended concentration

Prep Sink # 8

FC 5-205.15(B) Plumbing System, Operations and Maintenance: Plumbing system not maintained in

good repair, faucet dripping

Steam Hood Area

No Violations Noted

Handwash Sink # 4

No Violations Noted

Vegetable Prep and Sink Area

**Cutting Area** 

No Violations Noted

Ice Machine #3

No Violations Noted

Handwash Sink # 5

No Violations Noted

Walk-in Refrigerator # 2

FC 3-305.11(A)(2)\*

Preventing Contamination from Premises: Food exposed to dust, fans in cooler dusty

Back Kitchen

Pots & Pans Sink

No Violations Noted

Heater # 1-4

No Violations Noted

Dry Goods Bins

FC 3-304.12(A)

Preventing Contamination from Utensils: Service utensils handle stored below the

food and container line

**Baking Area** 

No Violations Noted

Handwash Sink # 3

FC 6-501.111(B)

Maintenance and Operations; Pest Control: Flies observed near handwash sink #3

Handwash Sink # 4

Unable to Inspect - Out-of-Order

Serve Line # 2

No Violations Noted

Mechanical Warewash Area

FC 6-501.111(B)\*

Maintenance and Operations; Pest Control: Flying insects observed around warewashing

machine and food digester

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, debris on floor near

food digester

Mechanical Warewash Machine

No Violations Noted

Food Digester

FC 6-304.11\*

Ventilation; Mechanical: Area not properly ventilated, strong odors around digester

Front Kitchen Pots & Pans Sink

FC 6-501.111(B)\*

Maintenance and Operations; Pest Control: Drain flies observed

FC 4-501.114(C)(2)

Maintenance and Operation; Equipment: Quaternary ammonium solution less than the

manufacturers recommended concentration

Rack Spray Area

FC 6-501.11\*

Maintenance and Operation; Repairing: Facility not in good repair, wall paint damaged

Inmate Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Kitchen Staff Break Room

No Violations Noted

Supply Room # 1 (Culinary Arts Supply Room)

No Violations Noted

Supply Room # 2 (Dry Storage Room)

No Violations Noted

Chemical Storage Cabinet

No Violations Noted

Spice Cabinet

No Violations Noted

Daily Cleaning Supply Cabinet

No Violations Noted

Culinary Arts Storage Cabinet

No Violations Noted

Loading Dock

FC 6-202.15(A)(2)\*

Design, Construction, and Installation; Functionality: Outer door not weather and

vermin tight

Spare Kitchen Equipment Room

No Violations Noted

Kitchen Surplus

No Violations Noted

## **Culinary Arts Program Kitchen**

Classroom

No Violations Noted

McCall Refrigerator

No Violations Noted

**Proofers** 

No Violations Noted

Walk-in Freezer

FC 4-501.11(A)\* Maintenance and Operation, Equipment: Equipment not maintained in a state of good

repair, ice build-up observed

**Smokers** 

**Ovens** 

No Violations Noted

Fryolator

No Violations Noted

Skillet

No Violations Noted

Barbecue

No Violations Noted

Handwash Sink

No Violations Noted

3-Bay Sink

No Violations Noted

Prep Sink

No Violations Noted

Prep Tables

No Violations Noted

Walk-in Refrigerator

No Violations Noted

**Health Service Unit** 

ISO # 1 & 2

No Violations Noted

Nurse's Pantry

FC 4-501.11(B) Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, gaskets damaged on refrigerator

Janitor's Closet

No Violations Noted

Risk Cell # 1 & 2

No Violations Noted

Holding Cell # 1-4

No Violations Noted

Ward A

No Violations Noted

Inmate Shower Room

105 CMR 451.123 Maintenance: Soap scum on shower wall 105 CMR 451.123 Maintenance: Soap scum on shower floor 105 CMR 451.123 Maintenance: Debris on shower floor

Nurse's Station and Bathroom

Cleaning Utility Room

No Violations Noted

Storage Room # 1

No Violations Noted

Storage Room # 2

No Violations Noted

Holding

No Violations Noted

Ward B

Unable to Inspect - In Use

Treatment Room # 1

No Violations Noted

Inmate Bathroom 105 CMR 451.123

Maintenance: Debris on floor

Treatment Room # 2

No Violations Noted

Physical Therapy

No Violations Noted

Dental Room

No Violations Noted

Pharmacy

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

105 CMR 480.500(B)(2)\*

Procedures; Records; Record-Keeping Log: Log book not up to date with recent tracking

receipts

Medical Waste Room

Unable to Inspect - Locked

Lab

No Violations Noted

Internal Medicine Office

No Violations Noted

Psychiatry Office

No Violations Noted

Treatment Room #3

No Violations Noted

Exam Room # 1

No Violations Noted

Exam Room # 2

Health Service Administrator's Office

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

105 CMR 451.123

Maintenance: Debris on floor

**OLD BUILDING** 

Main Level

105 CMR 451.350\*

Structural Maintenance: Wall tiles damaged near entrance

Lobby

No Violations Noted

Janitor's Closet

105 CMR 451.344

Illumination in Habitable Areas: Light not functioning properly, light not working

Female Bathroom

Unable to Inspect – In Use

Male Bathroom

105 CMR 451.130\*

Plumbing: No backflow preventer on sink

105 CMR 451.123

Maintenance: Debris on floor

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, drain cover missing in slop sink

Control Area

105 CMR 451.350\* 105 CMR 451.350\* Structural Maintenance: Windows not weathertight and structurally sound Structural Maintenance: Window sills and wall near windows damaged

105 CMR 451.350\*

Structural Maintenance: Several window panes broken

105 CMR 451.353

Interior Maintenance: Ceiling tiles missing

Roll Call Room

No Violations Noted

## **Old Administration Wing**

First Floor

105 CMR 451.353\*

Interior Maintenance: Ceiling tiles missing in hallway

Tool Crib Area

105 CMR 451.353

Interior Maintenance: Floor tiles missing

Tool Crib Bathroom

105 CMR 451.123\*

Maintenance: Sink rusted

Mail Room

Unable to Inspect - Locked

Chemical Area

105 CMR 451.353

Interior Maintenance: Mop left in bucket

Female Bathroom

105 CMR 451.350\*

Structural Maintenance: Windows not weathertight and structurally sound

451-15(1)-Middlesex-Billerica-Report 3-12-15

Page 17 of 26

#### Second Floor

Records Room

No Violations Noted

Male Bathroom

105 CMR 451.123\*

Maintenance: Wall vent missing

105 CMR 451.123

Maintenance: Floor dirty

**Third Floor** 

Male Locker Room

No Violations Noted

Male Locker Room Bathroom

No Violations Noted

Female Locker Room

Unable to Inspect - Locked

Officer's Weight Room

105 CMR 451.353\* 105 CMR 451.353\* Interior Maintenance: Floor paint damaged Interior Maintenance: Ceiling paint peeling

105 CMR 451.350

Structural Maintenance: Window damaged

105 CMR 451.353

Interior Maintenance: Exercise machine padding damaged on multiple machines

**Lower Report** 

A & B Side Cells

Unable to Inspect - No longer in use due to lack of natural lighting

## TRAINING BUILDING

### **First Floor**

Staff Meeting Room

No Violations Noted

Offices and Classroom

No Violations Noted

Library

No Violations Noted

Bathroom and Storage Room

No Violations Noted

#### **Second Floor**

Main Laundry

105 CMR 451.353\*

Interior Maintenance: Wall paint peeling

105 CMR 451.344

Illumination in Habitable Areas: Light not functioning properly, light not working

Inmate Bathroom

Officer's Bathroom

No Violations Noted

Laundry Storage

No Violations Noted

Canteen

105 CMR 451.350\*

Structural Maintenance: Windows not weathertight and structurally sound

Main Level

Old Wing Day Room

105 CMR 451.350\* Structural Maintenance: Windows not weathertight and structurally sound

105 CMR 451.353

Interior Maintenance: Wall damaged

Side Entry Stairs

No Violations Noted

Tier Building Dorm Room

No Violations Noted

Dorm Bathroom

105 CMR 451.130\*

Hot Water: Shower water temperature recorded at 132°F

105 CMR 451.123\*

Maintenance: Soap scum on walls in shower # 4 and 5

First Tier

Common Area

No Violations Noted

Control

No Violations Noted

A & B Side

105 CMR 451.320\*

Cell Size: Inadequate floor space in all cells

Bathroom and Shower Area

105 CMR 451.123\* 105 CMR 451.123\* Maintenance: Soap scum on walls in shower # 1 and 3 Maintenance: Soap scum on floor in shower # 1, 2, 3, and 4

105 CMR 451.123\*

Maintenance: Urinal dirty

105 CMR 451.125\*

Adequate Ventilation: Inadequate ventilation

105 CMR 451.123

Maintenance: Floor dirty in shower # 11

105 CMR 451.123

Maintenance: Debris on floor in shower # 1, 3, 4, 5, and 6

C & D Side (Administrative Segregation and Segregation Unit)

105 CMR 451.320\*

Cell Size: Inadequate floor space in all cells

105 CMR 451.141

Screens: Hallway screen missing

105 CMR 451.350

Structural Maintenance: Wall damaged outside cell # D13

Shower Room # D23

105 CMR 451.140\*

Adequate Ventilation: Inadequate ventilation

105 CMR 451.123\*

Maintenance: Ceiling paint peeling

105 CMR 451.123

Maintenance: Debris on floor

#### **Second Tier**

Common Area

No Violations Noted

Control

No Violations Noted

E & F Side

Cell Size: Inadequate floor space in all cells 105 CMR 451.320\*

Interior Maintenance: Wall paint damaged in cell # E2, E14, F3, F7, and F19 105 CMR 451.353\*

Mattresses: Mattress damaged in cell # F25 105 CMR 451.103

Bathroom and Shower Area

Maintenance: Ceiling paint damaged in shower # 1 105 CMR 451.123\*

Maintenance: Soap scum on walls in shower # 1, 2, 3, 4, 6, 8, 9, and 11 105 CMR 451.123\* Maintenance: Soap scum on floors in shower # 1, 3, 4, 5, 6, 8, 9, and 11

105 CMR 451.123\* Maintenance: Bottom of partitions damaged between shower # 4, 5, and 6

105 CMR 451.123\*

Maintenance: Debris on floor in shower #7 and 11 105 CMR 451.123

Janitorial Cage

No Violations Noted

G & H Side

No Violations Noted

Gym

Structural Maintenance: Windows not weathertight and structurally sound 105 CMR 451.350\*

Interior Maintenance: Ceiling left unfinished 105 CMR 451.353

Gym Office

Structural Maintenance: Floor tiles missing 105 CMR 451.350\*

Interior Maintenance: Ceiling dirty 105 CMR 451.353\*

Screens: Screen missing 105 CMR 451.141

Staff Bathroom

Maintenance: Floor tiles damaged 105 CMR 451.123\* Maintenance: Floor tiles missing 105 CMR 451.123

Stairway to Third Tier

Interior Maintenance: Ceiling paint peeling 105 CMR 451.353\*

**Third Tier** 

Common Area

No Violations Noted

Control

No Violations Noted

Offices

1 & J Side

105 CMR 451.350\* Structural Maintenance: Windows not weathertight and structurally sound in

cell # I1-I24 and J1-J26

105 CMR 451.350 Structural Maintenance: Center window missing in cell # I1-I24 and J1-J26

Bathroom and Shower Area

105 CMR 451.123\* Maintenance: Caulking damaged around sink

105 CMR 451.123\* Maintenance: Toilet dirty 105 CMR 451.123\* Maintenance: Urinal dirty

105 CMR 451.123 Maintenance: Debris on floor in shower # 2, 3, 8, 9, 10, and 11

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # 2,

4, and 6

105 CMR 451.123 Maintenance: Ceiling vent dusty

105 CMR 451.123 Maintenance: Ceiling paint peeling in shower # 7 105 CMR 451.123 Maintenance: Slop sink drain cover missing

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, slop sink leaking

105 CMR 451.123 Maintenance: Sock tied around faucet on slop sink

Janitor's Closet

105 CMR 451.353\* Interior Maintenance: Floor surface damaged

105 CMR 451.344 Illumination in Habitable Areas: Light not functioning properly, light not working

K & L Side

105 CMR 451.353 Interior Maintenance: Multiple cell windows painted

105 CMR 451.141 Screens: Hallway screen damaged

## **CWP BUILDING**

## First Floor

Entrance

No Violations Noted

Control

No Violations Noted

Officer's Bathroom

105 CMR 451.123\*

Maintenance: Light shield missing

Caseworker's Office

Unable to Inspect – In Use

Teacher's Office

Unable to Inspect – Locked

Closet

No Violations Noted

#### **Food Service Area**

Dining Room

105 CMR 451.331 Radiators and Heating Pipes: Pipes not properly insulated near ice machine

Kitchen FC 6-501.12(A)* FC 6-501.11*	Maintenance and Operation; Cleaning: Facility not cleaned properly, vent fan dirty Maintenance and Operation; Repairing: Facility not in good repair, floor surface damaged throughout kitchen
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, ceiling paint peeling above 3-bay sink
FC 4-501.11(B)*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged on hot holding unit
FC 4-501.11(B)*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged on Traulsen refrigerator
FC 4-601.11(A)*	Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, can opener dirty
FC 6-202.11(A)*	Design, Construction, and Installation; Functionality: Light bulbs not shatter-resistant or protected by light shields in closet
FC 4-903.11(A)(2)	Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils not covered
FC 3-305.11(A)(3)	Preventing Contamination from Premises: Food stored in an inappropriate location, food stored less than 6 inches from the floor

# **Inmate Housing Area**

Shower and Bathroom	
105 CMR 451.123*	Maintenance: Vent fan dirty
105 CMR 451.123*	Maintenance: Standing water in shower area
105 CMR 451.123*	Maintenance: Heat vents under sink rusted
105 CMR 451.123	Maintenance: Urinal # 1 out-of-order
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal # 1 leaking
Supply Cage	
77.	No Violations Noted
Hallway	
·	No Violations Noted
Laundry Area	
105 CMR 451.350*	Structural Maintenance: Wall not weathertight and structurally sound, old ventilation
	hole not covered
105 CMR 451.353*	Interior Maintenance: Debris and lint behind machines
105 CMR 451.331	Radiators and Heating Pipes: Pipes not properly insulated
105 CMR 451.353	Interior Maintenance: Debris and lint on floor in front of dryers

# Recreational and Weight Room

No Violations Noted

# **Second Floor**

Hallway 105 CMR 451.353*	Interior Maintenance: Standing water in bucket from hot water dispenser
Bathroom 105 CMR 451.123*	Maintenance: Vent fan dirty
105 CMR 451.123*	Maintenance: Floor paint damaged
105 CMR 451.123	Maintenance: Ceiling left unfinished, painting not complete
Plaza # 1 105 CMR 451.353	Interior Maintenance: Wall paint peeling

451-15(1)-Middlesex-Billerica-Report 3-12-15

105 CMR 451.103

Mattresses: Mattress damaged at bed #7

Plaza # 2

105 CMR 451.141

Screens: Screens missing from several windows

Plaza # 3

105 CMR 451.322\*

Cell Size: Inadequate floor space in dorm rooms

Room # 1

105 CMR 451.350\*

Structural Maintenance: Wall damaged

Room # 2

105 CMR 451.353\*

Interior Maintenance: Wall paint damaged

Room # 3

105 CMR 451.353\*

Interior Maintenance: Wall paint damaged

**Room #4** 

No Violations Noted

Room #5

No Violations Noted

**Room #6** 

No Violations Noted

Room # 7

No Violations Noted

**Room #8** 

No Violations Noted

**Room #9** 

No Violations Noted

Room # 10

No Violations Noted

## WORK RELEASE BUILDING

# House #1

## **First Floor**

Hallway

105 CMR 451.353\*

Interior Maintenance: Wall paint damaged near phones

Control

FC 4-501.11(B)

Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, gaskets damaged on refrigerator unit

Office

No Violations Noted

Bathroom

105 CMR 451.123\*

Maintenance: Ceiling tiles water damaged

451-15(1)-Middlesex-Billerica-Report 3-12-15

**Bedrooms** 

No Violations Noted

**Food Service Area** 

Dining Room

FC 4-602.12(B)\*

Cleaning of Equipment and Utensils; Frequency: Interior of toaster over dirty

Kitchen

FC 6-501.14(A)\*

Maintenance and Operation; Cleaning: Ventilation Systems, ventilation hoods dirty

**Second Floor** 

Stairway

No Violations Noted

Hallway

No Violations Noted

**Bedrooms** 

No Violations Noted

**Bathroom** 

No Violations Noted

Stairway to Basement

No Violations Noted

**Basement** 

Laundry Room

No Violations Noted

Boiler Room

No Violations Noted

Chemical Storage Room

No Violations Noted

**Day Room Between Houses** 

No Violations Noted

House # 2

**First Floor** 

Officer's Bathroom

No Violations Noted

**Bedrooms** 

No Violations Noted

**Second Floor** 

Hallway

Bathroom

105 CMR 451.123

Maintenance: Sink basin dirty

**Bedrooms** 

No Violations Noted

**Third Floor** 

Bedrooms

Unable to Inspect – Not in Use

**Basement** 

Day Room

105 CMR 451.141 105 CMR 451.141 Screens: Screen damaged Screens: Screen not secure

Bathroom

105 CMR 451.123\* 105 CMR 451.123 Maintenance: Shower wall tiles damaged in shower # 1 Maintenance: Debris on floor in shower # 1, 3, and 4

**WAREHOUSE** 

105 CMR 451.350

Structural Maintenance: Exterior door not weathertight

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Walk-in Freezer

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good

repair, 1 light out

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good

repair, damaged insulation on pipe

## **Observations and Recommendations**

1. The inmate population was 990 at the time of inspection.

2. The kitchen exhaust system was not in compliance with the provisions for inspection, cleaning and labeling required by 527 CMR 11.00 Commercial Cooking Operations. The Department recommends you contact the Department of Fire Services for further information.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451,404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at <a href="www.mass.gov/dph/dcs">www.mass.gov/dph/dcs</a> and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at <a href="www.mass.gov/dph/fpp">www.mass.gov/dph/fpp</a> and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X – Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

To review the Labeling regulations please visit the Food Protection website at <a href="www.mass.gov/dph/fpp">www.mass.gov/dph/fpp</a> and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,

Jonathan Brown

Environmental Health Inspector, CSP, BEH

cc: Suzanne K. Condon, Associate Commissioner, Director, BEH

Steven Hughes, Director, CSP, BEH

Jay Youmans, Director of Government Affairs

Marylou Sudders, Secretary, Executive Office of Health and Human Services

Carol Higgins O'Brien, Commissioner, DOC

Sean McAdam, Superintendent

Richard Vivier, Deputy Superintendent

Captain William Buckley, EHSO

Sergeant Rudy Chaput, EHSO

Richard Berube, Director, Billerica Board of Health

Clerk, Massachusetts House of Representatives

Clerk, Massachusetts Senate

Andrea Cabral, Secretary, EOPS