

CHARLES D. BAKER Governor

KARYN E. POLITO Lieutenant Governor The Commonwealth of Massachusetts Executive Office of Health and Human Services Department of Public Health Bureau of Environmental Health Community Sanitation Program 180 Beaman Street, West Boylston, MA 01583 Phone: 508-792-7880 Fax: 508-792-7706 TTY: 508-835-9796

MARYLOU SUDDERS Secretary

MONICA BHAREL, MD, MPH Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

January 31, 2017

Peter J. Koutoujian, Sheriff Middlesex County Sheriff's Office 400 Mystic Avenue Medford, MA 02155

Re: Facility Inspection - Middlesex County Jail and House of Corrections, Billerica

Dear Sheriff Koutoujian:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Middlesex County Jail and House of Corrections on January 18, 19, and 20, 2017 accompanied by Sergeant Shane Cassidy, EHSO and Captain William Buckley, EHSO. Violations noted during the inspection are listed below including 92 repeat violations:

#### HEALTH AND SAFETY VIOLATIONS

(\* indicates conditions documented on previous inspection reports)

#### **CHECKPOINT BUILDING**

<i>Janitor's Closet</i> 105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
Male Bathroom	No Violations Noted
Female Bathroom	No Violations Noted
Control Desk	No Violations Noted
NEW BUILDING	
Lobby	No Violations Noted

Water Fountain	No Violations Noted
Female Bathroom	No Violations Noted
Male Bathroom	No Violations Noted
Janitor's Closet 105 CMR 451.353	Interior Maintenance: Mop stored in bucket
Administration Wing	
Female Bathroom	No Violations Noted
Male Bathroom	No Violations Noted
Janitor's Closet	No Violations Noted
Kitchenette	No Violations Noted
Visiting Area	
Visitor's Side	No Violations Noted
Central Control	No Violations Noted
Bathroom	No Violations Noted
Attorney Visit Hallway	
Janitor's Closet 105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, 1 light out
Male Bathroom	No Violations Noted
Female Bathroom	No Violations Noted
Visiting Control Room	No Violations Noted
Inmate Bathroom 105 CMR 451.123	Maintenance: Ceiling vent dusty
Urinalyses Room	Unable to Inspect – Locked

usert seksu∰utikand dikan sesses an ana sesses kikadatan ta at

# Visiting Area – Inmate Side

uran Antitas A Mara ur

#### No Violations Noted

# Entrance Hallway for Pod A & B

Nurse's Station	Unable to Inspect – Locked
Female Bathroom	No Violations Noted
Male Bathroom	No Violations Noted
Janitor's Closet	Unable to Inspect – Locked
Caseworker's Office	No Violations Noted
Pod A	
Common Area	No Violations Noted
Storage Cage (Barber Shop)	No Violations Noted
Janitor's Closet	No Violations Noted
Storage Room	No Violations Noted
Lower Level Shower Area # 1-5 105 CMR 451.123 105 CMR 451.123 105 CMR 451.124	Maintenance: Ceiling paint damaged around light fixture in shower # 1-5 Maintenance: Shower # 1, 2, and 5 out-of-order Water Supply: Insufficient water supply in quantity and pressure in shower unit # 3
<i>Lower Cells</i> 105 CMR 451.113*	Toilet and Handwashing Sink in Locked Cells: No hot running water in locked
105 CMR 451.113	cell # 1-24 Toilet and Handwashing Sink in Locked Cells: No hot running water in locked
105 CMR 451.130	cell # 1-10 Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # 1-27
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink in cell # 1-15
105 CMR 451.126 105 CMR 451.126 105 CMR 451.353* 105 CMR 451.353	Hot Water: Hot water temperature recorded at $68^{\circ}$ F in cell # 1-15 Hot Water: Hot water temperature recorded at $104^{\circ}$ F in cell # 1-27 Interior Maintenance: Floor paint damaged in cell # 1-13 and 1-23 Interior Maintenance: Floor paint damaged in cell # 1-32

#### 11 - 10 1 01 , ----

e eret are tare a utilitated advances of a contract of the statement of the

Upper Level Shower Area # 6-	
105 CMR 451.123	Maintenance: Ceiling paint damaged outside shower # 6, 7, and 8
105 CMR 451.123	Maintenance: Shower # 9 out-of-order
105 CMR 451.126	Hot Water: Hot water temperature recorded at $90^{0}$ F at shower # 10
105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure in shower # 10
105 CMR 451.123	Maintenance: Flies observed in shower # 10
105 CMR 451.123	Maintenance: Handwash sink not draining properly near shower # 10
Upper Cells	
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 2-17 and 2-31
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, water continually running in cell # 2-30
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink not draining properly in cell # 2-30
Pod B	
Common Area	
	No Violations Noted
Counselor's Office	
	No Violations Noted
Storage Cage (Barber Shop)	
	No Violations Noted
Janitor's Closet	
105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light out
Storage Room (Small)	
105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
Storage Room (Large)	
	No Violations Noted
Lower Level Shower Area	
105 CMR 451.123	Maintenance: Shower # 4 out-of-order
105 CMR 451.123	Maintenance: Mold observed on ceiling in shower # 1
105 CMR 451.123	Maintenance: Ceiling paint damaged outside shower # 1-5
Lower Cells	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # 1-11
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink in cell # 1-03
105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 1-25
Upper Level Shower Area	
105 CMR 451.123*	Maintenance: Caulking damaged around handwash sink
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 6
105 CMR 451.123	Maintenance: Ceiling paint damaged outside shower # 6
105 CMR 451.123	Maintenance: Shower # 8 out-of-order

<i>Upper Cells</i> 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, water continually running in cell # 2-23
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # 2-01
Entrance Hallway for Pod C &	<u>&amp; D</u>
Nurse's Station	No Violations Noted
Female Bathroom	No Violations Noted
Male Bathroom	Unable to Inspect – In Use
Office	No Violations Noted
Pod C	
Common Area 105 CMR 451.353	Interior Maintenance: Floor paint damaged
<i>Storage Cage (Barber Shop)</i> 105 CMR 451.353* 105 CMR 451.353* 105 CMR 451.124	Interior Maintenance: Partition underneath countertop deteriorating Interior Maintenance: Floor paint damaged near handwash sink Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink with counter top
Janitor's Closet 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing from slop sink
Storage Room	No Violations Noted
Counselor/Interview Office	No Violations Noted
Multi-Purpose Room	No Violations Noted
Lower Level Shower Area 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.124	Unable to Inspect Shower # 3 – In Use Maintenance: Soap scum on walls in shower # 1 Maintenance: Flies observed in shower # 4 Maintenance: Debris on floor in shower # 1 Maintenance: Lower shower head not functioning in shower # 5 Water Supply: Insufficient water supply in quantity in shower # 2

a tradice 🛓 glitic d'aposta a construction de la destruction e act

Lower Cells	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, hot water continually running in
	cell # 1-06
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # 1-30
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water continually running in
	cell # 1-15 and 1-19
105 CMR 451.113*	Toilet and Handwashing Sink in Locked Cells: No cold running water in locked cell # 1-06
105 CMR 451.113	Toilet and Handwashing Sink in Locked Cells: No cold running water in locked cell # 1-23
105 CMR 451.113	Toilet and Handwashing Sink in Locked Cells: No hot running water in locked cell # 1-24
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink in cell # 1-27
Upper Level Shower Area # 6-	10
105 CMR 451.123	Maintenance: Shower # 7 and 10 out-of-order
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 6 and 8
105 CMR 451.123	Maintenance: Flies observed outside shower # 6 and 8
105 CMR 451.123	Maintenance: Debris on floor outside shower # 8
105 CMR 451.126	Hot Water: Hot water temperature recorded at $90^{\circ}$ F in shower # 6
Upper Cells	
105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 2-25
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 2-26
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink not draining properly in cell # 2-05
105 CMR 451.113*	Toilet and Handwashing Sink in Locked Cells: No hot running water in locked cell # 2-29
Pod D	
Common Area	
105 CMR 451.353	Interior Maintenance: Floor tiles missing
Storage Cage (Barber Shop)	No Violations Noted
Janitor's Closet 105 CMR 451.130* 105 CMR 451.353	Plumbing: Plumbing not maintained in good repair, drain cover missing on slop sink Interior Maintenance: Wet mop stored in bucket
Multi-Purpose Room	
	No Violations Noted
Storage Room	
	No Violations Noted
Lower Level Shower Area	Unable to Inspect Shower # 1 – In Use

Unable to Inspect Shower # 1 – In Use No Violations Noted

counterf induced affined where in a contract of data function good

Lower Cells	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, cold water continually running in cell # 1-08
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water continually running in cell # 1-17, 1-21, and 1-24
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # 1-25
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, sink not draining properly in cell # 1-22
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 1-07
Upper Level Shower Area	
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 4
105 CMR 451.123*	Maintenance: Soap scum on floor in shower # 3 and 4
105 CMR 451.126	Hot Water: Hot water temperature recorded at 92°F at shower # 5
105 CMR 451.123	Maintenance: Drain flies observed in shower # 2, 3, and 4
<i>Upper Cells</i> 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, water continually running in
	cell # 2-26
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # 2-01
105 CMR 451.113*	Toilet and Handwashing Sink in Locked Cells: No hot running water in locked cell # 2-06
105 CMR 451.113	Toilet and Handwashing Sink in Locked Cells: No hot running water in locked cell # 2-03, 2-04, and 2-25
105 CMR 451.113*	Toilet and Handwashing Sink in Locked Cells: No cold running water in locked cell # 2-28
105 CMR 451.113	Toilet and Handwashing Sink in Locked Cells: No cold running water in locked cell # 2-03, 2-04, and 2-25
105 CMR 451.124	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink in cell # 2-05 and 2-29
105 CMR 451.353	Interior Maintenance: Floor tiles missing outside upper level cells
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 2-21
<u>Pod F</u>	
Female Staff Bathroom	No Violations Noted
Janitor's Closet	
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light not working
Male Staff Bathroom	
	No Violations Noted
Administration Area	No Violations Noted
Medical Office	<b>**</b> . <b>**</b>
105 CMR 451.126	Hot Water: Hot water temperature recorded at 95°F at handwash sink
Block	
Janitor's Closet	

No Violations Noted

Protection of the state of the

Barber Shop	Unable to Inspect – In Use
Storage	No Violations Noted
Lower Showers	Unable to Inspect Shower # 3 – In Use No Violations Noted
Lower Cells	No Violations Noted
Assessment Office 105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, coffee pot dirty
Library/Multi-Purpose Room	No Violations Noted
Case Worker's Office	No Violations Noted
Upper Cells	No Violations Noted
Upper Showers # 1-10 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # 9 Maintenance: Dead flies observed on ceiling in shower # 8, 9, and 10 Maintenance: Soap scum on walls in shower # 10
Common Area	No Violations Noted
Dorm # 3 and 4 Landing	
Male Bathroom	Unable to Inspect – In Use
Female Bathroom	Unable to Inspect - Locked
Janitor's Closet	No Violations Noted
Storage/Med Pass	No Violations Noted
Medical Office	No Violations Noted
Classroom # 2	No Violations Noted

and the state of a state of a state of the state of the state of the state of the

Multi-Purpose Hallway	
Storage Room # 1 and 2	No Violations Noted
Classroom A and B	No Violations Noted
Dorm # 3	
Sleeping Area 105 CMR 451.103	Mattresses: Mattress damaged at bed # 24
Common Area	No Violations Noted
<i>Toilet Area</i> 105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash
105 CMR 451.124*	sink # 3 and 5 Water Supply: Insufficient hot water supply in quantity and pressure at handwash
105 CMR 451.124	sink # 7 Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink # 3, 5, and 6
Sink Area	No Violations Noted
<i>Shower Area</i> 105 CMR 451.126	Hot Water: Hot water temperature recorded at $80^{0}$ F at shower # 1
Janitor's Closet	No Violations Noted
<i>Case Worker's Office</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, silverware left uncovered
Barber Shop	No Violations Noted
Dorm # 4	
Barber Shop	No Violations Noted
Case Worker's Office	Unable to Inspect – In Use
Janitor's Closet	No Violations Noted
Shower Area	No Violations Noted

<i>Toilet Area</i> 105 CMR 451.124	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink $#2, 3, 4, 6$ and 7
105 CMR 451.124	sink # 2, 3, 4, 6, and 7 Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink # 2, 4, and 7
105 CMR 451.126	sink # 3, 4, and 7 Water Supply: No hot and cold water supplied to handwash sink # 1
<i>Sink Area</i> 105 CMR 451.123 105 CMR 451.126	Maintenance: Hand dryer out-of-order Hot Water: Hot water temperature recorded at 70°F at handwash sink # 3
Common Area	No Violations Noted
Sleeping Area	No Violations Noted
Pod E	
Administration Area	
Female Staff Bathroom	No Violations Noted
Janitor's Closet	No Violations Noted
Male Staff Bathroom	No Violations Noted
Offices	No Violations Noted
Nurse's Station	No Violations Noted
Block	
Janitor's Closet 105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
Barber Shop 105 CMR 451.353	Interior Maintenance: Handwash sink dirty
Storage Room	No Violations Noted
Segregation Showers 105 CMR 451.123 105 CMR 451.126	Maintenance: Debris on floor in shower # 2 and 4 Hot Water: Hot water temperature recorded at $90^{\circ}$ F in shower # 6
Segregation Cells 105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 1-30
Classroom Assessment	No Violations Noted

Library	No Violations Noted
Caseworker's Office	No Violations Noted
Upper Cells	No Violations Noted
Upper Showers 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123	Maintenance: Soap scum on walls and floor in shower # 8, 9, and 10 Maintenance: Black substance observed on walls in shower # 4 Maintenance: Black substance observed on walls in shower # 5 Maintenance: Drain flies observed in shower # 3, 8, 9, and 10
Dorm # 1 and 2 Landing	
Shift Administrator's Office	No Violations Noted
Janitor's Closet	No Violations Noted
Male Staff Bathroom	No Violations Noted
Female Staff Bathroom	Unable to Inspect - Locked
Storage/Med Pass	Unable to Inspect – Locked
Medical Office	Unable to Inspect – Locked
Classroom # 1	No Violations Noted
Dorm # 1	
Sleeping Area	No Violations Noted
Common Area	No Violations Noted
Toilet Area	
105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure at handwash sink # 3, 4, 5, and 7
105 CMR 451.126*	Water Supply: No cold water supplied to handwash sink # 6
105 CMR 451.126	Water Supply: No cold water supplied to handwash sink # 8
105 CMR 451.123	Maintenance: Handwash sink dirty in stall # 8
105 CMR 451.123	Maintenance: Toilet # 8 out-of-order
<i>Sink Area</i> 105 CMR 451.126	Water Supply: No hot water supplied to handwash sink # 3
105 CIVIL TJ1.120	water suppry. No not water supplied to natiowasit slift # 5

451-17(1)-Middlesex-Billerica-Report 1-31-17

- 1 va. Següre 4 alam - 1 -

<i>Shower Area</i> 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Soap scum observed on walls in shower # 2 Maintenance: Soap scum observed on floor in shower # 1 Maintenance: Mold observed on caulking around shower controls in shower # 1
Janitor's Closet	No Violations Noted
Case Worker's Office	No Violations Noted
Barber Shop	No Violations Noted
Dorm # 2	
Barber Shop	No Violations Noted
Case Worker's Office	No Violations Noted
Janitor's Closet	No Violations Noted
<i>Shower Area</i> 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Mold observed on caulking in shower # 7 and 8 Maintenance: Soap scum observed on walls in shower # 3, 4, 5, and 7 Maintenance: Floor dirty in shower # 8
<i>Toilet Area</i> 105 CMR 451.123 105 CMR 451.126* 105 CMR 451.124*	Maintenance: Toilet # 2, 3, and 7 out-of-order Water Supply: No hot water supplied to handwash sink # 1 Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink # 1 and 6
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink # 5 and 7
105 CMR 451.124*	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink # 4
105 CMR 451.124	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink # 5, 6, and 8
<i>Sink Area</i> 105 CMR 451.123	Maintenance: Handwash sink # 3 out-of-order
Common Area	No Violations Noted
Sleeping Area	No Violations Noted
Intake and Discharge	
Janitor's Closet	No Violations Noted

and received about a low an

Administrative Office	No Violations Noted	
Holding Tank # 2	No Violations Noted	
Shake Room # 1 & 2	No Violations Noted	
Holding Cell # 1 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, water continually runnin	ıg
Institutional Property 105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light out	
Desk Area	No Violations Noted	
Sally Port	No Violations Noted	
Old Shower Room # 1	No Violations Noted	
Holding Cell # 1-6 105 CMR 451.140 105 CMR 451.130	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 1 Plumbing: Plumbing not maintained in good repair, cold water continually ru # 2	unning in cell
105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 4	
<i>Break Room</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance 105 CMR 590.000, interior of microwave oven dirty	with
Male Bathroom	No Violations Noted	
Female Bathroom 105 CMR 451.123	Maintenance: Bathroom out-of-order	
Inmate Property Room	No Violations Noted	
Change Room #1 and 2	No Violations Noted	
<u>A &amp; B Hall Entrance</u>		
Janitor's Closet	Unable to Inspect - Locked	
Teacher's Office	No Violations Noted	
Hall A	No Violations Noted	
451-17(1)-Middlesex-Billerica-R		ge 13 of 28

Hall B	No Violations Noted
Food Service Area	
<i>Staff Dining Room</i> FC 3-306.11	Preventing Contamination from Consumer: Food display not protected by an
FC 3-501.16(A)	appropriate guard, sliced cake not kept under appropriate food guards Limitation of Growth of Organisms, Temperature and Time Control: Potentially hazardous food not held at the proper hot holding temperature, mashed potatoes temperature recorded at 104°F
Male Bathroom	No Violations Noted
Female Bathroom	No Violations Noted
Supply Dock	
Loading Dock	No Violations Noted
Surplus Storage Room	No Violations Noted
Storage Room	No Violations Noted
Back of Kitchen	
Supply Room # 2 (Dry Storage) FC 3-304.12(A)	Preventing Contamination from Utensils: Service utensils handle stored below the food and container line, scoop stored in cereal container
Culinary Arts Storage Cabinet	Unable to Inspect - Locked
Chemical Supply Closet	No Violations Noted
Daily Cleaning Cabinet	No Violations Noted
Kitchen Staff Break Room	No Violations Noted
<i>Inmate Bathroom</i> 105 CMR 451.124 105 CMR 451.123	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink Maintenance: Unlabeled chemical bottle
Staff Bathroom	No Violations Noted
Rack Spray Area	No Violations Noted

 $\sim$  , we set that  $\frac{1}{2} \sqrt{2} \left( \frac{1}{2} \left( \frac{1}{2} + \frac{1}{2} \right) \right) \left( \frac{1}{2} + \frac{$ 

# Main Kitchen Area

Cooler # 1	
	No Violations Noted
Warmer #1 and 2	
FC 4-501.11(B)	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged on warmer # 2
Old Serving Line	
	No Violations Noted
Handwash Sink – Near Pots and	d Pans Sink
FC 6-501.11	Maintenance and Operation; Repairing: Facility not in good repair, floor tiles damaged around floor drain
Pots and Pan Sink	
FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, 3-bay sink faucet leaking
Mechanical Warewash Area	
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, floor tiles damaged around tables
Warewash Machine	
FC 4-501.112(A)(2)*	Maintenance and Operation, Equipment: Inadequate water temperature in the mechanical warewashing machine
Handwash Sink after Warewash	Machine
iiunuwush shik ujici n'u cwush	No Violations Noted
Inmate Coffee Area	
FC 3-302.11(A)(4)	Preventing Food and Ingredient Contamination: Preventing cross contamination, food not
	appropriately covered, sugar container left uncovered
FC 4-903.11(A)(2)*	Protection of Clean Items, Storing: Single-service items not protected from contamination, disposable silverware left uncovered
Serving Line # 2	
200 100 2000 10 2	No Violations Noted
Warmer # 3 and 4	
	No Violations Noted
Refrigerator # 2	
	No Violations Noted
McCall Proofer # 1	
<i>o</i> –	No Violations Noted
3 Warmers (under hoods)	
	No Violations Noted

Prep Tables and Sinks FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in
FC 5-205.15(B)	good repair, no cold water supplied to 3-bay sink near warmers Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, handwash sink near 3-bay out-of-order
Ice Machine # 3	No Violations Noted
Ice Machine # 2	No Violations Noted
Handwash Sink (after ice mach	
	No Violations Noted
Kettle Area	No Violations Noted
<i>Walk-in Refrigerator # 2</i>	No Violations Noted
Spice Cabinet FC 3-304.12(A)	Preventing Contamination from Utensils: Service utensils handle stored below the food and container line, scoop left in container
<i>Walk-in Refrigerator</i> # 1	No Violations Noted
<i>Hood Area with Warmers</i> FC 6-501.11	Maintenance and Operation; Repairing: Facility not in good repair, 2 lights not working under hoods
Walk-in Freezer	No Violations Noted
Ice Machine # 1	No Violations Noted
Sallyport/Changing Area	No Violations Noted
Janitor's Closet	No Violations Noted
<i>Officer's Area/Office</i> 105 CMR 590.009(G)(3)(b)(1)	Special Requirements: Food Allergen Awareness Training, no prominently posted food allergen awareness training certificate
Culinary Arts Program Kitch	en
Classroom	No Violations Noted
McCall Refrigerator	No Violations Noted

unite international address in the contract of the destruction of

<i>Proofers</i> FC 4-501.11(B)* FC 4-501.11(B)	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged on warmer # 1 Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged on warmer # 2
Walk-in Freezer	No Violations Noted
Hood Area	No Violations Noted
Handwash Sink	No Violations Noted
3-Bay Sink	No Violations Noted
Prep Sink	No Violations Noted
Prep Tables	No Violations Noted
Walk-in Refrigerator	No Violations Noted
Health Service Unit	
<i>ISO # 1 &amp; 2</i> 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, water continually running at handwash sink in ISO # 1
Nurse's Pantry	No Violations Noted
Janitor's Closet	No Violations Noted
Risk Cell # 1 & 2	No Violations Noted
Private Rooms # 1-4 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, water continually running at handwash sink in room # 3
Ward A	No Violations Noted
Storage Room	No Violations Noted
Handicap Shower Room 105 CMR 451.123* 105 CMR 451.126	Maintenance: Soap scum on walls in shower Water Supply: No cold water supplied to handwash sink

and also kuista kuista kuista aa aasaa aa kaasaa aa

Nurse's Station and Bathroom	No Violations Noted
Cleaning Utility Room	No Violations Noted
Storage Room # 1	No Violations Noted
Storage Room # 2	No Violations Noted
Holding	No Violations Noted
Ward B	Unable to Inspect – In Use
Treatment Room # 1	No Violations Noted
Inmate Bathroom	No Violations Noted
Treatment Room # 2	No Violations Noted
Medical Waste Storage 105 CMR 480.300(B)	Packaging, Labeling, and Shipping: Medical and biological waste not placed in secondary containers
Physical Therapy (Treatment R	oom # 4) No Violations Noted
Dental Room	No Violations Noted
Pharmacy	No Violations Noted
Janitor's Closet 105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out
Lab	No Violations Noted
Infectious Disease Office	No Violations Noted
Psychiatry Office	No Violations Noted
Treatment Room # 3	No Violations Noted

Coordinator's Office	No Violations Noted
Exam Room # 1	
Exam Room # 2	No Violations Noted
Exum Room # 2	No Violations Noted
Health Service Administrator's	Office No Violations Noted
Female Bathroom	No Violations Noted
Male Bathroom	No Violations Noted
Medical Records	No Violations Noted
<b>Classifications Building</b>	
Main Level	
Lobby	No Violations Noted
Janitor's Closet	No Violations Noted
<i>Female Bathroom</i> 105 CMR 451.123* 105 CMR 451.123*	Maintenance: Toilet # 2 out-of-order Maintenance: Window broken
<i>Male Bathroom</i> 105 CMR 451.130* 105 CMR 451.130* 105 CMR 451.124	Plumbing: No backflow preventer on sink Plumbing: Plumbing not maintained in good repair, drain cover missing in slop sink Water Supply: Insufficient cold water supply in quantity and pressure at slop sink
Control Area 105 CMR 451.350* 105 CMR 451.350* 105 CMR 451.350* 105 CMR 451.353*	Structural Maintenance: Windows not weathertight and structurally sound Structural Maintenance: Window sills and wall near windows damaged Structural Maintenance: Several window panes broken Interior Maintenance: Ceiling tiles missing
Roll Call Room	No Violations Noted
Old Administration Wing	
First Floor	
Offices	No Violations Noted

. The state of the state of the second seco

Storage Closet	No Violations Noted
Tool Crib Area	
1001 CHU Areu	No Violations Noted
<i>Tool Crib Bathroom</i> 105 CMR 451.123* 105 CMR 451.353*	Maintenance: Sink rusted Interior Maintenance: Light shield missing
<i>Mail Room</i> 105 CMR 451.353* 105 CMR 451.200	Interior Maintenance: Ceiling tiles missing Food Storage, Preparation and Service: Food storage not in compliance with
105 CMR 451.200	105 CMR 590.000, excessive ice buildup in freezer
Canteen Area 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, canteen bags stored on floor
Female Bathroom 105 CMR 451.123*	Maintenance: Windows not weathertight
Second Floor	
<i>Male Bathroom # 2</i> 105 CMR 451.123 105 CMR 451.126	Maintenance: Ceiling tiles water damaged Hot Water: Hot water temperature recorded at 92°F at handwash sink # 1
New Male Locker Room	No Violations Noted
Male Locker Room Bathroom 105 CMR 451.123 105 CMR 451.123	Maintenance: Window broken Maintenance: Water stained ceiling tiles
Male Shower Room	No Violations Noted
<b>Old Infirmary</b> 105 CMR 451.353	Interior Maintenance: Ceiling tiles missing
Offices	No Violations Noted
Female Bathroom 105 CMR 451.123	Maintenance: Wall damaged around window
Male Bathroom # 1 105 CMR 451.123* 105 CMR 451.124 105 CMR 451.123	Maintenance: Window broken Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink Maintenance: Wall paint damaged
Old Shower Room	No Violations Noted

und standaldad dagents in survivor dagenara e a in

<i>Staff Break Room</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance v 105 CMR 590.000, uncovered silverware	vith
105 CMR 451.353	Interior Maintenance: Wall paint damaged	
Offices	No Violations Noted	
Third Floor		
Male Locker Room	No Violations Noted	
Male Locker Room Bathroom 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Window broken Maintenance: Wall paint damaged near soap dispenser # 3 Maintenance: Floor paint damaged Maintenance: Handwash sink # 3 dirty Maintenance: Toilet # 2 dirty Maintenance: Soap scum observed on walls in shower # 1 and 2 Maintenance: Light out in shower # 2	
Female Locker Room	Unable to Inspect - Locked	
Officer's Weight Room 105 CMR 451.350* 105 CMR 451.353 105 CMR 451.124	Structural Maintenance: Window damaged Interior Maintenance: Hole in wall near slop sink Water Supply: Insufficient water supply in quantity and pressure at slop s	sink
Lower Report		
A & B Side Cells	Unable to Inspect – No longer in use due to lack of natural lighting	
<b>Training Center</b>		
First Floor		
Barber Area	No Violations Noted	
<i>Library</i> 105 CMR 451.350	Structural Maintenance: Window pane missing	
Meeting Room	No Violations Noted	
Offices and Classroom	No Violations Noted	
Bathroom 105 CMR 451.123*	Maintenance: Window broken	
Storage Room 105 CMR 451.130	Plumbing: No backflow preventer on slop sink	
451-17(1)-Middlesex-Billerica-Rep	port 1-31-17	Page

and the second second second

# Chapel

and a strategy framework.

### No Violations Noted

#### **Second Floor**

<i>Main Laundry</i> 105 CMR 451.350*	Structural Maintenance: Window broken
Inmate Bathroom 105 CMR 451.350*	Structural Maintenance: Window broken
<i>Officer's Bathroom</i> 105 CMR 451.123 105 CMR 451.123* 105 CMR 451.124	Maintenance: Wall paint peeling on brick wall Maintenance: Window cracked Water Supply: Insufficient water supply in quantity and pressure at handwash sink
Laundry Storage	No Violations Noted
Main Level	
Old Wing Day Room	No Violations Noted
Side Entry Stairs	No Violations Noted
HUMV Dorm Room	No Violations Noted
Dorm Bathroom 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, lower showerhead does not work in handicap shower
105 CMR 451.124	Water Supply: Insufficient hot and cold water supply in quantity and pressure at handwash sink # 1, 2, 5, and 7
105 CMR 451.123	Maintenance: Toilet # 7 out-of-order
First Tier	
Control	No Violations Noted
Janitor's Closet 105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
A & B Side 105 CMR 451.320* 105 CMR 451.353 105 CMR 451.353 105 CMR 451.353*	Cell Size: Inadequate floor space in all cells Interior Maintenance: Wall paint damaged in cell # A12 and A16 Interior Maintenance: Floor paint damaged in cell # A2, A15, B12, and B19 Interior Maintenance: Ceiling damaged in cell # A12 and B1

Bathroom and Shower Area		
105 CMR 451.123*	Maintenance: Shower curtain missing on shower # 7, 8, 9, 10, and 11	
105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # 1 and 2	
105 CMR 451.123	Maintenance: Mold observed on ceiling in shower # 3	
105 CMR 451.123	Maintenance: Mold observed on tile grout in shower # 4	
105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure in shower unit # 11	
C & D Side (Administrative Seg	regation and Segregation Unit)	
105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	
105 CMR 451.353*	Interior Maintenance: Ceiling damaged in cell # C14, C20, and D2	
105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # C13, C15, C16, C19, D7, D13, and	
	D16	
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # C11, C18, and D12	
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # D2	
Shower Room # D23		
105 CMR 451.123*	Maintenance: Ceiling paint damaged	
105 CMR 451.123	Maintenance: Mold observed on wall near shower head	
Second Tier	Leterior Meinten and Meiltin le cell suin denne mainte d	
105 CMR 451.353	Interior Maintenance: Multiple cell windows painted	
Nurse's Room		
	No Violations Noted	
Control		
	No Violations Noted	
E & F Side		
105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	
105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # E12 and E19	
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # F5	
105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # E9 and E11	
Bathroom and Shower Area		
105 CMR 451.123	Maintenance: Wall tile grout dirty in shower # 2 and 4	
105 CMR 451.123	Maintenance: Wall tile grout missing in shower # 10	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, no drain cover in shower # 3	
105 CMR 451.123	Maintenance: Floor drain not draining properly in shower # 3	
105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # 1	
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at slop sink	
105 CMR 451.123	Maintenance: Mold observed on wall around handwash sink	
Janitorial Cage		
105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket	
G & H Side		
105 CMR 451.320*	Cell Size: Inadequate floor space in all cells	
105 CMR 451.320*		
	Interior Maintenance: Floor paint damaged in cell # G3, G8, and G10	
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # G2, G4, G11, G19, H5, H7, H9, H11, and H25	
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # H2, H11, H24, and H26	
105 CMR 451.353	Interior Maintenance: Wall cracked in cell # G2 and G4	
105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # H11 and H19	
	C C C C C C C C C C C C C C C C C C C	

<b>Gym</b> 105 CMR 451.350* 105 CMR 451.353*	Structural Maintenance: Windows not weathertight and structurally sound Interior Maintenance: Ceiling left unfinished
Gym Office	No Violations Noted
<i>Staff Bathroom</i> 105 CMR 451.110(A) 105 CMR 451.123 105 CMR 451.123	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink Maintenance: Unlabeled chemical bottle Maintenance: Screen missing
Stairway to Third Tier	No Violations Noted
<b>Third Tier</b> 105 CMR 451.353*	Interior Maintenance: Multiple cell windows painted
Day Room	No Violations Noted
Control	No Violations Noted
Offices	No Violations Noted
<i>I &amp; J Side</i> 105 CMR 451.320* 105 CMR 451.130 105 CMR 451.126 105 CMR 451.353 105 CMR 451.353	Cell Size: Inadequate floor space in all cells Plumbing: Plumbing not maintained in good repair, cold water continually running in cell # J11 Hot Water: Hot water temperature recorded at 72 <sup>o</sup> F in cell # J5 Interior Maintenance: Floor paint damaged in cell # I9 and J18 Interior Maintenance: Wall paint damaged in cell # I9, I17, I18, J24, and J26
Bathroom and Shower Area 105 CMR 451.123 105 CMR 451.130* 105 CMR 451.123 105 CMR 451.123	Maintenance: Caulking damaged around slop sink Plumbing: Plumbing not maintained in good repair, drain cover missing on slop sink Maintenance: Cold water handle broken on handwash sink Maintenance: Mold observed on wall tile grout in shower # 3 and 8
Janitor's Closet 105 CMR 451.353 105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket Interior Maintenance: Standing water left in bucket
K & L Side 105 CMR 451.320* 105 CMR 451.353 105 CMR 451.353 105 CMR 451.130	Cell Size: Inadequate floor space in all cells Interior Maintenance: Wall paint damaged in cell # K19, K24, and L17 Interior Maintenance: Floor paint damaged in cell # K2, L15, L17, L19, and L21 Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # K13
CWP Building	Did Not Inspect – Building Closed and Being Renovated

# Work Release Building FC 5-501.113(A)\*

Refuse, Recyclables, and Returnables: Trash receptacles not kept covered

## <u>House # 1</u>

u dan dikada alah sa u u

### **First Floor**

Hallway	No Violations Noted
Infirmary	No Violations Noted
Control	No Violations Noted
Office	No Violations Noted
Bathroom 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Floor and wall tiles missing in shower stall Maintenance: Soap scum observed on shower curtain Maintenance: Soap scum observed walls in shower Maintenance: Baseboard and wall damaged in toilet stall Maintenance: Ceiling removed and left unfinished
<i>Bedrooms</i> 105 CMR 451.353	Interior Maintenance: Wall paint damaged in room # 2 and 3
Food Service Area	
Dining Room	No Violations Noted
<i>Kitchen</i> FC 5-205.15(B)* FC 4-101.16* FC 2-402.11	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, handwash sink leaking Materials for Construction and Repair; Multiuse: Sponges used in kitchen Hygienic Practices; Hair Restraints: Food service personnel not wearing appropriate hair restraints, beard guards not in use
Second Floor	
Stairway	No Violations Noted
Hallway	No Violations Noted
Bedrooms	No Violations Noted

Bathroom 105 CMR 451.124 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Water Supply: Insufficient water supply in quantity and pressure in show Maintenance: Wall damaged near shower head in shower # 1 Maintenance: Drain cover missing in shower # 1 Maintenance: Floor stained red in shower # 4	wer unit # 2
Shower	No Violations Noted	
Stairway to Basement	No Violations Noted	
Basement		
Laundry Room 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, no hot water supplie	ed to slop sink
Boiler Room	No Violations Noted	
Chemical Storage Room	No Violations Noted	
Day Room Between Houses	No Violations Noted	
<u>House # 2</u>		
First Floor		
Hallway	No Violations Noted	
Night Shift Office 105 CMR 451.353	Interior Maintenance: Ceiling paint damaged near light fixture	
<i>Officer's Bathroom</i> 105 CMR 451.140*	Adequate Ventilation: Inadequate ventilation, no means for ventilation	
Bedrooms	No Violations Noted	
Administration Office	No Violations Noted	
Second Floor		
Hallway	No Violations Noted	
Bathroom 105 CMR 451.123* 105 CMR 451.123	Maintenance: Mold observed on caulking around sink # 2 Maintenance: Counter top cracked near sink # 2	
Bedrooms 105 CMR 451.141	Screens: Screen missing in room # 3	
451-17(1)-Middlesex-Billerica-Report 1-31-17 Page 26 of 28		

#### **Third Floor**

atora di alta di alcora

Bedrooms	No Violations Noted
Basement	
Day Room	
105 CMR 451.353	Interior Maintenance: Padding damaged on exercise equipment
Property	
	No Violations Noted
Bathroom	
105 CMR 451.123	Maintenance: Hole in wall above wooden heater covering
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1, 3, and 4
105 CMR 451.123	Maintenance: Soap scum on floor in shower # 1
105 CMR 451.123	Maintenance: Soap scum on shower curtain in shower # 1, 2, 3, and 4
Storage Room	
	No Violations Noted
WAREHOUSE	
	No Violations Noted
Office	
- ,,	No Violations Noted
Female Bathroom	
	No Violations Noted
Male Bathroom	
	No Violations Noted
Janitor's Closet	
	No Violations Noted
Old Walk-in Freezer	
	No Violations Noted
Back Freezer and Refrigerator	

No Violations Noted

#### **Observations and Recommendations**

- 1. The inmate population was 980 at the time of inspection.
- 2. While conducting the main kitchen inspection, the warewash machine was unable to reach the proper temperature to sanitize dishes. Kitchen staff then began using a chemical sanitizer to properly sanitize dishes.
- 3. During the inspection of the House # 1 kitchen, a new 3-bay sink was in the process of being installed. It was stated that food service personnel were using Styrofoam dishes and sending necessary dishes to the main kitchen to be cleaned and sanitized.
- 4. The Department recommended posting the proper medical and biological waste storage procedures within the medical waste storage closet within the Health Services Unit.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at <u>www.mass.gov/dph/dcs</u> and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at <u>www.mass.gov/dph/fpp</u> and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X – Minimum Sanitation Standards for Food Establishments" and "<u>1999 Food Code</u>".

To review the Labeling regulations please visit the Food Protection website at <u>www.mass.gov/dph/fpp</u> and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,

TAMAS Warn

Kerry Wagner Environmental Health Inspector, CSP, BEH

Jan Sullivan, Acting Director, BEH cc: Steven Hughes, Director, CSP, BEH Timothy Miley, Director of Government Affairs Marylou Sudders, Secretary, Executive Office of Health and Human Services Thomas Turco, Commissioner, DOC Shawn Jenkins, Special Sheriff Osvaldo Vidal, Superintendent of Operations Carole Cafferty, Superintendent of Administration and Programs Services Sergeant Shane Cassidy, EHSO Captain William Buckley, EHSO Richard Berube, Director, Billerica Board of Health Clerk, Massachusetts House of Representatives Clerk, Massachusetts Senate Daniel Bennett, Secretary, EOPSS Jennifer Gaffney, Director, Policy Development and Compliance Unit