

CHARLES D. BAKER Governor

KARYN E. POLITO Lieutenant Governor

# The Commonwealth of Massachusetts Executive Office of Health and Human Services Department of Public Health Bureau of Environmental Health Community Sanitation Program 180 Beaman Street, West Boylston, MA 01583 Phone: 508-792-7880 Fax: 508-792-7706 TTY: 508-835-9796

MARYLOU SUDDERS Secretary

MONICA BHAREL, MD, MPH Commissioner

Tel: 617-624-6000 www.mass.gov/dph

February 6, 2019

Peter J. Koutoujian, Sheriff Middlesex County Sheriff's Office 400 Mystic Avenue Medford, MA 02155

Re: Facility Inspection - Middlesex County Jail and House of Corrections, Billerica

# Dear Sheriff Koutoujian:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 2013 Food Code; 105 CMR 500.000 Good Manufacturing Practices for Food; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Middlesex County Jail and House of Corrections on January 29, 30, and 31, 2019 accompanied by Captain William Buckley and Sergeant Shane Cassidy, Environmental Health and Safety Officers. Violations noted during the inspection are listed below including 83 repeat violations:

## **HEALTH AND SAFETY VIOLATIONS**

(\* indicates conditions documented on previous inspection reports)

## CHECKPOINT BUILDING

Janitor's Closet

105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Control Desk

No Violations Noted

# **PODULAR BUILDING**

Lobby

Water Fountain

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

**Administration Wing** 

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Kitchenette

No Violations Noted

**Visiting Area** 

No Violations Noted

Visitor's Side

No Violations Noted

**Central Control** 

No Violations Noted

Bathroom

105 CMR 451.123 Maintenance: Floor dirty

**Attorney Visit Hallway** 

Janitor's Closet

No Violations Noted

Male Bathroom

Unable to Inspect – In Use

Female Bathroom

No Violations Noted

Visiting Control Room 105 CMR 451.353

15 CMR 451.353 Interior Maintenance: Ceiling water damaged

Inmate Bathroom

105 CMR 451.126 Water Supply: No hot water supplied to handwash sink

Evidence Room

Unable to Inspect – Locked

Visiting Area – Inmate Side

No Violations Noted

#### **Entrance Hallway for Pod A & B**

Nurse's Station

105 CMR 451.126 Hot Water: Hot water temperature recorded at 60°F

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Caseworker's Office

No Violations Noted

Pod A

Common Area

No Violations Noted

Storage Cage (Barber Shop)

No Violations Noted

Janitor's Closet

105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

Pod Storage Room

105 CMR 451.383(B) Fire Safety System: Facility not in compliance with State Building Code provisions for

fire safety, items stored within 18 inches of ceiling

Lower Level Shower Area # 1-5

105 CMR 451.123\* Maintenance: Soap scum on walls in shower # 5

105 CMR 451.123\* Maintenance: Mold on ceiling outside shower # 2 and 5 105 CMR 451.123 Maintenance: Mold on ceiling outside shower # 3

105 CMR 451.123 Maintenance: Ceiling dirty shower # 1

Lower Cells

105 CMR 451.353\* Interior Maintenance: Floor paint damaged in cell # 1-13 105 CMR 451.353 Interior Maintenance: Floor paint damaged in cell # 1-15

Upper Level Shower Area # 6-10

105 CMR 451.123 Maintenance: Mold on ceiling outside shower # 6 and 8

105 CMR 451.123 Maintenance: Light out outside shower # 9

Upper Cells

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, water continually running in

cell # 2-20

Pod B

Common Area

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, 1 water bubbler out-of-order

Counselor's Office

No Violations Noted

Storage Cage (Barber Shop)

No Violations Noted

Janitor's Closet

No Violations Noted

Storage Room (Small)

No Violations Noted

Storage Room (Large)

No Violations Noted

Lower Level Shower Area

105 CMR 451.123 Maintenance: Mold on wall and ceiling outside shower # 1

Lower Cells

105 CMR 451.353\* Interior Maintenance: Floor paint damaged in cell # 1-15 105 CMR 451.353 Interior Maintenance: Wall vent blocked in cell # 1-08

Upper Level Shower Area

No Violations Noted

Upper Cells

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, water continually running in

cell # 2-26

105 CMR 451.353 Interior Maintenance: Wall vent blocked in cell # 2-07, 2-18, 2-20, 2-24, and 2-29

## Entrance Hallway for Pod C & D

Nurse's Station

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

No Violations Noted

Office

No Violations Noted

Pod C

Common Area

105 CMR 451.353\* Interior Maintenance: Floor paint damaged

Storage Cage (Barber Shop)

Janitor's Closet

No Violations Noted

Storage Room

No Violations Noted

Counselor/Interview Office

No Violations Noted

Multi-Purpose Room

No Violations Noted

Lower Level Shower Area

No Violations Noted

Lower Cells

105 CMR 451.353 Interior Maintenance: Wall vent blocked in cell # 1-08, 1-09, 1-19, and 1-21

Upper Level Shower Area

105 CMR 451.123 Maintenance: Shower # 6 and 10 out-of-order

105 CMR 451.123 Maintenance: Mold observed on caulking around handwash sink

Upper Cells

105 CMR 451.353\* Interior Maintenance: Floor paint damaged in cell # 2-25 105 CMR 451.353 Interior Maintenance: Floor paint damaged in cell # 2-22

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, water continually running in

cell # 2-03

#### Pod D

Common Area

No Violations Noted

Storage Cage (Barber Shop)

105 CMR 451.353 Interior Maintenance: Unlabeled chemical bottle

Janitor's Closet

105 CMR 451.130\* Plumbing: Plumbing not maintained in good repair, backflow preventer leaking on slop

sink

105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

Counselor/Interview Room

No Violations Noted

Multi-Purpose Room

No Violations Noted

Pod Storage Room

No Violations Noted

Lower Level Shower Area

105 CMR 451.130 Hot Water: Shower water temperature recorded at 90°F in shower # 5

105 CMR 451.123\* Maintenance: Ceiling paint damaged outside shower # 1

105 CMR 451.123 Maintenance: Mold observed on ceiling and wall outside shower # 1

Lower Cells

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, cold water continually running in

cell # 1-28

Upper Level Shower Area

105 CMR 451.123 Maintenance: Shower # 1 out-of-order

105 CMR 451.123 Maintenance: Ceiling vents dusty outside showers

Upper Cells

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, water continually running in

cell # 2-19

Pod F

Administration Area

No Violations Noted

Female Staff Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Male Staff Bathroom

No Violations Noted

Medical Office

No Violations Noted

**Block** 

Janitor's Closet

No Violations Noted

Storage

No Violations Noted

Lower Showers

105 CMR 451.123 Maintenance: Floor dirty in shower # 1 and 6

Lower Cells

No Violations Noted

*Barber Shop # 1-06* 

105 CMR 451.117 Toilet Fixtures: Toilet fixture dirty

*Music Room # 1-05* 

No Violations Noted

Laundry Room # 1-04

No Violations Noted

The Club House # 1-03

Meditation Room # 1-02

No Violations Noted

*Library # 1-01* 

No Violations Noted

Assessment Office

Unable to Inspect – In Use

Library/Multi-Purpose Room

No Violations Noted

Case Worker's Office

No Violations Noted

Upper Cells

No Violations Noted

*Upper Showers # 1-10* 

105 CMR 451.123 Maintenance: Floor dirty in shower # 9

Common Area

No Violations Noted

# Dorm # 3 and 4 Landing

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Trash Room

No Violations Noted

Janitor's Closet

No Violations Noted

Storage/Med Pass

No Violations Noted

Medical Office

105 CMR 451.126 Hot Water: Hot water temperature recorded at 80°F

Classroom # 2

No Violations Noted

**Multi-Purpose Hallway** 

No Violations Noted

Storage Room # 1 and 2

No Violations Noted

Classroom A and B

**Dorm #3** 

Sleeping Area

No Violations Noted

Common Area

No Violations Noted

Toilet Area

105 CMR 451.124\* Water Supply: Insufficient cold water supply in quantity and pressure at handwash

sink # 5 and 7

Water Supply: Insufficient cold water supply in quantity and pressure at handwash

sink#6

105 CMR 451.124\* Water Supply: Insufficient hot water supply in quantity and pressure at handwash

sink # 5, 6, 7, and 8

105 CMR 451.123 Maintenance: Toilet # 4 clogged

Sink Area

Hot Water: Hot water temperature recorded at 100°F at sink # 1

105 CMR 451.124 Water Supply: Insufficient hot water supply in quantity and pressure at handwash

sink # 3

105 CMR 451.123 Maintenance: Hand dryer out-of-order

Shower Area

Maintenance: Black substance on baseboard of shower # 2 and 7 105 CMR 451.130 Hot Water: Shower water temperature recorded at 80°F in shower # 1

Janitor's Closet

No Violations Noted

Case Worker's Office

Unable to Inspect – In Use

Barber Shop

No Violations Noted

**Dorm #4** 

Barber Shop

No Violations Noted

Case Worker's Office

105 CMR 451.200\* Food Storage, Preparation and Service: Food storage not in compliance with

105 CMR 590.000, gaskets damaged on refrigerator

Janitor's Closet

No Violations Noted

Shower Area Unable to Inspect Shower # 2 and 7 – In Use

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, lower shower head not functioning

Toilet Area Unable to Inspect Toilet Stall # 4 - 8 – In Use

105 CMR 451.124\* Water Supply: Insufficient hot and cold water supply in quantity and pressure at

handwash sink # 1 and 2

Sink Area

Hot Water: Hot water temperature recorded at 100°F at handwash sink # 1

Common Area

No Violations Noted

Sleeping Area

No Violations Noted

Pod E

**Administration Area** 

Female Staff Bathroom

Unable to Inspect - Locked

Janitor's Closet

No Violations Noted

Male Staff Bathroom

No Violations Noted

Offices

No Violations Noted

Nurse's Station

No Violations Noted

**Block** 

Janitor's Closet

No Violations Noted

Barber Shop

No Violations Noted

Storage Room

No Violations Noted

Segregation Showers

No Violations Noted

Segregation Cells

105 CMR 451.103 Mattresses: Mattress damaged in cell # 1-28 105 CMR 451.353 Interior Maintenance: Floor dirty in cell # 1-14

Classroom/Assessment

No Violations Noted

Library

No Violations Noted

Caseworker's Office

Upper Cells

No Violations Noted

**Upper Showers** 

No Violations Noted

Dorm # 1 and 2 Landing

Shift Administrator's Office

No Violations Noted

Janitor's Closet

No Violations Noted

Male Staff Bathroom

No Violations Noted

Female Staff Bathroom

Unable to Inspect - Locked

Storage/Med Pass

No Violations Noted

Medical Office

No Violations Noted

Classroom # 1

No Violations Noted

**Dorm # 1** 

Sleeping Area

No Violations Noted

Common Area

No Violations Noted

Toilet Area

Unable to Inspect – In Use

Sink Area

No Violations Noted

Shower Area

105 CMR 451.124\* Water Supply: Insufficient water supply in quantity and pressure from lower shower head

in shower unit #1

Hot Water: Shower water temperature recorded at 80°F in shower # 1

105 CMR 451.123 Maintenance: Mold observed on caulking in shower # 1

105 CMR 451.123 Maintenance: Soap scum observed on walls in shower # 1, 2, and 3

Janitor's Closet

105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

Case Worker's Office

Barber Shop

No Violations Noted

**Dorm # 2** 

Barber Shop

No Violations Noted

Case Worker's Office

No Violations Noted

Janitor's Closet

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, drain cover missing

Shower Area

105 CMR 451.123\* Maintenance: Ceiling vent rusted in shower # 8

Toilet Area

Water Supply: Insufficient hot water supply in quantity and pressure at handwash

sink # 2

Sink Area

No Violations Noted

Common Area

No Violations Noted

Sleeping Area

No Violations Noted

# **Intake and Discharge**

Deputy's Office

No Violations Noted

Janitor's Closet

No Violations Noted

Administrative Office

No Violations Noted

Holding Tank # 2

No Violations Noted

*Shake Room #1 & 2* 

105 CMR 451.126 Water Supply: No cold water supplied to handwash sink in room # 2

Holding Cell # 1

No Violations Noted

Institutional Property

No Violations Noted

Desk Area

Sally Port

No Violations Noted

Old Shower Room # 1

No Violations Noted

Holding Cell # 1-6

105 CMR 451.353\* Interior Maintenance: Ceiling damaged around light fixture in cell # 4
105 CMR 451.126 Water Supply: No cold water supplied to handwash sink in cell # 1, 4, and 5

Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink

in cell # 2 and 3

Break Room

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Inmate Property Room

No Violations Noted

Change Room # 1 and 2 Unable to Inspect Change Room # 1 – Locked

No Violations Noted

## A & B Hall Entrance

Janitor's Closet

No Violations Noted

Teacher's Office

No Violations Noted

Hall A

Unable to Inspect – In Use

Hall B

No Violations Noted

## **Food Service Area**

Staff Dining Room

FC 4-501.11(B)\* Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, gasket damaged on right side refrigerator

FC 5-205.15(B) Plumbing System, Operations and Maintenance: Plumbing system not maintained in

good repair, hot water handle leaking at handwash sink

Male Bathroom

No Violations Noted

Female Bathroom

**Supply Dock** 

Loading Dock

No Violations Noted

Surplus Storage Room

No Violations Noted

Storage Room

No Violations Noted

**Back of Kitchen** 

Supply Room # 2 (Dry Storage)

No Violations Noted

Chemical Supply Closet

No Violations Noted

Daily Cleaning Cabinet

No Violations Noted

Kitchen Staff Break Room

No Violations Noted

Supply Room #1

No Violations Noted

Inmate Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Rack Spray Area

No Violations Noted

Main Kitchen Area

Cooler # 1

No Violations Noted

Warmer # 1 & 2

FC 4-501.11(B) Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, gaskets damaged in warmer # 1

FC 4-502.11(C) Maintenance and Operation, Utensils and Temperature and Pressure Measuring Devices:

Ambient air temperature measuring device not maintained in good repair, thermometer

on warmer # 2 not functioning properly

Serving Line

FC 3-501.16(A)(1) Limitation of Growth of Organisms, Temperature and Time Control: Time/Temperature

control for safety food not held at the proper hot holding temperature, broccoli

temperature recorded at 118°F

Handwash Sink – Near Pots and Pans Sink

Pots and Pan Sink

No Violations Noted

Mechanical Warewash Area

FC 6-501.11 Maintenance and Operation; Repairing: Facility not in good repair, floor tiles damaged to

the left and in front of warewash machine

Warewash Machine

No Violations Noted

Handwash Sink after Warewash Machine

No Violations Noted

Inmate Coffee Area

No Violations Noted

Diet Area/Serving Line # 2

No Violations Noted

Warmer # 3 & 4

FC 4-501.11(B)\* Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, gaskets damaged on warmer # 3

New Refrigerator

No Violations Noted

McCall Proofer # 1

FC 4-502.11(C) Maintenance and Operation, Utensils and Temperature and Pressure Measuring Devices:

Ambient air temperature measuring device not maintained in good repair, thermometer

not functioning properly

3 Warmers (Under Hoods)

No Violations Noted

Prep Tables and Sinks

No Violations Noted

Ice Machines

No Violations Noted

Handwash Sink (After Ice Machine # 2)

No Violations Noted

Kettle Area

No Violations Noted

Walk-in Refrigerator # 2

No Violations Noted

Spice Cabinet

FC 3-302.12 Protection from Contamination After Receiving: Food storage containers, Identified with

Common Name of Food, mislabeled sugar container

Walk-in Refrigerator # 1

Hood Area with Warmers

No Violations Noted

Walk-in Freezer

FC 4-501.11(A)\* Maintenance and Operation, Equipment: Equipment not maintained in a state of good

repair, door frame damaged

Sallyport/Changing Area

No Violations Noted

Janitor's Closet

No Violations Noted

Officer's Area/Office

No Violations Noted

## **Culinary Arts Program Kitchen**

Classroom

No Violations Noted

McCall Refrigerator

FC 4-501.11(B) Maintenance and Operation, Equipment: Equipment components not maintained in a

state of good repair, gaskets damaged

Proofers

No Violations Noted

Walk-in Freezer

No Violations Noted

Hood Area

No Violations Noted

Handwash Sink

No Violations Noted

3-Compartment Sink

No Violations Noted

Prep Sink

No Violations Noted

Prep Tables

No Violations Noted

Walk-in Refrigerator

No Violations Noted

# **Health Service Unit**

*ISO # 1 & 2* 

No Violations Noted

Nurse's Pantry

Janitor's Closet

No Violations Noted

Risk Cell # 1 & 2

105 CMR 451.353 Interior Maintenance: Floor paint damaged in both risk cells

Private Rooms # 1-4

No Violations Noted

Ward A

No Violations Noted

Storage Room

No Violations Noted

Handicap Shower Room

105 CMR 451.123 Maintenance: Soap scum on bench and walls in shower

Nurse's Station and Bathroom

No Violations Noted

Treatment Room # 1

No Violations Noted

Inmate Bathroom

No Violations Noted

Treatment Room # 2

No Violations Noted

Medical Waste Storage

No Violations Noted

Treatment Room # 3

No Violations Noted

Coordinator's Office

No Violations Noted

Lab

Unable to Inspect - In Use

Dental Room

No Violations Noted

Infectious Disease Office

105 CMR 480.500(A)(3) Procedures; Records; Record-Keeping Log: Generator had no written documentation for

blood borne pathogen training

Psychiatry Office

No Violations Noted

Exam Room # 2

Exam Room # 1

No Violations Noted

Cleaning Utility Room

No Violations Noted

Storage Room #1

No Violations Noted

Mental Office

No Violations Noted

Physical Therapy (Treatment Room # 4)

No Violations Noted

**Pharmacy** 

No Violations Noted

Janitor's Closet

No Violations Noted

**Holding** 

No Violations Noted

Storage Room # 2

No Violations Noted

Ward B

105 CMR 451.123 Maintenance: Soap scum on walls in shower

# **HSU Administration Hallway**

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Medical Records

No Violations Noted

Health Service Administrator's Office

No Violations Noted

# **Classifications Building**

#### **Main Level**

Lobby

105 CMR 451.350\* Structural Maintenance: Window panes broken at entrance

Janitor's Closet

105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

Female Bathroom

105 CMR 451.123\* Maintenance: Toilet # 2 out-of-order 105 CMR 451.350\* Structural Maintenance: Window broken

Male Bathroom

105 CMR 451.130\* Plumbing: No backflow preventer on sink

105 CMR 451.123\* Maintenance: Urinal dirty

105 CMR 451.123 Maintenance: Strong odor present

Control Area

105 CMR 451.350\* Structural Maintenance: Windows not weathertight and structurally sound

105 CMR 451.350\* Structural Maintenance: Several window panes broken

105 CMR 451.350\* Structural Maintenance: Window sills and wall near windows damaged

105 CMR 451.141\* Screens: Screen damaged

105 CMR 451.353 Interior Maintenance: Ceiling tiles missing

Roll Call Room

No Violations Noted

**Jail Visiting Hallway** 

Parole Office

No Violations Noted

Additional Offices

No Violations Noted

**Old Administration Wing** 

First Floor

Offices

Unable to Inspect – Locked

Storage Closet

No Violations Noted

Female Bathroom

No Violations Noted

Mail Room

105 CMR 451.353\* Interior Maintenance: Ceiling tiles missing

Tool Crib Area

No Violations Noted

Tool Crib Bathroom

No Violations Noted

Maintenance Area

No Violations Noted

Maintenance Break Room

Unable to Inspect – Under Construction

**Second Floor** 

105 CMR 451.353\* Interior Maintenance: Ceiling tiles missing throughout

Offices

No Violations Noted

Male Bathroom # 2

105 CMR 451.123 Maintenance: Urinal out-of-order 105 CMR 451.123 Maintenance: Strong odor present

#### **New Male Locker Room**

Male Locker Room Bathroom

105 CMR 451.350\* Structural Maintenance: Window broken

105 CMR 451.123\* Maintenance: Screen missing

105 CMR 451.123 Maintenance: Ceiling tiles water damaged

Male Shower Room

105 CMR 451.123 Maintenance: Ceiling vent dusty

# Classifications & Old Infirmary Hallway

Offices

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom # 1

105 CMR 451.350\* Structural Maintenance: Window broken

105 CMR 451.124\* Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink

105 CMR 451.123\* Maintenance: Wall paint damaged

Old Shower Room

Unable to Inspect – No Longer In Use

Staff Break Room

105 CMR 451.353\* Interior Maintenance: Wall paint damaged

Offices

105 CMR 451.353\* Interior Maintenance: Ceiling tiles water stained in copy room

Third Floor

105 CMR 451.350\* Structural Maintenance: Several window panes broken throughout area

105 CMR 451.141\* Screens: Screens damaged throughout area

Male Locker Room

No Violations Noted

Male Locker Room Bathroom

105 CMR 451.123\* Maintenance: Wall paint damaged near soap dispenser # 3

105 CMR 451.123\* Maintenance: Floor paint damaged 105 CMR 451.123\* Maintenance: Dead bugs in light shield 105 CMR 451.117 Toilet Fixtures: Toilet fixture dirty in stall # 2 Female Locker Room

105 CMR 451.117 Toilet Fixtures: Toilet fixture dirty

Officer's Weight Room

105 CMR 451.353 Interior Maintenance: Gym equipment padding damaged

**Lower Report** 

A & B Side Cells

Unable to Inspect – No longer in use due to lack of natural lighting

**Training Center** 

**First Floor** 

Barber Area

No Violations Noted

Library

105 CMR 451.350 Structural Maintenance: Window pane broken

Meeting Room

No Violations Noted

Offices and Classroom

105 CMR 451.353\* Interior Maintenance: Ceiling tiles water damaged in the classroom next to the library

Print Shop

No Violations Noted

Chapel

105 CMR 451.350\* Structural Maintenance: Window panes broken

**Bathroom** 

105 CMR 451.350\* Structural Maintenance: Window broken 105 CMR 451.123\* Maintenance: Ceiling tiles water stained

105 CMR 451.126 Hot Water: Hot water temperature recorded at 90°F

Storage Room

Unable to Inspect – Locked

**Second Floor** 

Main Laundry

105 CMR 451.350\* Structural Maintenance: Window broken

Inmate Bathroom

105 CMR 451.350\* Structural Maintenance: Window broken

Officer's Bathroom

105 CMR 451.123\* Maintenance: Wall paint peeling on brick wall 105 CMR 451.350\* Structural Maintenance: Window cracked

105 CMR 451.124\* Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink

Laundry Storage

Unable to Inspect – Locked

**HUMV Dorm Room** 

No Violations Noted

Dorm Bathroom

105 CMR 451.124 Water Supply: Insufficient cold water supply in quantity and pressure at handwash

sink # 2

105 CMR 451.126 Water Supply: No cold water supplied to handwash sink # 1
105 CMR 451.123\* Maintenance: Wall paint damaged outside handicap shower
105 CMR 451.123 Maintenance: Soap scum on bench and walls in handicap shower

**First Tier** 

Day Room

105 CMR 451.360 Protective Measures: Bird observed in the Day Room

Control

No Violations Noted

Janitor's Closet

105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

A & B Side

105 CMR 451.320\* Cell Size: Inadequate floor space in all cells

105 CMR 451.353 Interior Maintenance: Wall paint damaged in cell # A9 Interior Maintenance: Ceiling paint damaged in cell # B1

105 CMR 451.353 Interior Maintenance: Floor paint damaged in cell # A15 and B18

Bathroom and Shower Area

105 CMR 451.123 Maintenance: Ceiling paint damaged in shower # 1

105 CMR 451.124 Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink

C & D Side

No Violations Noted

Shower Room # D23

Unable to Inspect – Not Used

**Second Tier (Unoccupied)** 

105 CMR 451.353\* Interior Maintenance: Multiple cell windows painted

Nurse's Room

Unable to Inspect – Locked

Control

No Violations Noted

E & F Side

105 CMR 451.353\* Interior Maintenance: Ceiling paint damaged in cell # E11

105 CMR 451.353 Interior Maintenance: Ceiling paint damaged in cell # E16 and F18

Bathroom and Shower Area 105 CMR 451.123\* Maintenance: Floor drain sealed off resulting in standing water in shower # 3 105 CMR 451.123\* Maintenance: Floor drain cover damaged in shower # 5 105 CMR 451.123 Maintenance: Floor drain cover damaged outside shower #8 Maintenance: Floor drain missing outside shower # 3 and in shower # 7 and 11 105 CMR 451.123 105 CMR 451.123\* Maintenance: Ceiling damaged in shower # 1 and 9 Maintenance: Floor dirty in shower # 2, 9, and around handwash sink 105 CMR 451.123 105 CMR 451.126 Water Supply: No cold water supplied to handwash sink Janitorial Cage No Violations Noted G & H Side 105 CMR 451.353\* Interior Maintenance: Wall paint damaged in cell # G23 and H24 Interior Maintenance: Wall paint damaged in cell # H6, H13, H16, H18, H19, and H21 105 CMR 451.353 Interior Maintenance: Wall damaged in cell # H8 105 CMR 451.353\* 105 CMR 451.353\* Interior Maintenance: Ceiling paint damaged in cell # G5, H3, H4, H11, H19, and H25 Interior Maintenance: Ceiling paint damaged in cell # G19, H8, H18, and H22 105 CMR 451.353 Gvm 105 CMR 451.353 Interior Maintenance: Wooden window coverings damaged Gym Office 105 CMR 451.344 Illumination in Habitable Areas: Light not functioning properly, light out Staff Bathroom No Violations Noted Stairway to Third Tier No Violations Noted Third Tier (Unoccupied) 105 CMR 451.353\* Interior Maintenance: Multiple cell windows painted Day Room No Violations Noted Control No Violations Noted Offices No Violations Noted I & J Side 105 CMR 451.126\* Hot Water: Hot water temperature recorded at 80°F in cell # J5 105 CMR 451.353\* Interior Maintenance: Window dirty in cell # J3 105 CMR 451.117 Toilet Fixtures: Toilet fixture dirty in cell # J16 Bathroom and Shower Area 105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, drain cover missing in shower # 3 Janitor's Closet No Violations Noted

451-19(1)-Middlesex-Billerica-Report 2-6-19

No Violations Noted

K & L Side

# **CWP Building**

Unable to Inspect – Closed

# **Work Release Building**

**House # 1** 

**First Floor** 

Hallway

No Violations Noted

*Infirmary* 

No Violations Noted

Control

No Violations Noted

Office

No Violations Noted

Bathroom

105 CMR 451.123 Maintenance: Screen missing

**Bedrooms** 

No Violations Noted

#### **Food Service Area**

Dining Room

FC 6-501.16 Maintenance and Operation; Drying Mops: Wet mop stored in bucket

FC 4-904.11(B) Protection of Clean Items, Preventing Contamination: Knives, forks, and spoons not

presented to avoid contamination

Kitchen

FC 4-501.11(A)\* Maintenance and Operation, Equipment: Equipment not maintained in a state of good

repair, freezer out-of-order

FC 4-303.11(A) Numbers and Capacities; Cleaning Agents and Sanitizers: Cleaning agents used to clean

equipment and utensils not available during all hours of operation

FC 4-303.11(B) Numbers and Capacities; Cleaning Agents and Sanitizers: Sanitizers used to sanitize

equipment and utensils not available during all hours of operation

#### **Second Floor**

Stairway

105 CMR 451.353\* Interior Maintenance: Light shield missing

Hallway

No Violations Noted

Bedrooms

105 CMR 451.350\* Structural Maintenance: Properly sized window missing in window in bedroom # 8

105 CMR 451.353 Interior Maintenance: Wall paint damaged in room # 8 105 CMR 451.353 Interior Maintenance: Ceiling paint damaged in room # 7

105 CMR 451.141 Screens: Screen damaged in room # 6

Bathroom

105 CMR 451.123\* Maintenance: Screen missing

Stairway to Basement

No Violations Noted

**Basement** 

Laundry Room

No Violations Noted

Boiler Room

Unable to Inspect - Locked

Chemical Storage Room

No Violations Noted

**Day Room Between Houses** 

No Violations Noted

House # 2

**First Floor** 

Hallway

No Violations Noted

Night Shift Office

No Violations Noted

Officer's Bathroom

No Violations Noted

**Bedrooms** 

No Violations Noted

Administration Office

No Violations Noted

**Second Floor** 

Hallway

No Violations Noted

Bathroom

105 CMR 451.123\* Maintenance: Screen missing

**Bedrooms** 

105 CMR 451.141\* Screens: Screen missing in bedroom # 6 105 CMR 451.141 Screens: Screen missing in bedroom # 5 105 CMR 451.141 Screens: Screen damaged in bedroom # 3 Third Floor

105 CMR 451.344 Illumination in Habitable Areas: Light not functioning properly, light out between rooms

**Bedrooms** 

105 CMR 451.141\* Screens: Screen missing in room # 8 105 CMR 451.141 Screens: Screen missing in room # 7

**Basement** 

Day Room

No Violations Noted

**Property** 

Unable to Inspect - Locked

Bathroom

105 CMR 451.123 Maintenance: Mold observed on wooden heater cover

105 CMR 451.123 Maintenance: Mold on ceiling in shower # 3 105 CMR 451.123 Maintenance: Light out over toilet stall # 3 105 CMR 451.123 Maintenance: Slop sink not draining properly 105 CMR 451.123 Maintenance: Wet mop stored in bucket

Storage Room

Unable to Inspect - Locked

**WAREHOUSE** 

No Violations Noted

Office

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom

Unable to Inspect – In Use

Janitor's Closet

105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

Old Walk-in Freezer

No Violations Noted

Back Freezer and Refrigerator

No Violations Noted

## **Observations and Recommendations**

1. The inmate population was 774 at the time of inspection.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at <a href="www.mass.gov/dph/dcs">www.mass.gov/dph/dcs</a> and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment Regulations or download a copy, please visit the Food Protection website at <a href="https://www.mass.gov/dph/fpp">www.mass.gov/dph/fpp</a> and click on "Retail food". Then under DPH Regulations and FDA Code click "Merged Food Code" or "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments".

To review the Labeling regulations please visit the Food Protection website at <a href="www.mass.gov/dph/fpp">www.mass.gov/dph/fpp</a> and click on "Food Protection Program regulations". Then under Food Processing click "105 CMR 500.000: Good Manufacturing Practices for Food".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,

Kerry Wagner, MPH

Environmental Health Inspector, CSP, BEH

cc: Monica Bharel, MD, MPH, Commissioner, DPH

Jana Ferguson, Director, BEH

Steven Hughes, Director, CSP, BEH

Marylou Sudders, Secretary, Executive Office of Health and Human Services (electronic copy)
Carol A. Mici, Commissioner, DOC (electronic copy)

Thomas Turco, Secretary, EOPSS (electronic copy)
Nelson Alves, Director, Policy Development and Compliance Unit (electronic copy)

Osvaldo Vidal, Superintendent (electronic copy)
Captain William Buckley, EHSO (electronic copy)

Sergeant Shane Cassidy, EHSO (electronic copy)
Richard Berube, Director, Billerica Board of Health (electronic copy)

Clerk, Massachusetts House of Representatives

Clerk, Massachusetts Senate