

CHARLES D. BAKER Governor

KARYN E. POLITO Lieutenant Governor The Commonwealth of Massachusetts Executive Office of Health and Human Services Department of Public Health Bureau of Environmental Health Community Sanitation Program 180 Beaman Street, West Boylston, MA 01583 Phone: 508-792-7880 Fax: 508-792-7706 TTY: 508-835-9796

MARYLOU SUDDERS Secretary

MONICA BHAREL, MD, MPH Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

June 27, 2017

Peter J. Koutoujian, Sheriff Middlesex County Sheriff's Office 400 Mystic Avenue Medford, MA 02155

Re: Facility Inspection - Middlesex County Jail and House of Corrections, Billerica

Dear Sheriff Koutoujian:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Middlesex County Jail and House of Corrections on June 13, 14, and 19, 2017 accompanied by Sergeant Shane Cassidy, EHSO, Captain William Buckley, EHSO, and Amy Medeiros, Community Sanitation Program. Violations noted during the inspection are listed below including 122 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

CHECKPOINT BUILDING

Janitor's Closet 105 CMR 451.353	Interior Maintenance: Standing water left in bucket
Male Bathroom	No Violations Noted
Female Bathroom	No Violations Noted
Control Desk	No Violations Noted
NEW BUILDING	
Lobby	

No Violations Noted

Water Fountain	No Violations Noted
Female Bathroom	No Violations Noted
Male Bathroom	No Violations Noted
Janitor's Closet	No Violations Noted
Administration Wing	
Female Bathroom	No Violations Noted
Male Bathroom	Unable to Inspect – In Use
Janitor's Closet 105 CMR 451.353	Interior Maintenance: Wet mop improperly stored
<i>Kitchenette</i> 105 CMR 451.344	Illumination in Habitable Areas: Light not functioning properly, light out
Visiting Area 105 CMR 451.353	Interior Maintenance: Ceiling tiles water stained outside main door
Visitor's Side	No Violations Noted
Central Control 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functioning thermometer in refrigerator
Bathroom 105 CMR 451.123	Maintenance: Handwash sink not draining properly
Attorney Visit Hallway	
Janitor's Closet 105 CMR 451.344* 105 CMR 451.353	Illumination in Habitable Areas: Light not functioning properly, 1 light out Interior Maintenance: Wet mop stored in bucket
Male Bathroom	No Violations Noted
Female Bathroom	No Violations Noted
<i>Visiting Control Room</i> 105 CMR 451.353 105 CMR 451.200	Interior Maintenance: Hole in ceiling Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Inmate Bathroom 105 CMR 451.123*	Maintenance: Ceiling vent dusty
Urinalyses Room	Unable to Inspect – Locked
Visiting Area – Inmate Side	No Violations Noted
Entrance Hallway for Pod A	<u>& B</u>
Nurse's Station	No Violations Noted
Female Bathroom	No Violations Noted
Male Bathroom	No Violations Noted
Janitor's Closet	Unable to Inspect – Locked
Caseworker's Office	No Violations Noted
Pod A	
Common Area	No Violations Noted
Storage Cage (Barber Shop)	No Violations Noted
Janitor's Closet	No Violations Noted
Storage Room	No Violations Noted
Lower Level Shower Area # 1-5 105 CMR 451.123* 105 CMR 451.124* 105 CMR 451.124 105 CMR 451.123	Maintenance: Ceiling paint damaged around light fixture in shower # 4 Water Supply: Insufficient water supply in quantity and pressure in shower unit # 3 Water Supply: Insufficient water supply in quantity and pressure in shower unit # 2 and 4 Maintenance: Light out in shower # 5
Lower Cells 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # 1-09
105 CMR 451.126 105 CMR 451.353*	Hot Water: Hot water temperature recorded at 95°F in cell # 1-24 Interior Maintenance: Floor paint damaged in cell # 1-23
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 1-31
<i>Upper Level Shower Area # 6-1</i> 105 CMR 451.123*	0 Maintenance: Shower # 9 out-of-order

<i>Upper Cells</i> 105 CMR 451.353 105 CMR 451.113	Interior Maintenance: Floor paint damaged in cell # 2-17 and 2-23 Toilet and Handwashing Sink in Locked Cells: No hot and cold running water in locked cell # 2-27
Pod B	
Common Area	No Violations Noted
Counselor's Office	No Violations Noted
Storage Cage (Barber Shop)	No Violations Noted
Janitor's Closet	No Violations Noted
Storage Room (Small) 105 CMR 451.353*	Interior Maintenance: Wet mop stored in bucket
Storage Room (Large) 105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
Lower Level Shower Area 105 CMR 451.123 105 CMR 451.123	Maintenance: Soap scum on mat outside shower # 1 Maintenance: Soap scum on walls in shower # 1
Lower Cells 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # 1-11
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water continually running in cell # 1-16
105 CMR 451.353* 105 CMR 451.353 105 CMR 451.103	Interior Maintenance: Floor paint damaged in cell # 1-25 Interior Maintenance: Floor paint damaged in cell # 1-23 Mattresses: Mattress damaged in cell # 1-19
<i>Upper Level Shower Area</i> 105 CMR 451.123 105 CMR 451.123* 105 CMR 451.123	Maintenance: Mold observed on wall outside shower # 10 Maintenance: Ceiling paint damaged outside shower # 6 Maintenance: Ceiling paint damaged outside shower # 9 and 10
<i>Upper Cells</i> 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water continually running in cell # 2-07 and 2-19
Entrance Hallway for Pod C a	<u>& D</u>

Nurse's Station

No Violations Noted

Female Bathroom

No Violations Noted

Male Bathroom	No Violations Noted
Office	No Violations Noted
Pod C	
<i>Common Area</i> 105 CMR 451.353*	Interior Maintenance: Floor paint damaged
Storage Cage (Barber Shop)	No Violations Noted
Janitor's Closet	No Violations Noted
Storage Room	No Violations Noted
Counselor/Interview Office	No Violations Noted
Multi-Purpose Room	No Violations Noted
Lower Level Shower Area 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Soap scum on walls in shower # 5 Maintenance: Floor dirty in shower # 1 and 5 Maintenance: Debris on floor in shower # 1 Maintenance: Light out in shower # 2 Maintenance: Shower # 3 continually running
Lower Cells 105 CMR 451.126	Hot Water: Hot water temperature recorded at 80^{0} F in cell # 1-06, 1-18, and 1-29
Upper Level Shower Area # 6-7 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123	Maintenance: Shower # 7 out-of-order Maintenance: Soap scum on walls in shower # 6 and 8 Maintenance: Soap scum on floor in shower # 8 and 10
Upper Cells 105 CMR 451.353* 105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 2-25 and 2-26 Interior Maintenance: Floor paint damaged in cell # 2-21
Pod D	
Common Area	No Violations Noted
Storage Cage (Barber Shop)	No Violations Noted
<i>Janitor's Closet</i> 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing on slop sink

Multi-Purpose Room	No Violations Noted
Storage Room	No Violations Noted
Lower Level Shower Area 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Shower # 3 out-of-order Maintenance: Flies observed outside shower # 2 and 3 Maintenance: Walls dirty outside shower # 5 Maintenance: Soap scum on floor in shower # 5
<i>Lower Cells</i> 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, cold water continually running in cell # 1-17
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 1-07
Upper Level Shower Area	No Violations Noted
Upper Cells 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, water continually running in cell # 2-16
<u>Pod F</u>	
<i>Female Staff Bathroom</i> 105 CMR 451.123	Maintenance: Ceiling vent dusty
Janitor's Closet 105 CMR 451.344* 105 CMR 451.353	Illumination in Habitable Areas: Light not functioning properly, light not working Interior Maintenance: Ceiling vent dusty
Male Staff Bathroom	No Violations Noted
Administration Area	No Violations Noted
Medical Office	No Violations Noted
Block	
Janitor's Closet 105 CMR 451.353	Interior Maintenance: Wet mop not stored properly
Barber Shop	Unable to Inspect – In Use
Storage	No Violations Noted
Lower Showers	Unable to Inspect Shower # 6 – In Use No Violations Noted

Lower Cells	No Violations Noted
Assessment Office	No Violations Noted
Library/Multi-Purpose Room	No Violations Noted
Case Worker's Office	No Violations Noted
Upper Cells	No Violations Noted
Upper Showers # 1-10 105 CMR 451.123 105 CMR 451.123	Unable to Inspect Shower # 1 and 2 – In Use Maintenance: Soap scum on walls in shower # 8 Maintenance: Soap scum on floor in shower # 3, 7, 8, and 9
Common Area	No Violations Noted
Dorm # 3 and 4 Landing	
Male Bathroom	No Violations Noted
Female Bathroom	Unable to Inspect - Locked
Janitor's Closet	No Violations Noted
Storage/Med Pass	No Violations Noted
<i>Medical Office</i> 105 CMR 451.126	Hot Water: Hot water temperature recorded at 85 ⁰ F at handwash sink
Classroom # 2	No Violations Noted
Multi-Purpose Hallway	Unable to Inspect Area – Video Trial in Progress
Storage Room # 1 and 2	Unable to Inspect - Video Trial in Progress
Classroom A and B	Unable to Inspect - Video Trial in Progress
Dorm # 3	
Sleeping Area	No Violations Noted

Common Area	No Violations Noted
Toilet Area	
105 CMR 451.124*	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink # 3 and 5
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink # 4 and 7
105 CMR 451.124*	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink $\#$ 3, 5, 6, and 7
105 CMR 451.124	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink # 4
Sink Area	No Violations Noted
Shower Area	Unable to Inspect Shower # 1 – In Use No Violations Noted
Janitor's Closet	No Violations Noted
<i>Case Worker's Office</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, excessive ice buildup in freezer
Barber Shop	No Violations Noted
Dorm # 4	
Barber Shop	No Violations Noted
Case Worker's Office	No Violations Noted
Janitor's Closet	No Violations Noted
<i>Shower Area</i> 105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 1, 2, 3, 4, and 6
<i>Toilet Area</i> 105 CMR 451.123	Maintenance: Handwash sink not draining properly at handwash sink $\# 1$ and 2
<i>Sink Area</i> 105 CMR 451.126* 105 CMR 451.123	Hot Water: Hot water temperature recorded at 90^{0} F at handwash sink # 3 Maintenance: Handwash sink not draining properly at handwash sink # 3
Common Area	No Violations Noted
Sleeping Area	No Violations Noted

<u>Pod E</u>

Administration Area

Female Staff Bathroom	Unable to Inspect – Locked
Janitor's Closet	No Violations Noted
Male Staff Bathroom	No Violations Noted
Offices	No Violations Noted
Nurse's Station	Unable to Inspect – Locked
Block	
Janitor's Closet	No Violations Noted
Barber Shop	No Violations Noted
Storage Room	No Violations Noted
Segregation Showers	No Violations Noted
Segregation Cells 105 CMR 451.113	Toilet and Handwashing Sink in Locked Cells: No cold running water in locked cell # 1-30
Classroom Assessment	No Violations Noted
Library	No Violations Noted
Caseworker's Office	No Violations Noted
Upper Cells	No Violations Noted
Upper Showers 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123*	Maintenance: Soap scum on walls and floor in shower # 3 and 9 Maintenance: Soap scum on floor in shower # 3, 5, and 9 Maintenance: Drain flies observed in shower # 8 and 10

Dorm #1 and 2 Landing

Shift Administrator's Office	No Violations Noted
Janitor's Closet	No Violations Noted
Male Staff Bathroom	No Violations Noted
Female Staff Bathroom	Unable to Inspect - Locked
Storage/Med Pass	Unable to Inspect – Locked
Medical Office	No Violations Noted
Classroom # 1	No Violations Noted
Dorm # 1	
Sleeping Area	No Violations Noted
Common Area	No Violations Noted
Toilet Area	
105 CMR 451.124*	Water Supply: Insufficient hot and cold water supply in quantity and pressure at handwash sink # 3, 5, and 7
105 CMR 451.124	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink # 1, 2, 4, 6, and 8
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash
105 CMR 451.126*	sink # 1 Water Supply: No cold water supplied to handwash sink # 6 and 8
<i>Sink Area</i> 105 CMR 451.126*	Water Supply: No hot water supplied to handwash sink # 3
Shower Area 105 CMR 451.123 105 CMR 451.123*	Maintenance: Mold observed in corner of shower # 3 Maintenance: Mold observed on caulking around shower controls in shower # 1
Janitor's Closet 105 CMR 451.353	Interior Maintenance: Unlabeled chemical bottle
Case Worker's Office	No Violations Noted
Barber Shop 105 CMR 451.353	Interior Maintenance: No cleaning solution present for hair clipping equipment

Dorm # 2

Barber Shop	No Violations Noted
Case Worker's Office 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator out-of-order
Janitor's Closet	No Violations Noted
Shower Area 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Mold observed on caulking in shower # 7 Maintenance: Mold observed on caulking in shower # 6 Maintenance: Soap scum observed on walls in shower # 3 Maintenance: Floor dirty in shower # 6 and 8
Toilet Area	Unable to Inspect – In Use
Sink Area	Unable to Inspect – In Use
Common Area	No Violations Noted
Sleeping Area	No Violations Noted
Intake and Discharge	
Deputy's Office 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functioning thermometer in refrigerator
Janitor's Closet	No Violations Noted
Administrative Office	No Violations Noted
Holding Tank # 2	No Violations Noted
Shake Room #1 & 2	No Violations Noted
<i>Holding Cell # 1</i> 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, water continually running
Institutional Property	No Violations Noted
Desk Area	No Violations Noted

Sally Port	No Violations Noted
Old Shower Room # 1	No Violations Noted
<i>Holding Cell # 1-6</i> 105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 4
Break Room	No Violations Noted
Male Bathroom	No Violations Noted
Female Bathroom	No Violations Noted
Inmate Property Room	No Violations Noted
Change Room # 1 and 2	No Violations Noted
<u>A & B Hall Entrance</u>	
Janitor's Closet	No Violations Noted
Teacher's Office	No Violations Noted
Hall A	No Violations Noted
Hall B	No Violations Noted
Food Service Area	
Staff Dining Room FC 4-501.11(B)	Maintenance and Operation, Equipment: Equipment components not maintained in a
FC 4-501.114(A)	state of good repair, gasket damaged on right side refrigerator Maintenance and Operation; Equipment: Chlorine sanitizer solution tested less than recommended concentration
Male Bathroom	No Violations Noted
<i>Female Bathroom</i> 105 CMR 451.123	Maintenance: Handwash sink not draining properly
Supply Dock	
Loading Dock	No Violations Noted

Surplus Storage Room	No Violations Noted
Storage Room	No Violations Noted
Back of Kitchen	
Supply Room # 2 (Dry Storage) FC 3-304.12(A)*	Preventing Contamination from Utensils: Service utensils handle stored below the food and container line, scoop stored in cereal container
Culinary Arts Storage Cabinet	Unable to Inspect - Locked
Chemical Supply Closet	No Violations Noted
Daily Cleaning Cabinet	No Violations Noted
Kitchen Staff Break Room	No Violations Noted
Supply Room # 1	No Violations Noted
Inmate Bathroom 105 CMR 451.124 105 CMR 451.123	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink Maintenance: Door paint damaged
Staff Bathroom 105 CMR 451.123	Maintenance: Cold water handle leaking at handwash sink
Rack Spray Area	No Violations Noted
Main Kitchen Area	
Cooler # 1	No Violations Noted
<i>Warmer # 1 & 2</i> FC 4-501.11(B)*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged on warmer # 2
<i>Serving Line</i> FC 4-901.11(A) FC 2-402.11	Protection of Clean Items, Drying: Clean and sanitized trays not allowed to air dry fully Hygienic Practices; Hair Restraints: Food service personnel not wearing appropriate hair restraints, hair nets not worn properly
Handwash Sink – Near Pots and FC 5-205.15(B)	<i>d Pans Sink</i> Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, handwash sink out-of-order
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, floor tiles damaged around floor drain

Pots and Pan Sink FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, wash basin leaking
Mechanical Warewash Area FC 6-501.11	Maintenance and Operation; Repairing: Facility not in good repair, grease trap access panel rusted
Warewash Machine	No Violations Noted
Handwash Sink after Warewash	<i>Machine</i> No Violations Noted
Inmate Coffee Area FC 4-903.11(A)(2)*	Protection of Clean Items, Storing: Single-service items not protected from contamination, disposable silverware left uncovered
Serving Line # 2	No Violations Noted
<i>Warmer # 3 & 4</i> FC 4-502.11(C)	Maintenance and Operation, Temperature: Temperature measuring devices not calibrated properly on warmer # 3
<i>Refrigerator # 2</i> FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, refrigerator # 2 out-of-order
McCall Proofer # 1	No Violations Noted
3 Warmers (under hoods) FC 6-501.11 FC 3-304.12(A)	Maintenance and Operation; Repairing: Facility not in good repair, light out under hood Preventing Contamination from Utensils: Service utensils handle stored below the food and container line, scoop stored in oats bin
Prep Tables and Sinks FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in
FC 5-205.15(B)	good repair, hot water handle leaking on prep sink # 8 Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, no hot water supplied to both single bay prep sinks
FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, trap leaking on single bay prep sink closets to hoods
FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, uncovered floor drain under single bay prep sink
FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, no cold water supplied to handwash sink
Ice Machine # 4	No Violations Noted
Ice Machine # 2	No Violations Noted

Handwash Sink (after ice machine # 2) No Violations Noted

Kettle Area		
FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, fill station broken on kettle # 1-3	
FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, kettle hinges not functioning properly	
FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, uncovered floor drain	
FC 6-501.11	Maintenance and Operation; Repairing: Facility not in good repair, standing water observed on floor around kettle area	
<i>Walk-in Refrigerator # 2</i>	No Violations Noted	
Spice Cabinet FC 3-302.12	Preventing Food and Ingredient Contamination: Unlabeled food containers	
Walk-in Refrigerator # 1	No Violations Noted	
Hood Area with Warmers FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, 2 lights not working under hoods	
Walk-in Freezer FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, 2 wall condenser fans out-of-order	
Sallyport/Changing Area	No Violations Noted	
Janitor's Closet	No Violations Noted	
Officer's Area/Office	No Violations Noted	
Culinary Arts Program Kitchen		
Classroom	No Violations Noted	
McCall Refrigerator	No Violations Noted	
<i>Proofers</i> FC 4-501.11(B)	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, proofer out-of-order	
Walk-in Freezer	No Violations Noted	

<i>Hood Area</i> FC 4-501.11(B)	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, 1 oven out-of-order
Handwash Sink	No Violations Noted
3-Bay Sink	No Violations Noted
Prep Sink	No Violations Noted
Prep Tables	No Violations Noted
Walk-in Refrigerator	No Violations Noted
Health Service Unit	
ISO # 1 & 2	Unable to Inspect ISO # 2 – No Longer in Use No Violations Noted
<i>Nurse's Pantry</i> 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, handwash sink continually running
Janitor's Closet	No Violations Noted
Risk Cell # 1 & 2	No Violations Noted
Private Rooms # 1-4 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, water continually running at handwash sink in room # 4
Ward A	No Violations Noted
Storage Room	No Violations Noted
Handicap Shower Room	No Violations Noted
Nurse's Station and Bathroom	No Violations Noted
Cleaning Utility Room	No Violations Noted
Storage Room # 1	No Violations Noted

Storage Room # 2	No Violations Noted
Holding	No Violations Noted
Ward B	No Violations Noted
Pharmacy	No Violations Noted
Janitor's Closet 105 CMR 451.344* 105 CMR 451.130	Illumination in Habitable Areas: Light not functioning properly, light out Plumbing: Plumbing not maintained in good repair, brown water observed coming out of slop sink
Physical Therapy (Treatment R	oom # 4) No Violations Noted
Treatment Room # 1	No Violations Noted
Inmate Bathroom	No Violations Noted
Treatment Room # 2	No Violations Noted
Medical Waste Storage	No Violations Noted
Treatment Room # 3	No Violations Noted
Coordinator's Office	No Violations Noted
Lab	No Violations Noted
Dental Room	Unable to Inspect – In Use
Infectious Disease Office 105 CMR 480.500(B)(2)	Procedures; Records; Record-Keeping Log: Generator did not maintain a record-keeping log for waste sent off-site for treatment, incomplete record keeping log
Psychiatry Office	No Violations Noted
Exam Room # 2	No Violations Noted
Exam Room # 1	No Violations Noted

HSU Administration Hallway

Male Bathroom	No Violations Noted
Female Bathroom	No Violations Noted
Medical Records	No Violations Noted
Health Service Administrator's	Office No Violations Noted
Classifications Building	
Main Level	
Lobby	No Violations Noted
Janitor's Closet 105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
<i>Female Bathroom</i> 105 CMR 451.123* 105 CMR 451.123*	Maintenance: Toilet # 2 out-of-order Maintenance: Window broken
Male Bathroom 105 CMR 451.130* 105 CMR 451.130* 105 CMR 451.124*	Plumbing: No backflow preventer on sink Plumbing: Plumbing not maintained in good repair, drain cover missing in slop sink Water Supply: Insufficient cold water supply in quantity and pressure at slop sink
<i>Control Area</i> 105 CMR 451.350* 105 CMR 451.350* 105 CMR 451.350* 105 CMR 451.353* 105 CMR 451.141	Structural Maintenance: Windows not weathertight and structurally sound Structural Maintenance: Window sills and wall near windows damaged Structural Maintenance: Several window panes broken Interior Maintenance: Ceiling tiles missing Screens: Screen damaged
Roll Call Room	No Violations Noted
Old Administration Wing	
First Floor	
Offices	No Violations Noted
Storage Closet	No Violations Noted
Female Bathroom	Unable to Inspect – In Use

Tool Crib Area	No Violations Noted
<i>Tool Crib Bathroom</i> 105 CMR 451.123* 105 CMR 451.353*	Maintenance: Sink rusted Interior Maintenance: Light shield missing
Mail Room 105 CMR 451.353* 105 CMR 451.200*	Interior Maintenance: Ceiling tiles missing Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, excessive ice buildup in freezer
Canteen Area	No Violations Noted
Second Floor	
Male Bathroom # 2 105 CMR 451.123* 105 CMR 451.126*	Maintenance: Ceiling tiles water damaged Hot Water: Hot water temperature recorded at 92°F at handwash sink # 1
New Male Locker Room 105 CMR 451.353	Interior Maintenance: Window sills and floor dirty
Male Locker Room Bathroom 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123	Maintenance: Window broken Maintenance: Water stained ceiling tiles Maintenance: Screen missing
Male Shower Room	No Violations Noted
Old Infirmary 105 CMR 451.353	Interior Maintenance: Ceiling tiles missing
Offices	No Violations Noted
Female Bathroom 105 CMR 451.123*	Maintenance: Wall damaged around window
Male Bathroom # 1 105 CMR 451.123* 105 CMR 451.124* 105 CMR 451.123*	Maintenance: Window broken Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink Maintenance: Wall paint damaged
Old Shower Room	No Violations Noted
<i>Staff Break Room</i> 105 CMR 451.353 105 CMR 451.360	Interior Maintenance: Wall paint damaged Protective Measures: Bird observed in break room
Offices	No Violations Noted

Third Floor 105 CMR 451.350 105 CMR 451.141	Structural Maintenance: Several window panes broken throughout area Screens: Screens damaged throughout area
Male Locker Room	No Violations Noted
<i>Male Locker Room Bathroom</i> 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123	Maintenance: Wall paint damaged near soap dispenser # 3 Maintenance: Floor paint damaged Maintenance: Light out in shower # 1 and 2
Female Locker Room 105 CMR 451.350 105 CMR 451.123	Structural Maintenance: Window pane broken Maintenance: Water stained ceiling tiles outside right side shower
<i>Officer's Weight Room</i> 105 CMR 451.350*	Structural Maintenance: Window panes broken
Lower Report	
A & B Side Cells	Unable to Inspect – No longer in use due to lack of natural lighting
Training Center	
First Floor	
Barber Area	No Violations Noted
Library	No Violations Noted
Meeting Room	No Violations Noted
Offices and Classroom	No Violations Noted
Bathroom 105 CMR 451.123*	Maintenance: Window broken
Storage Room 105 CMR 451.130*	Plumbing: No backflow preventer on slop sink
Chapel	No Violations Noted
Second Floor	
<i>Main Laundry</i> 105 CMR 451.350*	Structural Maintenance: Window broken
Inmate Bathroom 105 CMR 451.350*	Structural Maintenance: Window broken

451-17(2)-Middlesex-Billerica-Report 6-27-17

<i>Officer's Bathroom</i> 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.124	Maintenance: Wall paint peeling on brick wall Maintenance: Window cracked Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink
Laundry Storage	No Violations Noted
Main Level	
Old Wing Day Room	No Violations Noted
Side Entry Stairs	No Violations Noted
HUMV Dorm Room	No Violations Noted
Dorm Bathroom 105 CMR 451.124*	Water Supply: Insufficient hot and cold water supply in quantity and pressure at handwash sink # 1 and 2
105 CMR 451.123	Maintenance: Wall paint damaged outside handicap shower
First Tier	
Control	No Violations Noted
Janitor's Closet	No Violations Noted
A & B Side 105 CMR 451.320* 105 CMR 451.353 105 CMR 451.353* 105 CMR 451.353 105 CMR 451.353* 105 CMR 451.353*	Cell Size: Inadequate floor space in all cells Interior Maintenance: Wall paint damaged in cell # A16 and A17 Interior Maintenance: Floor paint damaged in cell # A2, A15, and B12 Interior Maintenance: Floor paint damaged in cell # A8 and B8 Interior Maintenance: Ceiling damaged in cell # A12 Interior Maintenance: Ceiling damaged in cell # B9
Bathroom and Shower Area 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.124* 105 CMR 451.124* 105 CMR 451.124 C & D Side (Administrative Seg 105 CMR 451.320* 105 CMR 451.353*	Cell Size: Inadequate floor space in all cells Interior Maintenance: Ceiling damaged in cell # C14 and C20
105 CMR 451.353* 105 CMR 451.353 105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # C13, C16, C19, D7, D13, and D16 Interior Maintenance: Wall paint damaged in cell # C5, C10, and C18 Interior Maintenance: Floor paint damaged in cell # C9, C10, and D12

Shower Room # D23 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123	Maintenance: Ceiling paint damaged Maintenance: Mold observed on wall near shower head Maintenance: Floor drain dirty
Second Tier 105 CMR 451.353* 105 CMR 451.350	Interior Maintenance: Multiple cell windows painted Structural Maintenance: Window pane broken in stairway
Nurse 's Room 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water foot petal broken at handwash sink
Control	No Violations Noted
<i>E & F Side</i> 105 CMR 451.320* 105 CMR 451.353 105 CMR 451.353 105 CMR 451.103	Cell Size: Inadequate floor space in all cells Interior Maintenance: Floor paint damaged in cell # E6, E7, F5, F6, F14, and F16 Interior Maintenance: Ceiling paint damaged in cell # E10, E11, E16, and F18 Mattresses: Mattress damaged in cell # F4
Bathroom and Shower Area 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.124 105 CMR 451.123	Maintenance: Wall tile grout dirty in shower # 4 Maintenance: Wall tiles dirty in shower # 1, 2, 4, 7, 8, 10, and 11 Maintenance: Wall tile grout missing in shower # 10 Maintenance: Floor drain not draining properly in shower # 3 Water Supply: Insufficient cold water supply in quantity and pressure at slop sink Maintenance: Mold observed on wall around handwash sink
Janitorial Cage 105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
G & H Side 105 CMR 451.320* 105 CMR 451.353 105 CMR 451.353 105 CMR 451.353	Cell Size: Inadequate floor space in all cells Interior Maintenance: Floor paint damaged in cell # G12, G19, G20, H4, and H13 Interior Maintenance: Wall paint damaged in cell # G22 and H24 Interior Maintenance: Ceiling paint damaged in cell # H3, H4, H19, and H25
Gym 105 CMR 451.350*	Structural Maintenance: Windows not weathertight and structurally sound
Gym Office	No Violations Noted
Staff Bathroom 105 CMR 451.110(A)*	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink
Stairway to Third Tier	No Violations Noted
Third Tier 105 CMR 451.353*	Interior Maintenance: Multiple cell windows painted
Day Room	No Violations Noted

Control	
	No Violations Noted
Offices	
	No Violations Noted
I & J Side	
105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
105 CMR 451.126*	Hot Water: Hot water temperature recorded at 80°F in cell # J5
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet continually flushing in cell # J10
105 CMR 451.103	Mattresses: Mattress damaged in cell # J8 and I21
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 15, 111, 120, J5, J14, and J18
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # J24
Bathroom and Shower Area	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing on slop sink
105 CMR 451.123	Maintenance: Wall tiles dirty in shower # 2 and 10
105 CMR 451.123	Maintenance: Drain flies observed in shower # 3 and 10
105 CMR 451.123	Maintenance: Urinal out-of-order
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water continually running at
	handwash sink
Janitor's Closet	
	No Violations Noted
K & L Side	
105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # L24
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # K2, L16, and L19
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water continually running in cell # L15
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet not flushing properly in cell $\#$ L15
105 CMR 451.113	Toilet and Handwashing Sink in Locked Cells: No hot running water in locked cell # K11
105 CMR 451.103	Mattresses: Mattress damaged in cell # K3
CWP Building	Unable to Insure the Duilding Classed and Dains Demonstral
	Unable to Inspect – Building Closed and Being Renovated
Work Release Building	
<u>House # 1</u>	
First Floor	
Hallway	
	No Violations Noted
Infirmary	No. Violationa Notad
	No Violations Noted
Control	No Violations Noted

Office	No Violations Noted
Bathroom	No Violations Noted
Bedrooms 105 CMR 451.353*	Interior Maintenance: Wall paint damaged in room # 3
Food Service Area	
Dining Room FC 6-202.15(A)(3)	Design, Construction, and Installation; Functionality: Outer door not weather and vermin tight
<i>Kitchen</i> FC 4-101.16* FC 3-501.16(B)	Materials for Construction and Repair; Multiuse: Sponges used in kitchen Limitation of Growth of Organisms, Temperature and Time Control: Refrigerator temperature recorded at 48°F
Second Floor	
<i>Stairway</i> 105 CMR 451.353	Interior Maintenance: Light shield missing
Hallway	No Violations Noted
Bedrooms	No Violations Noted
Bathroom 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Wall damaged near shower head in shower # 1 Maintenance: Floor dirty in shower # 1 and 2 Maintenance: Soap scum on shower curtain in shower # 2 and 3 Maintenance: Screen missing
Stairway to Basement	No Violations Noted
Basement	
Laundry Room 105 CMR 451.353	Interior Maintenance: Excessive lint buildup in dryer
Boiler Room	Unable to Inspect – Locked
Chemical Storage Room	No Violations Noted
Day Room Between Houses 105 CMR 451.353 105 CMR 451.353	Interior Maintenance: Floor tiles damaged Interior Maintenance: Small hole in floor near vending machine

<u>House # 2</u>

First Floor

Hallway	No Violations Noted	
Night Shift Office 105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged near light fixture	
<i>Officer's Bathroom</i> 105 CMR 451.140*	Adequate Ventilation: Inadequate ventilation, no means for ventilation	
Bedrooms	Concerne Concerning in an an # 1	
105 CMR 451.141 105 CMR 451.346	Screens: Screen missing in room # 1 Safe Wiring: Inappropriate use of temporary wiring, cord to standing fan extended through doorway	
Administration Office	No Violations Noted	
Second Floor		
Hallway	No Violations Noted	
Bathroom		
105 CMR 451.123*	Maintenance: Mold observed on caulking around sink # 2	
105 CMR 451.123*	Maintenance: Counter top cracked near sink # 2	
105 CMR 451.123 105 CMR 451.123	Maintenance: Curtain dirty on toilet stall # 2 Maintenance: Screen missing	
Bedrooms 105 CMR 451.141	Screens: Screen missing in room # 3	
Third Floor		
Bedrooms	No Violations Noted	
Basement		
Day Room		
105 CMR 451.353*	Interior Maintenance: Padding damaged on exercise equipment	
Property	Unable to Inspect – Locked	
Bathroom		
105 CMR 451.123	Maintenance: Hole in wall above wooden heater covering	
105 CMR 451.123	Maintenance: Wall covering damaged in toilet stall # 1	
105 CMR 451.123	Maintenance: Ceiling damaged near toilet stall # 2	
105 CMR 451.123	Maintenance: Mold observed on caulking in shower # 3	
Storage Room	NT- X7:-1-4: NT-4-J	
	No Violations Noted	

WAREHOUSE

WINDHOUSE	No Violations Noted
Office	No Violations Noted
Female Bathroom	No Violations Noted
Male Bathroom	No Violations Noted
Janitor's Closet	No Violations Noted
Old Walk-in Freezer	No Violations Noted
Back Freezer and Refrigerator	No Violations Noted

Observations and Recommendations

- 1. The inmate population was 907 at the time of inspection.
- 2. The Department recommended the use of anti-slip and anti-fatigue floor mats within the kitchen.
- 3. During the inspection of Pod A, the Department observed an inmate to be without hot or cold running water within his cell. As an interim measure the Unit Officer's immediately moved the inmate to another cell with access to hot and cold running water.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at <u>www.mass.gov/dph/dcs</u> and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at <u>www.mass.gov/dph/fpp</u> and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X – Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

To review the Labeling regulations please visit the Food Protection website at <u>www.mass.gov/dph/fpp</u> and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,

Wagne

Kerry Wagner, MPH Environmental Health Inspector, CSP, BEH

cc:

Jan Sullivan, Acting Director, BEH Steven Hughes, Director, CSP, BEH Timothy Miley, Director of Government Affairs Marylou Sudders, Secretary, Executive Office of Health and Human Services Thomas Turco, Commissioner, DOC Shawn Jenkins, Special Sheriff Osvaldo Vidal, Superintendent of Operations Carole Cafferty, Superintendent of Administration and Programs Services Sergeant Shane Cassidy, EHSO Captain William Buckley, EHSO Richard Berube, Director, Billerica Board of Health Clerk, Massachusetts House of Representatives Clerk, Massachusetts Senate Daniel Bennett, Secretary, EOPSS Nelson Alves, Director, Policy Development and Compliance Unit