

MAURA T. HEALEY Governor KIMBERLEY DRISCOLL Lieutenant Governor

The Commonwealth of Massachusetts

Executive Office of Health and Human Services Department of Public Health Bureau of Climate and Environmental Health **Community Sanitation Program** 67 Forest Street, Suite # 100 Marlborough, MA 01752 Phone: 617-448-7410

KATHLEEN E. WALSH Secretary

ROBERT GOLDSTEIN, MD, PhD Commissioner

> Tel: 617-624-6000 www.mass.gov/dph

May 23, 2024

Peter J. Koutoujian, Sheriff Middlesex County Sheriff's Office 400 Mystic Avenue Medford, MA 02155

(electronic copy)

Re: Facility Inspection - Middlesex County Jail and House of Corrections, Billerica

Dear Sheriff Koutoujian:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Minimum Requirements for the Management of Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 2013 Food Code; 105 CMR 500.000 Good Manufacturing Practices for Food; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; the Department's Community Sanitation Program (CSP) conducted an inspection of Middlesex County Jail and House of Corrections on May 8, 9, and 10, 2024 accompanied by Deputy Dan Finn, Captain Kara Turco, and Captain Shane Cassidy, Environmental Health and Safety Officer. Violations noted during the inspection are listed below including 154 repeat violations:

Should you have any questions, please don't hesitate to contact me.

Sincerely,

Kerry Wagner, MPH Field Supervisor, EA III, CSP, BCEH

cc:	Robert Goldstein, MD, PhD, Commissioner, DPH	
	Nalina Narain, Director, BCEH	
	Steven Hughes, Director, CSP, BCEH	
	Kathleen E. Walsh, Secretary, Executive Office of Health and Human Services	(electronic copy)
	Carol A. Mici, Commissioner, DOC	(electronic copy)
	Terrence Reidy, Secretary, EOPSS	(electronic copy)
	Brianna Arruda, Director, Policy Development and Compliance Unit	(electronic copy)
	Osvaldo Vidal, Superintendent	(electronic copy)
	Captain Shane Cassidy, EHSO	(electronic copy)
	Kristel Bennett, Director, Billerica Board of Health	(electronic copy)
	Clerk, Massachusetts House of Representatives	(electronic copy)
	Clerk, Massachusetts Senate	(electronic copy)

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

CHECKPOINT BUILDING

Janitor's Closet	No Violations Noted
Male Bathroom	No Violations Noted
Female Bathroom	No Violations Noted
Control Desk	No Violations Noted
PODULAR BUILDING	
Lobby	No Violations Noted
Water Fountain	No Violations Noted
Female Bathroom	Unable to Inspect – In Use
Male Bathroom # 5-164	No Violations Noted
Janitor's Closet	No Violations Noted
Administration Wing	
Offices	Unable to Inspect – Locked
<i>Female Bathroom # 5-183</i> 105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 100 ⁰ F at handwash sink
Male Bathroom # 5-180	No Violations Noted
Janitor's Closet # 5-181	No Violations Noted
Kitchenette 105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, single service utensils left uncovered
Conference Room	No Violations Noted

Visiting Area	No Violations Noted
Visitor's Side	No Violations Noted
Central Control	No Violations Noted
Bathroom	No Violations Noted
Attorney Visit Hallway	
Janitor's Closet	No Violations Noted
Visiting Rooms	No Violations Noted
Male Bathroom # 5-148	No Violations Noted
Female Bathroom # 5-146	No Violations Noted
Visiting Control Room # 5-144 105 CMR 451.350* 105 CMR 451.353* 105 CMR 451.200*	Structural Maintenance: Ceiling heavily damaged Interior Maintenance: Floor tiles damaged Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, single service utensils left uncovered
105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, drawer broken in white refrigerator
105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of large white refrigerator dirty
105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
105 CMR 451.353	Interior Maintenance: Floor dirty throughout Control Room
<i>Inmate Bathroom # 5-145A</i> 105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink
Storage Room # 5-145B	Unable to Inspect – Locked
Visiting Area – Inmate Side	No Violations Noted
Family/Child Visiting Area	No Violations Noted
Entrance Hallway for Pod A	<u>& B</u>
Nurse's Station	No Violations Noted

Female Bathroom	No Violations Noted
Male Bathroom 105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 90°F at handwash sink
Janitor's Closet	No Violations Noted
Caseworker's Office	No Violations Noted
Pod A	
Common Area 105 CMR 451.353	Interior Maintenance: Padding damaged on exercise equipment
Storage Cage (Barber Shop)	Unable to Inspect – Under Construction
Janitor's Closet 105 CMR 451.353 105 CMR 451.130	Interior Maintenance: Ceiling damaged Plumbing: Plumbing not maintained in good repair, backflow preventer rusted
Counselor/Interview Room # 5- 105 CMR 451.200	062Food Storage, Preparation and Service: Food storage not in compliance with105 CMR 590.000, no functioning thermometer in refrigerator
<i>Room # 5-063</i>	No Violations Noted
Pod Storage Room # 5-061	No Violations Noted
Lower Level Shower Area # 1-5 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.130	Maintenance: Screws missing on wall in handicapped shower Maintenance: Ceiling damaged outside shower # 1 and 3 Maintenance: Soap scum on walls in shower # 1 and handicapped shower Maintenance: Soap scum on bench in handicapped shower Maintenance: Wall dirty outside shower # 1 Plumbing: Plumbing not maintained in good repair, shower head leaking in handicapped shower
Lower Cells	No Violations Noted
<i>Upper Level Shower Area # 6-1</i> 105 CMR 451.123 105 CMR 451.130	0 Maintenance: Mold on walls in shower # 9 Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # 9
Upper Cells	No Violations Noted

Pod B

Common Area	No Violations Noted	
Storage Room # 5-085	No Violations Noted	
<i>Counselor's Office # 5-084</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty	
Storage Cage (Barber Shop) # .	5-081 No Violations Noted	
Janitor's Closet # 5-080	No Violations Noted	
Storage Room # 5-082	No Violations Noted	
Classroom/Storage Room # 5-0	83 No Violations Noted	
Lower Level Shower Area 105 CMR 451.123 105 CMR 451.123	Maintenance: Soap scum on walls in shower # 2 and handicapped shower Maintenance: Debris on floor in handicapped shower	
Lower Cells	No Violations Noted	
Upper Level Shower Area 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Ceiling damaged outside shower # 9 and 10 Maintenance: Mold on ceiling outside shower # 10 Maintenance: Debris on floor in shower # 7, 8, and 10	
Upper Cells	No Violations Noted	
Entrance Hallway for Pod C & D		
<i>Nurse's Station # 5-212</i>	No Violations Noted	
Female Bathroom # 5-215	No Violations Noted	
Male Bathroom # 5-204	No Violations Noted	
Offices	No Violations Noted	

Pod C

<i>Common Area</i> 105 CMR 451.353*	Interior Maintenance: Mold on ceiling and ceiling tile near cell # 2-01
Storage Cage (Barber Shop) # 105 CMR 451.130*	5-207 Plumbing: Plumbing not maintained in good repair, urinal clogged
Janitor's Closet # 5-206	No Violations Noted
Pod Storage Room # 5-201	No Violations Noted
Counselor/Interview Office #5- 105 CMR 451.200 105 CMR 451.200	202 Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of refrigerator dirty Food Storage, Preparation and Service: Food preparation not in compliance with
	105 CMR 590.000, interior of microwave oven dirty
<i>Multi-Purpose Room # 5-203</i> 105 CMR 451.353	Interior Maintenance: Chair seat damaged
Lower Level Shower Area 105 CMR 451.130* 105 CMR 451.130 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # 2 Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # 3 Maintenance: Light fixture rusted in shower # 1 Maintenance: Light fixture rusted in shower # 3 Maintenance: Screws missing on wall in handicapped shower Maintenance: Soap scum on walls in shower # 1, 2, and 3 Maintenance: Wall dirty outside shower # 3
<i>Lower Cells</i> 105 CMR 451.353 105 CMR 451.353 105 CMR 451.130	Interior Maintenance: Floor paint damaged in cell # 1-13 and 1-22 Interior Maintenance: Wall vent clogged in cell # 1-13 Plumbing: Plumbing not maintained in good repair, hot water push button not secured to handwash sink in cell # 1-13
Upper Level Shower Area 105 CMR 451.110(A)* 105 CMR 451.110(A) 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink Maintenance: Handwash sink dirty Maintenance: Soap scum on floor in shower # 6, 7, and 8 Maintenance: Ceiling vents outside showers dusty
<i>Upper Cells</i> 105 CMR 451.353	Interior Maintenance: Wall vent clogged in cell # 2-26
Pod D	
Common Area	No Violations Noted

Storage Cage (Barber Shop) #.	5-214	
105 CMR 451.130 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, urinal clogged Plumbing: Plumbing not maintained in good repair, handwash sink leaking at bottom	
105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	
Janitor's Closet # 5-213 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing	
Counselor/Interview Room # 5-	217	
	No Violations Noted	
Multi-Purpose Room # 5-216	No Violations Noted	
Pod Storage Room # 5-218	No Violations Noted	
Lower Level Shower Area		
105 CMR 451.123*	Maintenance: Debris on floor in shower # 1	
105 CMR 451.123 105 CMR 451.123	Maintenance: Ceiling damaged outside shower # 1 Maintenance: Mold on ceiling outside shower # 5	
105 CMR 451.125	Maintenance: Ceiling vents dusty outside showers	
Lower Cells		
105 CMR 451.130* 105 CMR 451.353	Plumbing: Plumbing not maintained in good repair, toilet leaking in cell # 1-17 Interior Maintenance: Pooling water on floor in cell # 1-17	
Upper Level Shower Area		
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # 1 and 2	
105 CMR 451.123	Maintenance: Floor damaged outside shower # 3	
105 CMR 451.123	Maintenance: Debris on floor in shower # 4 and 5	
105 CMR 451.123	Maintenance: Wall dirty outside shower # 5	
105 CMR 451.123	Maintenance: Ceiling vents dusty outside showers	
Upper Cells		
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, water continually running in	
	cell # 2-31	
105 CMR 451.353	Interior Maintenance: Floor dirty in cell # 2-01	
<u>Pod F</u>		
Administration Area		
	No Violations Noted	
Trash Storage Room # 6-200	No Violations Noted	
Female Staff Bathroom # 6-201		
	No Violations Noted	
Janitor's Closet # 6-202		
105 CMR 451.353*	Interior Maintenance: Wet mop stored in bucket	
	1	
Male Staff Bathroom # 6-203		
	No Violations Noted	
451-24(1)-Middlesex-Billerica-Re	port 5-23-24 Page 7 of 32	

<i>Medical Office # 6-206</i> 105 CMR 451.353	Interior Maintenance: Ceiling damaged near light fixture
Block	
Janitor's Closet # 6-207	No Violations Noted
<i>Storage</i> # 6-208	No Violations Noted
Lower Showers 105 CMR 451.123* 105 CMR 451.130* 105 CMR 451.123	Maintenance: Mold on caulking in shower # 6 Hot Water: Shower water temperature recorded at 80°F in shower # 6 Maintenance: Soap scum on walls in shower # 6
<i>Lower Cells</i> 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet push button leaking in cell # 1-24
Gym # 1-19	No Violations Noted
Laundry Room # 1-01	No Violations Noted
Music Room #1-02	No Violations Noted
The Club House #1-03	No Violations Noted
<i>Kitchen # 1-04</i>	No Violations Noted
Library #1-05	No Violations Noted
Barber Shop # 1-06 105 CMR 451.124*	Water Supply: Insufficient hot and cold water supply in quantity and pressure at handwash sink
Assessment Office # 6-211	No Violations Noted
Library/Multi-Purpose Room #	6-210 No Violations Noted
Case Worker's Office # 6-209	No Violations Noted

<i>Upper Cells</i> 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, toilet/handwash sink combination
105 CMR 451.130	unit out-of-order in cell # 2-02 Plumbing: Plumbing not maintained in good repair, toilet push button not working in cell # 2-16
105 CMR 451.346*	Safe Wiring: Inappropriate use of temporary wiring, extension cord running across top tier walkway
<i>Upper Showers # 1-10</i> 105 CMR 451.123 105 CMR 451.123	Maintenance: Soap scum on walls in shower # 9 and 10 Maintenance: Floor dirty in shower # 7, 9, and 10
<i>Common Area</i> 105 CMR 451.123 105 CMR 451.124	Maintenance: Pooling water at base of toilet near entrance Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink near entrance
Dorm # 3 and 4 Landing	
Male Bathroom #6-212	No Violations Noted
Female Bathroom # 6-213	Unable to Inspect – Locked
Trash Room # 6-214	No Violations Noted
Janitor's Closet # 6-215	No Violations Noted
Storage/Med Pass # 6-221	No Violations Noted
<i>Medical Office # 6-226</i>	Unable to Inspect – In Use
Classroom # 2 (6-227)	No Violations Noted
Multi-Purpose Hallway	No Violations Noted
Storage Room # 6-217	Unable to Inspect – Locked
Storage Room # 6-218	No Violations Noted
<i>Classroom A and B # 6-219 and</i> 105 CMP 451 200	
105 CMR 451.200 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of refrigerator dirty in Classroom B Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty in Classroom B

Dorm # 3

Sleeping Area	No Violations Noted
<i>Common Area</i> 105 CMR 451.353*	Interior Maintenance: Standing fan dusty
<i>Toilet Area</i> 105 CMR 451.117 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.124	Toilet Fixtures: Toilet fixture dirty in stall # 3 Maintenance: Handwash sink dirty in stall # 7 Maintenance: Floor dirty in stall # 1, 2, and 3 Maintenance: Hot and cold water push buttons corroded in stall # 8 Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink # 2
Handwash Sink Area 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, handwash sink # 3 slow to drain
Shower Area 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Mold on caulking in shower # 1 and 2 Maintenance: Soap scum on floor in shower # 4 and 5 Maintenance: Floor dirty in shower # 8 Maintenance: Soap scum on bench in shower # 1
Janitor's Closet	No Violations Noted
<i>Case Worker's Office</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
Barber Shop	No Violations Noted
Dorm # 4	
Barber Shop	No Violations Noted
Case Worker's Office	No Violations Noted
Janitor's Closet	No Violations Noted
Shower Area 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123*	Unable to Inspect Shower # 7 – In Use Maintenance: Soap scum on walls in shower # 3 and 6 Maintenance: Soap scum on floor in shower # 2 and 3 Maintenance: Floor dirty in shower # 1 Maintenance: Soap scum on bench in shower # 8
<i>Toilet Area</i> 105 CMR 451.124	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink in stall # 3 and 4
105 CMR 451.124*	Water Supply: No cold water supplied to handwash sink in stall # 3

Handwash Sink Area 105 CMR 451.126 105 CMR 451.124	Hot Water for Bathing and Hygiene: No hot water supplied to handwash sink # 2 Water Supply: Discolored water observed at handwash sink # 1
<i>Common Area</i> 105 CMR 451.353	Interior Maintenance: Padding damaged on exercise equipment
Sleeping Area	No Violations Noted
<u>Pod E</u>	
Administration Area	
Female Staff Bathroom # 6-101	No Violations Noted
Janitor's Closet # 6-102	No Violations Noted
Male Staff Bathroom #6-103	No Violations Noted
<i>Offices # 6-104 and 6-105</i>	No Violations Noted
<i>Nurse's Station</i> # 6-107	Unable to Inspect – Locked
Trash Storage Room # 6-100	No Violations Noted
Block	
Janitor's Closet # 6-106	No Violations Noted
Barber Shop	No Violations Noted
Storage Room # 6-108 105 CMR 451.383(B)*	Fire Safety System: Facility not in compliance with 780 CMR Massachusetts Building Code provisions for fire safety, items stored within 18 inches of the ceiling
Lower Showers 105 CMR 451.123	Maintenance: Floor drain damaged in shower # 2
Lower Cells 105 CMR 451.130 105 CMR 451.353	Plumbing: Plumbing not maintained in good repair, toilet clogged in cell # 1-12 Interior Maintenance: Wall vent blocked in cell # 1-19 and 1-31
Classroom/Assessment # 6-111	No Violations Noted

Caseworker's Office # 6-110 105 CMR 451.340* Illumination: Insufficient lighting, lights out

<i>Office # 6-109</i>	No Violations Noted
<i>Upper Cells</i> 105 CMR 451.103 105 CMR 451.353	Mattresses: Mattress damaged in cell # 2-16 Interior Maintenance: Wall vent blocked in cell # 2-19, 2-25, 2-27, 2-29, 2-30, and 2-31
Upper Showers 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123	Maintenance: Debris observed in floor drain in shower # 2 Maintenance: Floor dirty in shower # 4 and 5 Maintenance: Mold on ceiling in shower # 5
Outside Rec Area	No Violations Noted
Dorm # 1 and 2 Landing	
Shift Administrator's Office # 6	-112 No Violations Noted
Trash Storage Room # 6-113	No Violations Noted
Janitor's Closet #6-114	No Violations Noted
Male Staff Bathroom # 6-115	No Violations Noted
Female Staff Bathroom # 6-116	Unable to Inspect – Locked
Storage/Med Pass # 6-118	No Violations Noted
Medical Office # 6-122	Unable to Inspect – Locked
Classroom # 6-123	No Violations Noted
Dorm # 1	
Sleeping Area	No Violations Noted
Common Area	No Violations Noted
<i>Toilet Area</i> 105 CMR 451.126* 105 CMR 451.130	Hot Water for Bathing and Hygiene: No hot water supplied to handwash sink # 3 Plumbing: Plumbing not maintained in good repair, toilet # 5 out-of-order
Handwash Sink Area 105 CMR 451.124	Water Supply: Discolored water observed at handwash sink # 3

Shower Area 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.124	Maintenance: Mold on caulking in shower # 2 and 3 Maintenance: Floor and walls dirty in shower # 1 Maintenance: Floor and walls dirty in shower # 3 Maintenance: Ceiling water damaged in shower # 4, 5, 6, and 8 Maintenance: Ceiling water damaged in shower # 7 Maintenance: Soap scum on walls in shower # 2 Maintenance: Ceiling vent dusty in shower # 2 Maintenance: Debris on floor drain in shower # 4 Water Supply: Insufficient water supply in quantity and pressure at lower shower head in handicapped shower Hot Water: Shower water temperature recorded at 80°F in shower # 1
Janitor's Closet 105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty
Case Worker's Office 105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
Barber Shop	No Violations Noted
Dorm # 2	
Barber Shop	No Violations Noted
Case Worker's Office 105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
Janitor's Closet	No Violations Noted
Shower Area 105 CMR 451.123 105 CMR 451.123*	Maintenance: Mold on caulking in shower # 6 Maintenance: Floor tiles damaged outside of showers
<i>Toilet Area</i> 105 CMR 451.124*	Water Supply: Insufficient hot and cold water supply in quantity and pressure at handwash sink in stall # 4
105 CMR 451.124	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink in stall $\# 6$
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink in stall $\# 1$
105 CMR 451.123	Maintenance: Hot and cold water push button corroded at handwash sink in stall # 1
Handwash Sink Area 105 CMR 451.126	Hot Water for Bathing and Hygiene: No hot water supplied to handwash sink # 1
Common Area	No Violations Noted
Sleeping Area	No Violations Noted

Intake and Discharge

<i>Transportation Office # 5-017</i>	No Violations Noted
Janitor's Closet # 5-016	No Violations Noted
Administrative Office # 5-015	No Violations Noted
Holding Tank # 2 # 5-014 105 CMR 451.124*	Water Supply: Insufficient hot and cold water supply in quantity and pressure at handwash sink
Shake Room #1 (5-011) & 2 (5-	-010) No Violations Noted
Holding Cell #1 (#5-013)	No Violations Noted
Institutional Property (# 5-009)	No Violations Noted
Desk Area	No Violations Noted
Sally Port	No Violations Noted
<i>Old Shower Room #1 (# 5-07)</i>	No Violations Noted
<i>Cell # 5-008</i>	No Violations Noted
Holding Cell # 1-6 105 CMR 451.124	Water Supply: Insufficient hot and cold water supply in quantity and pressure at handwash sink in cell # 5
105 CMR 451.353	Interior Maintenance: Wall vent dusty in cell # 4
Break Room # 5-018	No Violations Noted
Male Bathroom # 5-018 105 CMR 451.124	Water Supply: Discolored water observed at handwash sink
Female Bathroom # 5-020	No Violations Noted
<i>Inmate Property Room # 5-021</i> 105 CMR 451.383(B)*	Fire Safety System: Facility not in compliance with 780 CMR Massachusetts Building Code provisions for fire safety, items stored within 18 inches of ceiling
Change Room # 1 and 2 (# 5-02	22 and 5-023) No Violations Noted

A & B Hall Entrance

Janitor's Closet # 5-025A	Unable to Inspect – Locked
Storage Room # 5025C	No Violations Noted
<i>Teacher's Office</i> # <i>5-025B</i> 105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink
Hall A	No Violations Noted
Hall B # 5-026	No Violations Noted
<u>Housekeeping Hallway</u>	No Violations Noted
Food Service Area The following Food Code violat	tions listed in BOLD were observed to be corrected on-site.
Staff Dining Room 105 CMR 451.126 FC 3-302.11(A)(4)	Hot Water for Bathing and Hygiene: Hot water temperature 100 ⁰ F at handwash sink Preventing Contamination after Receiving; Preventing Food and Ingredient
FC 3-304.12(B)	Contamination: Food not appropriately covered, sugar left uncovered Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Utensil handle not stored above the food in the container, scoop left in sugar
Male Bathroom	No Violations Noted
Female Bathroom	No Violations Noted
Supply Dock	
Loading Dock	No Violations Noted
Surplus Storage Room # 5-028	No Violations Noted
Storage Room # 5-027	No Violations Noted
Back of Kitchen	
Supply Room # 2 (Dry Storage) FC 4-903.11(A)(3)	# 5-029 Protection of Clean Items, Storing: Single-Service items not stored at least 6 inches above the floor, food container lids stored on ground
Chemical Supply Closet	No Violations Noted

Daily Cleaning Cabinet	No Violations Noted
Kitchen Staff Break Area # 5-0	30 No Violations Noted
Supply Room # 1 (# 5-031) FC 6-404.11	Location and Placement; Distressed Merchandise: Dented cans not properly segregated ^{Pf} , dented can observed
<i>Inmate Bathroom # 5-032</i> 105 CMR 451.126*	Hot Water: Hot water temperature recorded at 100°F at handwash sink
Staff Bathroom # 5-033	No Violations Noted
Rack Spray Area	No Violations Noted
Main Kitchen Area	
Cooler # 1	No Violations Noted
<i>Warmer # 1 & 2</i> FC 4-501.11(B)*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged on warmer # 1
Serving Line	No Violations Noted
Handwash Sink – Near Pots an	d Pans Sink No Violations Noted
Pots and Pan Sink FC 4-702.11	Sanitization of Equipment and Utensils; Frequency: Utensils and food contact surfaces not sanitized before use and after cleaning ^P , no sanitizing solution in 3-compartment sink while in use
Mechanical Warewash Area	
Warewash Machine FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, soap dispenser out-of-order on warewash machine
Inmate Coffee Area	No Violations Noted
Diet Area/Serving Line #2	No Violations Noted
Warmer # 3 & 4	No Violations Noted

Cooler # 2 FC 3-305.11(A)(3)	Preventing Contamination from the Premises; Food Storage: Food not stored at least 6" off the ground, milk container on ground in cooler
3 Ovens (Under Hoods)	No Violations Noted
Pots and Pans Storage FC 4-903.11(B)(2)*	Protection of Clean Items; Storing: Equipment and Utensils not stored covered or inverted, pots and pans not covered or inverted
Prep Tables and Sinks 105 CMR 451.126*	Hot Water: Hot water temperature recorded at 100°F at handwash sink near 3-compartment sink
Ice Machines	No Violations Noted
Handwash Sink (After Ice Mach	<i>hine # 2)</i> No Violations Noted
Kettle Area	No Violations Noted
<i>Walk-in Refrigerator # 2</i> FC 4-501.11(B)* FC 3-302.11(A)(1)(b)	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, door frame damaged at bottom Preventing Contamination after Receiving; Preventing Food and Ingredient Contamination: Raw animal food not stored separate from cooked ready-to-eat food ^P , beef stored above sandwiches
Spice Cabinet	No Violations Noted
Walk-in Refrigerator # 1 FC 4-501.11(B)*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, door frame damaged at bottom
Hood Area with Warmers	No Violations Noted
Walk-in Freezer FC 4-501.11(B)*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, door frame damaged at bottom
Sallyport/Changing Area	No Violations Noted
Janitor's Closet FC 5-205.15(B)	Plumbing System; Operation and Maintenance: Plumbing system not maintained in good repair, drain cover missing on slop sink
Handwash Sink	No Violations Noted

Officer's Area/Office

No Violations Noted

Culinary Arts Program Kitchen		
Classroom	No Violations Noted	
True Refrigerator	No Violations Noted	
Proofers	No Violations Noted	
Walk-in Freezer	No Violations Noted	
Hood Area FC 3-302.12	Protection from Contamination After Receiving, Preventing Food and Ingredient Contamination: Food or food ingredients that have been removed from original packages not labeled with common name of food, bottles unlabeled near stove top	
Handwash Sink	No Violations Noted	
3-Compartment Sink	No Violations Noted	
Prep Sink	No Violations Noted	
Prep Tables	No Violations Noted	
Walk-in Refrigerator	No Violations Noted	
Reach-in Refrigerators	No Violations Noted	
Health Service Unit		
<i>ISO # 1 & 2</i> 105 CMR 451.353	Interior Maintenance: Wall vent blocked in ISO # 1	
Nurse's Pantry	No Violations Noted	
Janitor's Closet 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing	
<i>Risk Cell # 1 & 2</i> 105 CMR 451.353	Interior Maintenance: Wall paint damaged in Risk Cell # 2	
Patient Rooms # 1-4 105 CMR 451.353	Interior Maintenance: Floor paint damage in cell # 3	

<i>Ward A # 5-130</i> 105 CMR 451.103	Mattresses: Mattress damaged	
Storage Room # 5-131	No Violations Noted	
Handicapped Shower Room 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.130* 105 CMR 451.123 105 CMR 451.123	Maintenance: Soap scum on floor and walls of shower Maintenance: Soap scum on bench Hot Water: Shower water temperature recorded at 90 ⁰ F Maintenance: Ceiling vent dusty Maintenance: Debris on floor outside of shower	
<i>Nurse's Station and Bathroom</i> 105 CMR 451.123* 105 CMR 451.126*	Maintenance: Cabinet countertop near sink damaged Hot Water: Hot water temperature recorded at 95°F at handwash sink	
HSU Main Entrance	No Violations Noted	
<i>Treatment Room # 1 (# 5-126)</i> 105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 102°F at handwas	sh sink
Inmate Bathroom # 5-124	No Violations Noted	
<i>Treatment Room # 2 (# 5-122)</i>	No Violations Noted	
Medical Waste Storage	No Violations Noted	
<i>Treatment Room # 3 (# 5-120)</i> 105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, excessive ice build-up in freezer	
Coordinator's Office # 5-118	No Violations Noted	
Lab/Temporary Pharmacy # 5-	117 No Violations Noted	
Dental Room # 5-119	No Violations Noted	
Infectious Disease Office	No Violations Noted	
<i>Psychiatry Office # 5-123</i> 105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink	
Exam Room # 2 (# 5-125)	No Violations Noted	
Exam Room # 1 (# 5-127)	No Violations Noted	
A = 1 - 2 A (1) M' + 1 = D' = D' = D'	n and 5, 22, 24	

Cleaning Utility Room (# 5-111)) No Violations Noted
Storage Room #1 (# 5-110)	No Violations Noted
Mental Health Office #1 (#5-1	15) No Violations Noted
<i>Physical Therapy</i> # <i>5-113 (Trea</i> 105 CMR 451.353*	<i>tment Room # 4)</i> Interior Maintenance: Handwash sink dirty
<i>Office # 5-114</i>	No Violations Noted
Pharmacy # 5-112 105 CMR 451.353* 105 CMR 451.353* 105 CMR 451.110(A)	Interior Maintenance: Handwash sink dirty Interior Maintenance: Floor dirty under handwash sink Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink
Janitor's Closet # 5-106 105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, drain cover missing
<i>Office # 5-108</i>	No Violations Noted
<i>Office # 5-107</i>	No Violations Noted
Storage Room # 5-109	No Violations Noted
Ward B # 5-102 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123 105 CMR 451.103 105 CMR 451.353	Maintenance: Soap scum on walls in left and right shower Maintenance: Soap scum on door in left and right shower Maintenance: Soap scum on floor in left shower Maintenance: Floor and floor mat dirty outside showers Mattresses: Mattress damaged Interior Maintenance: Ceiling paint damaged
HSU Administration Hallway	
Male Bathroom	No Violations Noted
Female Bathroom # 5-104	No Violations Noted
<i>MAT Room # 5-103</i>	Unable to Inspect – Locked
<i>Office # 5-100</i>	No Violations Noted

Health Service Administrator's Office

105 CMR 451.200*

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, single service utensils left uncovered

Billerica Control Building

Main Level

<i>Lobby</i> 105 CMR 451.350* 105 CMR 451.350*	Structural Maintenance: Window broken at entrance Structural Maintenance: Wall damaged at entrance
Janitor's Closet 105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
<i>Female Bathroom</i> 105 CMR 451.350* 105 CMR 451.123	Structural Maintenance: Window broken Maintenance: Wall left unfinished in stall # 2
Male Bathroom	No Violations Noted
Transportation-Hub Hallway	Unable to Inspect Cells – Not Used
<i>Office # 2-111</i>	No Violations Noted
<i>Office # 2-108</i>	No Violations Noted
<i>IT Office # 2-101</i> 105 CMR 451.350*	Structural Maintenance: Hole in ceiling in back storage area
Control Area 105 CMR 451.350* 105 CMR 451.353* 105 CMR 451.141*	Structural Maintenance: Several windows broken Interior Maintenance: Ceiling tiles missing Screens: Screen damaged
Roll Call Room	No Violations Noted
Motorcycle Unit Locker Room #	# 2-116 Unable to Inspect – Locked
Administration Locker Room # .	2-117 Unable to Inspect – Locked
Jail Visiting Hallway	
<i>Parole Office # 2-125</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, single service utensils left uncovered
Religious Services Offices	Unable to Inspect – Locked

Additional Offices

No Violations Noted

Old	Administration	Wing

First Floor

<i>Office # 2-131</i>	Unable to Inspect – Locked
Storage Closets	No Violations Noted
Female Bathroom #2-136	No Violations Noted
<i>Mail Room # 2-138</i> 105 CMR 451.353*	Interior Maintenance: Ceiling tiles missing
Tool Crib Area	No Violations Noted
Tool Crib Bathroom	No Violations Noted
Maintenance Area	No Violations Noted
Maintenance Break Room 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, single service plates stored on floor
105 CMR 451.200*	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, multi-use sponges observed
105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
105 CMR 451.346* Chemical Room # 2-139	Safe Wiring: Inappropriate use of temporary wiring, cord running through doorway
	Unable to Inspect – Locked
Inventory Control Area	Unable to Inspect – Locked
Second Floor 105 CMR 451.353* 105 CMR 451.353	Interior Maintenance: Ceiling tiles missing throughout Interior Maintenance: Floor tiles missing throughout
<i>Offices</i> 105 CMR 451.350 105 CMR 451.200	Structural Maintenance: Window pane broken in office # 2-222 Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functioning thermometer in refrigerator in office # 2-222
Bathroom # 2-232	Unable to Inspect – In Use

Nursing Mother's Room # 2-22	
	No Violations Noted
Records Storage Rooms # 2-23	
	Unable to Inspect – Locked
New Male Locker Room	
	Unable to Inspect – In Use
Classifications & Old Infirma	ry Hallway
Offices	
105 CMR 451.353*	Interior Maintenance: Ceiling tile missing in office # 2-200
105 CMR 451.350	Structural Maintenance: Window pane broken in office # 2-220
Storage Room # 2-207 and 2-1	
	No Violations Noted
Male Bathroom # 2-214	
	No Violations Noted
Female Bathroom # 2-208	
105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 65°F at handwash sink
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water handle leaking
Old Shower Room	
	Unable to Inspect – Not Used
Staff Break Room # 2-206	
	No Violations Noted
Additional Offices	
105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with
	105 CMR 590.000, no functioning thermometer in refrigerator in office # 2-202
Janitor's Closet #2-205	
	No Violations Noted
Third Floor	
105 CMR 451.141* 105 CMR 451.350*	Screens: Screens damaged throughout area
105 CIVIK 451.550	Structural Maintenance: Several windows broken throughout area
Female Weight Room	
	Unable to Inspect – Under Construction
Female Locker Room	
105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 2
105 CMR 451.123 105 CMR 451.141	Maintenance: Ceiling tile water damaged in shower # 2 Screens: Screen damaged in work out area
Officer's Weight Room	No Violations Noted
Male Locker Room	No Violations Noted
	INU VIUIAIIUIIS INUICU

Male Locker Room Bathroom # 2-308

Unable to Inspect – In Use

Lower Report

A & B Side Cells	Unable to Inspect – Not Used
Training Center	
First Floor	
Male Bathroom # 4-123	No Violations Noted
Medical Triage	Unable to Inspect – Locked
Video Court Area # 4-122	No Violations Noted
Meeting Room # 4-120 105 CMR 451.350* 105 CMR 451.353*	Structural Maintenance: Ceiling actively leaking Interior Maintenance: Ceiling tile water damaged
Offices and Classroom # 4-1	18 – 4-121 No Violations Noted
Print Shop # 4-115	No Violations Noted
<i>Library # 4-116</i>	No Violations Noted
<i>Offices # 4-112 – 4-114</i> 105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged in office # 4-112 and 4-114
Bathroom # 4-110 105 CMR 451.126* 105 CMR 451.123* 105 CMR 451.350*	Hot Water: Hot water temperature recorded at 100 ⁰ F at handwash sink Maintenance: Ceiling tile water damaged Structural Maintenance: Window broken
<i>Storage Room # 4-111</i> 105 CMR 451.353* 105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket Interior Maintenance: Ceiling tile missing
Second Floor	
<i>Main Laundry</i> 105 CMR 451.200*	Food Storage, Preparation and Service: Food service not in compliance with 105 CMR 590.000, water catch on water dispenser dirty
105 CMR 451.350* Inmate Bathroom # 4-201	Structural Maintenance: Windows broken
105 CMR 451.350*	Structural Maintenance: Window broken

Officer's Bathroom	Unable to Inspect – Locked
<i>Officer's Office</i> # 4-213	No Violations Noted
<i>Canteen Storage # 4-215</i> 105 CMR 451.350*	Structural Maintenance: Window broken
Canteen Office # 4-216 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of refrigerator dirty
105 CMR 451.353	Interior Maintenance: Chair damaged
Tier Dorm Room (Unoccupied 105 CMR 451.350	d) Structural Maintenance: Main entrance door not rodent and weathertight
Sleeping Area	Unable to Inspect – Under Construction
Dorm Bathroom	
105 CMR 451.126 105 CMR 451.124	Hot Water for Bathing and Hygiene: No hot water supplied to handwash sink # 3 and 8 Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink # 2 and 6
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink # 3 and 6
First Tier	
Recreational Area(s) 105 CMR 451.370	Garbage Storage: Garbage stored in an unsanitary condition, garbage observed on ground around telephones
Day Room 105 CMR 451.353	Interior Maintenance: Wall vents dusty
<i>Control # 4-100</i>	No Violations Noted
<i>Staff Room # 4-102</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, single service utensils left uncovered
<i>Storage Cage # 4-103</i> 105 CMR 451.353	Interior Maintenance: Standing water in bucket
Janitor's Closet # 4-103B	No Violations Noted
A & B Side 105 CMR 451.353* 105 CMR 451.353 105 CMR 451.353* 105 CMR 451.353* 105 CMR 451.353 105 CMR 451.353	Interior Maintenance: Wall damaged in cell # B4 Interior Maintenance: Wall damaged in cell # A6 and A14 Interior Maintenance: Wall damaged outside cell # A21 Interior Maintenance: Ceiling damaged in cell # A15 and B4 Interior Maintenance: Ceiling damaged in cell # B10 and B12 Interior Maintenance: Floor paint damaged in cell # A11, B10, B11, B15, and B16

Bathroom and Shower Area	
105 CMR 451.123*	Maintenance: Wall grout missing in shower # 3, 4, 5, and 6
105 CMR 451.123	Maintenance: Wall grout missing in shower # 1
105 CMR 451.123*	Maintenance: Screw missing from wall in shower # 8
105 CMR 451.123	Maintenance: Wall tile damaged in shower # 1
105 CMR 451.123	Maintenance: Ceiling water damaged near shower # 9
105 CMR 451.123	Maintenance: Mold on ceiling outside showers
105 CMR 451.123	Maintenance: Walls dirty in shower # 2, 5, and 6
105 CMR 451.123	Maintenance: Soap scum on floor in shower # 8, 9, and 10
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # 1
	and 3
105 CMR 451.117	Toilet Fixtures: Toilet fixture dirty, urinal dirty
C & D Side	
105 CMR 451.353*	Interior Maintenance: Wall damaged in cell # C21 and D14
105 CMR 451.353	Interior Maintenance: Wall damaged in cell # D2 and D16
105 CMR 451.353	Interior Maintenance: Wall damaged near window in cell # D20
105 CMR 451.353*	Interior Maintenance: Ceiling damaged in cell # C19, C24, D13, and D16
105 CMR 451.353	Interior Maintenance: Ceiling damaged in cell # C14
Shower Room #D23	
	Unable to Inspect – Not Used
Second Tier (Unoccupied)	
105 CMR 451.353*	Interior Maintenance: Multiple windows painted
Nurse's Room	
	Unable to Inspect – Locked
Control	
	No Violations Noted
E & F Side	
105 CMR 451.117*	Toilet Fixtures: Toilet fixture not easily cleanable, interior of toilet bowl rusted in cell # F25
105 CMR 451.353*	Interior Maintenance: Ceiling damaged at end of hallway
105 CMR 451.353	Interior Maintenance: Ceiling damaged in cell # E23
105 CMR 451.353	Interior Maintenance: Wall damaged in cell # F9
Bathroom and Shower Area	
105 CMR 451.123*	Maintenance: Ceiling damaged in shower # 1, 6, and 9
105 CMR 451.125	Maintenance: Wall grout damaged in shower # 2
105 CMR 451.125*	Hot Water: Hot water temperature recorded at 90 ⁰ F at handwash sink
105 CMR 451.120*	Plumbing: Plumbing not maintained in good repair, floor drain sealed off in shower # 3
105 CMR 451.150	Maintenance: Pooling dirty water on floor in shower $#3$
105 CMR 451.125 105 CMR 451.123	Maintenance: Floor dirty outside showers and in shower $\# 9$
$I \sim 10$	
Janitorial Cage	No Violations Noted
	No Violations Noted
G & H Side	
<i>G & H Side</i> 105 CMR 451.353*	Interior Maintenance: Wall damaged in cell # G7
G & H Side	

Gym 105 CMR 451.353*	Interior Maintenance: Wooden window coverings damaged
Gym Office	No Violations Noted
Staff Bathroom	No Violations Noted
Stairway to Third Tier	No Violations Noted
Third Tier (Unoccupied) 105 CMR 451.353*	Interior Maintenance: Multiple windows painted
Control	No Violations Noted
Offices	Unable to Inspect – Locked
<i>I & J Side</i> 105 CMR 451.353* 105 CMR 451.353 105 CMR 451.353	Interior Maintenance: Wall damaged in cell # J26 Interior Maintenance: Floor dirty at end of tier Interior Maintenance: Ceiling damaged in cell # J18
Bathroom and Shower Area 105 CMR 451.126* 105 CMR 451.130* 105 CMR 451.117 105 CMR 451.123	Hot Water for Bathing and Hygiene: No hot water supplied to handwash sink Plumbing: Plumbing not maintained in good repair, pipe damaged near shower # 1 Toilet Fixtures: Toilet fixture dirty Maintenance: Door missing to shower # 4
Janitor's Closet	Unable to Inspect – Locked
K & L Side 105 CMR 451.141 105 CMR 451.360 105 CMR 451.360 105 CMR 451.353* 105 CMR 451.353 105 CMR 451.353* 105 CMR 451.353*	Screens: Screen missing in cell # K7 and K9 Protective Measures: Birds observed nesting in window in cell # K7 Protective Measures: Dead bird observed at end of tier Interior Maintenance: Ceiling damaged in cell # K3, K16, L13, and L19 Interior Maintenance: Ceiling damaged in cell # K5 and K16 Interior Maintenance: Wall damaged in cell # K24 and L19 Interior Maintenance: Window frame damaged in cell # L23
CWP Building	
Entrance	No Violations Noted
Officer's Station	No Violations Noted
<i>Storage # 3-107</i>	No Violations Noted

Bathroom # 3-111	No Violations Noted
Shower Room # 3-113 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower head leaking in shower # 2, 4, and 6
<i>Med Room # 3-112</i>	Unable to Inspect – Locked
Day Area # 3-114 105 CMR 451.350 105 CMR 451.353	Structural Maintenance: Window left unfinished in the Day Area cell Interior Maintenance: Wet mop stored in bucket
Laundry Area 105 CMR 451.353	Interior Maintenance: Dryer exhaust disconnected
<i>Dining Area</i> FC 4-903-11(A)(2)*	Protection of Clean Items, Storing: Single-Use items not stored in an area where they are protected from contamination, single service utensils left uncovered
FC 3-304.12(B)	Protection from Contamination, single service dichsins left direovered Protection from Contamination After Receiving; Preventing Contamination from Equipment, Utensils, and Linens: Utensil handle not stored above the food in the container, scoop stored in cereal
FC 3-302.11(A)(4)	Preventing Contamination after Receiving; Preventing Food and Ingredient
FC 4-601.11(C) FC 6-501.12(A)	Contamination: Food not appropriately covered, cereal left uncovered Cleaning of Equipment and Utensils, Objective: Vending machine drawer dirty Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, old lunches left on table tops
<i>Offices</i> # 3-103 – 3-105	No Violations Noted
Kitchen	Unable to Inspect – Under Construction
2 nd Floor	
<i>Inmate Bathroom # 3-201</i> 105 CMR 451.117	Toilet Fixtures: Toilet fixture dirty in stall # 1 and 2
Dorm # 3-200	No Violations Noted
Janitor's Closet # 3-204	No Violations Noted
<i>Office # 3-205</i>	No Violations Noted
Dorm # 3-203 105 CMR 451.353*	Interior Maintenance: Ceiling damaged
Staff Bathroom # 3-202	No Violations Noted

Basement

Property # 3-B04	No Violations Noted
Storage Closet # 3-B 02 a	nd 3-B03 No Violations Noted
Work Release Building	
<u>House # 1</u>	
First Floor	
Hallway	No Violations Noted
Infirmary	No Violations Noted
Control	No Violations Noted
Office	No Violations Noted
Bathroom	No Violations Noted
Bedrooms 105 CMR 451.141* 105 CMR 451.141*	Screens: Screen not properly sized for window in bedroom # 2 Screens: Screen missing in bedroom # 3
Food Service Area The following Food Code	violations listed in BOLD were observed to be corrected on-site.
Dining Room FC 6-202.15(A)(3)*	Design, Construction, and Installation; Functionality: Exterior door not tight-fitting, weather stripping damaged on left side door
Kitchen FC 3-501.16(A)(2)	Limitation of Growth of Organisms of Public Health Concern, Temperature and Time Control: Time/temperature control for safety food not held at 41°F or less ^P ,
FC 4-601.11(C)	margarine labeled "keep refrigerated" not kept under refrigeration Cleaning of Equipment and Utensils, Objective: Nonfood contact surfaces of equipment dirty, grease buildup observed on wire storage rack
Second Floor	
Stairway	No Violations Noted
Hallway	

No Violations Noted

Bedrooms 105 CMR 451.141* 105 CMR 451.141	Screens: Screen not properly sized for window in bedroom # 5, 7, and 8 Screens: Screen not properly sized for window in bedroom # 4 and 6
Bathroom 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.130	Maintenance: Screen not tight-fitting Maintenance: Dead bugs accumulating in window Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 2
Stairway to Basement	No Violations Noted
Basement	
Laundry Room 105 CMR 451.350* 105 CMR 451.350*	Structural Maintenance: Water leaking in from exterior in back left corner of room Structural Maintenance: Door leading to exterior not rodent and weathertight
Janitor's Closet	Unable to Inspect – Locked
Boiler Room	Unable to Inspect – Locked
Storage Room	Unable to Inspect – Locked
Day Room between Houses 105 CMR 451.141	Screens: Screen missing
House # 2 (Unoccupied)	
First Floor 105 CMR 451.353	Interior Maintenance: Pooling water on floor at front entrance to House # 2
Hallway 105 CMR 451.141	Screens: Screen missing
Strip Search Room	No Violations Noted
<i>Staff Bathroom</i> 105 CMR 451.123 105 CMR 451.126*	Maintenance: Screen not tight-fitting Hot Water: Hot water temperature recorded at 80 ⁰ F at handwash sink
Group Room	No Violations Noted
Officer's Bathroom	No Violations Noted
Offices	No Violations Noted
Administration Office	No Violations Noted

Second Floor

<i>Hallway</i> 105 CMR 451.141	Screens: Screen not tight-fitting in hallway
Bathroom 105 CMR 451.123* 105 CMR 451.126 105 CMR 451.350	Maintenance: Screen missing Hot Water for Bathing and Hygiene: Hot water temperature 80°F at handwash sink Structural Maintenance: Window broken
Bedrooms 105 CMR 451.141* 105 CMR 451.141* 105 CMR 451.141	Screens: Screen missing in bedroom # 267-2-202 Screens: Screen not properly sized for window in bedroom # 267-2-201 and 267-2-205 Screens: Screen not properly sized for window in bedroom # 267-2-204
Third Floor 105 CMR 451.350*	Structural Maintenance: Emergency exit door not rodent and weathertight
<i>Bedrooms</i> 105 CMR 451.141*	Screens: Screen not properly sized for window in bedroom # 267-2-301 and 267-2-303
Basement	
Day Room 105 CMR 451.353* 105 CMR 451.353*	Interior Maintenance: Mold on walls Interior Maintenance: Floor water stained
<i>Property</i> 105 CMR 451.353	Interior Maintenance: Mold on walls
Bathroom 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123 105 CMR 451.123 105 CMR 451.123	Maintenance: Wall tiles missing in shower # 3 Maintenance: Ceiling paint damaged in shower # 3 Maintenance: Curtain missing at shower # 1 and 3 Maintenance: Mold on curtain in shower # 2 Maintenance: Toilet partitions rusted
Storage Room	Unable to Inspect – Locked
<u>WAREHOUSE</u>	
<i>Office # 9-101</i>	No Violations Noted
<i>Female Bathroom # 9-102</i> 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water handle leaking at handwash sink
Male Bathroom #9-103	No Violations Noted
Janitor's Closet #9-104	No Violations Noted

No Violations Noted

Back Freezer and Refrigerator

No Violations Noted

Observations and Recommendations

- 1. The inmate population was 677 at the time of inspection.
- 2. During the main kitchen inspection, the warewash machine was not in operation. Kitchen staff stated a service order was already placed to repair the warewash machine and staff had already started utilizing interim measures such as manually sanitizing dishes or using Styrofoam trays until repairs could be made. By the completion of the inspection, the warewash machine was repaired and working in accordance with the manufacturer's instructions.
- 3. The CSP recommends:
 - a. Installing a shower curtain at the toilet stall in the 2nd floor bathroom of Work Release House # 1; and
 - b. Utilizing a dehumidifier in the basement of Work Release House # 1 and 2.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at <u>www.mass.gov/dph/dcs</u> and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment Regulations or download a copy, please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Retail food". Then under DPH Regulations and FDA Code click "Merged Food Code" or "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments".

To review the Labeling regulations please visit the Food Protection website at <u>www.mass.gov/dph/fpp</u> and click on "Food Protection Program regulations". Then under Food Processing click "105 CMR 500.000: Good Manufacturing Practices for Food".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,

Herry Wagn

Kerry Wagner, MPH Field Supervisor, EA III, CSP, BCEH