Drought Management Task Force October 08, 2025 Meeting

MWRA

- MWRA is in normal operating range
- MWRA's Actions
 - Update the MWRA web posting right after the 1st.
 - Acknowledge that the state was in drought
 - MWRA refers its communities to the EEA web pages for information on drought
 - MWRA is asking that communities use water thoughtfully

Rivers and Brooks Conditions in Western Massachusetts

Gate 10







Atherton Brook on 202






Keystone Bridge



Keystone Bridge



Keystone Bridge



North Quabbin: Gate 36



Swift River East Branch





Downstream from the road

Upstream from the road

Swift River East Branch



CT River at Northampton





