



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Environmental Health
Community Sanitation Program
5 Randolph Street, Canton, MA 02021
Phone: 781-828-7700 Fax: 781-828-7703

CHARLES D. BAKER
Governor

KARYN E. POLITO
Lieutenant Governor

MARYLOU SUDDERS
Secretary

MONICA BHAREL, MD, MPH
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

February 23, 2018

Joseph D. McDonald, Jr., Sheriff
Plymouth County Correctional Facility
26 Long Pond Road
Plymouth, MA 02360

Re: Facility Inspection - Plymouth County Correctional Facility

Dear Sheriff McDonald:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Plymouth County Correctional Facility on February 21 and 22, 2018 accompanied by Captain Eugene Irvine, Environmental Health and Safety Officer. Violations noted during the inspection are listed below including 82 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

Front Lobby

Main Area

No Violations Noted

Janitor's Closet

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Administration Area

Break Room # 1014

No Violations Noted

Male Bathroom # 1013

105 CMR 451.123 Maintenance: Ceiling vent dusty

Female Bathroom # 1015

105 CMR 451.123 Maintenance: Ceiling vent dusty

Administration - Main Hallway

105 CMR 451.350 Structural Maintenance: Ceiling leaking in hallway

Janitor's Closet # 1027

No Violations Noted

Female Locker Room

105 CMR 451.123* Maintenance: Ceiling vent dusty above toilets

105 CMR 451.123 Maintenance: Interior of light shield dirty

Showers

No Violations Noted

Male Locker Room

105 CMR 451.123* Maintenance: Ceiling vent dusty

Showers

105 CMR 451.123 Maintenance: Soap scum on walls in shower # 3

Staff Gym

No Violations Noted

IPS Office

105 CMR 451.353 Interior Maintenance: Ceiling tiles water damaged outside IPS office

105 CMR 451.350 Structural Maintenance: Ceiling leaking outside IPS office

Kitchen

Staff Dining

Staff Dining Area

No Violations Noted

Staff Serving Line

FC 4-601.11(C)* Cleaning of Equipment and Utensils, Objective: Nonfood contact surface dirty, interior of oven doors dirty

FC 3-305.11(A)(1) Preventing Contamination from Premises: Food stored in an inappropriate location, coffee creamer left out on counter

FC 4-903.11(A)(2) Protection of Clean Items, Storing: Utensils not stored in an area where they are protected from contamination, utensils stored uncovered under serving line

Kitchen Area

Warming Units

No Violations Noted

Bakery Area

No Violations Noted

Ice Machine

No Violations Noted

Office

No Violations Noted

Office Bathroom

105 CMR 451.123

Maintenance: Ceiling vent dusty

Dry Storage

No Violations Noted

Tool Closet

No Violations Noted

Cooler # 2

No Violations Noted

Inmate Break Area

No Violations Noted

Inmate Bathroom

105 CMR 451.123

Maintenance: Ceiling vent dusty

Janitor's Closet

FC 6-501.16

Maintenance and Operation; Cleaning: Wet mop stored in bucket

Freezer # 1

No Violations Noted

Cooler # 3

No Violations Noted

Cooler # 4

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, ceiling cooling fan leaking water

Cooler # 5

No Violations Noted

Freezer # 6

FC 3-202.15

Sources, Specifications; Specifications for Receiving: Package integrity, ice cream containers damaged

Prep Area

FC 6-201.11*

Design, Construction and Installation: Floor not easily cleanable, floor damaged throughout

FC 4-601.11(C)*

Cleaning of Equipment and Utensils, Objective: Nonfood contact surface dirty, interior of oven doors dirty

FC 5-501.16(C)

Refuse, Recyclables, and Returnables; Numbers and Capacities: No conveniently located waste receptacle at handwashing sink

2-Compartment Sink Area

FC 5-501.16(C)

Refuse, Recyclables, and Returnables; Numbers and Capacities: No conveniently located waste receptacle at handwashing sink

Kettle Area

No Violations Noted

Dishwashing Machine Area

No Violations Noted

Laundry

105 CMR 451.353*

Interior Maintenance: Ceiling vent dirty

Janitor's Closet

No Violations Noted

Office

No Violations Noted

Chemical Closet

No Violations Noted

Inmate Bathroom # 1058

No Violations Noted

Loading Dock

No Violations Noted

Maintenance # 1053

Small Tool Room

No Violations Noted

Bathroom

105 CMR 451.123*

Maintenance: Ceiling vent dirty

105 CMR 451.123

Maintenance: Wet mop stored in bucket

Office

No Violations Noted

Office Bathroom

No Violations Noted

Attorney Visits

No Violations Noted

Chapel

105 CMR 451.353*

Interior Maintenance: Carpet dirty

105 CMR 451.353

Interior Maintenance: Ceiling vent dirty

Medical Corridor

No Violations Noted

HSU

Waiting Room # M103

No Violations Noted

<i>Staff Break Room</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of utensil storage unit dirty
105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, unlabeled food containers
<i>Nurse's Station # M106</i>	No Violations Noted
<i>Storage # M133</i>	No Violations Noted
<i>Room # M132</i> 105 CMR 451.110(A) 105 CMR 451.130	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink Plumbing: Plumbing not maintained in good repair, sink faucet leaking
<i>Autoclave # M131</i>	No Violations Noted
<i>Staff Bathroom # M130</i> 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet head loose
<i>Pharmacy # M128</i> 105 CMR 451.110(A) 105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink
<i>Janitor's Closet # M127</i> 105 CMR 451.353	Interior Maintenance: Wet mop stored in sink
<i>Laboratory # M126</i> 105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink
<i>Dentist # M124</i>	No Violations Noted
<i>X-Ray Room # M123</i> 105 CMR 451.110(A) 105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink
<i>Inmate Bathroom # M122</i>	No Violations Noted
<i>Exam Room # M121</i>	No Violations Noted
<i>Room # M119</i>	No Violations Noted
<i>Room # 115</i>	No Violations Noted
<i>Handicapped Bathroom</i>	No Violations Noted
<i>Office # M112</i>	No Violations Noted

Cell # M113 - M116

No Violations Noted

Office # M117

No Violations Noted

Office # M118

No Violations Noted

Property

No Violations Noted

Booking

Main Area

No Violations Noted

Office # R112

No Violations Noted

Records # R106

No Violations Noted

Inmate Toilet # R105

No Violations Noted

Inmate Bathroom # R118

No Violations Noted

Janitor's Closet # R126

105 CMR 451.353

Interior Maintenance: Unlabeled chemical bottles

Showers

No Violations Noted

Staff Bathroom # R127

No Violations Noted

Kitchen Area

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 95⁰F

Officer's Landing

No Violations Noted

Watch Cells

No Violations Noted

Holding Cells

105 CMR 451.353*

Interior Maintenance: Ceiling vent blocked in cell # R103

105 CMR 451.353*

Interior Maintenance: Wall paint damaged in cell # R124

Library

No Violations Noted

Library Bathroom

105 CMR 451.123

Maintenance: Ceiling vent dusty

Human Services # 1079

105 CMR 451.353 Interior Maintenance: Ceiling tiles water stained
105 CMR 451.353 Interior Maintenance: Floor covered with dust outside legal office

Break Room

105 CMR 451.200* Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, unlabeled food in the refrigerator
105 CMR 451.200 Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, food left out on table
105 CMR 451.200 Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, counter top damaged behind sink
105 CMR 451.370 Garbage Storage: Garbage stored in an unsanitary condition, trash receptacle missing cover

Offices

No Violations Noted

Staff Bathroom # 1069

No Violations Noted

Janitor's Closet # 1064

No Violations Noted

Gymnasium

105 CMR 451.353 Interior Maintenance: Landing dirty above office

Main Hallway**Female Staff Bathroom # 1039**

No Violations Noted

Male Staff Bathroom # 1040

No Violations Noted

Janitor's Closet # 1084

105 CMR 451.353 Interior Maintenance: Floor dirty

Staff Bathroom # 1090

Unable to Inspect --- In Use

Janitor's Closet # 1095

105 CMR 451.353* Interior Maintenance: Ceiling vent dusty

Staff Bathroom # 1098

No Violations Noted

Staff Bathroom # 1099

No Violations Noted

Staff Bathroom # 1107

No Violations Noted

Janitor's Closet # 1108

No Violations Noted

Unit Manager's Office # 1112

No Violations Noted

Classroom # 1102

No Violations Noted

Staff Bathroom # 1102

No Violations Noted

Classroom # 1110

No Violations Noted

Cell Blocks/Pods

A1

Trap

No Violations Noted

Classroom

105 CMR 451.353

Interior Maintenance: Ceiling tiles rusted

Slop Sink

No Violations Noted

Bathroom

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet loose at sink # 2

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty outside showers

Cell # A107 - A110

No Violations Noted

Main Area -- Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Several ceiling vents dusty

BS101

Trap -- First Floor

No Violations Noted

Slop Sink

No Violations Noted

Bathroom

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty outside showers

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 7

105 CMR 451.123

Maintenance: Floor dirty in shower # 5

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

BN101

Slop Sink

No Violations Noted

Bathroom

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty outside showers

105 CMR 451.123

Maintenance: Curtain missing in shower # 2, 3, and 7

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

BS201

Trap – Second Floor

No Violations Noted

Slop Sink

No Violations Noted

Bathroom

No Violations Noted

Showers

105 CMR 451.123

Maintenance: Ceiling vent dusty outside showers

105 CMR 451.123

Maintenance: Light fixture rusted inside shower # 1 - 7

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 4 leaking

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

BN201

Slop Sink

No Violations Noted

Bathroom

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty outside showers

105 CMR 451.123*

Maintenance: Curtain missing in shower # 6 and 7

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

105 CMR 451.353

Interior Maintenance: Baseboard damaged near wall phones

C1

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 2 and 9 leaking

105 CMR 451.123

Maintenance: Walls dirty in shower # 9

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 109 and 111

105 CMR 451.353

Interior Maintenance: Ceiling paint damaged in cell # 116

DN1

Main Area

No Violations Noted

Slop Sink

105 CMR 451.353

Interior Maintenance: Noxious odor

Showers – 1st Floor

105 CMR 451.123

Maintenance: Walls stained in shower # 3

Showers – 2nd Floor

105 CMR 451.123

Maintenance: Walls stained in shower # 5

Recreation Deck

105 CMR 451.353*

Interior Maintenance: Wall paint damaged

Second Floor – Rooms

105 CMR 451.353

Interior Maintenance: Floor dirty in room # 208

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty in room # 208

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 207

DS1

Main Area

105 CMR 451.353

Interior Maintenance: Wall stained near recreational door

Slop Sink

No Violations Noted

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 5

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

E1

Main Area

No Violations Noted

Slop Sink

105 CMR 451.353*

Interior Maintenance: Wall vent dusty

Showers

105 CMR 451.123*

Maintenance: Mold on ceiling outside showers

Recreation Deck

105 CMR 451.353

Interior Maintenance: Wall paint damaged

Second Floor – Rooms

105 CMR 451.353*

Interior Maintenance: Ceiling tiles damaged in room # 238

Cells

105 CMR 451.321*

105 CMR 451.140

Cell Size: Inadequate floor space in all cells

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 220, 229, 230, and 233

FN1

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Recreation Deck

105 CMR 451.353*

105 CMR 451.353*

Interior Maintenance: Wall paint damaged

Interior Maintenance: Wall dirty

Showers – 1st Floor

105 CMR 451.123

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 1

Maintenance: Walls dirty in shower # 2 and 3

Showers – 2nd Floor

105 CMR 451.123

105 CMR 451.123

105 CMR 451.123

Maintenance: Ceiling tiles stained outside showers

Maintenance: Walls dirty in shower # 4, 5, 6, and 7

Maintenance: Mold on ceiling outside showers

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

FS1

Main Area

No Violations Noted

Slop Sink

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Showers – 1st Floor

105 CMR 451.123*

105 CMR 451.123

105 CMR 451.123

Maintenance: Walls dirty in shower # 1

Maintenance: Shower # 3 leaking

Maintenance: Mold on ceiling outside showers

Showers – 2nd Floor

105 CMR 451.123*

105 CMR 451.123

105 CMR 451.123

Maintenance: Walls dirty in shower # 5

Maintenance: Walls dirty in shower # 7

Maintenance: Mold on ceiling outside showers

Recreation Deck

105 CMR 451.353*

105 CMR 451.353*

Interior Maintenance: Wall paint damaged

Interior Maintenance: Wall dirty

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

105 CMR 451.103

Cell Size: Inadequate floor space in all cells

Mattresses: Mattress damaged in cell # 101

III

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers

105 CMR 451.123*

105 CMR 451.123

Maintenance: Mold on ceiling outside showers

Maintenance: Staircase rusted outside showers

Recreation Deck

105 CMR 451.353*

105 CMR 451.353*

Interior Maintenance: Wall paint damaged

Interior Maintenance: Wall dirty

Second Floor – Rooms

105 CMR 451.353
105 CMR 451.353

Interior Maintenance: Ceiling vent blocked in room # 238
Interior Maintenance: Floor dirty in room # 238

Cells

105 CMR 451.321*
105 CMR 451.140
105 CMR 451.353

Cell Size: Inadequate floor space in all cells
Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 207 and 212
Interior Maintenance: Wall paint damaged in cell # 102, 111, 113, 114, 115, 125, 216, 229, 231, and 234

G Block

Main Area

No Violations Noted

GE South

Slop Sink

105 CMR 451.353

Interior Maintenance: Wet mop stored in sink

Showers

No Violations Noted

Chemical Storage

No Violations Noted

Cells

105 CMR 451.321*
105 CMR 451.140

Cell Size: Inadequate floor space in all cells
Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 104, 108, 201, and 206

GE North

105 CMR 451.353*

Interior Maintenance: Ceiling tiles water damaged

Slop Sink

105 CMR 451.353*

Interior Maintenance: Unlabeled chemical bottle

Showers

105 CMR 451.123*
105 CMR 451.123

Maintenance: Ceiling vents dusty outside showers
Maintenance: Shower # 2 dirty

Recreation Deck

No Violations Noted

Cells

105 CMR 451.321*
105 CMR 451.140*
105 CMR 451.140

105 CMR 451.353*
105 CMR 451.353

Cell Size: Inadequate floor space in all cells
Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 213
Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 109, 114, 115, 117, 210, 216, and 218
Interior Maintenance: Light fixture blocked in cell # 118
Interior Maintenance: Light fixture blocked in cell # 110 and 217

GW North

105 CMR 451.353*

Interior Maintenance: Floor paint damaged

Slop Sink

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Ceiling vents dusty in shower area

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

105 CMR 451.353

Interior Maintenance: Light fixture blocked in cell # 110 and 211

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 109, 112, 115, 116, 117, 118, 210, 212, 214, 215, and 218

GW South

Slop Sink

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Floor dirty in shower # 1 and 2

Cells

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 204 and 207

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 105, 107, 108, 201, 202, 203, 206, and 208

105 CMR 451.353

Interior Maintenance: Light fixture blocked in cell # 106 and 208

3rd Floor

Main Hallway

Janitor's Closet # 3022

No Violations Noted

Staff Bathroom # 3021

No Violations Noted

Storage # 3020

No Violations Noted

Janitor's Closet # 3018

No Violations Noted

Classroom # 3015

No Violations Noted

Storage # 3011

Unable to Inspect - Under Construction

Janitor's Closet # 3010

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Staff Bathroom # 3009

No Violations Noted

Break Room # 3008

105 CMR 451.200*

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
Interior Maintenance: Wall fan dusty

105 CMR 451.353*

Janitor's Closet # 3006

No Violations Noted

Classroom # 3005

No Violations Noted

Storage # 3004

No Violations Noted

Staff Bathroom # 3003

No Violations Noted

3rd Floor - Cell Blocks/Pods

C3

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers

105 CMR 451.123

Maintenance: Ceiling vent clogged in shower # 6, 7, 8, and 9

105 CMR 451.123

Maintenance: Staircase rusted outside showers

Recreation Deck

No Violations Noted

Second Floor --- Rooms

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty in room # 437

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 422

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 322, 323, 402, 410, 419, 423, 424, 425, 427, and 433

DN3

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers -- 1st Floor

No Violations Noted

Showers -- 2nd Floor

No Violations Noted

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

DS3

Main Area

No Violations Noted

Slop Sink

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Showers – 1st Floor

105 CMR 451.123

Maintenance: Wall vent dusty in shower # 3

Showers – 2nd Floor

105 CMR 451.123

Maintenance: Walls dirty in shower # 4, 5, 6, and 7

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 4, 5, 6, and 7

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

E3

Main Area

No Violations Noted

Slop Sink

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet leaking

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Showers

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 8 leaking

105 CMR 451.123

Maintenance: Wall paint surface damaged in shower # 7

105 CMR 451.123

Maintenance: Walls stained in shower # 7

Second Floor – Rooms

105 CMR 451.353

Interior Maintenance: Ceiling vents dirty in room # 437 and 438

105 CMR 451.353

Interior Maintenance: Outlet cover missing in room # 437

Cells

105 CMR 451.321*

105 CMR 451.140*

105 CMR 451.140

105 CMR 451.353

Cell Size: Inadequate floor space in all cells

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 305 and 311

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 303, 307, 407, and 411

Interior Maintenance: Wall paint damaged in cell # 306, 401, and 423

FS3

Main Area

105 CMR 451.353

Interior Maintenance: Ceiling tiles water damaged

Slop Sink

No Violations Noted

Medical Room

No Violations Noted

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor

105 CMR 451.123*

105 CMR 451.123

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 4 and 5

Maintenance: Soap scum on walls in shower # 6 and 7

Maintenance: Floor paint damaged outside showers

Second Floor – Rooms

105 CMR 451.353

105 CMR 451.353

Interior Maintenance: Outlet cover missing in room # 408

Interior Maintenance: Ceiling vent dirty in room # 409

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

FN3

Main Area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

Slop Sink

No Violations Noted

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 5 and 6

Second Floor – Rooms

105 CMR 451.353

Interior Maintenance: Ceiling vent dirty in room # 408

Cells

105 CMR 451.321*

105 CMR 451.353*

105 CMR 451.353

Cell Size: Inadequate floor space in all cells

Interior Maintenance: Ceiling paint damaged in cell # 307

Interior Maintenance: Wall paint damaged in cell # 305 and 306

H3

Main Area

105 CMR 451.350*

Structural Maintenance: Ceiling leaking in back stairwell

Slop Sink

No Violations Noted

Showers

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 8 and 9

105 CMR 451.123

Maintenance: Mold on ceiling outside showers

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Garage

Bathroom # W124

No Violations Noted

Janitor's Closet # W123

No Violations Noted

Print Shop

No Violations Noted

Inmate Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Janitor's Closet # W111

No Violations Noted

Warehouse – Support Building

Freezer # 1

No Violations Noted

Freezer # 2

No Violations Noted

Fridge # 1

No Violations Noted

Fridge # 2

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Inmate Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Uniforms

No Violations Noted

Work Crew Area

Bathroom

No Violations Noted

Break Area

No Violations Noted

Record Storage

No Violations Noted

K9 Unit

Female Bathroom

No Violations Noted

Bathroom # 2

No Violations Noted

Janitor's Closet

105 CMR 451.353

Interior Maintenance: Unlabeled chemical bottles

Laundry

105 CMR 451.353

Interior Maintenance: Ceiling tiles water damaged outside laundry room

Observations and Recommendations

1. The inmate population was 1,027 at the time of inspection.
2. On the first day of the inspection, the 3-compartment sink in the kitchen was removed while new flooring was installed. On the second day of the inspection, a new 3-compartment sink was being installed. The two warewash machines and the two 2-compartment sinks in the prep area were used to wash equipment while the 3-compartment sink was disconnected.
3. At the time of inspection, the Department recommended that metering faucets throughout the facility be adjusted so they remain running for 20 seconds at minimum. This will allow for the hot water to reach the desired range of 110°F – 130°F and provide the opportunity for staff and inmates to thoroughly wash their hands.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

To review the Labeling regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Nicholas Gale
Environmental Health Inspector, CSP, BEH

cc: Jana Ferguson, Director, BEH
Steven Hughes, Director, CSP, BEH
Marylou Sudders, Secretary, Executive Office of Health and Human Services
Thomas Turco, Commissioner, DOC
Antone Moniz, Superintendent
Captain Eugene Irvine, EHSO
Michelle Roberts, MA, CHO, Health Director, Plymouth Health Department
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Daniel Bennett, Secretary, FOPSS
Nelson Alves, Director, Policy Development and Compliance Unit