



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Environmental Health
Community Sanitation Program
5 Randolph Street, Canton, MA 02021
Phone: 781-828-7700 Fax: 781-828-7703

CHARLES D. BAKER
Governor

KARYN E. POLITO
Lieutenant Governor

MARYLOU SUDDERS
Secretary

MONICA BHAREL, MD, MPH
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

October 27, 2015

Joseph D. McDonald, Jr., Sheriff
Plymouth County Correctional Facility
26 Long Pond Road
Plymouth, MA 02360

Re: Facility Inspection – Plymouth County Correctional Facility

Dear Sheriff McDonald:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Minimum Requirements for the Management of Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Plymouth County Correctional Facility on September 21 and 22, 2015 accompanied by Captain Eugene Irvine, Environmental Health and Safety Officer. Violations noted during the inspection are listed below including 121 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

Administration/Entrance Area

Front Lobby

Main Area

105 CMR 451.353* Interior Maintenance: Ceiling tiles water damaged

Janitor's Closet

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Main Hallway*Janitor's Closet – 1027*

105 CMR 451.353

Interior Maintenance: Wet mop stored in sink

Female Locker Room

105 CMR 451.123

Maintenance: Ceiling vent dusty

Showers

No Violations Noted

Male Locker Room

105 CMR 451.123

Maintenance: Ceiling vent dusty

105 CMR 451.123

Maintenance: Light out

Showers

No Violations Noted

Staff Gym

No Violations Noted

Administration Area – 1018*Break Room - 1014*

No Violations Noted

Male Bathroom – 1013

No Violations Noted

Female Bathroom – 1015

No Violations Noted

IPS Office

No Violations Noted

Kitchen

FC 6-201.11*

Design, Construction and Installation: Floor damaged in many areas

Staff Dining Area

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, ceiling vents dirty

Staff Serving Line

FC 6-201.11*

Design, Construction and Installation: Floor damaged

Kitchen Entrance

No Violations Noted

Warming Units

No Violations Noted

Ice Machine

No Violations Noted

Office

No Violations Noted

Office Bathroom

No Violations Noted

Dry Storage

No Violations Noted

Tool Closet

No Violations Noted

Cooler # 2

No Violations Noted

Inmate Break Area

No Violations Noted

Inmate Bathroom

105 CMR 451.123*

Maintenance: Door does not close properly

Janitor's Closet

FC 6-501.16

Maintenance and Operation; Cleaning: Wet mop stored in bucket

Freezer # 1

No Violations Noted

Cooler # 3

No Violations Noted

Cooler # 4

No Violations Noted

Cooler # 5

No Violations Noted

Freezer # 6

No Violations Noted

Prep Area

Kettle Area

No Violations Noted

Bakery Area

No Violations Noted

3-Bay Sink Area

No Violations Noted

Dishwashing Machine Area

Spray Station

FC 6-201.11

Design, Construction and Installation: Floor damaged

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, standing water around dishwashing machine

FC 6-201.16(A)

Design, Construction, and Installation; Cleanability: Wall paint peeling

Chapel/Contact Room

105 CMR 451.350*

105 CMR 451.353*

Structural Maintenance: Water leak behind wall

Interior Maintenance: Carpet dirty

Medical Corridor

105 CMR 451.350*

105 CMR 451.353*

105 CMR 451.350*

Structural Maintenance: Ceiling leaking

Interior Maintenance: Ceiling tiles damaged

Structural Maintenance: Door leading to exterior not rodent and weathertight

HSU*Kitchen*

No Violations Noted

Nurse's Station -- M106

No Violations Noted

Soiled Utility -- M133

No Violations Noted

Room -- M132

No Violations Noted

Autoclave -- M131

No Violations Noted

Staff Bathroom -- M130

No Violations Noted

Pharmacy -- M128

No Violations Noted

Janitor's Closet -- M127

No Violations Noted

Laboratory -- M126

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 77°F

Dentist -- M124

No Violations Noted

X-Ray Room -- M123

No Violations Noted

Inmate Bathroom -- M122

No Violations Noted

Exam Room -- M121

No Violations Noted

Room -- M119

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 80°F

Handicap Bathroom

No Violations Noted

Cells

No Violations Noted

Laundry

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353

Interior Maintenance: Washing machine out-of-order

Janitor's Closet

No Violations Noted

Office

No Violations Noted

Chemical Closet

No Violations Noted

Maintenance

Small Tool Room

No Violations Noted

Bathroom

No Violations Noted

Office

No Violations Noted

Office Bathroom

No Violations Noted

Inmate Bathroom – 1058

Unable to Inspect – No Access

Loading Dock

No Violations Noted

Gymnasium

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353*

Interior Maintenance: Baseboard missing

105 CMR 451.353*

Interior Maintenance: Ceiling ventilation missing diffusers

Hallway

Female Staff Bathroom – 1039

No Violations Noted

Male Staff Bathroom – 1040

No Violations Noted

Janitor's Closet - 1084

No Violations Noted

Staff Bathroom – 1090

No Violations Noted

Janitor's Closet – 1095
105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Staff Bathroom – 1098
105 CMR 451.123

Maintenance: Ceiling vent dusty

Staff Bathroom – 1099

No Violations Noted

Staff Bathroom – 1107
105 CMR 451.350*

Structural Maintenance: Ceiling damaged

Janitor's Closet – 1108

No Violations Noted

Unit Manager's Office – 1112
105 CMR 451.350*
105 CMR 451.353*

Structural Maintenance: Ceiling leaking
Interior Maintenance: Ceiling tiles damaged

Classroom – 1102

No Violations Noted

Staff Bathroom – 1102
105 CMR 451.350

Structural Maintenance: Ceiling damaged

Classroom – 1110

No Violations Noted

Library

No Violations Noted

Human Services

105 CMR 451.353*
105 CMR 451.350*
105 CMR 451.353

Interior Maintenance: Floor tiles damaged at cubicles
Structural Maintenance: Ceiling leaking
Interior Maintenance: Appearance of mold on floor

Break Room
FC 4-601.11(A)*

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, toaster oven dirty

FC 3-701.11(A)

Contaminated Food, Disposition: Unsafe, adulterated, or not honestly presented food not properly reconditioned or discarded

Offices
105 CMR 451.350

Structural Maintenance: Ceiling leaking in office # 1071

Staff Bathroom – 1069
105 CMR 451.123
105 CMR 451.123

Maintenance: Ceiling vent dusty
Maintenance: Wall damaged above toilet

Janitor's Closet – 1064
105 CMR 451.353
105 CMR 451.353

Interior Maintenance: Wet mop stored in sink
Interior Maintenance: Unlabeled chemical bottle

Booking

Main Area
FC 3-302.12

Preventing Food and Ingredient Contamination: Unlabeled food in refrigerator

Office – R112

No Violations Noted

Records – R106
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Inmate Toilet – R105

No Violations Noted

Inmate Bathroom – R118

No Violations Noted

Janitor's Closet – R126

No Violations Noted

Showers
105 CMR 451.123

Maintenance: Floor dirty in shower # 1 and 2

Staff Bathroom – R127
105 CMR 451.123

Maintenance: Ceiling vent dusty

Kitchen Area
FC 4-501.11(B)*

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets dirty
Interior Maintenance: Ceiling tile damaged across from sink

105 CMR 451.353*

Officer's Landing

No Violations Noted

Cells
105 CMR 451.353*
105 CMR 451.353

Interior Maintenance: Ceiling tiles damaged in cell # R110 and R111
Interior Maintenance: Ceiling vent dusty in cell # R107 and R108

Property

No Violations Noted

Cell Blocks/Pods

A1

Trap
105 CMR 451.353

Interior Maintenance: Ceiling dirty

Main Area
105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

Slop Sink

No Violations Noted

Showers
105 CMR 451.123*

Maintenance: Ceiling vent dusty

Bathroom

105 CMR 451.123 Maintenance: Sink # 2 out-of-order

Cells

105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, ceiling vent blocked

E1

Main Area

105 CMR 451.350* Structural Maintenance: Rec door not rodent and weathertight
105 CMR 451.353* Interior Maintenance: Ceiling tile damaged near rec door

Slop Sink

105 CMR 451.353 Interior Maintenance: Wall vent dusty
105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

Showers

105 CMR 451.123 Maintenance: Vent dusty in shower # 5
105 CMR 451.123 Maintenance: Soap scum on walls in shower # 9

Recreation Area

No Violations Noted

Cells

105 CMR 451.321* Cell Size: Inadequate floor space in cell # 101-134 and 201-236
105 CMR 451.353* Interior Maintenance: Ceiling tiles damaged in cell # 238
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 117, 119, 124, 131, 203, 206, and 207

H1

Main Area

105 CMR 451.350* Structural Maintenance: Rec door not rodent and weathertight
105 CMR 451.353* Interior Maintenance: Ceiling tiles damaged above rec deck door

Slop Sink

105 CMR 451.353* Interior Maintenance: Baseboard damaged

Showers

105 CMR 451.123* Maintenance: Appearance of mold outside showers

Recreation Area

No Violations Noted

Cells

105 CMR 451.321* Cell Size: Inadequate floor space in cell # 101-134 and 201-236
105 CMR 451.353 Interior Maintenance: Light fixture blocked in cell # 103, 111, 122, and 219
105 CMR 451.350* Structural Maintenance: Ceiling damaged in room # 237
105 CMR 451.353* Interior Maintenance: Floor tiles damaged in room # 238

FN1

Main Area

105 CMR 451.350 Structural Maintenance: Rec door not rodent and weathertight

Slop Sink

No Violations Noted

Rec Area

No Violations Noted

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor
105 CMR 451.123

Maintenance: Ceiling tiles rusted outside showers

Cells
105 CMR 451.321*

Cell Size: Inadequate floor space in cell # 101, 102, 104-107, 201, 202, and 204-207

FS1

Main Area
105 CMR 451.353*
105 CMR 451.350*

Interior Maintenance: Ceiling tiles damaged near rec door
Structural Maintenance: Rec door not rodent and weathertight

Slop Sink

No Violations Noted

Toilet Area

No Violations Noted

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor
105 CMR 451.123*

Maintenance: Floor paint peeling outside of showers

Recreation Area

No Violations Noted

Cells
105 CMR 451.321*

Cell Size: Inadequate floor space in cell # 101, 102, 104-107, 201, 202, and 204-207

DN1

Main Area
105 CMR 451.350*

Structural Maintenance: Rec door not rodent and weathertight

Slop Sink

No Violations Noted

Toilet Area

No Violations Noted

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor
105 CMR 451.123*
105 CMR 451.123*

Maintenance: Ceiling dirty, appearance of mold outside showers
Maintenance: Ceiling tiles damaged outside showers

105 CMR 451.123	Maintenance: Soap scum on walls in shower # 4, 5, 6, and 7
<i>Recreation Area</i>	
105 CMR 451.353	Interior Maintenance: Bird nests in rafters
<i>Cells</i>	
105 CMR 451.321*	Cell Size: Inadequate floor space in cell # 101, 102, 104-107, 201, 202, and 204-207
DS1	
<i>Main Area</i>	
105 CMR 451.350*	Structural Maintenance: Rec door not rodent and weathertight
<i>Slop Sink</i>	
	No Violations Noted
<i>Showers – 1st Floor</i>	
105 CMR 451.123*	Maintenance: Appearance of mold outside showers
<i>Showers – 2nd Floor</i>	
105 CMR 451.123*	Maintenance: Floor paint peeling outside showers
105 CMR 451.123*	Maintenance: Appearance of mold outside showers
105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 4, 5, 6, and 7
<i>Recreation Area</i>	
105 CMR 451.353	Interior Maintenance: Bird nests in rafters
<i>Cells</i>	
105 CMR 451.321*	Cell Size: Inadequate floor space in cell # 101, 102, 104-107, 201, 202, and 204-207
BS101	
<i>Bunks</i>	
105 CMR 451.322*	Cell Size: Inadequate floor space in dorm area
<i>Bathroom</i>	
105 CMR 451.353*	Interior Maintenance: Ceiling tiles rusted outside bathroom
<i>Showers</i>	
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower leaking in shower # 6
105 CMR 451.123	Maintenance: Shower # 4 out-of-order
105 CMR 451.123	Maintenance: Ceiling tiles rusted outside shower room
BN101	
105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty
105 CMR 451.353*	Interior Maintenance: Ceiling vent rusted
<i>Bunks</i>	
105 CMR 451.322*	Cell Size: Inadequate floor space in dorm area
<i>Bathroom</i>	
	No Violations Noted
<i>Showers</i>	
105 CMR 451.123*	Maintenance: Ceiling vent dusty
105 CMR 451.353*	Interior Maintenance: Ceiling tiles damaged at bathroom entrance

BS201

105 CMR 451.353* Interior Maintenance: Ceiling vents dusty
105 CMR 451.353* Interior Maintenance: Ceiling tiles damaged outside of bathroom
105 CMR 451.353* Interior Maintenance: Baseboard damaged under phones
105 CMR 451.353 Interior Maintenance: Ceiling vents rusted

Bunks

105 CMR 451.322* Cell Size: Inadequate floor space in dorm area

Bathroom

No Violations Noted

Showers

Unable to Inspect -- In Use

BN201

105 CMR 451.353* Interior Maintenance: Ceiling vents dusty
105 CMR 451.353* Interior Maintenance: Ceiling ventilation grilles rusty

Bunks

105 CMR 451.322* Cell Size: Inadequate floor space in dorm area

Bathroom

No Violations Noted

Showers

No Violations Noted

C1*Main Area*

105 CMR 451.353 Interior Maintenance: Ceiling tiles damaged outside cell # 236
105 CMR 451.353 Interior Maintenance: Ceiling tiles damaged above rec deck door
105 CMR 451.350 Structural Maintenance: Rec deck door not rodent and weathertight

Slop Sink

No Violations Noted

Showers

105 CMR 451.123 Maintenance: Shower # 8 leaking
105 CMR 451.123 Maintenance: Soap scum on walls in shower # 9

Recreation Area

105 CMR 451.353 Interior Maintenance: Bird nests in rafters

Cells

105 CMR 451.321* Cell Size: Inadequate floor space in cell # 101-134 and 201-236
105 CMR 451.140* Adequate Ventilation: Inadequate ventilation, wall ventilation grilles blocked in cell # 109
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall ventilation grilles blocked in cell # 105, 117, and 118

G Block*Main Area*

No Violations Noted

GE South

105 CMR 451.353*
105 CMR 451.350*
105 CMR 451.353

Interior Maintenance: Ceiling tiles damaged
Structural Maintenance: Ceiling leaking
Interior Maintenance: Appearance of mold on ceiling

Slop Sink

No Violations Noted

Showers

Unable to Inspect – In Use

Chemical Storage

No Violations Noted

Cells

105 CMR 451.321

Cell Size: Inadequate floor space in cell # 201-207

GE North*Slop Sink*

No Violations Noted

Showers

105 CMR 451.123

Maintenance: Shower # 1 leaking

Recreation Deck

No Violations Noted

Cells

105 CMR 451.321*
105 CMR 451.140

Cell Size: Inadequate floor space in cell # 109-118 and 209-218
Adequate Ventilation: Inadequate ventilation, wall ventilation grille blocked in cell # 215

GW North*Main Area*

105 CMR 451.350*

Structural Maintenance: Hole in wall near cell # 109

Slop Sink

No Violations Noted

Showers

105 CMR 451.123*
105 CMR 451.123

Maintenance: Ceiling vent rusted in shower # 1-3
Maintenance: Shower # 2 out-of-order

Cells

105 CMR 451.321*
105 CMR 451.353

Cell Size: Inadequate floor space in cell # 109-118 and 209-218
Interior Maintenance: Light fixture blocked in cell # 118

GW South*Main Area*

105 CMR 451.350

Structural Maintenance: Ceiling leaking

Slop Sink

No Violations Noted

Showers

105 CMR 451.123
105 CMR 451.123

Maintenance: Shower # 1 leaking
Maintenance: Floor dirty in shower # 1 and 2

Cells

No Violations Noted

3rd Floor

Main Hallway

Janitor's Closet – 3022

No Violations Noted

Staff Bathroom – 3021

No Violations Noted

Storage – 3020

Unable to Inspect – No Access

Janitor's Closet – 3018

No Violations Noted

Classroom – 3015

No Violations Noted

Storage – 3011

No Violations Noted

Janitor's Closet - 3010

No Violations Noted

Staff Bathroom – 3009

No Violations Noted

Storage – 3008

FC 3-701.11(A)*

FC 4-903.11(A)(2)*

Contaminated Food, Disposition: Unsafe, adulterated, or not honestly presented food not properly reconditioned or discarded, expired milk in refrigerator
Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered

Janitor's Closet – 3006

No Violations Noted

Classroom – 3005

No Violations Noted

Staff Bathroom – 3003

No Violations Noted

FS3

Main Area

105 CMR 451.350*
105 CMR 451.353*
105 CMR 451.353*

Structural Maintenance: Ceiling leaking
Interior Maintenance: Ceiling tiles damaged
Interior Maintenance: Ceiling vents dusty

105 CMR 451.350*	Structural Maintenance: Rec deck door not rodent and weathertight
<i>Slop Sink</i>	No Violations Noted
<i>Medical Room</i>	No Violations Noted
<i>Toilet Area</i>	No Violations Noted
<i>Showers – 1st Floor</i>	No Violations Noted
<i>Showers – 2nd Floor</i>	
105 CMR 451.123*	Maintenance: Floor paint peeling outside showers
105 CMR 451.123*	Maintenance: Shower hooks rusty in shower # 6 and 7
105 CMR 451.123*	Maintenance: Appearance of mold outside showers
105 CMR 451.123*	Maintenance: Ceiling leaking outside shower
<i>Cells</i>	
105 CMR 451.321*	Cell Size: Inadequate floor space in cell # 301, 302, 304-307, 401, 402, and 404-407

FN3

<i>Main Area</i>	
105 CMR 451.353*	Interior Maintenance: Ceiling vents dusty
105 CMR 451.353*	Interior Maintenance: Ceiling tiles damaged
105 CMR 451.350*	Structural Maintenance: Roof leaking
105 CMR 451.350*	Structural Maintenance: Rec deck door not rodent and weathertight

<i>Slop Sink</i>	No Violations Noted
------------------	---------------------

<i>Toilet Area</i>	
105 CMR 451.123*	Maintenance: Baseboard damaged

<i>Showers – 1st Floor</i>	
105 CMR 451.123	Maintenance: Appearance of mold on ceiling outside showers

<i>Showers – 2nd Floor</i>	
105 CMR 451.123*	Maintenance: Shower hooks rusty in shower # 4 and 5
105 CMR 451.123*	Maintenance: Appearance of mold outside showers

<i>Cells</i>	
105 CMR 451.321*	Cell Size: Inadequate floor space in cell # 301, 302, 304-307, 401, 402, and 404-407
105 CMR 451.350	Structural Maintenance: Floor damaged in cell # 402

H3

<i>Main Area</i>	
105 CMR 451.350*	Structural Maintenance: Rec deck door not rodent and weathertight
105 CMR 451.350*	Structural Maintenance: Hole in wall outside cell # 322
105 CMR 451.350	Structural Maintenance: Ceiling leaking

105 CMR 451.353

Interior Maintenance: Appearance of mold on ceiling

Slop Sink

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Showers

105 CMR 451.123

Maintenance: Shower # 2 leaking

105 CMR 451.123*

Maintenance: Appearance of mold outside showers

105 CMR 451.123*

Maintenance: Vents dusty in shower # 9

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in cell # 301-334 and 401-436

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty in cell # 438

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty in cell # 437

105 CMR 451.353*

Interior Maintenance: Baseboard damaged in cell # 437

105 CMR 451.353

Interior Maintenance: Floor paint peeling in cell # 419, 422, and 434

DN3

Main Area

105 CMR 451.350*

Structural Maintenance: Rec deck door not rodent and weathertight

Slop Sink

105 CMR 451.353*

Interior Maintenance: Ceiling tiles damaged

Toilet Area

No Violations Noted

Showers -- 1st Floor

No Violations Noted

Showers -- 2nd Floor

105 CMR 451.123

Maintenance: Shower # 6 and 7 leaking

Recreation Deck

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in cell # 301, 302, 304-307, 401, 402, and 404-407

DS3

Main Area

105 CMR 451.350*

Structural Maintenance: Rec deck door not rodent and weathertight

Slop Sink

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Toilet Area

No Violations Noted

Showers -- 1st Floor

No Violations Noted

Showers – 2nd Floor
105 CMR 451.123*

Maintenance: Appearance of mold outside showers

Recreation Deck

No Violations Noted

Cells
105 CMR 451.321*

Cell Size: Inadequate floor space in cell # 301, 302, 304-307, 401, 402, and 404-407

E3

Main Area
105 CMR 451.350*

Structural Maintenance: Rec deck door not rodent and weathertight

Slop Sink
105 CMR 451.353

Interior Maintenance: Floor not easily cleanable, rubber floor

Showers
105 CMR 451.123
105 CMR 451.123

Maintenance: Vent dusty in shower # 8 and 9
Maintenance: Shower # 2 leaking

Cells
105 CMR 451.321*
105 CMR 451.353*
105 CMR 451.353

Cell Size: Inadequate floor space in cell # 301-334 and 401-436
Interior Maintenance: Light fixture blocked in cell # 312
Interior Maintenance: Light fixture blocked in cell # 313, 401, and 402

C3

Main Area
105 CMR 451.353
105 CMR 451.350*
105 CMR 451.350

Interior Maintenance: Ceiling tiles damaged
Structural Maintenance: Rec deck door not rodent and weathertight
Structural Maintenance: Ceiling leaking

Slop Sink
105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

Showers
105 CMR 451.123
105 CMR 451.123

Maintenance: Soap scum on walls in shower # 9
Maintenance: Appearance of mold outside showers

Recreation Deck

No Violations Noted

Cells
105 CMR 451.321*

Cell Size: Inadequate floor space in cell # 301-334 and 401-436

Warehouse – Support Building

Freezer

No Violations Noted

Fridge # 1

No Violations Noted

Fridge # 2

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Inmate Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Work Crew Area

Bathroom

No Violations Noted

Break Area

No Violations Noted

K9 Unit

Female Bathroom
105 CMR 451.123

Maintenance: Vent dusty

Bathroom # 2

No Violations Noted

Janitor's Closet

No Violations Noted

Kitchen Area

No Violations Noted

Garage

Bathroom – W124

No Violations Noted

Janitor's Closet – W123

No Violations Noted

Print Shop

No Violations Noted

Inmate Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Janitor's Closet – W111

No Violations Noted

Observations and Recommendations

1. The inmate population was 1061 at the time of inspection.
2. At the time of inspection, the Department recommended that all of the rubber flooring in the janitor's closets be removed.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

To review the Labeling regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Nicholas Gale
Environmental Health Inspector, CSP, BEH

cc: Jan Sullivan, Acting Director, BEH
Steven Hughes, Director, CSP, BEH
Jay Youmans, Director of Government Affairs
Marylou Sudders, Secretary, Executive Office of Health and Human Services
Carol Higgins O'Brien, Commissioner, DOC
Antone Moniz, Superintendent
Captain Eugene Irvine, EHSO
Michelle Roberts, MA, CHO, Health Director, Plymouth Health Department
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Daniel Bennett, Secretary, EOPSS