



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Environmental Health
Community Sanitation Program
5 Randolph Street, Canton, MA 02021
Phone: 781-828-7700 Fax: 781-828-7703

CHARLES D. BAKER
Governor

KARYN E. POLITO
Lieutenant Governor

MARYLOU SUDDERS
Secretary

MONICA BHAREL, MD, MPH
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

October 22, 2018

Joseph D. McDonald, Jr., Sheriff
Plymouth County Correctional Facility
26 Long Pond Road
Plymouth, MA 02360

Re: Facility Inspection - Plymouth County Correctional Facility

Dear Sheriff McDonald:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 2013 Food Code; 105 CMR 500.000 Good Manufacturing Practices for Food; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Plymouth County Correctional Facility on September 24 and 25, 2018 accompanied by Captain Eugene Irvine, Environmental Health and Safety Officer. Violations noted during the inspection are listed below including 81 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

Front Lobby

Main Area

No Violations Noted

Janitor's Closet

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Administration Area

Break Room # 1014

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

105 CMR 451.200	Food Storage, Preparation and Service: Food service not in compliance with 105 CMR 590.000, expired milk in refrigerator
<i>Male Bathroom # 1013</i>	No Violations Noted
<i>Female Bathroom # 1015</i>	No Violations Noted
Administration - Main Hallway	
<i>Janitor's Closet # 1027</i>	
105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
Female Locker Room	
105 CMR 451.123*	Maintenance: Ceiling vent dusty above toilets
<i>Showers</i>	
	No Violations Noted
Male Locker Room	
105 CMR 451.123*	Maintenance: Ceiling vent dusty above toilets
<i>Showers</i>	
105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 3
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1 and 2
Staff Gym	
	No Violations Noted
IPS Office	
	No Violations Noted
<u>Kitchen</u>	
Staff Dining	
<i>Staff Dining Area</i>	
	No Violations Noted
<i>Staff Serving Line</i>	
FC 4-601.11(C)*	Cleaning of Equipment and Utensils, Objective: Nonfood contact surface dirty, interior of oven doors dirty
Kitchen Area	
<i>Warming Units</i>	
	No Violations Noted
<i>Bakery Area</i>	
	No Violations Noted
<i>Office</i>	
	No Violations Noted

<i>Office Bathroom</i>	No Violations Noted
<i>Dry Storage</i>	No Violations Noted
<i>Tool Closet</i>	No Violations Noted
<i>Cooler # 2</i>	Unable to Inspect – Closed for Repair
<i>Inmate Break Area</i>	No Violations Noted
<i>Inmate Bathroom</i> 105 CMR 451.123	Maintenance: Urinal out-of-order
<i>Janitor's Closet</i>	No Violations Noted
<i>Freezer # 1</i> FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, ice build-up throughout
<i>Cooler # 3</i>	No Violations Noted
<i>Cooler # 4</i>	No Violations Noted
<i>Cooler # 5</i>	No Violations Noted
<i>Freezer # 6</i> FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, ice build-up on fans
Prep Area FC 6-201.11*	Design, Construction and Installation: Floor not easily cleanable, floor damaged throughout
<i>2-Compartment Sink Area</i>	No Violations Noted
<i>Kettle Area</i>	No Violations Noted
Manual Rinse Station	
<i>3-Compartment Sink</i>	No Violations Noted
Dishwashing Machine Area FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, 1 warewash machine out-of-order

Laundry

No Violations Noted

Janitor's Closet

No Violations Noted

Office

No Violations Noted

Chemical Closet

No Violations Noted

Inmate Bathroom # 1058

No Violations Noted

Loading Dock

No Violations Noted

Maintenance # 1053*Small Tool Room*

No Violations Noted

Bathroom

No Violations Noted

Office

No Violations Noted

Office Bathroom

No Violations Noted

Attorney Visits

No Violations Noted

Chapel

No Violations Noted

Medical Corridor

No Violations Noted

HSU*Waiting Room # M103*

No Violations Noted

Staff Break Room

105 CMR 451.200 Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave dirty

105 CMR 451.200 Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of freezer dirty

105 CMR 451.200 Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, cookies not stored properly

105 CMR 451.200 Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, ice tray left inside sink in Staff Bathroom # M130

<i>Nurse's Station # M106</i>	No Violations Noted
<i>Storage # M133</i>	No Violations Noted
<i>Room # M132</i>	No Violations Noted
<i>Autoclave # M131</i>	No Violations Noted
<i>Staff Bathroom # M130</i>	No Violations Noted
<i>Records # M129</i>	No Violations Noted
<i>Pharmacy # M128</i>	
105 CMR 451.110(A)*	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink
105 CMR 451.110(A)*	Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink
<i>Janitor's Closet # M127</i>	
105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
<i>Laboratory # M126</i>	No Violations Noted
<i>Dentist # M124</i>	No Violations Noted
<i>X-Ray Room # M123</i>	No Violations Noted
<i>Inmate Bathroom # M122</i>	No Violations Noted
<i>Exam Room # M121</i>	No Violations Noted
<i>Room # M119</i>	No Violations Noted
<i>Room # 115</i>	No Violations Noted
<i>Handicapped Bathroom</i>	No Violations Noted
<i>Office # M112</i>	No Violations Noted
<i>Cell # M113 - M116</i>	No Violations Noted

Office # M117

No Violations Noted

Office # M118

No Violations Noted

Property

No Violations Noted

Booking

Main Area

No Violations Noted

Office # R112

No Violations Noted

Records # R106

No Violations Noted

Inmate Toilet # R105

No Violations Noted

Inmate Bathroom # R118

No Violations Noted

Janitor's Closet # R126

105 CMR 451.353*

Interior Maintenance: Unlabeled chemical bottles

Showers

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 2

Staff Bathroom # R127

No Violations Noted

Kitchen Area

105 CMR 451.126*

105 CMR 451.200

Hot Water: Hot water temperature recorded at 95°F

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, unlabeled food in refrigerator

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functioning thermometer in refrigerator

Officer's Landing

No Violations Noted

Watch Cells

No Violations Noted

Holding Cells

105 CMR 451.353

Interior Maintenance: Floor paint damaged in cell # 116

Library

No Violations Noted

Library Bathroom

No Violations Noted

Human Services # 1079

105 CMR 451.353 Interior Maintenance: Appearance of mold on floor tiles in many areas

Break Room

105 CMR 451.200* Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of freezer dirty

105 CMR 451.200 Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functioning thermometer in refrigerator

105 CMR 451.200 Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, interior of cabinet above sink dirty

105 CMR 451.353 Interior Maintenance: Ceiling vent dusty

Offices

No Violations Noted

Staff Bathroom # 1069

No Violations Noted

Janitor's Closet # 1064

No Violations Noted

Gymnasium

105 CMR 451.353* Interior Maintenance: Landing dirty above office

Main Hallway**Female Staff Bathroom # 1039**

No Violations Noted

Male Staff Bathroom # 1040

No Violations Noted

Janitor's Closet # 1084

No Violations Noted

Staff Bathroom # 1090

Unable to Inspect --- In Use

Janitor's Closet # 1095

No Violations Noted

Staff Bathroom # 1098

No Violations Noted

Staff Bathroom # 1099

Unable to Inspect --- In Use

Staff Bathroom # 1107

No Violations Noted

Janitor's Closet # 1108

No Violations Noted

Unit Manager's Office # 1112

No Violations Noted

Classroom # 1102

No Violations Noted

Staff Bathroom # 1102

No Violations Noted

Classroom # 1110

No Violations Noted

Cell Blocks/Pods

A1

Classroom

No Violations Noted

Slop Sink

No Violations Noted

Bathroom

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty outside showers

105 CMR 451.123

Maintenance: Floor surface damaged in shower # 1-6

Cell # A107 - A110

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty in cell # A107 and A108

Main Area Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Several ceiling vents dusty

105 CMR 451.353

Interior Maintenance: Floor generally dirty

BS101

Trap – First Floor

No Violations Noted

Slop Sink

No Violations Noted

Bathroom

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty outside showers

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 7

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

BN101*Slop Sink*

No Violations Noted

Bathroom

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty outside showers

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

BS201*Slop Sink*

No Violations Noted

Bathroom

105 CMR 451.123

Maintenance: Floor dirty in toilet area

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty outside showers

105 CMR 451.123*

Maintenance: Light fixture rusted inside shower # 1-3

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

BN201*Slop Sink*

No Violations Noted

Bathroom

No Violations Noted

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty outside showers

105 CMR 451.123*

Maintenance: Curtain missing in shower # 6 and 7

105 CMR 451.123

Maintenance: Floor dirty in shower # 3 and 4

Main Area – Dorm Bunks

105 CMR 451.322*

Cell Size: Inadequate floor space in dorm area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

C1*Main Area*

No Violations Noted

Slop Sink

No Violations Noted

Showers

105 CMR 451.123 Maintenance: Ceiling access panel door rusted in shower # 5

Recreation Deck

No Violations Noted

Second Floor --- Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 117, 120, 128, 213, and 224

DNI

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers -- 1st Floor

No Violations Noted

Showers -- 2nd Floor

No Violations Noted

Recreation Deck

105 CMR 451.353

Interior Maintenance: Walls dirty

Second Floor -- Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 107 and 206

DSI

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers -- 1st Floor

No Violations Noted

Showers -- 2nd Floor

No Violations Noted

Recreation Deck

No Violations Noted

Second Floor -- Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

E1

Main Area

105 CMR 451.353

Interior Maintenance: Ceiling vents dusty

Slop Sink

105 CMR 451.353*

Interior Maintenance: Wall vent dusty

105 CMR 451.353

Interior Maintenance: Mop stored on floor

Showers

105 CMR 451.123*

Maintenance: Mold on ceiling outside showers

105 CMR 451.123

Maintenance: Ceiling tiles dusty outside showers

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 4, 5, 6, 7, 8, and 9

Recreation Deck

105 CMR 451.353*

Interior Maintenance: Wall paint damaged

105 CMR 451.353

Interior Maintenance: Walls dirty

Second Floor -- Rooms

105 CMR 451.353*

Interior Maintenance: Ceiling tiles damaged in room # 238

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 126

FN1

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Recreation Deck

105 CMR 451.353*

Interior Maintenance: Wall dirty

Showers -- 1st Floor

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 1

Showers -- 2nd Floor

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 7

Second Floor -- Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

FS1

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor

No Violations Noted

Recreation Deck

105 CMR 451.353*

Interior Maintenance: Wall dirty

Second Floor -- Rooms

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty in room # 208

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

H1

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers

No Violations Noted

Recreation Deck

No Violations Noted

Second Floor – Rooms

105 CMR 451.353*

Interior Maintenance: Ceiling vent blocked in room # 238

Cells

105 CMR 451.321*

105 CMR 451.140

Cell Size: Inadequate floor space in all cells

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 103, 109, 110, 111, 112, 117, 133, 204, 205, 209, 211, 214, 220, 229, and 234

G Block

Main Area

No Violations Noted

GE South

Slop Sink

No Violations Noted

Showers

105 CMR 451.123 Maintenance: Generally dirty conditions in shower # 1 and 2

Chemical Storage

No Violations Noted

Cells

105 CMR 451.321* Cell Size: Inadequate floor space in all cells

GE North

105 CMR 451.353* Interior Maintenance: Ceiling tiles water damaged

Slop Sink

No Violations Noted

Showers

105 CMR 451.123* Maintenance: Shower # 2 dirty

105 CMR 451.123 Maintenance: Shower # 1 dirty

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower # 1 and 3 leaking

Recreation Deck

No Violations Noted

Cells

105 CMR 451.321* Cell Size: Inadequate floor space in all cells

105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 211

GW North

105 CMR 451.353* Interior Maintenance: Floor paint damaged

105 CMR 451.353 Interior Maintenance: Ceiling tiles water stained

Slop Sink

No Violations Noted

Showers

105 CMR 451.123* Maintenance: Ceiling vents dusty in shower area

Cells

105 CMR 451.321* Cell Size: Inadequate floor space in all cells

105 CMR 451.140* Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 116, 117, and 215

105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 211

GW South

Slop Sink

No Violations Noted

Showers

Unable to Inspect – In Use

Cells

105 CMR 451.140* Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 202 and 203

3rd Floor

Main Hallway

Janitor's Closet # 3022

No Violations Noted

Staff Bathroom # 3021

No Violations Noted

Storage # 3020

No Violations Noted

Janitor's Closet # 3018

No Violations Noted

Classroom # 3015

No Violations Noted

Storage # 3011

No Violations Noted

Janitor's Closet # 3010

105 CMR 451.353*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Interior Maintenance: Ceiling vent not secured

Staff Bathroom # 3009

No Violations Noted

Break Room # 3008

No Violations Noted

Janitor's Closet # 3006

No Violations Noted

Classroom # 3005

No Violations Noted

Storage # 3004

No Violations Noted

Staff Bathroom # 3003

No Violations Noted

3rd Floor - Cell Blocks/Pods

C3

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers

105 CMR 451.123

Maintenance: Generally dirty conditions in shower # 6

Recreation Deck

No Violations Noted

Second Floor Rooms

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty in room # 437

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 422 and 425

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 313, 330, 331, 404, 408, and 421

105 CMR 451.353

Interior Maintenance: Ceiling dirty in cell # 426

DN3

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor

No Violations Noted

Recreation Deck

No Violations Noted

Second Floor – Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 302, 303, 404, and 405

DS3

Main Area

No Violations Noted

Slop Sink

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

Showers – 1st Floor

No Violations Noted

Showers – 2nd Floor

105 CMR 451.123

Maintenance: Mold on walls outside showers

Recreation Deck

No Violations Noted

Second Floor -- Rooms

No Violations Noted

Cells

105 CMR 451.321*
105 CMR 451.140

Cell Size: Inadequate floor space in all cells
Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 301, 302, 303, and 402

E3

Main Area

105 CMR 451.353

Interior Maintenance: Wall paint damaged behind phones

Slop Sink

No Violations Noted

Showers

105 CMR 451.123

Maintenance: Walls stained in shower # 8 and 9

Recreation Deck

105 CMR 451.353

Interior Maintenance: Wall paint damaged

Second Floor -- Rooms

No Violations Noted

Cells

105 CMR 451.321*
105 CMR 451.140*

Cell Size: Inadequate floor space in all cells
Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 303, 305, and 407

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 301, 304, 309, 318, 415, and 424

FS3

Main Area

No Violations Noted

Slop Sink

No Violations Noted

Medical Room

No Violations Noted

Showers -- 1st Floor

No Violations Noted

Showers -- 2nd Floor

105 CMR 451.123*
105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 6 and 7
Maintenance: Floor paint damaged outside showers

Second Floor -- Rooms

No Violations Noted

Cells

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

FN3

Main Area

105 CMR 451.353* Interior Maintenance: Ceiling vents dusty

Slop Sink

No Violations Noted

Showers -- 1st Floor

105 CMR 451.123 Maintenance: Soap scum on walls in shower # 1 and 3

Showers 2nd Floor

105 CMR 451.123* Maintenance: Soap scum on walls in shower # 5 and 6

105 CMR 451.123 Maintenance: Soap scum on walls in shower # 4 and 7

105 CMR 451.123 Maintenance: Mold on walls outside showers

Second Floor Rooms

No Violations Noted

Cells

105 CMR 451.321* Cell Size: Inadequate floor space in all cells

105 CMR 451.353* Interior Maintenance: Ceiling paint damaged in cell # 307

105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 307

H3

Main Area

105 CMR 451.350* Structural Maintenance: Ceiling leaking in back stairwell

Slop Sink

No Violations Noted

Showers

105 CMR 451.123* Maintenance: Ceiling vent dusty in shower # 9

105 CMR 451.123* Maintenance: Mold on ceiling outside showers

Cells

105 CMR 451.321* Cell Size: Inadequate floor space in all cells

105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 309, 325, 326, 328, 413, and 414

105 CMR 451.353 Interior Maintenance: Wall paint damaged in cell # 309, 333, and 424

Garage

Bathroom # W124

No Violations Noted

Janitor's Closet # W123

No Violations Noted

Print Shop

No Violations Noted

Inmate Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Janitor's Closet # W111

No Violations Noted

Warehouse – Support Building

Canteen Storage

105 CMR 451.200

Food Storage, Preparation and Service: Food service not in compliance with 105 CMR 590.000, Poland Spring water catch dirty

Freezer # 1

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, ice cream container packaging compromised

Freezer # 2

No Violations Noted

Fridge # 1

No Violations Noted

Fridge # 2

No Violations Noted

Male Bathroom

No Violations Noted

Female Bathroom

No Violations Noted

Inmate Bathroom

No Violations Noted

Janitor's Closet

No Violations Noted

Uniforms

No Violations Noted

Work Crew Area

Bathroom

No Violations Noted

Break Area

105 CMR 451.200

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, toaster oven damaged

Record Storage

No Violations Noted

K9 Unit

Female Bathroom

No Violations Noted

Bathroom # 2

No Violations Noted

Janitor's Closet

105 CMR 451.353

Interior Maintenance: Noxious odor

Laundry

No Violations Noted

Observations and Recommendations

1. The inmate population was 1,018 at the time of inspection.
2. At the time of inspection, the Department recommended that metering faucets throughout the facility be adjusted so they remain running for 20 seconds at minimum. This will allow for the hot water to reach the desired range of 110°F - 130°F and provide the opportunity for staff and inmates to thoroughly wash their hands.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Retail Food". Then under "Regulations" click "2013 Food Code Merged with 105 CMR 590 and 2013 Food Code"

To review the Labeling regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Processing". Then under "Regulations" click "105 CMR 500.000: Good Manufacturing Practices for Food"

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Nicholas Gale
Environmental Health Inspector, CSP, BEH

cc: Monica Bharel, MD, MPH, Commissioner, DPH
Jana Ferguson, Director, BEH
Steven Hughes, Director, CSP, BEH
Marylou Sudders, Secretary, Executive Office of Health and Human Services
Thomas Turco, Commissioner, DOC (electronic copy)
Antone Moniz, Superintendent (electronic copy)
Captain Eugene Irvine, EHSO (electronic copy)
Dr. Nate Horwitz-Willis, CHO, Health Director, Plymouth Board of Health (electronic copy)
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Daniel Bennett, Secretary, EOPSS
Nelson Alves, Director, Policy Development and Compliance Unit (electronic copy)