



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Environmental Health
Community Sanitation Program
5 Randolph Street, Canton, MA 02021
Phone: 781-828-7700 Fax: 781-774-6700

CHARLES D. BAKER
Governor

KARYN E. POLITO
Lieutenant Governor

MARYLOU SUDDERS
Secretary

MONICA BHAREL, MD, MPH
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

April 12, 2018

Steven W. Tompkins, Sheriff
Suffolk County Sheriff's Department
20 Bradston Street
Boston, MA 02118

Re: Facility Inspection – Suffolk County House of Correction, Boston

Dear Sheriff Tompkins:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Suffolk County House of Correction on March 26, 27, and 28, 2018 accompanied by John Fallon, Environmental Health and Safety/Fire Safety Officer and Captain Brian Reynolds, Support Service Supervisor. Violations noted during the inspection are listed below including 576 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

BUILDING # 1

11th Floor

Staff Bathroom # 1142
105 CMR 451.123*

Maintenance: Ceiling vent dusty

Classroom # 1145

No Violations Noted

Classroom # 1156

No Violations Noted

Slop Sink Room # 1158

No Violations Noted

Meeting Room

No Violations Noted

Program Area

Classroom # 1 1151

No Violations Noted

Classroom # 2 1153

No Violations Noted

Caseworker's Office # 1143

No Violations Noted

Unit 1-11-1

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

Showers

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 2

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower 1, 2, and 3

Supply Closet

No Violations Noted

Bathroom

Unable to Inspect - No Longer Used

Kitchenette

105 CMR 451.126

Hot Water: Hot water temperature recorded at 85⁰F at handwash sink

Laundry Area

105 CMR 451.353

Interior Maintenance: Dryer duct damaged

Cells

105 CMR 451.103

Mattresses: Mattress damaged in cell # 2

Unit 1-11-2

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Showers

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 3

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 2

Bathroom

Unable to Inspect - No Longer Used

Laundry Area

No Violations Noted

Kitchenette

No Violations Noted

Cells

No Violations Noted

10th Floor

10th Floor Visiting Room

No Violations Noted

Room # 1053

No Violations Noted

Room # 1054

No Violations Noted

Room # 1059

No Violations Noted

Offices

No Violations Noted

Staff Bathroom # 1074

No Violations Noted

Slop Sink Room # 1050

No Violations Noted

Unit 1-10-1

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353*

Interior Maintenance: Wall vent dusty

Shower

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 1 and 2

Kitchenette

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # 9, 10, 12, and 13

Unit 1-10-2

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Showers

105 CMR 451.123*

Maintenance: Ceiling vent dusty in shower # 1 and 2

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 3

Kitchenette

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, drain clogged at handwash sink

Laundry Area

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # 10

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 2

105 CMR 451.353

Interior Maintenance: Floor paint damaged in cell # 8

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 3 and 10

Unit 1-10-3

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Cells

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # 1, 2, 3, 5, and 6

Shower

105 CMR 451.123

Maintenance: Ceiling vent dusty

105 CMR 451.123

Maintenance: Soap scum on walls

Caseworker's Office

No Violations Noted

Unit 1-10-4 Women's Infirmary Area

Supply Closet

No Violations Noted

Exam Room

No Violations Noted

Staff Bathroom

105 CMR 451.123

Maintenance: Ceiling vent dusty

9th Floor

Staff Bathroom # 944

105 CMR 451.123*

Maintenance: Ceiling vent dusty

Slop Sink # 956

No Violations Noted

Recreation Deck # 940

105 CMR 451.353*

Interior Maintenance: Floor paint damaged

105 CMR 451.353*

Interior Maintenance: Ceiling paint damaged

Programs/Education Offices

No Violations Noted

Unit 1-9-1

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353*

Interior Maintenance: Ceiling vents dusty

Laundry Area

No Violations Noted

Shower Area

No Violations Noted

Closet

105 CMR 451.353*

Interior Maintenance: Wet mop stored in bucket

Kitchenette

105 CMR 451.130*

Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink

Cells

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 9

105 CMR 451.353

Interior Maintenance: Wall paint damaged in cell # 2

105 CMR 451.103

Mattresses: Mattress damaged in cell # 16

Unit 1-9-2

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Laundry Area

No Violations Noted

Shower Area

No Violations Noted

Closet

No Violations Noted

Kitchenette

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # 1, 2, 3, 4, 5, 6, 7, 8, 11, 13, 14, 15, and 16

105 CMR 451.353

Interior Maintenance: Floor paint damaged in cell # 12

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 2

105 CMR 451.353

Interior Maintenance: Bed paint damaged in cell # 10

8th Floor

8th Floor Program Area

No Violations Noted

Slop Sink # 848

No Violations Noted

Recreation Deck

105 CMR 451.353*

Interior Maintenance: Floor paint damaged

Unit 1-8-1

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

No Violations Noted

Kitchenette

105 CMR 451.130*
105 CMR 451.353*

Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink
Interior Maintenance: Ceiling vent dusty

Laundry Area

105 CMR 451.353

Interior Maintenance: Dryer duct damaged

Utility Closet

No Violations Noted

Showers

No Violations Noted

Cells

105 CMR 451.353*
105 CMR 451.353

Interior Maintenance: Floor paint damaged in cell # 2 and 6
Interior Maintenance: Floor paint damaged in cell # 1, 3, 4, 7, 13, and 15

Unit 1-8-2

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

No Violations Noted

Kitchenette

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty

Laundry Area

No Violations Noted

Utility Closet

No Violations Noted

Showers

105 CMR 451.123*
105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 2 and 3
Maintenance: Ceiling vent dusty in shower # 1

Cells

105 CMR 451.353*
105 CMR 451.103

Interior Maintenance: Floor paint damaged in cell # 3, 4, 5, 6, 7, 8, 10, 11, 12, 13, and 16
Mattresses: Mattress cover missing in cell # 1

7th Floor (Office Space)

Slop Sink Room # 755

No Violations Noted

Parole Office

No Violations Noted

Gang Intelligence Unit Office

No Violations Noted

6th Floor

6th Floor Meeting Room and Dining Hall

105 CMR 451.360*

Protective Measures: Building not protected against infestation, rodent droppings observed on window sills and on floor below windows

Unit 1-6-1

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty outside cell # 32

Kitchenette

No Violations Noted

Upper Cells

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 29, 30, 31, and 32

105 CMR 451.353

Interior Maintenance: Wall paint damaged in cell # 17, 19, and 20

Upper Showers

105 CMR 451.123*

Maintenance: Door framed rusted in shower # 1, 2, and 3

105 CMR 451.123*

Maintenance: Ceiling vent dusty in shower # 1, 2, and 3

105 CMR 451.130*

Plumbing: Plumbing not maintained in good repair, faucet leaking in shower # 2

105 CMR 451.123

Maintenance: Curtain damaged in shower # 3

Lower Cells

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # 1, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, and 15

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 4

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 6

105 CMR 451.353

Interior Maintenance: Wall paint damaged in cell # 1, 4, 7, and 8

Lower Laundry Area

No Violations Noted

Storage Closet # 634

No Violations Noted

Lower Shower Area

105 CMR 451.123

Maintenance: Ceiling paint damaged in shower # 2 and 3

105 CMR 451.123

Maintenance: Door framed rusted in shower # 1, 2, and 3

Recreation Deck

105 CMR 451.353*

Interior Maintenance: Floor paint damaged

105 CMR 451.353*

Interior Maintenance: Walls dirty

Unit 1-6-2

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged throughout

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty outside cell # 1 and 17

105 CMR 451.350

Structural Maintenance: Window cracked on door to dining hall

Kitchenette

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink

Upper Storage Closet

105 CMR 451.353

Interior Maintenance: Ceiling paint damaged

Upper Cells

105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 17, 18, 19, 25, 26, 27, 28, 30, and 32
105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 24
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 21
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 20, 22, and 30
105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 19 and 25
105 CMR 451.103	Mattresses: Mattress damaged in cell # 20 and 27

Upper Showers

105 CMR 451.123*	Maintenance: Door frame rusted in shower # 1 and 3
105 CMR 451.123*	Maintenance: Walls dirty in shower # 2
105 CMR 451.123*	Maintenance: Floor dirty in shower # 2
105 CMR 451.123*	Maintenance: Ceiling vent dusty in shower # 1, 2, and 3
105 CMR 451.123	Maintenance: Door frame rusted in shower # 2
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1, 2, and 3
105 CMR 451.123	Maintenance: Soap scum on floor in shower # 1, 2, and 3

Lower Laundry

105 CMR 451.353*	Interior Maintenance: Wall dirty behind washer and dryer
------------------	--

Lower Cells

105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 1, 2, 3, 4, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, and 16
105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 2
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 2
105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 8
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 2, 4, 8, 9, and 12
105 CMR 451.103	Mattresses: Mattress damaged in cell # 7 and 9

Lower Showers

105 CMR 451.123*	Maintenance: Door frame rusted in shower # 3
105 CMR 451.123*	Maintenance: Ceiling vent dusty in shower # 1, 2, and 3
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, shower # 3 out-of-order

Staff Bathroom # 656

105 CMR 451.123*	Maintenance: Floor paint damaged
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink

Slop Sink Closet

No Violations Noted

5th Floor

Slop Sink Room # 563

No Violations Noted

5th Floor Custody

Bathroom # 1

No Violations Noted

Bathroom # 2

No Violations Noted

Kitchenette

No Violations Noted

Unit 1-5-1

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Utility Closet

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

Laundry Area

No Violations Noted

Shower Area

105 CMR 451.123*

Maintenance: Door frame rusted in shower # 1, 2, and 3

Kitchenette

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # 1, 2, 3, 4, 5, 6, 7, 8, 9, 11, 12, 13, 14, 15, and 16

105 CMR 451.104

Beds: Bed not in good repair in cell # 7, bed surface damaged

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet continuously running at handwash sink in cell # 16

Classrooms

No Violations Noted

Library

No Violations Noted

Unit 1-5-2*Control*

No Violations Noted

Shower

105 CMR 451.123

Maintenance: Ceiling vent dusty

Common Area

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Kitchenette

No Violations Noted

Dorm Room

No Violations Noted

Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Unit 1-5-2 A*Office # 566*

No Violations Noted

Shower

No Violations Noted

Slop Sink Closet

No Violations Noted

Cells

105 CMR 451.353

Interior Maintenance: Floor paint damaged in cell # 2

4th Floor*Hallway*

No Violations Noted

Staff Bathroom # 445

No Violations Noted

Slop Sink # 454

No Violations Noted

CERT Office

No Violations Noted

Utility Room

No Violations Noted

Visiting Area

No Violations Noted

Unit 1-4-1

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Storage Closet

No Violations Noted

Shower Area

105 CMR 451.123*

Maintenance: Walls dirty in shower # 1

105 CMR 451.123*

Maintenance: Door frame rusted in shower # 2

105 CMR 451.123*

Maintenance: Floor dirty in shower # 3

105 CMR 451.123*

Maintenance: Ceiling vent dusty in shower # 1 and 2

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 1 and 3

Kitchenette

105 CMR 451.353*

Interior Maintenance: Handwash sink dirty

Cells

105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 1, 2, 3, 9, 10, 12, 14, 15, and 16
105 CMR 451.140*	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 13
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 7, 11, and 15
105 CMR 451.103	Mattresses: Mattress damaged in cell # 5, 6, and 9
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 4

Recreation Deck

No Violations Noted

Unit 1-4-2

Unable to Inspect – Closed

3rd Floor

Slop Sink Room # 371

No Violations Noted

Non-Contact Visiting Area # 355

No Violations Noted

Supervisor's Office

No Violations Noted

Unit 1-3-1

105 CMR 451.321*	Cell Size: Inadequate floor space in all cells
------------------	--

Common Area

105 CMR 451.353*	Interior Maintenance: Ceiling vent dusty outside cell # 16
------------------	--

Room # 333 and 334

105 CMR 451.353*	Interior Maintenance: Floor dirty in room # 334
------------------	---

Storage Room # 336

No Violations Noted

Staff Bathroom # 337

No Violations Noted

Cells

105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 1, 2, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, and 16
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 3
105 CMR 451.103	Mattresses: Mattress damaged in cell # 12
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 1, 14, 15, and 16

Recreation Room

No Violations Noted

Recreation Deck

No Violations Noted

Unit 1-3-2

105 CMR 451.321*	Cell Size: Inadequate floor space in all cells
------------------	--

Common Area

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty outside cell # 1

Staff Bathroom # 360

105 CMR 451.123*

Maintenance: Floor paint damaged

Storage Closet # 361

No Violations Noted

Recreation Room # 368

No Violations Noted

Shower Area

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 3

105 CMR 451.123*

Maintenance: Door frame rusted in shower # 1, 2, and 3

105 CMR 451.123*

Maintenance: Ceiling vent dusty in shower # 1 and 2

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 2

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 3

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 3 continuously running

Kitchenette

105 CMR 451.353*

Interior Maintenance: Handwash sink dirty

105 CMR 451.130*

Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink

Cells

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # 2, 3, 4, 5, 6, 9, 10, 11, 12, 13, 14, and 15

105 CMR 451.104*

Beds: Bed not in good repair in cell # 3, bed paint damaged

105 CMR 451.353

Interior Maintenance: Floor paint damaged in cell # 1, 8, and 16

Recreation Deck

No Violations Noted

2nd Floor

Checkpoint

No Violations Noted

Office Area

No Violations Noted

Staff Bathroom # 242

No Violations Noted

Attorney Rooms

No Violations Noted

Main Visiting

105 CMR 451.353

Interior Maintenance: Carpet damaged

Chapel # 170

No Violations Noted

Mosque # 269

No Violations Noted

Staff Bathroom # 263

105 CMR 451.123

Maintenance: Ceiling vent dusty

Slop Sink Room # 271

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

Unit 1-2-1

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.344

Illumination in Habitable Areas: Lights not functioning properly, lights out under skylight

105 CMR 451.200

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty outside bathroom # 235

Slop Sink Room # 229

No Violations Noted

Bathroom # 230

105 CMR 451.123*

Maintenance: Floor paint damaged throughout

105 CMR 451.123*

Maintenance: Curtain missing in shower # 1

105 CMR 451.123*

Maintenance: Floor dirty in shower # 1

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 1, 2, and 4

105 CMR 451.123*

Maintenance: Ceiling vent dusty above toilets

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 2

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, toilet # 1 and 3 out-of-order

Day Room

105 CMR 451.353

Interior Maintenance: Wall paint damaged around phones

Closet # 236

No Violations Noted

Bathroom # 235

105 CMR 451.123*

Maintenance: Floor paint damaged throughout

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 3

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 1 and 4

105 CMR 451.130*

Plumbing: Plumbing not maintained in good repair, urinal # 1 out-of-order

105 CMR 451.123*

Maintenance: Ceiling vents dusty

105 CMR 451.123*

Maintenance: Curtain missing in shower # 4

105 CMR 451.123

Maintenance: Curtain missing in shower # 1

Storage Room # 20

No Violations Noted

Cells

105 CMR 451.353

Interior Maintenance: Ceiling water damaged in cell # 14, 16, 30, and 32

105 CMR 451.353

Interior Maintenance: Wall paint damaged in cell # 18

105 CMR 451.353

Interior Maintenance: Baseboard damaged in cell # 27

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, ceiling vent blocked in cell # 22, 24, and 28

Workout Room # 21

No Violations Noted

Laundry Room
105 CMR 451.353 Interior Maintenance: Ceiling water damaged

TV Area
No Violations Noted

1st Floor

Lobby Area
105 CMR 451.353 Interior Maintenance: Ceiling tiles water stained

Male Bathroom # 139
105 CMR 451.123* Maintenance: Floor paint damaged throughout

Female Bathroom # 140
105 CMR 451.123* Maintenance: Floor paint damaged throughout

Lower Administration

Break Area
No Violations Noted

Male Bathroom
105 CMR 451.123* Maintenance: Ceiling vent dusty

Female Bathroom
105 CMR 451.123* Maintenance: Ceiling vent dusty

Central Control
No Violations Noted

Central Control Bathroom
No Violations Noted

Community Work Program
105 CMR 451.321* Cell Size: Inadequate floor space in all rooms

Control Desk
No Violations Noted

Storage Closet
No Violations Noted

Staff Bathroom # 121
No Violations Noted

Computer Room # 122
No Violations Noted

Office # 123
No Violations Noted

Common Area
No Violations Noted

Serving Area

105 CMR 451.200* Food Storage, Preparation and Service: Food preparation not in compliance with
105 CMR 590.000, interior of microwave oven dirty
105 CMR 451.353* Interior Maintenance: Floor dirty
105 CMR 451.353* Interior Maintenance: Ceiling tiles water damaged

Uniform Closet

No Violations Noted

Sergeant's Office # 129

No Violations Noted

Slop Sink # 125

105 CMR 451.353* Interior Maintenance: Unlabeled chemical bottle

Laundry Room

105 CMR 451.353 Interior Maintenance: Floor paint damaged

TV Area

105 CMR 451.353 Interior Maintenance: Floor tiles damaged

Shower # 3

105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, shower head leaking
105 CMR 451.123* Maintenance: Soap scum on walls
105 CMR 451.123* Maintenance: Ceiling vent dusty

Shower # 2

105 CMR 451.123* Maintenance: Ceiling vent dusty
105 CMR 451.123* Maintenance: Wall damaged
105 CMR 451.123 Maintenance: Soap scum on walls

Bathroom/Shower # 109

105 CMR 451.123* Maintenance: Ceiling vent dusty in shower
105 CMR 451.123* Maintenance: Privacy partition paint damaged
105 CMR 451.123* Maintenance: Floor paint damaged

Bathroom # 2

105 CMR 451.123* Maintenance: Floor dirty
105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, left faucet leaking
105 CMR 451.123* Maintenance: Ceiling vent dusty
105 CMR 451.123* Maintenance: Ceiling vent damaged near entrance
105 CMR 451.123 Maintenance: Floor paint damaged
105 CMR 451.123 Maintenance: Paint damaged on privacy partition

Rooms

105 CMR 451.350* Structural Maintenance: Window broken in room # 9
105 CMR 451.140* Adequate Ventilation: Inadequate ventilation, ceiling vent blocked in room # 3 and 4
105 CMR 451.140 Adequate Ventilation: Inadequate ventilation, ceiling vent blocked in room # 5

BUILDING # 2

Staff Lounge

No violations Noted

Vending Machines

No Violations Noted

Female Locker Room # 2109

105 CMR 451.123* Maintenance: Soap scum on walls in all showers

Male Locker Room # 2110 and 2111

105 CMR 451.123* Maintenance: Light out in shower area

Weight Room

No Violations Noted

Cardio Room

No Violations Noted

Locker Room # 2119

105 CMR 451.353* Interior Maintenance: Ceiling tiles water damaged

105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, water bubbler out-of-order

Janitor's Closet # 2121

No Violations Noted

Administrative Staff Area

Male Bathroom # 2221

No Violations Noted

Female Bathroom # 2222

No Violations Noted

Kitchenette

No Violations Noted

BUILDING # 3

4th Floor

Staff Bathroom

105 CMR 451.123* Maintenance: Ceiling vent dusty

Unit 3-3

105 CMR 451.321* Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.350* Structural Maintenance: Windows broken in entrance

105 CMR 451.353* Interior Maintenance: Phone bases damaged

Recreation Deck

105 CMR 451.353* Interior Maintenance: Wall paint damaged

Staff Bathroom

No Violations Noted

Case Worker's Office

No Violations Noted

Handicapped Shower

No Violations Noted

Utility Closet

No Violations Noted

Lower Laundry Area

105 CMR 451.353*

Interior Maintenance: Dryer not vented to the exterior, duct damaged

Lower Shower Area

105 CMR 451.123*

Maintenance: Door frame rusted in shower # 5

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 3 and 5

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 4

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 1 and 3

105 CMR 451.123

Maintenance: Curtain missing in shower # 1

105 CMR 451.123

Maintenance: Ceiling paint damaged in shower # 5

Kitchenette

105 CMR 451.353

Interior Maintenance: Hole in countertop

Upper Laundry Area

No Violations Noted

Upper Shower Area

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 6, 7, 8, 9, and 10

105 CMR 451.123*

Maintenance: Ceiling vent dusty in shower # 9

105 CMR 451.123*

Maintenance: Walls dirty in shower # 6, 7, 8, 9, and 10

105 CMR 451.123*

Maintenance: Wall paint damaged in shower # 8

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 6, 7, 8, and 10

105 CMR 451.123

Maintenance: Curtain missing in shower # 7

105 CMR 451.123

Maintenance: Ceiling paint damaged in shower # 6, 8, 9, and 10

Slop Sink Room

No Violations Noted

Uniform Storage Room

No Violations Noted

Cells

105 CMR 451.140*

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 33, 35, 36, 39, 42, 49, 50, and 51

105 CMR 451.350*

Structural Maintenance: Window cracked in cell # 35 and 39

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 40, 44, 52, 53, 55, 56, and 64

105 CMR 451.353

Interior Maintenance: Wall paint damaged in cell # 6 and 19

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, toilet clogged in cell # 42

105 CMR 451.353

Interior Maintenance: Ceiling paint damaged in cell # 20

Unit 3-4

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

105 CMR 451.353

Interior Maintenance: Door frame rusted at entrance

105 CMR 451.353

Interior Maintenance: Wall paint damaged around phones

Recreation Deck

105 CMR 451.353*

Interior Maintenance: Floor and wall paint damaged

Handicapped Shower # 3491

No Violations Noted

Closet # 3492

105 CMR 451.353*

Interior Maintenance: Floor dirty

Staff Bathroom # 3494

105 CMR 451.123*

Maintenance: Floor paint damaged

105 CMR 451.123*

Maintenance: Ceiling vent dusty

Lower Laundry Area

No Violations Noted

Lower Shower Area

105 CMR 451.123*

Maintenance: Ceiling vent dusty in shower # 1, 2, 3, 4, and 5

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 1, 2, 3, 4, and 5

105 CMR 451.123

Maintenance: Floor dirty in shower # 1 and 2

105 CMR 451.123

Maintenance: Door frame rusted in shower # 1, 2, 3, 4, and 5

Kitchenette

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 65°F at handwash sink

105 CMR 451.353

Interior Maintenance: Wall paint damaged

105 CMR 451.200

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Upper Laundry Area

105 CMR 451.353

Interior Maintenance: Excessive lint build-up observed behind dryer

Upper Shower Area

105 CMR 451.123*

Maintenance: Floor drains dirty in shower # 6, 7, 9, and 10

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 6, 7, 8, 9, and 10

105 CMR 451.123*

Maintenance: Soap scum on floor in shower # 9

105 CMR 451.123

Maintenance: Ceiling paint damaged in shower # 6, 7, 8, 9, and 10

105 CMR 451.123

Maintenance: Curtain missing in shower # 6

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 6, 7, 8, 9, and 10

Slop Sink Room # 3582

105 CMR 451.353*

Interior Maintenance: Walls dirty

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

Uniform Storage # 3581

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Wall paint damaged in cell # 41 and 48

105 CMR 451.353*

Interior Maintenance: Ceiling paint damaged in cell # 12, 39, 45, and 48

105 CMR 451.350*

Structural Maintenance: Window cracked in cell # 44, 46, and 58

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged at entrance to cell # 29

105 CMR 451.353

Interior Maintenance: Wall paint damaged in cell # 3, 4, 5, 6, 8, 11, 42, 43, 45, 46, 47, 53, 54, 55, 56, and 60

105 CMR 451.353

Interior Maintenance: Ceiling paint damaged in cell # 3, 5, 6, 8, 10, 11, 13, 20, 24, 30, 31, and 64

3rd Floor

Staff Bathroom # 3378
105 CMR 451.123*

Maintenance: Ceiling vent dusty

Chemical Storage # 3380

No Violations Noted

Case Worker's Office # 3382

No Violations Noted

2nd Floor

Staff Bathroom # 3278 and 3470
105 CMR 451.123*

Maintenance: Ceiling vent dusty

Unit 3-1

105 CMR 451.321*

Cell Size: Inadequate floor space in all cells

Common Area

No Violations Noted

Staff Bathroom # 3270
105 CMR 451.123*

Maintenance: Ceiling vent dusty

Closet # 3265

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

105 CMR 451.344

Illumination in Habitable Areas: Light not functioning properly, light out

105 CMR 451.360

Protective Measures: Building not protected against infestation, drain flies observed

Handicapped Shower Unit # 3266

No Violations Noted

Laundry Storage # 3366

No Violations Noted

Lower Laundry Area
105 CMR 451.353*

Interior Maintenance: Wall dirty behind washer and dryer units

Lower Shower Area

105 CMR 451.123*

Maintenance: Ceiling vent dusty in shower # 3 and 4

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 4 and 5

105 CMR 451.123

Maintenance: Ceiling vent dusty in shower # 1, 2, and 5

105 CMR 451.123

Maintenance: Door frame rusted in shower # 1, 2, 3, 4, and 5

105 CMR 451.123

Maintenance: Ceiling paint damaged in shower # 4 and 5

Kitchenette

105 CMR 451.200*

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

105 CMR 451.353*

Interior Maintenance: Countertop dirty

Upper Laundry Area

No Violations Noted

Slop Sink # 3365

No Violations Noted

Upper Shower Area

105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 6, 7, 8, 9, and 10
105 CMR 451.123*	Maintenance: Ceiling vent dusty in shower # 9, and 10
105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 8
105 CMR 451.123	Maintenance: Light out in shower # 9
105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # 6, 7, 8, and 10

Cells

105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 13, 26, 29, 30, 37, 41, 44, 45, 47, 48, 49, and 64
105 CMR 451.350*	Structural Maintenance: Window cracked in cell # 1, 5, 8, 11, 13, 15, 34, 40, 42, 44, and 46
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 6, 33, and 52
105 CMR 451.104*	Beds: Bed not in good repair in cell # 25, bed surface damaged
105 CMR 451.140*	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 31
105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 9, 11, 14, 15, 16, 34, 35, 36, 38, 39, 40, 43, and 46
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 1, 5, 17, and 21
105 CMR 451.350	Structural Maintenance: Ceiling water damaged in cell # 33 and 37

Recreation Deck 3-1 and 3-2

105 CMR 451.353*	Interior Maintenance: Floor paint damaged
------------------	---

Unit 3-2

105 CMR 451.321*	Cell Size: Inadequate floor space in all cells
------------------	--

Common Area

105 CMR 451.353*	Interior Maintenance: Wall vent dusty above entrance
------------------	--

Staff Bathroom # 3296

105 CMR 451.123	Maintenance: Ceiling vent dusty
-----------------	---------------------------------

Storage Room # 3392

No Violations Noted

Handicapped Shower # 3293

No Violations Noted

Slop Sink Room # 3294

105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
105 CMR 451.353	Interior Maintenance: Standing water observed in bucket

Lower Laundry Area

105 CMR 451.353*	Interior Maintenance: Wall dirty behind dryer
105 CMR 451.353*	Interior Maintenance: Dryer not vented to the exterior, duct damaged
105 CMR 451.353*	Interior Maintenance: Debris and lint build-up observed behind dryer

Lower Shower Area

105 CMR 451.123*	Maintenance: Door frame rusted in shower # 1
105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 5
105 CMR 451.123	Maintenance: Door frame rusted in shower # 2, 3, 4, and 5
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1, 2, and 4
105 CMR 451.123	Maintenance: Ceiling paint damaged in shower # 2 and 4
105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 1, 2, 3, 4, and 5

Kitchenette

105 CMR 451.353
105 CMR 451.130

Interior Maintenance: Unlabeled chemical bottle
Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink

Upper Laundry Area

No Violations Noted

Upper Shower Area

105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123*
105 CMR 451.123
105 CMR 451.123
105 CMR 451.123

Maintenance: Soap scum on walls in shower # 7, 8, 9, and 10
Maintenance: Door frame rusted in shower # 6, 7, 8, 9, and 10
Maintenance: Ceiling paint damaged in shower # 10
Maintenance: Ceiling paint damaged in shower # 6, 7, 8, and 9
Maintenance: Curtain missing in shower # 8 and 10
Maintenance: Ceiling vent dusty in shower # 6, 7, 8, 9, and 10

Slop Sink Room # 3393

No Violations Noted

Cells

105 CMR 451.353*
105 CMR 451.353*
105 CMR 451.350
105 CMR 451.353
105 CMR 451.353
105 CMR 451.350

Interior Maintenance: Ceiling paint damaged in cell # 5, 6, 7, 10, 12, 29, 34, and 48
Interior Maintenance: Wall paint damaged in cell # 5, 38, and 40
Structural Maintenance: Window cracked in cell # 46
Interior Maintenance: Ceiling paint damaged in cell # 4, 35, and 36
Interior Maintenance: Wall paint damaged in cell # 12, 32, 44, and 62
Structural Maintenance: Ceiling water damaged in cell # 32

Recreation Deck

105 CMR 451.353
105 CMR 451.353

Interior Maintenance: Floor paint damaged
Interior Maintenance: Wall paint damaged

1st Floor

Education Area

Common Area

105 CMR 451.353
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty in hallway outside staff bathroom
Interior Maintenance: Ceiling tiles water damaged in hallway

Classrooms

No Violations Noted

Library # 3149

105 CMR 451.353

Interior Maintenance: Ceiling tiles water damaged

Staff Bathroom # 3142

No Violations Noted

Inmate Bathroom # 3162

105 CMR 451.123

Maintenance: Ceiling paint damaged

Inmate Legal Services

105 CMR 451.200*

Food Storage, Preparation and Service: Food storage not in compliance with
105 CMR 590.000, plastic utensils left uncovered and open to contamination

Office Area # 3131

No Violations Noted

Office Staff Bathroom # 3126

No Violations Noted

Law # 3166

No Violations Noted

Main Laundry

Hallway

105 CMR 451.350*

105 CMR 451.353*

Structural Maintenance: Door leading to the exterior not rodent and weathertight

Interior Maintenance: Ceiling tiles water damaged

Office

No Violations Noted

Storage # 3184

No Violations Noted

Laundry Area

105 CMR 451.350

Structural Maintenance: Floor paint damaged throughout

Two-Compartment Sink

No Violations Noted

Handwash Sink

No Violations Noted

Bathroom # 3181

No Violations Noted

Storage # 3182

No Violations Noted

BUILDING # 4

105 CMR 451.350*

105 CMR 451.353

Structural Maintenance: Main entrance not rodent and weathertight

Interior Maintenance: Walls dirty throughout entrance area

Dining Hall # 4137

FC 6-501.12(A)*

FC 6-501.12(A)*

FC 6-501.12(A)*

Maintenance and Operation; Cleaning: Facility not cleaned properly, floor dirty

Maintenance and Operation; Cleaning: Facility not cleaned properly, ceiling dirty

Maintenance and Operation; Cleaning: Facility not cleaned properly, handwash sink full of debris

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, window broken on door at entrance

FC 7-101.11

Poisonous or Toxic Materials; Original Containers: Cleaning chemicals not labeled properly, original manufactures label missing

Unit 4-1

Common Area

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 60°F at handwash sink

Kitchenette

105 CMR 451.200*

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Lower Shower Area

105 CMR 451.123*	Maintenance: Ceiling vent dusty in shower # 1, 2, 3, and 6
105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 1, 2, 3, 4, 5, and 6
105 CMR 451.123*	Maintenance: Door frame rusted in shower # 1, 2, 3, 4, 5, and 6
105 CMR 451.123	Maintenance: Ceiling vent dusty in shower # 4 and 5
105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure in shower # 6

Storage # 4265

105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
-----------------	--

Upper Shower Area

105 CMR 451.123*	Maintenance: Ceiling vent dusty in shower # 7, 8, 9, 10, 11, and 12
105 CMR 451.123*	Maintenance: Door frame rusted in shower # 7, 8, 9, 10, 11, and 12
105 CMR 451.123*	Maintenance: Dead drain flies on ceiling in shower # 7
105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 7, 8, 9, 10, 11, and 12
105 CMR 451.123	Maintenance: Ceiling paint damaged in cell # 11

Storage # 4364

105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
-----------------	--

Cells

105 CMR 451.350*	Structural Maintenance: Window cracked in cell # 3 and 15
------------------	---

Unit 4-2

1st Tier Bathroom # 4257 and 4268

105 CMR 451.123*	Maintenance: Floor dirty and covered with debris
105 CMR 451.123*	Maintenance: Counter top dirty
105 CMR 451.123	Maintenance: Handwash sink # 8 and 7 dirty
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink # 1 and 5
105 CMR 451.123	Maintenance: Floor paint damaged

Slop Sink Closet (inside bathroom)

105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
-----------------	--

Common Area

105 CMR 451.353	Interior Maintenance: Wall paint damaged throughout
105 CMR 451.353	Interior Maintenance: Walls dirty throughout

Kitchenette

105 CMR 451.200*	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
105 CMR 451.353*	Interior Maintenance: Counter top dirty
105 CMR 451.353*	Interior Maintenance: Walls dirty

1st Tier Bathroom # 4285 and 4275

105 CMR 451.123*	Maintenance: Floor dirty throughout
105 CMR 451.126*	Hot Water: Hot water temperature recorded at 90°F in sink # 8
105 CMR 451.123*	Maintenance: Wall dirty under sinks
105 CMR 451.123	Maintenance: Floor paint damaged
105 CMR 451.123	Maintenance: Ceiling vent dusty

Slop Sink Closet (inside Bathroom # 4285 and 4275)

105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
-----------------	--

<i>Room # 4272</i>	No Violations Noted
<i>TV Room # 4273</i>	No Violations Noted
<i>Laundry Area</i>	No Violations Noted
<i>Handicapped Shower # 4274</i> 105 CMR 451.123*	Maintenance: Ceiling vent dusty
<i>Uniform Storage # 4249</i>	No Violations Noted
<i>Room # 4250</i>	No Violations Noted
<i>Room # 4251</i>	No Violations Noted
<i>Room # 4252</i>	No Violations Noted
<i>Staff Bathroom # 4254</i>	No Violations Noted
<i>Handicapped Shower # 4256</i>	No Violations Noted
<i>TV Room # 4270 and 4271</i>	No Violations Noted
<i>2nd Tier Utility Room # 4388</i> 105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
<i>2nd Tier Storage Room # 6123</i>	No Violations Noted
<i>Storage Room # 4353</i> 105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
<i>Storage Room # 4369</i>	No Violations Noted
<i>2nd Tier Bathroom # 4366 and 4354</i> 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123*	Maintenance: Floor paint damaged throughout Maintenance: Ceiling vents dusty Maintenance: Vent between bathroom and hallway filled with debris
<i>Slop Sink Closet (inside bathroom)</i> 105 CMR 451.353	Interior Maintenance: Ceiling vent dusty

2nd Tier Bathroom # 4374 and 4387

105 CMR 451.123 Maintenance: Floor paint damaged throughout
105 CMR 451.123 Maintenance: Floor dirty
105 CMR 451.123 Maintenance: Ceiling vents dusty

Cells

105 CMR 451.350* Structural Maintenance: Window cracked in cell # 26 and 30
105 CMR 451.103 Mattresses: Mattress damaged in cell # 8 and 46

Unit 4-3

Common Area

No Violations Noted

Kitchenette

No Violations Noted

Lower Shower Area # 1 - 6

105 CMR 451.123* Maintenance: Ceiling dirty in shower # 3, 4, and 5
105 CMR 451.123* Maintenance: Soap scum on walls in shower # 1, 2, 3, 4, 5, and 6
105 CMR 451.123* Maintenance: Ceiling vent dusty in shower # 1, 2, 3, 4, 5, and 6
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, shower # 4 out-of-order
105 CMR 451.123 Maintenance: Curtain missing in shower # 4

Upper Shower Area # 7 - 12

105 CMR 451.123* Maintenance: Door frame rusted in shower # 8, and 12
105 CMR 451.123* Maintenance: Ceiling vent dusty in shower # 7, 8, 9, and 10
105 CMR 451.123* Maintenance: Soap scum on walls in shower # 7, 8, 9, 10, 11, and 12
105 CMR 451.123 Maintenance: Ceiling vent dusty in shower # 11 and 12

Storage Room # 4283

No Violations Noted

Cells

105 CMR 451.353 Interior Maintenance: Ceiling paint damaged in cell # 5
105 CMR 451.353 Interior Maintenance: Wall paint damaged in cell # 14 and 15

Unit 4-4 Video Court Rooms

Holding Cells

No Violations Noted

Inmate Bathroom

Unable to Inspect – Not in Use

Slop Sink Closet # 4130

105 CMR 451.353 Interior Maintenance: Wet mop stored in bucket

Staff Bathroom

No Violations Noted

CGI

Officer Station

No Violations Noted

Office

No Violations Noted

Industries

No Violations Noted

Slop Sink Closet

No Violations Noted

Staff Bathroom

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink

Inmate Bathroom

No Violations Noted

Maintenance

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet leaking at slop sink

Bathroom # 5166

105 CMR 451.123*

Maintenance: Ceiling vent dusty

Bathroom # 5163

No Violations Noted

Kitchenette

105 CMR 451.200*

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator gaskets damaged

Laundry/Slop Sink # 5162

No Violations Noted

Break Area

No Violations Noted

BUILDING # 5

Food Service Area

FC 6-501.11

Maintenance and Operation; Repairing: Facility not in good repair, floor tiles damaged throughout kitchen

Section 1

Inmate Locker Room

No Violations Noted

Slop Sink Room

105 CMR 451.353*

Interior Maintenance: Wall surface damaged

Chemical Storage

105 CMR 451.353*

Interior Maintenance: Wet mop stored in bucket

Staff Bathroom

No Violations Noted

Mechanical Warewashing Area

FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, ceiling tiles water damaged
FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, floor damaged
FC 4-204-113(A)*	Design and Construction, Functionality: Unable to read data plates on left warewashing machine
FC 4-204.115	Design and Construction, Functionality: Thermometer not functioning properly on left warewashing machine

Pot Wash Area

FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, wall damaged under 3-compartment sink unit
FC 5-205.15(B)*	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, air conditioner drain pipe draining onto floor
FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, garbage disposal out-of-order
FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, pipes leaking water below 3-compartment sink unit
FC 5-205.15(B)	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, left faucet leaking at 3-compartment sink
FC 6-501.11	Maintenance and Operation; Repairing: Facility not in good repair, grease trap cover not properly secured to ground

Pot Wash Handwash Sink

No Violations Noted

Tray Area Handwash Sink

No Violations Noted

Section 2

Kettles

No Violations Noted

Handwash Sink

No Violations Noted

Prep-Sink

No Violations Noted

Pot/Pan Storage Room

FC 6-501.12(A)*	Maintenance and Operation; Cleaning: Facility not cleaned properly, rodent droppings observed on floor
-----------------	--

Officer's Office

No Violations Noted

Chef's Office

FC 4-602.12(B)*	Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty
-----------------	---

Section 3

Stove Top Area

No Violations Noted

Section 4

Prep-Table

No Violations Noted

Refrigerator # 1
FC 6-501.12(A)*

Maintenance and Operation; Cleaning: Facility not cleaned properly, rodent droppings observed on floor

FC 7-206.12

Poisonous or Toxic Materials; Pesticides: Rodent traps not covered and tamper resistant, snap trap observed

Bread Cooler # 2
FC 6-501.12(A)*

Maintenance and Operation; Cleaning: Facility not cleaned properly, rodent droppings observed

Refrigerator # 3
FC 4-601.11(C)*

Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty, ceiling dirty near ventilation fans

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, rodent droppings observed

Freezer # 4
FC 6-501.12(A)
FC 4-501.11(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, floor dirty
Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, one fan not working

Ice Machine
FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, left side ice machine out-of-order

Section 5

Special Diet Area

No Violations Noted

Dry Storage Area
FC 6-501.12(A)*

Maintenance and Operation; Cleaning: Facility not cleaned properly, rodent droppings observed near dented can storage and along perimeter of room

FC 7-206.12*

Poisonous or Toxic Materials; Pesticides: Rodent traps not covered and tamper resistant

Loading Dock
FC 6-202.15(A)(2)

Design, Construction, and Installation; Functionality: Outer door not weather and vermin tight

Commissary

No Violations Noted

Staff Bathroom # 5152
105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Section 6

Refrigerator # 6

FC 3-305.11(A)(2)

FC 6-501.12(A)

FC 6-501.12(A)

Preventing Contamination from Premises: Food exposed to dust, ceiling fans dusty
Maintenance and Operation; Cleaning: Facility not cleaned properly, floor dirty
Maintenance and Operation; Cleaning: Facility not cleaned properly, water pooling on floor

2-Compartment Sink Area

FC 5-202.12(A)*

FC 5-205.15(B)

Plumbing System, Design: Handwashing sinks water temperature recorded at 136⁰F
Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, faucet loose on 2-compartment sink

Prep-Refrigerators and Tray Assembly Line

FC 4-501.11(A)*

FC 6-501.111(B)

FC 4-501.11(B)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, hot holding units unable to fully close
Maintenance and Operations; Pest Control: Flies observed
Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged on hold holding unit # 1

Staff Food Line and Dining Room

FC 4-903.11(B)(2)*

FC 4-501.11(B)

Protection of Clean Items, Storing: Plastic utensils not stored in an inverted position
Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged in dining room

Culinary Arts Kitchen

Tool Storage

No Violations Noted

Coolers and Freezers

No Violations Noted

Steam Kettle Area

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, steam kettle out-of-order

Hoods

No Violations Noted

Prep Tables and Sinks

No Violations Noted

3-Compartment Sink

No Violations Noted

Slop Sink

No Violations Noted

Handwash Sink

FC 5-202.12(A)*

Plumbing System, Design: Handwashing sinks water temperature recorded at 105⁰F

Bathroom

No Violations Noted

Classroom Section

No Violations Noted

Gym

105 CMR 451.353
105 CMR 451.130

Interior Maintenance: Padding damaged on exercise equipment
Plumbing: Plumbing not maintained in good repair, water fountain out-of-order

Bathroom # 5204

105 CMR 451.123
105 CMR 451.130

Maintenance: Floor paint damaged
Plumbing: Plumbing not maintained in good repair, pipes leaking under sink

Staff Bathroom # 5207

No Violations Noted

Slop Sink Closet # 5203

No Violations Noted

Automotive Garage

No Violations Noted

BUILDING # 6

105 CMR 451.350*

Structural Maintenance: Outer door not rodent and weathertight at entrance to Health Services

Health Services Medical Area

Hallway

105 CMR 451.353*

Interior Maintenance: Ceiling vent dusty outside room # 6268

Exam Room # 1 3172

No Violations Noted

Exam Room # 2 3134

No Violations Noted

Exam Room # 3 3171

No Violations Noted

Exam Room # 4 3133

No Violations Noted

File Room # 6226

No Violations Noted

Inmate Bathroom # 6229

105 CMR 451.117*
105 CMR 451.123*

Toilet Fixtures: Toilet fixtures damaged
Maintenance: Ceiling vent dusty

Medication Room

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Office # 6267

No Violations Noted

Lab Room # 6268

Unable to Inspect – In Use

Office # 6269

No Violations Noted

X-Ray Room # 6265

105 CMR 451.353

Interior Maintenance: Floor paint damaged

105 CMR 451.353

Interior Maintenance: Wall paint damaged

Dental Exam Room # 6261

No Violations Noted

Dental Storage Closet # 6262

No Violations Noted

Medical Director's Office # 6263

105 CMR 451.350*

Structural Maintenance: Window cracked

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

Medical Unit

Recreation Room # 6258

No Violations Noted

Kitchenette # 6256

No Violations Noted

Isolation Cells

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty in cell # 5

Isolation Handwash Sink

105 CMR 451.126*

Hot Water: Hot water temperature recorded at 100°F

Office # 6254

No Violations Noted

Storage Room # 6253

No Violations Noted

Storage Room # 6252

No Violations Noted

Medical Waste/Biohazard Storage # 6250

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

105 CMR 451.353

Interior Maintenance: Ceiling paint damaged

105 CMR 451.353

Interior Maintenance: Ceiling dirty

105 CMR 451.353

Interior Maintenance: Walls dirty

Staff Bathroom # 6247

No Violations Noted

Chemical Storage Room # 6248

No Violations Noted

Inmate Property # 6246

No Violations Noted

Shower Area

105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 2
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1 and 3
105 CMR 451.123	Maintenance: Door paint damaged in shower # 2 and 3
105 CMR 451.123	Maintenance: Ceiling dirty in shower # 2

Staff Lounge

105 CMR 451.353	Interior Maintenance: Floor tiles damaged
-----------------	---

Staff Bathroom # 6237

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink
-----------------	---

Cells

105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 16 and 18
105 CMR 451.140*	Adequate Ventilation: Inadequate ventilation, ceiling vent blocked in cell # 1
105 CMR 451.103	Mattresses: Mattress damaged in cell # 11
105 CMR 451.353	Interior Maintenance: Ceiling vent dusty in cell # 1, 5, 6, 7, 9, 10, 11, 13, 15, 16, and 17
105 CMR 451.353	Interior Maintenance: Floor tile damaged in cell # 17
105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 1, 8, 9, 10, and 15
105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 12

Booking Area

Hallway

No Violations Noted

Control

No Violations Noted

Male Changing Room # 6109

105 CMR 451.353*	Interior Maintenance: Floor paint damaged
------------------	---

Property Room # 6106

105 CMR 451.353*	Interior Maintenance: Ceiling tiles missing
105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged

Old Shower Room # 6111

No Violations Noted

Male Holding Cells

105 CMR 451.353*	Interior Maintenance: Floor paint damaged in cell # 1 and 2
105 CMR 451.353*	Interior Maintenance: Floor dirty in cell # 1 and 6
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 3 and 6
105 CMR 451.353	Interior Maintenance: Floor dirty in cell # 10
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 10

Slop Sink # 6110

No Violations Noted

Medical Intake Office

No Violations Noted

Medical Bathroom # 6114

105 CMR 451.123	Maintenance: Ceiling paint damaged
-----------------	------------------------------------

Break Room # 6131

No Violations Noted

Staff Bathroom # 6135

105 CMR 451.123*

Maintenance: Ceiling vent dusty

Female Property Room # 6139

No Violations Noted

Female Changing Room # 6138

No Violations Noted

Storage Room # 6132

No Violations Noted

Room # 6137

105 CMR 451.344*

Illumination in Habitable Areas: Light not functioning properly, light out

Female Holding Cells

105 CMR 451.353*

Interior Maintenance: Wall paint damaged in cell # 6

105 CMR 451.353*

Interior Maintenance: Floor dirty in cell # 6

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in cell # 7

Sally Port

No Violations Noted

BUILDING # 7

Vehicle Trap

1st Floor

No Violations Noted

Bathroom

No Violations Noted

2nd Floor

105 CMR 451.353*

Interior Maintenance: Unlabeled chemical bottle

105 CMR 451.353*

Interior Maintenance: Ceiling tiles water damaged

BUILDING # 8

1st Floor - Unit 8-1

Staff Area

Staff Bathroom # 8-106

No Violations Noted

Electrical # 8-108

No Violations Noted

Property # 8-111

No Violations Noted

Offices

105 CMR 451.200* Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, excessive ice build-up in freezer in office # 8-113

Common Area

No Violations Noted

Video Court # 8-114

No Violations Noted

Office # 8-115

No Violations Noted

Staff Break Room # 8-116

105 CMR 451.353 Interior Maintenance: Wall paint damaged

Immigration Office # 8-117

No Violations Noted

Storage # 8-118 A & B

No Violations Noted

Laundry Area

No Violations Noted

Slop Sink Room # 8-123

No Violations Noted

Housing Area

Inmate Bathroom # 8-121

105 CMR 451.123* Maintenance: Floor damaged near handwash sinks
105 CMR 451.123* Maintenance: Floor dirty outside showers
105 CMR 451.123* Maintenance: Wall water damaged near showers
105 CMR 451.123 Maintenance: Wall vent dusty above showers
105 CMR 451.123 Maintenance: Water stains on walls near showers
105 CMR 451.126 Hot Water: Hot water temperature recorded at 92⁰F at handwash sink # 6

Inmate Bathroom # 8-122

105 CMR 451.123* Maintenance: Floor damaged near showers
105 CMR 451.123* Maintenance: Floor dirty outside showers
105 CMR 451.123* Maintenance: Wall and ceiling water damaged near showers
105 CMR 451.123 Maintenance: Wall vent dusty above showers

Holding Cell # 7

No Violations Noted

Cells

105 CMR 451.103 Mattresses: Mattress damaged in cell # 12

2nd Floor - Unit 8-2

Staff Area

Staff Bathroom # 8-206

No Violations Noted

Medical # 8-207

No Violations Noted

Property # 8-211

No Violations Noted

Medical # 8-212

No Violations Noted

Electrical # 8-226

No Violations Noted

Common Area

No Violations Noted

Computer Room # 8-214

No Violations Noted

Recreation Room # 8-215 and 8-216

No Violations Noted

Recreation Room # 8-217

105 CMR 451.353

Interior Maintenance: Wall paint damaged

Uniform Storage # 8-219

No Violations Noted

Storage # 8-218 A

No Violations Noted

Storage # 8-218 B

105 CMR 451.353*

Interior Maintenance: Wet mop stored in bucket

Laundry Area

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet leaking at handwash sink

Housing Area

Inmate Bathroom # 8-221

105 CMR 451.123*

105 CMR 451.123*

105 CMR 451.123

105 CMR 451.123

Unable to Inspect Shower # 2 and 4 – In Use

Maintenance: Floor damaged outside shower # 5 and near toilets

Maintenance: Wall vent dusty above showers

Maintenance: Wall paint damaged

Maintenance: Wall dirty behind handwash sinks

Inmate Bathroom # 8-222

105 CMR 451.123*

105 CMR 451.123*

105 CMR 451.123*

Maintenance: Floor damaged near toilet stall # 2

Maintenance: Wall vent dusty above showers

Maintenance: Wall water damaged near showers

Slop Sink # 8-223

105 CMR 451.353*

Interior Maintenance: Wet mop stored in bucket

Cells

105 CMR 451.353

Interior Maintenance: Floor tile missing in cell # 11

3rd Floor - Unit 8-3

Staff Area

Staff Bathroom # 8-306

No Violations Noted

Storage # 8-307

No Violations Noted

Property # 8-311

No Violations Noted

Electrical # 8-326

No Violations Noted

Offices

No Violations Noted

Common Area

105 CMR 451.353*

Interior Maintenance: Unlabeled chemical bottle

Computer Room # 8-314

No Violations Noted

Recreation Room # 8-315

No Violations Noted

Recreation Room # 8-316

105 CMR 451.350*

Structural Maintenance: Window shattered

Recreation Room # 8-317

No Violations Noted

Uniform Storage # 8-319

No Violations Noted

Storage # 8-318 A & B

No Violations Noted

Laundry Area

No Violations Noted

Housing Area

Slop Sink Room # 8-323

105 CMR 451.344

Illumination in Habitable Areas: Light not functioning properly, light out

Inmate Bathroom # 8-321

105 CMR 451.123*

Maintenance: Floor damaged by toilets

105 CMR 451.123*

Maintenance: Floor damaged in back corner outside showers

105 CMR 451.123*

Maintenance: Wall vent dusty above showers

105 CMR 451.123

Maintenance: Toilet # 1 rusted

105 CMR 451.123

Maintenance: Light shield water stained

Inmate Bathroom # 8-322

105 CMR 451.123*	Maintenance: Floor left unfinished
105 CMR 451.123*	Maintenance: Floor dirty outside showers
105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, faucet leaking in sink # 1
105 CMR 451.123*	Maintenance: Curtain missing in shower # 4
105 CMR 451.123	Maintenance: Curtain missing in shower # 3
105 CMR 451.123	Maintenance: Wall vent dusty above showers

Cells

105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 8, 11, and 12
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 5

4th Floor - Unit 8-4

Unable to Inspect – Closed for Renovations

Observations and Recommendations

1. The inmate population was 907 at the time of inspection.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X – Minimum Sanitation Standards for Food Establishments" and "[1999 Food Code](#)".

To review the Labeling regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Patrick Wallace
Environmental Health Inspector, CSP, BEH

cc: Jana Ferguson, Director, BEH
Steven Hughes, Director, CSP, BEH
Marylou Sudders, Secretary, Executive Office of Health and Human Services
Thomas Turco, Commissioner, DOC
Yolanda Smith, Superintendent
Brian Reynolds, Captain, Support Service Supervisor
John Fallon, EHS/FSO
John Meaney, Assistant Commissioner of Health, Boston Inspectional Services
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Daniel Bennett, Secretary, EOPSS
Nelson Alves, Director, Policy Development and Compliance Unit